## **BEECH 18 PRODUCTION LIST**

Compiled by Geoff Goodall

## PART 4: BEECH SUPER 18: E18S, G18S & Super H18

(Built at Wichita, Kansas 1953-1969)



Production E18S N53S (c/n BA-293) at Denver CO in December 1960.

Photo by Eddie Coates



The final production model of the Beech 18 line, this H18 N34AP (c/n BA-746) was built in 1967 for Japan Air Lines with factory-fitted Volpar trigear. Seen at Lanai, Hawaii on an early morning All Hawaii Air freight run from Honolulu delivering freshly baked bread to Hawaiian islands in September 1979. Photo by Geoff Goodall

The final developments of the Beech 18 line, the E18S, G18S and ultimate Super H18 were built at Wichita, Kansas between 1953 and 1968. Aimed squarely at the business aircraft market, they were advertised as *Beech Super 18s*, featuring a raised roof and enlarged cockpit windows. Many were retro-fitted with the

popular Volpar trigear undercarriage modification, and Beech offered the final model, the *Super H18* with factory fitted Volpar trigear.

The Super 18s had increased wingspan and improved performance, extended range, and all models had larger windows and door. The initial E18S had a All Up Weight of 9300 pounds, 550 pounds more than the current production D18S. Payload was further increased with later models.

Model E18S-9700 had AUW increased to 9700 lbs, and was first model with 3 bladed propellers. A larger centre cabin window was introduced during the last third of the G18S production. The H18 was fitted with three-bladed Hartzell propellers as standard.

Beech used the BA- prefix for the construction numbers of all models of *Super 18s*, presented in documentation and aircraft plates with and without the hyphen:



Typical Beech construction plate: BA-81 N3781B, VH-CIJ. (courtesy Ron Cuskelly)

BA-1	E18S	N3460B	Beech Aircraft Corp, Wichita KS	12.53/55
			(first E18S, first flight Wichita 10.12.53)	
			(certification flight trials, then demonstrator)	
			Air Orlando Inc, Orlando FL	63
			George H. Bailey Co/ Bailey Leasing Corp, Ft Wayne IN	64/66
			Albany Air Service, Albany GA	69
			Jack Adams Aircraft Sales, Walls MS	70
		N511WP (1	rereg	
		N3460B	Albany Air Service, Albany GA	70
		XA-BEK	Perez Morales, Guerrero Negro	10.70/77
			Aerolineas California Pacifico SA - ACAPSA,	
			Guerrero Negro, Baja California	78/89

BA-2 E18S	E18S	N500V N992	Atlantic Aviation, Wilmington DE: delivered new rereg	8.54	
		N9921	Bahnson Co, Winston Salem NC crashed, destroyed by fire, landing Wooster OH	63/64 3.6.64	

13.1.55
10.55/60
5.12.60/64
14.1.64
1.9.64/66
11.66/71
71
1.4.71/72
5.71
5.6.72/74
.74
2.74/75
10.6.75/79
28.2.79/86
20.7.82
9.86/90
3.12.90/91
.91)
27.8.91/93
27.8.91
7.3.93
8.93
using
23 que se)
26.10.93/95
27.4.95

(note: no ref. to conv. to PacAero Tradewind in FAA file)

N3606B was displayed at Dayton OH airshow 7.55;

N3606B noted Detroit MI 11.11.76;

N3606B accident report 20.7.82: Executive Aviation Inc, a small post crash engine fire was extinguished;

C-FMQS rebuilt at Redditt ONT by Rollie Hammerstedt of Redditt Aviation, who were Beech 18 overhaul specialists;

BA-4	E18S	N3605B	built Roselie Shumaker, Moab UT (last annual inspection report 8.55)	.55 64/71
•			struck-off USCR	15.7.71
BA-5	E18S	N3612B	built Empire State Airlines, Syracuse NY op: Command Airways struck vehicle taxying, New York-JFK NY Flight Service Inc, Syracuse-Hancock Field NY Brandt Air/ Alii Air Hawaii, Honolulu HI (retired, stripped, Honolulu 77/79) struck-off USCR	.55 63/70 67 20.2.67 15.10.70/72 26.2.73/81 5.10.81

N3612B noted Baltimore MD 15.6.63 Empire State Airlines;

accident report 20.2.67: Command Airways, struck vehicle while taxying for takeoff;

N3612B photo c67: "Empire State Airlines" titles, tailwheel; N3612B noted Van Nuys CA 6.1.72;

N3612B noted Honolulu 1.9.79, wfu stripped tailwheel, in Brandt aircraft storage compound with other Beech 18s and Dove;

N3612B noted Honolulu 12.11.79 Brandt Air retired, stripped;

BA-6 E18S	E18S	N3600B	Atlantic Aviation Corp: CofA issued	2.9.54/55
			L. P. Graner Inc	26.4.55
		Philips Gloeilampenfabrieken NV, Netherlands (del. to Netherlands via Prestwick 6.5.55)	6.5.55	
		(PH-NFU) nt	ntu: NV Philips, Eindoven, Netgherlands	6.55
		PH-LPS	Philips NV, Eindhoven (commenced schedued company courier services 1.	20.6.55/65 10.55

(PH-ILA)	from Eindhoven throughout Europe and UK) ntu: Philips NV	.57
PH-LPS	Philips NV, Eindhoven	57/65
	damaged in accident, Woodvale Aerodrome UK	3.7.57
	Transair Switzerland	27.10.65
(HB-GBD)	ntu: Transair Switzerland	11.65/67
CN-MAQ	Directeur Generale de la Securite Nationale, Rabat	3.67/78
	(CofA expired 10.71, parked in open Malaga, Spain 71/7)	7)
	struck-off Register	12.10.77
N9886A	David C. Tallichet & John R. Hawke/	
	Euroworld California Inc, Long Beach CA	20.1.78/80
	David C. Tallichet/ Visionair International, Miami FL	3.7.80/83
	David C. Tallichet/ Military Aircraft Restoration Corp,	
	Chino CA	24.6.83/90
	(abandoned, open storage, Malaga Spain 79/96)	
	(no CofA issued as N9886A)	
	Fundacion Infante de Orleans Museum,	
	Cuatro Vientos AB, Spain	.90/95
	Museo Nacional De Aeropuettos Y transporte Aereo,	
	Malaga, Spain	98/16
	(static rest. at Malaga, displayed from 98 as "EC-ASJ Spantax SA")	

Philips NV, large electrical manufacturing company based at Eindhoven decided to purchase its own corporate aircraft and a flight department commenced on 1.10.55 using the E18S. During first year the E18S flew 259 hrs and carried 150 passengers. Second aircraft was Dove PH-ILI delivered 29.7.57.

then Heron PH-ILA 1.59. The E18S served for 10 years before replaced by a Falcon 20 business jet; N3600B noted Prestwick 7.5.55 on delivery to Holland for Philips;

PH-LPS visited Blackbushe 4.6.56;

PH-LPS visited Blackbushe 3.9.56 in visitors' park for 56 Farnborough Air Show;

PH-LPS visited Dublin, Ireland 3.8.56 Philips NV;

PH-LPS visited Renfrew UK 8.5.57 Philips NV;

PH-LPS visited Southampton 22.4.58 Philips NV; Manchester 28.8.58;

PH-LPS noted Kidlington UK 25.4.59;

PH-LPS visited Southampton 7.10.59 Philips NV to Eindhoven next day;

PH-LPS visited Gatwick 22.2.60

PH-LPS visited Glasgow-Renfrew 4.4.60 & 14/15.6.60 Philips Ltd, Einhoven;

PH-LPS visited Birmingham 23.5.62;

PH-LPS visited Gatwick 4.3.64, 28.5.64; Manchester-Yeadon 17.9.64;

PH-LPS visited Southend 16.12.64 from Gatwick, to Eindhoven 17.12.64;

PH-LPS noted Heathrow 18.12.64 Philips Electronics;

PH-LPS flew Eindhoven-Leeds Bradford-Eindhoven 7.5.65 Philips Electronics;

PH-LPS overflew Sidmouth UK 15.7.65;

PH-LPS visited London-Heathrow 14.10.65 Philips Electronics;

CN-MAQ noted Colombier Neu Chatel, Switzerland 31.5.67, 20.4.68 & 17.7.68;

CN-MAQ noted Cannes 14.2.71 on overhaul in hangar;

N9886A noted stored Malaga, Spain 5.84

N9886A noted Malaga 8.91 derelict on airfield with Dove N9888A;

N9886A noted Malaga 18.8.93 semi-derelict;

N9886A noted Malaga 7.11.99 dispayed near GA terminal;

EC-ASJ noted Cuatro Vientos 23.10.98 with FldOM, rep. plate "AT-764";

"EC-ASJ" noted Malaga 8.4.00 "SPANTAX S.A.", excellent condition, 3 bladed props:

wheels jacked up, under sun cover;

"Airways" magazine 00 states displayed since 12.99 by Aeropuerto de Malaga and AENA;

"EC-ASJ Spantax" noted Malaga 26.6.02 on display (no sun cover);

BA-7	E18S	N3611B	Alamo Aviation, San Antonio TX	20.9.54
			H. B. Zachry Co	10.54/56
		Gulf Interstate Gas Co N30G (1 Gulf Interstate Gas Co Columbia Gulf Transmission Co N155JH Commandair Inc	17.1.56	
			27.6.57/58	
			12.58/59	
			30.10.59/60	
Grau			Starflite Inc	31.3.60/62
	Graubart	N426SF	Graubart Aviation, Valparaiso IN	1.11.62/64
	Aviation		(Volitan Aviation installed Volpar trigear 2.63:	
	Trigear		other mods. comprising Graubart Aviation Trigear)	

	Guaranty Financial Corp	6.10.64/66
	gear collapsed landing, Chicago-Miway IL	3.1.66
(N588YA)	ntu: Yegen Associates Midwest Inc, Northfield IL	10.66
N426SF	Yegen Associates Midwest Inc/ Bonav Corp, Northfield IL	11.66/68
	Executaire Inc, Cincinatti-Lunkin OH	7.10.68/69
	R. J. Paquette Co	26.6.69/70
	Hamilton Aircraft Co, Tucson AZ	22.7.70/71
	Flint Air Inc, Flint MI	24.6.71/72
	(cargo floor and cargo door installed 2.72)	
	op: Great Lakes Commuter, Chicago IL	72
	Richard A. Carroll	8.1.73/78
	First Tennessee Bank, Johnson TN: restored USCR	4.78
	K & K Aircraft Inc, Bridgewater VA	26.6.78
	Brennan Air Freight Inc	28.7.78/80
	Wayne Sturman Aircraft Sales, Merritt Island FL	31.5.80/06
	struck-off USCR	10.8.06

Graubart Avtn: see Beech 18 by Parmerter p.354; N426SF photo 12.64 Graubart Aviation Trigear; N426SF noted Chicago-O'Hare 15.6.72 Great Lakes Commuter, trigear;

BA-8	E18S	N3613B	Page Airways, Rochester NY	24.9.54
			National Home Corp	4.11.54/59
		N444Z	Page Airways, Rochester NY	19.2.59/61
			Ontario Airways, Auburn NY	23.1.61/64
			T. R. Carpenter/ Flight Service Inc/ Empire State Airlin	nes,
			Syracuse-Hancock Field NY	1.12.64/72
			Richard Visser/ Twin Brook Aviation	5.1.72
			Richard Visser/ Sky-Train Inc	16.5.72/76
			Wilbur W. Martin	8.1.76
			Carol Dean Kyle, Elba AL	22.6.76
			State of Utah: forfeited by court order	17.1.78
			Leonard W. Bartish	1.8.78
			Aerospace Products Inc, North Hollywood CA	3.8.78
			Charles E. Bush/ Bush Aviation, Ft Lauderdale FL	4.9.78/79
			lost without trace en route Fort Lauderdale FL to	
			Cat Island, Bahamas	2.4.79
			struck-off USCR	3.86

N444Z noted New York-JFK 5.4.66 Empire State AL; N444Z went missing on flight by pilot Jim Catron who flew to Bahamas regularly;

3A-9	E18S	N3614B	J. D. Reed Co, Houston TX	8.10.54/55
			Growers Ice & Development Co	15.1.55/59
			O. R. Burden Construction Corp, Tulsa OK	23.3.59/64
			Southeastern Beechcraft Inc, Kingsport TN	1.6.64/65
	trigear		(Volitan Aviation installed Volpar trigear 6.64)	
			Mack Trucks Inc, Montville NJ	13.4.65/66
		N1021B	Mack Trucks Inc, Montville NJ	3.66
		N10216	Mack Trucks Inc, Montville NJ	11.66/67
			Princeton Aviation Corp, Princeton NJ	31.1.67/69
			East Coast Aviation, Hackensack NJ	7.5.69/73
			Thomas Werner	4.5.73/74
			International Airmotive Corp	12.74/75
			International Sales & Leasing, Warrenton OR	31.1.75
			Ram Air Charter Ltd, Inuvik NWT	3.9.75
		C-GWYJ	Ram Air Charter Ltd, Inuvik NWT	1.12.75/79
			Sam Haladay/ The Air Ranger Ltd	81
		N8535X	Bill Walker & Associates, St Simons Island GA	3.1.81
			Paul O'Conner: sale documention not completed	22.1.81
		N10216	International Sales & Leasing, Warrenton OR	3.93
			sale reported, McAllen TX: USCR	95/02

BA-10	E18S	N3615B N501J	Anderson Air Activities Malvern Co Western Tool & Stamping Co, Des Moines IA Corey Custom Airtravel Inc Tobey Inc, Simsbury CT	29.9.54/55 30.7.55/57 1.11.57/64 27.8.64 2.11.64/66
		N911E	Tobey Inc, Simsbury CT (cargo floor, cargo airstair cabin door and cockpit hatch installed 10.73)	10.66/76
			struck snowbank landing, Boston-Logan MA gear collapsed during landing, Simsbury CT Brennan & Hargreaves Inc, Hartford CT	24.12.75 24.6.76 6.7.76/80
			Hamilton Aviation, Tucson AZ Leo J. Crum/ Pronto Aviation Services, El Paso TX	27.5.80 12.80/82
			Atorie Air Inc, El Paso TX Flying Fish Inc, El Paso TX	10.82/83 21.9.83/84
			G. W. Griffin, Reno NV	17.2.84/85
			Union Flights, Sacramento CA	2.8.85/89
			minor damage in ground collision with PA32 at LAX	21.12.87
			Michael C. Lauver, San Clemente CA	20.6.89/90
			Aeronautical Services Inc, Friday Harbour WA	10.90/95 90/95
			op: Catalina Flying Boats Inc, Long Beach CA Robert A. Younkin/ Younkin Air Service, Spingdale AR	18.9.97/98
		(N22YA)	ntu: Younkin Air Service: reg. reserved	10.1.98
		N911E ´	Southern Cross Aviation Inc, Lake Placid FL	1.4.98/99
			Beer & Morgan LLC, Warsaw IN	22.4.99
			Mark Hathaway/ C-Tiger Enterprises Ltd, Wilmington DE	
		(N369GB)	ntu: C Tiger Enterprises	12.99
		N911E	sale rep, Wilmington DE: USCR	17
			sale rep, Pasadena TX: struck-off USCR	1.6.18

N911E noted TF Green Airport, Providence RI 14.8.74;

N911E accident report 24.12.75: Tobey Inc, flight Windsor Locks CT to Boston, 5.13am;

N911E noted Palo Alto CA 11.3.84 Flying Fish Exclusive Charters;

N911E noted LAX 12.12.85 Union Flights;

N911E noted Sacramento-Executive CA 7.7.87;

accident report 21.12.87: op Union Flights, ground collision with PA32 N75397 at LAX, (See note at BA-312 re Catalina Flying Boats);

N911E noted Long Beach CA 7.91 at Catalina Flying Boats ramp;

N911E noted Long Beach CA 22.4.92;

N911E noted Long Beach CA 4.95;

N911E noted Springdale AR 8.97 "Catalina Flying Boats" titles, owned Bobby Younkin, plate BA-10 built 9.54;

N911E at flyin Lakeland FL 11.4.99 owned Southern Cross Aviation;

N911E noted Ft Lauderdale FL 4.4.01;

N911E noted Ft Lauderdale FL 11.8.05 in service;

BA-11 E18S	E18S	N3616B	built	.54	
			Union Producing Co, Shreveport LA	63/66	
			Mississippi School Supply Co, Jackson MS	69/70	
			Jim Hankins Air Service, Jackson MS	72	
			op: Flight Express Cargo, Essington PA	74	
			damaged mid-air collision with Bell 47G N54397 on		
		approach t	approach to Detroit MI	27.6.74	
			Flight Express Cargo, Essington PA	18.4.75/77	
			ditched due fuel exhaustion, Buckeye Lake OH	17.8.77	

accident report 27.6.74: Flight Express, flight Olive Branch MS to Bowling Green KY then Detroit, impact with Bell over Detroit city area, 11pm;
N3616B noted Detroit-City Airport MI 24.5.76;

accident report 17.8.77: flight Philadelphia to Columbus OH, fuel exhaustion 5.29am, 2 crew unhurt;

BA-12	E18S	N3610B	built	.54
		N206C	Castleton Inc, Detroit MI: USCR	63/66
		CF-OYT	reg	.62
			M. Loeb Ltd, Ottawa ONT	65/66

N702H	Midstate Airlines, Chicago IL	68
	op: Hub Airlines, Fort Wayne IN	69
	Marshfield Airways, Marshfield WI	69/70
	op: Midstate Commuter, Chicago IL	70
N310WA	Air Iowa	72/73
	structural failure of right spar, right wing folded in flight,	
	crashed destroyed, Davenport IA	19.4.73
N310WA	Air lowa structural failure of right spar, right wing folded in flight,	72/73

N206C USCR63: FAA inspection 10.62;

N702H noted Chicago-O'Hare 29.3.68 Midstate AL;

N310W accident report 19.4.73: Air Iowa, flight Muscatine IA to Chicago, spar crack

had not been detected in 6 years of inspections, 6k;

BA-13	E18S	N3617B	Atlantic Aviation Service	12.10.54
			Sun Oil Co, Philadelphia PA	10.54/55
		N30S	Sun Oil Co, Philadelphia PA	28.2.55/62
		N148G	Virginia Coal & Iron Co, Big Stone Gap VA	17.7.62/65
			Aircraft Owners Inc. Miami FL	14.9.65/67
			Harry H. Bassett	25.8.67/68
			Kentucky Fried Chicken of Florida, Miami FL	19.3.68/77
			Thomas E. Kirchner: sale documentation not completed	23.2.77
			sale reported, Audubon NJ: USCR	8.80/91

N148G noted Opa Locka FL 6.10.68 & 23.8.71;

BA-14	E18S	N3618B	Bobby Manziel, Tyler TX	63/72
			Walter Fuller Aircraft Sales	75
		C-GWSV	Millardair Ltd, Toronto ONT: delivered	9.2.75/93
			sold to USA, struck-off Canadian Register	28.4.93
		N118SA	reg. candidate	12.5.93
			reg.	1.94
			Steve Culbertson, Lakeport CA	28.4.97/02
			Jay A. Danford, Chico CA	7.6.04/05
			Marici P. Reid, San Jose CA, later Independence OR	06/20

C-GWSV noted Toronto 9.2.75, delivery date to Millardair;

C-GWSV noted Toronto 15.9.79 "Millardair" titles;

C-GWSV noted Toronto 9.81 full Millardair scheme & titles,

C-GWSV noted Toronto 10.86 Millardair;

C-GWSV noted Toronto 18.7.90 "Millardair" titles in service;

BA-14 noted Lakeport CA 10.96 under rebuild, being reskinned: plate BA-14 built 10.54;

N118SA noted Lakeport CA 12.9.01 smart colour scheme, plate BA-14;

N118SA visited Oshkosh 7.15, all metallic;

BA-15	E18S	HI-30	Porfirio Rubirosa, Dominican Embassy, Paris (name <i>Moineau Flier</i> above windows)	10.54/57
			Luciene Benitez Rexach, Ciudad Trujillo, DR	57
		N93V	reg	
		N93U	rereg	
	PacAero	N402T	G. C. Landry, East Troy WI	63/66
	Turbo		Eastern Aviation Corp, Baltimore MD	69
	Tradewind		Jack Wall Aircraft Sales, Memphis TN	70/72
			Export Airmotive Inc, Miami FL	19.1.72
			sold to Colombia, struck-off USCR	7.3.72
		HK-1419P	Transportes Aereos Nacionales - TANA, Bogota	3.72
		HK-1419	Transportes Aereos Nacionales - TANA, Bogota	74/76
			Aerolineas Especiales de Colombia Ltda - AE Colombia,	
			Bogota-El Dorado (retired at Medellin, Colombia 79/85,	77/84
			under maintenance Tucson AZ 87/90)	

HI-30 noted at Blackbushe 12.54 Dominican Embassy Paris, "Moineau Flier" above windows; HI-30 reported as a regular visitor to Heathrow during 1955: Dominican Embassy, Paris; HI-30 noted London Airport 9.2.55, 13.3.56 Dominican Embassy, Paris "Moineau Flier";

HI-30 noted Blackbushe 23.6.57;

HI-30 noted Prestwick 25.6.57 Dominican Embassy in Paris;
HK-1419 noted Bogota 29.9.72 TANA (note: TANA also quoted as Taxi Aereo Nacional)
HK-1419 noted San Andres, Colombia 2.78 "Aerolineas Especiales" titles
BA-15 noted Tucson AZ 10.87: rep as last production Hamilton-Liner
HK-1419 noted Tucson 4.6.80 AE Colombia colour scheme & titles (not rep. as trigear);
BA-15 noted Tucson AZ 31.5.90 no registration:

BA-16	E18S	N3642B	Roscoe Turner Aeronautical Corp	11.54
			Stokely-Van Camp Inc	11.54/60
			L. C. Cassidy & Son Inc	13.2.60/62
		N255DC	L. C. Cassidy & Son Inc	15.2.62
		N255D	Merchants National Bank, Indianapolis IN	28.9.62/68
			Clanton Air Carriers, Clanton AL	11.68/70
			Aircraft Acceptance Corp, Columbus OH	15.9.70/72
			Robert L. Smith	21.1.72/73
			C. O. Williams	31.7.73/74
			Associated Airways	14.2.74
			damaged forced landing, Atlanta-Fulton County GA (reported stored damaged Charle Brown GA 78)	17.4.74
			National Independent Insurance Co	74
			Hill Aircraft & Leasing Corp	10.74/75
			John R. Jackson	15.4.75/80
			Allen Fadel	25.2.80
			Palm Beach County Sheriff's Office FL: seized	10.80
			(forfeited from Michael McGovern along with D18S N90562/A-414)	
			Missionary Flights & Services Inc	12.80/83
			Air Cargo America Inc, Miami FL	7.6.83
			(arrived Miami 8.6.83 on delivery)	
			James R. Bell, Miami FL	12.83/89
			(cargo door & cockpit entrance door, both ex BA-120/N171LG, installed 6.84)	
			Aaron Pirani/ Mangalji Airways, Miami FL	3.11.89/96
			op: Eagle Wings, St. Lucia	90/96
			Eagle Air Charter, Miami FL	11.9.96/99
			South Florida Aircraft Leasing, Opa Locka FL	22.4.99/02
			Alan G. Foster, Anchorage AK	19.2.04/14
			struck-off USCR	22.9.14
	N255D no N255D no N255D no N255D no N255D no Opa Lock N255D no N255D no N255D no	oted Miami FL & Sted St. Lucia 2 Sted Opa Locka Sted Opa Locka Sted Opa Locka 1.97,11.4.97, Sted Opa Locka Sted Anchorage Sted Anchorage Sted ANC-Lake	22.3.87 Air Cargo America; Miami 11.87; 3.6.83 arrived on delivery to Air Cargo America; 90 "Eagle Wings", 9 FL 7.6.90, 9.90 & 2.12.90 all "Eagle Wings St Lucia" title 9 FL 30.4.95 Eagle Wings St Lucia" reportedly op. Expres 9 FL 1.96 faded "Eagle Wings St Lucia" titles, op. by Aard 9.97 faded "Eagle Wings St Lucia" titles, all metallic; 9 FL 4.4.01, all metallic, plate BA-16; 9 Lake Hood strip 17.4.04, airworthy; 9 Lake Hood strip 11.9.04, tailwheel, windows faired over, Hood strip 7.4.06 no windows, all metal finish, tailwheel; 6.6.13 all metal finish, control surfaces removed;	s Airways; on Pirani; in service
BA-17	E18S	N3621B	built	.54
			Manhattan Construction Co, Muskogee OK	63/66
			Winchester Development Co, San Jose CA	69/70
			crashed destroyed during forced landing off-airport	45 5 70
			near Joseph OR	15.5.70
	accident r	report 15.5.70: i	flight San Jose CA to Oxbow OR, complete engine power	r loss, 7k;
BA-18	E18S	N3602B	Currey Sanders Aircraft Co	8.11.54
			Carthage Co	8.11.54/56
			Hudson Gas & Oil Corp	1.9.56/63
			San Jacinto Petroleum Corn, Shrevenort I A	1.9.50/05

San Jacinto Petroleum Corp, Shreveport LA

Aircraftsmen Inc, Oklahoma City OK

15.1.63/64

27.4.64/70

	(Beech cargo door installed 4.68)	
	Engborg Leasing Corp	15.8.70/72
	Banner Flight Ltd	4.3.72/75
	(Hamilton cargo floor installed 7.74)	
	undercarriage collapsed landing, Toronto ONT	3.12.74
	Ridder Air Enterprises Inc, Whitman MA	5.3.75/83
	(cockpit crew door installed 5.75)	
	Crow Inc/ Crow Executive Air Charter, Millbury OH	26.8.83/89
	Central Business Brokers/ Gateway Air Service,	
	Mt Pleasant MI	29.3.89/90
N666AK	Gateway Air Services, Mt Pleasant MI	20.4.90/96
	Kenneth R. Phillips, Brackettville TX	16.7.98/99
	Beechnut Inc, Wilmington DE	19.9.01/05
	Kenneth R. Phillips, Brackettville TX	9.3.05/10
	William E. Signs, Dallas TX	2.10/12
N7BS	William E. Signs, Dallas TX	12/15
	Runyon Aviation, Fort Worth TX	1.9.15/20
	•	

N3602B noted Stewart NY 11.8.74;

N3602B accident report 3.12.74: gear collapsed due mechanical fault, 4.50am;

N666AK noted Mt Pleasant MI 10.96 Gateway AS; Claire MI 6.98;

N666AK noted Victoria TX 7.5.03;

Bill Signs purchased N666AK from Ken Phillips at Del Rio TX in January 2010, also Dumod Liner N445DM (AF-152). N666AK was retired and needed restoration: parts source was Ken Phillips' E18S N2083C stored damaged dismantled at Brackettville TX, plus parts from all over USA; N7BS restored and repainted visited Oshkosh 28.7.14 flown by Bill Signs; Oshkosh 7.15, 7.16;

BA-19	E18S	N3622B N712	reg rereg	
		N721D (2	Butler Drilling Co, Houston TX	15.2.63/65
		•	struck-off USCR	22.5.65

BA-19 has been reported as having first reg N700N but that was Beech G17S c/n B-19;

BA-20	E18S	CF-IOP	built	.54
		CF-HOP	Canadian Breweries Ltd	58
			Dominion Tar & Chemical Co, Montreal QUE	60/65
			Canadian Inspection & Testing Co Ltd, Montreal QUE	14.4.65/70
			(converted by Aircraft Industries of Canada, St Johns QU	ΙE
	AIC/Howard		to PT-6A-20s with Volpar Mk.IV trigear completed 2.67,	
	Jobmaster		marketed as Jobmaster Prop-Jet 18)	
	Prop-Jet 18		(AIC demos to RCAF 3.67 offering conversion program)	
	trigear		dam. landing lles aux Ruaux airstrip QUE	19.10.68
	· ·		Omni Aircraft Sales, Washington DC	9.12.70
			(ferry permit 12,70 St Jean QUE to Baltimore MD)	
		(N13173)	ntu: Omni Investment Corp, Washington DC	12.70
		N11AB	Omni Investment Corp/ Omni Aircraft Sales,	
			Washington DC	9.12.70
			Howard A. Weiss, Chicago IL	12.70/73
			(cargo floor installed 7.71, cockpit door 11.73)	
			Arkansas Aero Inc	25.7.73
			op: Sierra West Airlines, Oxnard CA	73
			Great Western Airlines, Tulsa OK	10.74/82
	Westwind III		(Volpar Mk.IV trigear replaced with original	
	long nose/		Beech tail gear & extended nose installed 10.74)	
	tailgear		Hamilton Aircraft Co, Tucson AZ	10.9.82/83
	-		(FAA report 4.89: aircraft salvaged for parts)	
			struck-off USCR	31.5.89

N11AB photo 5.71 trigear turbines, no titles;

N11AB noted Tucson AZ 20.9.74 inside Hamilton hangar under rebuild to Westwind with tailwheel, turbines being installed, Hamilton extended nose installed;

N11AB noted Pittsburgh PA 10.75, turbines, tailwheel, extended nose, no titles;

N11AB noted Wichita KS 6.6.76 Westwind;

BA-21	E18S	N3647B	built	.54
		N1234X	Pillsbury Mills	
		N1234G	Jen Mar Construction Co, Minneapolis MN	63/64
			National Music Service, Spokane WA	66
			C. W. Nuggent, Houston TX	69
			Vercoa Air Service/ Allegheny Commuter, Danville IL	70
			Combs Airways, Billings-Logan MT	70/72
			Burlington Airways/ Burl Air Freight, Burlington WI	30.4.66/79
			crashed destroyed on takeoff, Chicago-O'Hare IL	3.4.79
			3.4.79: Burlington Air Freight: flight Chicago to Indianapolice, destroyed, fire after impact 4.39am, pilot minor injuries	
BA-22	E18S	N3604B	J.F.Anderson Lumber Co, Minneapolis MN	4.12.61/63
			sold to Mexico, struck-off USCR	21.10.63
		N3604B	Great Lakes Aviation Corp, Chicago IL	69/70
			op: Great Lakes Airlines, Chicago IL	69/70
			crashed, destroyed by fire, forced landing New Carlisle	IN 10.12.70
	N3604B no: N3604B no:	ted Chicago-N	964 & 1966; D'Hare 11.3.69 Great Lakes Airlines; Midway IL 9.8.70 "Great Lakes Airlines: titles, tailwheel; Great Lakes Aviation, struck trees in forced landing due t	iuel expiry, 1k;
BA-23	E18S	N3620B	Atlantic Aviation Corp	24.11.54
	-9700		Merritt-Chapman & Scott Corp	11.54/60
			Shulton Inc	1.6.60/63
			Gopher Aviation, Rochester Airport MN	25.2.63/64
	trigear		(Volpar tricycle gear installed 5.63)	
	900		Hylan Flying Service, Rochester NY	3.8.64/83
			(Aerospace Products cargo door installed 2.82)	0.0.0 00
			Ray Hylan School of Aeronautics, Rochester NY	12.83/86
			Detor Properties Inc, Rochester NY	1.87
			Jerry L. Englund/ Englund Aviation, Mobile AL	19.2.87/91
			539561 Ontario Ltd ONT	27.12.91
			sold to Canada: struck-off USCR	15.4.92
	N3620B no	ted Youngsto	wn OH 12.1.83 Hylan Flying Service;	
BA-24	E18S	N3625B	R. L. Manning Co	14.9.55/58
			crashed, struck-off USCR	19.2.58
BA-25	E18S	N3650B	built	.55
D/ \ 20	L100	N127H	rereg	.00
		N127W	rereg	
		N1900W	rereg	
		N1900R	Belton Bagging Co, Belton SC	63/64
		11100011	S. W. Sisk/ Orion Airways, St Louis MO	68/69
			Sisk Aviation Activities Inc, St Louis MO	70
			op: Golden Eagle Aviation	.70
			Harry W. Wardell, Billings MT	72
			Van Dusen Acceptance Corp, Minneapolis MN	14.6.72/73
			op: Buckeye Air Service, Elyria OH	.72/73
			lost without trace en route Cleveland OH-Detroit MI	20.3.73
			isst minest tass on reals slovelend on Bottok in	20.0.70
BA-26	E18S	N3644B	built	.55
			K C Tractor & Implement Co, Springfield MO	63/66
			S. W. Sisk/ Orion Airways, St Louis MO	68/69
			Sisk Aviation Activities Inc., St Louis MO	70
			Skyway Aviation, Fort Leonardwood MO	71/73
			gear collapsed during landing with engine fire,	
			Fort Leonardwood MO	5.11.73
BA-27	E18S	OO-SUM	Union Miniere du Haut Katanga, Elizabethville	13.8.55/57
	-		struck-off Register	11.10.57
			<del>- U</del>	

F-BFDR Sud Aviation, Paris-Le Bourget 26.12.57/71
Air Continent, Cannes-Mandelieu 17.9.71/75
Aviasud, Nice 28.3.75/79
retired Nice: CofA expired 17.2.75
Nantes Aviation, Nantes 4.4.79
struck-off register 24.10.79

OO-SUM noted Blackbushe 6.9.55 & 3.9.56 visitor for Farnborough air show;

F-BFDR visited London-Heathrow 1.5.59 Sud Aviation; 21.1.60 Sud Aviation;

F-BFDR visited Bristol-Filton 27.4.60 Sud Aviation;

F-BFDR noted Gatwick 6.9.61 Sud Aviation, Farnborough visitor;

F-BFDR noted Paris-Orly 11.7.62; Hucknall 17.4.63 Sud Aviation; Bristol 22.11.63;

F-BFDR visited London-Gatwick 23.6.64, 8.9.64;

F-BFDR visited Bristol-Filton 3.10.64;

F-BFDR visited Filton 11.1.65, flew Filton-Tolouse 12.1.65; flew Filton-Le Bourget 3.2.65;

F-BFDR overflew London 23.3.65; noted Filton 9.9.65 & 10.5.66,

F-BFDR visited London-Heathrow 25.1.67;

F-BFDR visited Dublin 15.4.67 rep op by Escadrille Mercure, visiting for football match;

F-BFDR visited Yeadon 25.4.67 rep as Sud Aviation;

F-BFDR noted Paris-Le Bourget 1.6.67;

F-BFDR visited Heathrow 18.1.68 Sud Aviation;

F-BFDR visited Heathrow 18.1.68 owner reported as Sud Aviation;

F-BFDR visited London-Heathrow 21.5.68; Le Bourget 27.12.68;

F-BFDR visited Bournemouth-Hurn 26.2.70;

F-BFDR visited London-Gatwick 6.1.72;

F-BFDR noted Toussus c6.73, Air Continent, visitor;

BA-28	E18S	N3626B	Ohio Aviation Co, Dayton OH	6.12.54/55
			White Motor Co, Cleveland OH	13.7.55/60
			Donges Aircraft Sales	25.1.60/61
			Cleveland Hangars Inc, Cleveland-Hopkins OH	21.3.61/62
			Robert Gore	11.62/63
			Appliance Buyers Credit Corp, St Joseph MO	64
			Bernard Little/ Angels Inc	10.1.64
		N18T (1	Addison Products Co, Addison TX	22.2.64
		N3626B	Addison Products Co, Addison TX	11.64/65
			Airline Management Corp, Chicago IL	12.4.65/67
			Executive Airlines	14.8.67/68
			Horizon Aviation Enterprises Inc, Chicago IL	12.68/71
			American Turbine Aircraft Co, Long Beach CA	71
			Aircraft Rebuilders Inc, Long Beach CA	19.5.71/73
			Volpar Inc, Van Nuys CA	6.7.73/74
	Volpar		(converted to Volpar Turboliner II: tricycle gear,	
	Turboliner II		AiResearch TPE331 turbines, 81.5 inch fuselage	
			extension, completed 28.3.74)	
		N700WA	William E. Winship/ Winship Air Service, Anchorage AK	11.2.74/82
			op: Troy Air Inc, Anchorage AK	79/82
			Troy Air Inc, Anchorage AK	11.82/90
			Connie Kalitta Services, Willow Run MI	30.5.90
			American International Airways, Willow Run MI	10.90/92
			Connie Kalitta Service, Willow Run MI	1.1.92
			Kalitta Flying Service, Willow Run MI	11.92/99
			op: FS Air Service, Anchorage AK	94/96
			gear collapsed after landing, Van Curler mine strip,	
			Chena Hot Springs via Fairbanks AK	6.7.96
			Kitty Hawk Charters Inc, Morristown TN	15.6.99
			stripped for parts .99, struck-off USCR	30.11.99
			(stripped hulk on belly still near mine strip 6.04)	

N700WA noted Anchorage 3.7.76, 1.9.76;

N700WA noted Anchorage 13.9.79 & 6.9.81: both "Troy Air" titles, "Volpar Turbo Liner" small titles:

N700WA noted Anchorage 27.5.90 Turboliner, no titles;

N700WA noted Anchorage AK 8.94 Turboliner, op. FS Air Services;

accident report 6.7.96: badly damaged, ran off gravel runway landing Fairbanks-Van Curler's Bar, operator FS Air Service, Garrett TPE-331turbines;

photo 13.6.04 on belly near mine strip, completely stripped: red & white;

BA-29	E18S	N3627B	Beech Aircraft Corp, Wichita KS	12.54/55
			Capitol Air Sales Inc	28.4.55
			Super Service Motor Freight Co	28.4.55/58
			Bowman Transportation Inc, East Gadsden AL	6.3.58/66
			Air Journeys Inc, Little Rock AR	3.1.67
			John W. Pennington	28.6.67
			Stella Aircraft Investment Co, Santee CA	15.2.68/69
			Florida Airmotive Inc, Lantana-Palm Beach FL	23.4.69/70
		N333FL	Florida Airmotive Inc, Lantana-Palm Beach FL	21.8.70
			Frank E. Fairchild/ F.E.F. Enterprises Inc,	
			Port Washington NY	1.11.70/76
			Ronald L. Simmons & Richard B. Neff	17.9.76/77
			Robert L. Johnson, Louisville KY	19.4.77/78
			Blackhawk Airways, Janesville WI	12.78/80
			(cargo floor & door, cockpit hatch installed 8.79)	
			International Trade & Investments, Orem UT	28.5.80/91
			crashed on takeoff off icy runway, Candle AK (wreck stored dism. Fairbanks Airport 90)	3.10.80
			Chenna Marina, Fairbanks AK: wreck	06

N333FL accident report 3.10.80: no operator quoted, pax flight Candle to Kotzebue AK, unable to get airborne ran into brush at end of runway, pilot & 4 pax unhurt; N333FL fuselage noted Fairbanks AK 25.5.90;

BA-30	E18S	N3646B	Atlantic Aviation Corp	29.12.54
			New York Wire Cloth Co	12.54/56
			Lee Wilson Engineering Co, Cleveland OH (visited Africa & UK, via Prestwick 8.8.60)	12.56/73
			mid-air collision with PA-23 N4165P, emergency landing	,
			Fremont OH	31.8.66
			(E18S cabin roof torn open & tail badly damaged)	
			Air Best de Puerto Rico, San Juan, Puerto Rico	8.73/81
			retired derelict, San Juan, Puerto Rico	78/79
			Julio F. Morales: \$1000 at auction	30.6.81/82
			Jorge A. Toledo, Villa Andalucia, Puerto Rico	18.6.82/83
			Julio A. Colon, St Croix, US Virgin Islands	24.8.83/91

N3646B arrived Prestwick 8.8.60 ex Keflavik, to Cardiff-Rhoose, Lee Wilson, Cleveland OH; N3646B arrived Heathrow 11.8.60 from Rhoose, Lee Wilson, departed 13.8.60 to Paris; N3646B visited Dakar, Senegal 4.10.60 to Natal, Lee Wilson Co;

N3646B noted Heathrow 27.9.60 Lee Wilson;

N3646B photo 8.66 after midair collision: roof & tail wrecked. "Lee Wilson Engineering Co" logo and titles: see Beech 18 by Parmerter p.286, 287;

N3646B noted San Juan PR 30.12.79 Air Best de PR, retired;

BA-31	E18S	N80008	Tulsair Distributors Inc	12.54/55
			Williams Brothers Co	11.55/56
		N108WB	Williams Brothers Co	10.56/57
		YV-P-EPC	Williams Brothers Sudamericana Ltd	2.57/58
		N107WB	Williams Brothers Co	11.4.58/62
		N475AB	Arkansas Best Fast Freight System, Fort Smith AR	8.11.62/64
			Central Plains Enterprises Inc, Tulsa OK	5.1.65/69
		N13JC	Jaqueline Cochran, Indio CA	12.3.69/71
		N333MG	Merv Griffin/ Anthony Productions Inc, Hollywood CA	29.4.71/78
			James H. Bond/ Bond Operating Co, Las Vegas NV	15.2.79
		N444GR	James H. Bond/ Gemini Resources, Las Vegas NV	1.7.79/83
			US Customs Service CA: seized	7.83/85
			Tarrant County Junior College,	
			Fort Worth-Meacham Field TX	3.10.85/12
			(instructional airframe: donated by USCS)	
		N13JC	Tarrant County College, Ft Worth-Meacham Field TX	27.9.12/19
			(rest. to airworthy by Tarrant County College Aviation	
			Department: rereg. in honour of aviatrix Jacki Cohran)	
			Vintage Flying Museum, Fort Worth TX	30.9.19.20

N333MG noted Long Beach CA 8.6.71 tailwheel; N444GR noted Ft Worth-Meacham TX 30.3.87, 10.87 in technical school grounds; N444GR noted Tarrant County Junior College 9.5.03 at Meacham Field & 12.8.03, plate BA-31 built 12.54;

BA-32	E18S	N3651B	J. R. Gray Co, Dallas TX	23.12.54
DA-32	_100	1400010	H. L. Brown	17.1.55/62
	E18S-9800		Fort Worth National Bank, Fort Worth TX	17.4.62/66
		N22T (1	Fort Worth National Bank, Fort Worth TX	8.1.66
		`	O. P. Leonard, Fort Worth TX	9.6.66/71
			The Windy Co, Fort Worth TX	19.4.71/72
			Roy A. Rogers	12.72/74
			Ginners Aviation	10.74/77
			Deanie Montgomery, Coriscana TX	3.5.77/79
			Southern Aero Traders, Miami FL	8.1.80/83
		(N205Z)	ntu: Southern Aero Traders. Miami FL	3.80
		N205A	House of Sesame Inc, Miami FL	16.2.83/89
			(noted impounded Boscobal, Jamaica 12.83)	
			Ben R. Bradley/ Ben Air Ltd, Frostproof FL	1.9.89/90
			Valentine Aviation, Pompano Beach FL	2.90
		N929DV	Valentine Aviation, Fort Lauderdale FL	6.90/91
			(fitted wings removed from N68V BA-282 c86)	
			Ben Air Ltd, Frostproof FL	.91
			Billy J. Wallace, Evergreen CO	2.10.91/92
			Styles Aviation, Lagrangeville NY	1.94
			Rand W. Siegfried, Palo Alto CA	7.3.94/20

N205A noted Fort Worth-Meacham Field TX 1.5.73;

N205A noted Opa Locka FL 18.7.81;

N205A noted Boscobal, Jamaica 12.83;

N929DV at Beech Flyin Tullahoma TN 10.94, 13.10.95;

N929DV noted Richards-Gebaur AFB near Kansas City MO 7.97: plate BA-32 built 12.54;

N929DV at Oshkosh WI 7.96 won classic award. Rand Siegried;

N929DV based Edwards AFB CA for period in 97 for evaluation by USAF Test Pilot School;

N929DV at flyin Lakeland FL 7.4.97;

N929DV at Oshkosh WI 8.97; Wichita KS 9.10.97;

N929DV visited Beech FlyIn Wichita KS 11.10.97;

N929DV at Oshkosh 1.8.98 Rand Siegfried, Palo Alto CA, plate BA-32 built 12.54, plate: conv. to -9800 4.62;

N929DV at Oshkosh 30.7.00 Rand Siegfried;

N929DV at Beech FlyIn, Tullahoma TN 18.10.00;

N929DV noted Janesville WI 10.8.02;

N929DV at Beech flyin Tullahoma TN 16.10.02;

N929DV at Oshkosh 30.7.03 Rand Siegfried; at Oshkosh 31.7.04, 7.05, 7.06;

N929DV at Beech flyin Tullahoma TN 14.10.07; at Oshkosh 25.7.08 Rand Siegfried;

N929DV at Oshkosh 28.7.14 Rand Siegfried; Oshkosh 7.15, 7.16;

BA-33	E18S	N3648B N45CM	Fort Worth National Bank, Fort Worth TX rereg	63
		N49UC	Union Bag Camp Paper Corp, New York NY	63
		N499C	Wimbish Aviation, Greensboro NC	69/70
			John L. Wesley, Niles MI	72
			Stockert Flying Service, South Bend IN	20.7.77/82
			struck-off USCR	.82
BA-34	E18S	N3628B	Gopher Aviation, Rochester Airport MN	30.12.54
	-9700		Beloit Iron Works, West Orange NJ	12.54/68
			Earl W. Fugate, Janesville WI	10.68/70
			Russell L. Ingram	10.70/71
		Pullman Bank & Trust Co, Chicago IL	12.2.71/72	
			Robert L. Mishler/ Four Winds Aviation	10.1.72/73
			Air Best de Puerto Rico Inc, San Juan, Puerto Rico crashed forced landing on highway due weather,	11.5.73
			San Juan, Puerto Rico Banco Commercial de Mayaguez:	13.11.73
			derelict San Juan-Isla Grade Puerto Rico	79

70USCR quotes owner Pullman Bank & Trust! N3628B accident report 13.11.73: Air Best de PR, flight St Thomas-San Juan, continued VFR flight into adverse weather, refused SPC VFR by ATC, did not divert, pilot & 10 pax minor injuries;

	, , , , , , , , , , , , , , , ,		,	
BA-35	photo 01: N	203C derelict	Mountain States Aviation Colorado Oil & Gas Corp, Houston TX Colorado Oil & Gas Corp, Houston TX R. C. Hitchcock & Sons/ Hitchcock Industries, Minneapolis MN Carl V. Hass/ Kingston Enterprises Inc Torry Service Distributors Inc Nevada Pacific Airlines, Las Vegas NV gear collapsed landing, Grand Canyon AZ Aircraft Associates ARL Flying Service Ruiz Fernando O'Brien George B. Carlton, El Paso TX (FAA report 1.81: Carlton gave false address) stripped airframe at Globe-San Carlos Apache AZ	6.1.55 6.1.55/58 26.6.58/64 7.5.64/72 11.7.72/73 17.9.73/75 9.4.75/79 24.8.75 11.1.79 5.79/81 12.1.81 24.1.81/91
	N203C note	ed Globe AZ a	irfield 12.17 stripped hulk;	
BA-36	E18S	N3333C	Metallurgical Inc, Minneapolis MN General United Leasing Corp, Bettendorf IA registration pending: USCR crashed destroyed by fire, Delavan WI after takeoff from Lake Lawn Strip WI	63/64 66/69 70 25.7.70
BA-37	E18S	N3456B (2	reg	
		N117S	rereg	
	trigear	N274TW N403FW	Transwestern Pipeline Co, Houston TX Rolair Corp/ Wright Air Lines, Cleveland OH damaged in ground collision with parked Beech Bonanza N3421B, Cleveland-Burke Lakefront OH Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA	63/63 9.7.66/70 27.9.67 70 3.2.70
	accident rep	oort 3.2.70: Sh	/right Airlines, commuter air carier; nenandoah Air, flight Washington DCA to Weyers Cave VA, during landing approach;	
BA-38	E18S	N3702B	Wings Inc	26.1.55
		N700R	Dexter D. Coffin/ C. H. Dexter & Sons C. H. Dexter & Sons Atlantic Aviation Corp Consolidated Aircraft Repair Inc, Fort Wayne IN Comfo-Air Corp, Wakarusa IN Skystream Inc, Plymouth IN Frank A. Hill	17.5.55 1.12.58/60 1.3.60/61 12.61/68 29.1.68/71 72 12.71/73
		N10PK	Frank A. Hill John S. Glitsky/ Airplane Leasing Inc James A. Price, Fort Lauderdale FL Sun Air Services Ltd, Bahamas Lucaya Beach Air Services Ltd, Bahamas Kym Pitts: sale documentation not completed sale reported, Freeport, Bahamas: USCR	11.73/74 12.7.74/81 21.9.81/84 11.84/87 20.2.87 9.9.87
BA-39	E18S	N42CS	Southern Airways Co Colonial Stores Inc Southern Airways Co	25.1.55 26.1.55/59 16.7.59

N144NK	American Enka Corp/Enka Foundation, Enka NC	19.1.60/71
N144NB	Asheville Flying Service, Asheville NC	9.7.71/86
	O. D. Griffin, Asheville NC	23.9.86/88
	Eagle Neck Aviation, Townsend GA	1.9.88/90
	Bradley Flying Service, Wethersfield CT	22.6.90/91
	Sacramento Aviation, Sacramento CA	12.2.91
	F1 Systems Inc, Bandon OR	5.93/94
	Wiley C. Sanders, Troy Al	1.4.94/20

N144NB noted Oshkosh WI 27.7.89, plate BA-39; N144NB noted Troy AL 7.97; N144NB noted Troy AL 13.8.98, plate: BA-39 built 1.55 owner Wiley Sanders;

BA-40	E18S	N3704B	Atlantic Aviation Service	2.2.55
		N83CP (1	Atlantic Aviation Service	11.55/56
		N83Q	Linden Flight Service	24.9.56
			Cornell Dubilier Electric Corp	12.56/59
			Airfactors Corp	15.9.59/60
			Wiles-Holloway Inc, Baton Rouge LA	29.6.60/61
			H. O. Montag/ American Air Lease, The Dalles OR	27.3.61/65
			Cummins Oregon Diesel Inc, Portland OR	11.2.65/69
			Flightcraft Inc, Portland OR	69
			Midstate Aviation, Ellensburg WA	28.5.69/74
			Roger E. Hirst/ Pacific West Transportation/ Sintak Inc	5.5.74/81
			Eagle Aero Services, Carson City NV	10.81/82
			Victor L. Hawkins, Carmichael CA	2.8.82/14
			struck-off USCR	19.11.14
BA-41	E18S	N3705B	J. D. Reed Co, Houston TX	7.2.55/56
			Bridwell Oil Co	13.7.56/57
			G. L. Rowsey	26.7.57/59
			Moss-Gordin Lint Cleaner Co	4.6.59/61
		N75140	Moss-Gordin Lint Cleaner Co	22.3.61/64
			Botany Industries Inc, Dallas TX	63/64
			Continental Gin Co, Dallas TX	22.9.64/70
			Ralph E. Smelser, Memphis TN	20.5.70/72
			Seminole Flying Service	17.8.72/73
			Jack L. Rhoades/ Rhoades Aviation, Columbus IN	11.73/78
			(cargo floor installed 5.74, cockpit door 2.78)	
		N138JR	Rhoades Aviation/ Rhoades International Inc,	
			Seymour IN	31.8.78/88
			Centre Airlines, Centre Hall PA	3.4.88/89
			crashed into house after takeoff, destroyed,	
			Baltimore-Washington International MD	19.7.89
		N138JJ	Centre Airlines, Centre Hall PA: USCR	20.7.89/90
			struck-off USCR	18.6.90

N138JR accident report 19.7.89: fire in cockpit after takeoff, crashed into house while attempting to return for landing, Centre Airlines;

BA-42	E18S	N3706B	Atlantic Aviation Corp	2.2.55
			Coats & Clarks Operations Inc	10.2.55/57
		N380	Coats & Clarks Operations Inc	10.9.57/60
			Richardson Homes Corp, Elkhart IN	21.9.60/66
			Ohio Aviation Co, Dayton OH	10.3.66/68
			Abrams Aerial Survey Corp, Lansing MI	11.7.68/78
			(conv. for aerial photographic survey 12.68)	
			Jeffrey J. Welch/ J & J Enterprises	11.78/80
			Stanrich Aviation	29.1.80/90
			op: Eighth Air Cargo	81
			Centre Air Inc, Greenville SC	18.3.90
			Thomas A. Faulkner, Ooltewah TN	12.4.91/14
			Southern Cross Aviation Inc, Wilmington DE	1.10.15/16
			Tessos Air Service, Wilmington DE	23.2.17/20
			reg pending, Peachtree City GA	21/22

N380 noted Oshawa ONT 10.5.79 Abrams Aerial Survey;

N380 noted Stewart NY 16.1.81 Eight Air Cargo, operating for Emery;

N380 noted La Guardia NY 11.8.81 Eighth Air Cargo;

N380 at flyin Lakeland FL 8.4.97;

N380 at Beech flyin Tullahoma TN 18.10.98 tailwheel, Pete Faulkner, Ooltawah TN;

N380 at Beech FlyIn, Tullahoma TN 18.10.00;

N380 visited Sun-n-Fun, Lakeland FL 3.18;

N380 visited Beech fly-in, Tullahoma TN 16.10.21;

BA-43	E18S	N3703B	Currey Sanders Aircraft Co	31.1.55
			Lufkin Foundry & Machine Co	5.3.55
			Southland Paper Mills Inc, Lufkin TX	24.6.55/63
			Malone Freight Lines, Birmingham AL	12.7.63/64
		N282M (1	Malone Freight Lines, Birmingham AL	29.6.64/68
		`	Albany Air Service, Albany GA	11.9.68/70
		N711DN	Robert Nelson/Air Transportation Co	19.4.70
			Sherno Research Centre Inc, Cresco PA	12.70/72
			Robert W. Trainer & J. William Bohmier	18.1.72
			Hamilton Aircraft Co, Tucson AZ	28.8.72
			SMB Stage Line Inc, Des Moines IA	12.72/88
	Hamilton		(conversion to Hamilton Westwind III, PT-6A-20 turbing	es,
	Westwind III		completed by Hamilton Aircraft Co 9.3.73)	
			Shark Aviation	11.88/89
			Aero Tech, Molalla OR	28.9.89/90
			Lawrence E. Hill/ Para Drop, Coolidge AZ	29.5.90/93
			Para Drop, Las Vegas NV	3.92/93
			damaged in groundloop on takeoff, Eloy AZ	15.4.92
			K & K Aircraft Inc. Bridgewater VA	2.2.93/11
			(stored dismantled Bridgewater VA 99, spares use)	
			struck-off USCR	4.8.11

N711DN noted Syracuse NY 23.6.77 "SMB Stage Lines" titles, Westwind III tailwheel; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" Westwind turboprop; N711DN fuselage noted Bridgewater VA 11.8.99 "Skydive" titles in K&K storage shed;

BA-44	E18S	N3710B	Ohio Aviation Co, Dayton OH	28.7.55
			North American Van Lines Inc	28.7.55/59
			Westcot Inc/ Calcot Ltd, Bakersfield CA	31.7.59/76
			Polestar Inc, San Diego CA	11.76/84
			Air Machines & Service Inc, St James MO	14.8.84/85
			(Aerospace Products cockpit hatch installed 10.84,	
		Aerospace Products cargo door installed 7.85)		
		Hoganair Inc, Hamilton OH	22.7.85/90	
			Jim West/ Sky-Dive Green County Inc, Xenia OH	2.4.90/02
			Parawings LLC, Frankfort KY	18.2.04/06
			Endless Mountain Skydivers Inc, Dalton PA	23.4.07/20

N3710B noted Burbank CA 12.8.84 Polestar Inc; N3710B noted Green County OH 6.8.99 Skydive, being flown by owner Jim West, titles "Sky Dive The Legend, Xenia OH";

BA-48	5 E18S	N3709B	J. R. Gray Co, Dallas TX	31.1.55	
	-9700	N62T	Frank Wood Associates Inc	8.2.55	
			Texas Pacific Coal & Oil Co, Fort Worth TX	2.5.55/64	
		N62TP	Texas Pacific Oil Co, Dallas TX	10.64/69	
			Lamb Rental Tools Inc, Lafayette LA	28.4.69/73	
			Festus Flying Service, Festus MO	25.2.73/74	
			Telles Inc	22.5.74	
		(N62TS)	ntu: Telles Inc	8.74	
		N62TP	Southern National Leasing Corp, Charlotte NC	12.75/81	
			(Aerospace Products cargo door & floor		
			installed 12.75)		
			op: General Aviation Inc, Greenville TN	79	
			op: Mountain Air Cargo, Denver NC	80	
			ground collision with Cessna 421, Norfolk VA	22.12.80	
			-		

Equipment Leasing Corp of SC, Greenville SC	10.2.81/82
lsd: Mountain Air Cargo, Denver NC	11.2.81/85
Coastal States Aviation, Denver NC	24.3.85
Lafayette Aviation, Pontiac MI	25.3.85/88
John R. Fick/ Freight West Airways, Eagle River AK	1.6.88/95
Ryan Air Service, Anchorage AK	15.3.95
Arctic Transportation Services, Anchorage AK	15.3.95/99
Catalina Flying Boats, Long Beach CA	10.2.00/02
dismantled at Long Beach CA due corrosion	3.01
struck-off USCR	22.4.03
Mark Thomson/ Aviation Warehouse, El Mirage CA (on truck at El Mirage 8.04)	04

N62TP accident report 22.12.80: Mountain Air Cargo, taxying for flight to Baltimore MD,

6.45pm, struck C421 in dark run-up area; N62TP noted Anchorage-Merrill Field AK 27.5.90, 5.5.91: both "Freight West Airways", nose wheel; N62TP noted Long Beach CA 17.8.99 parked, at Catalina Flying Boats ramp, stripped of parts;

N62TP noted Long Beach CA 10.3.01 broken up due corrosion; N62TP noted Long Beach CA 13.8.02 fuselage standing on gear;

BA-46	E18S	N3715B	Gerald C. Francis/ Francis Aviation, Lansing MI	2.55
		N52D	Arthur V. Davis	23.3.55/56
		N95C	New York Belting & Packing Co	6.6.56/57
			Broyhill Furniture Factories, Lenoir NC	11.5.57/67
		N561S	Pinellas Aircraft Inc, St Petersburg FL	29.5.67
			Goldways Inc, Winter Park FL	10.67/69
			Nevada Aviation, Las Vegas NV	12.69/71
			Bruce K. Battleson, Santa Ana CA	8.10.71/76
			William M. Meyers	1.12.76/77
			damaged parachute jumper struck tailplane, Chino CA	30.4.77
			Richard V. Gerdau, Los Angeles CA	4.6.77/84
			Air Machines & Services Inc	15.2.84
			op: St Louis Flight System Inc	84
			crashed after takeoff, Marion IL	11.5.84
			Central Air Parts Inc, Staunton IL	7.7.84
			struck-off USCR	.84
		N561S	Central Air Parts Inc, Staunton IL: rest. to USCR	2.92/95
			sale reported, House Springs MO: USCR	98/12
			struck-off USCR	24.9.12

N561S noted Orange County CA 13.4.72, 22.5.73; N561S noted Rubidoux-Flabob CA 2.9.81 blue & white, tailwheel, named The Yukon Jack:

BA-47	E18S	N3716B	Ohio Aviation Co, Dayton OH	9.2.55
			Airgo Inc	9.2.55/58
		N250RP	Rea Magnet Wire Co, Fort Wayne IN	10.58/67
			R. L. Taege & Associates Inc, Barrington IL	2.5.67/73
			Bennett C. Pollard/ Central Air Charter/	
			Midnight Air Express	2.2.73/77
			damaged struck unlit tug while taxying after landing	
		at night, Chicago-O'Hare IL	7.6.73	
			Stuart E. Aegler	10.6.77/78
			Joseph Kubick, North Jackson OH	10.2.78
			Southern National Leasing Corp, Charlotte NC	22.6.78/83
			op: General Aviation Inc, Greenville TN	80
			op: Mountain Air Cargo, Denver NC	81/83
			Mountain Air Cargo, Denver NC	12.83/85
			Equipment Leasing Corp, Greenville SC	3.84
			J. Richard Wixom/ Blackhawk Airways, Janesville WI	20.3.85/91
			Methow Aviation, Everett WA	2.10.91/95
			crashed into mountain, near Butte MT	26.1.95

N250RP accident report 7.6.73: Central Air Charter: midnight, pilot unhurt;

BA-48	E18S	N3719B	J. D. Reed Co, Houston TX Union Producing Co, Shreveport LA Sidney K. Herold & Henry E. Linam S. W. Sisk/ Orion Airways, St Louis MO Maplewood Bank & Trust Co: repossessed Sisk Aviation Activities Inc, St Louis MO Hattiesburg Aviation, Hattiesburg MS (Beech cargo door installed 8.76) Roy E. Ray Airport Inc: documentation not completed struck-off USCR	22.4.55/58 17.3.58/67 26.6.67/68 30.8.68/69 3.11.69/70 14.1.70/74 27.7.74/81 21.5.81 10.81
	N3719B no	oted St Louis-L	Downtown MO 1.6.76;	
BA-49	E18S	N3721B	built Helms Express Inc, Pittsburgh PA Quarnstrom Land Co, Detroit MI crashed destroyed on takeoff, Charlevoix MI	.55 63 19.9.63/66 25.9.66
			erash date 15.5.73: not correct; .9.66 struck embankment on takeoff, destroyed, 2k;	
BA-50	E18S	JA5014	Yomiuri Shimbunsha Newspaper, Tokyo (delivered across Pacific by Fleetaway) Maritime Safety Agency "The Yomiuri" retired, broken-up 21.12.73: struck-off Register	5.55/60 70 27.12.72
BA-51	E18S	N3769B	Union Lumber Co, Fort Bragg CA Victory Assembly of God, Beaumont TX Red Val Industries, Garland AR	63/69 70 72
		N777AF	Jack Counts, Dallas TX op: Horizon Cargo Transport Inc, Honolulu HI renamed: Kahila Airlines, Honolulu HI damaged landing Lanai HI (repaired) op: Island Airlines Hawaii, Honolulu HI (retired, stripped Honolulu HI 81/83) struck-off USCR	22.2.78/85 79 .79 29.5.80 81 27.6.85
	N777AF no N777AF no	ted Honolulu	23.8.81 engineless "Horizon";	
BA-52	E18S -9700	N3723B	J. D. Reed Co, Houston TX Wyatt C. Hedrick J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN	11.3.55 12.3.55/56 13.9.56/57 23.1.57/62 15.3.60
	trigear	N137AJ	Al Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by Gopher Aviation, Rochester Airport MN) Twin Cities Aviation, Minneapolis MN Pemton Inc, Minneapolis MN	18.6.62/69 10.69/70 6.4.70/71
		N1FC N1FN	Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Northern Airmotive Inc Allen W. Mobey/ 18 Inc/ Airmergency Inc/ MPC Inc, St Paul MN Exec-u-air Inc Jack D. Sloan K & K Aircraft Inc, Bridgewater VA retired, broken-up for parts struck-off USCR	25.6.71/72 2.72/73 7.2.73 2.3.73/78 30.6.78 7.11.78/79 .79/88 4.4.88
BA-53	E18S	N3727B	Roscoe Turner Aeronautical Corp Cape Hosiery Inc Wayne Knitting Mills	7.6.55 7.6.55 6.7.55

JATO	N92WK	Wayne Knitting Mills (Beech JATO jet assisted takeoff kit fitted 12.60)	11.4.56/62
0,110	N92W	Little Rock Road Machinery Co, Little Rock AR	31.5.62/67
	N924W	Kenneth Starnes Aviation Service	17.4.67
		W. G. Thomas	21.9.67/68
		Walter Miller & Dan Auclair Associates, Waco TX	30.8.68/70
		(cabin furnishings removed to carry mail 10.68,	
		convertable pax/cargo interior installed 2.70)	
		S I Industries Inc	11.70/71
		op: Miller Aircraft Inc, Waco TX	71
		Freedom Airlines, Buffalo NY	26.7.71/73
		Gilley Airways Corp, Fulton NY	11.4.73/77
		landed gear-up, Syracuse-Hancock NY	11.11.74
		Aero American Aviation	26.10.77
		Robert Z. Blue, Mount Prospect IL	12.77/78
		Trujillo-Ramirez Investment Co	10.78/79
		Henry Oliver III, Santa Fe NM	7.5.79/83
		(FAA report 11.82: aircraft destroyed or scrapped)	
		struck-off USCR	26.3.83

N924W noted Rochester NY 3.11.73 Gilley Airways; N924W noted Syracuse NY 27.8.74 Gilley Airways; N924W accident report 11.11.74: Gilley AW, failed to extend gear 6.29pm, pilot unhurt;

BA-54	E18S	N700W	Roscoe Turner Aeronautical Corp	9.3.55
			Inland Container Corp	9.3.55/61
			Beverly Agency Inc, Chicago IL: USCR	63
			Modern Welding Co, Owensboro KY	9.2.62/73
			SMB Stage Line Inc, Des Moines IA	27.8.73/81
		Jason C. Springer, Dallas TX Federated Air Freight Corp, Medford OR	21.7.81	
			Federated Air Freight Corp, Medford OR	29.9.81/82
			crashed on takeoff from clearing, landing gear	
			struck concrete cattle trough, San Miguel Ranch,	
			Charlotte TX	8.3.82
		(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX:		
			(hulk noted stored in their yard with DC-3s 10.97)	

N700W noted Ottumwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; reported still in service with SMB Stage Line 81; N700W hulk stored in Tradewinds Aircraft Salvage yard 8.09;

3A-55	E18S	N4641A	Gopher Aviation, Rochester Airport MN	10.3.55
	-9700		Alexander Construction Co	10.3.55/58
			Arthur W. Mall	23.7.58/59
			King-Stevenson Oil Co	21.7.59/62
			Alsam Inc, Youngstown OH	23.3.62/63
			Mark Aero Inc, St Louis MO	12.63/64
			Carmen Di Orio, Philadelphia PA	28.5.64/66
			James B. Kelly/ Speedbird Aircraft Corp	27.4.66/68
			(mods installed for aerial survey 1.68)	
			Albany Air Service, Albany GA	12.68/70
			landed gear locked-up, Albany GA	25.8.69
			Central Flying Service, Little Rock AR	7.4.70/79
			(converted to all-cargo configuration 4.70)	
			Catalina Air Freight	20.3.79
			(Aerospace Products cargo door installed 9.79)	
			Newton B. Collinson & Richard T. Farrell	12.79/82
			Paul Milam	29.1.82/83
			Mid-South Operations Inc, Fayetteville AR	4.5.83/88
			op: Richards Aviation, Memphis TN	84
			M. Corley Tedder, Texarkana TX	2.8.88/99
			op: May Air Xpress, Texarkana TX	97/98
			Air Calypso, San Juan, Puerto Rico	22.9.99/00
		N749T	MBD Corp, San Juan, Puerto Rico	31.7.00/06
			gear collapse landing Virgin Gorda USVI (repaired)	13.4.05

accident report 25.8.69: Albany Air Service, gear jammed by mechanical failure, 4.30am;

N4641A noted Dallas-FTW 12.93, at cargo terminal;

N4641A noted Dallas-FTW 26.4.95, 9.95;

N4641A noted Texarkana AR 8.97 May Air Xpress: plate BA-55 built 2.55;

noted Texarkana AR 6.8.98 rep operated by May Air Xpress;

N749T noted San Juan PR 15.1.03 all metallic no titles, tailwheel, flying;

N749T noted San Juan PR 26.2.06 all metallic freighter, tailwheel, in service;

N749T noted St Thomas 1.2.08 all silver, no windows, appears in service;

	E18S	N3737B	Flightcraft Inc	17.3.55
BA-56	-9700	NOIOIB	Weyerhaeuser Timber Co	17.3.55 17.3.55/57
	-9700		(right wing replaced 9.57 due accident damage)	17.5.55/57
			Freeway Equipment Co	28.9.57/62
			Union Oil Co of California, Los Angeles CA	1.10.62/63
		N1776U	Union Oil Co of California, Los Angeles CA	8.1.63/74
	trigear		(Volpar Mk.IV trigear installed 2.63)	
	Ü	N54BT	Brown Tool & Supply Co	6.4.74/75
			Piper Corporate Aircraft Southeast	11.75/76
			James Noel Flying Service	11.76/77
			Alroco Services Inc	11.76/78
			Edward W. Strotman/ Strotman Aviation	12.5.78/81
			Ronald W. Smith/ Smithair, Sharpsburg GA later	
			Fort Myers FL	3.12.81/95
			Jim Hankins Air Service, Jackson MS	18.8.95/97
			Blu Sky Enterprises, Overland Park KS	25.2.97
			op: Polaris Aviation	97
			crashed destroyed, Elkins WV	6.3.97
BA-57	E18S	N3728B	Anderson Air Activities	15.3.55
BA-57	-9700	N3728B	Inland Steel Co, Chicago IL	15.3.55 15.3.55/66
BA-57		N3728B	Inland Steel Co, Chicago IL (Volpar Mk.IV tricycle landing gear installed	
BA-57	-9700	N3728B	Inland Steel Co, Chicago IL (Volpar Mk.IV tricycle landing gear installed by Gopher Aviation, Rochester MN 12.62)	15.3.55/66
BA-57	-9700	N3728B	Inland Steel Co, Chicago IL (Volpar Mk.IV tricycle landing gear installed by Gopher Aviation, Rochester MN 12.62) Hartzog-Schneck Aviation, Rockford IL	15.3.55/66 20.1.66
BA-57	-9700	N3728B	Inland Steel Co, Chicago IL (Volpar Mk.IV tricycle landing gear installed by Gopher Aviation, Rochester MN 12.62) Hartzog-Schneck Aviation, Rockford IL D. C. Aircraft Inc, Detroit MI	15.3.55/66 20.1.66 23.9.66/68
BA-57	-9700	N3728B	Inland Steel Co, Chicago IL (Volpar Mk.IV tricycle landing gear installed by Gopher Aviation, Rochester MN 12.62) Hartzog-Schneck Aviation, Rockford IL D. C. Aircraft Inc, Detroit MI Hartzog-Schneck Aviation, Rockford IL	15.3.55/66 20.1.66 23.9.66/68 1.3.68/70
BA-57	-9700	N3728B	Inland Steel Co, Chicago IL (Volpar Mk.IV tricycle landing gear installed by Gopher Aviation, Rochester MN 12.62) Hartzog-Schneck Aviation, Rockford IL D. C. Aircraft Inc, Detroit MI Hartzog-Schneck Aviation, Rockford IL Burnside-Ott Aviation Training Centre	15.3.55/66 20.1.66 23.9.66/68 1.3.68/70 16.6.70
BA-57	-9700	N3728B	Inland Steel Co, Chicago IL (Volpar Mk.IV tricycle landing gear installed by Gopher Aviation, Rochester MN 12.62) Hartzog-Schneck Aviation, Rockford IL D. C. Aircraft Inc, Detroit MI Hartzog-Schneck Aviation, Rockford IL Burnside-Ott Aviation Training Centre Executive Airway Leasing Inc	15.3.55/66 20.1.66 23.9.66/68 1.3.68/70
BA-57	-9700	N3728B N57AE	Inland Steel Co, Chicago IL (Volpar Mk.IV tricycle landing gear installed by Gopher Aviation, Rochester MN 12.62) Hartzog-Schneck Aviation, Rockford IL D. C. Aircraft Inc, Detroit MI Hartzog-Schneck Aviation, Rockford IL Burnside-Ott Aviation Training Centre	15.3.55/66 20.1.66 23.9.66/68 1.3.68/70 16.6.70 5.10.70/71 3.71/72
BA-57	-9700		Inland Steel Co, Chicago IL (Volpar Mk.IV tricycle landing gear installed by Gopher Aviation, Rochester MN 12.62) Hartzog-Schneck Aviation, Rockford IL D. C. Aircraft Inc, Detroit MI Hartzog-Schneck Aviation, Rockford IL Burnside-Ott Aviation Training Centre Executive Airway Leasing Inc Crow Inc, Millbury OH	15.3.55/66 20.1.66 23.9.66/68 1.3.68/70 16.6.70 5.10.70/71
BA-57	-9700		Inland Steel Co, Chicago IL (Volpar Mk.IV tricycle landing gear installed by Gopher Aviation, Rochester MN 12.62) Hartzog-Schneck Aviation, Rockford IL D. C. Aircraft Inc, Detroit MI Hartzog-Schneck Aviation, Rockford IL Burnside-Ott Aviation Training Centre Executive Airway Leasing Inc Crow Inc, Millbury OH Air East Inc	15.3.55/66 20.1.66 23.9.66/68 1.3.68/70 16.6.70 5.10.70/71 3.71/72 25.2.72/74
BA-57	-9700		Inland Steel Co, Chicago IL (Volpar Mk.IV tricycle landing gear installed by Gopher Aviation, Rochester MN 12.62) Hartzog-Schneck Aviation, Rockford IL D. C. Aircraft Inc, Detroit MI Hartzog-Schneck Aviation, Rockford IL Burnside-Ott Aviation Training Centre Executive Airway Leasing Inc Crow Inc, Millbury OH Air East Inc Hollywood Flying Service	15.3.55/66 20.1.66 23.9.66/68 1.3.68/70 16.6.70 5.10.70/71 3.71/72 25.2.72/74
BA-57	-9700		Inland Steel Co, Chicago IL (Volpar Mk.IV tricycle landing gear installed by Gopher Aviation, Rochester MN 12.62) Hartzog-Schneck Aviation, Rockford IL D. C. Aircraft Inc, Detroit MI Hartzog-Schneck Aviation, Rockford IL Burnside-Ott Aviation Training Centre Executive Airway Leasing Inc Crow Inc, Millbury OH Air East Inc Hollywood Flying Service International Transfer Corp/ Pro-Air Service, Opa Locka FL op: Shawnee Airlines, Fort Lauderdale FL	15.3.55/66 20.1.66 23.9.66/68 1.3.68/70 16.6.70 5.10.70/71 3.71/72 25.2.72/74 10.6.74/75
BA-57	-9700		Inland Steel Co, Chicago IL (Volpar Mk.IV tricycle landing gear installed by Gopher Aviation, Rochester MN 12.62) Hartzog-Schneck Aviation, Rockford IL D. C. Aircraft Inc, Detroit MI Hartzog-Schneck Aviation, Rockford IL Burnside-Ott Aviation Training Centre Executive Airway Leasing Inc Crow Inc, Millbury OH Air East Inc Hollywood Flying Service International Transfer Corp/ Pro-Air Service, Opa Locka FL op: Shawnee Airlines, Fort Lauderdale FL William E. Hauck, Fort Lauderdale FL	15.3.55/66 20.1.66 23.9.66/68 1.3.68/70 16.6.70 5.10.70/71 3.71/72 25.2.72/74 10.6.74/75
BA-57	-9700		Inland Steel Co, Chicago IL (Volpar Mk.IV tricycle landing gear installed by Gopher Aviation, Rochester MN 12.62) Hartzog-Schneck Aviation, Rockford IL D. C. Aircraft Inc, Detroit MI Hartzog-Schneck Aviation, Rockford IL Burnside-Ott Aviation Training Centre Executive Airway Leasing Inc Crow Inc, Millbury OH Air East Inc Hollywood Flying Service International Transfer Corp/ Pro-Air Service, Opa Locka FL op: Shawnee Airlines, Fort Lauderdale FL William E. Hauck, Fort Lauderdale FL op: Air International Airlines, Miami FL	15.3.55/66  20.1.66 23.9.66/68 1.3.68/70 16.6.70 5.10.70/71 3.71/72 25.2.72/74 10.6.74/75  10.75/77 77 18.2.77/80 77
BA-57	-9700		Inland Steel Co, Chicago IL (Volpar Mk.IV tricycle landing gear installed by Gopher Aviation, Rochester MN 12.62) Hartzog-Schneck Aviation, Rockford IL D. C. Aircraft Inc, Detroit MI Hartzog-Schneck Aviation, Rockford IL Burnside-Ott Aviation Training Centre Executive Airway Leasing Inc Crow Inc, Millbury OH Air East Inc Hollywood Flying Service International Transfer Corp/ Pro-Air Service, Opa Locka FL op: Shawnee Airlines, Fort Lauderdale FL William E. Hauck, Fort Lauderdale FL op: Air International Airlines, Miami FL William E. Hauck/ Hawk Aviation Corp	15.3.55/66  20.1.66 23.9.66/68 1.3.68/70 16.6.70 5.10.70/71 3.71/72 25.2.72/74 10.6.74/75  10.75/77 77 18.2.77/80
BA-57	-9700		Inland Steel Co, Chicago IL (Volpar Mk.IV tricycle landing gear installed by Gopher Aviation, Rochester MN 12.62) Hartzog-Schneck Aviation, Rockford IL D. C. Aircraft Inc, Detroit MI Hartzog-Schneck Aviation, Rockford IL Burnside-Ott Aviation Training Centre Executive Airway Leasing Inc Crow Inc, Millbury OH Air East Inc Hollywood Flying Service International Transfer Corp/ Pro-Air Service, Opa Locka FL op: Shawnee Airlines, Fort Lauderdale FL William E. Hauck, Fort Lauderdale FL op: Air International Airlines, Miami FL William E. Hauck/ Hawk Aviation Corp International Aircraft Corp, Princeton FL	15.3.55/66  20.1.66 23.9.66/68 1.3.68/70 16.6.70 5.10.70/71 3.71/72 25.2.72/74 10.6.74/75  10.75/77 77 18.2.77/80 77
BA-57	-9700		Inland Steel Co, Chicago IL (Volpar Mk.IV tricycle landing gear installed by Gopher Aviation, Rochester MN 12.62) Hartzog-Schneck Aviation, Rockford IL D. C. Aircraft Inc, Detroit MI Hartzog-Schneck Aviation, Rockford IL Burnside-Ott Aviation Training Centre Executive Airway Leasing Inc Crow Inc, Millbury OH Air East Inc Hollywood Flying Service International Transfer Corp/ Pro-Air Service, Opa Locka FL op: Shawnee Airlines, Fort Lauderdale FL William E. Hauck, Fort Lauderdale FL op: Air International Airlines, Miami FL William E. Hauck/ Hawk Aviation Corp International Aircraft Corp, Princeton FL (cabin interior converted for cargo 9.84)	15.3.55/66  20.1.66 23.9.66/68 1.3.68/70 16.6.70 5.10.70/71 3.71/72 25.2.72/74 10.6.74/75  10.75/77 77 18.2.77/80 77 6.2.80/83 11.83/85
BA-57	-9700		Inland Steel Co, Chicago IL (Volpar Mk.IV tricycle landing gear installed by Gopher Aviation, Rochester MN 12.62) Hartzog-Schneck Aviation, Rockford IL D. C. Aircraft Inc, Detroit MI Hartzog-Schneck Aviation, Rockford IL Burnside-Ott Aviation Training Centre Executive Airway Leasing Inc Crow Inc, Millbury OH Air East Inc Hollywood Flying Service International Transfer Corp/ Pro-Air Service, Opa Locka FL op: Shawnee Airlines, Fort Lauderdale FL William E. Hauck, Fort Lauderdale FL op: Air International Airlines, Miami FL William E. Hauck/ Hawk Aviation Corp International Aircraft Corp, Princeton FL	15.3.55/66  20.1.66 23.9.66/68 1.3.68/70 16.6.70 5.10.70/71 3.71/72 25.2.72/74 10.6.74/75  10.75/77 77 18.2.77/80 77 6.2.80/83

N3728B photo 63 trigear, Inland Steel Co titles; N57AE visited Miami FL 27.4.85 Air South, no titles; accident report 6.5.85: crashed WPB during landing on passenger flight op Air South Inc;

BA-58	E18S	N3731B N4F (2	reg Latrobe Construction Co, Earlington PA written-off: struck-off USCR	.55 30.3.55/57 18.6.57

BA-59	E18S -9700 N3773B no	N3773B (N73R) N3773B (N16FB) N3773B	J. R. Gray Co, Dallas TX Aztec Oil & Gas Co ntu: Aztec Oil & Gas Co Aztec Oil & Gas Co, Dallas TX AiResearch Aviation Co The Aggie Club, College Station TX Belvon Leasing Inc Mike Spivey/ Limestone Aviation Westark Air Service ntu: Westark Air Service Stone Air Freight, Fort Smith AR Stewart Aviation Service Mayan Marble & Tile Parker Harrington, Sherwood AR Jose Martinez-Alegria, Cooper City FL Samuel Smith, Miami FL Julio A. Guell & Enrique A. Mejia, Miami FL Mario A. Enriquez, Miami FL struck-off USCR	23.3.55 1.4.55 10.56 10.56/69 24.3.69 9.69/72 28.2.73/76 10.9.76/77 19.8.77/78 1.78 1.3.78/80 10.80/83 18.2.83/85 10.6.85/86 6.1.86/87 18.3.87/89 8.89 22.11.89/13 13.8.13
BA-60	E18S	N3734B	built Lane Construction Corp, Meriden CT Alaska Air Service, Anchorage AK crashed into river on takeoff from beach, Montague Island AK	.55 63/72 9.12.74/75 27.4.75
	N3734B Ala	aska Air Servid	ce, took off 9.30pm, aborted, gear collapsed, 3 unhurt;	
BA-61	E18S	N3730B	built Sunray DX Oil Co, Tulsa OK Pioneer Airlines, Washington DC Combs Airways, Billings-Logan MT Courtesy Air Service, Glen Falls NY ran off runway landing, struck trees, Manahawkin NJ (Courtesy advise FAA 11.76: sold for parts) United Counties Trust Corp, Elizabeth NJ struck-off USCR	.55 63/66 69/70 72 76 29.1.76 22.4.76 1.12.76
	N3730B no	ted Teterboro	NJ 20.7.71;	
BA-62	E18S		(to FA Colombiana as FAC521)	
BA-63	E18S	HK-1815X HK-1850X	•	.76/78 13.9.78
		oted Bogota 3. oted Opa Lock	10.76 id. BA-63; a FL 12.3.77;	
BA-64	E18S	N3751B N503J	John D. Askew, Fayetteville AR Lawrence R. Lippert, Alma MI Jim Hankins Air Service, Jackson MS Van Dusen Acceptance Corp, Minneapolis MN Isd: Buckeye Air Service, Elyria OH wrecked in forced landing wheels-up, off-airport, Genev	63/64 69 70/72 26.7.72/73 72/73 a IL 13.12.73
	N503J acci	ident report 13. Itended wheels	966 as either reg; .12.73: Buckeye Air Service, flight Omaha NB-Des Moine s-up landing in snow storm, right engine failed, left reduce	
BA-65	E18S	N3753B	J. R. Gray Co, Dallas TX Perkins-Prothro Co	8.4.55 10.55/61

		damaged on takeoff, Boulder CO	14.7.60
		J. W. Duff Aircraft Co, Denver CO	13.1.61/63
		Volitan Aviation, Van Nuys CA	17.6.63
	N340V (1	Volpar Inc, Van Nuys CA	4.12.63/67
Volpar		(prototype Volpar Super Turbo 18:	1.12.00/01
Super		experimental CofA 10.64: R&D for type certification,	
Turbo 18		AiResearch TPE-331 developmental turbines;	
10100 10		trigear, windows replacing portholes 11.64;	
		• • • • • • • • • • • • • • • • • • • •	
		G18S cab & windows, ff Van Nuys 12.64 as	
		Volpar Super Turbo 18;	
		installation of TPE-331-25 production turbines	
		completed 2.66, FAA STC issued 17.2.66)	
		Ransome Air, Philadelphia PA: leased	3.67
Volpar		(further conversion to prototype Volpar Turboliner,	
Turboliner		ff Van Nuys 12.4.67: TPE-331-1-101Bs &	
		fuselage lengthened by 81.5 inches)	
		Central Trust Leasing, Cleveland OH	67
		(further Turboliner mods. completed 8.69, conv. #014)	
		Ransome Air/ Allegheny Commuter,	
		Philadelphia PA Flagship Trenton	2.9.69/74
		propeller blade separated in flight, landed safely,	
		Philadelphia PA	20.10.69
Turboliner II		(converted 12.71 to Volpar Turboliner II)	
		Fairbanks Flight Service, Fairbanks AK	5.2.74/76
		(forward cargo door modified to hinge upward,	
		pilot cockpit entrance door installed 4.74)	
		damaged on takeoff, Fairbanks AK	23.2.75
		Polar Airways, Anchorage-Merrill Field AK	3.76
	N114PA	Polar Airways, Anchorage-Merrill Field AK	24.3.76/78
		Soonair Lines, Tulsa OK	19.4.78
	N16SL	Soonair Lines, Tulsa OK	11.78/81
	ITIOOL	Connie Kalitta Services, Willow Run MI	2.6.81/90
		American International Airways, Willow Run MI	10.90/92
		Kalitta Flying Service, Detroit-Willow Run MI	1.1.92/99
		Kitty Hawk Charters Inc, Morristown TN	6.5.99/01
		(sold at Kitty Hawk auction 10.01 for parts)	0.0.00/01
		sale reported: USCR	24.6.02/13
		struck-off USCR by FAA	18.4.13
		SHUCK-OH OOCK BY FAA	10.4.13

Turboliner details see Beech 18 by Parmerter p.385-387 & 389;

Steve Darke states: N340V prototype: flying Spring 65 with TPE-331-25, FAA Supplemental Type Certificate issued 17.2.66; around this time engines replaced by TPE-331-47 rated at the same 575shp; engines replaced again around 68 with TPE-331-101 at 605shp giving cruise speed 280mph;

N340V noted San Fernando Valley CA 23.2.65 & 3.3.65;

N340V noted Oakland CA 8.66 as demonstrator Volpar Super Turbo 18, no titles;

N340V accident report 20.10.69: Ransome Airlines, prop blade separated from right engine, damaged engine nacelle, landed safely;

N340V noted Philadelphia PA 13.4.70 Turboliner "Ransome Airlines" titles;

N340V Turboliner noted Philadelphia PA 14.9.70 "Allegheny Commuter" titles;

N340V noted Washington-DCA 30.9.70 Ransome AL/Allegheny Commuter;

N340V photo Wichta KS .70 Turboliner, "Allegheny Commuter" titles;

N340V noted Van Nuys CA 28.12.71 Allegheny Commuter, Turboliner;

N340V noted Seattle-Boeing Field WA 4.74 Turboliner, no titles;

N340V accident report 23.2.75: Volpar 18, Fairbanks Flight Service, took off with frost on wings, stalled in, 2 unhurt, flight to Bettles AK;

N16SL noted Detroit-Metro 1.9.79 "Soonair" titles, Turboliner, freighter;

N16SL noted Youngstown IN 3.5.83 Volpar Turboliner, Connie Kalitta Services;

N16SL noted Indianapolis IN 7.9.84 Turboliner freighter Connie Kalitta titles;

N16SL noted Boston MA 6.2.85 turbines, Kalitta, op. for Zantop;

N16SL noted Willow Run MI 3.8.89 Connie Kalitta Air Services, Turboliner;

N16SL Willow Run MI 7.91 Connie Kalitta, turbine trigear, plates BA-65, Volpar #014;

N16SL Willow Run MI 8.96 Kalitta, as Turboliner; Willow Run 5.98 Turboliner, Kalitta;

N16SL based Morristown TN 5.05: had been sold by Kitty Hawk but not picked up;

N16SL noted Morristown TN 3.8.05 open storage engines removed, "Kitty Hawk

Charter" on rear fuselage in small letters;

BA-66	E18S -9700	(N3759B) N28S N284S F-OCPG C-GLQF N9152F	ntu: Beech Aircraft Corp J. R. Gray Co, Dallas TX Sun Oil Co/ Sun Pipe Line Co, Philadelphia PA Houston Beechcraft Inc, Houston TX Armair Inc, Coral Gables FL Air Saint Pierre, St. Pierre et Miquelon Air Saint Pierre, St. Pierre et Miquelon CofA expired 7.74, struck-off Register reg Herbert A. Hartley, Brownsville FL Roy D. Hartley (FAA report 2.86: aircraft destroyed or scrapped)	4.55 19.4.55 3.5.55/67 23.2.67 10.67/69 29.4.70 19.1.71/79 29.10.79 13.7.81/82 20.4.82/86
			struck-off USCR ale FL 6.10.68; Dorval 30.6.70;	4.86
BA-67	E18S	N3760B N86E N49891 N7891 N277U CF-QCD	Atlantic Aviation Corp Shea Chemical Corp Shea Chemical Corp Hooker Chemical Corp Ontario Airways, Porterville NY Valley Equipment Corp, Paducah KY Green River Rural Electric Cooperative Corp, Owensboro KY Univair Corp, Milwaukee WI Fontana Aviation Aviation Sales International Canada Ltd Labelle Touristair, Laval QUE dam. emergency belly landing on frozen lake surface, Matagami QUE (9 on board unhurt) Parachute School of Toronto Ltd, Toronto ONT sold to USA, struck-off Canadian Register Charles E. Leonard, Covington LA Samuel N. Nipper, Fayetteville GA Midland College, Midland TX Mark Lee, Floydada TX Ray Lee, Plainview TX Texas Air Museum, Slaton TX	21.4.55 7.6.55/57 30.4.57/58 29.5.58/60 22.1.60/63 10.63/65 12.65/68 23.5.68/71 2.10.71/72 4.72 73/74 18.2.73 83/85 13.1.85 14.1.85/90 28.9.90/91 6.12.91/95 7.5.98/04 23.1.04/15 25.3.15/20
BA-68	BA-68 visited BA-68 & BA- BA-68 visited BA-68, 69, 7 BA-68 noted BA-68 noted BA-68 noted Note: Musee E18S F-SDS	d Blackbushe 70 both Fren d London-Hea d RAF Northo 0, 83 listed w Le Bourget Hamburg 6.4 stored Chate de l'Air, Le E F stored Dug		55 31.5.55 5.55/73 72/73
BA-69	E18S	BA-69	French Air Force/ Armee de l'Air as BA-69 "F-RAEM" (delivered by Fleetaway to Paris 5.55) Chateaudun AB: retired, stored	5.55/75 72/75

BA-69 F-RAEM noted Idlewild NY 9.5.55 on del to France; BA-69 visited Blackbushe 3.9.56 in visitors park for 1956 Farnborough Air Show; BA-69 French AF visited RAF Northolt 22.8.61; Ba-69 French AF visited RAF Northolt & RAF Odiham both 5.9.62 tailwheel;

BA-69 French AF visited RAF Northolt 22.5.66;

BA-69 French AF noted Brussels 26.3.68;

BA-68, 69,70, 83 listed with 60th Escadre, Escadron 2/60 based Villacoublay AB in 68;

BA-69 noted stored Chateaudun AB 7.72, 3.6.73, 6.75;

BA-70	E18S	BA-70	French Air Force/ Armee de l'Air as BA-70 "F-RAEN" (delivered by Fleetaway to Paris 5.55)	5.55/75	_
			Chateaudun AB: retired, stored	75	

BA-70 F-RAEN noted Idlewild NY 9.5.55 on del. to France;

BA-70 visited Heathrow 26.6.57; Blackbushe 12.7.59;

BA-70 & BA-68 both French AF at Northolt 6.9.60 for Farnborough Air Show;

BA-70 French AF visited Northolt 28.7.61;

BA-68, 69, 70, 83 listed with 60th Escadre, Escadron 2/60 based Villacoublay AB in 68;

BA-70 noted Le Bourget 27.12.68;

BA-70 French AF noted Hamburg 6.4.70;

BA-70 visited RAF Northolt 9.70 "F-GAEL";

BA-70 noted stored Chateaudun AB 6.75;

3A-71	E18S	N3765B	Tulsair Distributors Inc	6.5.55
	-9700		Skelly Oil Co, Tulsa OK	22.8.55/68
	0.00		damaged gear-up landing on foamed runway, Tulsa OK	22.3.67
			Parker Truck & Equipment Inc, Muskogee OK	22.5.68/77
		N12PT	Parker Truck & Equipment Inc, Muskogee OK	2.8.77/79
			Oklahoma Aircraft Corp, Yukon OK	7.8.79
			David C. Colombo, Stillwater MN:	
			sale documentation not completed	7.9.79
			derelict Braco strip near Montego Bay, Jamaica	83

BA-72	E18S	N304K CF-ORD YV-T-KTE YV-344P YV-201C YV-1233P YV-196CP	Ford Motor Co, Detroit MI exported to Canada, struck-off USR Ford Motor Co of Canada, Oakville ONT reg rereg ASCRCA rereg rereg	15.6.55/61 21.9.61 .61/67 11.67
BA-73	E18S	HB-GAH	reg (delivered via Prestwick 18.6.55)	6.55
		D-IBAC	Helmut Horton GmbH, Dusseldorf	13.7.56
		HB-GAH	reg	7.56
		N6074C	reg	
		N34L	William P. Lear/ Lear Siegler Inc, Santa Monica CA op: Lear Integrated Flight Equipment, Geneva,	7.12.56/62
			Switzerland	58/62
			struck-off USCR	27.7.62
		HB-GAV	reg	.62
			Sintesi S.A., Lugano	64
			retired at Colombier: struck-off Swiss Register	1.71

N34L photo Santa Monica CA 58 no titles, tailwheel;

N34L visited Croydon Aerodrome, London 8.9.59 Lear Inc;

N34L noted at Blackbushe 11.9.59 "LIFE";

N34L visited Shoreham UK several times during 1960, "L.I.F.E." titles (for Lear

Integrated Flight Equipment) with Bill Lear on board;

N34L noted Gatwick 4.3.60, 1.2.61,

N34L visited Gatwick 4.9.61 named "Chessy", Farnborough visitor;

N34L noted Manchester 29.5.61 Life Magazine;

N34L displayed at Paris Air Show, Le Bourget 3.6.61 with E18S F-BERT;

HB-GAV visited Gatwick 16.1.63; Milan, Italy 24.7.63;

HB-GAV noted Colombier 21.7.71 retired;

BA-74	E18S	N3770B	Beech Aircraft Corp, Wichita KS (support aircraft for 1955 US demo tour of the MS.760 Paris business jet marketed by Beech)	1.7.55
			Gerald C. Francis/ Francis Aviation, Lansing MI (commercial CofA issued 2.11.55)	2.11.55
			Shakespeare Co, Kalamazoo MI	2.11.55/61
			damaged struck metal stand taxying, Newark NJ	30.9.60
			W. C. Grant CoPunta Gorda FL	28.9.61/63
			Business Aircraft Leasing Corp, Gainsville FL	3.10.63/67
			lsd: Satterfield Construction Co	3.10.63/67
		N279SC	Satterfield Construction Co, Greenwood SC	10.7.68/69
			Frank Cannavo/ Aero Taxi, Lester PA	29.5.70/72
			Frank Cannavo/Aero Taxi-Rockford IL	11.73/00
			forced landing gear-up in soy bean field,	
			due fuel exhaustion, Rockford IL	19.7.70
			(Hamilton cockpit door installed 10.78)	
			Sally B. Stewart, Chandler AZ	15.5.01/05
			Triton Holding Corp, Wilmington DE	20.12.05/06
			Scott H. Gloodt, Orland Park IL	22.8.06/20

N279SC accident report 19.7.70: Aero Taxi: flight Philadelphia to Rockford, minor dam;

N279SC noted Rockford IL 23.7.71;

N279SC noted Rockford IL 7.91 plate BA-74;

N279SC noted Rockford IL 7.97 plate BA-74 built 5.55 i/s with Aero Taxi;

N279SC noted Rockford IL 3.8.98 Aero Taxi; N279SC noted Rockford 26.7.99 based Rockford with Aero Taxi Rockford IL, flying;

N279SC noted Rockford IL 30.7.00 Aero Taxi;

N279SC at Beech flyin Tullahoma TN 16.10.02;

N279SC at Beech flyin Tullahoma TN 16.10.03; noted at Janesville WI 25.7.08;

further details Shakespeare Co: see Beech 18 by Parmerter p.290;

BA-75	E18S	N3771B	Tulsair Distributors Inc, Tulsa OK	20.5.55	
			Sunray Mid-Continent Oil Co, Tulsa OK	20.5.55/62	
			Sunray DX Oil Co/ Sun Oil Co, Tulsa OK	8.5.62/69	
			Robert R. Haack/ Spirit Lake Airways, Okoboji IA	28.2.69/70	
			(9 pax high-density seating installed 25.2.70)		
			SMB Stage Line, Des Moines IA	16.5.70/75	
			Central Northern Ltd	27.3.75	
			(cargo door installed 4.75)		
			Cal-North Construction, Klondike Line AK	10.75/76	
			sale documentation not completed		
			sale reported, Anchorage AK: USCR	2.76	
			forced landing after takeoff, Anchorage AK	8.12.76	

N3771B accident report 8.12.76: Klondike Line, forced landing gear down off airport after takeoff on cago flight to Bethel AK, pilot unhurt;

BA-76	E18S	N3774B	Tulsair Distributors Inc, Tulsa OK	31.5.55
2.00		Sunray Mid-Continent Oil Co	31.5.55/60	
			Big Chief Drilling Co	12.60/61
			Jack Richards Aircraft Sales, Oklahoma City OK	12.61/64
			lsd: Arkansas Valley Industries Inc	1.3.62
			Aircraftsmen Inc, Oklahoma City OK	20.5.64/65
	trigear		(Volpar Mk.IV trigear installed 2.65)	
			Tulakes Aviation, Bethany OK	26.8.65/66
			Ceco Corp	3.1.67/68
			Corley Manufacturing Co, Chattanooga TN	28.2.68/73
		N471CM	Corley Manufacturing Co, Chattanooga TN	4.4.73
			(noted painted as N471CM by 8.71)	
			W. F. Huston/ Huston Aviation	3.7.73/75
			John Decker/ Occidental Land Research,	
			West Covina CA	4.11.75/83
			gear inadvertantly retracted on takeoff run,	
			Laverne-Brackett Field CA	16.12.79
			Antonio G. Ginard, Rockaway NJ	24.9.83/00
			WTK Aviation, Miami FL	3.4.02

N471CM noted Ft Lauderdale FL 24.8.71;

N471CM noted Long Beach CA 26.7.81 trigear;

N471CM noted Ft Lauderdale FL 9.90 & 5.92;

N471CM noted Ft Lauderdale 2.1.98 stored, no reg;

N471CM noted Opa Locka FL 6.9.98 trigear;

N471CM noted Opa Locka 22.10.98 all white, hand-painted reg; Opa Locka 8.12.98;

N471CM noted Opa Locka 5.2.99 allover white, trigear;

N471CM noted Opa Locka FL 4.4.01 trigear;

N471CM noted Opa Locka FL 4.11.04,

(no reg) noted Opa Locka FL 10.8.05 trigear, plate BA-76 built 5.55 all metallic;

BA-77	E18S	HK-1111G	Ministerio de Obras Publicas Colombia (built 5.55, US Export Certificate 27.5.55)	5.55
			Institute Geographique (noted Bogota Airport 2.75 with damaged rear fuselage)	72
Alternativ	ve version			
			Hamilton Aircraft Co, Tucson AZ	80
	Hamilton HA-1		(rebuilt at Tucson AZ as Hamilton HA-1 Turboliner completed 4.80)	
	Turboliner	HK-1111 (2	Aerolineas Especiales de Colombia, Florencia	.80
			rep. op: US Border Patrol, based Florida	80/81
			rep. returned to Hamilton Aircraft Co, Tucson AZ rep. broken up for parts Tucson AZ	81

HK-1111G noted Barranquilla, Colombia 30.9.72 Inst. Geo.

HK-1111 noted Tucson AZ 4.6.80 rep as BA-77 trigear turbine, AE Colombia scheme but no titles;

HK-1111 noted Tucson AZ 28.10.80 rep as BA-77 Hamilton HA-1 Aerolineas Especiales

freighter, converted from E18S in 4.80;

HK-1111 noted Tucson 5.11.81 rep as BA-77 Aerolineas Especiales;

HK-1111 noted Tucson 9.11.81 trigear "AE", operational;

Note: E18S BA-77 manufacturers plate offered for sale on EBay 7.12.04 by a Waco TX resident;

Robert Parmerter advises (1/07):

BA-57 w/o in Bogota, rear fuse at Bogota 2.75. No link to HK-1111

HK-1111 (1 Westwind III tailwheel was BA-157 HK-1111 (2 HA-1 Turboliner nose gear was 3596

BA-78	E18S	N3768B	L. A. Grelling, Tyler TX	8.7.55/56
			crashed 5.56, struck-off USCR	30.7.56
BA-79	E18S	N3772B	built	.55
		N136C	Downing Box Co, Milwaukee WI	63/69
			Pocono Airlines/ Allegheny Commuter	69/70
			Duncan Aviation, Lincoln NE	70/72
			Hamilton Aviation, Hamilton OH	73
			minor damage in ground collision with Beech 18 N179	)L,
			Covington KY	14.6.73
			gear collapsed landing, Colorado Springs CO	14.10.76
			Eagle Air Inc, St Louis MO	5.2.79
			destroyed in forced landing off-airport, Dayton OH	11.7.79

N136C accident report 14.6.73: Hamilton Aviation, struck N179L while taxying after landing, 1.45am; N136C accident report 14.10.76: swerved during landing during wind gust, tailwheel unlocked, flight

from Chicago, 4pm, pilot unhurt;

BA-80	E18S	N4277B	built	.55
			Champion Steel Corp, Orwell OH	63/72
			Swift Air Charter, Elyria OH	7.5.74/76
			forced landing gear-up on rough terrain near Shafter TX,	

N4277B accident report 6.3.76: unapproved three 80 gallon tanks installed in cabin, flight from unknown location to eventual destination Pontiac MI, 2 unhurt;

BA-81	E18S	N3781B	built	5.55
	-9600		Harvest Queen Mill & Elevator Co, Plainview TX	63/72
			Richard R. Bogenreif, Las Vegas NV	78/91
			op: Air Vegas Airlines, Las Vegas NV	78
			gear collapsed landing, Grand Canyon AZ	9.11.78
			(retired derelict Van Nuys CA 87/92)	
			Aerospace Products Inc, North Hollywood CA	4.92
			Glenn A. Bagley, Honolulu HI	29.10.92/95
			sold to Micronesia: struck-off USCR	12.96
		V6-CAB	Caroline Pacific Air, Pohnpei, Palau	.96
		N3781B	Bob Keys, Palau	98/02
			(flew in Palau mispainted as "N7581B", changed to	
			N3781B during maintenance prior to ferry to Australia;	
			delivered Palau to Bundaberg QLD via Cairns 22.8.98,	
			parked open storage Bundaberg 98/05 as N3781B)	
		VH-CIJ	Robert H. Keys, Noosa Heads QLD	16.6.00/13
			(no CofA, stored Bundaberg 02/13 as N3781B)	
			Queensland Air Museum, Caloundra Airport QLD	16.12.13/20
			(arr. on truck at museum 1.2.14 ex Bundaberg,	
			outer wings moved earlier 30.12.13)	

N3781B accident report 9.11.78: Air Vegas Airlines: pax flight Las Vegas NV to Grand Canyon, mechanical failure of gear on landing roll, pilot & 10 pax unhurt;

N3781B noted Van Nuys CA 7.4.87;

N3781B noted Van Nuys CA 10.87 derelict;

N3781G noted Van Nuys CA 23.4.92: prob this acft (GG);

FAA quote cancellation date USCR as 5.11.97;

N3781B del.via Pt Moresby-Cairns 22.8.98 to Bundaberg 23.8.98 for maintenance, tailwheel, yellow/white;

noted Bundaberg 29.8.98,19.9.98,15.10.98: plate E18S BA81 built 5.55 conv. to 9600lbs 5.4.62:

N3781B noted Bundaberg 30.1.99,11.2.99, 4.99, 5.99 outside yellow & white; 7.99 & 9.99 parked outside with N753CW;

N3781B outside Bundaberg 9.02 yellow & white, tailplane removed;

N3781B noted Bundaberg 7.03 yellow & white, tatty, outside; same 28.1.04, 12.6.05; 1.8.07;

Note: photograph taken by aircraft engineer Don Dummer who performed an overhaul on this E18S at Palau prior to the ferry flight to Australia in 1998 shows aircraft in the yellow & white paint scheme but painted as "N7581B": he wrote on back of photo "N number changed to N3781B to match the FAA CofA"

BA-82	E18S	N2939B	built	.55
			Copeland Refrigeration Corp, Sidney OH	63/70
			Southern Aviation, Lawton OK	7.6.71/75
			ground-loop landing, gear collapsed, Oklahoma City OK	13.12.73
			struck-off USCR	11.11.75
24.02	pilot unhu	,	Southern Aviation: mail flight, Lawton-OKC-Tulsa-Kansas	
BA-83		,	Southern Aviation: mail flight, Lawton-OKC-Tulsa-Kansas (to Armee de l'Air as BA-83) "F-RAEO"	7.55/68
BA-83	pilot unhu	,		
BA-83	pilot unhu	rt;	(to Armee de l'Air as BA-83) "F-RAEO"	
BA-83	E18S  BA-83 Fre BA-83 Fre	rt; ench AF visited ench AF visited	(to Armee de l'Air as BA-83) "F-RAEO" (delivered by Fleetway to Paris 7.55)  Blackbushe 25.7.59; Heathrow 27.10.60, c/n BA-63 callsign "F-RAEO";	
BA-83	E18S  BA-83 Fre BA-83 Fre	rt; ench AF visited ench AF visited	(to Armee de l'Air as BA-83) "F-RAEO" (delivered by Fleetway to Paris 7.55)  Blackbushe 25.7.59;	

BA-84	E18S	N3545B	Currey Sanders Aircraft Co: CofA issued	22.6.55
		N100X (1	American Snuff Co	4.12.55/62
		N180X	Jebco Inc, Shreveport LA	30.7.62/64

BA-68, 69, 70, 83 listed with 60th Escadre, Escadron 2/60 based Villacoublay AB in 68;

	Falco Inc, Shreveport LA M. O. Rasberry/ Rasberry & Rasberry Firmin Wilkinson, Detroit MI	4.3.64/67 1.3.67/68 10.68/72
Hamilton	Shorter Airlines, Miami FL (Hamilton extended nose installed 5.73)	25.5.72/74
	,	25 2 74/77
Westwind	R.C.D. Inc	25.3.74/77
extended nose	Swift Air Charter, Cleveland OH	30.8.77/78
	op: Flight Express Cargo, Philadelphia PA	78/79
	nosed over on takeoff, Middletown PA	17.2.78
	M & K Aviation	8.5.78
	Perkiomen Airways, Reading PA:	
	sale documentation not completed	8.5.78

N180X noted San Antonio TX 31.8.73 Hamilton conversion, Shorter Airlines; N180X accident report 17.2.78: Flight Express Cargo, cargo flight Middletown to Pittsburgh PA, took off in fog 11.32pm, groundlooped, nosed over, pilot unhurt; USCR 95/99: reg. pending, Reading PA;

BA-85	E18S	N3785B	Anderson Air Activities	23.6.55
			Allis Chalmers Manufacturing Co	24.6.55/61
			Robert B. Phillips, Tulsa OK	6.7.61/66
			Marshfield Airways, Marshfield WI	9.8.66/70
			op: Midstate Air Commuter, Chicago IL	66/69
			hit trees landing, Ashland WI, diverted to Duluth	12.10.69
			Skyway Aviation/ Skyway Airlines, Ft Leonardwood MO	11.70/80
			landed gear locked-up, Fort Leonardwood MO	25.7.79
			Nevada Aircraft Leasing Corp	4.4.80/81
			Nolan F. Carter, El Paso TX	23.4.81/95
			struck-off USCR	6.12.95

N3785B accident report: struck trees during approach Ashland, diverted to Duluth; N3785B noted St Louis-Lambert Field MO 8.4.72 Skyways; accident report 25.7.79: Skyway Aviation; pax flight from Kaiser MO, 5 pax, 2 crew unhurt;

BA-86	E18S	N50W (2	Page Airways, Rochester NY: delivered new	.55
		•	D. W. Winkelman Co, Syracuse NY	14.7.55/72
			crashed after takeoff. Skaneateles NY	6.4.72

accident report 6.4.72: took off from strip too short to obtain minimum speed in snow storm, near `maximum weight, right engine lost power, slid into ground off-airport, 3k 3 hurt;

BA-87	E18S	N3787B	Southern Airways Co	7.11.55/56
	-9700		American Leasing Corp, Hartford CT	24.1.56/60
			lsd: Anaconda Wire & Cable Co, Hastings NY	23.6.56/60
			Anaconda Wire & Cable Co, Hastings NY	25.1.60/67
			Pardue University, Lafayette IN	8.11.67/72
			Twin City Airways Corp	13.9.72/74
			Hamilton Aviation, Hamilton OH	17.1.74/77
			Sue A. Swenson	2.8.77/78
			Air Service Center, Hamilton OH	8.4.78/79
			tailwheel torn off landing, Beaver Falls PA	11.5.79
			John T. Hogan/ Hoganair Inc, Hamilton OH	1.7.79
		N87HA	HoganAir Inc, Hamilton OH	19.6.80/86
		N8711H	HoganAir Inc, Hamilton OH	10.86
			The Eagle & The Hawks Inc, Middletown OH	1.11.86/94
			Miami Valley Aviation, Middletown OH	18.3.94/98
			The Eagle & The Hawks Inc, Middletown OH	29.5.98/07
			op: Miami Valley Aviation, Middletown OH	98/05
			Seven Stars Air Cargo Corp, Carolina, Puerto Rico	07/20

N3787B accident report 11.5.79: Air Service Centre, cargo flight Gainsville GA to Buffalo NY, groundloop landing Beaver Falls, tailplane & tailwheel damaged, 8.10pm; N87HA noted Hamilton OH 13.5.85 no titles;

N8711H noted Middletown OH 2.92 MVA tailwheel, large fuse freight doors, no titles; N8711H noted Middletown OH 5.97 "Miami Valley";

N8711H noted Middletown OH 1.1.98 & 22.7.98 no titles;

N8711H noted Middletown OH 6.8.99 Miami Valley Aviation, plate BA-87 built 6.55;

N8711H noted Middletown OH 6.8.99 Miami Valley Aviation;

N8711H noted Middletown OH 20.7.02 Miami Valley Aviation;

N8711H noted Middletown OH 1.8.05, for sale with N9669N, Miami Valley Aviation has ceased ops;

N8711H noted Columbus-Bolton Field OH 11.8.06, not titles, tailwheel;

N8711H noted Columbus OH 8.07 "Seven Stars Air Cargo" titles;

BA-88	E18S	N3789B	Florida Airmotive Inc	7.7.55
			Stockton, Whatley, Davin & Co	7.7.55/60
		N135W (1	Winn-Dixie Stores Inc, Charlotte NC	9.8.60/66
		N739F (2	George H. Bailey Co, Fort Wayne IN	25.2.66
		N135X `	Hatteras Yacht Co	7.3.66/68
			North American Rockwell Corp	14.5.68/69
			Conner Homes Corp, Newport NC	25.1.69/73
			Hausserman Aviation	26.5.73/78
			J. C. Sales Corp, Brownsville TX	23.2.78
			Herbert A. Hartley & Eduardo Pizana/	
			Aircraft Leasing & Pilot Service, Brownsville TX	30.9.78/82
			(owner reported 4.82 N135X destroyed or scrapped)	
			struck-off USCR	12.8.82
BA-89	E18S	N4906B	built	.55
			Puerto Rico Water Resources Authority, San Juan	63/64
			T. W. Henley, Birmingham AL	69/72
			struck fence landing, Geiger AL	8.5.69
			Morrey L. Wyman/ Wyman Pilot Service, Pontiac MI	24.8.73/77
			(retired, derelict Pontiac MI 77/80)	
	N4906B note	ed Pontiac MI	struck-off USCR  17.9.78 derelict, also 10.89, 9.80;	6.7.77
PA 00			struck-off USCR 17.9.78 derelict, also 10.89, 9.80;	
BA-90	N4906B note	ed Pontiac MI N3794B	struck-off USCR  17.9.78 derelict, also 10.89, 9.80;  Pacific Aircraft Sales Co	14.7.55/56
BA-90			struck-off USCR  17.9.78 derelict, also 10.89, 9.80;  Pacific Aircraft Sales Co California Eastern Aviation	14.7.55/56 13.4.56/60
BA-90		N3794B	struck-off USCR  17.9.78 derelict, also 10.89, 9.80;  Pacific Aircraft Sales Co California Eastern Aviation Kaiser Services	14.7.55/56 13.4.56/60 15.4.60/61
BA-90		N3794B N153GP (1	struck-off USCR  17.9.78 derelict, also 10.89, 9.80;  Pacific Aircraft Sales Co California Eastern Aviation Kaiser Services Georgia-Pacific Corp, Portland OR	14.7.55/56 13.4.56/60 15.4.60/61 10.4.61/66
BA-90		N3794B	struck-off USCR  17.9.78 derelict, also 10.89, 9.80;  Pacific Aircraft Sales Co California Eastern Aviation Kaiser Services Georgia-Pacific Corp, Portland OR Bailey Leasing Corp, Fort Wayne IN	14.7.55/56 13.4.56/60 15.4.60/61 10.4.61/66 3.6.66/68
BA-90		N3794B N153GP (1	struck-off USCR  17.9.78 derelict, also 10.89, 9.80;  Pacific Aircraft Sales Co California Eastern Aviation Kaiser Services Georgia-Pacific Corp, Portland OR Bailey Leasing Corp, Fort Wayne IN Isd: Standard Airways	14.7.55/56 13.4.56/60 15.4.60/61 10.4.61/66
BA-90		N3794B N153GP (1	struck-off USCR  17.9.78 derelict, also 10.89, 9.80;  Pacific Aircraft Sales Co California Eastern Aviation Kaiser Services Georgia-Pacific Corp, Portland OR Bailey Leasing Corp, Fort Wayne IN Isd: Standard Airways (executive interior replaced by 9 pax seats 7.66)	14.7.55/56 13.4.56/60 15.4.60/61 10.4.61/66 3.6.66/68 7.6.66/68
BA-90		N3794B N153GP (1	struck-off USCR  17.9.78 derelict, also 10.89, 9.80;  Pacific Aircraft Sales Co California Eastern Aviation Kaiser Services Georgia-Pacific Corp, Portland OR Bailey Leasing Corp, Fort Wayne IN Isd: Standard Airways (executive interior replaced by 9 pax seats 7.66) op: Hub Airlines, Ft Wayne IN	14.7.55/56 13.4.56/60 15.4.60/61 10.4.61/66 3.6.66/68 7.6.66/68
BA-90		N3794B N153GP (1	struck-off USCR  17.9.78 derelict, also 10.89, 9.80;  Pacific Aircraft Sales Co California Eastern Aviation Kaiser Services Georgia-Pacific Corp, Portland OR Bailey Leasing Corp, Fort Wayne IN Isd: Standard Airways (executive interior replaced by 9 pax seats 7.66) op: Hub Airlines, Ft Wayne IN Eastern Aviation/ Shenandoah Airlines, Baltimore MD	14.7.55/56 13.4.56/60 15.4.60/61 10.4.61/66 3.6.66/68 7.6.66/68 c68 8.8.68/69
BA-90		N3794B N153GP (1	struck-off USCR  17.9.78 derelict, also 10.89, 9.80;  Pacific Aircraft Sales Co California Eastern Aviation Kaiser Services Georgia-Pacific Corp, Portland OR Bailey Leasing Corp, Fort Wayne IN Isd: Standard Airways (executive interior replaced by 9 pax seats 7.66) op: Hub Airlines, Ft Wayne IN Eastern Aviation/ Shenandoah Airlines, Baltimore MD landed gear partially locked-up, Roanoke VA	14.7.55/56 13.4.56/60 15.4.60/61 10.4.61/66 3.6.66/68 7.6.66/68 c68 8.8.68/69 31.1.69
BA-90		N3794B N153GP (1	struck-off USCR  17.9.78 derelict, also 10.89, 9.80;  Pacific Aircraft Sales Co California Eastern Aviation Kaiser Services Georgia-Pacific Corp, Portland OR Bailey Leasing Corp, Fort Wayne IN Isd: Standard Airways (executive interior replaced by 9 pax seats 7.66) op: Hub Airlines, Ft Wayne IN Eastern Aviation/ Shenandoah Airlines, Baltimore MD landed gear partially locked-up, Roanoke VA Jack Walls Aircraft Sales, Memphis TN	14.7.55/56 13.4.56/60 15.4.60/61 10.4.61/66 3.6.66/68 7.6.66/68 c68 8.8.68/69 31.1.69 12.69/70
BA-90		N3794B N153GP (1	struck-off USCR  17.9.78 derelict, also 10.89, 9.80;  Pacific Aircraft Sales Co California Eastern Aviation Kaiser Services Georgia-Pacific Corp, Portland OR Bailey Leasing Corp, Fort Wayne IN Isd: Standard Airways (executive interior replaced by 9 pax seats 7.66) op: Hub Airlines, Ft Wayne IN Eastern Aviation/ Shenandoah Airlines, Baltimore MD landed gear partially locked-up, Roanoke VA Jack Walls Aircraft Sales, Memphis TN Vercoa Air Service/ Allegheny Commuter, Danville IL	14.7.55/56 13.4.56/60 15.4.60/61 10.4.61/66 3.6.66/68 7.6.66/68 c68 8.8.68/69 31.1.69 12.69/70 23.9.70/71
BA-90		N3794B N153GP (1	struck-off USCR  17.9.78 derelict, also 10.89, 9.80;  Pacific Aircraft Sales Co California Eastern Aviation Kaiser Services Georgia-Pacific Corp, Portland OR Bailey Leasing Corp, Fort Wayne IN Isd: Standard Airways (executive interior replaced by 9 pax seats 7.66) op: Hub Airlines, Ft Wayne IN Eastern Aviation/ Shenandoah Airlines, Baltimore MD landed gear partially locked-up, Roanoke VA Jack Walls Aircraft Sales, Memphis TN Vercoa Air Service/ Allegheny Commuter, Danville IL Executive Air Travel Inc, Sioux Falls SD	14.7.55/56 13.4.56/60 15.4.60/61 10.4.61/66 3.6.66/68 7.6.66/68 c68 8.8.68/69 31.1.69 12.69/70 23.9.70/71 21.1.71/73
BA-90		N3794B N153GP (1	struck-off USCR  17.9.78 derelict, also 10.89, 9.80;  Pacific Aircraft Sales Co California Eastern Aviation Kaiser Services Georgia-Pacific Corp, Portland OR Bailey Leasing Corp, Fort Wayne IN Isd: Standard Airways (executive interior replaced by 9 pax seats 7.66) op: Hub Airlines, Ft Wayne IN Eastern Aviation/ Shenandoah Airlines, Baltimore MD landed gear partially locked-up, Roanoke VA Jack Walls Aircraft Sales, Memphis TN Vercoa Air Service/ Allegheny Commuter, Danville IL Executive Air Travel Inc, Sioux Falls SD op: Pro Airlines	14.7.55/56 13.4.56/60 15.4.60/61 10.4.61/66 3.6.66/68 7.6.66/68 c68 8.8.68/69 31.1.69 12.69/70 23.9.70/71 21.1.71/73
BA-90		N3794B N153GP (1	struck-off USCR  17.9.78 derelict, also 10.89, 9.80;  Pacific Aircraft Sales Co California Eastern Aviation Kaiser Services Georgia-Pacific Corp, Portland OR Bailey Leasing Corp, Fort Wayne IN Isd: Standard Airways (executive interior replaced by 9 pax seats 7.66) op: Hub Airlines, Ft Wayne IN Eastern Aviation/ Shenandoah Airlines, Baltimore MD landed gear partially locked-up, Roanoke VA Jack Walls Aircraft Sales, Memphis TN Vercoa Air Service/ Allegheny Commuter, Danville IL Executive Air Travel Inc, Sioux Falls SD op: Pro Airlines Southern Aviation	14.7.55/56 13.4.56/60 15.4.60/61 10.4.61/66 3.6.66/68 7.6.66/68 68 8.8.68/69 31.1.69 12.69/70 23.9.70/71 21.1.71/73 73 12.73/77
BA-90		N3794B N153GP (1	struck-off USCR  17.9.78 derelict, also 10.89, 9.80;  Pacific Aircraft Sales Co California Eastern Aviation Kaiser Services Georgia-Pacific Corp, Portland OR Bailey Leasing Corp, Fort Wayne IN Isd: Standard Airways (executive interior replaced by 9 pax seats 7.66) op: Hub Airlines, Ft Wayne IN Eastern Aviation/ Shenandoah Airlines, Baltimore MD landed gear partially locked-up, Roanoke VA Jack Walls Aircraft Sales, Memphis TN Vercoa Air Service/ Allegheny Commuter, Danville IL Executive Air Travel Inc, Sioux Falls SD op: Pro Airlines Southern Aviation Southern Aero Services, Montgomery AL	14.7.55/56 13.4.56/60 15.4.60/61 10.4.61/66 3.6.66/68 7.6.66/68 68 8.8.68/69 31.1.69 12.69/70 23.9.70/71 21.1.71/73 73 12.73/77 10.77/78
BA-90		N3794B N153GP (1	struck-off USCR  17.9.78 derelict, also 10.89, 9.80;  Pacific Aircraft Sales Co California Eastern Aviation Kaiser Services Georgia-Pacific Corp, Portland OR Bailey Leasing Corp, Fort Wayne IN Isd: Standard Airways (executive interior replaced by 9 pax seats 7.66) op: Hub Airlines, Ft Wayne IN Eastern Aviation/ Shenandoah Airlines, Baltimore MD landed gear partially locked-up, Roanoke VA Jack Walls Aircraft Sales, Memphis TN Vercoa Air Service/ Allegheny Commuter, Danville IL Executive Air Travel Inc, Sioux Falls SD op: Pro Airlines Southern Aviation	14.7.55/56 13.4.56/60 15.4.60/61 10.4.61/66 3.6.66/68 7.6.66/68 68 8.8.68/69 31.1.69 12.69/70 23.9.70/71 21.1.71/73 73 12.73/77

N164F accident report 31.1.69 Eastern Aviation, night mail flight, 6.45am, landing gear jammed during previous retraction, landed partially extended, minor damage only; N164F noted Springfield IL 4.8.73 Pro Airlines;

BA-91	E18S	N3788B	Beech Aircraft Corp, Wichita KS	8.7.55	
	-9700	CF-IJI	Field Aviation Co Ltd, Oshawa ONT	19.8.55	
		CF-FEM	Sky Harbour Air Services Sales, Goderich ONT	65/66	
		N244D	Jack Adams Aircraft Sales, Walls MS	19.5.65	
			Chattanooga Aviation, Chattanooga TN	21.9.65	
			Welding Gas Products Co, Chattanooga TN	20.1.66/68	
			Amherst Airways, Buffalo NY	12.68/71	
			Buffalo Aeronautical Corp, Buffalo NY	4.2.71/83	
			Crow Inc, Millbury OH	9.9.83/91	
			Crow Executive Air Inc, Millbury OH	20.10.91	

	CF-FEM S	uper 18 noted	Josephs Four Inc, Fayetteville GA Daniel E. Disbrow, Texas City TX destroyed in hangar fire, Conroe TX struck-off USCR  Toronto 2.65;	4.93/94 17.5.94 12.6.94 11.8.94
BA-92	E18S	N3797B	Southern Airways Co Colonial Oultry Co Brazos Engineering Co	12.9.55 11.55/56 11.56/57
			William D. P. Carey/ Packaging Corp of America, Hutchinson KS	12.57/61
		N300W	Packaging Corp of America, Hutchinson KS	4.1.61/73
			Eureka Aero Industries, Eureka CA (cargo floor & cockpit door installed 5.74)	28.6.73/76
			Nor-Cal Aviation, Novato CA	14.6.76/77
			op: Nor-Cal Airlines, Redding CA	76/77
			Hill Aircraft & Leasing Corp, Atlanta GA (cabin cargo door installed 2.78)	11.1.78/79
			Specialty Leasing System Inc	25.6.79/82
			op: General Aviation Inc, Greenville TN	80/81
			J. W. Evans, Hamilton AL	12.4.82/85
			Aero Taxi-Rockford Inc, Rockford IL emergency landing due engine fire, ran off runway,	22.3.85/88
			struck building, Cynthiana KY	29.4.88
			A 24.7.76 Norcal Avtn; wn OH 4.9.81 General Aviation Inc;	
BA-93	E18S	N4905B	Atlantic Aviation Corp	27.7.55
		N2979	General Foods Corp, White Plains NY General Foods Corp, White Plains NY	27.7.55/58 21.8.58/63
	trigear		(Volpar Mk.IV trigear installed 6.64)	
		N30Y	American Aero Leasing Corp, Elizabeth NJ	1.8.63/64
			AFLC Inc, Birmingham AL	12.64/65
			American Aero Leasing Corp, Elizabeth NJ	9.12.65/72
			Donald E. Watson, Washington DC	7.4.72/79
			Gilley Airways Corp, Fulton NY Sol Levine	10.1.79
				26.4.79/82
			State of Florida: forfeited by court action Aerospace Products Inc, North Hollywood CA	17.2.82/84
			(cargo floor & cabin door installed 5.84)	2.2.84
			Pacific Air Express, Honolulu HI	12.6.84/86
			crashed destroyed during landing, Kalaupapahi HI	13.2.86
			struck-off USCR	7.86
	accident re	port 13.2.86: (	crashed during go-around, Pacific Air Express;	
BA-94	E18S	OO-CHK	Union Miniere du Haut Katanga, Elizabethville	28.9.55/63
		90-CHK	(del. to Tangier via Prestwick 25.8.55) Union Miniere du Haut Katanga, Elizabethville	.61/62
		OO-CHK	Union Miniere du Haut Katanga, Elizabethville	10.9.62/63
		9Q-CHK	Union Miniere du Flaut Katanga, Elizabethville	13.3.63/65
	OO-CHK S	uper 18 arrive	k 25.8.55 on delivery to Tangiers by Fleetaways; ed Heathrow 27.8.55, dep for Tangiers 31.8.55; rRhodesia 16.12.64;	
BA-95	OO-CHK S	uper 18 arrive	ed Heathrow 27.8.55, dep for Tangiers 31.8.55;	
BA-95	OO-CHK S 9Q-CHK no	uper 18 arrive oted Salisbury	ed Heathrow 27.8.55, dep for Tangiers 31.8.55; Rhodesia 16.12.64;	63
BA-95	OO-CHK S 9Q-CHK no	tuper 18 arrive oted Salisbury N80D (1	ed Heathrow 27.8.55, dep for Tangiers 31.8.55; r Rhodesia 16.12.64; Youngstown Airways/Lease Air, Youngstown OH	63 64
BA-95	OO-CHK S 9Q-CHK no	tuper 18 arrive oted Salisbury N80D (1	Youngstown Airways/Lease Air, Youngstown OH Morris Grain Corp, Evansville IN Malcolm Jacobs Co, St Louis MO Jetco Contracting Co, Mobile AL	
BA-95	OO-CHK S 9Q-CHK no	tuper 18 arrive oted Salisbury N80D (1	Youngstown Airways/Lease Air, Youngstown OH Morris Grain Corp, Evansville IN Malcolm Jacobs Co, St Louis MO Jetco Contracting Co, Mobile AL George Sisk/ Orion Airways, St Louis MO	64 66 68/69
BA-95	OO-CHK S 9Q-CHK no	tuper 18 arrive oted Salisbury N80D (1	Ad Heathrow 27.8.55, dep for Tangiers 31.8.55; A Rhodesia 16.12.64;  Youngstown Airways/Lease Air, Youngstown OH Morris Grain Corp, Evansville IN Malcolm Jacobs Co, St Louis MO Jetco Contracting Co, Mobile AL George Sisk/ Orion Airways, St Louis MO Maplewood Bank & Trust Co: repossessed	64 66 68/69 3.11.69/70
BA-95	OO-CHK S 9Q-CHK no	tuper 18 arrive oted Salisbury N80D (1	Youngstown Airways/Lease Air, Youngstown OH Morris Grain Corp, Evansville IN Malcolm Jacobs Co, St Louis MO Jetco Contracting Co, Mobile AL George Sisk/ Orion Airways, St Louis MO	64 66 68/69

N386 accident report 1.3.76: Burlington Airways, stalled on approach after flight from St Cloud MN, airframe icing, 8.20pm, pilot k;

BA-96	E18S	N4966B	Roscoe Turner Aeronautical Corp	1.9.55/56
			Ebco Manufacturing Co, Columbus OH	31.1.56
			Howard Aero Inc, San Antonio TX	22.4.56
			Columbus Aviation	23.4.56/59
			Baldwin Piano Co	5.6.59/62
			Hidden Splendor Mining Co/ Atlas Corp,	
			Salt Lake City UT	24.7.62/65
			damaged taxying after landing, Moab UT	15.1.64
			Alpena Flying Service/ Detroit Northern Airlines,	
			Alpena MI	3.5.65/72
		N101SA	Shorter Airlines, Miami FL	17.3.72/75
	Hamilton		(9 passenger interior fitted 9.72,	
	extended no	ose	Hamilton extended nose installed 4.73)	
			Package Express	17.9.75/76
			Stanner Air Inc, Hollister CA	23.7.76/83
			(owner reported 2.83 aircraft destroyed/scrapped)	
			struck-off USCR	8.6.83
	N101SA not	ted Ft Lauder	rdale FL 15.9.76 long nose, all metallic;	
3A-97	E18S	N42B	Vernon L. Wright, Dartmouth MA	63/64
115-01	trigear	N6308	Vernon L. Wright, Dartmouth MA	66/69
	liligeal	N4012	Hendrix Aviation, Oxford AL	70
		114012	gear collapsed landing, Anniston AL	3.10.70
			Jack Wall Aircraft Sales, Memphis TN	72
			Gary V. Covington, Las Vegas NV	3.12.75/85
			Mexico City Airport, Mexico: retired, inst. airframe	85
			moxico ony rimport, moxico. Fourou, mot. amiumo	
3A-98	E18S	N37M	Arnold O. Morgan, Corpus Christi TX	63/79
	trigear		Richard T. Mitchell, Broussard LA	3.82
	Ü		swung landing, nose gear collapsed, Corpus Christi TX	12.8.82
			Robert J. Pate, Mission TX	5.1.84
			struck-off USCR	30.4.84
	N37M noted	d Corpus Chr	isti TX 10.5.73 trigear;	
3A-99	E18S	N18X (1	Joy Manufacturing Co, Pittsburgh PA	63/64
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	2.00	N918X	C. W. Mathews Constructing Co, Marietta GA	12.1.66/67
			crashed in water after wing spar structural failure,	
			Acworth GA	28.4.67
	N918X note	d Detroit City	Airport MI 7.4.65;	
3A-100	E18S	N27M	built	.55
		N27MD	rereg	
		N135J	J. E. Green Co, Johnson City TN	63
			Southeastern Beechcraft Inc, Kingsport TN	64
		N135FC	rereg	<b>~</b> .
		N633DN	Valley Co, Chattanooga TN	66
		11000011	Vercoa Air Service/ Allegheny Commuter, Danville IL	69/70
			op: Pennsylvania Commuter	70
			Semo Aviation/ Semo Airways, Malden MO	20.12.71/76
			crashed landing in fog, Blountville TN	8.10.76
			oracinea landing in rog, bloatityiilo TTV	5.15.75
	N633DN no	ted Washing	ton-DCA 29.4.70 Pennsylvania Commuter:	

N633DN noted Washington-DCA 29.4.70 Pennsylvania Commuter;

N633DN noted Memphis TN 22.5.72 Semo Airways;

N633DN accident report 8.10.76: Semo Aviation, crashed on approach in weather below minimums,

fog, struck fence 4.05am flight from Memphis, pilot unhurt;

BA-101	E18S -9700	N45A	Atlantic Aviation Corp American Leasing Corp, Hartford CT Isd: Ratner Manufacturing Co Lee Ratner damaged in gear-up landing, Alva FL Equilease Corp Graubart Aviation, Valparaiso IN Robinson Manufacturing Inc, Coleman MI S. W. Sisk/ Orion Airways, St Louis MO Maplewood Bank & Trust Co: repossessed Sisk Aviation Activities, St Louis MO Golden Eagle Aviation Combs Airways, Billings-Logan MT (converted to all-cargo interior 3.71) Employee Benefits Inc, Billings MT Van Dusen Acceptance Corp, Minneapolis MN Hamilton Aircraft Co, Tucson AZ (Hamilton cargo door, cockpit door installed 1.74) Flightways Corp Precision Valley Aviation, Springfield VT Rockingham Aviation Corp, Bridgewater VA Robert A. Youkin/ Youkin Air Service, Lowell AR Porsche Galesburg Inc, Galesburg IL Robert A.Younkin/ Younkin Air Service, Springdale AR op: Midwest Executive crashed, destroyed near Vienna MO	20.9.55/56 2.3.56/60 2.3.56/60 5.3.60 15.9.60 13.7.61 10.62/63 5.2.63/68 11.68/69 3.11.69 14.1.70 .70 .70/71 30.3.71/72 5.6.72/74 16.1.74 25.1.74/75 16.4.75/84 21.6.84/86 9.1.86/87 4.87 7.87/88 88 3.3.88
	N45A noted	Wilmington C	DH 2.9.74;	
BA-102	E18S	N22X (1	built New York Conservation Department, Albany NY	.55 63/64
		N422X (2	Page Airways, Rochester NY	64
		NICOCI	Charlottesville & Albermarle Bus Co, Charlottesville VA	66
		N882L	Robert A. Goodman, Memphis TN	70
			UC Leasing Inc, Memphis TN Scott M. Niswonger	72 75
			crashed, destroyed by fire, Charlotte NC	1.10.75
				1.10.75
	USCR69: no	t listed as N4	122X or N882L;	
BA-103	E18S	N24K (1	built	.55
		N791AA	rereg	00
		N791A	Mahlon C. Kline, Philadelphia PA	63 64/66
			Ritz Craft Inc, Argos IN Skystream Inc, Plymouth IN	69
			Duncan Aviation, Lincoln NE	70/72
			Hamilton Aviation, Hamilton OH	3.3.73/75
			crashed destroyed after takeoff, Toledo-Express OH	26.6.75
BA-104	E18S	N43B	reg	
DA-10 <del>1</del>	L100	CF-LPD	reg	
		CF-ALL	Lamothe Transport Co	
			crashed dest. by fire, 5 miles south Val-d'Or Airport QUE	16.6.60
BA-105	E18S	N21X	Tulsair Distributors Inc	10.10.55
	-9700		Winthrop Rockefeller, Little Rock AR	23.1.56/59
	A.T.C.		Rebsamen & East Inc, Little Rock AR	5.1.59/69
	ATE		(rebuilt as American Turbine Engine Co ATE Westwind I:	
	Westwind I		PT6A turbines, trigear completed 6.66, CofA issued 23.6.	•
	trigear	N521GP	windscreen struck by large bird, Walnut Ridge AR Georgia-Pacific Corp, Portland OR	21.9.67 31.1.69/74
		1402 101	Dole Aviation	26.3.74/75
	Hamilton		(rebuilt at Tucson AZ 7.74 by Hamilton Aircraft Co as	20.0.1 7/10
	Westwind III		Hamilton Westwind III: Volpar trigear replaced by	
	tailgear		conventional tailgear, Hamilton extended cargo nose	
	J		& cargo door, cockpit hatch)	
			- · · · · · · · · · · · · · · · · · · ·	

Great Western Airlines, Tulsa OK	3.11.75/81
damaged when hit snowbank on takeoff, Springfield IL	27.1.79
Mark Peterson/ Desert Flying Service, Tonopah NV	1.5.81
Gold Creek Mining & Development Corp	20.7.81
deliberately destroyed by fire on ground Mexico,	
after attempted overloaded takeoff with drugs	.81
(Peterson arrested by DEA: Gold Creek Mining	
was a hogus sale)	

N21X noted Prestwick, Scotland 21.6.56 owned W. Rockefeller; N521GP noted Brownsville TX 8.5.79 freighter no titles, turbine tailwheel, extended nose;

BA-106	E18S	N46M	Elliot Flying Service	14.10.55
			Collins Radio Co, Cedar Rapids IA	10.55/65
			Wiles Holloway Inc, Baton Rouge LA	26.2.65/68
			struck powerlines landing, Fairhope AL	17.2.67
			King's Flying Service, Olathe KS	19.8.68/69
			Avonics Inc	12.69/70
			Broadcast Industries Inc, Philadelphia PA	10.70/72
			Virginia Aviation	20.7.72/74
			US Government: forfeited by court order	22.4.74
			Leon Redman/ Lee's Motor City	19.6.74
			Volpar Inc, Van Nuys CA	24.7.74
	Volpar		(conversion to Volpar Turboliner II completed 11.7.75:	
	Turboliner II		turbines, 81" fuselage extension, Volpar trigear)	
	trigear	N900WA Volpar Inc, Van Nuys CA William E. Winship/ Winship Air Service/ Airco	Volpar Inc, Van Nuys CA	2.7.75
	(#19)		William E. Winship/ Winship Air Service/ Aircon Co,	
			Anchorage AK Alaskan Trader	10.75/82
			Troy Air Inc, Anchorage AK	11.82/85
		N900TH	Troy Air Inc, Anchorage AK	8.7.85/90
			op: FS Flying Service, Anchorage AK	90
			emergency landing wheels-up, Anchorage AK	15.1.90
			Connie Kalitta Services, Willow Run MI	30.5.90
			renamed: American International Airways, Willow Run MI	10.90/92
			renamed: Kalitta Flying Service, Detoit-Willow Run MI	1.1.92/99
			(stored damaged Willow Run 91/98, dismantled 98)	
			Kitty Hawk Charters Inc, Morristown TN	15.6.99/04
			"sold for scrap 9.01", struck-off USCR	1.7.04
			-	

N900WA noted Anchorage AK 3.7.76 Winship Air Service;

N900WA noted Anchorage AK 3.7.76 Winship Air Service,
N900WA noted Anchorage 1.9.76;
N900TH accident report 15.1.90: FS Flying Service, emergency landing after takeoff;
N900TH noted Anchorage AK 27.5.90 Turboliner;
N900TH noted Willow Run MI 7.91 Connie Kalitta, trigear turbine, stored poor condition,

plates: BA-106 & Volpar conversion #19;

	•	•	Run MI 7.98 dismantled;	
BA-107	E18S -9700	N29W	Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN	26.10.55/63 63
			Frank D. Hansen/ Hansen Air Activities, Morris IL	4.6.63/65
			Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation,	1.4.65/66
			Peoria IL (cargo door installed 5.68)	26.2.66/69
			Atlas Cargo Airlines	10.69
			JSA Financial Corp, Boston MA	70
			Byerly Aviation, Peoria IL	19.9.70
			dest. by fire ground collision with Cessna 337, Keokuk IA	29.9.70
			sale reported, Keokuck IA: USCR	72/91
BA-108	E18S	N45B	built	.55
		N102MC	Commonwealth Plan Inc, Boston MA	62/64
		N405T	Trostel Aviation Co, Milwaukee WI	66
			Gweneth C. Landry, East Troy WI	69/72
			Business Aircraft Leasing, East Troy WI	79
			Mode Air Enterprises, Delray Beach FL	1.82

	George K. Armagost/ Pro Air Services, Opa Locka FL	6.82/83
	Pamela E. Shanks, Woodland CA	22.2.83
	sold to Canada, struck-off USCR	31.8.83
C-GIFR	Byron Armstrong, Campbell River BC	11.83/84
	lsd: CoVal Air Ltd, Campbell River BC	.83/84
	crashed on takeoff Port Hardy BC (9k)	2.7.84

C-GIFR noted Vancouver 26.6.84 Coval Air;

BA-109	E18S	N44N	The Norman Larson Co	9.11.55
			McCulloch Motors Corp/ McCulloch Corp,	
			Los Angeles CA	9.11.55/68
			Valley Airlines, Phoenix AZ	10.6.68
			McCulloch Corp, Los Angeles CA	26.9.68/70
			J. W. Duff Aircraft Co, Denver CO	10.9.70/71
			Leo Pike/ Bakersfield Aviation Service CA	12.2.71/72
			Sierra West Airlines, Oxnard CA	5.4.74/75
			Avenales Aviation Inc, Las Vegas NV	16.5.75/76
			Great Western Airlines, Tulsa OK	15.10.76
			Sam Vires/ Mid-South Aircraft Sales, Memphis TN	10.76/77
			Deleware Valley Airways	28.2.77
			(cargo door installed 2.77)	
			Jamson Corp, Palmyra NY	14.3.77/82
			Coker Air Freight, Dallas TX	26.7.82/84
			nn: Skyfreighters Corp, Dallas TX	1.5.84
			Allen Godwin/ Memphis Recipro	25.7.84
			Sam Vires/ Mid-South Aircraft Sales, Memphis TN	1.1.85
			op: Skyfreighters Corp, Dallas TX	85
			forced landing in field, Billings MT after struck by lightning	]
			and right engine deflected downwards due turbulence sold: documentation not completed	15.8.85

N44N photo Long Beach 1959 titles "McCulloch Motors Inc, Los Angeles" N44N noted Long Beach CA 18.9.67; N44N noted Bakersfield-Meadows Field CA 20.4.72

F18S	N38Δ	Currey Sanders Aircraft Co. CofA issued	11.11.55
L100	NOOA		12.55/57
			22.1.57/61
			19.6.61/62
			11.62/63
trigear			11.02/00
900			3.9.63/67
			1.2.67/69
Volpar		•	1.2.01700
•			
	N352V		
			21.4.69/74
Turboliner	II		
		()	Fairbanks Flight
`	,		
		oor installed 23.9.74)	
(		·	1.76
	N115PA		25.4.76/78
		•	19.4.78
	N17SL		21.7.78/81
	N408TH		13.5.81/84
		Connie Kalitta Services, Willow Run MI	10.2.84/90
		renamed: American International Airways, Willow Run M	10.90/92
			1.1.92/99
			6.5.99/01
			29.1.02/20
			nrs)
	(conv. #01 airbanks AK	trigear  Volpar Turboliner N352V  Turboliner II (conv. #011) airbanks AK 5.2.74/76 (cargo door & cockpit ding N115PA N17SL	Tecon Engineers Inc, Frankfort KY Capitol Engineering Services, Frankfort KY Blue Grass Airmotive Inc Capitol Aviation, Springfield IL (Volpar Mk.IV trigear installed 6.63) Atkinson & Co, Indianapolis IN Ransome Air Inc, Philadelphia PA  Volpar (converted to Volpar Turboliner, Kit #011 23.4.69: Turboliner turbines, 81" fuse. extension, ventral fin; N352V Ransome Air/ Allegheny Commuter, Philadelphia PA Flagship North Phillie  Turboliner II (further modified 4.73 to Volpar Turboliner II) (conv. #011) airbanks AK 5.2.74/76 (cargo door & cockpit door installed 23.9.74) Polar Airways, Anchorage-Merrill Field AK N115PA Polar Airways, Anchorage-Merrill Field AK Soonair Lines Inc, Tulsa OK N17SL Soonair Lines Inc, Tulsa OK N408TH Troy Air Inc, Anchorage AK

N352V noted Washington-DCA 30.9.70 Allegheny Commuter,

N352V noted Trenton NJ 22.7.72 Allegheny Commuter;

N352V noted Philadelphia PA 8.73 Turboliner "Allegheny Commuter" titles;

N352V noted Boeing Field WA 18.9.75 type V T-L, "Fairbanks FLIGHT" titles;

N17SL noted Detroit-Metro MI 22.9.79 Soonair, Turboliner, freighter;

N17SL noted Kansas City Downtown MO 26.8.80 Turboliner "Soonair" titles;

N408TH noted Columbus OH 17.4.83 Turboliner, ex Troy Air;

N408TH noted Willow Run MI 7.91 Connie Kalitta, turbine trigear, plates BA-110, Volpar #011;

N408TH noted Willow Run 12.6.96 Kalitta. noted as Turboliner:

N408TH Willow Run 8.97 Kalitta, noted as Turboliner;

N408TH noted Boston-Logan MA 22.8.98 Turboliner Kalitta FS;

N408TH noted Willow Run 3.8.99;

N408TH noted Ankeky IA 31.7.03 Turboliner trigear, no titles, ex Kalitta scheme, appears in service

N408TH noted Ankeny IA 22.7.06 Turboliner, no engines; Ankeny IA 24.7.08, red & gold;

N408TH noted Ankeny 24.7.14 Turboliner, white with red & gold trim, operational; same 16.7.15;

BA-111	E18S	N24R	Beech Aircraft Corp: built	8.55
	-9700		Atlantic Aviation Services	12.12.55
		N555CB (1	Cleveland Brothers Equipment Co, Harrisburg PA	.56
			(mods to E18S-9700, 3 bladed props completed 10.59)	
		N575C	Univac Division, Sperry Rand Corp	19.10.62/64
			National Financing Inc, Wilmington DE: USCR	63/64
			Atlantic Aviation Corp, Teterboro NJ	5.64
			sold to Great Britain, struck-off USCR	30.6.64
			(ferry tanks installed Amityville NY, dep. on del. 11.6.64,	
			N575C arr. London-Gatwick 15.6.64)	
		G-ASUG	Survey Flights Ltd, Coleraine, Northern Ireland	7.64/68
			(British CofA issued 31.3.65 after transparent nose cone	
			and other survey mods completed at Stansted)	
			Loganair Ltd, Glasgow-Abbotsinch: delivered	28.5.68/76
	E18S-9700		(mod. to E18S-9700 11.2.69)	
			retired Glasgow-Abbotsinch	12.3.75
			Museum of Flight, East Fortune, Scotland	3.76/20
			(displayed as "G-ASUG Loganair")	

N575C noted London-Gatwick 15.6.64 (plate BA-111), 16.6.64 & 2.8.64;

Originally planned to have survey nose and camera gear installed by Air Couriers Ltd at Gatwick, But G-ASUG flown Gatwick-Stansted 12.8.64 for Field Aircraft Services to install perspex nose and survey camera gear, cream & brown; departed Stansted 3.65 on completion of mods by Fields; G-ASUG noted Leeds-Bradford (Yeadon) 28.3.65 owned Survey Flights (Yeadon) Ltd, a subsidiary

## of BKS Aerial Surveys

G-ASUG departed Stansted 4.65 after 7 months here with Survey Flights;

G-ASUG noted Newcastle 4.4.65 survey flying, to Yeadon;

G-ASUG noted Dublin 7.4.65 Survey Flights Ltd: first visit of many on survey ops;

G-ASUG visited Lulsgate 27.6.65 on survey flight;

G-ASUG visited Stansted 16.10.65 Survey Flights;

G-ASUG visited Dublin 27.2.66;

G-ASUG arrived Stansted 7.12.65 for overhaul by Fields for Survey Flights, testflown 21.12.65 after overhaul;

G-ASUG arrived Stansted 28.7.66 for overhaul by Fields for Survey Flights;

G-ASUG visited Dublin 6.6.67 Survey Flights;

G-ASUG visited Newcastle 2.11.65 Survey Flights, refuelled while operating in the area;

## G-ASUG visited Gatwick 23.4.66;

G-ASUG returned to Yeadon 22.1.67 where based after overhaul and respray at Stansted;

G-ASUG visited Exeter 8.2.67, visited Gatwick 12.3.67;

G-ASUG arrived Abotsinch on delivery to Loganair 28.5.68;

Purchased by Loganair 5.68 and used for passenger services, including a Scandinavian passenger service Glasgow-Aberdeen-Stavanger 7.69-11.70, then charter work from Glasgow until grounded 3.75 due cost of regulatory wingspar inspection;

G-ASUG noted Dublin 28.2.70 Loganair; Dublin 4.71, 8.71, 10.71, 3.74, 9.74, all Loganair;

G-ASUF visited Cork 30.4.74; Heathrow 17.10.74 Loganair;

last Dublin visit 10.3.75 Loganair;

retired Abbotsinch 12.3.75 ahead of CofA expiry 23.7.75:

G-ASUG noted in museum East Fortune 10.8.02:

BA-112	E18S	N62B	Beech Aircraft, Wichita KS	.55			
B/( 112	2.00	11025	(demonstrator "Super 18" model .55)	.00			
			Warren Teed Products Co. Columbus OH	62			
			,	63			
			Jack Adams Aircraft Sales, Walls MS	64			
			Air Credit Inc, Long Beach CA	66			
			Mobile Aircraft Inc, Mobile AL	69			
			Northern Airlines, St Marys OH	70			
			Jed Air Inc	76			
			Francisco Cruz, San Juan, Puerto Rico	14.4.77/79			
			op: Air Caribbean, San Juan, Puerto Rico	79			
			crashed destroyed in night landing on abandoned strip,				
			cocaine on board, San Juan, Puerto Rico	13.7.79			
	N62B noted San Juan PR 30.4.78;						
3A-113	E18S	N81D (1	Youngstown Airways, Youngstown OH	1.12.55			
37-113	L103	ו) טוטאו					
			The Wean Engineering Co	12.55/56			
			Lease Air Inc	10.7.56/60			
		N8111	Jack Adams Aircraft Sales, Walls MS	10.60/61			
			Farrell-Cheek Steel Co of Delaware, Sandusky OH	2.3.61/64			
			Crescent City Aviation, Evansville IN	10.64/69			
			Lexington Airways, Lexington KY	25.2.69/70			
			op: Lexington Air Taxi, Lexington KY	69			
			Alliance Aero Enterprises, Jackson OH	22.4.70			
			Flint Air	11.8.70/71			
			Hamilton Aircraft Co, Tucson AZ	24.6.71/73			
			(converted to all-cargo configuration 12.73)				
			Banner Flight Ltd	12.73/75			
			Precision Valley Aviation, Springfield VT	1.75/84			
			(operated windowless, "Precision Freighter" titles)				
			damaged, hit snowbank landing, Boston-Logan MA	31.1.77			
			Rockingham Aviation Corp/ K&K Aircraft, Bridgewater VA	1 21.0.84/89			
			(converted for aerial application, 350 gallon cabin				
			chemical tank installed 4.85 for gipsy moth and mosquito				
			spraying contracts)				
			Bill Walker & Associates, St Simons Island GA	.89			
			Center Air Inc, Greenville SC	10.89/90			
			Milton B. & Darlene P. Henry, Juno FL	14.2.91			
			Westwind Trading Inc, Lake Worth FL	10.12.91			
			Jetlease Finance Corp, Fort Lauderdale FL	9.9.93/95			
			op: Caribe Air Cargo	95			
			ditched during landing, Walkers Cay, Bahamas	23.3.95			
	N8111 noted Stewart NY 11.8.74; N8111 accident report 31.1.77: Precision Valley, groundloop on landing from Keen NH, 8.30pm, pilot unhurt; N8111 noted Boston-Logan MA 8.78, tailwheel, windowless "Precision Freighter", in service;						
			erdale-Executive FL 10.11.91 all metallic;	20			
BA-114	E18S	N52A	Atlantic Aviation Service	8.12.55			
	-9700		E. I. duPont de Nemours & Co, Wilmington DE	12.55/60			
	0.00		Lehigh Portland Cement Co, Allentown PA	11.60/65			
			T. R. Carpenter/ Flight Service Inc/ Empire State Airlines				
			Syracuse NY	3.1.66/72			
			Tampa Air Centre Inc, Tampa FL	19.5.72			
			William G. Thomas	2.1.73/75			
			(cargo floor installed 1.73, cargo door 10.74)				

(cargo floor installed 1.73, cargo door 10.74)
Stockert Flying Service, South Bend IN
(cockpit door installed 1.77)
AeroServ Inc

St. Joseph Bank & Trust Co Bruce & Mark McSwiggan, Fayetteville GA

gear collapsed taxiing, Anderson SC

Tol-Air Services, San Juan, Puerto Rico MBD Corp, San Juan, Puerto Rico 5.6.75/79

27.6.79

25.5.99

5.2.97/99 8.2.99/01

8.9.79/82 9.2.82/97 (retired, stripped San Juan, Puerto Rico 12/13)

reg expired 31.12.13, struck-off USCR 26.1.18

N52A noted Indianapolis IN 28.4.79 titles "Stockert Flying Service/SFS Freightliner";

N52A noted Atlanta GA 8.9.82 SFS Freighter;

N52A noted Griffin GA 12.92 all metallic;

N52A noted Griffin GA 26.6.96, metallic, in service;

N52A noted St Croix USVI 1.97 "Tol Air":

N732T noted Opa Locka FL 4.11.04;

N732T noted Tamiami FL 10.8.05;

BA-115	E18S	N39A	IBM Corp	
	trigear		American Aero Leasing Corp, Elizabeth NJ	63/66
	Ü		Leasing Consultants Inc, Forest Hill NY	69
			Bonita Airlines, San Juan, Puerto Rico	70
			op: South Atlantic Airlines, Hilton Head Island SC	71
			op: Caribbean Island Airways, San Juan, Puerto Rico	.71
			op: Caribbean Executive Airlines	71
			Pleasant Financing Co, Lynn MA	72
			ditched in Pacific Ocean, 22 miles from Maui HI,	
			on ferry flight Honolulu-Van Nuys CA	12.6.74
	=			
BA-116	E18S	N29S (2	J. R. Gray Co, Dallas TX	12.55
			Sun Oil Co/ Sun Pipe Line Co, Philadelphia PA	12.55/64
			(D18S N29S traded in on E18S 12.55)	
		N290S	Houston Beechcraft Inc, Houston TX	66
			Fort Myers Airways, Fort Myers FL	13.12.67
		N281FM	Miller Aviation	
			crashed destroyed, forced landing due in-flight fire,	
			Salisbury NC	2.3.68

N281FM accident report: Miller Aviation, struck trees during forced landing on cargo flight due fire in cabin and cockpit;

BA-117	E18S	N42D	Southern Airways Co	27.12.55
	-9700		Southern Aircraft Co	29.6.56/57
			Watkins Motor Lines Inc, Miami FL	19.4.57/65
			minor damage, landing Thomasville GA	13.2.60
			Flowers Baking Co, Thomasville GA	11.65/69
			Properties Inc, Jacksonville FL: USCR	66
			Allied Helicopter Service, Tulsa OK	30.6.69/73
			S. S. Airways, Kansas City KS	22.6.73/81
			Methow Aviation, Wenatchee WA & Everett WA	29.5.81/98
			lsd: Airpac Airlines, Seattle WA	81 /84
			Comanche Air, Winthrop WA	25.9.98/06
			op: Methow Aviation, Everett-Paine Field WA	00/06
			Emerald Aircraft LLC, Issaquah WA	22.11.06/11
			Northern Aviation LLC, Palmer AK (bulk fuel carrier)	12.1.12/18
			struck-off USCR	8.6.18
		N42D	Raymond A. Evarts, Cedar City UT: rest. to USCR	1.11.18/19
			Michael A. Majerle, Big Lake AL	11.3.19/20

N42D noted Kansas City KS 28.8.79 tailwheel, no titles;

N42D noted Burbank CA 4.6.85 "Methow" titles, in service, tailwheel;

N42D noted Arlington WA 11.8.98 "Methow titles, tailwheel, in service;

N42D noted Friday Harbour WA 21.9.99 on mail run from Paine Field, rep. op Methow Aviation, tailwheel, "Methow" above cabin windows;

N42D noted Moses Lake WA 5.01 Methow Aviation;

N42D noted Arlington WA 3.6.02 "Methow" tailwheel in service;

N42D noted Seattle-Boeing field 27.4.04 "Methow" in service;

N42D noted Ephrata WA 16.9.04 "Methow", tailwheel, in service;

N42D noted Renton WA 21.10.06 "Methow", tailwheel, in service;

BA-118	E18S	N23X	Vernon F. Neuhaus, Mission TX	63/70
		N23XY	Stripling Coleman, El Paso TX	72
			Omar Stoltzfus, Salisbury MD crashed destroyed after takeoff, Salisbury MD	28.2.75 15.5.75
			15.5.75: destroyed 12.07am, engine failure after takeoff, t, 1k 4 hurt, departing on flight to Haiti, 400lb over Gross I	
BA-119	E18S	N63B	Beech Aircraft Corp, Wichita KS	11.1.56
371 110	2.00	11002	(CofA for experimental research & development)	
			Atlantic Aviation Corp	9.5.56
			Air Associates Inc	10.56/57
			Trade-Ayer Inc, Linden NJ	4.3.57/58
			C. K. McCan, Victoria TX	25.7.58/71
			George A. Constant	7.7.71/72
			Apollo Airways, Detroit MI	17.7.73/79
			(conversion to all-cargo configuration completed 7.73)	
			renamed: Gelco Courier Services, Chicago IL	79
			United Leasing Corp	4.79/83
			Isd: Little Mountain Airport Inc/	
			Mountain Air Cargo, Denver NC	3.5.79/85
			Equipment Leasing Corp, Greenville SC	19.8.83/85
			Coastal States Aviation, Denver NC	2.85
			J. Richard Wixom/ Blackhawk Airways, Janesville WI	20.3.85/86
			Charles J. Vannoy/ K-Airways, Kenosha WI	21.5.86/88
			Northern Airmotive Corp, Kenosha WI crashed in forced landing, destroyed, Martinsville OH	29.8.88/91 20.8.91
	N63B note	d Kenosha W	「16.6.74, "Apollo Airways" titles, tailwheel, in service; /I 7.91, plate BA-119; ced landing off airport after takeoff Martinsville OH. opera	ated bv Garv
) A 120	N63B note 20.8.91 cra Jelinek;	d Kenosha W ash report: for	/I 7.91, plate BA-119; reed landing off airport after takeoff Martinsville OH, opera	
3A-120	N63B note 20.8.91 cra	d Kenosha W	/I 7.91, plate BA-119; ced landing off airport after takeoff Martinsville OH, opera Ohio Aviation Co, Dayton OH	6.1.56
3A-120	N63B note 20.8.91 cra Jelinek;	d Kenosha W ash report: for N52C	7/1 7.91, plate BA-119; rced landing off airport after takeoff Martinsville OH, opera Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA	6.1.56 6.1.56/67
3A-120	N63B note 20.8.91 cra Jelinek;	d Kenosha W ash report: for	71.7.91, plate BA-119; reed landing off airport after takeoff Martinsville OH, operation Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA George M. Humphrey, Cleveland OH	6.1.56 6.1.56/67 2.6.67/70
3A-120	N63B note 20.8.91 cra Jelinek;	d Kenosha W ash report: for N52C	7/1 7.91, plate BA-119; rced landing off airport after takeoff Martinsville OH, opera Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA	6.1.56 6.1.56/67 2.6.67/70
3A-120	N63B note 20.8.91 cra Jelinek;	d Kenosha W ash report: for N52C	Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA George M. Humphrey, Cleveland OH Morrow Aviation Co, Marion OH Van Dusen Acceptance Corp, Minneapolis MN Hamilton Aircraft Co, Tucson AZ	6.1.56 6.1.56/67 2.6.67/70 26.5.70/72
8A-120	N63B note 20.8.91 cra Jelinek;  E18S  Hamilton	d Kenosha W ash report: for N52C	Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA George M. Humphrey, Cleveland OH Morrow Aviation Co, Marion OH Van Dusen Acceptance Corp, Minneapolis MN Hamilton Aircraft Co, Tucson AZ (cargo conversion and Hamilton extended nose fitted	6.1.56 6.1.56/67 2.6.67/70 26.5.70/72 23.6.72/74
3A-120	N63B note 20.8.91 cra Jelinek;  E18S  Hamilton Extended	d Kenosha W ash report: for N52C	77.91, plate BA-119; reed landing off airport after takeoff Martinsville OH, operation Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA George M. Humphrey, Cleveland OH Morrow Aviation Co, Marion OH Van Dusen Acceptance Corp, Minneapolis MN Hamilton Aircraft Co, Tucson AZ (cargo conversion and Hamilton extended nose fitted by Hamilton Aircraft Co at Tucson AZ 9.74)	6.1.56 6.1.56/67 2.6.67/70 26.5.70/72 23.6.72/74 14.8.74
3A-120	N63B note 20.8.91 cra Jelinek;  E18S  Hamilton	d Kenosha W ash report: for N52C	Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA George M. Humphrey, Cleveland OH Morrow Aviation Co, Marion OH Van Dusen Acceptance Corp, Minneapolis MN Hamilton Aircraft Co, Tucson AZ (cargo conversion and Hamilton extended nose fitted by Hamilton Aircraft Co at Tucson AZ 9.74) Chris Crowell & Co Inc	6.1.56 6.1.56/67 2.6.67/70 26.5.70/72 23.6.72/74 14.8.74 7.10.74/75
BA-120	N63B note 20.8.91 cra Jelinek;  E18S  Hamilton Extended	nd Kenosha W ash report: for N52C N152H	Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA George M. Humphrey, Cleveland OH Wan Dusen Acceptance Corp, Minneapolis MN Hamilton Aircraft Co, Tucson AZ (cargo conversion and Hamilton extended nose fitted by Hamilton Aircraft Co at Tucson AZ 9.74) Chris Crowell & Co Inc Palm Beach Air Traders	6.1.56 6.1.56/67 2.6.67/70 26.5.70/72 23.6.72/74 14.8.74 7.10.74/75 2.4.75
BA-120	N63B note 20.8.91 cra Jelinek;  E18S  Hamilton Extended	nd Kenosha W ash report: for N52C N152H	Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA George M. Humphrey, Cleveland OH Worrow Aviation Co, Marion OH Van Dusen Acceptance Corp, Minneapolis MN Hamilton Aircraft Co, Tucson AZ (cargo conversion and Hamilton extended nose fitted by Hamilton Aircraft Co at Tucson AZ 9.74) Chris Crowell & Co Inc Palm Beach Air Traders Florida Airmotive Inc, Lantana-Palm Beach FL	6.1.56 6.1.56/67 2.6.67/70 26.5.70/72 23.6.72/74 14.8.74 7.10.74/75 2.4.75
BA-120	N63B note 20.8.91 cra Jelinek;  E18S  Hamilton Extended	nd Kenosha W ash report: for N52C N152H	Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA George M. Humphrey, Cleveland OH Wan Dusen Acceptance Corp, Minneapolis MN Hamilton Aircraft Co, Tucson AZ (cargo conversion and Hamilton extended nose fitted by Hamilton Aircraft Co at Tucson AZ 9.74) Chris Crowell & Co Inc Palm Beach Air Traders Florida Airmotive Inc, Lantana-Palm Beach FL (Florida Airmotive request N171LG be removed	6.1.56 6.1.56/67 2.6.67/70 26.5.70/72 23.6.72/74 14.8.74 7.10.74/75 2.4.75
BA-120	N63B note 20.8.91 cra Jelinek;  E18S  Hamilton Extended	nd Kenosha W ash report: for N52C N152H	Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA George M. Humphrey, Cleveland OH Morrow Aviation Co, Marion OH Van Dusen Acceptance Corp, Minneapolis MN Hamilton Aircraft Co, Tucson AZ (cargo conversion and Hamilton extended nose fitted by Hamilton Aircraft Co at Tucson AZ 9.74) Chris Crowell & Co Inc Palm Beach Air Traders Florida Airmotive Inc, Lantana-Palm Beach FL (Florida Airmotive request N171LG be removed from register: letter to FAA 4.6.83)	6.1.56 6.1.56/67 2.6.67/70 26.5.70/72 23.6.72/74 14.8.74 7.10.74/75 2.4.75 9.10.75/83
3A-120	N63B note 20.8.91 cra Jelinek;  E18S  Hamilton Extended	nd Kenosha W ash report: for N52C N152H	Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA George M. Humphrey, Cleveland OH Morrow Aviation Co, Marion OH Van Dusen Acceptance Corp, Minneapolis MN Hamilton Aircraft Co, Tucson AZ (cargo conversion and Hamilton extended nose fitted by Hamilton Aircraft Co at Tucson AZ 9.74) Chris Crowell & Co Inc Palm Beach Air Traders Florida Airmotive Inc, Lantana-Palm Beach FL (Florida Airmotive request N171LG be removed from register: letter to FAA 4.6.83) struck-off USCR	6.1.56 6.1.56/67 2.6.67/70 26.5.70/72 23.6.72/74 14.8.74 7.10.74/75 2.4.75
BA-120	N63B note 20.8.91 cra Jelinek;  E18S  Hamilton Extended	nd Kenosha W ash report: for N52C N152H	Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA George M. Humphrey, Cleveland OH Morrow Aviation Co, Marion OH Van Dusen Acceptance Corp, Minneapolis MN Hamilton Aircraft Co, Tucson AZ (cargo conversion and Hamilton extended nose fitted by Hamilton Aircraft Co at Tucson AZ 9.74) Chris Crowell & Co Inc Palm Beach Air Traders Florida Airmotive Inc, Lantana-Palm Beach FL (Florida Airmotive request N171LG be removed from register: letter to FAA 4.6.83)	6.1.56 6.1.56/67 2.6.67/70 26.5.70/72 23.6.72/74 14.8.74 7.10.74/75 2.4.75 9.10.75/83
BA-120	N63B note 20.8.91 cra Jelinek;  E18S  Hamilton Extended Nose  N152H note N171LG note	N52C N152H  N171LG (1	Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA George M. Humphrey, Cleveland OH Wan Dusen Acceptance Corp, Minneapolis MN Hamilton Aircraft Co, Tucson AZ (cargo conversion and Hamilton extended nose fitted by Hamilton Aircraft Co at Tucson AZ 9.74) Chris Crowell & Co Inc Palm Beach Air Traders Florida Airmotive Inc, Lantana-Palm Beach FL (Florida Airmotive request N171LG be removed from register: letter to FAA 4.6.83) struck-off USCR (broken-up: cargo door & cockpit entrance door	6.1.56 6.1.56/67 2.6.67/70 26.5.70/72 23.6.72/74 14.8.74 7.10.74/75 2.4.75 9.10.75/83
BA-120 BA-121	N63B note 20.8.91 cra Jelinek;  E18S  Hamilton Extended Nose  N152H note N171LG note	N52C N152H  N171LG (1	Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA George M. Humphrey, Cleveland OH Morrow Aviation Co, Marion OH Van Dusen Acceptance Corp, Minneapolis MN Hamilton Aircraft Co, Tucson AZ (cargo conversion and Hamilton extended nose fitted by Hamilton Aircraft Co at Tucson AZ 9.74) Chris Crowell & Co Inc Palm Beach Air Traders Florida Airmotive Inc, Lantana-Palm Beach FL (Florida Airmotive request N171LG be removed from register: letter to FAA 4.6.83) struck-off USCR (broken-up: cargo door & cockpit entrance door ex BA-120 installed in BA-16/N255D 6.84)  Z 20.9.74 inside Hamilton hangar, extended nose just installed FL 16.3.81 reported as Hamilton Westwind;  Topeka Aircraft Sales & Service, Topeka KS	6.1.56 6.1.56/67 2.6.67/70 26.5.70/72 23.6.72/74 14.8.74 7.10.74/75 2.4.75 9.10.75/83 9.83
	N63B note 20.8.91 cra Jelinek;  E18S  Hamilton Extended Nose  N152H note N171LG n	ted Kenosha Wash report: for N52C N152H N171LG (1 ted Tucson A2oted Miami 4.oted Ft Laude	Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA George M. Humphrey, Cleveland OH Morrow Aviation Co, Marion OH Van Dusen Acceptance Corp, Minneapolis MN Hamilton Aircraft Co, Tucson AZ (cargo conversion and Hamilton extended nose fitted by Hamilton Aircraft Co at Tucson AZ 9.74) Chris Crowell & Co Inc Palm Beach Air Traders Florida Airmotive Inc, Lantana-Palm Beach FL (Florida Airmotive request N171LG be removed from register: letter to FAA 4.6.83) struck-off USCR (broken-up: cargo door & cockpit entrance door ex BA-120 installed in BA-16/N255D 6.84)  Z 20.9.74 inside Hamilton hangar, extended nose just installed FL 16.3.81 reported as Hamilton Westwind;  Topeka Aircraft Sales & Service, Topeka KS Panhandle Eastern Pipe Line Co	6.1.56 6.1.56/67 2.6.67/70 26.5.70/72 23.6.72/74 14.8.74 7.10.74/75 2.4.75 9.10.75/83 9.83
	N63B note 20.8.91 cra Jelinek;  E18S  Hamilton Extended Nose  N152H note N171LG n	ted Kenosha Wash report: for N52C N152H N171LG (1 ted Tucson A2oted Miami 4.oted Ft Laude	Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA George M. Humphrey, Cleveland OH Morrow Aviation Co, Marion OH Van Dusen Acceptance Corp, Minneapolis MN Hamilton Aircraft Co, Tucson AZ (cargo conversion and Hamilton extended nose fitted by Hamilton Aircraft Co at Tucson AZ 9.74) Chris Crowell & Co Inc Palm Beach Air Traders Florida Airmotive Inc, Lantana-Palm Beach FL (Florida Airmotive request N171LG be removed from register: letter to FAA 4.6.83) struck-off USCR (broken-up: cargo door & cockpit entrance door ex BA-120 installed in BA-16/N255D 6.84)  Z 20.9.74 inside Hamilton hangar, extended nose just installed FL 16.3.81 reported as Hamilton Westwind; Topeka Aircraft Sales & Service, Topeka KS Panhandle Eastern Pipe Line Co S & S Aviation Inc	6.1.56 6.1.56/67 2.6.67/70 26.5.70/72 23.6.72/74 14.8.74 7.10.74/75 2.4.75 9.10.75/83 9.83
	N63B note 20.8.91 cra Jelinek;  E18S  Hamilton Extended Nose  N152H note N171LG n	ted Kenosha Wash report: for N52C N152H N171LG (1 ted Tucson A2oted Miami 4.oted Ft Laude	Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA George M. Humphrey, Cleveland OH Wan Dusen Acceptance Corp, Minneapolis MN Hamilton Aircraft Co, Tucson AZ (cargo conversion and Hamilton extended nose fitted by Hamilton Aircraft Co at Tucson AZ 9.74) Chris Crowell & Co Inc Palm Beach Air Traders Florida Airmotive Inc, Lantana-Palm Beach FL (Florida Airmotive request N171LG be removed from register: letter to FAA 4.6.83) struck-off USCR (broken-up: cargo door & cockpit entrance door ex BA-120 installed in BA-16/N255D 6.84)  Z 20.9.74 inside Hamilton hangar, extended nose just installed FL 16.3.81 reported as Hamilton Westwind;  Topeka Aircraft Sales & Service, Topeka KS Panhandle Eastern Pipe Line Co S & S Aviation Inc Tempo Design Corporation, Miami FL	6.1.56 6.1.56/67 2.6.67/70 26.5.70/72 23.6.72/74 14.8.74 7.10.74/75 2.4.75 9.10.75/83 9.83
	N63B note 20.8.91 cra Jelinek;  E18S  Hamilton Extended Nose  N152H note N171LG n	ted Kenosha Wash report: for N52C N152H N171LG (1 ted Tucson A2oted Miami 4.oted Ft Laude	Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA George M. Humphrey, Cleveland OH Wan Dusen Acceptance Corp, Minneapolis MN Hamilton Aircraft Co, Tucson AZ (cargo conversion and Hamilton extended nose fitted by Hamilton Aircraft Co at Tucson AZ 9.74) Chris Crowell & Co Inc Palm Beach Air Traders Florida Airmotive Inc, Lantana-Palm Beach FL (Florida Airmotive request N171LG be removed from register: letter to FAA 4.6.83) struck-off USCR (broken-up: cargo door & cockpit entrance door ex BA-120 installed in BA-16/N255D 6.84)  Z 20.9.74 inside Hamilton hangar, extended nose just installed FL 16.3.81 reported as Hamilton Westwind;  Topeka Aircraft Sales & Service, Topeka KS Panhandle Eastern Pipe Line Co S & S Aviation Inc Tempo Design Corporation, Miami FL Continental Aviation Corp, Opa Locka FL	6.1.56 6.1.56/67 2.6.67/70 26.5.70/72 23.6.72/74 14.8.74 7.10.74/75 2.4.75 9.10.75/83 9.83 talled, radials, 12.1.56 12.1.56/62 2.7.62 63 10.63/64
	N63B note 20.8.91 cra Jelinek;  E18S  Hamilton Extended Nose  N152H note N171LG n	ted Kenosha Wash report: for N52C N152H N171LG (1 ted Tucson A2oted Miami 4.oted Ft Laude	Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA George M. Humphrey, Cleveland OH Morrow Aviation Co, Marion OH Van Dusen Acceptance Corp, Minneapolis MN Hamilton Aircraft Co, Tucson AZ (cargo conversion and Hamilton extended nose fitted by Hamilton Aircraft Co at Tucson AZ 9.74) Chris Crowell & Co Inc Palm Beach Air Traders Florida Airmotive Inc, Lantana-Palm Beach FL (Florida Airmotive request N171LG be removed from register: letter to FAA 4.6.83) struck-off USCR (broken-up: cargo door & cockpit entrance door ex BA-120 installed in BA-16/N255D 6.84)  Z 20.9.74 inside Hamilton hangar, extended nose just installed FL 16.3.81 reported as Hamilton Westwind;  Topeka Aircraft Sales & Service, Topeka KS Panhandle Eastern Pipe Line Co S & S Aviation Inc Tempo Design Corporation, Miami FL Continental Aviation Corp, Opa Locka FL Charles W. Gering, Miami FL	6.1.56 6.1.56/67 2.6.67/70 26.5.70/72 23.6.72/74 14.8.74 7.10.74/75 2.4.75 9.10.75/83 9.83 falled, radials, 12.1.56 12.1.56/62 2.7.62 63 10.63/64 12.64/69
	N63B note 20.8.91 cra Jelinek;  E18S  Hamilton Extended Nose  N152H note N171LG n	ted Kenosha Wash report: for N52C N152H N171LG (1 ted Tucson A2oted Miami 4.oted Ft Laude	Ohio Aviation Co, Dayton OH Pittsburgh Consolidation Coal, Pittsburgh PA George M. Humphrey, Cleveland OH Wan Dusen Acceptance Corp, Minneapolis MN Hamilton Aircraft Co, Tucson AZ (cargo conversion and Hamilton extended nose fitted by Hamilton Aircraft Co at Tucson AZ 9.74) Chris Crowell & Co Inc Palm Beach Air Traders Florida Airmotive Inc, Lantana-Palm Beach FL (Florida Airmotive request N171LG be removed from register: letter to FAA 4.6.83) struck-off USCR (broken-up: cargo door & cockpit entrance door ex BA-120 installed in BA-16/N255D 6.84)  Z 20.9.74 inside Hamilton hangar, extended nose just installed FL 16.3.81 reported as Hamilton Westwind;  Topeka Aircraft Sales & Service, Topeka KS Panhandle Eastern Pipe Line Co S & S Aviation Inc Tempo Design Corporation, Miami FL Continental Aviation Corp, Opa Locka FL	6.1.56 6.1.56/67 2.6.67/70 26.5.70/72 23.6.72/74 14.8.74 7.10.74/75 2.4.75 9.10.75/83 9.83 talled, radials, 12.1.56 12.1.56/62 2.7.62 63 10.63/64

		Kno-Mac Asphalt Paving Inc	10.69/75	
		N11HT	(FAA report 3.70: aircraft is still painted as N1EK) Charles E. Bush/ Bush Aviation, Ft Lauderdale FL Bill Swipe, Coconut Grove FL:	9.5.75/78
			fictitious address, sale documentation not completed struck-off USCR	29.3.78 8.82
	N10EK no		.10.68; dale FL 28.9.70; dale FL 15.9.76;	
BA-122	E18S	N2002A N412A	Aluminum Company of America, Pittsburgh PA Aluminum Company of America, Pittsburgh PA Hess Manufacturing Co, Quincy PA	.56 63/64 66
		N198HA N107T	Henson Aviation, Hagerstown MD Tobey Inc, Simsbury CT crashed on takeoff, destroyed by fire, Newark NJ	69/70 9.3.71/72 23.9.72
BA-123	E18S -9700	N700E (2	Atlantic Aviation Corp Esso Shipping Co	19.1.56 23.1.56/58
	0.00	N73114	Esso Shipping Co	27.2.58
		N700CC (1	Butterworth Systems Inc The Chemstrand Corp	16.6.58 12.58/61
		N563R	The Chemstrand Corp	9.3.61
		N370M	Murphy Oil Corp, El Dorado AR	5.4.61/67
		N378M	Stan Burnstein/ Continental Aviation Co John Rourke/ Rourke Aviation, Bartlesville OK	10.1.67/69
			Caribe Air Sales Inc, Opa Locka FL	10.4.69 11.69/76
			op: Pro Air Services, Opa Locka FL	77
			Davis Horne Flying Service, McAlester OK	26.9.76/79
			(cockpit entrance door installed 3.78) op: Pro Air Services, Opa Locka FL	78
			Marcus B. Butler, Shreveport LA	1.6.79/91
		oted Miami FL oted Miami 25.	3.10.77 in service; 10.78;	
BA-124	E18S	N64B	Young Aviation Corp, Fort Smith AR Bailey Leasing Corp, Fort Wayne IN	63/64
			op: Standard Airways	66/68 7.6.66/68
			Eastern Aviation Corp/ Shenandoah Airlines,	
			Baltimore-Friendship MD	68/69
			Coastal Airways, San Juan, Puerto Rico crashed landing, San Juan, Puerto Rico	23.1.70 10.2.70
			crashed fanding, San Juan, Fuerto Nico	10.2.70
	N64B note	ed Baltimore M	1D 21.9.68 & 28.9.68, both Shenandoah;	
BA-125	E400	14 = = 0.4	1 70	30.1.56
	E18S	JA5501	built	
	E185	JA5501	Maritime Safety Board, Tokyo-Haneda	65
	E185	JA5501	Maritime Safety Board, Tokyo-Haneda Maritime Safety Agency, Fukuoka	
	E185	JA5501	Maritime Safety Board, Tokyo-Haneda Maritime Safety Agency, Fukuoka retired, struck-off Register derelict complete in junk yard, Wakamiya Town,	65 70/81 24.3.81
	E185	JA5501	Maritime Safety Board, Tokyo-Haneda Maritime Safety Agency, Fukuoka retired, struck-off Register	65 70/81
	JA5501 no JA5501 no	oted Tokyo-Ha	Maritime Safety Board, Tokyo-Haneda Maritime Safety Agency, Fukuoka retired, struck-off Register derelict complete in junk yard, Wakamiya Town, Fukuoka Prefecture, Japan aneda 1.4.69; rd, Wakamiya Town, Fukuoka Prefecture, 10.03 in faded	65 70/81 24.3.81
BA-126	JA5501 no JA5501 no	oted Tokyo-Ha oted in junkyar	Maritime Safety Board, Tokyo-Haneda Maritime Safety Agency, Fukuoka retired, struck-off Register derelict complete in junk yard, Wakamiya Town, Fukuoka Prefecture, Japan aneda 1.4.69; rd, Wakamiya Town, Fukuoka Prefecture, 10.03 in faded	65 70/81 24.3.81
BA-126	JA5501 no JA5501 no Japanese	oted Tokyo-Ha oted in junkyar Coast Guard (	Maritime Safety Board, Tokyo-Haneda Maritime Safety Agency, Fukuoka retired, struck-off Register derelict complete in junk yard, Wakamiya Town, Fukuoka Prefecture, Japan aneda 1.4.69; ad, Wakamiya Town, Fukuoka Prefecture, 10.03 in faded colours;  built Maritime Safety Board, Tokyo-Haneda	65 70/81 24.3.81 03 30.1.56 65
BA-126	JA5501 no JA5501 no Japanese	oted Tokyo-Ha oted in junkyar Coast Guard (	Maritime Safety Board, Tokyo-Haneda Maritime Safety Agency, Fukuoka retired, struck-off Register derelict complete in junk yard, Wakamiya Town, Fukuoka Prefecture, Japan aneda 1.4.69; ad, Wakamiya Town, Fukuoka Prefecture, 10.03 in faded colours;  built Maritime Safety Board, Tokyo-Haneda Maritime Safety Agency, Sendai	65 70/81 24.3.81 03 30.1.56 65 70/80
BA-126	JA5501 no JA5501 no Japanese	oted Tokyo-Ha oted in junkyar Coast Guard (	Maritime Safety Board, Tokyo-Haneda Maritime Safety Agency, Fukuoka retired, struck-off Register derelict complete in junk yard, Wakamiya Town, Fukuoka Prefecture, Japan aneda 1.4.69; ad, Wakamiya Town, Fukuoka Prefecture, 10.03 in faded colours;  built Maritime Safety Board, Tokyo-Haneda Maritime Safety Agency, Sendai Nihon Technology Corp	65 70/81 24.3.81 03 30.1.56 65 70/80 80
BA-126	JA5501 no JA5501 no Japanese	oted Tokyo-Ha oted in junkyar Coast Guard ( JA5502	Maritime Safety Board, Tokyo-Haneda Maritime Safety Agency, Fukuoka retired, struck-off Register derelict complete in junk yard, Wakamiya Town, Fukuoka Prefecture, Japan  aneda 1.4.69; ad, Wakamiya Town, Fukuoka Prefecture, 10.03 in faded colours;  built Maritime Safety Board, Tokyo-Haneda Maritime Safety Agency, Sendai Nihon Technology Corp sold to USA, struck-off Japanese Register	65 70/81 24.3.81 03 30.1.56 65 70/80 80 21.7.80
BA-126	JA5501 no JA5501 no Japanese	oted Tokyo-Ha oted in junkyar Coast Guard (	Maritime Safety Board, Tokyo-Haneda Maritime Safety Agency, Fukuoka retired, struck-off Register derelict complete in junk yard, Wakamiya Town, Fukuoka Prefecture, Japan  aneda 1.4.69; ad, Wakamiya Town, Fukuoka Prefecture, 10.03 in faded colours;  built Maritime Safety Board, Tokyo-Haneda Maritime Safety Agency, Sendai Nihon Technology Corp sold to USA, struck-off Japanese Register Eugene C. Eversole, Honolulu HI Adrian I. Dalsey, Honolulu HI	65 70/81 24.3.81 03 30.1.56 65 70/80 80 21.7.80 22.7.80/81 28.5.81/82
BA-126	JA5501 no JA5501 no Japanese	oted Tokyo-Ha oted in junkyar Coast Guard ( JA5502	Maritime Safety Board, Tokyo-Haneda Maritime Safety Agency, Fukuoka retired, struck-off Register derelict complete in junk yard, Wakamiya Town, Fukuoka Prefecture, Japan  aneda 1.4.69; ad, Wakamiya Town, Fukuoka Prefecture, 10.03 in faded colours;  built Maritime Safety Board, Tokyo-Haneda Maritime Safety Agency, Sendai Nihon Technology Corp sold to USA, struck-off Japanese Register Eugene C. Eversole, Honolulu HI	65 70/81 24.3.81 03 30.1.56 65 70/80 80 21.7.80 22.7.80/81

	op: Alpha Air, Manila, Philippines	82
	(ferry permit 4.6.82 from Honolulu to Manila)	
RP-C707	Commuter Air Philippines, Manila	.82/87
	Air Charter Philippines, Manila	90
	crashed on takeoff, Masbate, Philippines	14.8.91
Hamilton	(rebuilt, fitted with Hamilton Extended Nose mod)	
Extended Nose	last report, parked engineless at Manila	13

JA5502 noted Tokyo-Haneda 13.3.67;

N8475D noted Honolulu 23.8.81 full DHL scheme, in service;

RP-C707 noted Manila 7.5.86 "Commuter Air Philippines" titles, ex DHL orange & white scheme, tailwheel;

RP-C707 noted Manila 10.9.86 "Commuter Air Philippines" titles;

BA-127	E18S	N82D (1	Youngstown Airways/ Lease Air, Youngstown OH	
		N8211	Minneapolis Lakers Basketball Corp, Minneapolis MN	61/65
			Marshfield Airways Inc, Marshfield WI	66/69
			op: Midstate Air Commuter/ MAC Airlines, Marshfield WI	66/68
			landed gear-up Fond du Lac WI	23.4.67
			Lake Geneva Airways, Lake Geneva WI	69/73
			Stockert Flying Service, South Bend IN	23.9.74/76
			nosed over in snowbank landing, Elyria OH	3.12.74
			struck-off USCR	27.5.76
			derelict in scrapyard, DuPage IL	91

N8211 noted Chicago-O'Hare 2.68 Midstate Air Commuter;

N8211 noted O'Hare 18.5.70 Lake Geneva AW;

N8211 noted O'Hare 4.71 "Lake Geneva Airways" titles, tailwheel; N8211 noted O'Hare 23.7.71, 30.4.72 no titles;

N8211 noted Lake Geneva WI 3.8.73, Lake Geneva Airways;

N8211 accident report 3.12.74: Stockert Aviation: South Bend IN to Elyria, 11.55pm;

N8211 noted derelict in scrapyard DuPage IL 7.91;

BA-128	E18S	N45N (1	Topeka Aircraft Sales & Service	7.2.56	
		211 (1	C. E. Brehm Drilling & Producing Co, Mt Vernon IL	5.7.56/79	
			Niles Airways	16.3.79/80	
			op: General Aviation Inc, Greenville TN	80	
		N977RB	Niles Airways	3.80	
			William Jackson	3.6.80/81	
			Hector Rocha & Vanessa Rocha Gandara,		
			Brownsville TX	22.1.82/86	
			(cockpit door installed 5.86, cargo floor 4.87)		
			Mario E. Britt & John J. Singer, Brownsville TX	10.6.86/87	
			Air America Freight Inc, Reno NV	17.4.87	
		N9187W	Air America Freight Inc, Reno NV	7.6.87/89	
			Aerospace Products Inc, North Hollywood CA	3.3.89	
			sold to Canada, struck-off USCR	20.3.89	
		C-FSAO	Summit Air Charters Ltd, Atlin BC	28.4.89/96	
			crashed, landing Atlin BC	28.7.92	
			struck-off Register	7.96	
BA-129	E18S	N54C (2	Pittsburgh Consolidation Coal, Pittsburgh PA	63/66	
		N5402	Mid Continent Airlines, Morris IL	69/70	
			Norbert F. Ogorek, Naperville IL	4.2.74/79	
			struck-off USCR	19.12.79	
			stripped hulk stored Pontiac MI	97/00	
			Al 2.97 stripped hulk; Al 3.3.97		
	N5402 noted Pontiac MI 3.3.97; N5402 noted Pontiac MI 2.98 fuselage only;				
			Il 23.7.00 derelict, plate BA-129 built 2.56;		
BA-130	E18S	N28V	J. R. Gray Co, Dallas TX: CofA issued	10.2.56	
			J. R. Gray/ Executive Air Transportation, Dallas TX	13.3.56	

Joe Fetchell/ Western Services Inc/

	Western Hatcheries of Waco/	
	Poultry Improvement Agency Inc, Dallas TX	14.3.56/73
	The Catholic Foundation	1.3.73
	Gibbes Lease-Air Inc	24.7.73/75
	Berg Aviation Ltd	13.3.75/76
	Ronald Ruble	10.76/77
	(cargo door installed 6.77)	
	Aero American Aviation, Chicago IL	29.8.77/78
	Royal Air Freight, Pontiac MI	24.7.78/95
	Tol Air Services, San Juan, Purto Rico	18.5.95/99
	MBD Corp, San Juan, Puerto Rico	8.2.99/00
N728T	MBD Corp, San Juan, Puerto Rico	6.12.00/13
	op: Tol Air Services, San Juan, Puerto Rico	99/13
	reg expired 31.12.13, struck-off USCR	26.1.18

N28V noted Dallas-Love TX 2.10.71, 1.5.73;

N28V noted Pontiac MI 7.91 at Royal Air ramp;

N28V noted St Croix USVI 1.98 "Tol Air";

N28V noted San Juan PR 16.6.00 all metallic, op by Tolair;

N728T noted Opa Locka FL 4.11.04;

N728T noted San Juan PR 24.6.05 all metallic, tailwheel, op by Tolair;

N728T noted San Juan PR 26.2.06 all metallic no windows, i/s;

N728T noted San Juan PR 2.2.08 all metallic no windows, i/s;

N728T photo in service Tol Air at Puerto Rico 5.10, all metallic, windows faired over;

BA-131	E18S	CF-IKM	R. J. McFarland Construction Co, Picton ONT	22.2.56/63
	-9600		Carl Millard Ltd/ Millardair Ltd, Toronto-Malton ONT	3.9.63/67
			Hicks & Lawrence Ltd, St Thomas ONT	27.6.67/72
			Voyageur Airways Ltd, North Bay ONT	6.72
			Bradley Air Services Ltd, Carp ONT	6.73/78
			undercarriage collapsed landing Ottawa ONT	17.12.73
			slid off runway on takeoff, struck snow bank, Carp ONT	30.11.75
			not repaired, struck-off Register	22.9.78
			(CF-IKM wreck stored at Carp ONT 78)	
			(cabin roof from rivet line beneath windows removed and	
			installed in TC-45J Westwind III C-GBLI/6323 by Buckeye	Э
			for Interflite Aviation Service for increased freight	
			capacity)	

CF-IKM visited Toronto ONT 23.4.64;

CF-IKM noted Indianapolis IN 5.68 reported as Hicks & Lawrence, no titles, tailwheel;

CF-IKM noted Carp ONT 24.8.74 Voyageur Airways;

CF-IKM noted Carp ONT 12.8.78, damaged, derelict, Bradley AS;

further details of grafting of cabin: see Beech 18 by Parmerter p. 345;

BA-132	E18S	N3611F	Aircraftsmen Inc, Oklahoma City OK	2.3.56
	-9700		R. H. Fulton & Co	5.3.56/61
			minor damage landing, Helena MT	10.7.60
			Wiles-Holloway Inc, Baton Rouge LA	14.8.61/64
			Louisiana Dept. of Highways	24.1.64
			Louisiana Television Broadcasting Corp,	
			Baton Rouge LA	31.7.64
		N362M	Louisiana Television Broadcasting Corp	23.9.65/70
			Wiles-Holloway Inc, Baton Rouge LA	1.12.70/71
			sold to Iceland: struck-off USCR	3.71
		TF-FHM	Landflug, Reykjavik	4.71.73
		TF-JMB	Nordurflug, Reykjavik	5.73
			Flugfelag Norourlands, Akureyri	.75/76
		TF-EBB	Flugstoedin HF, Reykjavik	8.77/78
			sold to USA: struck-off Icelandic Register	9.11.78
			(TF-EBB delivered Reykjavik-Philadelphia PA 6-8.11.78)	
		N90276	Frank Cannavo/ Aero Taxi, Philadelphia PA	11.78/79
			(US CofA renewed 19.4.79)	
			Robert Avery/ Rancho Perdido, Devine TX	19.6.79/91
			•	

BA-133	E18S	N42A	built	.56 59
			E. I. duPont de Nemours & Co, Wilmington DE Atlantic Aviation Service, Philadelphia PA	63/70
			Sebastino Cannavo/ Aero Taxi, Philadelphia PA	28.9.70/72
			op: Quaker City Airways	72
			left wing failed & folded up in flight, crashed,	12
			destroyed by fire, Cleveland OH	22.6.72
			destroyed by life, Cleverand On	22.0.72
	crash repo	ort 22.6.72 Cle	veland OH: operator Aero Taxi;	
	NTSB rep	ort 22.6.72: op	perator Quaker City Airways, flight Philadelphia to Rockford	d IL, pilot k;
BA-134	E18S	N99L	built	.56
	trigear	N699JG	Travel Leasing Co, San Bernardino CA	63/64
	J	N299JD	Juanita Daly, Las Vegas NV	66
			Fletcher Aircraft Leasing Corp, Houston TX	69/70
		N2993D	unconf.	
		N1131T	Fletcher Aircraft Leasing Corp, Bellaire TX	72
			Harry W. Nichoalds, Boulder CO	21.11.74/75
			struck-off USCR	13.3.75
			10.57, "Les Cal" emblem; tailwheel;	
	N11311 n	oted Van Nuys	s CA 19.8.72;	
BA-135	E18S	N43A	Chalmers & Barton Construction Co	59
		N2000H (2	Chalmers & Barton Construction Co	12.2.59
		N2000R `	rereg	
		N218A	Business Counselors Inc, Salina KS	63/64
			Hamilton Airport Inc, Hamilton OH	66/70
			Hamilton Aviation Inc, Hamilton OH	16.9.70/76
			struck vehicle during forced landing off runway,	
			Fort Campbell KY	13.1.76
			struck-off USCR	17.5.76
BA-136	E18S trigear G18S cab	N19X	Hawthorne Metal Products Co, Royal Oak MI Page Airways, Rochester NY (G18S cabin mod. installed) Page Airways, Rochester NY Rolair Corp/ Wright Air Lines, Cleveland OH Burlington Airways, Burlington WI crashed on landing, gear collapsed, Burlington WI Blackhawk Airways, Janesville WI (damaged)	63/64 66 66 69/72 15.6.73/75 25.7.75 75/79
	N402FW (	accident repon	(trucked damaged to Janesville: cabin roof, cargo doors & G18S cab of N402FW fitted .78 to Westwind III C-45H N35136/AF-629 by Blackhawk Airways, Janesville WI)  r.p.334, 339; appears leased fleet to Wright Airlines, Cleveland; t 25.7.75: flight Janesville Wi to Burlington, fuel mismanage each to Burlington, forced landed on airport,	ement,
BA-137	E18S	N17T	reg	.56
			Francis Aviation, Lansing MI	25.5.59/72
			struck-off USCR	21.1.72
BA-138	E18S	N198B	Butler Co/ Butler Airplane Sales	17.3.56
5/1 100	-9700	141000	Structo Manufacturing Co	10.56/60
	-9100			
	tricos-		International Steel Co, Evansville IN	10.8.60/73
	trigear		(Volpar Mk.IV trigear & two-piece windshield	
			installed 3.64)	40 5 70/70
			Charles M. Booth/ Goco Inc	16.5.73/76

Lily F. Browne, Melbourne FL

27.8.76/79

N198B accident report: no operator quoted: passenger flight Orlando-Herndon to Opa Locka, poor weather 12.40am, destroyed, pilot & 3 pax k;

	Ора Lock	ka, poor wealii	er 12.40am, destroyed, pilot & 3 pax k,	
BA-139	E18S	N43D (1	Anderson Air Activities	23.3.56/61
			Lake Shore Inc, Iron Mountain MI	5.7.56/62
			Nelson M. Robinson, DeKalb IL	6.2.62
		N503W (2	Capitol Aviation Inc, Springfield IL	13.8.62
	trigear	,	(Volpar trigear installed 11.62)	
	ŭ		S. J. Groves & Sons Co, Minneapolis MN	11.62/68
		N563W	Flite Training Center	11.68/69
			Bayou Transit Inc, St. Louis MO	69
			Williams Patent Crusher & Pulverizer Co, St Louis MO	15.5.70/72
			Malcolm Jacobs Aviation (agents)	15.5.72
			sold to Canada, struck-off USCR	7.72
		CF-DCC	Sud Aviation Canada, St Jean Crysostome QUE	2.8.72/74
			J. Wright Enterprises Ltd, Edmonton ALTA	4.4.75/78
			lsd: Newfoundland & Labrador Air Transport,	
			Corner Brook NFLD	18.9.75/76
			lsd: International Forest Fire Systems Ltd, Calgary ALTA	
			(modified with fire spotter window 5.76)	
			crashed ran off runway landing, Abbotsford BC	27.9.77
			(ferry permit 2.78 Abbotsford-Vancouver BC)	27.0.77
			William Kostich, Clarkston MI	6.9.78
			(CF-DCC ferry permit 9.78 Vancouver to US)	0.0.70
		N563W	Royal Air Freight, Pontiac MI	28.9.78/90
		1400077	(stored Pontiac .78/84: Royal planned rest. to fly .84)	20.5.70/50
			crashed & burned on takeoff, Greenwood SC	9.8.90
			crashed a burned on takeon, oreenwood oc	3.0.30
		_	ton-DCA 8.5.64 Groves;	
			MI 9.80 trigear;	
	N563W r	eported entere	ed service with Royal Air Freight late 84;	
BA-140	E18S	N65B	Beech Aircraft Corp, Wichita KS: CofA issued	11.4.56
			Elliot Flying Service	27.8.56
			Gardner-Denver Co, Quincy IL	27.8.56/59
			(mods to E18S-9700 by Remmert-Werner Inc,	
	-9700		St Louis MO .56)	
		N165GD	Gardner-Denver Co, Quincy IL	12.59/65
			Topeka Aircraft Sales & Service, Topeka KS	12.65/66
		N165G	Topeka Aircraft Sales & Service, Topeka KS	5.5.66
	trigear		(Volpar Mk.IV trigear & G18S type two-piece	
	- 3		windshield installed 12.66)	
			Atlas Tool and Manufacturing Co, St Louis MO	12.66/69
			James O. Holton/ L & H Co, Jackson Hole WY	8.11.69/71
			Air Travel Inc	11.71/72
			L & H Co, St Louis MO	72
		N611CW	Air Travel Inc	21.3.72/76
			Southernoire Inc. Chattanaga TN	22 5 76/77

			Odesa Inc: sale documentation not completed	.78
BA-141	E18S	N72SF	J. P. Stevens & Co, New York NY	56/61
			Mele Manufacturing Co, Richmond Hill NY	63/70
			Utica Mutual Insurance Co, Utica NY	72/78
			Robert F. Dorsey, Athens TX	78
			Fredrico L. Cantu, Brownsville TX	3.10.78/82
			struck-off USCR	23.8.82

Southernaire Inc, Chattanooga TN

National Aviation Underwriters, Atlanta GA

22.5.76/77

.77

photo shows N72SF, N73SF, N74SF, N75SF & N176SF in row at Wallace NC 4.61, all tailwheel, all owned J.P.Stevens & Co; N72SF noted Brownsville TX 8.5.79 in service;

BA-142	E18S	N83D (1	Youngstown Airways/ Lease Air, Youngstown OH		
		N8311	Capitol Aviation, Springfield IL	63	
			Weston Paper & Manufacturing Co, Dayton OH	64/72	
			Gifford Aviation, Anchorage AK	23.1.75/76	
			ditched in sea after takeoff, sank, Kodiak AK	22.5.76	

N8311 accident report: Gifford Aviation: flight Kodiak to Anchorage, engine failed on takeoff, forced landing on water, 2 unhurt;

BA-143	E18S	N31M	Isbell Construction Co, Phoenix AZ	63
	-9700		Union Rock & Materials Corp, Phoenix AZ	64
			Arizona Highway Patrol, Phoenix AZ	66/69
			Cutter Beechcraft Inc, El Paso TX	70
			reg. pending, Albuquerque NM	72
			K & K Aircraft, Bridgewater VA	79
			Morey Wyman/ Wyman Pilot Service, Pontiac MI	2.86
			Majestic Airlines, Salt Lake City UT	10.8.87/95
			sold to Canada, struck-off USCR	5.10.95
		C-FCLO	Enterprise Air Inc, Oshawa ONT	25.1.96/17

C-FCLO noted Oshawa ONT 9.96 & 6.98, 17.8.03, 17.4.04: all Enterprise Air: 4.04 report states that the company uses DC-3s and CLO on freight work for car industry; C-FCLO noted Toronto-Downsview 17.4.04 in service with Enterprise Air Inc; C-FCLO noted Oshawa ONT 15.5.05, 24.6.05, 24.6.06 no titles, tailwheel, in service;

BA-144	E18S	N65V	Texas Gulf Producing Co, Houston TX	63/64
			Michigan Bank Association, Detroit MI	66/69
	trigear		reg. pending: USCR	70
			Kingery Drilling Co, Saint Jo TX	72
			Tampa Air Centre Inc, Tampa FL	28.3.78/80
			struck towers, forced landing off-airport, crashed	
			destroyed by fire, Gainesville FL	24.10.80

N65V noted Tampa FL 11.4.79 trigear;

N65V accident report 24.10.80: Tampa Air Centre: pax flight Bartow FL to Lake City FL, 1 engine mechanical failure, forced landing in fog 9.47am, pilot & 2 pax k;

BA-145	E18S	N575Q	J. D. Reed Co, Houston TX: CofA issued	23.4.56
	trigear		Quintana Petroleum Corp	25.4.56/58
	_		Southern Airways Co	12.58/60
		N1906L	Special Services Corp	29.3.60
			Martha White Mills Inc, Nashville TN	4.6.60/64
		N233MW	Martha White Mills Inc, Nashville TN	29.1.64/68
		N263MW	Martha White Mills Inc, Nashville TN	7.68
			Cousins Properties Inc, Atlanta GA	12.68/69
			Omni Investment Corp, Washington DC	15.9.69
			Sherman Aircraft Sales, West Palm Beach FL	17.9.69/70
			Continental Aero Space Corp, Ft Lauderdale FL	28.4.70/71
			Sherman Aircraft Sales, West Palm Beach FL	1.9.71
		N263VG	Tamboo Aviation, Palm Beach FL	11.71/72
			Lucille Quattlebaum/ L. G. Equipment Co	11.72/73
			BTR Enterprises Inc/ Johnny Bolton Aircraft	7.9.73/74
			L T D Development Inc	22.4.74/75
			Rich Ice Cream Co	17.3.75
		(N263JF)	ntu: Jerry Fairbanks Productions	5.12.75
		N263VG	Jerry Fairbanks Productions, Hollywood CA	5.12.75/77
			John L. Moore, Sarasota FL	11.5.77
			R. A. Johnson: documentation not completed	.77

## N263MW noted Ft Lauderdale FL 28.9.70 trigear;

BA-146	E18S	N40DC (1	built	.56
		N404C `	Trippeer Organizations Inc, Memphis TN	63
		N606S	Coca Cola Co/ Minute Maid Co	64/65
	trigear	XB-ZEE (2	The Coca Cola Export Corp	.65/67
	•	N14610 `	Southern Airways Co, Orlando FL	10.10.67

District Equipment Co, Decatur GA	6.3.68/70
Silver Enterprises Inc, Charleston WV	14.8.70/72
Patrick J. Horrington/ Horrington Bonding Co	18.3.72/73
Tampa Air Centre, Tampa FL	23.8.73/77
Herbert E. Guynn, St. Petersburg FL	18.3.77
Aamtax Corp	18.3.77/78
G. R. Lowe, Clinton MO	14.1.78/13
struck-off USCR	9.7.13

### XB-ZEE noted Mexico City 25.4.66 trigear;

BA-147	E18S	N19T	Atlantic Aviation Corp: CofA issued	24.4.56
DA-141	-9700	14191	•	1.5.56/60
	-9700		Wayfarer Ketch Corp	
			Nelson A. & David Rockefeller, New York NY	6.60/67
			Cornell University, Ithica NY	10.3.67/70
			Colgan Airways Corp, Manassas VA	21.3.70/73
			Aero Leasing Inc	28.9.73/78
			Midwest Air Charter, Elyria OH: leased	5.10.73/78
			(Hamilton cockpit door installed 11.77)	
			op: Airborne Express	78
			Youngstown Executive Beechcraft Inc, Jackson OH	14.4.78
			Executive Air Express	4.79/80
			Wolverine Air Charter	3.12.80/81
			Ajax Aircraft Leasing Inc, Dover DE	11.81/82
			Raul Mireless, McAllen TX	8.6.82/83
			SmithAir Inc, Sharpsburg GA	26.3.83/85
			op: Airborne Express, Wilmington OH	85
			destroyed, struck on runway by landing USAF F-4,	
			Birmingham AL	20.6.85

N19T noted Washington-DCA 30.9.70; N19T noted Willow Run MI 14.7.81;

accident report 20.6.85: op SmithAir Inc on a Airborne Express cargo flight, lined up on runway then overlooked by Tower controller who cleared F-4 to land, Beech destroyed;

BA-148	E18S	N98B	Piedmont Aviation, Winston Salem NC	12.7.56
	-9700		Hennis Freight Lines	12.7.56/63
		N751H	Hennis Freight Lines	15.4.63
			Piedmont Aviation, Winston Salem NC	7.5.63
			Joseph I. O'Neill, Midland TX	10.63/65
			M. W. Branum, Midland TX	11.65/74
			Farmington Airmotive, Farmington MO	10.74/82
			(pilot cockpit door installed 7.78)	
			Festus Flying Service, Festus MO	17.9.82/84
			HoganAir Inc, Hamilton OH	8.2.84
		N95HA	HoganAir Inc, Hamilton OH	8.5.84/85
			crashed destroyed on takeoff, Huntington WV	31.1.85
			struck-off USCR	9.85
			South West Aero Exchange, Owasso OK	00
			(wreck dismantled in salvage yard, Owasso OK 00)	

N751H noted Sr Louis MO 2.6.76;

N95HA fuselage and detached tailplane noted in SW Aero Exchange yard Owasso OK 10.8.00;

BA-149	E18S	N82B	Narmid Inc, Lubbock TX	63
			Jack Adams Aircraft Sales, Walls MS	64
	Volpar		Volitan Aviation, Pacoima CA	66
	Super		(converted c65 to the 2nd Volpar Super Turbo 18,	
	Turbo 18		with AiResearch TPE-331-25 turbines)	
			Imperial Commuter Airlines, Imperial CA	29.11.67/68
			crashed destroyed on takeoff, San Diego CA	8 1 68

further details, see Beech 18 by Robert Parmerter p.386; N82B noted San Diego CA 14.9.67 Imperial Commuter AL, turbine trigear; crash 8.1.68 3 k; Visco Flying Co operated third level service Imperial CA to Blythe CA 68, renamed Imperial Commuter Airlines by 69;

BA-150	E18S	N32M	Gerald C. Francis/ Francis Aviation, Lansing MI	30.4.56
	-9600		Howard Sober Inc	30.4.56/60
			Francis Aviation, Lansing MI	11.4.60/70
			MacGillivray Buick Co, Swartz Creek MI	13.4.70/73
			Donald A. Paolucci, Cleveland OH	28.9.73/94
			(cargo door installed 5.74)	
			op: Mohican Air Service, Cleveland OH	79/84
			Piedmont Air Cargo, Gastonia NC	17.3.94/95
			Kestrel Inc, Waukee IA	31.3.98/16
			reg. expired 30.11.16, struck-off USCR	13.3.18

Mohican Air Service was owned by Don Paolucci, who purchased the airfield at Wakeman OH in 1981, still there 2007. Mohican had 2 DC-3s, 2 Convairs and Beech 18s including a turbine version.

N32M noted Oskaloosa IA 24.7.98 in service, freighter owned Kestrel Inc, old titles Piedmont Air Cargo readable through paint, plate: BA-150 built 4.56;

another plate: Aerospace Products spar kit 156 to 9600 lbs 18.12.61;

N32M noted Oskaloosa IA 25.7.99 parked in same position, props & flaps removed: owned Bill Chase of Kestrel Inc:

paperwork in aircraft gave CofR issued 1.8.56, ownership change 22.6.94 to Piedmont;

BA-151	E18S	N23T	Alamo Aviation, San Antonio TX: CofA issued	27.4.56
			B. L. McFarland Inc, Midland TX	1.5.56/63
			Rich-Air Co, Midland TX	4.10.63/64
			E. C. Johnston, Longview TX	17.1.64/75
			(two-piece G18S type windshield installed 8.65,	
			picture windows installed 10.65)	
			Rich-Air Co	27.2.75/76
			San Angelo Flight Service Inc	5.4.76/77
			Albert W. Long/Long Construction Co/	
			Kanga Exporting Inc, Cocoa FL	2.78/81
			D'Arlee Inc, McAllen TX	22.5.81
			(FAA report 5.81: ficticious address)	
	N23T not	ed St Thomas	s USVI 30.4.78;	
BA-152	E18S	(N32R)	ntu: J. D. Reed Co, Houston TX	3.56
	-9700	N33JD (1	J. D. Reed Co, Houston TX	11.5.56
		N330LL	J. D. Reed Co, Houston TX	11.56/57
			Northern Electric Co, Chicago IL	28.5.57
		N330N	Northern Electric Co, Chicago IL	12.9.57/65
	trigear		(Volpar tricycle gear installed 4.65,	
	Ü		picture windows installed 5.65)	
			Wells Stewart, Houston TX	22.9.65/68
			Fiber Controls Corp	26.1.69
			Carolina Fleets Inc., Anderson SC	21.2.69/71
		N116FC	Carolina Fleets Inc, Anderson SC	27.1.71/72
			damaged, struck trees, Tocca GA	29.1.72
			Malcolm Jacobs Aviation	12.8.72
			sold to Canada, struck-off USCR	10.72
		CF-FSB	Commuter Air Services Ltd, Quebec QUE	10.72/
			(ferry permit St Louis MO to Montreal 10.72, CofA 30.11	
			Sud Aviation Canada Ltd, St Jean Crysostome QUE	4.73
			J. Wright Enterprises Ltd, Edmonton ALTA	4.75
			International Forest Fire Systems Ltd, Calgary ALTA	4.76
			Patricia Air Transport Ltd, Sioux Lookout ONT	11.77
			Skycraft Air Transport Ltd, Oshawa ONT	4.78
			Pacific Coastal Airines Ltd, Nanaimo BC	5.78
			Labrador Airways, Goose Bay LAB	7.78
			sold to USA, struck-off Canadian Register	20.10.78
		N9013Y	Tobey Inc, Simsbury CT	10.78/80
			(aircraft in full cargo configuration by 11.78)	
			Lawrence E. Dietrich/ Gateway Associates	18.1.80/81
				<del>-</del> <del>-</del>

N75BC	op: Bahamas Caribbean Airlines	81
N9013Y	Astro Airways Corp, Pine Bluff AR	11.81/82
	Goodner Bros Aircraft Inc, Mena AR	1.82
	Mid-South Aircraft Sales, Memphis TN	4.1.82/84
	Allen Godwin, Memphis TN	.84
	Schindler Energy Inc, Columbus TX	11.7.84/13
	struck-off USCR	12.9.13

63/64

N9013Y noted Hartford CT 21.6.79;

N47A

BA-153

E18S

N75BC noted Mena AR 14.3.81 trigear, "Bahamas Caribbean Airlines" titles, good condition;

Andre J. Andreoli, Akron OH

D/ \ 100	L100	14777	Andre G. Andreon, Anton On	00/04
	trigear		Ohio University, Athens OH	66
			Southwestern Skyways Inc, Albuquerque NM	69
			Distribute Aire Inc, Albuquerque NM	70
			Florida Communities Sales Inc, Beachwood OH	23.12.70/71
			crashed, destroyed landing in fog, Columbia SC	26.2.71
	accident re	port 26.2.71:	Volpar E18S: hit ground during missed approach in poor	weather, 8k;
BA-154	E18S	N48W (1	Tulsair Distributors Inc, Tulsa OK	16.5.56
	-9700		Norango Inc	16.5.56/57
			Flight Service Inc	30.1.57/58
			The Ridge Tool Co	26.1.59/60
			(modified 5.59 to E18S-9700)	
			Hanover Shoe Farms Inc, Hanover PA	6.5.60/64
	PacAero		Pacific Airmotive Corp, Burbank CA	28.9.64
	Turbo	N6651R (2	Pacific Airmotive Corp, Burbank CA	11.64/67
	Tradewind		(converted by PacAero to Turbo Tradewind with	
			PT-6A-6s, Volpar trigear, single fin: flight testing 10.65,	
			completed 25.7.66)	
			Continental Air Services, Laos	66
			Boun Oum Airways, Laos	
			Ken Air Inc	4.10.67
		B-1530	China Airlines, Taipei	4.10.67/73
		N40AP	Sizer Airways, Rochester MN	18.6.73
		- <del></del>	Aveneles Aviation, Las Vegas NV	28.6.74/76
			(cargo floor & cabin cargo door installed 9.75,	_5.5 0
			cockpit door installed 1.76)	
		N25SM	Aveneles Aviation, Las Vegas NV	27.2.76/78
			Oliver Smith/ Umiat Enterprises, Van Nuys CA	10.78/79
			(op. as Alaska Umiat Enterprises)	. 5.7 6,7 6
			Union Flights, Sacramento CA	2.4.79/91
			Ministic Air Ltd, Winnipeg MAN	29.4.91
			sold to Canada, struck-off USCR	1.5.91
		C-FRGT	Ministic Air Ltd, Winnipeg MAN	14.5.91/00
		O-FRG1	• •	14.5.81/00
			undershot on landing approach, crashed on frozen lake,	5.2.92
			Little Grand Rapids MAN	
			K & K Aircraft Inc, Bridgewater VA	.92/98
			(salvaged ex lake crash site by K&K, stored at	
			Bridgewater for spares use)	

This aircraft? or possibly Tradewind AF-831/N9981Z/HS-SKA?

- In early 1967, CIA was preparing a programme of surveillance of the Ho Chi Minh Trail: Air America planned to use its Volpar Turbo 18s, also bidding for the contract was Boun Oum Airways (BOA) owned by Laotian prince Boun Oum: since 1965 BOA had expanded when Continental Air Service (CASI) loaned it 2 PA18s, 2 C-47s, a second Dornier Do28 and a Beech Tradewind conversion: none of BOA's aircraft carried any airline logo and aircraft and their

Thai pilots were integrated with CASI by early 1967;

- As part of the overall shift of CIA paramilitary programmes to the US Dept of Defense, covert operations in Vietnam were turned over to a new Saigon-based Special Operations Group (SOG) controlled by the Pentagon from January 1964. Under SOG, infiltratiion missions into North Vietnam were to continue, using Chinese Air Force C-123Bs with ECM gear flown by Chinese and SVNAF crews, plus C-46s. From 1966 two unmarked China Airlines aircraft, a C-47 & Beech C-45 plus

crews, were contracted by SOG for flights within South Vietnam. The C-45 was used primarily by

the SOG commander and other senior personnel. The following year the C-45 was found to be unairworthy and was replaced by a modified PAC Tradewind effective 1.9.67;

- In June 1971 the Tradewind had been replaced by a C-46, which was used for SOG passenger flights. The C-46 hit a mountain 5.6.72 in Central Highlands, killing 11 Americans,1 South Vietnamese and 6 Chinese. After this, the remaining CAL crew returned to Taiwan, bringing to an

end this secret chapter of Republic of China participation in the Vietnam War;

- Parmerter p.375: "The prototype Tradewind N9981Z was operating in SE Asia in late 1966 for Continental Air Services Inc, then with Boun Oum Airways (owned by Laotian Prince Boun Oum)

then then for Sahakol Air in Thailand as HS-SKA. Its fate is unknown".

- photo of B-1530 in Taiwan: Tradewind single tail, trigear, E18S type fuselage, 4 square cabin windows: by 1979 N25SM had middle two windows extended to one long vista window + 2 standard windows;

N6651R noted Burbank 6.5.66.

N6651R noted Burbank CA 6.8.66 Turbo Tradewind, plate BA-154;

N25SM noted Bakersfield Air Park CA 8.76 Trigear Turbo Tradewind, plate BA-154;

N25SM noted Mojave CA 8.76 Turbo Tradewind;

N25SM noted Van Nuys CA 18.10.78 Tradewind;

N25SM photo (no date) in Alaska (looks like Fairbanks:GG) Turbo Tradewind trigear

"Umiat Alaska - Umiat Enterprises" titles above windows;

N25SM photo with titles "Alaska Umiat Enterprises";

BA-155	E18S	N48M	Ohio Aviation Co, Dayton OH	9.5.56
			Ohio Oil Co, Findlay OH	25.5.56/62
			Marathon Oil Co	23.8.62/63
			Ohio Aviation Co, Dayton Airport OH	63
			Broughton Plant & Equipment Co	11.63/66
			Ohio Aviation Co, Dayton Airport OH	7.66/72
			Van Dusen Acceptance Corp, Minneapolis MN	12.6.72/74
			Woods-Tucker Leasing Corp	15.7.74/75
		NASA948	NASA: leased	.74/75
			(NASA sensors, extended nose, cargo floor &	
			cockpit door installed 9.74)	
	Hamilton	N48M	Gordon B. Hamilton/ Hamilton Aircraft Co, Tucson AZ	10.75/76
	extended		Edward West/ American Turbine Aircraft Corp	.76/77
	nose		Hamilton Aviation Co, Tucson AZ	.77/80
			NASA, Space Technology Laboratories	19.5.80/81
			State of Louisiana, Dept. of Natural Resources,	
			Baton Rouge LA	12.3.81/88
			Hilderbrand Aero Service	2.2.88/89
			Thomas W. May/ May Air Xpress, New Boston TX	22.8.89/95
			crashed De Witt AR	27.9.96
			Springdale Air Services, Springdale AR	13.7.98/99
			Paul F. Amidon, Avondale AZ, later Lakespur CO	26.2.01/13
			Bill L. Rogers, Mukilteo WA	10.5.13/16
			William E. Garrison, Nickerson KS	7.9.16/20

NASA948: see Beech 18 by Robert Parmerter p.372;

NASA943 noted Tucson AZ 20.11.75: probably mislogging of this aircraft?

photo no date or place: NASA 948 & N48M painted on, NASA scheme, long nose, "Earth Resources Labortatory" above windows;

N48M noted Texarkana TX 7.97, 8.97 May Air Xpress: plate BA-155 built 5.56: long nose; N48M Springdale AR 16.8.99 long nose "Springdale Air Service" & "May Air Xpress" titles; N48M noted Phoenix-Goodyear Municiple AZ 24.12.00, tatty, tailwheel, fitted with nose section from a different aircraft:

BA-156	E18S	N39GB	Southern Airways Co: CofA issued	17.5.56
	-9700		Greene Brothers Lumber Co	21.5.56/62
		N11827 (3	Southern Natural Gas Co, Birmingham AL	12.62/66

N1182T	Southern Natural Gas Co, Birmingham AL	11.66/67
N4980V	Kieran Construction Co, Birmingham AL	12.1.67/72
	E L A Corp	20.6.72/73
	Tampa Air Center Inc, Tampa FL	21.2.73/78
	Air Continental Flying Association Inc	21.7.78/82
	(Aerospace Products cargo door installed 9.78)	
	Robert W. Metz, Sacramento CA	12.6.82/86
	engine fire during parachuting flight, Davis CA,	
	landed safely without airframe damage	16.4.83
	Aerospace Products Inc, North Hollywood CA	20.1.86
	Springdale Air Service, Springdale AR	2.86/99
	ground collision with Springdale AS E18S N2069C	
	on taxiway at UPS cargo ramp, Dalls-FTW TX	29.12.97
	Bush Air Inc, Wilmington DE	12.2.01/13
	reg expired 30.9.13, struck-off USCR	19.1.18

N4980V noted California City CA 9.83 plate BA-156;

N4980V noted Springdale AR 8.97 Springdale Air Service: plate BA-156 built 5.56, another plate: converted to E18S-9700 2.63;

N4980V noted Springdale AR 13.10.97;

N4980V noted Texarkana AR 6.8.98 Springdale AS, departed on freight flight to Shreveport-Dallas-Springdale AR

N4980V noted Springdale AR 16.8.99 Springdale AS;

N4980V noted Ft Lauderdale Exec FL 4.4.01;

BA-157	E18S	N26T	Baggett Transportation Co, Birmingham AL	.56/69
	ATE		(converted to American Turbine Engine Co ATE Westw	ind I:
	Westwind I		PT6A turbines, trigear, completed 4.69)	
	trigear	N2699	Thunderbolt Land & Cattle Co, Houston TX	.69/72
		N111EL	Air Transport Corp/ E&L Truck Rental, Dearborn MI	14.6.74/77
	Hamilton		(rebuilt as Hamilton Westwind III with tail gear,	
	Westwind I	II	extended nose by Hamilton Aviation at Tucson AZ)	
	tailwheel		exported to Colombia, struck-off USCR	2.77
		HK-1111 (1	Aerolineas Especiales de Colombia Ltda-	
			AE Colombia, Bogota-Eldorado	.76/78

HK-1111 noted Opa Locka FL 1.77 "A E Colombia" titles, Westwind III tailwheel (photo confirms no "G" suffix")

HK-1111G noted Opa Locka FL 30.3.77 AEC, Turbo Westwind;

HK-1111 noted Tucson AZ 4.6.80 rep as BA-77 trigear turbine, AE Colombia scheme but no titles;

HK-1111 noted Tucson AZ 28.10.80 reported as BA-77 Hamilton HA-1 Aerolineas Especiales freighter, converted from E18S in 4.80:

HK-1111 noted Tucson 5.11.81 rep as BA-77 Aerolineas Especiales;

HK-1111 noted Tucson 9.11.81 (GG) trigear "AE";

N111EL BA-157 on USCR 1991 printout (with many other long deleted BE18s): Air Transport Corp

Above is Parmerter's version (12/06) but HK-1111 was a trigear by 1980!!!!!!!!! Probably HK-1111(2 was BA-77;

BA-158	E18S	N38M	Andrew Schwartz, Chicago IL	63/64
	-9700		(converted 8.59 by Graubart Aviation: various mods,	
	Graubart		enlarged cabin windows; trigear installed 63)	
	Aviation		(displ. at Paris Air Show 6.63 as Graubart Trigear)	
	Trigear	D-IBEV	Battenfeld Maschinenfabrik, Meinershagen	.63/75
	_		dam. landing Meinershagen, West Germany	2.12.64
			(delivered to USA via Prestwick 12.9.75 as N70DG)	
		N70DG	reg	12.75
			gear collapsed landing, Chicago-DuPage IL	26.10.76
			M. A. Ammerman, Fort Sumner NM	8.7.77/82
			struck-off USCR	21.5.82

N38M noted Le Bourget 15.6.63 trigear, displayed at Paris Airshow 16.6.63; N38M visited Gatwick 31.8.63, 1.9.63, trigear large picture window;

N38M noted Geneva 17.9.63;

D-IBEV flew Meinershagen-Southend-Heathrow 20.1.64, Battenfield, plate BA-158;

D-IBEV visited London-Heathrow 20.1.64 Battenfeld, visited Heathrow 4.2.64; D-IBEV visited Schiphol 25.2.64;

D-IBEV arrived Sydney-Mascot 31.8.64 delivering a heavy industrial compression moulding press for a Sydney company, built by Battenfeld Machinery Co of Cologne,

flown by Battenfeld pilot Captain J. H. Blumschein: white & blue, trigear, "Battenfeld" above windows, enlarged cabin windows, airstair door:

plate: BA-158 built 5.56. modified to trigear 8.59;

100 hourly inspection at Flight Facilities, Mascot, departed Mascot 11.9.64 for Germany; D-IBEV noted Heathrow 11.2.66, 11.3.66, 22.6.66, 23.6.66, 30.6.66, 23.7.66, 31.7.66,

4.8.66, 19.8.66, 3.9.66, 30.9.66, 19.10.66, 17.12.66, 18.5.67: all Battenfield;

D-IBEV visited Yeadon 18.5.67 Battenfield;

D-IBEV noted Munich 27.5.66, 22.11.66 & 11.1.67;

E18S -9700 trigear	N46A (1	Atlantic Aviation Service: CofA issued E. I. duPont de Nemours & Co, Wilmington DE (Volpar tricycle gear, picture windows & G18S type two-piece windshield installed by	21.5.56 20.7.56/65
		Capital Aviation 4.65)	
	N299Z	Dow Jones & Co/ The Wall Street Journal,	
		Princeton NJ	24.5.65/67
		gear retracted during landing, Linden NJ	23.6.66
		J. J. Crosetti Co, Watsonville CA	27.7.67/73
		Sam L. Manatt	4.5.73/74
		S. R. Chaney	12.74/76
		Bryce Wisener, Garland TX	18.2.77/88
		William H. Wisner, Dallas TX	1.7.88/99
		J. D. Daniel, San Angelo TX	17.3.99
		Ray Johnson, Bridgeport TX	22.5.00/12
		Great Gulf Corp, Dallas TX	24.1.13
		sold to Canada, struck-off USCR	10.7.13
		(N299Z parked Brantford ONT 17/18 parts removed)	
	N299Z	Dakota Express LLC, Wilmington DE	9.7.19/20

N299Z noted Watsonville CA 23.4.72 trigear;

N299Z at Beech FlyIn, Tullahoma TN 18.10.00;

N299Z noted Mineola TX 2.8.02 rep has been based here past 20 years, reportedly recently sold; N299Z at Beech flyin Tullahoma TN 14.10.07;

N299Z nited Bratford ONT 8.17 trigear, props and panels removed, red and white; same 6.18;

BA-160	E18S	N40K	Southwest Forest Industries, Phoenix AZ	64
			National Commerce Bank, Tulsa OK	66
			damaged landing, cargo flight, Cheyenne WY	22.4.68
			Ross Aviation, Tulsa-Riverside OK	68/69
			Great Western Airlines, Tulsa-Riverside OK	28.7.69/74
			crashed destroyed landing in snow, Cheyenne WY	12.4.74

N40K accident report 12.4.74: Great Western, flight Riverton WY to Cheyenne to Denver CO, hit trees & pole on go-around in blowing snow, 11.46pm, pilot unhurt;

BA-161	E18S	N36V (1	J. R. Gray Co Inc, Dallas TX	29.5.56
	-9700	N3000S	J. R. Gray Co Inc, Dallas TX	11.7.56
			Roselie Shumaker	2.8.56/58
			The Hardy Corp	21.1.58/59
		N432U	The Hardy Corp	21.8.59/60
			Minne-Tex Inc	9.11.60/62
	trigear		(Volitan Aviation installed Volpar trigear 30.6.62)	
			Indiana-Michigan Corp, Chicago IL	10.5.63/65
			Jones & Lamson Machine Co: leased	10.5.63
			landed with nosewheel locked up, Boston-Logan MA	23.11.64
			Jones & Lamson Machine Co	26.7.65
			Chester County Aviation	2.8.65/66
			(G18S type two-piece windshield installed 9.65)	
			Federal Airlines/ Air North, Burlington VT	5.3.66/67
	ATE		(converted to American Turbine Engine ATE Westwind I	

Westwind I trigear conv. #22	by American Turbine Aircraft Corp, completed 1.67: type quoted in FAA file as "American Turbine 600R": trigear, PT6A-20 turbines)	
	Varis Leasing Corp, Burlington VT	7.3.67/70
	landed gear-up, Nassau, Bahamas	12.3.69
	McCollum Aviation, Danville IL	18.3.70/71
	Connell Chevrolet Co, Killeen TX	18.2.71/72
	Dee Howard Aircraft Sales, San Antonio TX	22.6.72
	Apollo Airways, Pine Bluff AR	26.6.72/77
Hamilton	(rebuilt as Hamilton Westwind III 3.77: tricycle gear	
Westwind III	replaced by conventional tailwheel, cargo floor,	
tailgear	Hamilton extended cargo nose, cockpit door)	
	Tilman E. Rosenblatt/ Baltimore Airways/	
	Baltair Cargo, Baltimore MD	25.3.77/83
	op: Pronto Aviation Services, El Paso TX	81
	gear retracted on landing roll, Albuquerque NM	23.1.81
	Methow Aviation, Wenatchee WA, later Everett WA	4.8.83/98
	Comanche Air, Winthrop WA	28.9.98/05
	op: Cascade Air, Ephrata WA	00
	(stripped for parts, Ephrata WA 00	
	op: Jim Baron, St Charles IL for skydiving	04
	ran off runway on takeoff, gear collapsed,	
	skydiving ops., Tullahoma TN (10 pax unhurt)	6.9.04
	(stripped fuselage on belly in trees, Tullahoma TN 06/14)	
	Jim E. Baron, St Charles IL	7.4.09/14
	Bill Stuart, Tullahoma TN	.17/20

N432U noted Reading PA 6.67 as American Turbine 600R trigear;

N432U noted visiting Montreal-Dorval QUE 10.67, turbines;

N432U noted Millville NJ 2.9.74 Westwind trigear;

N432U noted Burlington VT 12.79 "Baltimore Airways" titles, tailwheel; turbine in service; N432U accident report 23.1.81: Pronto Aviation, cargo flight from Denver CO, 7.17am,

pilot inadvertantly retracted gear, minor dam;

N432U noted Seattle-Boeing Field WA 16.3.85 turbines Methow Aviation "Pinocchio"; N432U noted Everett WA 24.5.90 Methow Aviation;

	7170207701	04 210,011 1	The solution invalidity	
BA-162	E18S	N32W	Alamo Aviation, San Antonio TX: new	.2.7.56/57
			sold to Mexico, struck-off USCR	23.1.57
		XB-YOT	reg	
			Aviones se Sonora, Hermosillo	77
			Guillermo S. Lopez	93
	XB-YOT no	oted Phoeni	x AZ 10.8.71;	
BA-163	E18S	N42E	Piedmont Aviation, Winston Salem NC: CofA issued	31.5.56
	-9700		Food Fair Stores Inc, Miami FL	11.56/67
		N4288	William C. Whitesell/ Continental Aircraft Sales/	
			Longhorn Airways, Medford NJ	6.3.67/69
			Carolina Aircraft Corp, Ft Lauderdale FL	69
	ATE		American Turbine Aircraft Corp, Long Beach CA	25.4.69/72
	Westwind I		(converted at Long Beach CA to ATE Westwind I:	
	trigear		Volpar trigear, PT-6A turbines, cargo door,	
			picture window, two-piece windshield, completed 9.69)	
			Hamilton Aircraft Co, Tucson AZ	16.2.72
	Hamilton		(rebuilt as Hamilton Westwind III: trigear replaced by	
	Westwind I	II	tailwheel gear, cockpit door, Hamilton extended cargo n	ose
	tailgear		completed by Hamilton 6.72)	
			SMB Stage Line Inc, Des Moines IA	29.6.72/78
			Blackhawk Airways, Janesville WI	5.9.78/79
		N4288T	Blackhawk Airways, Janesville WI	15.2.79/80
		N924J	Earl L. Christ, Racine WI	2.80
			The Beta Corp	20.2.80/84
			op: Check-Air Inc, Milwaukee WI	81
			Coastal States Aviation, Denver NC	18.9.84/85
			op: Mountain Air Cargo, Denver NC	84

American Federal Bank, Equipment Leasing Division,

	Greenville SC	1.2.85/89
	lsd: Mountain Air Cargo, Denver NC	1.2.85/89
	Methow Aviation, Everett WA & Wenatchee WA	1.3.89/91
	Jim & Louise A. Baron, St Charles IL	11.3.93/13
	(retired engineless Aurora IL 99/02)	
	struck-off USCR	28.10.13
N924J	Dash Flying Service, Chilton WI: rest. to USCR	26.11.17/20

N4288 noted Burbank CA 15.11.69 Westwind Mk.1 trigear turbine;

N4288 noted Long Beach CA 8.6.71 Westwind trigear, "Westwind I" titles;

N4288 noted Tucson AZ 3.4.72 at Hamilton Aircraft ramp, Westwind;

N4288 noted Columbus OH 10.72 Westwind III tailwheel, "SMB Stage Line" titles;

N924J noted Coeur d'Alene ID17.10.91 "Methow" tailwheel turbine Westwind;

N924J noted Seattle-Boeing Field 24.5.90, 10.8.90: both "Methow" titles, in service, Westwind III;

N924J noted Aurora IL 8.97 as Westwind III;

N924J noted Aurora IL 7.99, tailwheel, long nose, no titles, engineless;

N924J noted Aurora IL 2.8.99 "The Bear", plate BA-163 built 5.56, conv. -9700 mods 10.59;

report 2000: parachute jump plane at Xenia OH;

N924J noted Aurora IL 30.12.01 engineless; unchanged 9.6.02;

N924J noted Aurora IL 24.7.03 Westwind III engineless, not titles;

BA-164 •	E18S	N49A (1	Anderson Air Activities: CofA issued	31.5.56
	-9700	N510Ġ (2	Gisholt Machine Co	25.7.56/61
		N510Q `	Gisholt Machine Co	7.2.61
			Western Mutual Insurance Co, Des Moines IA (picture windows, extra window, and G18S type two-piece windshield installed 3.62)	10.61/67
			Air Travel Inc. Des Moines IA	18.7.67/70
			Barton Manufacturing Inc, Campbellsport WI	9.12.70/71
			Thomas L. Waller & Mark D. Goforth	14.6.72/73
			Circle S Farms Inc	13.7.73/77
			A. L. Sutton, Fort Davis TX	2.9.77/78
			Thomas Bussard	14.3.79/86
			US Customs Service: aircraft forfeited	6.1.86
			Jim Hankins Air Service, Jackson MS	13.8.86
			Tora Express Inc, Monroe LA	11.86/88
			Aircraft Technical Support Inc, Galena OH	20.1.89/96
			John S. Rux, Chicago IL	2.7.96/13
			op: Skytrain Inc, Wakeman OH	99
			struck-off USCR	25.3.13

N510Q noted Van Nuys CA 13.11.76;

N510Q noted Oshkosh WI 27.7.89, plate BA-164;

N510Q noted Wakeman OH 8.97;

N510Q noted Wakeman OH 9.8.99 "Sky Train" placard in window, plate: BA-164 built 6.56, converted to -9700 10.59;

N510Q noted Cleveland-Hopkins OH 8.99 flying;

N510Q noted Tulsa OK 11.17 open storage complete, brown and cream, vusta windows;

BA-165	E18S	N48A	Aircraftsmen Inc, Oklahoma City OK: CofA issued	5.6.56/57
		N225H	Halliburton Oil Well Cementing Co, Duncan OK	25.3.57/68
			Princeton Mining Co, Terre Haute IN	22.2.68/69
			SMB Stage Line Inc, Des Moines IA	5.8.69/78
			gear collapsed landing, Muskogee OK (cargo door installed 9.77)	20.1.71
			Ralph Quinlan/ Mountain Air Cargo, Denver NC (cockpit pilot door installed 10.78)	18.9.78/82
			op: General Aviation Inc, Greenville TN	80
			ABC Flying Inc, Cedarville OH	29.3.82/83
			Carlos Rosario: sale documentation not completed (noted retired derelict Beef Island Airport, BVI 85)	.83
	N225H n	oted Kansas	City MO 30.10.69;	
BA-166	E18S	N27T	Page Airways, Rochester NY: CofA issued	5.6.56/57

8.5.57/58

Webb & Knapp Inc

trigear		The Allan Corp, Morristown NJ Clayton Irwin Allan P. Kirby/ Allan Corp, Morristown NJ Tri-State Aviation, Washington PA (Volpar Mk.IV tricycle gear installed 6.64 by Capitol Aviation, Springfield IL)	10.7.58/59 10.59/60 8.4.60/64 17.1.64/67
	N405FW	Rolair Corp/ Wright Air Lines, Cleveland OH Metro Commuter, Denver CO: leased Frank E. Bachner US Bureau of Customs: aircraft forfeited	19.5.67/70 69 2.10.70/72 22.5.72
	N2395M	US Bureau of Customs Michael K. Knight Franklin B. Davis, Coral Springs FL (FAA report 78: false address)	5.7.72/78 1.3.78 31.3.78/80

N405FW owned Rolair, appears leased fleet to Wright Airlines, Cleveland; N405FW noted Ft Lauderdale FL 13.6.71; N2395M noted NAS Corpus Christi TX 10.5.73 "US Bureau of Customs", trigear; N2395M noted Opa Locka FL 2.10.77 trigear;

BA-167	E18S	N32R	J. D. Reed Co, Houston TX	2.56
		N4321D	Beech Aircraft Corp, Wichita KS	.56
			(delivered to India via Prestwick 28.6.56)	
			sold to India, struck-off USCR	2.7.56
		VT-DIR	Hind Provincial Flying Club, Lucknow	7.56/79
			Indamer Co, Bombay-Juhu	.89/92
			(noted Juhu 13.7.92, dismanted stored under sheets	
			outside Indamer hangar, with D18S VT-CJV)	
			broken-up for scrap, Bombay-Juhu	.96

VT-DIR noted Juhu 13.7.92, dism. under sheets outside Indamer hangar, with VT-CJV; VT-DIR noted Bombay-Juhu 1.93 "being rebuilt";

BA-168	E18S	N34W	Combs Aircraft Inc: CofA issued	11.6.56
			Midwest Oil Corp, Fort Worth TX	9.7.56/64
		N234W (2	Combs Aircraft Inc	12.64/65
		•	Mark Warinner, Boulder CO	9.11.65/67
			(smoke spotters hatch behind door fitted 5.66)	
		N904BC	Birko Chemical Corp	24.4.67/68
			Sentinel Airways Systems Inc	20.9.68
			Wallace R. Sitton, Tarzana CA	2.4.70
		N555WS	Wallace R. Sitton, Tarzana CA	11.70/71
	Hamilton		Circle S Farms Inc, Ashland OR	17.2.71/76
	Little Liner		Schaefer Air Service, Los Angeles CA	1.8.76/84
			Telcom Communications Inc, Fresno CA	16.5.84/86
			Paul A. Broussard/ Classic Aeroplane Leasing,	
			Madera CA	11.6.86/05
			Jack Shepard, Columbia MS	29.7.05/18
			Deer Creek Dusters Inc, Rolling Fork MS	24.10.20/21

N555WS noted Van Nuys CA 17.4.72;

N555WS noted Van Nuys CA 2.76 & 13.11.76: both "Schaefler Air Ambulance" titles, tailwheel;

N555WS noted Long Beach CA 8.78;

N555WS noted Van Nuys CA 23.6.82 no titles, excellent condition, tailwheel; N555WS noted Van Nuys CA 26.7.82 Shaefer Air Ambulance emblem;

N555WS noted LAX 2.84 no titles, landed;

N555WS at Beech flyin Tullahoma TN 14.10.07;

BA-169	E18S	N45E	Veeder Root Inc, Hartford CT	63/64
	trigear		American National Bank, Jacksonville FL	66
	J		op: Florida Atlantic Airlines, Fort Lauderdale FL	68
			Leasing Consultants Inc, Forest Hills NY	69
			Burnside Ott Aviation Training Centre, Opa Locka FL	4.5.70/71
			op: South Atlantic Airlines, Hilton Head Island SC	71
			sold to Colombia, struck-off USCR	10.8.71
		HK-1248P	reg	8.71

	Jairo P. Forero	26.4.72
HK-1248	Aerotor	72
	Aerotabo	
	Aerolineas Medellin, Medellin	76
	M. Gandur de Cabrates	82

Florida Atlantic Airlines, FLL operate daily third level services to Freeport, Bahamas with three Beech 18s in 68: six Hansa jets have been ordered;

N45E noted Opa Locka FL 6.10.68 trigear, N45E noted Opa Locka FL 27.5.70 trigear;

HK-1248 noted Bucaramanga, Colombia 30.9.72 Aertor;

BA-170	E18S	N51K (1	Gopher Aviation, Rochester Airport MN: CofA issued	18.6.56
			Rockford Screw Products Inc	26.6.56/62
	-9700		(mods. to E18S-9700 4.59)	
		N251K	Rockford Screw Products Inc	21.8.62
			Beloit Corp, Beloit WI	6.9.62/70
			Griffing-Sandusky Airport Inc., Sandusky OH	8.7.70/72
			Blackhawk Airways, Janesville WI	23.4.72/73
			North Continent Airlines, Long Beach CA	23.2.73/84
			op: Blackhawk Airways, Janesville WI	73
			struck baggage carts taxying, Chicago-O'Hare IL	1.11.73
			Richard Wixom/ Blackhawk Airways, Janesville WI	78/84
			Aero Taxi-Rockford Inc. Rockford IL	30.7.84/95
			Earl V. Long, Wichita KS	31.7.95/96
			Kestrel Inc, Waukee IA	12.96/99
			Methow Aviation, Everett WA	12.9.00/05
			Kestrel Inc. Waukee IA	25.5.05/06
			Neenah Classic Aircraft LLC, Menasha WI	21.8.07/20

N251K noted Chicago-O'Hare 1.10.72 Blackhawk Airways;

N251K noted Chicago-O'Hare 17.11.76 Blackhawk Airways;

N251K accident report 1.11.73: Blackhawk Airways, flight Waterloo IA to O'Hare, taxying after landing, 9.50pm;

N251K noted Chicago-O'Hare 117.11.76 Blackhawk Airways;

N251K noted Long Beach CA 7.9.83 North Continent Airlines;

N251K noted Rock Falls IL 12.88 arr on freighter charter, op Aero Taxi, tailwheel;

N251K noted Tucson AZ 30.4.92;

N251K noted Ankenky IA 24.7.98 freighter Kestrel Inc, plate: BA-170 built 6.56,

plate: conv. 4.59 to E18S-9700;

N251K noted Moses Lake WA 22.3.00 "Methow" titles;

N251K noted Sitka AK 6.8.03 "Methow" titles;

N251K noted Neenah WI 22.7.17 "Methow" titles, having maintenance in hangar;

E18S	N73V	Topeka Aircraft Sales & Service, Topeka KS	13.7.56
-9700		Wilcox Electric Co	17.7.56/61
		Seaboard Allied Milling Corp, Kansas City MO	11.61/63
		Wylie-Stewart Machinery Co, Oklahoma City OK	25.4.64/68
trigear		(tricycle gear, picture windows, G18S type	
Ü			
		Webster B. Todd/ Princeton Aviation Corp	8.67/69
		· · · · · · · · · · · · · · · · · · ·	5.10.67
	N4303Y		27.4.68/69
		· ·	
			10.69/71
		,	70
		Panorama Air Tour Inc. Honolulu HI	1.2.71/75
		Ray Berney, Warren Bailey, Berney Thompson/	
		•	30.9.75/82
			26.7.82/85
		·	71/84
		·	12.85/87
		•	3.2.87/89
		·	10.5.89/91
		accident Bimini, Bahamas	15.8.91
	-9700	-9700	-9700 Wilcox Electric Co Seaboard Allied Milling Corp, Kansas City MO Wylie-Stewart Machinery Co, Oklahoma City OK trigear (tricycle gear, picture windows, G18S type two-piece windshield installed 6.65) Webster B. Todd/ Princeton Aviation Corp damaged gear collapsed landing, Newark NJ N4303Y Princeton Aviation Corp Bernard L. Warner/ Spectrum Leasing Corp, Van Nuys CA op: Hawaii Pacific Airlines, Honolulu HI

struck-off USCR 28.10.91

N73V accident report 5.10.67 Princeton Aviation, gear collapsed due maintenance;

N4303Y noted Washington-DCA 2.10.68 trigear;

N4303Y noted Honolulu 9.9.70 & 5.10.70 both "Hawaii Pacific" trigear;

N4303Y noted Honolulu 8.9.71 & 1.76 trigear "Panorama AT";

N4303Y noted Kahului HI 27.7.76 Panorama AT;

N43034Y noted Honolulu 12.11.79;

N4303Y noted Hilo 26.8.81 "Panorama AT" #53, in Beech 18 tour formation;

N4303Y in Panorama fleet list as at 15.11.83: BA-171 tt 14,860 hrs, fleet #53;

N4303Y noted Van Nuys CA 25.8.85 "Panorama Air" titles #53;, trigear;

N4303Y noted Van Nuys CA 15.10.85 "Panorama Air" titles #53 trigear;

N4303Y noted Ft Lauderdale FL 20.9.90;

accident 28.10.91: no details in NTSB listing, op quoted as Pleasure Flying Airways;

BA-172	E18S	N42RJ	The Norman Larson Co: CofA issued	25.6.56
	-9800		Robert O. Cummings/ Cummings Research	9.7.56
			Hughes Aircraft Co: leased	12.7.56/61
			Ten Sixty Corp, Beverly Hills CA	63
		N139HH	Hastings Harcourt/ Santa Barbara Aviaton CA	11.63/65
			(PacAero installed two-piece windshield 1.64)	
		N1399H	Hastings Harcourt/ Santa Barbara Aviation CA	12.65/66
			Wholesale Aircraft Inc	11.5.66
		N797S	Aircraft Owners Inc, Miami FL	11.66/67
			(picture windows installed 12.66)	
			Calhoun Aviation, Battle Creek MI	2.8.68/71
			Michigan Air Activities, Battle Creek-Kellog MI	15.2.71/76
		N797SB	Security National Bank	6.76/77
			G E M Interstate Development Co, Hickory Corners WI	12.77/83
			SmithAir Inc, Sharpsburg GA	7.8.83/94
			Piedmont Air Cargo, Gastonia GA	6.7.94
			Aero Express Inc, Dearborn Heights MI	6.6.95/96
			Jim Hankins Air Service, Jackson MS	7.3.96/99
			Jim Ryan/ Brazoria County Mosquito Control District,	
			Angelton TX	21.10.99/09
			(under-wing spray bars fitted .99)	
			forced landing, struck two cows and wood pile, after	
			wing hit a correctional facility tower during a turn followin	g
			a mosquito spray run, Jones Creek TX	3.10.09

N42RJ flown by TV star Bob Cummings, often appeared featured in his TV shows; N797SB noted Albany GA 20.8.98 in service, freight, Hankins Air Service, plate: BA-172 built 6.56, another plate: converted to E18S-9800 9.64;

N797SB on Jim Hankins Air Service fleet Status Report 10.8.98, TT9323 hrs;

N797SB noted Angleton TX 8.5.03,

N797SB noted San Marcos TX 18.7.03 good condition, "Brazoria County Mosquito Control District" titles, spray-bars under wings;

N797SB noted Angleton TX 9.8.03 flying, pilot Jim Ryan owner, plate BA-172;

BA-173	E18S	N46W	built	.56
		N456T	Transwestern Pipeline Co, Houston TX	63/66
			Fletcher Aircraft Leasing Corp, Bellaire TX	69
			Coastal Airways, San Juan, Puerto Rico	25.8.69/71
			crashed destroyed on takeoff, hit Beachcomber Hotel,	
			St. Thomas-Truman USVI (8k)	21.4.71
		,	21.4.71: Coastal Airways: engine failed on takeoff;	
BA-174	N456T a	n23W	21.4.71: Coastal Airways: engine failed on takeoff;  Beech Aircraft Corp, Wichita KS: CofA issued	29.6.56
BA-174		,	· •	29.6.56 17.8.56
BA-174	E18S	,	Beech Aircraft Corp, Wichita KS: CofA issued	
BA-174	E18S	,	Beech Aircraft Corp, Wichita KS: CofA issued Ohio Aviation Co, Dayton OH	17.8.56 11.56/65
BA-174	E18S	,	Beech Aircraft Corp, Wichita KS: CofA issued Ohio Aviation Co, Dayton OH Perfect Circle Corp, Hagerstown IN	17.8.56 11.56/65
BA-174	E18S	N23W	Beech Aircraft Corp, Wichita KS: CofA issued Ohio Aviation Co, Dayton OH Perfect Circle Corp, Hagerstown IN Dana Corp	17.8.56 11.56/65 15.3.65/66

	Louis W. Mack Aircraftsmen Inc, Oklahoma City OK (Beech cargo door installed 6.68)	10.67/68 9.2.68/70
NOOOL	Stuart E. Aegler/ Great Lakes Aviation Corp	13.1.71
N20GL	Great Lakes Airlines, Chicago IL	11.71/74
	Semo Aviation Inc, Malden MO	17.5.74/79
	Word Science Corp	15.3.79
	Glades County Sheriffs Department FL: seized	4.10.79
	Knight Aircraft Corp	11.79/80
	Carl Morriss	12.80/82
(N174CM)	ntu: Carl Morriss	30.5.81
N20GL	Karl Knight/ Global Aircraft Inc, Miami FL	28.5.82/84
	Mark Olson, Humboldt IA	8.82
	Brian Clark, Miami FL	9.84/85
	US Marshal: seized at Sylvania GA by	
	Drug Enforcement Administration:	23.9.85/91
	Hubert J. Dwyer, Clear Lake IA	19.4.91/13
	struck-off USCR	22.5.13

N423W noted Ft Lauderdale FL 24.8.71;

N20GL noted Mason City IA 8.97, open storage poor condition: plate BA-174 built 6.56; N20GL noted Mason City IA 25.7.98 unchanged;

N5600D & N20GL auction at Mason City IA 6.17: N20GL stripped hulk in very high grass;

3A-175	E18S	N46D	Cutter Carr Flying Service, Cutter Carr Airport,	•
			Albuquerque NM: CofA issued	10.7.56/57
			Galles Motor Co	28.2.57/60
			Continental Oil Co, Houston TX	3.1.60/66
			Dunham-Price Inc	10.66/69
			Wiles-Holloway Inc, Baton Rouge LA	20.1.69/70
			Southern Fleet Leasing Corp, Baton Rouge LA	5.70/72
			Transcontinental Air Service	6.1.73/75
			Robert Robinson/ National Aviation	8.75/76
			op: National Air Freight	75
			Aerospace Products Inc, North Hollywood CA	28.2.76
			Patrick W. Lawing	12.76/77
			Fess E. Parker	15.9.77/78
			Aerospace Products Inc, North Hollywood CA	11.78
			Leon & Velma Wheeler	11.78/80
			Landwealth Inc, Houston TX	10.81/82
			P. W. Burtis, Dallas TX	21.5.82/83
			Charles R. Warren, Dallas TX	5.83
		N599DC	Charles R. & Dorothy J. Warren, Dallas TX	16.5.83/90
		N818TW	Tom J. Wakefield/ Devils Lake Aviation, Devils Lake ND	3.90/94
			Robert H. Powell, Wayzata MN	17.6.94/96
		N818RP	Robert H. Powell, Wayzata MN	22.7.96/97
			Powell Air Inc, Wayzata MN	3.3.97/16
			Island City Seaplanes Inc, Cordova AK	17.2.16/19
		N54CX	Island City Seaplanes Inc, Cordova AK	2.5.19

N46D noted Hayward CA 19.9.75 "National Air Freight" titles, tailwheel; N818TW noted Pine Bluff AR 2.95, tailwheel;

N818RP at Oshkosh WI 8.97 plate BA-175 built 7.56;

N818RP at Oshkosh 8.98 owned Powell Air;

N818RP noted Anoka County MN 13.7.03 tailwheel;

BA-176	E18S	N50K	Continental Oil Co, Houston TX	63/64
			Great Western Investment Corp, Corpus Christi TX	66
			Davis Airlines, Bryan TX	68/70
			MS & C Realty, Killeen TX	71/72
		N50JR	Bromley Corp, Dallas TX	26.1.72/73
			op: Robert Airways	73
			crashed destroyed on takeoff, Natchitoches LA	20.9.73
			(6k including singer Jim Croce)	

N50K noted College Station TX 7.70 "Davis Airlines" titles, tailwheel, in service; 20.9.73 crash report: Robert Airways: 10.45pm, slow climb after takeoff from Natchitoches Municiple Airport, wing struck top of tree and aircraft crashed to ground. Pilot incapacitation, had coronary artery disease, had just run 3 miles from motel to airport; singer Jim Croce had just completed a performance at Northwest State University:

BA-177	E18S	N70A	Protective Insurance Underwriters, Omaha NE	63/66
	-9700	N2070A	SMB Stage Line Inc, Des Moines IA	69/79
	Hamilton		op: Little Mountain Alr Cargo, Denver NC	78
	Westwind		Southern National Leasing Corp, Charlotte NC	30.6.78/81
			minor damaged in gear-up landing, Blountville TN	5.9.78
			op: General Aviation Inc, Greenville TN	80
			op: Mountain Air Cargo, Denver NC	80/81
			crashed forced landing off-airport at night, struck poles	
			while avoiding buildings, Glen Burnie MD	15.12.81

N2070A noted Chicago-O'Hare IL 3.2.69 SMB Stage Line;

N2070A noted Harrison AR 13.7.73 SMB Stage Line;

N2070A accident report 5.9.78: Little Mountain Air Cargo, cargo flight Greenville TN to Blountville, 5.48pm, pilot unhurt;

N2070A accident report 15.12.81: Mountain Air Cargo, cargo flight from Glen Burnie MD to Columbus OH, carb icing, right engine failed, left running rough, 11.07pm, pilot unhurt;

BA-178	E18S	N41R	US Department of Agriculture, US Forest Service: CofA	25.7.56
		N141Z	USDA /US Forest Service, Ogden UT	5.3.59/78
	Aerojet		(Aerojet rocket engines installed 17.6.59)	
	rockets		struck trees during low pass, Taos NM	15.11.65
			unairworthy: struck-off USCR	12.4.78
			US Dept. of Agriculture,	
			Animal & Plant Health Inspection Service (APHIS)	25.1.79/80
		N141ZA	USDA/ APHIS: restored to USCR	15.1.80/85
			(converted for fruit fly spraying 1.81)	
			USAF Museum Foundation	20.7.85/86
			struck-off USCR	11.85
			Hawkins & Powers Aviation, Greybull WY	11.2.86/00
			D & G Inc, Greybull WY	24.8.00/02
			Advanced Air Inc. Council Bluffs IA	16.11.04/07
			struck-off USCR as "sold to New Zealand" (not del.)	4.10.07
			Taigh Ramey, Stockton CA	10/15
		N141ZA	Taigh Ramey/ Vintage Aircraft Inc, Stockton CA	11.12.15/19
			Airventures LLC, Englewood CO	6.2.20/21
			·	

N141ZA noted at USFS base Illinois Valley OR 5.9.66, tailwheel, cream & red, USFS insignia, JATO equipped;

N141ZA noted Greybull 2.8.89 metallic, in service;

N141ZA noted Greybull 26.6.90, 12.10.92, H&P in service;

N141ZA noted Sheridan WY 8.8.95 in Big Horn Airways hangar (H&P subsidiary)

N141ZA noted Sheridan WY 3.8.00 H&P, stored in hangar, plate BA-178 built 7.56; Further details on USFS use: see Beech 18 by Robert Parmerter p.291;

N141ZA noted at Stockton CA 14.9.10 parked outside in civil paint scheme;

N141ZA noted Stockton CA 29.6.17 reported in excellent condition; Stockton 19.10.20;

BA-179	E18S	N49S N70TG N7010	built Texas Gas Transmission Corp, Owensboro KY Indianapolis Transit Service, Indianapolis IN Wisconsin Airways, Milwaukee WI Horizon Aviation Enterprises, Chicago IL SS Airways Inc, Mission KS	.56 63/64 66 69 70 6.11.75 24.12.75
BA-180	E18S	N48D N83CP (2	built Chas Pfizer & Co, Maywood NJ American Aero Leasing Corp, Elizabeth NJ Jack Adams Aircraft Sales, Walls MS Leasing Consultants Inc, Forest Hills NY	.56 63/64 66 69 70

	Burnside Ott Aviation Training Centre, Opa Locka FL	70
	Jordan Klein Inc, Miami FL	72
	International Airmotive Corp, Fort Lauderdale FL	8.11.72
	sold to Chile, struck-off USCR	8.11.72
CC-CLJ	req	.72

N83CP noted Miami FL 27.5.70, N83CP noted Ft Lauderdale FL 13.6.71; CC-CLJ noted Ft Lauderdale FL 1.10.72;

BA-181	E18S	N60K	Beech Aircraft Corp, Wichita KS: CofA issued	10.7.56
			Gerald C. Francis/ Francis Aviation, Lansing MI	12.56/57
			Galion Iron Works & Manufacturing Co	12.2.57/60
			Bailey Leasing Corp/ George H. Bailey Co, Ft Wayne IN	16.9.60/62
			Aircraftsmen Inc, Oklahoma City OK	5.5.62/63
			Texas Aviation Investments Inc, Amarillo TX	63
			Shulton Inc, Clifton NJ	21.8.63/69
	trigear		(Volpar Mk.IV trigear & two-piece G18S type windscreen installed 1.64)	
			Mercury Aircraft Inc, Hazard KY	10.5.69/73
			op: Catawba Air Transport	72
			gear collapsed landing, Hickory NC	20.3.72
			Jimsair Aviation Services, San Diego CA	6.6.73
			Santiago F. Braccamonte	6.6.73
		N407JB	Santiago F. Braccamonte	.74/77
		XA-GOX	Servicos Aeronauticos de Baja California S.A.	10.1.77/83
			struck-off Register	6.83
			G. L. Gaylor Construction Co, Thermal CA (stored Thermal CA 83/84)	16.7.83/84
		N18LG	G. L. Gaylor Construction Co, Thermal CA	18.1.84/14
			George L. Gayler, Thermal CA	6.1.14/20

#### N60K noted Toronto 1.4.64;

N60K accident report 20.3.72: Catawba Air Transport, gear failed due mechanical fault; XA-GOX noted San Diego-Lindberg Field CA 12.78 landing, trigear "Servicios Aeronauticos de Baja California" titles: rep. used by Governor of Baja California; N18LG noted Thermal CA 12.8.08;

BA-182	E18S	N43T	Tulsair Distributors Inc, Tulsa OK: CofA issued	19.7.56
			Texas Natural Gasoline Corp	10.8.56/60
			Union Texas Petroleum	10.60/62
			Madden & Smith Aircraft Corp, Miami FL	5.6.62
			John T. Oxley, Tulsa OK	6.6.62/74
			Great Western Airlines, Tulsa OK	13.3.74/76
			(cabin cargo door installed 4.74)	
			minor damage on takeoff, Erie PA	30.1.76
			Sam Vires/ Mid-South Aircraft Sales, Memphis TN	12.76/77
			Carlisle Air Transport, Carlisle AR	22.2.77/78
			Larry Blatt & Robert Mascaro/ Lake County Aviation	10.78/83
			Richard A. Healey & Jose Masrtinez-Alegria, Miami FL	18.3.83/85
			(Aerospace Products cargo door installed 5.83)	
			Andres Suarez, Miami FL	1.12.85/86
			damaged ran off runway on takeoff, Opa Locka FL	13.12.85
			Guidi Luis Felipe Gonzalez, Miami FL	2.86
			Rafael A. Medrano: sale documention not completed	31.3.86
			Intermarketing Air Corp, Miami FL	21.4.86/91
			(noted parked at Paitilla, Panama 12.86)	
			·	

N43T accident report 30.1.76: Great Western, takeoff on flight to Pittsburgh PA, swerved on takeoff, struck right wing on runway, landed again, 9.50pm, pilot unhurt; N43T noted Ft Lauderdale FL 31.10.81 Carlisle Air Transport titles on roof, appears retired;

N43T noted Ft Lauderdale FL 31.10.81 Carlisle Air Transport titles on roof, appears retired; N43T noted Miami FL 25.10.84;

accident report 13.12.85: no owner quoted, tailwheel;

BA-183	E18S	N47E	Gerald C. Francis/ Francis Aviation, Lansing MI	20.8.56	
			Hydro Manufacturing Co, Detroit MI	12.9.56/73	

Blackhawk Airways, Janesville WI	19.5.73/81
(cargo door installed 6.73, cockpit door 10.76)	
Sky Train Inc	13.3.81
Kevin P. Donnelly & Gary D. Douris/ Big Iron Airways,	
Culver City CA	14.7.81/82
Coast Air Freight Inc, Long Beach CA	11.5.82/87
Aerospace Products Inc, North Hollywood CA	12.87/90
Centre Airlines Inc, Reedville PA	18.7.90/93
crashed Mount Nittany near State College PA	23.2.93

N47E noted Chicago-O'Hare 17.11.76 Blackhawk Airways titles;

N47E noted Chino CA 31.1.81 no titles, ex Blackhawk AW;

N47E noted Long Beach CA 9.83 no engines;

N47E noted LAX 11.1.84 Coast Air Freight;

N47E noted LAX 3.85 no titles, all metal finish, tailwheel, flying;

N47E noted Van Nuys CA 12.6.90;

N47E noted Philadelphia PA 20.10.90, all metallic no titles;

BA-184	E18S	F-OAXQ	Gouvernement du Niger, Niamey	5.9.56/65
		(delivered via Prestwick 7.8.56)		
	5U-MAW	Niger Air Force	.65/73	
		(F-BUOP)	ntu	.73
		,	noted Cannes Airport, as "F-BCCI Chambre de Commer	ce
			et d'Industrie de Cannes"	8.74
			Cannes-Mandelieu, France: displayed on pole at airport	
			entrance as "F-BCCI Aeroport Cannes Mandelieu",	
			later repainted various colours, and "Breitling" titles	76/14

F-BCCI noted Cannes 8.74 "Chambre de Commerce et d'Industrie de Cannes" (F-BUOP reallocated to a Do.27 in 12.74)

F-BCCI noted Cannes as gate guard 6.76, 8.8.79, 8.86; F-BCCI noted 7.6.00 white with green cheat line "Aeroport Cannes Mandelieu" titles noted 7.6.01 repainted with no reg, white with grey/blue cheatlines (no reg) and titles "Aeroport Cannes-Mandelieu Chambre de Commerce et d'Industrie Nice Cote d'Azur";

F-BCCI on pole unmoved 22.2.03; unchanged 17.8.05; same 9.07, 1.5.08; on pole 12.1.14;

BA-185	E18S	N84D (1	Youngstown Airways/ Lease Air, Youngstown OH	56
		N820	Youngstown Airways, Youngstown OH	11.56
			Studebaker Corp, Minneapolis MN	63/64
			Tulakes Aviation, Bethany OK	66
			tail gear collapsed landing, Albuquerque NM	22.12.66
			Wat Henry Car Leasing Co, Tulsa OK	12.12.67/68
			ditched, sank Gulf of Mexico, Marco Island FL	5.9.68

N820 accident report 22.12.66: Tulakes Aviation, swung on landing tail wheel collapsed;

BA-186	E18S	N18Y	Alamo Aviation, San Antonio TX	56
			O. L. Longoria	12.56
		XB-ZEO	O. L. Longoria/Empresas Longoria S. A.	57/72
		N38219	Sam Vires/ Mid-South Aircraft Sales, Memphis TN (US CofA renewed18.12.72)	11.72
			Century Granite Co	12.72/76
			California Western University, Santa Ana CA	11.76/81
			Chipola Oil Corp, Brighton CO	20.5.81/82
			Antilles Air Charters	5.10.82/83
			Jorge Castro, Rio Pedras, Puerto Rico US Marshal, District of Pueto Rico:	1.11.83/85
			seized by Drug Enforcement Agency	16.9.85/88
			Atlanta Air Salvage	22.8.88
			Don J. Oglesby, Fayetteville GA	19.9.88/90
		N18SE	Don J. Oglesby, Fayetteville GA	14.1.90
			Eastport Enterprises Inc, Wilmington DE	23.8.90/95
			Shores Ag Air Inc, Robstown TX	12.95/19

# N18SE at Beech fly-in Tullahoma TN 10.93, N18SE at Beech fly-in Wichita KS 11.10.97;

BA-187	E18S	N55H	built	.56
			Fram Corp, East Providence RI struck-off USCR	63/72 27.11.72
3A-188	E18S	N18R (1	built	
		N4X	rereg	17.12.56
		N650M	Mathieson Olin Chemical Corp, New York NY forced landing gear-up off airport after engine broke	63
			away in flight, Columbia LA	21.4.66
		N139K	Modern Aero Sales, Dallas-Redbird TX	66/69
			Georgia Air Inc, Atlanta GA	26.1.70
			crashed destroyed during forced landing off-airport, due in-flight fire, Sioux City IA	19.5.70
	N139K a	ccident report	19.5.70: Georgia Air, cargo flight;	
3A-189	E18S	N48E	J. R. Gray & Co/ Executive Air Transportation Service,	
			Dallas TX	14.8.56/59
			Tecon Corp	2.1.59
			Jeffries & Betts Gravel Co	11.9.59/60
			Trishman Equipment Leasing Inc	18.3.60/62
			Wesco Leasing Corp, Addison TX	19.9.62/67
		N6039F	Wesco Leasing Corp, Addison TX	
		N165X	Aerodyne Engineering Corp	5.10.67/68
			Transamerica Commercial Corp, New York NY	14.6.68/69
			Marvin Hambrick/ Hambrick Aircraft, Lafayette CA	11.69/79
			George C & Janet L. Holberton	10.79/81
			Christopher J. & Christine A. Petrikas,	
			Lake Havasu City AZ	6.81/88
			(Aerospace Products wrap-around windshield	
			installed 9.87)	
			Cal Corp, Oakdale CA	28.1.88/94
			F1 Systems Inc, Bandon OR	9.11.94/95
			Hardin Optical Co, Bandon OR	20.3.95
			FIL Systems, Bandon OR	11.97
			Thomas E. Duzan, Kennewick WA	23.4.98/15
			Redhead LLC, Wilmington DE	10.3.15/17
			J & M Aviation Enterprises. Greendale WI	30.1.18
		oted Van Nuy oted Van Nuy	s CA 4.11.69; s 10.87;	
			KS 4.8.96 warbird flyin, in military scheme;	
3A-190	E18S	N49E	Atlantic Aviation Corp	22.8.56/58
			D.A. Financial Service Co	5.6.58/61
		NIZOOM	Dayco Corp, Dayton OH	1.6.61/67
		N722K	Skyways Inc	26.6.67
			John Palmer/Metro Air Service, Detroit MI (cargo door installed 2.69)	26.9.67/71
			Ed Bowlin Associates Inc, Memphis TN	16.6.71/72
			Vero Aero Inc	7.4.72/74
		N300JH	Sedalia-Marshall-Boonville Stage Line, Des Moines IA	24.1.74/76
		N380JH	Precision Valley Aviation, Springfield VT	12.8.76/81
			(pilot cockpit door installed 3.77)	
			P B Leasing Inc, Naperville IL	24.3.81
		N14041 (=	leased: Viking Express Inc, Minneapolis MN	81
		N101VE	P B Leasing Inc, Naperville IL	13.7.81/84
			leased: Viking Express Inc, Chicago-Midway IL	81/84
			op: Titan Air crashed residential area on takeoff Chicago IL	86 29.9.86
3A-191	E18S	N4346D	Beech Aircraft Corp, Wichita KS	8.56

		sold to India, struck-off USCR	23.8.56
		(delivered to India via Prestwick 22.9.56)	
trigear	VT-DIS	The Tata Iron & Steel Co Ltd, Jamshedpur	9.56/77
		Goldensun Aviation, Bombay-Juhu Urvashi	77/85
		retired Bombay-Juhu, reported as derelict	82
		rep. crashed	.85
		burnt-out wreck, Bombay-Juhu	85/86
		CofA expired 10.6.86: struck-off Register	28.3.06

Goldensun Aviation inaugural service 20.12.77 from Bombay-Juhu, scheduled passenger airline services intially to Surat & Bhavnagar with VT-DIS & -DCW, later other ports; VT-DIS noted Ratnagiri, India 12.77 trigear "Goldensun Aviation";

VT-DIS noted Bombay-Juhu 9.82;

VT-DIS noted Bombay 1.84 trigear, retired but complete, engine & cockpit covers; VT-DIS noted Bombay-Juhu 9.85 burnt-out wreck dumped in Bombay Flying Club hangar; VT-DIS noted Juhu 3.86 " burnt out wreck";

BA-192	E18S	N25X (1	Butler Airplane Sales	14.9.56/57
		N125X	Butler Airplane Sales	16.1.57
			Ridge Associates	17.6.57/60
			W. B. Osborne	4.1.60/62
			(Airline Training one-piece windshield fitted 1.62)	
			H. L. Brown, Fort Worth TX	11.62/63
			R. B. Montcreif, Fort Worth TX	12.63/65
			The Texstar Corp, San Antonio TX	2.4.65/67
			Sherwood Van Lines	20.7.67/68
			B & B Construction Co, Youngstown OH	11.68/73
			Dade Leasing Inc/ Dade Air Charter, Miami FL	27.7.73/74
			Great Western Airlines, Tulsa OK	10.74/80
			Aircraft Leasing & Pilot Services Inc, Brownsville TX	1.80/87
		(N8PZ)	ntu: Aircraft Leasing & Pilot Services Inc TX	2.83
		N125X	William R. Sandlin, Evant TX	18.4.87/91
		XB-CRK	reg	c.91
			Luis J. P. Rangel	93
		N125X	Jim Hankins Air Service, Jackson MS	6.93/95
			sold to Canada: struck-off USCR	2.96
		C-FXKG	Gold Belt Air Transport, Pickle Lake ONT	1.3.96/00
			G. Andrew Swartman	01
			sold to USA, struck-off Canadian Register	31.8.01
		N125X	Denis G. Lison, Mason NH	7.9.01/21
			reg expired 30.4.21, struck-off USCR	31.7.21

N125X noted Dallas-Love TX 21.4.66; N125X noted McAllen TX 10.87;

BA-193	E18S	N37V	Transcontinental Gas Pipe Line Corp, Houston TX	63/66
			Pocoflite Inc, Lakville PA	69
			Cherry Ridge Flying Service, Honesdale PA	70/72
			Export Airmotive Inc, Miami FL	29.8.72
			sold to Colombia, struck-off USCR	3.10.72
		HK-1382	reg	c72
			Transportes Aereos Nacionales - TANA, Bogota	74/76
			Aerolineas Especiales de Colombia Ltda - AE Colombia,	
			Florencia	76/77
		HK-1382P	J. F. Pulido	82

TANA also quoted as Taxi Aereo Nacional;

HK-1382 noted Opa Locka FL 3.10.72;

HK-1382 photo at Bogota c76 "AE Colombia" tailwheel;

HK-1382 noted Tucson AZ 11.1.83;

HK-???? fuselage E18S "AE Colombia" titles on roof noted Bridgewater VA 11.8.99 in K&K Aircraft storage compound with other dismantled E18S: probably this acft;

BA-194	E18S	XB-XEO	built	9.56
	trigear		Manuel J. Galvan, Mexicali	93

BA-195	E18S	N70V	Nevada Plane Rentals, Las Vegas NV J. W. Duff/ Duffy's Aircraft Parts, Denver CO	63/70 71/08
			(stored dismantled in Duff's salvage yard, Denver 71/00) struck-off USCR	20.2.08
			rd next to Denver-Stapleton CO 31.7.71; ard, Denver 9.8.00 fuselage only seen;	
BA-196	E18S	N37N	Ohio Aviation Co, Dayton OH: CofA issued	10.9.56
			McDowell-Wellman Engineering Co, Cleveland OH	9.9.56/63
			Corey Custom Airtravel Inc, Detroit MI Midwestern Airlines, Detroit-City Airport MI	5.11.63/67 21.7.67/70
			Aircraft Painting Inc	11.70/71
		N333EH	Air Journeys Inc, Little Rock AR	6.10.71/72
		11000211	SMB Stage Line Inc, Des Moines IA	10.72/78
			(converted to cargo interior 2.73)	
			nosed over landing, Kirksville MO	25.3.75
			(Aerospace Products cargo door fitted 3.78)	
			Aero Craft Leasing Inc, Plymouth MI	20.4.78/79
			Hoffman Flying Service, Cheboygon MI	7.3.79/02
			(Aerospace Products wrap-around windshield	
			installed 3.88)	
			sold to Canada, struck-off USCR	18.6.04
		C-FBKD	Parachutisme Nouvel Air Inc, Farnham QUE	21.6.04/17
		N07470	sold to USA, struck-off Canadian reg	24.4.17
		N3717S	Thomas Setter, Burnsville MN	3.5.17/20
	USCR72 N333EH a 4.15am, s N333EH i JP78 quo	still N37N Air accident repoi swerved off ru noted Willow I tes N333EH a	gee OK 2.3.73 SMB at SMB maintenance base; Journeys Inc; rt 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl nway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh as Westwind III: incorrect!! rgan MI 10.96 Hoffman FS;	
	USCR72 N333EH & 4.15am, s N333EH I JP78 quo N333EH I C-FBKD I	still N37N Air accident report werved off runoted Willow Ites N333EH anoted Cheboynoted St Math	Journeys Inc; rt 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl nway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh as Westwind III: incorrect!!	eel; em .04;
BA-197	USCR72 N333EH & 4.15am, s N333EH I JP78 quo N333EH I C-FBKD I	still N37N Air accident report werved off runoted Willow Ites N333EH anoted Cheboynoted St Math	Journeys Inc; rt 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl nway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh as Westwind III: incorrect!! rgan MI 10.96 Hoffman FS; rias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the	eel; em .04;
BA-197	USCR72 N333EH & 4.15am, s N333EH I JP78 quo N333EH I C-FBKD I	still N37N Air accident repoismerved off runoted Willow Ites N333EH anoted Cheboynoted St Mathnoted Farnhar	Journeys Inc; Int 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl Inway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh It incorrect!! Ingan MI 10.96 Hoffman FS; It ias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the Indicate QUE 11.9.05 Parachutisme Nouvel Air, flying parachute  Pacific Aircraft Sales Ivar Akselsen	eel; em .04; drops, tailwheel; 18.10.56 22.1.57
BA-197	USCR72 N333EH & 4.15am, s N333EH I JP78 quo N333EH I C-FBKD I	still N37N Air accident repoismerved off runoted Willow Ites N333EH anoted Cheboynoted St Mathnoted Farnhar	Journeys Inc; Int 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl Inway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh It incorrect!! Ingan MI 10.96 Hoffman FS; It ias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the Indicate QUE 11.9.05 Parachutisme Nouvel Air, flying parachute  Pacific Aircraft Sales Ivar Akselsen KPF Electric Co, Stockton CA	eel; em .04; drops, tailwheel; 18.10.56 22.1.57 7.6.57/69
BA-197	USCR72 N333EH & 4.15am, s N333EH I JP78 quo N333EH I C-FBKD I	still N37N Air accident repoismerved off runoted Willow Ites N333EH anoted Cheboynoted St Mathnoted Farnhar	Journeys Inc; rt 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl nway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh as Westwind III: incorrect!! rgan MI 10.96 Hoffman FS; rias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the m QUE 11.9.05 Parachutisme Nouvel Air, flying parachute  Pacific Aircraft Sales Ivar Akselsen KPF Electric Co, Stockton CA Richard E. Keith, San Anselmo CA	eel; em .04; drops, tailwheel; 18.10.56 22.1.57 7.6.57/69 30.4.69/73
BA-197	USCR72 N333EH & 4.15am, s N333EH I JP78 quo N333EH I C-FBKD I	still N37N Air accident repoismerved off runoted Willow Ites N333EH anoted Cheboynoted St Mathnoted Farnhar	Journeys Inc; rt 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl nway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh as Westwind III: incorrect!! rgan MI 10.96 Hoffman FS; rias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the m QUE 11.9.05 Parachutisme Nouvel Air, flying parachute  Pacific Aircraft Sales Ivar Akselsen KPF Electric Co, Stockton CA Richard E. Keith, San Anselmo CA Air Courier Inc	eel; em .04; drops, tailwheel; 18.10.56 22.1.57 7.6.57/69
3A-197	USCR72 N333EH & 4.15am, s N333EH I JP78 quo N333EH I C-FBKD I	still N37N Air accident repoismerved off runoted Willow Ites N333EH anoted Cheboynoted St Mathnoted Farnhar	Journeys Inc; Int 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl Inway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh It incorrect!! Ingan MI 10.96 Hoffman FS; It ias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the Indicate QUE 11.9.05 Parachutisme Nouvel Air, flying parachute  Pacific Aircraft Sales Ivar Akselsen KPF Electric Co, Stockton CA Richard E. Keith, San Anselmo CA Air Courier Inc (cabin cargo door installed 3.74)	eel; em .04; drops, tailwheel; 18.10.56 22.1.57 7.6.57/69 30.4.69/73 12.73/76
BA-197	USCR72 N333EH & 4.15am, s N333EH I JP78 quo N333EH I C-FBKD I	still N37N Air accident repoismerved off runoted Willow Ites N333EH anoted Cheboynoted St Mathnoted Farnhar	Journeys Inc; Int 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl Inway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh It incorrect!! Ingan MI 10.96 Hoffman FS; It ias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the Indicate QUE 11.9.05 Parachutisme Nouvel Air, flying parachute  Pacific Aircraft Sales Ivar Akselsen KPF Electric Co, Stockton CA Richard E. Keith, San Anselmo CA Air Courier Inc (cabin cargo door installed 3.74) op: Eureka Aero	eel; em .04; drops, tailwheel; 18.10.56 22.1.57 7.6.57/69 30.4.69/73 12.73/76
BA-197	USCR72 N333EH & 4.15am, s N333EH I JP78 quo N333EH I C-FBKD I	still N37N Air accident repoismerved off runoted Willow Ites N333EH anoted Cheboynoted St Mathnoted Farnhar	Journeys Inc; rt 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl nway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh as Westwind III: incorrect!! rgan MI 10.96 Hoffman FS; rias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the m QUE 11.9.05 Parachutisme Nouvel Air, flying parachute  Pacific Aircraft Sales Ivar Akselsen KPF Electric Co, Stockton CA Richard E. Keith, San Anselmo CA Air Courier Inc (cabin cargo door installed 3.74) op: Eureka Aero Cargo Air Transport Inc	eel; em .04; drops, tailwheel; 18.10.56 22.1.57 7.6.57/69 30.4.69/73 12.73/76 74 25.2.76
BA-197	USCR72 N333EH & 4.15am, s N333EH I JP78 quo N333EH I C-FBKD I	still N37N Air accident repoismerved off runoted Willow Ites N333EH anoted Cheboynoted St Mathnoted Farnhar	Journeys Inc; Int 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl Inway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh It incorrect!! Ingan MI 10.96 Hoffman FS; It ias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the Indicate QUE 11.9.05 Parachutisme Nouvel Air, flying parachute  Pacific Aircraft Sales Ivar Akselsen KPF Electric Co, Stockton CA Richard E. Keith, San Anselmo CA Air Courier Inc (cabin cargo door installed 3.74) op: Eureka Aero Cargo Air Transport Inc Peninsular Air Delivery/ Adelphic Cargo Enterprises	eel; em .04; drops, tailwheel; 18.10.56 22.1.57 7.6.57/69 30.4.69/73 12.73/76 74 25.2.76 1.8.76/77
BA-197	USCR72 N333EH & 4.15am, s N333EH I JP78 quo N333EH I C-FBKD I	still N37N Air accident repoismerved off runoted Willow Ites N333EH anoted Cheboynoted St Mathnoted Farnhar	Journeys Inc; rt 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl nway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh as Westwind III: incorrect!! rgan MI 10.96 Hoffman FS; rias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the m QUE 11.9.05 Parachutisme Nouvel Air, flying parachute  Pacific Aircraft Sales Ivar Akselsen KPF Electric Co, Stockton CA Richard E. Keith, San Anselmo CA Air Courier Inc (cabin cargo door installed 3.74) op: Eureka Aero Cargo Air Transport Inc	eel; em .04; drops, tailwheel; 18.10.56 22.1.57 7.6.57/69 30.4.69/73 12.73/76 74 25.2.76
BA-197	USCR72 N333EH & 4.15am, s N333EH I JP78 quo N333EH I C-FBKD I	still N37N Air accident repoismerved off runoted Willow Ites N333EH anoted Cheboynoted St Mathnoted Farnhar	Journeys Inc; rt 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl nway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh as Westwind III: incorrect!! rgan MI 10.96 Hoffman FS; rias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the m QUE 11.9.05 Parachutisme Nouvel Air, flying parachute  Pacific Aircraft Sales Ivar Akselsen KPF Electric Co, Stockton CA Richard E. Keith, San Anselmo CA Air Courier Inc (cabin cargo door installed 3.74) op: Eureka Aero Cargo Air Transport Inc Peninsular Air Delivery/ Adelphic Cargo Enterprises Mat Mattson/ Rio Dusters, San Benito TX Dorlaine Romain	eel; em .04; drops, tailwheel; 18.10.56 22.1.57 7.6.57/69 30.4.69/73 12.73/76 74 25.2.76 1.8.76/77 10.77/79
3A-197	USCR72 N333EH & 4.15am, s N333EH I JP78 quo N333EH I C-FBKD I	still N37N Air accident repoismerved off runoted Willow Ites N333EH anoted Cheboynoted St Mathnoted Farnhar	Journeys Inc; rt 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl nway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh as Westwind III: incorrect!! rgan MI 10.96 Hoffman FS; rias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the m QUE 11.9.05 Parachutisme Nouvel Air, flying parachute  Pacific Aircraft Sales Ivar Akselsen KPF Electric Co, Stockton CA Richard E. Keith, San Anselmo CA Air Courier Inc (cabin cargo door installed 3.74) op: Eureka Aero Cargo Air Transport Inc Peninsular Air Delivery/ Adelphic Cargo Enterprises Mat Mattson/ Rio Dusters, San Benito TX	eel; em .04; drops, tailwheel; 18.10.56 22.1.57 7.6.57/69 30.4.69/73 12.73/76 74 25.2.76 1.8.76/77 10.77/79
BA-197	USCR72 N333EH a 4.15am, s N333EH a JP78 quo N333EH a C-FBKD a E18S	still N37N Air accident reports werved off runded Willow I tes N333EH and the content of the con	Journeys Inc; rt 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl nway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh as Westwind III: incorrect!! rgan MI 10.96 Hoffman FS; rias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the m QUE 11.9.05 Parachutisme Nouvel Air, flying parachute  Pacific Aircraft Sales Ivar Akselsen KPF Electric Co, Stockton CA Richard E. Keith, San Anselmo CA Air Courier Inc (cabin cargo door installed 3.74) op: Eureka Aero Cargo Air Transport Inc Peninsular Air Delivery/ Adelphic Cargo Enterprises Mat Mattson/ Rio Dusters, San Benito TX Dorlaine Romain (owner report 7.85: aircraft destroyed/scrapped) struck-off USCR	eel; em .04; drops, tailwheel;  18.10.56 22.1.57 7.6.57/69 30.4.69/73 12.73/76  74 25.2.76 1.8.76/77 10.77/79 9.2.79
BA-197	USCR72 N333EH a 4.15am, s N333EH a JP78 quo N333EH a C-FBKD a E18S	still N37N Air accident reports werved off runded Willow I tes N333EH and ted Cheboy noted St Mathematical Farnham N45L	Journeys Inc; rt 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl nway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh as Westwind III: incorrect!! rgan MI 10.96 Hoffman FS; rias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the m QUE 11.9.05 Parachutisme Nouvel Air, flying parachute  Pacific Aircraft Sales Ivar Akselsen KPF Electric Co, Stockton CA Richard E. Keith, San Anselmo CA Air Courier Inc (cabin cargo door installed 3.74) op: Eureka Aero Cargo Air Transport Inc Peninsular Air Delivery/ Adelphic Cargo Enterprises Mat Mattson/ Rio Dusters, San Benito TX Dorlaine Romain (owner report 7.85: aircraft destroyed/scrapped) struck-off USCR	eel; em .04; drops, tailwheel;  18.10.56 22.1.57 7.6.57/69 30.4.69/73 12.73/76  74 25.2.76 1.8.76/77 10.77/79 9.2.79
BA-197	USCR72 N333EH ( 4.15am, s N333EH ( JP78 quo N333EH ( C-FBKD ( C-FBKD (  E18S	still N37N Air accident reports werved off runded Willow I tes N333EH and ted Cheboynoted St Mathematical Farnham N45L  ed Novato CA ad Gnoss Field	Journeys Inc; rt 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl nway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh as Westwind III: incorrect!! rgan MI 10.96 Hoffman FS; rias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the rm QUE 11.9.05 Parachutisme Nouvel Air, flying parachute  Pacific Aircraft Sales Ivar Akselsen KPF Electric Co, Stockton CA Richard E. Keith, San Anselmo CA Air Courier Inc (cabin cargo door installed 3.74) op: Eureka Aero Cargo Air Transport Inc Peninsular Air Delivery/ Adelphic Cargo Enterprises Mat Mattson/ Rio Dusters, San Benito TX Dorlaine Romain (owner report 7.85: aircraft destroyed/scrapped) struck-off USCR	eel; em .04; drops, tailwheel;  18.10.56 22.1.57 7.6.57/69 30.4.69/73 12.73/76  74 25.2.76 1.8.76/77 10.77/79 9.2.79
	USCR72 N333EH a 4.15am, s N333EH a JP78 quo N333EH a C-FBKD a E18S  N45L note N45L note N45L note	still N37N Air accident reports werved off runded Willow I tes N333EH anoted St Mathemated Farnham N45L  and Novato CA and Gnoss Field Bakersfield	Journeys Inc; rt 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl nway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh as Westwind III: incorrect!! rgan MI 10.96 Hoffman FS; rias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the m QUE 11.9.05 Parachutisme Nouvel Air, flying parachute  Pacific Aircraft Sales Ivar Akselsen KPF Electric Co, Stockton CA Richard E. Keith, San Anselmo CA Air Courier Inc (cabin cargo door installed 3.74) op: Eureka Aero Cargo Air Transport Inc Peninsular Air Delivery/ Adelphic Cargo Enterprises Mat Mattson/ Rio Dusters, San Benito TX Dorlaine Romain (owner report 7.85: aircraft destroyed/scrapped) struck-off USCR  1.22.8.72; Id. San Francisco CA 10.9.72; Id. San Francisco CA 10.9.72; Id. San Francisco CA 10.6.74 "Eureka Aero", tailwheel;	eel; em .04; drops, tailwheel;  18.10.56 22.1.57 7.6.57/69 30.4.69/73 12.73/76  74 25.2.76 1.8.76/77 10.77/79 9.2.79  12.85
BA-197 BA-198	USCR72 N333EH ( 4.15am, s N333EH ( JP78 quo N333EH ( C-FBKD ( C-FBKD (  E18S	ed Novato CA ed Gnoss Fieled Bakersfield  N48N (2	Journeys Inc; Int 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl Inway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh It is westwind III: incorrect!! Irgan MI 10.96 Hoffman FS; It is QUE 20.3.05 Parachutisme Nouvel Air, delivered to the Image of QUE 11.9.05 Parachutisme Nouvel Air, flying parachute  Pacific Aircraft Sales Ivar Akselsen IVAT Akselsen IVAT Electric Co, Stockton CA Richard E. Keith, San Anselmo CA Air Courier Inc IVAT (cabin cargo door installed 3.74) IVAT OP: Eureka Aero IVAT Cargo Air Transport Inc IVAT Peninsular Air Delivery/ Adelphic Cargo Enterprises IVAT Mattson/ Rio Dusters, San Benito TX IVAT Dorlaine Romain IVAT (country IVAT IVAT (country IVAT IVAT IVAT IVAT IVAT IVAT IVAT IVAT	eel; em .04; drops, tailwheel;  18.10.56 22.1.57 7.6.57/69 30.4.69/73 12.73/76  74 25.2.76 1.8.76/77 10.77/79 9.2.79 12.85
	USCR72 N333EH a 4.15am, s N333EH a JP78 quo N333EH a C-FBKD a E18S  N45L note N45L note N45L note	still N37N Air accident reports werved off runded Willow I tes N333EH anoted St Mathemated Farnham N45L  and Novato CA and Gnoss Field Bakersfield	Journeys Inc; rt 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl nway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh as Westwind III: incorrect!! rgan MI 10.96 Hoffman FS; rias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the m QUE 11.9.05 Parachutisme Nouvel Air, flying parachute  Pacific Aircraft Sales Ivar Akselsen KPF Electric Co, Stockton CA Richard E. Keith, San Anselmo CA Air Courier Inc (cabin cargo door installed 3.74) op: Eureka Aero Cargo Air Transport Inc Peninsular Air Delivery/ Adelphic Cargo Enterprises Mat Mattson/ Rio Dusters, San Benito TX Dorlaine Romain (owner report 7.85: aircraft destroyed/scrapped) struck-off USCR  1.22.8.72; Id. San Francisco CA 10.9.72; Id. San Francisco CA 10.9.72; Id. San Francisco CA 10.6.74 "Eureka Aero", tailwheel;	eel; em .04; drops, tailwheel;  18.10.56 22.1.57 7.6.57/69 30.4.69/73 12.73/76  74 25.2.76 1.8.76/77 10.77/79 9.2.79  12.85
	USCR72 N333EH a 4.15am, s N333EH a JP78 quo N333EH a C-FBKD a E18S  N45L note N45L note N45L note	ed Novato CA ed Gnoss Fieled Bakersfield  N48N (2	Journeys Inc; Int 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl Inway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh It incorrect!! Ingan MI 10.96 Hoffman FS; It ias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the Indicate Aircraft Sales Ivar Akselsen Ivar Akselsen Ivar Akselsen Ivar Akselsen Ivar Courier Inc Ivar (cabin cargo door installed 3.74) Ivar Op: Eureka Aero Ivar Cargo Air Transport Inc Ivar Peninsular Air Delivery/ Adelphic Cargo Enterprises Ivar Mattson/ Rio Dusters, San Benito TX Ivar Dorlaine Romain Ivar Courier Inc Ivar Cargo Air Transport Inc Ivar Cargo Enterprises Ivar Ca	eel; em .04; drops, tailwheel;  18.10.56 22.1.57 7.6.57/69 30.4.69/73 12.73/76  74 25.2.76 1.8.76/77 10.77/79 9.2.79  12.85
	USCR72 N333EH a 4.15am, s N333EH a JP78 quo N333EH a C-FBKD a E18S  N45L note N45L note N45L note	ed Novato CA ed Gnoss Fieled Bakersfield  N48N (2 N75SA	Journeys Inc; rt 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl nway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh as Westwind III: incorrect!! rgan MI 10.96 Hoffman FS; ias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the m QUE 11.9.05 Parachutisme Nouvel Air, flying parachute  Pacific Aircraft Sales Ivar Akselsen KPF Electric Co, Stockton CA Richard E. Keith, San Anselmo CA Air Courier Inc (cabin cargo door installed 3.74) op: Eureka Aero Cargo Air Transport Inc Peninsular Air Delivery/ Adelphic Cargo Enterprises Mat Mattson/ Rio Dusters, San Benito TX Dorlaine Romain (owner report 7.85: aircraft destroyed/scrapped) struck-off USCR  22.8.72; d. San Francisco CA 10.9.72; d-Meadows Field CA 10.6.74 "Eureka Aero", tailwheel;  Spartan Mills, Spartanburg SC Spartan Mills, Spartanburg SC Transit Homes Inc Dee Howard Sales Inc, San Antonio TX David Rogers, Baytown TX	eel; em .04; drops, tailwheel;  18.10.56 22.1.57 7.6.57/69 30.4.69/73 12.73/76  74 25.2.76 1.8.76/77 10.77/79 9.2.79  12.85
	USCR72 N333EH a 4.15am, s N333EH a JP78 quo N333EH a C-FBKD a E18S  N45L note N45L note N45L note	ed Novato CA ed Gnoss Fieled Bakersfield  N48N (2 N75SA	Journeys Inc; rt 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirl nway into soft ground; Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwh as Westwind III: incorrect!! rgan MI 10.96 Hoffman FS; rias QUE 20.3.05 Parachutisme Nouvel Air, delivered to the m QUE 11.9.05 Parachutisme Nouvel Air, flying parachute  Pacific Aircraft Sales Ivar Akselsen KPF Electric Co, Stockton CA Richard E. Keith, San Anselmo CA Air Courier Inc (cabin cargo door installed 3.74) op: Eureka Aero Cargo Air Transport Inc Peninsular Air Delivery/ Adelphic Cargo Enterprises Mat Mattson/ Rio Dusters, San Benito TX Dorlaine Romain (owner report 7.85: aircraft destroyed/scrapped) struck-off USCR  1. 22.8.72; d. San Francisco CA 10.9.72; d-Meadows Field CA 10.6.74 "Eureka Aero", tailwheel;  Spartan Mills, Spartanburg SC Spartan Mills, Spartanburg SC Transit Homes Inc Dee Howard Sales Inc, San Antonio TX	eel; em .04; drops, tailwheel;  18.10.56 22.1.57 7.6.57/69 30.4.69/73 12.73/76  74 25.2.76 1.8.76/77 10.77/79 9.2.79  12.85

BA-199	E18S	N49A (2	Anderson Air Activities	.56
		N123H	International Harvester Co, Chicago IL	57/59
		CF-LPC	W. Norman Smith/	4 5 50/01
			International Harvester Co of Canada Ltd, Hamilton ONT	4.5.59/64
			(ferry permit 6.59 Dayton OH to Hamilton ONT)	22 42 04/22
			International Harvester Co of Canada Ltd, Hamilton ONT	
			Carl Millard Ltd, Toronto-Malton ONT	4.11.66/74
			Millardair Ltd, Toronto-Malton ONT	16.5.68
	•	N81GA	dam by fire in left engine on start-up, London ONT Gilley Airways Corp, Fulton NY	19.1.74 29.1.74
		NOTGA	(purchased damaged London ONT "as is/where is",	29.1.74
			repaired, ferried London-Syracuse NY 6.3.74 pilot	
			William C. Gilley, Pesident of Gilley Airways)	
			K & K Aircraft Inc, Bridgewater VA	22.10.74/11
			struck-off USCR	4.8.11
			(CofA not renewed after return to US .74)	
	CE LBC	noted Taxanta		
	CF-LPC	notea Foronto-	-Malton ONT 17.4.68 tailwheel, not titles, at Millardair hanga	ar;
BA-200	E18S	N59K	Crosby Forest Products Co, Picayune MS	63/64
			Wiles-Holloway Inc, Baton Rouge LA	66
			Combs Aircraft Inc, Denver CO	6.3.67
			sold to Philippines, struck-off USCR	2.6.67
		PI-C798	Lianga Bay Logging Co Inc, Manila	.67/70
		RP-C798	Lianga Bay Logging Co Inc, Manila	78
			Swiftair Inc, Zamboanga	79/84
			Commuter Air Manila, Manila Charles R. Miller/ CM Aero, Manila	90/98 03
			7.5.86 tailwheel, no titles, yellow, red & white;	
	RP-C798	noted Manila	7.92 tailwheel i/s,	
	RP-C798 RP-C798	3 noted Manila 3 noted Manila	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel;	
	RP-C798 RP-C798 RP-C798	B noted Manila B noted Manila B noted Manila	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service;	
	RP-C798 RP-C798 RP-C798	B noted Manila B noted Manila B noted Manila	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel;	
BA-201	RP-C798 RP-C798 RP-C798	B noted Manila B noted Manila B noted Manila	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS	26.9.56
BA-201	RP-C798 RP-C798 RP-C798 RP-C798	3 noted Manila 3 noted Manila 3 noted Manila 3 noted Manila N16U (1	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR	26.9.56 6.1.58
BA-201	RP-C798 RP-C798 RP-C798 RP-C798	3 noted Manila 3 noted Manila 3 noted Manila 3 noted Manila	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez	26.9.56 6.1.58 5.8.58/61
BA-201	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed	26.9.56 6.1.58 5.8.58/61 27.3.61/64
BA-201	RP-C798 RP-C798 RP-C798 RP-C798	3 noted Manila 3 noted Manila 3 noted Manila 3 noted Manila N16U (1	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed Gob Pcia de Santa Cruz	26.9.56 6.1.58 5.8.58/61 27.3.61/64 28.2.64
BA-201	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed	26.9.56 6.1.58 5.8.58/61 27.3.61/64
	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed Gob Pcia de Santa Cruz crashed on takeoff, Largo Argentino  Atlantic Aviation Corp: CofA issued	26.9.56 6.1.58 5.8.58/61 27.3.61/64 28.2.64 4.11.65
	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1 LV-IKA LQ-IGN	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed Gob Pcia de Santa Cruz crashed on takeoff, Largo Argentino  Atlantic Aviation Corp: CofA issued Time Inc, New York NY	26.9.56 6.1.58 5.8.58/61 27.3.61/64 28.2.64 4.11.65 17.9.56 21.9.56/65
	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1 LV-IKA LQ-IGN	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed Gob Pcia de Santa Cruz crashed on takeoff, Largo Argentino  Atlantic Aviation Corp: CofA issued Time Inc, New York NY landed with gear locked up, Boston-Logan MA	26.9.56 6.1.58 5.8.58/61 27.3.61/64 28.2.64 4.11.65
	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1 LV-IKA LQ-IGN	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed Gob Pcia de Santa Cruz crashed on takeoff, Largo Argentino  Atlantic Aviation Corp: CofA issued Time Inc, New York NY landed with gear locked up, Boston-Logan MA (repairs completed 9.64) Louis McCollum/ McCollum Aviation, Danville IL	26.9.56 6.1.58 5.8.58/61 27.3.61/64 28.2.64 4.11.65 17.9.56 21.9.56/65
	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1 LV-IKA LQ-IGN	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed Gob Pcia de Santa Cruz crashed on takeoff, Largo Argentino  Atlantic Aviation Corp: CofA issued Time Inc, New York NY landed with gear locked up, Boston-Logan MA (repairs completed 9.64) Louis McCollum/ McCollum Aviation, Danville IL Lindley Johnson/ John Gard Development Service,	26.9.56 6.1.58 5.8.58/61 27.3.61/64 28.2.64 4.11.65 17.9.56 21.9.56/65 5,8,64 1.10.65/66
	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1 LV-IKA LQ-IGN	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed Gob Pcia de Santa Cruz crashed on takeoff, Largo Argentino  Atlantic Aviation Corp: CofA issued Time Inc, New York NY landed with gear locked up, Boston-Logan MA (repairs completed 9.64) Louis McCollum/ McCollum Aviation, Danville IL Lindley Johnson/ John Gard Development Service, Richmond IN	26.9.56 6.1.58 5.8.58/61 27.3.61/64 28.2.64 4.11.65 17.9.56 21.9.56/65 5,8,64 1.10.65/66 20.8.66/72
	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1 LV-IKA LQ-IGN	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed Gob Pcia de Santa Cruz crashed on takeoff, Largo Argentino  Atlantic Aviation Corp: CofA issued Time Inc, New York NY landed with gear locked up, Boston-Logan MA (repairs completed 9.64) Louis McCollum/ McCollum Aviation, Danville IL Lindley Johnson/ John Gard Development Service, Richmond IN Herbert E. Guynn, St Petersburg FL	26.9.56 6.1.58 5.8.58/61 27.3.61/64 28.2.64 4.11.65 17.9.56 21.9.56/65 5,8,64 1.10.65/66 20.8.66/72 6.72
	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1 LV-IKA LQ-IGN	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed Gob Pcia de Santa Cruz crashed on takeoff, Largo Argentino  Atlantic Aviation Corp: CofA issued Time Inc, New York NY landed with gear locked up, Boston-Logan MA (repairs completed 9.64) Louis McCollum/ McCollum Aviation, Danville IL Lindley Johnson/ John Gard Development Service, Richmond IN Herbert E. Guynn, St Petersburg FL McMillen Co Inc	26.9.56 6.1.58 5.8.58/61 27.3.61/64 28.2.64 4.11.65 17.9.56 21.9.56/65 5,8,64 1.10.65/66 20.8.66/72 6.72 12.9.72/73
	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1 LV-IKA LQ-IGN	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed Gob Pcia de Santa Cruz crashed on takeoff, Largo Argentino  Atlantic Aviation Corp: CofA issued Time Inc, New York NY landed with gear locked up, Boston-Logan MA (repairs completed 9.64) Louis McCollum/ McCollum Aviation, Danville IL Lindley Johnson/ John Gard Development Service, Richmond IN Herbert E. Guynn, St Petersburg FL McMillen Co Inc Blackhawk Airways, Janesville WI	26.9.56 6.1.58 5.8.58/61 27.3.61/64 28.2.64 4.11.65 17.9.56 21.9.56/65 5,8,64 1.10.65/66 20.8.66/72 6.72
	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1 LV-IKA LQ-IGN	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed Gob Pcia de Santa Cruz crashed on takeoff, Largo Argentino  Atlantic Aviation Corp: CofA issued Time Inc, New York NY landed with gear locked up, Boston-Logan MA (repairs completed 9.64) Louis McCollum/ McCollum Aviation, Danville IL Lindley Johnson/ John Gard Development Service, Richmond IN Herbert E. Guynn, St Petersburg FL McMillen Co Inc Blackhawk Airways, Janesville WI (cargo floor & cockpit door installed 3.73;	26.9.56 6.1.58 5.8.58/61 27.3.61/64 28.2.64 4.11.65 17.9.56 21.9.56/65 5,8,64 1.10.65/66 20.8.66/72 6.72 12.9.72/73
	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1 LV-IKA LQ-IGN	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed Gob Pcia de Santa Cruz crashed on takeoff, Largo Argentino  Atlantic Aviation Corp: CofA issued Time Inc, New York NY Ianded with gear locked up, Boston-Logan MA (repairs completed 9.64) Louis McCollum/ McCollum Aviation, Danville IL Lindley Johnson/ John Gard Development Service, Richmond IN Herbert E. Guynn, St Petersburg FL McMillen Co Inc Blackhawk Airways, Janesville WI (cargo floor & cockpit door installed 3.73; cabin cargo door fitted 7.81;	26.9.56 6.1.58 5.8.58/61 27.3.61/64 28.2.64 4.11.65 17.9.56 21.9.56/65 5,8,64 1.10.65/66 20.8.66/72 6.72 12.9.72/73
	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1 LV-IKA LQ-IGN	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed Gob Pcia de Santa Cruz crashed on takeoff, Largo Argentino  Atlantic Aviation Corp: CofA issued Time Inc, New York NY landed with gear locked up, Boston-Logan MA (repairs completed 9.64) Louis McCollum/ McCollum Aviation, Danville IL Lindley Johnson/ John Gard Development Service, Richmond IN Herbert E. Guynn, St Petersburg FL McMillen Co Inc Blackhawk Airways, Janesville WI (cargo floor & cockpit door installed 3.73; cabin cargo door fitted 7.81; G18S type windshield installed 11.81)	26.9.56 6.1.58 5.8.58/61 27.3.61/64 28.2.64 4.11.65 17.9.56 21.9.56/65 5,8,64 1.10.65/66 20.8.66/72 6.72 12.9.72/73 7.2.73/84
	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1 LV-IKA LQ-IGN	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed Gob Pcia de Santa Cruz crashed on takeoff, Largo Argentino  Atlantic Aviation Corp: CofA issued Time Inc, New York NY Ianded with gear locked up, Boston-Logan MA (repairs completed 9.64) Louis McCollum/ McCollum Aviation, Danville IL Lindley Johnson/ John Gard Development Service, Richmond IN Herbert E. Guynn, St Petersburg FL McMillen Co Inc Blackhawk Airways, Janesville WI (cargo floor & cockpit door installed 3.73; cabin cargo door fitted 7.81; G18S type windshield installed 11.81) J. Richard Wixom/ Blackhawk Airways, Janesville WI	26.9.56 6.1.58 5.8.58/61 27.3.61/64 28.2.64 4.11.65 17.9.56 21.9.56/65 5,8,64 1.10.65/66 20.8.66/72 6.72 12.9.72/73 7.2.73/84
	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1 LV-IKA LQ-IGN	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed Gob Pcia de Santa Cruz crashed on takeoff, Largo Argentino  Atlantic Aviation Corp: CofA issued Time Inc, New York NY Ianded with gear locked up, Boston-Logan MA (repairs completed 9.64) Louis McCollum/ McCollum Aviation, Danville IL Lindley Johnson/ John Gard Development Service, Richmond IN Herbert E. Guynn, St Petersburg FL McMillen Co Inc Blackhawk Airways, Janesville WI (cargo floor & cockpit door installed 3.73; cabin cargo door fitted 7.81; G18S type windshield installed 11.81) J. Richard Wixom/ Blackhawk Airways, Janesville WI damaged landed short of runway, Oak Creek WI	26.9.56 6.1.58 5.8.58/61 27.3.61/64 28.2.64 4.11.65 17.9.56 21.9.56/65 5,8,64 1.10.65/66 20.8.66/72 6.72 12.9.72/73 7.2.73/84 7.7.84/94 25.1.90
	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1 LV-IKA LQ-IGN	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed Gob Pcia de Santa Cruz crashed on takeoff, Largo Argentino  Atlantic Aviation Corp: CofA issued Time Inc, New York NY Ianded with gear locked up, Boston-Logan MA (repairs completed 9.64) Louis McCollum/ McCollum Aviation, Danville IL Lindley Johnson/ John Gard Development Service, Richmond IN Herbert E. Guynn, St Petersburg FL McMillen Co Inc Blackhawk Airways, Janesville WI (cargo floor & cockpit door installed 3.73; cabin cargo door fitted 7.81; G18S type windshield installed 11.81) J. Richard Wixom/ Blackhawk Airways, Janesville WI damaged landed short of runway, Oak Creek WI Cascade Air Inc, Seattle WA	26.9.56 6.1.58 5.8.58/61 27.3.61/64 28.2.64 4.11.65 17.9.56 21.9.56/65 5,8,64 1.10.65/66 20.8.66/72 6.72 12.9.72/73 7.2.73/84 7.7.84/94 25.1.90 17.3.94/95
	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1 LV-IKA LQ-IGN	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed Gob Pcia de Santa Cruz crashed on takeoff, Largo Argentino  Atlantic Aviation Corp: CofA issued Time Inc, New York NY Ianded with gear locked up, Boston-Logan MA (repairs completed 9.64) Louis McCollum/ McCollum Aviation, Danville IL Lindley Johnson/ John Gard Development Service, Richmond IN Herbert E. Guynn, St Petersburg FL McMillen Co Inc Blackhawk Airways, Janesville WI (cargo floor & cockpit door installed 3.73; cabin cargo door fitted 7.81; G18S type windshield installed 11.81) J. Richard Wixom/ Blackhawk Airways, Janesville WI damaged landed short of runway, Oak Creek WI Cascade Air Inc, Seattle WA Comanche Air Inc, Winthrop WA	26.9.56 6.1.58 5.8.58/61 27.3.61/64 28.2.64 4.11.65 17.9.56 21.9.56/65 5,8,64 1.10.65/66 20.8.66/72 6.72 12.9.72/73 7.2.73/84 7.7.84/94 25.1.90 17.3.94/95 28.2.95/07
	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1 LV-IKA LQ-IGN	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed Gob Pcia de Santa Cruz crashed on takeoff, Largo Argentino  Atlantic Aviation Corp: CofA issued Time Inc, New York NY landed with gear locked up, Boston-Logan MA (repairs completed 9.64) Louis McCollum/ McCollum Aviation, Danville IL Lindley Johnson/ John Gard Development Service, Richmond IN Herbert E. Guynn, St Petersburg FL McMillen Co Inc Blackhawk Airways, Janesville WI (cargo floor & cockpit door installed 3.73; cabin cargo door fitted 7.81; G18S type windshield installed 11.81) J. Richard Wixom/ Blackhawk Airways, Janesville WI damaged landed short of runway, Oak Creek WI Cascade Air Inc, Seattle WA Comanche Air Inc, Winthrop WA op: Methow Aviation, Everett-Paine Field WA	26.9.56 6.1.58 5.8.58/61 27.3.61/64 28.2.64 4.11.65 17.9.56 21.9.56/65 5,8,64 1.10.65/66 20.8.66/72 6.72 12.9.72/73 7.2.73/84 7.7.84/94 25.1.90 17.3.94/95 28.2.95/07 00
BA-201	RP-C798 RP-C798 RP-C798 RP-C798	R noted Manila R noted Manila R noted Manila R noted Manila N16U (1 LV-IKA LQ-IGN	7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with red;  Beech Aircraft Corp, Wichita KS sold to Argentina, struck-off USCR M. J. Ordonez Serv S Aereos Santa Isabel, Cap Fed Gob Pcia de Santa Cruz crashed on takeoff, Largo Argentino  Atlantic Aviation Corp: CofA issued Time Inc, New York NY Ianded with gear locked up, Boston-Logan MA (repairs completed 9.64) Louis McCollum/ McCollum Aviation, Danville IL Lindley Johnson/ John Gard Development Service, Richmond IN Herbert E. Guynn, St Petersburg FL McMillen Co Inc Blackhawk Airways, Janesville WI (cargo floor & cockpit door installed 3.73; cabin cargo door fitted 7.81; G18S type windshield installed 11.81) J. Richard Wixom/ Blackhawk Airways, Janesville WI damaged landed short of runway, Oak Creek WI Cascade Air Inc, Seattle WA Comanche Air Inc, Winthrop WA	26.9.56 6.1.58 5.8.58/61 27.3.61/64 28.2.64 4.11.65 17.9.56 21.9.56/65 5,8,64 1.10.65/66 20.8.66/72 6.72 12.9.72/73 7.2.73/84 7.7.84/94 25.1.90 17.3.94/95 28.2.95/07

struck-off USCR 11.4.07

N48K noted Chicago-O'Hare 20.3.73 Blackhawk; N48K noted Chicago-O'Hare 13.9.76; accident report 25.1.90 Blackhawk Airways; N48K noted Seattle-Paine Field WA 8.94; BA-202 noted Burlington WA 7.04 less engines & other components:

	BA-202 r	noted Burlingto	on WA 7.04 less engines & other components;	
BA-203	E18S	DT IZVN	FA Brasileira as U45 FAB 2876	,56
	U45	PT-KXN	Miguel F.P.Chaves, Sao Paulo	6.78/83
	FAB 287	6 noted Rio-Sa	antos Dumont 20.10.72;	
BA-204	E18S		FA Brasileira as U45 FAB 2877	.56
	U45	PT-KVQ	Jose A. Simioni Escola de Aviacan Elite Ltda, Golana	6.77 83
DA 205	E18S		FA Brasileira as U45 FAB 2878	.56
BA-205	U45		crashed in FAB service, Campo Grande AB (rebuilt)	5.12.67
	0.0	PT-KXO	crashed Bridgetown, Barbados	5.12.77
			derelict, Bridgetown-Grantley Adams	79/85
	FAB 287	8 noted Rio-Sa	antos Dumont 30.7.67, 8.9.67;	
	PT-KXO	noted Barbade	os 5.79 derelict, 30.12.83 derelict, dismantled;	
BA-206	E18S	N59E	Beech Aircraft Corp, Wichita KS	1.10.56/57
			(retained for development work, CofA issued 14.3.57)	
			Gerald C. Francis/ Francis Aviation, Lansing MI	11.5.57/73
			Executive Air Sales	11.73/76
			Mohican Air Service, Cleveland OH	9.6.76/91
			Skytrain Inc, Wakeman OH	4.2.94/99
			Jack L. Harmon, Jenks OK	18.5.01/06
			Daniel S. Jones, Panama City Beach FL	13.4.10/20
	another µ N59E no	olate Aerospad ted Middletow	n OH 20.7.02: frieght interior, all metallic, stored: plate BA-2 ce Products spar kit 1509 s/n 169 22.4.75; n OH 1.8.05 all silver in storage; n OH 17.6.06 all silver in storage;	
BA-207	E18S	N844KN	built	
		-	Hope Natural Gas Co, Clarksburg WV	28.5.63/65
			crashed destroyed on takeoff, struck terrain in snow, Bridgeport WV	10.3.65
			uotes reg "N844K": struck rising terrain 1.5 miles beyond rui	
	destroye	u, 4n,		
BA-208	E18S	N46L (1	built	.56
		PP-ECT	Govt. Est de Minas Gerais	65
BA-209	E18S	N34747	Anderson Air Activities: CofA issued	23.10.56
	-9700		Ladish Malting Co, Milwaukee WI	1.12.56/64
		N474L	Ladish Malting Co, Milwaukee WI	10.64/71
			(G18S two-piece windshield installed 8.66)	
		N474E	Ladish Malting Co, Milwaukee WI	21.6.71
			G. C. Landry/ Beechcraft Sales & Charter, East Troy WI	18.6.71
			The Polk Corp, Indianapolis IN minor damage when struck Beech A36 N3116W while	29.6.71/75
			taxying, Rockford IL	1.5.75
				3.6.75
			Aircraft Maintenance Specialists Inc	3.0.73
			(cargo floor & cabin door installed 10.75)	3 11 7E/00
			American Lease Plans Inc, Charlotte NC	3.11.75/80

lsd: Thomas J. Wood & Ralph Quinlan

4.11.75/80

minor damage landed gear locked-up, Asheville NC 4.3.76 op: General Aviation Inc, Greenville TN 79/80 Ralph Quinlan/ Mountain Air Cargo, Denver NC 4.9.80/81 Equipment Leasing Corp, Greenville SC 11.2.81/85 Isd: Mountain Air Cargo, Denver NC 11.2.81/83 Mountain Air Cargo, Denver NC: sale documentation not completed

N474E accident report 1.5.75: The Polk Corp, taxying for flight to Milwaukee WI, 4 on Beech unhurt; N474E accident report 4.3.76: op "Little Mountain Air Cargo", gear mechanical failure to extend, flight from Tricity TN, 7.45pm, pilot unhurt; N474E noted Miami FL 28.12.81, arrived, Mountain Air Cargo;

BA-210	E18S	N52E	J. R. Gray Co, Dallas TX: CofA issued	17.10.56/58
			Hunsaker Trucking Contractor, Carrollton TX	2.2.58/69
			James A. Pope	9.6.69/70
			ran off runway on takeoff, struck ditches, Jasper TX	2.1.70
			Universal Box & Packaging, Shreveport LA	7.5.70/71
			Dan Futrell	11.71/72
			Rodney F. McLean	15.6.72/74
			William G. Thomas	4.1.74/75
			(cargo kit installed 2.74)	
			Robert Robinson/ National Aviation	22.8.75
			Pinal County Sheriff, Tucson AZ: seized due	
			use in transportation of narcotic drugs	26.7.76/78
			Wilfred & Mary I. Dailey	15.7.78/79
			Aerospace Products Inc, North Hollywood CA	30.3.79
			Phoenix Charter Airways, St Croix USVI	7.11.79/82
			Francis J. McCarthy, St Thomas USVI	20.8.82/86
			op: Four Star Air Cargo, St Thomas USVI	84/85
			Jank Inc. Kotzebue AK	28.4.86/90
			Wade O. Kane, North Pole AK	10.90/96
			op: Alaska Airships	10.30/30
			Nicholas E. Mesmer, Baraboo WI	- 8.1.96/14
			struck-off USCR	27.10.14
			Struck-on OOCK	21.10.14

N52E noted Dallas-Love TX 21.4.66;

N52E arrived Miami FL 5.5.79 operator Donaldson, no titles;

N52E noted St Croix USVI 11.10.79 "Phoenix Charter AW", N52E noted San Juan PR 17.11.79 "Phoenix Charter AW"

N52E noted San Juan PR 5.11.80 "Phoenix Charter AW"

N52E noted Fairbanks AK 26.5.90 "Alaska Air Ships", tailwheel;

N52E at Oshkosh 1.8.03 "Alaska Airships" titles, plate BA-210 built 10.56;

N52E at Oshkosh 31.7.04;

N52E noted Oshkosh 7.05 open storage "Alaska Airships";

N52E at Oshkosh 7.06 "Alaska Airships": Oshkosh 7.08:

BA-211	E18S	N54E	General Electric Co, White Plains NY	63/66
	ATE		Northern Airways Inc, Burlington VT	68/69
	Westwind I	1	(rebuilt by American Turbine Engine Co, Long Beach CA	
	trigear		as the only ATE Westwind II, 2.08m fuselage stretch of	
	· ·		ATE Westwind I trigear, completed 23.6.68)	
		N14NA	Northern Airways Inc, Burlington VT	
		N51AN (1	renamed: Air North Inc, South Burlington VT	.69/70
		N51CS	Air North Inc, South Burlington VT	21.5.70/71
			Chicago & Southern Airlines, Chicago IL: leased	27.11.70/71
			crashed destroyed landing, Peoria IL (16 k)	21.10.71

Westwind II conversion: see Beech 18 by Robert Parmerter p.334; Parmeter: "The one and only ATECO Westwind II, completed 23.6.68 for Northern Airways under ATE STC SA1721WE. Modifications included a 9 feet fuselage extension, P&W PT6A-27 turboprop engines, Volpar tricycle landing gear and spar reinforcement strap.,14 pax seats & crew 2, maximum gross weight 11,500lb. The engineering for the fuselage extension was under licence from Volpar (developed for their Volpar Turboliner).

N54E noted Long Beach CA 18.9.67 trigear turbine;

N51CS noted Chiago-Meigs Field 6.71 "Chicago & Southern Airlines" titles, stretched trigear turbines;

crash report 21.10.71 Peoria IL: type ATECO Westwind II, Chicago & Southern Airlines Inc, landing in rain & low cloud, descended below MDA on approach, struck wires, 14 pax, 2 crew all killed;

BA-212	E18S	N39M	built	.56
		N3400 (2	N3400 (2 Rudd Melikian Inc, Hatboro PA	63
		•	Carl Johnstone, Longview TX	64
			Plane Co, Houston TX	66
			Black Hills Glass & Mirror Co, Rapid City SD	67/68
			forced landing, Rapid City SD	11.9.67
			crashed destroyed landing, Rapid City SD	17.3.68
BA-213	E18S	N64A	Anderson Air Activities: CofA issued	17.10.56
			(CofA issued 17.10.56)	
			Allis-Chalmers Manufacturing Co, West Allis WI Gordon K. Newstrom/ Mesaba Aviation,	1.12.56/62
			Grand Rapids MN	21.7.62/72
			C. Merrill Blumer/ B. J. Aero Freight, Oskaloosa IA (cargo cabin door & floor installed 1.73)	28.12.72/75
			Vannoy Airfreight, Oskaloosa IA	4.75
			Malcolm C. Thurmond, Georgetown TX	4.9.75/79
			Starship Leasing Service, Austin TX	79
			Corley M. Tedder/CMT Leasing, Texarkana TX	13.3.79/81
			Isd: ABC Airlines	79/80
			Clark Thurmond, Georgetown TX: skydiving ops	79/80
			tailwheel collapsed landing, Dallas-Ft Worth TX	2.10.80
			James L. Hudson, Mesquite TX	24.4.81/83
			lsd: ABC Airlines, Dallas TX	1.12.81/82
			Robert A. Nelson, Sulphur Bluff TX	24.12.83/85
			James L. Hudson, Dallas-Mesquite TX	18.3.85/93
			Howard Y. Sigler	4.1.93
			sale rep., Dallas TX: USCR	98/05
			(derelict in car wreckers yard, Mesquite TX 98/03,	
			advertised for sale complete in hangar by 3.04 TT 10,4	403)
			Velvet A. Carroll, Heath TX	19.4.05/13
			struck-off USCR	29.4.13

N64A noted Chicago-O'Hare 21.7.73 BJ Aero Freight:

Clark Thurmond recalls N64A was purchased from BJ Aero Freight in 75, he used it for skydiving at Georgetown TX for 4 years with "BJ Aero Freight" titles still on it, then sold it to Corley Tedder. Starship Leasing was an attempt to set up a freight company to use it while he retained ownership,

but never started operations (he understood that BJ Aero Freight shut down when another Beech 18 crashed c74 killing a company partner)

N64A noted Oklahoma City OK 5.9.79 all white, no titles;

N64A noted Dallas-Ft Worth TX 1.12.79 ABC Airlines;

Letter to Beech 18 SIte from Clark Thurmond: N64A was his first 18, photo of N64A skydiving over Georgetown TX in 1979 "ABC Airlines" titles, sold it for freight in 1980;

N64A accident report 2.10.80: ABC airlines, cargo flight from Abeline TX, 7.50pm;

N64A noted in car breakers yard, Dallas-Mesquite TX 10.4.98 with 5 other Beech 18s;

N64A noted unchanged 6.8.98 Lawson Road near Scyene Road, Mesquite;

N64A noted Mesquite 9.5.03 in scrapyard near airport with other Beech 18 hulks;

BA-214	E18S U45	PT-KXP	Brasileira as U45 FAB 2879 Jose Angelo Simioni, L Paulista	.56 13.7.78/83
BA-215	E18S -9700	N67V HK-1418P	built Wichita KS J. M. McDonald, Hastings NE W. K. Enterprises Inc, Memphis TN Hernando Sequera H. Segura	10.56 63/70 72 30.12.71/72 82

BA-216	E18S	ZS-CFC	Stewarts & Lloyds of South Africa Ltd, Vereeniging	1.57
			Letaba Airways, Johannesburg-Jan Smuts	.75/77
			Transport & Equipment Engineering Co, Baragwanath	80/81
			Wonderair Pty Ltd, Wonderboom	85
			minor damage, wheels-up landing, Lanseria	22.1.85
			(ferried to Wonderboom, repaired .85)	<b>5.7.05</b>
			Wonderair Pty Ltd, Wonderboom	5.7.85
			Johan S. Schoeman, Tzaneen	26.2.93/10
	ZS-CFC i ZS-CFC i	noted Johanne noted Johanne	y, Rhodesia 18.10.59 Stewarts & Lloyds; esburg-Jan Smuts 18.11.67; esburg-Rand 27.1.68, boom 10.75 "Letaba Lugdiens" titles, tailwheel;	
BA-217	E18S	N67A	Atlantic Aviation Services: CofA issued	31.10.56/60
-, . <b>-</b>	-9700		National Financing Inc	11.5.60/61
			Sullivan Trail Coal Inc, Pittston PA	11.61/77
			American Lease Plans Inc, Charlotte NC	19.7.77/81
			lsd: Ralph Quinlan/ Little Mountain Airport Inc/	
			Mountain Air Cargo, Denver NC	19.7.77/85
			(cargo cabin door & floor installed 8.77)	
			op: General Aviation Inc, Greenville TN	80
			Equipment Leasing Corp, Greenville SC	10.2.81/85
			Mountain Air Cargo, Denver NC: leased	.81/85
			Coastal States Aviation, Denver NC	1.2.85/86
			forced landing in field, came to rest on road,	
			Fisherville VA	25.4.85
			Jim Hankins Air Service, Jackson MS	12.86/87
			Triple C Aviation, Louisville MS Eglund Air Inc, St Elmo AL:	12.87
			ECHAND AN INC. OLEMNO AL	
	accident i	report 25.4.85	sale documentation not completed  26.5.81 arrived, Mountain Air Cargo; : op Mountain Air Cargo: forced landing in field due fuel ex	c90 cpiry,
	accident i came to r	report 25.4.85 est on VA Ro	sale documentation not completed 26.5.81 arrived, Mountain Air Cargo;	
3A-218	accident i came to r	report 25.4.85 est on VA Ro	sale documentation not completed 26.5.81 arrived, Mountain Air Cargo; : op Mountain Air Cargo: forced landing in field due fuel exute 608: no indication of extent of damage; road in Alabama in 2007;  J. P. Stevens & Co, New York NY	spiry, 57/64
3A-218	accident i came to r rep. stand	report 25.4.85 lest on VA Rou ding next to a	sale documentation not completed  26.5.81 arrived, Mountain Air Cargo; : op Mountain Air Cargo: forced landing in field due fuel exute 608: no indication of extent of damage; road in Alabama in 2007;  J. P. Stevens & Co, New York NY Topeka Aircraft Sales, Topeka KS	57/64 66
BA-218	accident i came to r rep. stand	report 25.4.85 est on VA Roo ding next to a N73SF	sale documentation not completed  26.5.81 arrived, Mountain Air Cargo; : op Mountain Air Cargo: forced landing in field due fuel exute 608: no indication of extent of damage; road in Alabama in 2007;  J. P. Stevens & Co, New York NY Topeka Aircraft Sales, Topeka KS Kings Skyline Inc, Olathe KS	57/64 66 69
3A-218	accident i came to r rep. stand	report 25.4.85 lest on VA Rou ding next to a	sale documentation not completed 26.5.81 arrived, Mountain Air Cargo; : op Mountain Air Cargo: forced landing in field due fuel exute 608: no indication of extent of damage; road in Alabama in 2007;  J. P. Stevens & Co, New York NY Topeka Aircraft Sales, Topeka KS Kings Skyline Inc, Olathe KS Jean M. Brannon, Greenville SC	57/64 66 69 70
BA-218	accident i came to r rep. stand	report 25.4.85 est on VA Roo ding next to a N73SF	sale documentation not completed  26.5.81 arrived, Mountain Air Cargo; : op Mountain Air Cargo: forced landing in field due fuel exute 608: no indication of extent of damage; road in Alabama in 2007;  J. P. Stevens & Co, New York NY Topeka Aircraft Sales, Topeka KS Kings Skyline Inc, Olathe KS	57/64 66 69
BA-218	eccident in came to rep. stand E18S  photo shot tailwheel, N73JB not N73JB according to the control of the cont	report 25.4.85 rest on VA Rod ding next to a  N73SF  N73JB  ows N72SF, N all owned J.Foted Muskogeo sted Dallas-Loc cident report	sale documentation not completed 26.5.81 arrived, Mountain Air Cargo; cop Mountain Air Cargo: forced landing in field due fuel exute 608: no indication of extent of damage; road in Alabama in 2007;  J. P. Stevens & Co, New York NY Topeka Aircraft Sales, Topeka KS Kings Skyline Inc, Olathe KS Jean M. Brannon, Greenville SC SMB Stage Line, Des Moines IA	57/64 66 69 70 17.12.71/73 31.5.73
	eccident in came to rep. stand E18S  photo shot tailwheel, N73JB not N73JB according to the control of the cont	report 25.4.85 rest on VA Rod ding next to a  N73SF  N73JB  ows N72SF, N all owned J.Foted Muskogeo sted Dallas-Loc cident report	Sale documentation not completed 26.5.81 arrived, Mountain Air Cargo; 3: op Mountain Air Cargo: forced landing in field due fuel extete 608: no indication of extent of damage; 3: road in Alabama in 2007;  J. P. Stevens & Co, New York NY Topeka Aircraft Sales, Topeka KS Kings Skyline Inc, Olathe KS Jean M. Brannon, Greenville SC SMB Stage Line, Des Moines IA crashed destroyed landing, Tyler TX 3: SF, N74SF, N75SF & N176SF in row at Wallace NC 4.6 3: Stevens & Co; 6: OK 2.3.73 SMB Stage Line, at SMB maintenance base, 3: ve 19.5.73 SMB; 3: 1.5.73: SMB Stage Line, struck trees on final approach 2: view TX, pilot fatigue a factor, 1k;  Roscoe Turner Aeronautical Corp: CofA issued	57/64 66 69 70 17.12.71/73 31.5.73 61, all
	eccident in came to rep. stand E18S  photo shot tailwheel, N73JB not N73JB act flight Dalle	report 25.4.85 rest on VA Rod ding next to a selfing next to a sel	Sale documentation not completed 26.5.81 arrived, Mountain Air Cargo; 3: op Mountain Air Cargo: forced landing in field due fuel extite 608: no indication of extent of damage; 3: road in Alabama in 2007;  J. P. Stevens & Co, New York NY Topeka Aircraft Sales, Topeka KS Kings Skyline Inc, Olathe KS Jean M. Brannon, Greenville SC SMB Stage Line, Des Moines IA crashed destroyed landing, Tyler TX 3:73SF, N74SF, N75SF & N176SF in row at Wallace NC 4.6 3: Stevens & Co; 6: OK 2.3.73 SMB Stage Line, at SMB maintenance base, 3: ve 19.5.73 SMB; 3: 1.5.73: SMB Stage Line, struck trees on final approach 2: view TX, pilot fatigue a factor, 1k;  Roscoe Turner Aeronautical Corp: CofA issued Inland Container Corp	57/64 66 69 70 17.12.71/73 31.5.73 61, all am,
	eccident in came to rep. stand E18S  photo shot tailwheel, N73JB not N73JB act flight Dalle	report 25.4.85 rest on VA Rod ding next to a N73SF  N73JB  ows N72SF, N all owned J.F oted Muskoge oted Dallas-Lo ccident report as-Tyler-Long	Sale documentation not completed 26.5.81 arrived, Mountain Air Cargo; 3: op Mountain Air Cargo: forced landing in field due fuel extite 608: no indication of extent of damage; 3: road in Alabama in 2007;  J. P. Stevens & Co, New York NY Topeka Aircraft Sales, Topeka KS Kings Skyline Inc, Olathe KS Jean M. Brannon, Greenville SC SMB Stage Line, Des Moines IA crashed destroyed landing, Tyler TX 3:73SF, N74SF, N75SF & N176SF in row at Wallace NC 4.6 3: Stevens & Co; 6: OK 2.3.73 SMB Stage Line, at SMB maintenance base, 3: ve 19.5.73 SMB; 3: 1.5.73: SMB Stage Line, struck trees on final approach 2: 3: View TX, pilot fatigue a factor, 1k;  Roscoe Turner Aeronautical Corp: CofA issued Inland Container Corp Roscoe Turner Aeronautical Corp	57/64 66 69 70 17.12.71/73 31.5.73 61, all am, 7.11.56 9.11.56/62 29.10.62
	eccident in came to rep. stand E18S  photo shot tailwheel, N73JB not N73JB act flight Dalle	report 25.4.85 rest on VA Rod ding next to a selfing next to a sel	26.5.81 arrived, Mountain Air Cargo; cop Mountain Air Cargo: forced landing in field due fuel extite 608: no indication of extent of damage; road in Alabama in 2007;  J. P. Stevens & Co, New York NY Topeka Aircraft Sales, Topeka KS Kings Skyline Inc, Olathe KS Jean M. Brannon, Greenville SC SMB Stage Line, Des Moines IA crashed destroyed landing, Tyler TX  73SF, N74SF, N75SF & N176SF in row at Wallace NC 4.6 C. Stevens & Co; e OK 2.3.73 SMB Stage Line, at SMB maintenance base, ve 19.5.73 SMB; 31.5.73: SMB Stage Line, struck trees on final approach 2: view TX, pilot fatigue a factor, 1k;  Roscoe Turner Aeronautical Corp: CofA issued Inland Container Corp Roscoe Turner Aeronautical Corp Basler Flight Service, Oshkosh WI	57/64 66 69 70 17.12.71/73 31.5.73 61, all am,
	eccident in came to rep. stand E18S  photo shot tailwheel, N73JB not N73JB act flight Dalle	report 25.4.85 rest on VA Rod ding next to a selfing next to a sel	Sale documentation not completed  26.5.81 arrived, Mountain Air Cargo; cop Mountain Air Cargo: forced landing in field due fuel extite 608: no indication of extent of damage; road in Alabama in 2007;  J. P. Stevens & Co, New York NY Topeka Aircraft Sales, Topeka KS Kings Skyline Inc, Olathe KS Jean M. Brannon, Greenville SC SMB Stage Line, Des Moines IA crashed destroyed landing, Tyler TX  273SF, N74SF, N75SF & N176SF in row at Wallace NC 4.6 C. Stevens & Co; e OK 2.3.73 SMB Stage Line, at SMB maintenance base, ve 19.5.73 SMB; 31.5.73: SMB Stage Line, struck trees on final approach 2: view TX, pilot fatigue a factor, 1k;  Roscoe Turner Aeronautical Corp: CofA issued Inland Container Corp Roscoe Turner Aeronautical Corp Basler Flight Service, Oshkosh WI (cabin cargo tie-downs installed 12.62)	57/64 66 69 70 17.12.71/73 31.5.73 61, all am, 7.11.56 9.11.56/62 29.10.62 2.11.62/64
	eccident in came to rep. stand E18S  photo shot tailwheel, N73JB not N73JB act flight Dalle	report 25.4.85 rest on VA Rod ding next to a selfing next to a sel	26.5.81 arrived, Mountain Air Cargo; cop Mountain Air Cargo: forced landing in field due fuel extite 608: no indication of extent of damage; road in Alabama in 2007;  J. P. Stevens & Co, New York NY Topeka Aircraft Sales, Topeka KS Kings Skyline Inc, Olathe KS Jean M. Brannon, Greenville SC SMB Stage Line, Des Moines IA crashed destroyed landing, Tyler TX  73SF, N74SF, N75SF & N176SF in row at Wallace NC 4.6 C. Stevens & Co; e OK 2.3.73 SMB Stage Line, at SMB maintenance base, ve 19.5.73 SMB; 31.5.73: SMB Stage Line, struck trees on final approach 2: view TX, pilot fatigue a factor, 1k;  Roscoe Turner Aeronautical Corp: CofA issued Inland Container Corp Roscoe Turner Aeronautical Corp Basler Flight Service, Oshkosh WI (cabin cargo tie-downs installed 12.62) Johnston Container Corp, Indianapolis IN	57/64 66 69 70 17.12.71/73 31.5.73 61, all am, 7.11.56 9.11.56/62 29.10.62 2.11.62/64 22.1.64/68
	eccident in came to rep. stand E18S  photo shot tailwheel, N73JB not N73JB act flight Dalle	report 25.4.85 rest on VA Rod ding next to a selfing next to a sel	26.5.81 arrived, Mountain Air Cargo; cop Mountain Air Cargo: forced landing in field due fuel extete 608: no indication of extent of damage; road in Alabama in 2007;  J. P. Stevens & Co, New York NY Topeka Aircraft Sales, Topeka KS Kings Skyline Inc, Olathe KS Jean M. Brannon, Greenville SC SMB Stage Line, Des Moines IA crashed destroyed landing, Tyler TX  73SF, N74SF, N75SF & N176SF in row at Wallace NC 4.6 2. Stevens & Co; e OK 2.3.73 SMB Stage Line, at SMB maintenance base, ve 19.5.73 SMB; 31.5.73: SMB Stage Line, struck trees on final approach 2. view TX, pilot fatigue a factor, 1k;  Roscoe Turner Aeronautical Corp: CofA issued Inland Container Corp Roscoe Turner Aeronautical Corp Basler Flight Service, Oshkosh WI (cabin cargo tie-downs installed 12.62) Johnston Container Corp, Indianapolis IN Arkansas Aviation Sales, Little Rock AR	57/64 66 69 70 17.12.71/73 31.5.73 61, all am, 7.11.56 9.11.56/62 29.10.62 2.11.62/64 22.1.64/68 10.2.69/70
	eccident in came to rep. stand E18S  photo shot tailwheel, N73JB not N73JB act flight Dalle	report 25.4.85 rest on VA Rod ding next to a selfing next to a sel	26.5.81 arrived, Mountain Air Cargo; cop Mountain Air Cargo: forced landing in field due fuel extite 608: no indication of extent of damage; road in Alabama in 2007;  J. P. Stevens & Co, New York NY Topeka Aircraft Sales, Topeka KS Kings Skyline Inc, Olathe KS Jean M. Brannon, Greenville SC SMB Stage Line, Des Moines IA crashed destroyed landing, Tyler TX  73SF, N74SF, N75SF & N176SF in row at Wallace NC 4.6 2. Stevens & Co; e OK 2.3.73 SMB Stage Line, at SMB maintenance base, ve 19.5.73 SMB; 31.5.73: SMB Stage Line, struck trees on final approach 2. view TX, pilot fatigue a factor, 1k;  Roscoe Turner Aeronautical Corp: CofA issued Inland Container Corp Roscoe Turner Aeronautical Corp Basler Flight Service, Oshkosh WI (cabin cargo tie-downs installed 12.62) Johnston Container Corp, Indianapolis IN Arkansas Aviation Sales, Little Rock AR ground-loop landing, gear collapsed, Big Spring TX	57/64 66 69 70 17.12.71/73 31.5.73 61, all am, 7.11.56 9.11.56/62 29.10.62 2.11.62/64 22.1.64/68 10.2.69/70 24.4.69
	eccident in came to rep. stand E18S  photo shot tailwheel, N73JB not N73JB act flight Dalle	report 25.4.85 rest on VA Rod ding next to a selfing next to a sel	26.5.81 arrived, Mountain Air Cargo; cop Mountain Air Cargo: forced landing in field due fuel extete 608: no indication of extent of damage; road in Alabama in 2007;  J. P. Stevens & Co, New York NY Topeka Aircraft Sales, Topeka KS Kings Skyline Inc, Olathe KS Jean M. Brannon, Greenville SC SMB Stage Line, Des Moines IA crashed destroyed landing, Tyler TX  73SF, N74SF, N75SF & N176SF in row at Wallace NC 4.6 2. Stevens & Co; e OK 2.3.73 SMB Stage Line, at SMB maintenance base, ve 19.5.73 SMB; 31.5.73: SMB Stage Line, struck trees on final approach 2. view TX, pilot fatigue a factor, 1k;  Roscoe Turner Aeronautical Corp: CofA issued Inland Container Corp Roscoe Turner Aeronautical Corp Basler Flight Service, Oshkosh WI (cabin cargo tie-downs installed 12.62) Johnston Container Corp, Indianapolis IN Arkansas Aviation Sales, Little Rock AR ground-loop landing, gear collapsed, Big Spring TX Golden Eagle Aviation	57/64 66 69 70 17.12.71/73 31.5.73 61, all am, 7.11.56 9.11.56/62 29.10.62 2.11.62/64 22.1.64/68 10.2.69/70 24.4.69 16.9.70
	eccident in came to rep. stand E18S  photo shot tailwheel, N73JB not N73JB act flight Dalle	report 25.4.85 rest on VA Rod ding next to a selfing next to a sel	26.5.81 arrived, Mountain Air Cargo; cop Mountain Air Cargo: forced landing in field due fuel extite 608: no indication of extent of damage; road in Alabama in 2007;  J. P. Stevens & Co, New York NY Topeka Aircraft Sales, Topeka KS Kings Skyline Inc, Olathe KS Jean M. Brannon, Greenville SC SMB Stage Line, Des Moines IA crashed destroyed landing, Tyler TX  73SF, N74SF, N75SF & N176SF in row at Wallace NC 4.6 2. Stevens & Co; e OK 2.3.73 SMB Stage Line, at SMB maintenance base, ve 19.5.73 SMB; 31.5.73: SMB Stage Line, struck trees on final approach 2. view TX, pilot fatigue a factor, 1k;  Roscoe Turner Aeronautical Corp: CofA issued Inland Container Corp Roscoe Turner Aeronautical Corp Basler Flight Service, Oshkosh WI (cabin cargo tie-downs installed 12.62) Johnston Container Corp, Indianapolis IN Arkansas Aviation Sales, Little Rock AR ground-loop landing, gear collapsed, Big Spring TX Golden Eagle Aviation Pioneer Bank & Trust Co	57/64 66 69 70 17.12.71/73 31.5.73 61, all am, 7.11.56 9.11.56/62 29.10.62 2.11.62/64 22.1.64/68 10.2.69/70 24.4.69 16.9.70 12.70/71
	eccident in came to rep. stand E18S  photo shot tailwheel, N73JB not N73JB act flight Dalle	report 25.4.85 rest on VA Rod ding next to a selfing next to a sel	26.5.81 arrived, Mountain Air Cargo; cop Mountain Air Cargo: forced landing in field due fuel extite 608: no indication of extent of damage; road in Alabama in 2007;  J. P. Stevens & Co, New York NY Topeka Aircraft Sales, Topeka KS Kings Skyline Inc, Olathe KS Jean M. Brannon, Greenville SC SMB Stage Line, Des Moines IA crashed destroyed landing, Tyler TX  73SF, N74SF, N75SF & N176SF in row at Wallace NC 4.6 2. Stevens & Co; e OK 2.3.73 SMB Stage Line, at SMB maintenance base, ve 19.5.73 SMB; 31.5.73: SMB Stage Line, struck trees on final approach 2. view TX, pilot fatigue a factor, 1k;  Roscoe Turner Aeronautical Corp: CofA issued Inland Container Corp Roscoe Turner Aeronautical Corp Basler Flight Service, Oshkosh WI (cabin cargo tie-downs installed 12.62) Johnston Container Corp, Indianapolis IN Arkansas Aviation Sales, Little Rock AR ground-loop landing, gear collapsed, Big Spring TX Golden Eagle Aviation Pioneer Bank & Trust Co Combs Airways, Billings MT	57/64 66 69 70 17.12.71/73 31.5.73 61, all am, 7.11.56 9.11.56/62 29.10.62 2.11.62/64 22.1.64/68 10.2.69/70 24.4.69 16.9.70 12.70/71 21.6.71/72
BA-218	eccident in came to rep. stand E18S  photo shot tailwheel, N73JB not N73JB act flight Dalle	report 25.4.85 rest on VA Rod ding next to a selfing next to a sel	26.5.81 arrived, Mountain Air Cargo; cop Mountain Air Cargo: forced landing in field due fuel extite 608: no indication of extent of damage; road in Alabama in 2007;  J. P. Stevens & Co, New York NY Topeka Aircraft Sales, Topeka KS Kings Skyline Inc, Olathe KS Jean M. Brannon, Greenville SC SMB Stage Line, Des Moines IA crashed destroyed landing, Tyler TX  73SF, N74SF, N75SF & N176SF in row at Wallace NC 4.6 2. Stevens & Co; e OK 2.3.73 SMB Stage Line, at SMB maintenance base, ve 19.5.73 SMB; 31.5.73: SMB Stage Line, struck trees on final approach 2. view TX, pilot fatigue a factor, 1k;  Roscoe Turner Aeronautical Corp: CofA issued Inland Container Corp Roscoe Turner Aeronautical Corp Basler Flight Service, Oshkosh WI (cabin cargo tie-downs installed 12.62) Johnston Container Corp, Indianapolis IN Arkansas Aviation Sales, Little Rock AR ground-loop landing, gear collapsed, Big Spring TX Golden Eagle Aviation Pioneer Bank & Trust Co	57/64 66 69 70 17.12.71/73 31.5.73 61, all am, 7.11.56 9.11.56/62 29.10.62 2.11.62/64 22.1.64/68 10.2.69/70 24.4.69 16.9.70 12.70/71

(cargo door & floor, cockpit pilot door installed 11.76)	
op: General Aviation Inc, Greenville TN	79
Equipment Leasing Corp, Greenville SC	11.2.81/85
Coastal States Aviation, Denver NC	1.2.85/86
P. B. Leasing Co, Naperville IL	1.7.86/90
lsd: Viking Express, Cleveland OH	90
crashed landing, Minneapolis MN	5.10.90

N703M accident report 24.4.69: Arkansas Aviation, Big Spring-Howard County, 30 knot winds; N703M noted Miami FL 25.8.83: Mountain Air Cargo, no titles, arrived; accident report 5.10.90: ran off runway landing, undercarriage collapsed, tailwheel;

BA-220	E18S	N2601	Mobil Oil Corp, New York NY	.56
		N2621	Socony Mobil Oil Co, New York NY	63/64
		N2630	rereg Mobil Oil Corp, New York NY	66
		N2630K	damaged gear-up landing, Boston MA	19.12.68
		14203010	William Hathaway, Somerset MA	69
			Midwest Airlines, Louisville KY	70/73
			W. A. Mims Inc, Jacksonville FL	29.10.73/91
			o-O'Hare 10.1.71 Midwest Airlines; o-O'Hare 10.6.71 Midwest Airlines;	
BA-221	E18S	N19R	Red Owl Stores, Minneapolis MN	63/64
		N198N	William J. Blohm, Omaha NE	66/69
			International Business Aircraft Inc, Reno NV (visited Europe 7-11.70)	70
			registration pending: USCR	72
		N16572	crashed on takeoff, Reno NV	31.5.72
	London-H		k 19.7.70, London-Gatwick 4.8.70 tailwheel; Glasgow 19.8 1.70; Glasgow 16.11.70; 2 USCR;	3.70;
	N16572 a	accident repor	t: E18S stalled from 20 feet, 4 unhurt;	
		NIAONA	Warren Petroleum Corp, Tulsa OK	63/64
BA-222	E18S	N49W		00/01
BA-222	E18S	114911	Colonial Pipeline Co, Atlanta GA	66
BA-222	E18S	N49VV	Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH	
BA-222	E18S	N49VV	Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL	66 69/72 1.12.75/81
BA-222	E18S	N49VV	Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH	66 69/72
	E18S E18S	N38L (1	Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK	66 69/72 1.12.75/81 10.81 11.56/57
			Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59
			Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co Mid-Continent Supply Co	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59 3.11.59/61
			Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co Mid-Continent Supply Co Loffland Brothers Co of Venezuela	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59 3.11.59/61 21.3.61/62
			Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co Mid-Continent Supply Co Loffland Brothers Co of Venezuela J. C. Scott	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59 3.11.59/61 21.3.61/62 18.1.62
			Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co Mid-Continent Supply Co Loffland Brothers Co of Venezuela J. C. Scott Sunny South Aircraft Service	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59 3.11.59/61 21.3.61/62 18.1.62 17.9.62/63
			Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co Mid-Continent Supply Co Loffland Brothers Co of Venezuela J. C. Scott Sunny South Aircraft Service J & M Transportation Co, Americus GA	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59 3.11.59/61 21.3.61/62 18.1.62 17.9.62/63 16.2.63
			Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co Mid-Continent Supply Co Loffland Brothers Co of Venezuela J. C. Scott Sunny South Aircraft Service J & M Transportation Co, Americus GA St Louis-San Francisco Railway, St Louis MO	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59 3.11.59/61 21.3.61/62 18.1.62 17.9.62/63 16.2.63 10.63/64
			Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co Mid-Continent Supply Co Loffland Brothers Co of Venezuela J. C. Scott Sunny South Aircraft Service J & M Transportation Co, Americus GA St Louis-San Francisco Railway, St Louis MO Gulf-Virola Corp	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59 3.11.59/61 21.3.61/62 18.1.62 17.9.62/63 16.2.63 10.63/64 24.1.65
			Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co Mid-Continent Supply Co Loffland Brothers Co of Venezuela J. C. Scott Sunny South Aircraft Service J & M Transportation Co, Americus GA St Louis-San Francisco Railway, St Louis MO Gulf-Virola Corp Ortner Air Service, Wakeman OH	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59 3.11.59/61 21.3.61/62 18.1.62 17.9.62/63 16.2.63 10.63/64 24.1.65 12.65/75
			Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co Mid-Continent Supply Co Loffland Brothers Co of Venezuela J. C. Scott Sunny South Aircraft Service J & M Transportation Co, Americus GA St Louis-San Francisco Railway, St Louis MO Gulf-Virola Corp Ortner Air Service, Wakeman OH damaged struck snowbank of takeoff, Wakeman OH	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59 3.11.59/61 21.3.61/62 18.1.62 17.9.62/63 16.2.63 10.63/64 24.1.65 12.65/75 3.2.66
			Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co Mid-Continent Supply Co Loffland Brothers Co of Venezuela J. C. Scott Sunny South Aircraft Service J & M Transportation Co, Americus GA St Louis-San Francisco Railway, St Louis MO Gulf-Virola Corp Ortner Air Service, Wakeman OH damaged struck snowbank of takeoff, Wakeman OH Sunnyside Enterprises Inc	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59 3.11.59/61 21.3.61/62 18.1.62 17.9.62/63 16.2.63 10.63/64 24.1.65 12.65/75 3.2.66 17.1.75
			Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co Mid-Continent Supply Co Loffland Brothers Co of Venezuela J. C. Scott Sunny South Aircraft Service J & M Transportation Co, Americus GA St Louis-San Francisco Railway, St Louis MO Gulf-Virola Corp Ortner Air Service, Wakeman OH damaged struck snowbank of takeoff, Wakeman OH Sunnyside Enterprises Inc Active Air Inc, Wakeman OH	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59 3.11.59/61 21.3.61/62 18.1.62 17.9.62/63 16.2.63 10.63/64 24.1.65 12.65/75 3.2.66
			Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co Mid-Continent Supply Co Loffland Brothers Co of Venezuela J. C. Scott Sunny South Aircraft Service J & M Transportation Co, Americus GA St Louis-San Francisco Railway, St Louis MO Gulf-Virola Corp Ortner Air Service, Wakeman OH damaged struck snowbank of takeoff, Wakeman OH Sunnyside Enterprises Inc Active Air Inc, Wakeman OH (stored Wakeman OH as a wreck 76)	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59 3.11.59/61 21.3.61/62 18.1.62 17.9.62/63 16.2.63 10.63/64 24.1.65 12.65/75 3.2.66 17.1.75 12.8.75/77
			Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co Mid-Continent Supply Co Loffland Brothers Co of Venezuela J. C. Scott Sunny South Aircraft Service J & M Transportation Co, Americus GA St Louis-San Francisco Railway, St Louis MO Gulf-Virola Corp Ortner Air Service, Wakeman OH damaged struck snowbank of takeoff, Wakeman OH Sunnyside Enterprises Inc Active Air Inc, Wakeman OH (stored Wakeman OH as a wreck 76) K & K Aircraft Inc, Bridgewater VA	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59 3.11.59/61 21.3.61/62 18.1.62 17.9.62/63 16.2.63 10.63/64 24.1.65 12.65/75 3.2.66 17.1.75
			Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co Mid-Continent Supply Co Loffland Brothers Co of Venezuela J. C. Scott Sunny South Aircraft Service J & M Transportation Co, Americus GA St Louis-San Francisco Railway, St Louis MO Gulf-Virola Corp Ortner Air Service, Wakeman OH damaged struck snowbank of takeoff, Wakeman OH Sunnyside Enterprises Inc Active Air Inc, Wakeman OH (stored Wakeman OH as a wreck 76) K & K Aircraft Inc, Bridgewater VA (owner report 7.84: aircraft destroyed/scrapped)	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59 3.11.59/61 21.3.61/62 18.1.62 17.9.62/63 16.2.63 10.63/64 24.1.65 12.65/75 3.2.66 17.1.75 12.8.75/77 9.4.77/89
BA-223			Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co Mid-Continent Supply Co Loffland Brothers Co of Venezuela J. C. Scott Sunny South Aircraft Service J & M Transportation Co, Americus GA St Louis-San Francisco Railway, St Louis MO Gulf-Virola Corp Ortner Air Service, Wakeman OH damaged struck snowbank of takeoff, Wakeman OH Sunnyside Enterprises Inc Active Air Inc, Wakeman OH (stored Wakeman OH as a wreck 76) K & K Aircraft Inc, Bridgewater VA (owner report 7.84: aircraft destroyed/scrapped) struck-off USCR: owner request	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59 3.11.59/61 21.3.61/62 18.1.62 17.9.62/63 16.2.63 10.63/64 24.1.65 12.65/75 3.2.66 17.1.75 12.8.75/77
	E18S	N38L (1	Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co Mid-Continent Supply Co Loffland Brothers Co of Venezuela J. C. Scott Sunny South Aircraft Service J & M Transportation Co, Americus GA St Louis-San Francisco Railway, St Louis MO Gulf-Virola Corp Ortner Air Service, Wakeman OH damaged struck snowbank of takeoff, Wakeman OH Sunnyside Enterprises Inc Active Air Inc, Wakeman OH (stored Wakeman OH as a wreck 76) K & K Aircraft Inc, Bridgewater VA (owner report 7.84: aircraft destroyed/scrapped) struck-off USCR: owner request (reg. tfd to K&K rebuild of Westwind c/n 6323)	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59 3.11.59/61 21.3.61/62 18.1.62 17.9.62/63 16.2.63 10.63/64 24.1.65 12.65/75 3.2.66 17.1.75 12.8.75/77 9.4.77/89
BA-223	E18S N38L not	N38L (1	Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co Mid-Continent Supply Co Loffland Brothers Co of Venezuela J. C. Scott Sunny South Aircraft Service J & M Transportation Co, Americus GA St Louis-San Francisco Railway, St Louis MO Gulf-Virola Corp Ortner Air Service, Wakeman OH damaged struck snowbank of takeoff, Wakeman OH Sunnyside Enterprises Inc Active Air Inc, Wakeman OH (stored Wakeman OH as a wreck 76) K & K Aircraft Inc, Bridgewater VA (owner report 7.84: aircraft destroyed/scrapped) struck-off USCR: owner request (reg. tfd to K&K rebuild of Westwind c/n 6323)  -Ortner Field OH 25.5.76 as wreck;	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59 3.11.59/61 21.3.61/62 17.9.62/63 16.2.63 10.63/64 24.1.65 12.65/75 3.2.66 17.1.75 12.8.75/77 9.4.77/89 14.8.89
	E18S  N38L not	N38L (1	Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co Mid-Continent Supply Co Loffland Brothers Co of Venezuela J. C. Scott Sunny South Aircraft Service J & M Transportation Co, Americus GA St Louis-San Francisco Railway, St Louis MO Gulf-Virola Corp Ortner Air Service, Wakeman OH damaged struck snowbank of takeoff, Wakeman OH Sunnyside Enterprises Inc Active Air Inc, Wakeman OH (stored Wakeman OH as a wreck 76) K & K Aircraft Inc, Bridgewater VA (owner report 7.84: aircraft destroyed/scrapped) struck-off USCR: owner request (reg. tfd to K&K rebuild of Westwind c/n 6323)  -Ortner Field OH 25.5.76 as wreck;  Tulsair Distributors Inc, Tulsa OK: CofA issued	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59 3.11.59/61 21.3.61/62 18.1.62 17.9.62/63 10.63/64 24.1.65 12.65/75 3.2.66 17.1.75 12.8.75/77 9.4.77/89 14.8.89
BA-223	E18S N38L not	N38L (1	Colonial Pipeline Co, Atlanta GA Admiral Equipment Corp, Akron OH Zephyr Aviation, Zephyr Hills FL struck-off USCR  Tulsair Distributors Inc, Tulsa OK Loffland Brothers Co Mid-Continent Supply Co Loffland Brothers Co of Venezuela J. C. Scott Sunny South Aircraft Service J & M Transportation Co, Americus GA St Louis-San Francisco Railway, St Louis MO Gulf-Virola Corp Ortner Air Service, Wakeman OH damaged struck snowbank of takeoff, Wakeman OH Sunnyside Enterprises Inc Active Air Inc, Wakeman OH (stored Wakeman OH as a wreck 76) K & K Aircraft Inc, Bridgewater VA (owner report 7.84: aircraft destroyed/scrapped) struck-off USCR: owner request (reg. tfd to K&K rebuild of Westwind c/n 6323)  -Ortner Field OH 25.5.76 as wreck;	66 69/72 1.12.75/81 10.81 11.56/57 19.3.57/59 3.11.59/61 21.3.61/62 17.9.62/63 16.2.63 10.63/64 24.1.65 12.65/75 3.2.66 17.1.75 12.8.75/77 9.4.77/89

N962BH	Butler Airplane Sales	29.1.60
	Gwen C. Landry, East Troy WI	4.3.60/62
	Campbell Sixty-Six Express, Springfield MO	5.5.62/65
N166X	Campbell Sixty-Six Express, Springfield MO	15.3.65/71
	Semo Aviation Inc/Semo Airways, Malden MO	12.71/84
	(cockpit emergency hatch installed 4.77)	
	Air Machine & Services Inc, St James OH	2.2.84/86
	Hoganair Inc, Hamilton OH	19.2.86
N76HA	Hoganair Inc, Hamilton OH	11.7.86
N766X (2	Hoganair Inc, Hamilton OH	10.86
	The Eagle & The Hawks Inc, Middletown OH	1.11.86/94
	Miami Valley Aviation, Middletown OH	18.3.94/98
	The Eagle & The Hawks Inc, Middletown OH	29.5.98/08
	(retired, spares source for MVA at Middletown 98/07)	
	Kurt M. Yearout, Middletown OH	30.7.08/10
	struck-off USCR	26.5.10
	Columbus Zoo & Aquarium, Columbus OH: arr. by road	19.2.14/17
	(displ. in lion enclosure, all metal finish)	
	, , , , , , , , , , , , , , , , , , , ,	

N166X noted Springfield IL 4.8.73 Semo Airways;

N76HA noted St Louis MO 8.86;

N766X noted Middletown OH 22.7.98 stored away from Miami Valley ramp; N766X noted Middletown OH 6.8.99 & 22.7.00: both all metallic poor condition, in hangar as spares source for Miami Valley Aviation, previous reg N166X visible, plate BA-224 built 11.56, another plate: converted to -9700 5.60;

N766X noted Middletown OH 20.7.02 still stored;

N766X noted Middletown OH 1.8.05 in hangar, spares ship for MVA who have now ceased ops;

N766X noted Middletown OH 17.6.06 wfu;

N766X noted Middletown OH 8.07 out on grass retired;

E18S	N45M	Memphis Aero Corp, Memphis TN: CofA issued	27.11.56/57
		Dealers Transport Co	24.5.57/63
		John Morrell & Co, Chicago IL	12.2.63/67
		(PacAero two-piece windshield fitted 6.64)	
		Vercoa Air Service/ Allegheny Commuter, Danville IL	9.11.67/70
		(cargo door installed 1.68)	
		Golden Eagle Aviation	2.9.70
		Great Plains Realty & Development Co	12.70/71
		Southern Aviation, Lawton OK	72
		Apollo Airways, Detroit MI	7.72/79
		(cargo tie-downs fitted 3.73)	
		renamed: Gelco Courier Services, Chicago IL	79
		Carl W. Drebing	5.4.79/80
		Bob Alexander Aircraft Sales	20.6.80
		FAA file report: seized by Mexican authorities	

N45M photo 6.81 new style two-piece windshield;

BA-226	E18S	N38D	Great Lakes Pipe Line Co, Kansas City MO	63/64
		N352WB	Williams Bros Pipe Line Co, Kansas City MO	66
			damaged struck snowbank landing, Minneapolis MN	7.1.67
		N319NF	rereg	
		N148JM	United Engines Inc, Shreveport LA	69/72
	Turbo-Mod 18		Robert A. Emmett/ Turbo-Mod Co, Birmingham MI ( <i>Turbo-Mod 18</i> conversion commenced by 6.80, fitted with Lycoming TIGO-541-D turbines: not completed)	18.4.77/81
			struck-off USCR	12.3.81
BA-227	E18S	N26X	Ohio Aviation Corp, Dayton OH: CofA issued	4.12.56
			Armco Steel Corp	12.56/59
		N1400E	Atwood Vacuum Machine Co, Rockford IL	10.59/67
			Aerodynamics Inc, Pontiac MI	3.7.67/71

Cryderman Air Service, Pontiac MI	13.4.71
Karl D. & Kenneth A. Stoltzfus/ K & K Aircraft Inc,	
Bridgewater VA	10.71/06
(cargo door installed 6.79; aerial spraying system	
350 gallon tank in cabin installed 7.80 for	
gipsy moth & mosquito spraying contracts)	
(retired, stored in open Bridgewater VA 3.98,	
stored dismantled in shed on airfield by 8.99)	
nn: Dynamic Avlease Inc, Bridgewater VA	4.5.10/20
(completing airworthy rest. at Bridgewater Air Park 6.19)	

N1400E noted Bridgewater Air Park VA 3.98 tailwheel, wfu in open, nose removed; N1400E noted Bridgewater VA 11.8.99 all metallic, wfu by K&K stored in "chicken coop" storage shed on far side of airfield;

further details K&K sprayers: see Beech 18 by Robert Parmerter p.292;\
N1400E noted Bridgwater Air Park VA 6.19 almost finished long-term rest, polished metallic, Tailwheel, extended nose, radials)

BA-228	E18S	N43L	Atlantic Aviation Corp: CofA issued	13.12.56/58
	-9700		Moran Brothers Inc	22.4.58/60
			Continental Pipe Line Co, Ponca City OK	26.2.60/66
			J. R. Hatton, Alice TX	31.8.66/72
			(G18S type windshield installed 11.66)	
		Valko T. E. DeMin	Valko	5.7.72/76
			T. E. DeMint, Pine Bluff AR	13.5.76/80
			(cargo door installed 1.80)	
		International Aero Sales Inc, Miami FL	5.9.80	
			groundlooped on takeoff, struck parked Goose N33S	
			and 3 other parked aircraft N9423G, N203L & N9473D,	
			destroyed by fire, Gainesville FL	9.9.80

N43L accident report 9.9.80: no operator quoted, pilot unknown, pax hurt, takeoff at 11.22pm for unknown destination, 132lbs over gross weight;

BA-229	E18S	N68A	Moffat Coal Co, Scranton PA	63/64
			Corporate Air Transport, Chicago IL	66/70
			Southern Aviation, Lawton OK	71/72
			Leone I. Van Torne, Van Dalia OH	25.8.76/77
			crashed destroyed by fire landing, Springfield OH	3.6.77
	N68A not	ted Kansas Ci	ty MO 12.72;	
BA-230	E18S	N84D (2	Youngstown Airways, Youngstown OH	12.56/57
			Harbison-Walker Refractories Co	2.1.57/60
			Forrest Beckett/Beckett Aviation/	
			Youngstown Airways/ Lease Air, Youngstown OH	25.5.60/62
		N8411	Jack Adams Aircraft Sales, Walls MS	28.7.62
			Jack Richards Aircraft Sales	24.8.62
			Graubart Aviation, Valparaiso IN	2.10.62/63
	trigear		(Volpar Mk.IV trigear installed 11.62)	
			National Equipment Sales Inc, Elmont NY	7.2.63/66
			Rolair Corp/ Wright Air Lnes, Cleveland OH	29.6.66/70
			(window & windshield mods installed 8.66)	
		N404FW	Wright Air Lines, Cleveland OH	2.8.66/70
			P. M. Bachner	2.2.71/72
	-9700		(modified 3.71 to E18S-9700)	
			Bureau of Customs: seized South Bend IN	5.72
		N2132M	P. M. Bachner	5.7.72/77
			Northrop University, Inglewood CA	28.4.77/84
			(retired: ground instructional airframe)	
			struck-off USCR	8.88
			Aerospace Products Inc, North Hollywood CA	97
		N2132M	Cameron & Stahl Inc, North Hollywood CA	6.97
			Empire Airways Corp, Jacksonville FL & Maplewood NJ	11.8.97/99
		(N18KG)	rereg. res: Empire Airways Corp	8.97

N18LK	Empire Airways Corp, Montville NJ	11.1.99
	George J. Kaminskyj, Montville NJ	14.2.00/05
	OTW Farms LLC, Wilmington DE	2.11.05/06
	Holli Aero Leasing Inc, Wilmington DE	17.8.10/16
	Gerald D. Quitney, Ennis MT	22.9.16/20
	(moved by road dism. to Stockton CA 9.19)	

N404FW owned Rolair, leased to Wright Airlines, Cleveland;

N404FW noted Ft Lauderdale FL 13.6.71 trigear;

"N2132" trigear advertised for sale 4.97: out of licence, ferriable, Aerospace Products;

N2132M noted Chino CA 10.98 trigear;

N18LK noted Chino 4.99 at Aero Trader hangar;

N18LK noted Chino CA 18.8.99 trigear in Aero Trader hangar, plate BA-230 built 12.56, another plate converted to -9700 3.71;

N18LK noted Chino CA 16.8.00,

N18LK noted Chino CA 17.9.01 trigear;
N18LK noted Perrin TX 27.10.18 trigeart parked flat tyres:

	N18LK noted Perrin TX 27.10.18 trigeart parked flat tyres;					
BA-231	E18S	N61E	Burlington Industries Inc, Greensboro NC	63/64		
_, , _, ,			Carolina Fleets Inc, Anderson SC	66/72		
			National Air Freight	75		
			Santa Nella Parachute Center, Gustine CA	6.5.76/81		
			forced landing off-airport, near Santa Nella CA	20.8.77		
			struck-off USCR	10.81		
BA-232	E18S	N75A	S. D. Warren Co, Boston MA	63/64		
		N7580	Jack Adams Aircraft Sales, Walls MS	66		
			op: Ambassador Airlines, Las Vegas-McCarran NV	67/68		
	ATE		(conv. to ATE Westwind I trigear .68)			
	Westwind I		Carco Air Service of Nevada, Las Vegas NV	69		
	trigear		Nevada National Bank, Las Vegas NV	70		
	J	N80GP	Georgia Pacific Corp, Portland OR	.71/72		
			Great Western Airlines, Tulsa OK	9.74		
		N201GW	Great Western Airlines, Tulsa OK	10.6.77/79		
	Hamilton		(rebuilt as <i>Hamilton Westwind III</i> with tail gear,			
	Westwind I	II	by Hamilton Aircraft at Tucson AZ)			
	tailgear		crashed destroyed on takeoff, Cedar Rapids IA	23.3.79		
	N758D noted LAX 18.8.67 Ambassador Airlines, rep. as Volpar Super Turbo: probably this acft GG; N201GW accident report 23.2.79: Great Western: stalled on takeoff on slushy runway, ice on airframe, flight to Springfield IL, pilot had high blood alcohol, 8.53pm, 2 crew k;					
BA-233	E18S	N49K (1	Flightcraft Inc	7.1.57/58		
			Walston Aircraft Sales & Service	1.7.58/61		
		N249K	Walston Aircraft Sales & Service	6.6.61/62		
			Graubart Aviation, Valparaiso IN	27.3.62/63		
			Frank D. Hansen/ Hansen Air Activities, Morris IL	4.6.63/65		
			James E. Kelley, Fort Wayne IN	18.2.65/67		
			Glen T. Albrecht/ Air Trader, Fairfax VA	30.3.67/71		
			Gilley Airways Corp, Fulton NY	6.4.71/74		
			damaged, struck snowbank landing, Syracuse NY Karl D. & Kenneth A. Stoltzfus/ K & K Aircraft Inc.	22.12.73		
				00.4.74/44		

N249K accident report 22.12.73: Gilley Airways, pilot unhurt,
---

Bridgewater VA

struck-off USCR

BA-234	E18S	N5Y (2	Southern Airways Co	7.1.57	
	-9700	•	Turner-Halsey Co, New York NY	7.1.57/65	
		N245RM	Riverside Manufacturing Co, Moultrie GA	12.3.65/69	
		N11RM	Riverside Manufacturing Co, Moultrie GA	17.4.69/76	
		N11RX	Nayak Aviation Corp	26.5.76	
			Ross-Hulett International Insurors	17.8.76/78	
			A. L. Sutton, Fort Davis TX	31.1.78	
			Larry Murphy, Florida City FL	5.10.78/82	

26.1.74/11

27.5.11

## N11RM noted Atlanta GA 24.9.70;

BA-235	E18S	N54K	Currey Sanders Aircraft Co	11.1.57
	-9700		Interstate Oil Pipe Line Co	14.3.57/61
			Humble Pipe Line Co, Houston TX	31.7.61/66
			Miami Aviation Corp, Opa Locka FL	5.8.66/72
			landed with gear retracted, Tampa FL	8.8.67
			Gilley Airways Corp, Fulton NY	15.9.72/73
			Charles E. Rockwell/ Rockwell Farm	1.11.73/74
			George P. Tobler/ Henry Ford Plantation	15.5.74/76
			Jerry A. Lindahl, Chardon OH	4.2.76/79
			KCR Airplane Co	11.79/84
			Daniel L. Brodsky-Chenfeld, Columbus OH	5.84/86
			William S. Jones, Clewiston FL	11.86/87
			William B. Lumley, Villa Park IL, later Delray Beach FL	21.8.87/20
	N54K noted	d Opa Locka	FL 23.8.71;	
BA-236	E18S	N33JD (2	J. D. Reed Co, Houston TX	11.2.57
	-9700	N514T	Tennessee Gas & Transmission Co, Houston TX	18.4.57/62
		N514J	J. S. Abercrombie, Houston TX	2.11.62/63
		N514JH	Executair Inc, Cincinatti-Lunken OH	8.2.63/65
	Aerojet		(Aerojet rockets fitted 4.63)	
	rockets		(Capitol Aviation G18S type two-piece windshield,	
	trigear		picture windows, Volpar Mk.IV trigear fitted 1.64)	
	Ü	N56S	American Management Association Inc, Hamilton NY	22.7.65
		N5681	Southern Ohio Aviation Sales, West Carollton OH	7.11.66
			Aircraft Owners Inc, Miami FL	11.66/67
		N787S	Aircraft Owners Inc, Miami FL	3.4.67
	ATE		(rebuilt by American Turbine Aircraft Co to ATE Westwin	d I
	Westwind I		at Long Beach CA 3.67: PT6A-20 turbines: type also	
	trigear		referred to as ATE Turbine 600R)	
	· ·		Harry H. Bassett, Miami FL	25.8.67/68
			Southeast Properties/ Financial Carriers Inc, Miami FL	12.68/70
			Southern Airways Co, Orlando FL	2.70
		N909GP	Georgia Pacific Corp, Portland OR	25.3.70/73
			Hamilton Aircraft Co, Tucson AZ	12.6.73/74
	Hamilton		(rebuilt as Hamilton Westwind III: trigear replaced with	
	Westwind II	II	conventional landing gear, cargo/airstair door,	
	tailgear		cockpit door, Hamilton extended cargo nose:	
			completed by Hamilton 5.74)	
			Tobey Inc, Belgrade Lakes ME	15.5.74/79
			Check-Air Inc, Milwaukee WI	20.8.74
			FFC Inc	4.10.74/86
			lsd: Mountain Air Cargo, Denver NC	4.10.74/89
			lsd: Check-Air Inc, Milwaukee WI	78/79
			Check Air Inc, Milwaukee WI	8.79
			Mountain Air Cargo, Denver NC	3.80
			Coastal States Aviation, Denver NC	5.86/89
			Karl D. & Kenneth A. Stoltzfus/ K & K Aircraft Inc,	
			Bridgewater VA	26.9.89/06
			(rebuilt by K&K 11.91, cabin windows skinned over,	
			ag. & pest control category, CofA renewed 29.4.94)	
			Brazoria County Mosquito Control, Angleton TX	21.4.10/16
			Countryside Aviation, Chilton WI	6.9.16/20
			•	-

N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles; N909GP photo 9.76 as Westwind III; N909GP noted Milwaukee WI 1.9.78 "Check Air" titles;

N909GP noted Des Moines IA 5.79 "Check-Air" titles, Westwind III tailgear; N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer,

"K&K Aircraft" titles, plate: BA-236 built 1.57;

N909GP noted Los Alamitos CA 13.8.02 with other K&K sprayers;

BA-237	E18S	N57H	built	.57		
	-9700	CF-TAB	Timmins Aviatio Ltd, Montreal QUE	.57		
			Transair Ltd, St James MAN			
			Steep Rock Iron Mines Ltd, Atikokan ONT	65/66		
			Commander Aviation Ltd	.66		
		N12421	Miami Aviation Corp, Opa Locka FL	4.7.66		
		N380MA	Miami Aviation Corp, Opa Locka FL	12.66/68		
			Dee Howard Co, San Antonio TX	31.5.68/69		
			Jim Hankins Air Service/ Hankins Airways, Jackson MS	22.4.69/76		
			Cape Central Airways, Cape Girardeau MO	12.76/77		
			Charles H.Southerland	27.4.77/78		
			Coastal Aviation	27.3.78/80		
			op: The Airplane Co, Pensacola FL	79		
			Missouri Aviation	29.1.80/82		
			Fitness Marketing Associates Inc, Manhasett NY	14.4.82		
			crashed destroyed landing, parachute ops, Lakewood NJ			
	CF-TAB v	isited Toronto	ONT 23.4.64;			
3A-238	E18S	N49M	Ohio Oil Co, Findlay OH			
			American Brake Shoe Co, Akron OH	63/70		
			emergency exit inadvertantly released in flight by			
			a passenger, over Lake Erie OH	25.3.64		
			ABEX Corp, Athens OH	72		
		N49MA	rereg	11.76		
			Tobey Inc, Belgrade Lakes ME, later Simsbury CT	78		
			Brennan & Hargreaves Inc, Bradford CT	79/80		
			minor damage landed gear-up, Newburgh-Stewart NY	15.9.79		
			Francis J. McCarthy, St Thomas USVI	8.82		
			op: Four Star Air Cargo, St Thomas USVI	84/85		
			groundlooped, crashed on takeoff St Thomas USVI	20.3.85		
			struck-off USCR	12.85		
	N49MA a	ccident report	15.9.79: Brennan & Hargreaves, pilot forgot to extend land	ling gear, he wa		
	No.1 in a	sequence of 3	3 inbound acft, No.2 was DC-9 with cargo for the others, 5.1	10am, pilot unhı		
	N49MA n	oted Burlingto	n VT 1.80 in service, tailwheel, "BH" on tail;			
BA-239	E18S	N51M	built	.56		
			Ohio Oil Co, Findlay OH			
			Marathon Oil Co, Findlay OH	63		
			Ohio Aviation, Dayton OH	64		
			Page Airways, Rochester NY	66		
			HAT Inc, Flint MI	69/70		
			Eagle Aviation, Flint MI	71/79		
			Green Aero Inc, Flint MI	2.2.79/82		
			struck-off USCR	1.12.82		
	SHUCK-OH USCK 1.12.82					

			struck-off USCR	1.12.82
	N51M no	oted Flint-Bisi	nop MI 8.80 "Green Aero" titles, tailwheel;	
BA-240	E18S	N41G	Gopher Aviation, Rochester Airport MN	29.1.57
			Gerald H. Galbreath	21.5.57/61
			John J. Shea, Memphis TN	11.61/63
			Memphis Air Taxi	24.7.63
			Leeward & Hart Aeronautical Corp, Miami FL	11.63/65
			Harry W. Hosford, Shaker Heights OH	2.2.65/75
			Morris L. Henderson	22.3.75
			Bernard L. Stella	12.75/76
			Jack R. Tarry, Elyria OH	12.76/77
			William R. Sandlin & Aubrey Buzan, Harlingen TX	12.77/78
			Lorena Sanchez	5.9.78/81
			William R. Sandlin, Harlingen TX	16.1.81/98
			struck off USCR	28.7.98

BA-241	E18S	N42T	McGean Chemical Co, Cleveland OH Chemetron Corp, Cleveland OH John R. Tarry, Elyria OH sold to owner, Texas (electrical goods smuggling operations into Mexico, undercarriage failed landing Mexico: TVs unloaded then aircraft set on fire)	63/70 71/72 21.4.78/82 82
			struck-off USCR	8.82
BA-242	E18S	N3333 (3	Beech Aircraft Corp, Wichita KS: CofA issued Southern Airways Co, Atlanta GA Swiflite Aircraft Corp, New York NY landed with tailwheel retracted, Des Moines IA Landy Taylor & Associates, Lansing MI Dexter D. Coffin Florida Airmotive Inc, Lantana-Palm Beach FL Riggers & Erectors of Florida Inc, St Croix USVI Eastern Caribbean Airways, St Croix USVI Thomas L. Hughes op: General Aviation Inc, Greenville TN International Airsalvage Co sale rep., Atlanta GA	31.1.57 12.2.57 12.2.57/67 23.2.66 22.9.67/70 11.70/71 30.4.71 10.71/77 10.77/79 31.3.79/82 80 5.9.82 91
	N3333 no N3333 no N3333 no N3333 no	ted Ft Worth ted Ft Lauder ted Opa Lock ted St Thoma	iso traded as Cities Service Co; TX 6.57, "Cities Service" titles & emblem; dale FL 28.9.70; a FL 4.10.77; s USVI 30.4.78; JSVI 2.5.78 ECA;	
BA-243	E18S	N4372D N21U (1	Beech Aircraft Corp, Wichita KS: CofA issued J. D. Reed Co, Houston TX Ceramic Engineers Inc, Houston TX Keystone Valve Corp, Houston TX	10.1.57/58 7.8.58 7.8.58/65 10.4.65/67
		N2107	damaged landing with gear locked-up, Chicago IL Keystone Valve Corp Robert M. Flagler Alberto Nayor, Santure, Puerto Rico op: Coastal Airways, San Juan, Puerto Rico Coastal Airways, San Juan, Puerto Rico Henry R. Collazo	14.3.67 5.9.67/68 18.1.68 16.9.68/71 70/71 10.71/72 20.4.72/73
		N6898	Belvon Aircraft Leasing Inc Jed Air	6.73/76 29.6.76/77
			(Aerospace Products cargo door installed 6.76) Burl-Air Freight Inc, Burlington WI James R. Beardsley/ Crystal Lake School of Aviation,	23.5.77/82
			Crystal Lake IL sale rep., USCR K & K Aviation, Bridgewater VA: broken-up for parts South West Aero Exchange, Owasso OK	11.82/84 10.5.84/91 .83 00
			(damaged fuselage in salvage yard, Owasso OK 00)	- 0
			PR 12.12.70 Coastal AW; Southwest Aero Exchange yard, Owasso OK 10.8.00;	
BA-244	E18S trigear	N650R (1 N770C (2	Atlantic Aviation Corp: CofA issued International Business Machines Corp The Chamstrand Corp	5.2.57 6.2.57/59
		N400S	The Chemstrand Corp Monsanto Chemical Co, St Louis MO Capitol Aviation, Springfield IL	10.59/62 24.4.62/63 29.4.63
		N7N	Capitol Aviation, Springfield IL (Volpar Mk.IV trigear, picture windows & G18S type	9.9.63/64

windshield installed 11.63)	
S & W Construction Co	14.1.64/66
Downtowner Corp, Memphis TN	25.7.66/69
Commercial Leasing & Financing, Lafayette LA	21.8.69/72
Isd: Marvin Pool & Associates	21.8.69/72
Super 18 Inc	2.10.72/74
Business Aircraft Corp	11.1.75/76
landed gear locked-up on foamed runway,	
Niagara Falls NY	29.5.75
Sam Vires/ Mid-South Aircraft Sales, Memphis TN	27.2.76/91
sale rep: USCR 91/12, struck-off USCR	15.10.12

N7N accident report 29.5.75: flight Bridgeport CT to Buffalo NY, pilot unhurt; (FAA file: Sam Vies advises 7.90: although N7N still reg. to him, he no longer owns it!)

BA-245	E18S	N73A	built	57 63/64
			Airlease Corp, San Francisco CA Fairchild Hiller Corp, St Augustine FL	66/72
			Gilley Airways Corp, Fulton-Oswego County NY	9.2.78/82
			struck-off USCR	8.82
			Struck-on OSCR	0.02
BA-246	E18S	CF-JMV	Field Aviation Co Ltd, Oshawa ONT: dealer (del. to Oshawa 15.2.57 ex Wichita)	2.57
			Canadian Nickel Alr Services Ltd, Copper Cliff ONT	24.4.57/71
			nn: International Nickel Co of Canada Ltd, Toronto ONT	12.71/74
			Exploraciones y Explotaciones Mineras Izabal SA	27.2.74
			struck-off Canadian Register	21.3.74
		TG-EXM	Exmibal SA, La Aurora, Guatemala	3.74/75
		TO EXIV	(CofA expired 31.4.75)	0.7 1170
			(TG-EXM arrived Toronto ONT 19.11.76 on delivery,	
			noted parked at Maple ONT 9.4.77)	
		C-FJMV	Floyd Carson	77
		C-I JIVIV	Strout Aviation Inc	21.9.77
		N70766	Ralph Quinlan/ Mountain Air Cargo, Denver NC	22.9.77
		1470700	(Aerospace Products cargo door, cargo floor,	22.9.11
			Hamilton pilot cockpit door installed 31.10.77)	
		NIZOOM (2		
		N700M (3	Ralph Quinlan, Lincolnton NC/ Mountain Air Cargo,	10 77/00
			Denver NC	12.77/83
			op: General Aviation, Greenville TN	80
			crashed, ran off runway into trees on takeoff,	0.40.00
			Denver-Little Mountain Airport NC	3.10.83
	N700M n	oted JFK NY 2	3.8.83 Mountain Air Cargo, no titles;	
BA-247	E18S	N25X (2	Butler Airplane Sales: CofA issued	14.2.57
	-9700	`	Thor Power Tool Co, Chicago IL	19.2.57/59
			Electric Auto-Lite Co	16.7.59/60
			O. C. Field, Palos Verdes CA	18.3.60/71
			op: Personnel Air	68
			struck runway lights landing, Los Angeles CA	20.12.68
			Crescent E. Clark, Sepulveda CA	4.5.71/75
			Theta Enterprises	15.1.75/77
			Trademark Aviation Corp, Van Nuys CA	2.77
			Aerospace Products Inc, North Hollywood CA	11.8.77/82
			Eugene A. O'Brien, Denver CO	12.82/87
			Leasing Equipment Services Inc, Penndel PA	17.2.87/88
			Audley Maduro, Pomona NY	25.5.88/13
			struck-off USCR	23.10.13

N25X noted Prestwick, Scotland 10.9.57 Thor Silver Line/ Thor Power Tools titles;

N25X visited Dublin, Ireland .57 Thor Silver Line, a power tool company;

N25X photo at London c57 Thor Tools titles; N25X noted San Fernando Valley CA 22.11.62;

N25X noted San Fernando Valley CA 7.68;

N25X accident report 20.12.68: Personnel Air, struck runway lights landing LAX;

N25X noted Van Nuys CA 17.4.72;

BA-248	E18S	N49N	Topeka Aircraft Sales & Service, Topeka KS: CofA	5.3.57
	-9700		Panhandle Eastern Pipe Line Co, Kansas City MO	7.3.57/65
			(G18S type windshield, picture windows,	
	JATO		JATO jet-assisted takeoff kit installed 2.62)	
	jets		Anadarko Production Corp, Fort Worth TX	12.9.65/69
			American Jet Leasing Inc, St Louis MO	3.6.69/75
			(Aerospace Products cargo door installed 7.74)	
			William Crowley/ East Central Lines Inc	11.75
			sale reported: USCR	77/91
BA-249	E18S	N2000 (3	Southern Airways Co, Atlanta GA: CofA issued	25.2.57
		•	Swiflite Aircraft Corp, New York NY	6.3.57/66
		N2000C	Swiflite Aircraft Corp, New York NY	21.1.66
		N2001C	Swiflite Aircraft Corp, New York NY	4.5.66
			Southern Airways Co	30.9.66/68
			Franklin Development Co, Newnan GA	10.4.68/71
			Georgia Sheriff's Boys Ranch	1.4.71
			David L. Zuck/ Tigre Aircraft Maintenance & Repair Inc	7.8.71
			Aircraft Unlimited Inc	11.71/72
			Philip Gilmore/ Gilmore Mobile Homes	7.12.72/73
			Semo Aviation Inc, Malden MO	12.73/83
			(cockpit emergency hatch installed 4.77)	
			struck fuel tanker taxiing, St Louis-Lambert MO	29.2.80
			Springdale Air Service, Springdale AR	10.83/87
			struck Metro taxying at night, Oklahoma City OK	23.6.86
			Julio M. Contrera, Miami FL	5.7.87
			Richard F. Kelley, Fort Lauderdale FL	11.87/88
		N238K	Charles M. Howell, Lake Worth FL	11.1.88
			Roy A. Hall, West Palm Beach FL	25.2.88/89
			William B. Lumley, Chattanooga TN	4.8.89/97
			Carol J. Lumley, Desplaines IL	28.10.97/12
			(noted at Lonoke AR 4.10 derelict) reg expired 31.12.12, struck-off USCR	20.7.17

N2001C accident report 29.2.80: Semo Aviation, cargo flight St Louis to Chattanooga TN, 11.01pm, pilot unhurt;

N2001C accident report 23.6.86: Springdale Air Service, taxiway collision at night;

BA-250	E18S	N58H	Kay Kimbell, Fort Worth TX	63/64
			Kimbell Milling Co, Fort Worth TX	66/69
			Schero & Waldren Inc, Houston TX	70
			Jess P. Kimball/ Spa Flying Service Hot Springs AR	8.7.71/78
	Hamilton		op: Tobey Inc, Simsbury CT	78
	Extended		op: Brennan & Hargreaves, Bradford CT	78
	Nose		crashed dest., night forced landing Latham NY	1.9.78

N58H accident report 1.9.78: Brennan & Hargreaves, cargo flight Albany NY to Windsor Locks CT, power failure initial climb, forced landing off airport, fire after impact, 8.46pm, pilot unhurt;

BA-251	E18S	N1111 (2	Southern Airways Co, Atlanta GA: CofA issued	1.3.57
	-9800		Swiflite Aircraft Corp, New York NY	4.4.57/66
		N1000C	Swiflite Aircraft Corp, New York NY	1.66
		N1002C	Swiflite Aircraft Corp, New York NY	5.5.66
			Atlantic Aviation Corp	24.6.66
			Ortner Air Service, Wakeman OH	24.8.66/74
			wing damaged during emergency landing after takeoff,	
			St. Louis MO	29.8.73
			Fred F. Ortner/ Rural Leasing Inc	30.8.74/75
			Active Air Inc, Wakeman OH	12.75/78
			K & K Aircraft, Bridgewater VA	7.9.78/96
			(cabin cargo floor installed 2.79, converted for aerial application 350 gallon chemical tank 2.82 for	
	a .		gipsy moth & mosquito spraying contracts)	10.00/04
	floats		Glenn Goodman, Venice FL	10.96/01
			Eagle Point Inc, Venice FL	19.11.01/02

N1002C noted Wakeman-Ortner OH 25.5.76;

N1002C noted Venice FL 15.8.98 under overhaul, no reg: plate: BA-251 built 3.57,

plate: -9800 conv. 12.61;

N1002C noted Sarasota FL 8.4.97 floats:

Beech 18 by Robert Parmerter book index lists N1002 for BA-251: RP confirms is error;

BA-252	E18S	PP-ECW	built Gov East de Minas Gerais, Belo Horizante	.57 65/83
			crashed	1.8.68
BA-253	E18S -9700	N166H	Ohio Aviation Co, Dayton OH: CofA issued M. A. Hanna Co/ Hanna Mining Co, Cleveland OH (miscellaneous improvements, Chemberlain radome 3.6 George H. Bailey Leasing Corp, Fort Wayne IN Life Insurance Co of Kentucky SMB Stage Line Inc, Des Moines IA ran off runway on takeoff, struck ditches, gear collapsed, Cleveland-Hopkins OH Crawford Aviation Allen R. Burrill damaged landing, Cedar Rapids IA Midwest Aviation Corp Pablo Gutierrez Richard Wixom/ Blackhawk Airways, Janesville WI (G18S cab mod. removed from N5696D/BA-422 and fitted to N166H by Blackhawk Airways) Blackhawk Airways, Janesville WI Gail Force Corp/ Gail Force Express, Beloit WI Falcon Field LLC, Sun Prairie WI Catalina Flying Boats Inc, Long Beach CA Hans W. Munich, Yakutak AK	21.3.57 3.57/66 50) 14.3.66/67 25.5.67/68 10.68/79 27.2.70 .79 17.9.79/81 24.4.80 7.4.81/85 19.2.85 1.5.85/91 1.94/95 10.1.97/00 2.3.01 24.8.01/06 20.2.08/
			dam. accident Yakutak AK reg expired 31.12.13, struck-off USCR	15.9.08 11.1.18

N166H noted Rock County WI 7.91 "Blackhawk AW" plate BA-253;

N166H noted Rock County WI 7.97, no titles, op. Gail Force Express:

N166H noted Rock County WI 2.8.98 no titles, op. Gail Force Express, plate BA-253 built 3.57, another plate -9700 conversion;

Report 1.00: Gail Force Express operating Beech 18s on US Mail run Albany NY to Williamsport PA including N166H rotating between maintenance at Blackhawk Alrways, Janesville WI;

N166H noted Rockford IL 30.7.00 parked outside Aero Taxi hangar, plate BA-253;

N166H noted Long Beach CA 29.4.01 at Catalina Flying Boat hangar, tailwheel;

N166H noted Phoenix AZ 27.5.01 with "Catalina Flying Boats" titles;

N166H noted Phoenix AZ 7.01 in service;

N166H noted Long Beach 8.01 in service Catalina FB, flying:

"6H" noted Long Beach CA 13.8.02 in Catalina Flying Boats compound;

BA-254	E18S	N1019B	Gerald C. Francis/ Francis Aviation, Lansing MI: CofA	21.3.57
	-9700		Herschel H. Decker/ Airtravel Service	23.4.57
			Matilda R. Wilson/ Meadow Brook Farms, Rochester MI	23.4.57/66
			Sargent Engineering Corp, Fort Dodge TX	8.3.66/67
			Warner & Swasey Co, Cleveland OH	11.67/69
			Ohio Aviation Co, Dayton OH	25.7.69/72
			Van Dusen Acceptance Corp, Minneapolis MN	8.6.72/74
			Maxson Aviation, Kotzebue AK	4.6.74/76
	Hamilton		(cargo door, floor, cockpit entrance door, and	
	extended		extended cargo nose installed 6.74)	
	nose		Conrad Kalitta, Willow Run MI	10.8.76
			Tobey Inc, Belgrade Lake ME	12.76/82
			op: Brennan & Hargreaves Inc, Hartford CT	79
			Jimmie L. Billingsley, Fort Worth TX	8.3.82/89
			Del Caribbean Corp, San Juan, Puerto Rico	17.11.89/06
			op: Boringuen Air, San Juan, Puerto Rico	00
			Antilian Puerto Rico Inc, San Juan, Puerto Rico	24.7.06/18

struck-off USCR 2.1.18

N1019B noted Waco TX 10.87, radials, Hamilton extended nose; N1019B noted San Juan PR 16.6.00 in service, operated Borinquen Air;

	11.0.02 11	otou oun ouun	TT N 10.0.00 III Service, operated Borniquen Air,	
BA-255	E18S	YV-P-EPA N74825	reg reg	1.57
		YV-P-AEA	reg	
		YV-P-GPX		10.61
		YV-E-BPV		5.62
		I V-E-DF V	Technica Cartografica	72
		YV-14CP	rereg	12
	YV-E-BPV	noted Caraca	as-Maiquetia 1.3.72 Technica Cartografica;	
BA-256	E18S	N5000 (2	Swiflite Aircraft Corp, New York NY	.56/66
		N5000J	Swiflite Aircraft Corp, New York NY	5.66
			Southern Airways Beechcraft Inc, Orlando FL	66
			Five Smiths Inc., Atlanta GA	69/70
			Goldways Inc, Winter Park FL	8.10.70/73
			crashed destroyed during landing Treasure Cay, Bahama	
			A 3.10.68, plate BA-256; A 24.9.70 "Falcons";	
DA 257	E100	NI72LI	Diadment Aviation Winston Salam NC	22.2.57
BA-257	E18S	N73H	Piedmont Aviation, Winston Salem NC	22.3.57 22.3.57/63
	-9700		Hanes Hosiery Mills Co, Winston Salem NC (mods to E18S-9700 installed .57 by Piedmont Aviation, Winston-Salem NC)	22.3.57/63
			Bailey Leasing Corp, Fort Wayne IN	31.5.63
			Northwestern Engineering Co, Rapid City SD	6.11.63/71
				1.7.71/77
			Snedigar Flying Service, Rapid City SD	1.7.7 1/77
			(cabin cargo floor installed 2.72)	40.77/70
		NOOOD	Bard Air Freight, Detroit MI	12.77/78
		N80CB	Bard Air Freight, Detroit MI	20.5.78/79
			(cockpit hatch entrance installed 9.78)	
			Bard Air Corp/ Bard Air Freight, Detroit MI	84/92
			Viking Group Inc, Detroit MI	10.5.92
			Robert B. Burwell, West Chicago IL	25.9.92/93
			lsd: Viking Express, Chicago-Midway IL	93
			crashed, struck trees during emergency landing,	
			Lone Rock WI	4.5.93
BA-258	E18S	N74SF	J. P. Stevens & Co, New York NY	.57/64
			Deltona Corp, Miami FL	66
			S. W. Sisk/ Orion Airways, St. Louis MO	68/69
			Maplewood Bank & Trust Co: repossessed	3.11.69/70
			Sisk Aviation Activities, St. Louis MO	14.1.70
			Harry B. Combs, Billings-Logan MT	71/72
			Merdel Inc	75
			Air International Inc, Houston TX	4.1.78/82
			struck-off USCR	24.9.82
			73SF, N74SF, N75SF & N176SF in row at Wallace NC 4.69 Stevens & Co;	1, all
BA-259	E18S	N39L	Norman Larson Co, Van Nuys CA	19.4.57/58
DU-509	L 100	INUUL	Charles A. Krause Milling Co, Milwaukee WI	12.58/65
			Wiles-Holloway Inc, Baton Rouge LA	
				23.3.66/67
	Volpar Turbo 18		Volpar Inc, Van Nuys CA (Volpar trigear installed, conversion to <i>Volpar Turbo 18</i> completed 17.7.67)	13.3.67/68
	10100 10		op: Ransome Air/ Allegheny Commuter, Philadelphia PA	67
			minor damage, elevator tab separated in flight near	00.0.07
	Mala		Baltimore-Friendship MD	20.8.67
	Volpar		(further converted 9.68 to Volpar Turboliner:	

Turboliner		81.5" fuse. stretch, ventral fin)	
	N1031B (2	Mack Trucks Inc, Allentown PA	26.9.68/74
	N139PM	Pilgrim Airlines, New London CT: delivered	27.3.74/78
		Perkiomen Airways, Reading PA	22.4.78
		Supreme Aviation, Belleville MI	11.78/84
		op: Connie Kalitta Services, Willow Run MI	79
		Supreme Machine Products Inc, Rockford IL	7.84
		Supreme Aviation, Belleville MI	9.85/91
		Atorie Air, El Paso TX:	
		sale documentation not completed	.85
		struck-off USCR	9.12.93
	XA-SMC	Aero Juarez SA de CV, Chihuahua	12.93
		sold to USA, struck-off Mexican Register	13.7.98
	N122GS	Dixie Aviation Enterprises LLC, Troy MI, Gallatin TN	28.8.98/20

Pilgrim Airlines details: see Beech 18 by Robert Parmerter p.391;

N39L accident report 20.8.67 Ransome AIr;

N1031B noted Washington-DCA 30.9.70;

N139PM noted Detroit-Willow Run MI 23.9.79 turbine trigear, in Butler hangar;

N139PM noted Columbus IN 27.3.80 Volpar Turboliner, Supreme Aviation, still in Pilgrim Airlines scheme but no titles;

N139PM noted Tucson AZ 9.11.81;

N139PM noted Indianapolis IN 7.9.84 Supreme Aviation, Willow Run, Volpar freighter;

N122GS noted El Paso TX 23.2.01 all white, not titles, in service;

N122GS noted El Paso TX 29.10.05 Dixie Aviation, active; N122GS noted El Paso TX 10.8.08, in service, all white, freighter, "BTZA630C" on fuselage; N122GS noited El Paso TX 4.8.15;

BA-260	E18S	N38W (1	Ohio Aviation Co, Dayton OH: CofA issued	26.3.57/60
			H. B. Layne Contractor Inc, Springfield OH	30.9.60/63
			Graubart Aviation, Valparaiso IN	10.63/66
		N616T (2	Duncan Beechcraft Inc, Omaha NE	21.7.66/67
		•	Iseman Corp, Sioux Falls SD	2.3.67/69
			Victor E. Katt, Chester IL	12.69/70
			Maples Aviation Co, Vichy MO	12.8.71/78
			William R. Sandlin/ Sandlin Flying Service, Harlingen TX	12.78/88
			William R. Sandlin, Harlingen TX	10.88/05
		N5001T (2	William R. Sandlin, Harlingen TX	3.11.05/14
		•	struck-off USCR	29.10.14

N616T noted Wichita KS 27.7.71;

N616T noted Kansas City-Fairfax MO 3.6.76;

BA-261	E18S	N69A	Atlantic Aviation Corp: CofA issued	1.4.57
	-9700		E. I. duPont de Nemours & Co, Wilmington DE	3.7.57/65
			Beverly Agency Inc, Chicago IL	29.1.66/70
			Isd: Modern Welding Co	28.2.66/70
		N69AB	Omni Investment Corp	6.2.70
			Fidelity Properties Inc., Northbrook IL	70
			Fred L. Irwin	10.9.70/75
			(high density pax seating installed 9.70)	
			op: Chicago & Southern Airlines, Chicago IL	71
			(cargo floor installed 4.74)	
			Semo Aviation Inc, Malden MO	25.3.75/78
			(cockpit emergency hatch installed 4.77,	
			G18S cab and G18S windshield fitted)	
			J. D. Enterprises, Harlingen TX	20.9.78/82
			crashed during Mexican electrical goods smuggling ops.,	
			reportedly shot down by ground fire	c81
			no owner contact with FAA since 1982: struck-off USCR	13.11.14

Further details: see Beech 18 by Robert Parmerter p.338;

N69AB noted Chicago-O'Hare 13.6.71 Chicago & Southern (no titles): freighter: G18S style windshield & skylight;

BA-262	E18S	N76A	Atlantic Aviation Corp: CofA issued	8.4.57
	-9700		L. G. deFelice & Sons Inc, North Haven CT	10.4.57/63
			Ridge Associates Inc, Flint MI	4.11.63/65
			Carrier Service Corp, Flint MI	11.65/74
			Frederick B. Annas/ Annas Airways	10.74/83
			Voight Implement Co Inc, Houston TX: USCR	13.3.83/90
			impounded Haiti due carrying marijuana	c83
			(to FA Haiti as 1279)	
			(retired, parked at Port-au-Prince, Haiti 92/94)	
		HH-DWM	Haiti Aviation, Port-au-Prince	94/98
			(restored at Port-au-Prince, flown 95-97,	
			ferried to Miami FL c98 for resale, parked Opa Locka 99)	
		N76A	Llisel M. Espego, Miami FL	13.4.00
			Lauren C. Dates, Red Creek NY Twin Bitch	29.8.01/05
			reg pending, Newnan GA: USCR	10/11
			Dynamic Avlease Inc, Bridgewater VA	6.6.13/20

N76A noted Pontiac MI 9.80, plate BA-262;

HH-DWM noted Santo Domingo-Hererra DR 20.5.94, plate BA-262: ex FA Haiti markings;

HH-DWM noted Port-au-Prince, Haiti 16.11.96 in service, civil scheme, "..i Aviation"; HH-DWM noted Opa Locka FL 17.4.99 civil scheme no titles; Opa Locka 4.8.99 N76A at Oshkosh 23.7.02 plate BA-262 built 4.57, plate -9700 mods, name "Twin Bitch";

BA-263	E18S	N110WB	built	.57
			Williams Bros Co, Tulsa OK	63
			Fabick Machinery Co, Marion IL	64
			crashed, destroyed by fire, near Knoxville TN	21.3.64
BA-264	E18S	N1525H	built	.57
	trigear		J. L. Gidwitz/ Analco Services Inc, Eagle River WI	63/64
	Ü	N417R	Modern Aero Sales, Dallas-Red Bird TX	.66
			op: Command Airways, Dutchess Country Airport,	
			Wappinger Falls NY	67/68
			emergency landing New York-JFK, no damage	26.12.67
			KGM Leasing Corp, Wappingers Falls NY	69/70
			Gilley Airways, Hartsville SC	18.2.71
			crashed destroyed during forced landing, Milford NY	29.7.71
	N417R a	ccident report	Command Airways titles, trigear; 29.7.71: Gilley Airways; forced landing off airport during rd-Westville on night mail flight, struck trees, 2 hurt;	
BA-265	E18S	N52N	built	.57
			Ball Bros Co Inc, Muncie IN	63/66
		N1052N	Andrew C. Ortner, Wakeman OH	20.2.68/76
			op: Ortner Air Services, Wakeman OH	75/76

tailgear collapsed landing, Columbus OH 26.4.75 crashed destroyed near Covington TN 1.9.76

N1052N accident report 26.4.75: Ortner Air Services, flight Cleveland to Columbus OH,

N1052N accident report 26.4.75: Ortner Air Services, flight Cleveland to Columbus OH, left tyre burst, swerved, tailwheel failed,12.37am; N1052N noited Wakeman-Ortner Field OH 25.5.76, no titles;

N1052N accident report 1.9.76: Ortner Air Services, flight Wakeman OH to Memphis TN crashed dest, 2 crew killed, total destruction, 10.40pm, reason undetermined;

BA-266	E18S U45		FA Brasileira as U45 FAB 2880	.57
BA-267	E18S	N85D	Youngstown Airways/ Lease Air, Youngstown OH	.57
			Adams Aircraft Sales, Walls MS	63/64
		N8511	John H. Hill, Dallas TX	66
			Fultz Oil Co, Graham TX	69
			Maurice Ray Smith, Midland TX	70/72
			Wilfredo E. Otero, Guaynabo, Puerto Rico crashed Nevis, Puerto Rico	15.11.72/75 15.10.75

BA-268	E18S	F-OAXI	SA Aerotechnique, Alger (delivered via Prestwick 4.5.57)	30.9.57/64
			struck-off Reguisert as destroyed	6.1.64
	F-OAXI r	noted Prestwic	ck 4.5.57 reported on delivery to Aerotec;	
BA-269	E18S	N61K	Piedmont Aviation, Winston Salem NC	63
B/ ( 200	2100	110111	Titmus Optical Co, Petersburg VA	64/66
			Arlington Real Estate & Equipment Leasing,	
			Arlington TX	69/72
			Apollo Airways, Detroit-City Airport MI	17.4.75/81
			op: Gelco Courier Services, Chicago IL	79/81
			struck-off USCR	10.81
	N61K no	ted 24.5.76 D	etroit-City MI, no titles;	
BA-270	E18S	N19Y (1	built	.57
		N219Y	Robert C. Watson, Lewistown PA	63/66
			landed gear-up after takeoff with frost on wings,	
			Reedsville PA	27.10.66
			George Sisk/ Orion Airways, St. Louis MO	68/69
			Maplewood Bank & Trust Co: repossessed	3.11.69/70
			Sisk Aviation Activities, St Louis MO	14.1.70
			Golden Eagle Aviation	.70 71/72
			Skyway Aviation, Fort Leonardwood MO Karl Knight, Miami FL	18.5.77/81
			struck-off USCR	10.81
			Struck-off Ocore	10.01
BA-271	E18S	N39T	Currey Sanders Aircraft Co: CofA issued	24.4.57
			Texas Eastern Transmission Corp, Shreveport LA	29.4.57/66
		N3971	Clayton Specialties Inc, Corpus Christi TX	3.6.66/68
			S. W. Sisk/ Orion Airways, St Louis MO	24.6.68/69
			Maplewood Bank & Trust Co: repossessed	3.11.69/70
			Sisk Aviation Activities, St Louis MO	14.1.70
			McGhee Aviation	10.70/71
			Skyway Aviation/ Skyway Airlines, Ft Leonard Wood MO Nevada Aircraft Leasing Corp, Carson City NV	4.71/80 4.4.80/12
			struck-off USCR	14.11.12
			Struck-off Ocore	14.11.12
BA-272	E18S	N234AP	APCO Oil Co, Oklahoma City OK	63/66
			Smyer Aircraft Co/ Smyer Commuter Airlines,	00/70
			Arkansas City KS	69/72
			crashed destroyed, engine fire in flight, wing broke away, Winfield KS	3.6.72
	N234AP	accident repo	rt 3.6.72: Smyer Aircraft, flight Arkansas City to White Plains	s NY 9.30am, 2k;
BA-273	E18S	N53N	Beech Aircraft Corp, Wichita KS	9.5.57/59
			Ohio Aviation Co, Dayton OH	19.2.59
			(CofA issued 19.2.59) Ohio Oil Co/ Marathon Oil Co, Findlay OH	23.2.59/65
			Youngstown Cartage Co, Youngstown OH	22.4.65
		N825YC	Youngstown Cartage Co, Youngstown OH	12.8.65/66
			Reeder Flying Service, Twin Falls ID	24.6.66/71
			(smoke spotters hatch behind door fitted 6.66;	- 3 <del>-1</del> 1-1
			converted to smoke-jumping configuration for USFS	6.67
			H. M. Newhall & Co	6.11.71/73
			(cabin cargo floor installed 11.72)	
			Vanpac Carriers Inc, Richmond CA	27.2.74/76
			D. L. McEwen & Harold Smith, Las Vegas NV	12.76/79
			Louis W. Stallings	20.2.79/81
			Southwind Inc: documentation not completed	4.6.81
			Bob Wood/ Wood Flying Service, Laredo TX	82
			sale reported: USCR	23.3.88/91

N825YC noted Bakersfield-Meadows Field 20.4.72;

N825YC noted Oakland CA 5.74 "Vanpac Carriers Inc" titles, tailwheel;

N825YC noted Oakland CA 19.9.75;

N825YC noted Tulsa OK 6.80, tailwheel, i/s

N825YC reported crashed into sea, South Caicos Island 5.11.79: but not in NTSB list;

BA-274	E18S	F-OAXJ	Ste Aerotechnique, Alger	30.9.57
			(delivered via Prestwick 12.5.57)	
		F-BLLN	Escadrille Mercure, Paris-Le Bourget	14.6.63/71
			fate unknown, struck-off Register in clean-up	8.9.83
	<u>F-OAXJ</u> r	oted Paris-Le	dge 2.5.63, carrying the Aga Khan; Bourget 14.10.67 (confirmed) Bourget 71, reported based there;	
3A-275	E18S	N227	Tulsair Distributors Inc, Tulsa OK: CofA issued	9.5.57
	-9700		Petrolite Corp, St Louis MO	29.5.57/70
		N2279 (2	Capitol Aviation, Springfield IL	12.70/71
		(_	tailgear failed during landing, Muskogee OK	30.4.71
			Sunco Manufacturing Co, Muskogee OK	11.71/80
			Stevenson Aviation	24.9.80
			Oklahoma Aircraft Corp, Yukon OK	.81
			Thomas M. Hajecate	2.81/84
			Charles H. Midkiff, San Antonio TX	17.9.84/85
		N10FM	Foy P. Midkiff, San Antonio TX	1.2.85/90
		IN IOI IVI	Thomas Migel, St Cloud FL	11.90/91
		N233TM	Thomas Migel, St Cloud FL Thomas Migel, St Cloud FL	
		INZ 33 I IVI	Discovery Air, San Jose CA	12.3.91/96 20.5.96
			Michael T. Warn, Milwaukie OR	8.4.98
		N63MW		
		INOSIVIVV	Michael T. Warn, Milwaukie OR	10.98/99
		NI (OD) (	Management West LLC, Aurora OR	20.3.99/00
		N18BY	18BY LLC, Hood River OR	8.6.00/20
		N18BY	Western Antique Aeroplane and Automobile Museum,	
			Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"	14/18
		ited Toronto C	Western Antique Aeroplane and Automobile Museum,	
BA-276		ited Toronto C	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  ONT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;	
BA-276	N18BY at	nted Toronto C Beech Fly-In,	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  ONT 3.5.79 Sunco Manufacturing;	14/18
BA-276	N18BY at	nted Toronto C Beech Fly-In,	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  ONT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp	14/18
3A-276	N18BY at	nted Toronto C Beech Fly-In,	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  ONT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp Texaco Oil Corp, New York NY	14/18 14.5.57 7.6.57/62
BA-276	N18BY at	nted Toronto C Beech Fly-In, N31XL N1626	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  ONT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp	14/18 14.5.57 7.6.57/62 19.4.62 6.8.62/63
3A-276	N18BY at E18S -9700	oted Toronto C Beech Fly-In, N31XL	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  INT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp Texaco Oil Corp, New York NY Texaco Oil Corp/Texaco Inc, New York NY Penn-Aire Aviation Ferro Stamping Co/ Ferro Manufacturing Corp, Detroit N	14/18 14.5.57 7.6.57/62 19.4.62 6.8.62/63 28.5.63
3A-276	N18BY at	nted Toronto C Beech Fly-In, N31XL N1626 N1626B	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  INT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp Texaco Oil Corp, New York NY Texaco Oil Corp/Texaco Inc, New York NY Penn-Aire Aviation Ferro Stamping Co/ Ferro Manufacturing Corp, Detroit N (Volpar trigear installed 1.64)	14/18 14.5.57 7.6.57/62 19.4.62 6.8.62/63 28.5.63 All 23.1.64/73
3A-276	N18BY at E18S -9700	nted Toronto C Beech Fly-In, N31XL N1626 N1626B	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  ONT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp Texaco Oil Corp, New York NY Texaco Oil Corp/Texaco Inc, New York NY Penn-Aire Aviation Ferro Stamping Co/ Ferro Manufacturing Corp, Detroit N (Volpar trigear installed 1.64) gear collapsed landing, Detroit-City MI	14/18 14.5.57 7.6.57/62 19.4.62 6.8.62/63 28.5.63 //I 23.1.64/73 9.10.68
3A-276	N18BY at E18S -9700	nted Toronto C Beech Fly-In, N31XL N1626 N1626B	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  INT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp Texaco Oil Corp, New York NY Texaco Oil Corp/Texaco Inc, New York NY Penn-Aire Aviation Ferro Stamping Co/ Ferro Manufacturing Corp, Detroit N (Volpar trigear installed 1.64) gear collapsed landing, Detroit-City MI Kingston Aero Lake Airport	14/18 14.5.57 7.6.57/62 19.4.62 6.8.62/63 28.5.63 //I 23.1.64/73 9.10.68 13.3.73/74
3A-276	N18BY at E18S -9700	N31XL N1626 N162F	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  ONT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp Texaco Oil Corp, New York NY Texaco Oil Corp/Texaco Inc, New York NY Penn-Aire Aviation Ferro Stamping Co/ Ferro Manufacturing Corp, Detroit N (Volpar trigear installed 1.64) gear collapsed landing, Detroit-City MI Kingston Aero Lake Airport A. P. St. Philip Inc, Tampa FL	14.5.57 7.6.57/62 19.4.62 6.8.62/63 28.5.63 /II 23.1.64/73 9.10.68 13.3.73/74 11.75/76
3A-276	N18BY at E18S -9700	nted Toronto C Beech Fly-In, N31XL N1626 N1626B	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  ONT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp Texaco Oil Corp, New York NY Texaco Oil Corp/Texaco Inc, New York NY Penn-Aire Aviation Ferro Stamping Co/ Ferro Manufacturing Corp, Detroit N (Volpar trigear installed 1.64) gear collapsed landing, Detroit-City MI Kingston Aero Lake Airport A. P. St. Philip Inc, Tampa FL A. P. St. Philip Inc, Tampa FL	14.5.57 7.6.57/62 19.4.62 6.8.62/63 28.5.63 //I 23.1.64/73 9.10.68 13.3.73/74 11.75/76 25.5.76/78
3A-276	N18BY at E18S -9700	N31XL N1626 N162F	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  ONT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp Texaco Oil Corp, New York NY Texaco Oil Corp/Texaco Inc, New York NY Penn-Aire Aviation Ferro Stamping Co/ Ferro Manufacturing Corp, Detroit N (Volpar trigear installed 1.64) gear collapsed landing, Detroit-City MI Kingston Aero Lake Airport A. P. St. Philip Inc, Tampa FL A. P. St. Philip Inc, Tampa FL Panorama Air Tour, Honolulu HI (fleet #63)	14.5.57 7.6.57/62 19.4.62 6.8.62/63 28.5.63 //I 23.1.64/73 9.10.68 13.3.73/74 11.75/76 25.5.76/78 30.5.78/83
3A-276	N18BY at E18S -9700	N31XL N1626 N162F	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  ONT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp Texaco Oil Corp, New York NY Texaco Oil Corp/Texaco Inc, New York NY Penn-Aire Aviation Ferro Stamping Co/ Ferro Manufacturing Corp, Detroit N (Volpar trigear installed 1.64) gear collapsed landing, Detroit-City MI Kingston Aero Lake Airport A. P. St. Philip Inc, Tampa FL A. P. St. Philip Inc, Tampa FL Panorama Air Tour, Honolulu HI (fleet #63) Ray Berney/ AirTour Acquisition Corp, Honolulu HI	14.5.57 7.6.57/62 19.4.62 6.8.62/63 28.5.63 //I 23.1.64/73 9.10.68 13.3.73/74 11.75/76 25.5.76/78
3A-276	N18BY at E18S -9700	N31XL N1626 N162F	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  ONT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp Texaco Oil Corp, New York NY Texaco Oil Corp/Texaco Inc, New York NY Penn-Aire Aviation Ferro Stamping Co/ Ferro Manufacturing Corp, Detroit N (Volpar trigear installed 1.64) gear collapsed landing, Detroit-City MI Kingston Aero Lake Airport A. P. St. Philip Inc, Tampa FL A. P. St. Philip Inc, Tampa FL Panorama Air Tour, Honolulu HI (fleet #63) Ray Berney/ AirTour Acquisition Corp, Honolulu HI minor damage runway collision on takeoff with	14.5.57 7.6.57/62 19.4.62 6.8.62/63 28.5.63 /II 23.1.64/73 9.10.68 13.3.73/74 11.75/76 25.5.76/78 30.5.78/83 26.7.82/83
BA-276	N18BY at E18S -9700	N31XL N1626 N162F	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  ONT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp Texaco Oil Corp, New York NY Texaco Oil Corp/Texaco Inc, New York NY Penn-Aire Aviation Ferro Stamping Co/ Ferro Manufacturing Corp, Detroit N (Volpar trigear installed 1.64) gear collapsed landing, Detroit-City MI Kingston Aero Lake Airport A. P. St. Philip Inc, Tampa FL A. P. St. Philip Inc, Tampa FL Panorama Air Tour, Honolulu HI (fleet #63) Ray Berney/ AirTour Acquisition Corp, Honolulu HI	14.5.57 7.6.57/62 19.4.62 6.8.62/63 28.5.63 //I 23.1.64/73 9.10.68 13.3.73/74 11.75/76 25.5.76/78 30.5.78/83
BA-276	N18BY at E18S -9700	N31XL N1626 N162F	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  ONT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp Texaco Oil Corp, New York NY Texaco Oil Corp/Texaco Inc, New York NY Penn-Aire Aviation Ferro Stamping Co/ Ferro Manufacturing Corp, Detroit N (Volpar trigear installed 1.64) gear collapsed landing, Detroit-City MI Kingston Aero Lake Airport A. P. St. Philip Inc, Tampa FL A. P. St. Philip Inc, Tampa FL Panorama Air Tour, Honolulu HI (fleet #63) Ray Berney/ AirTour Acquisition Corp, Honolulu HI minor damage runway collision on takeoff with	14.5.57 7.6.57/62 19.4.62 6.8.62/63 28.5.63 /II 23.1.64/73 9.10.68 13.3.73/74 11.75/76 25.5.76/78 30.5.78/83 26.7.82/83
BA-276	N18BY at E18S -9700	N31XL N1626 N162F	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  ONT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp Texaco Oil Corp, New York NY Texaco Oil Corp/Texaco Inc, New York NY Penn-Aire Aviation Ferro Stamping Co/ Ferro Manufacturing Corp, Detroit N (Volpar trigear installed 1.64) gear collapsed landing, Detroit-City MI Kingston Aero Lake Airport A. P. St. Philip Inc, Tampa FL A. P. St. Philip Inc, Tampa FL Panorama Air Tour, Honolulu HI (fleet #63) Ray Berney/ AirTour Acquisition Corp, Honolulu HI minor damage runway collision on takeoff with N888M in a flight of 5 scenic Beech 18s, Kahalui HI Robert A. Justman/ Hawaiian Sky Tour, Honolulu HI	14/18 14.5.57 7.6.57/62 19.4.62 6.8.62/63 28.5.63 VI 23.1.64/73 9.10.68 13.3.73/74 11.75/76 25.5.76/78 30.5.78/83 26.7.82/83
3A-276	N18BY at E18S -9700	N31XL N1626 N1626B N162F N162SP	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  ONT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp Texaco Oil Corp, New York NY Texaco Oil Corp/Texaco Inc, New York NY Penn-Aire Aviation Ferro Stamping Co/ Ferro Manufacturing Corp, Detroit N (Volpar trigear installed 1.64) gear collapsed landing, Detroit-City MI Kingston Aero Lake Airport A. P. St. Philip Inc, Tampa FL A. P. St. Philip Inc, Tampa FL Panorama Air Tour, Honolulu HI (fleet #63) Ray Berney/ AirTour Acquisition Corp, Honolulu HI minor damage runway collision on takeoff with N888M in a flight of 5 scenic Beech 18s, Kahalui HI Robert A. Justman/ Hawaiian Sky Tour, Honolulu HI Hawaiian Sky Tour, Honolulu HI Tasha	14/18 14.5.57 7.6.57/62 19.4.62 6.8.62/63 28.5.63 VI 23.1.64/73 9.10.68 13.3.73/74 11.75/76 25.5.76/78 30.5.78/83 26.7.82/83 23.7.83 12.83/84 5.84/85
3A-276	N18BY at E18S -9700	N31XL N1626 N1626B N162F N162SP	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  ONT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp Texaco Oil Corp, New York NY Texaco Oil Corp/Texaco Inc, New York NY Penn-Aire Aviation Ferro Stamping Co/ Ferro Manufacturing Corp, Detroit N (Volpar trigear installed 1.64) gear collapsed landing, Detroit-City MI Kingston Aero Lake Airport A. P. St. Philip Inc, Tampa FL A. P. St. Philip Inc, Tampa FL Panorama Air Tour, Honolulu HI (fleet #63) Ray Berney/ AirTour Acquisition Corp, Honolulu HI minor damage runway collision on takeoff with N888M in a flight of 5 scenic Beech 18s, Kahalui HI Robert A. Justman/ Hawaiian Sky Tour, Honolulu HI Hawaiian Sky Tour, Honolulu HI Tasha Big Island Air, Kailua-Kona HI	14.5.57 7.6.57/62 19.4.62 6.8.62/63 28.5.63 /II 23.1.64/73 9.10.68 13.3.73/74 11.75/76 25.5.76/78 30.5.78/83 26.7.82/83 23.7.83 12.83/84 5.84/85 5.4.85/86
3A-276	N18BY at E18S -9700	N31XL N1626 N1626B N162F N162SP	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  ONT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp Texaco Oil Corp, New York NY Texaco Oil Corp/Texaco Inc, New York NY Penn-Aire Aviation Ferro Stamping Co/ Ferro Manufacturing Corp, Detroit N (Volpar trigear installed 1.64) gear collapsed landing, Detroit-City MI Kingston Aero Lake Airport A. P. St. Philip Inc, Tampa FL A. P. St. Philip Inc, Tampa FL Panorama Air Tour, Honolulu HI (fleet #63) Ray Berney/ AirTour Acquisition Corp, Honolulu HI minor damage runway collision on takeoff with N888M in a flight of 5 scenic Beech 18s, Kahalui HI Robert A. Justman/ Hawaiian Sky Tour, Honolulu HI Hawaiian Sky Tour, Honolulu HI Tasha Big Island Air, Kailua-Kona HI Lani Bird Inc/ Scenic Air Tour, Honolulu HI	14/18 14.5.57 7.6.57/62 19.4.62 6.8.62/63 28.5.63 VI 23.1.64/73 9.10.68 13.3.73/74 11.75/76 25.5.76/78 30.5.78/83 26.7.82/83 23.7.83 12.83/84 5.84/85
3A-276	N18BY at E18S -9700	N31XL N1626 N1626B N162F N162SP	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  ONT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp Texaco Oil Corp, New York NY Texaco Oil Corp/Texaco Inc, New York NY Penn-Aire Aviation Ferro Stamping Co/ Ferro Manufacturing Corp, Detroit N (Volpar trigear installed 1.64) gear collapsed landing, Detroit-City MI Kingston Aero Lake Airport A. P. St. Philip Inc, Tampa FL A. P. St. Philip Inc, Tampa FL Panorama Air Tour, Honolulu HI (fleet #63) Ray Berney/ AirTour Acquisition Corp, Honolulu HI minor damage runway collision on takeoff with N888M in a flight of 5 scenic Beech 18s, Kahalui HI Robert A. Justman/ Hawaiian Sky Tour, Honolulu HI Hawaiian Sky Tour, Honolulu HI Tasha Big Island Air, Kailua-Kona HI	14.5.57 7.6.57/62 19.4.62 6.8.62/63 28.5.63 /II 23.1.64/73 9.10.68 13.3.73/74 11.75/76 25.5.76/78 30.5.78/83 26.7.82/83 23.7.83 12.83/84 5.84/85 5.4.85/86
A-276	N18BY at E18S -9700	N31XL N1626 N1626B N162F N162SP	Western Antique Aeroplane and Automobile Museum, Hood River OR: displ. as "NC18BY"  ONT 3.5.79 Sunco Manufacturing; Tullahoma TN 18.10.00;  J. R. Gray Co, Dallas TX TXL Oil Corp Texaco Oil Corp, New York NY Texaco Oil Corp/Texaco Inc, New York NY Penn-Aire Aviation Ferro Stamping Co/ Ferro Manufacturing Corp, Detroit N (Volpar trigear installed 1.64) gear collapsed landing, Detroit-City MI Kingston Aero Lake Airport A. P. St. Philip Inc, Tampa FL A. P. St. Philip Inc, Tampa FL Panorama Air Tour, Honolulu HI (fleet #63) Ray Berney/ AirTour Acquisition Corp, Honolulu HI minor damage runway collision on takeoff with N888M in a flight of 5 scenic Beech 18s, Kahalui HI Robert A. Justman/ Hawaiian Sky Tour, Honolulu HI Hawaiian Sky Tour, Honolulu HI Tasha Big Island Air, Kailua-Kona HI Lani Bird Inc/ Scenic Air Tour, Honolulu HI	14/18 14.5.57 7.6.57/62 19.4.62 6.8.62/63 28.5.63 VI 23.1.64/73 9.10.68 13.3.73/74 11.75/76 25.5.76/78 30.5.78/83 26.7.82/83 23.7.83 12.83/84 5.84/85 5.4.85/86

N162F noted Toronto ONT c2.65 trigear;

N162SP noted Honolulu 5.9.79 Panorama AT, trigear, fleet #63;

N162SP noted Honolulu 12.11.79;

N162SP noted Honolulu 9.80 "Panorama Air Tour" fleet #63;

N162SP noted Honolulu 23.8.81 "Panorama Air Tour #63";

N162SP noted Hilo 26.8.81 "Panorama AT" in Beech 18 tourist formation;

N162SP accident report 23.7.83: Panorama Airtour: flight of 5 Beech 18s with callsigns "Lani 6" to "Lani 10" on inter-island tour, collided on takeoff, 1 minor injury & 19 uninjured in both aircraft; N162SP noted Honolulu 9.83 "Panorama Air Tour, trigear, fleet #62, plate BA-276; N162SP in Panorama Air fleet list as at 15.11.83: BA-276 TT 10,610 hrs, fleet #63; N692T noted Honolulu 22.10.88 derelict, Scenic Air Tour; N692T noted Honolulu 6.10.91 derelict, Scenic Air Tour ramp, stripped for parts;

BA-277	E18S	N41LZ (2	Lubrizol Corp, Wickliffe OH	.57/64
		N418Z	Northern Bank & Trust, Little Rock AR	66/69
			First Arkansas Leasing Corp, Little Rock AR	70/72
			Catlin Aviation Co, Oklahoma City OK	8.8.72
			sold to Canada, struck-off USCR	8.8.72
		CF-STA	St Andrews Airways Ltd, Winnipeg MAN	8.72/74
			dest. forced landing near Cantin Lake MAN	9.1.74
BA-278	E18S	CF-CEL	Gutta Percha & Rubber Ltd, Toronto ONT	.57
	-9700		Stuart Brothers Co Ltd	62
		N9438H	Compass Exploration Inc, Denver CO	12.62/63
		(N64CE)	ntu: Compass Exploration Inc, Denver CO	3.63
			Compass Exploration Inc, Denver CO	3.63
		N130L	The Lewis Grocer Co, Indianola MS	9.12.63/68
			Gibbs Flying Service/ Gibbs Lease Air Inc,	
			San Diego-Montgomery Field CA	28.5.68/76
			op: Bank Air, San Diego CA	68/70
			Aire Sales & Service	15.9.76/77
			Pope Valley Parachute Ranch	7.77/78
			George C. Holberton, Medford OR	23.1.78
			M. Corley Tedder/ CMT Leasing Co, Texarkana TX (cargo floor, cargo door & crew door fitted 12.78)	18.8.78/81
			lsd: ABC Airlines Inc, Dallas-DFW TX	79/82
			James L. Hudson, Mesquite TX	24.4.81/93
			op: ABC Airlines, Dallas-DFW TX	.81/84
			damaged night taxying collision with D18S N80017,	
			Dallas-Fort Worth TX	17.3.83
			Howard Y. Sigler	4.1.93
			sale reported, Dallas TX	95/05
			(hulk in car wreckers yard, Mesquite TX 98/03)	20,00
			Velvet A. Carroll, Heath TX	19.4.05/12
			struck-off USCR	21.6.12

N130L noted Visalia CA 21.4.72;

N130L noted Fort Worth TX 1.12.79 ABC Airlines;

noted Dallas-FTW 7.11.81 at freight terminal "ABC Airlines" titles, freight door; N130L accident report 17.3.83: ABC Airlines: just landed at night from Lubbock TX, struck ABC Airlines Beech 18 N130L stopped on taxiway just landed from Amarillo TX; N130L noted in car breakers yard, Dallas-Mesquite TX 10.4.98 with 5 other Beech 18s; N130L noted 6.8.98 in contractors yard Lawson Road near Scyene Road, Mesquite;

N130L noted 3.8.02 on property 106 Lawson Road near Sceyene Road, Mesquite with other Beech18 hulks, reported that all Jim Hudson aircraft will shortly be sold by his estate; N130L noted Mesquite 9.5.03 in scrapyard near airport with other Twin beech hulks;

BA-279	E18S	N62V	built	.57
			Mitchell Aero Inc, Milwaukee WI	63/64
			Great Plains Water Co, Austin TX	66
			S. W. Sisk/ Orion Airways, St. Louis MO	68/69
			Sisk Aviation Activities, St Louis MO	70
			James E. Boyett, East Point GA	72
			Precision Valley Aviation, Springfield VT	75/82
			damaged groundloop landing, Springfield VT	9.12.75
			Air Cargo Inc, McAllen TX	22.10.82/83
			sold to Mexico, struck-off USCR	25.1.83

N62V noted Dallas-Love TX 21.4.66;

N62V accident report 9.12.75: Precision Valley Aviation, flight to Boston MA, groundloop when returned due brake mechanical problem on takeoff, struck object, pilot unhurt, 7pm; N62V noted Boston MA 9.80 "Precision";

#### N62V noted McAllen TX 7.10.82;

BA-280	E18S	N43G	built	.57
		XB-REP	Roberto M. Lopez, Mexicali	93
BA-281	E18S	N23Y	Atlantic Aviation Corp: CofA issued	24.5.57
	-9700		Food Fair Stores Inc, Philadelphia PA	18.7.57/66
		N231H	National Financing Inc, Wilmington DE	16.8.66/67
			Sebastaino Cannavo, Lester PA	8.12.67/71
			Call Air Transport, Goshen NY	30.3.71/72
			Belvon Aircraft Leasing Inc	14.3.72/76
			(Beech cargo door installed 3.72)	
			North American Publishing Co	5.8.76/77
			O. M. Richter	14.6.77
			I. D. Hill Co: sale documentation not completed	.77
			US Customs Service: seized	.78/80
			Commodities Recovery Corp	11.12.80
			K & K Aircraft Inc, Bridgewater VA	12.80/81
			Jorge L. Ibern, Guaynabo, Puerto Rico	23.4.81
			Raul Morales, Guaynabo, Puerto Rico	24.7.81
			Ramon Juan Alvarez, Miami FL	6.10.81/82
			Sergio B. Pantosa, Dania FL	29.6.82/84
			Aircraft Rebuilders, Opa Locka FL	12.84/86
			Harmer Inc, Miami FL	1.10.86/89
			Santee Aircraft, Manning SC	15.3.89/90
			James P. Ewing/ High Tech Classics, Fresno CA	16.2.90/93
			Matthew R. Barnet, Haleiwa HI	24.2.93/95
			Jerry H. Jackson, Mililani HI	11.95
			Kamaka Air Inc, Honolulu HI	6.3.98/19
			reg expired 31.10.19, struck-off USCR	31.1.20

N231H noted Tamiami FL 5.12.78

N231H noted Tamiami FL 11.87;

N231H noted Honolulu HI 26.2.01 all metallic, in service;

N231H noted Honolulu HI 26.8.01 fully painted "Kamaka Air" titles, tailwheel; N231H noted Honolulu 13.11.05 being painted for TV series "Lost" to be used in flying scene representing a Beech 18 wreck found in a tree, owned Kamaka Air;

N231H noted Honolulu 5.2.06 civil scheme no titles, at Kamaka Air hangar, with Tradewind & DC-3;

BA-282	E18S	N68V	Tulsair Distributors Inc, Tulsa OK	29.5.57
	-9700		Oklahoma Mississippi River Products Line Inc	17.6.57/59
			Sunray Mid-Continent Oil Co/ Sun Oil Co	19.2.59/61
			Lion Trailer Corp, La Crosse WI	7.11.61/68
			Gateway Aviation, La Crosse WI	10.68/70
	G18S cab		landed gear locked-up, La Crosse WI	5.2.69
			International Manufacturers & Representatives/ IMR Inc	15.5.70/75
			Bennett C. Pollard/ Midnight Air Express	4.12.75/76
			(cargo door & floor installed 1.76)	
			Blackhawk Airways, Janesville WI	1.7.76/84
			Richard J. Wixom, Janesville WI	11.10.84/91
			damaged by engine fire taxying, Janesville WI	20.4.85
			broken-up for parts: Beech cockpit cab installed in	
			N404T, wings to N929DV, tail to N103AF)	
			(owner report 1.91: aircraft destroyed or scrapped)	
			struck-off USCR	28.1.91

N68V accident report 5.2.69: Gateway Aviation, mechanical failure jammed gear; USCR70: reg pending, USCR72: not listed;

N68V photo mid 70s: bronze & white, windows, G18S cab, tailwheel, "Midnight" titles; N68V noted Cincinatti OH 3.84 "Blackhawk Airways" titles, tailwheel, G18S cab;

BA-283	E18S	N23R	Butler Airplane Sales	5.6.57/58
			Butler Co, Chicago IL	10.9.58/64
	-9700		(mods to E18S-9700 installed 7.59)	
			Theodore H. McNabb	10.5.64/65
			Chandler W. Drummond, Phoenix AZ	11.6.65/68

	Harry H. Webb, Shelburne VT	24.9.68/71
	Woodruff H. Griffin	11.2.72/73
	Hamilton Aviation, Hamilton OH	7.5.73/77
	Air Service Center Inc	15.4.77/79
	HoganAir Inc, Hamilton OH	1.7.79/86
N86HA	HoganAir Inc, Hamilton OH	12.8.80/86
N8627A (2		29.10.86
	The Eagle and the Hawks Inc, Middletown OH	1.11.86/94
	(cockpit exit hatch installed 4.87)	
	Miami Valley Aviation, Middletown OH	5.4.94/98
	The Eagle and the Hawks Inc, Middletown OH	29.5.98/06
	op: Miami Valley Aviation, Middletown OH	98/02
	Michael J. Hogan, Fruitland Park FL	11.7.06/20
	lsd: Stan Brock/ Remote Aera Medical Volunteer Corp,	
	Knoxville TN	.06/15

N8627A noted Middletown OH 2.92 no titles, tailwheel;

N8627A noted Middletown OH 30.8.97 no titles;

N8627A noted Middletown OH 22.7.98 no titles;

N8627A noted Bessemar AL 12.8.98 Miami Valley Aviation, Middletown OH, plate:

BA-283 built 6.57, another plate: -9700 conv. 7.59;

N8627A noted Middletown OH 6.8.99 Miami Valley Aviation;

N8627A noted Middletown OH 6.8.99 MVA, plate BA-283 built 6.57, -9700 conv 7.59;

N8627A noted Middletown OH 20.7.02 operated by Miami Valley Aviation;

N8627A noted Middletown OH 12.10.02 no titles;

N8627A noted Island Home TN 4.8.05 still in Miami Valley scheme but titles "Remote Area Medical" titles, pilot Stan Brock;

N8627A leased to Remote Aera Medical Volunteer Corp for \$1 per year for 15 years: takes medical assistance across USA and overseas offering medical help after disasters;

BA-284	E18S	N433AC	built	.57
			Plainsman Elevators Inc, Plainview TX	63/64
			Janson Industries Inc, Plainview TX	66
			Conquest Airways, San Juan, Puerto Rico	25.10.68
			crashed on takeoff, destroyed, St.Thomas USVI	6.12.68

N433AC accident report 6.12.68 Conquest Airways, stalled on takeoff St Thomas-Harry S.Truman,

11 on board, 3 k;

BA-285	E18S	N28X	built L. E. Dixon Co, Cleveland OH	.57 63
		N501W	Frank Sinatra, Palm Springs CA S. J. Groves & Sons Co, Minneapolis MN crashed destroyed, Johnson City NY	64 66/67 8.5.67
BA-286	E18S	N221H	built Beaumont Car Leasing Corp, Beaumont TX Air Lease Inc, Chicago-O'Hare IL Grand Forks Airmotive, Grand Forks ND forced landing gear-up off airport, due engine failure after takeoff, Detroit Lake MN Harold E. Roberts, Ivanhoe TX Herbert A. Hartley, Brownsville TX struck-off USCR	.57 63/64 66 69/70 1.6.70 79 22.8.79/82 8.11.82

accident report 1.6.70: operator Grand Forks Airmotive,

USCR72: not listed;

Probably the unidentified Beech 18 with "Grand Forks Airmotive" titles on roof in J.W.Duff Aircraft Co storage yard Denver CO 8.00;

BA-287	E18S	N51W	Ohio Aviation Co, Dayton OH	15.7.57
			Anchor Hocking Glass Corp	24.9.57/62
			Reading Aviation Service, Reading PA	1.10.62/73
			op: Suburban Airlines, Reading PA	72
			James T. Knight	13.4.73/76

(cargo floor installed 5.73)

Morey Wyman/ Wyman Pilot Service, Pontiac MI
op: Lafayette Aviation
crashed on takeoff, Youngstown OH
struck-off USCR, owner's request

10.1.76/98
85
18.7.85
8.10.98

N51W noted Reading PA 29.5.72 Suburban Airlines; N51W noted Pontiac MI 9.80 plate BA-287; accident report 18.7.85: operated by Lafayette Aviation;

BA-288	E18S	N45G	built	.57
		N448	R. Morgan, Corpus Christi TX	61/64
			H & F Ranch, Corpus Christi TX	66/70
		N4061L	H. C. Marks	71
			Biscayne Suffolk Associates, Miami FL	71/72
			International leasing Corp, Miami FL	22.11.72/73
			(del. to Ethiopia via Keflavik-Prestwick-Luton 4.10.73)	
		ET-AFE	Shebaland Air Service, Asmara, Ethiopia	10.9.73/75
			Ethiopian Government	17.5.75/87
			op: Admas Air Service, Addis Ababa	75/87
			crashed Wondo Tika Awassa Farm	8.4.87
	N4061L n	oted Opa Loc	ka FL 23.8.71;	
BA-289	E18S	N47G	Pacific Aircraft Sales Co: CofA issued	21.6.57
D/ ( 200	L100	11470	Georgia-Pacific Corp	28.6.57/59
			L. A. Johnson/ Rialto Co	6.11.59/60
			Pope & Talbot Inc, San Francisco CA	3.3.60/69
			George A. Pope, San Francisco CA	70/79
		XB-BPH	false registration: operated by drug dealer	c79
			d, owner arrested, San Jose de Cabo.	070
		cormodate	Southern Baja California, Mexico	c80
		(onen stora	age, Cabo San Lucas 80/92)	000
		(opon otor	Hacienda Publico Federal	17.3.89/91
			Francisco Jose Chavez Macias	91
			Banco Mercantil Del Norte: sales agent	91
		N47G	Westernair Inc, Albuquerque NM	1.10.91/92
			(ferried Cabo San Lucas to Van Nuys 29.3.92,	
			as XB-BPH, rebuilt at Van Nuys CA 92)	
			Brian L. Launder, Tulsa OK	9.10.92/20
				0

(note: N47G shown as N47D in 1961 USCR then reverted to N47G: no mention in FAA file)
"The Beech Eagle" article 3.92: N47G based Oakland CA as executive aircraft first 20 years, plush
4 leather seat cabin, sold c78 to drug runner who used it as personal transport with false reg
XB-BPH; engines overhaulled and interior retained, flew 120 hours with new owner until he took a
vacation at Cabo San Lucas, Mexico where he was arrested and aircraft confiscated by Mexican
authorities, parked in open at Cabo San Lucas airport near sea 80/91 when Dick Durand of
Westernair obtained title from Mexican Government, advertised "as is" in Trade-A-Plane; prepared

for ferry 3.92 by Matt Jackson/Airworks, Van Nuys CA who flew to Cabo in a Bonanza with a team from Van Nuys to Cabo 24.3.92, Lee Cameron provided metallised control surfaces already in Mexico to replace the rotted fabric surfaces, ferried 29.3.92 to Van Nuys as XB-BPH for complete restoration by Matt Jackson's Airworks;

N47G notd Madera CA 23.4.72;

N47G visited Beech Fly-In Tullahoma TN 13.10.95, plate BA-289;

N47G at Beech Fly-In Tullahoma TN 10.10.99 owned by Brian Launder OK;

N47G at Beech FlyIn Wichita KS 11.10.97, plate BA-289;

N47G noted Tucson AZ 9.02 executive scheme, in service, tailwheel;

N47G at Beech flyin Tullahoma TN 16.10.03;

-				
BA-290	E18S	N37T	Ohio Aviation Co, Dayton OH: CofA issued	28.6.57
			Thompson Products Inc/	
			Thempson Dome Wooldridge Foundation/	
			Thompson Ramo Wooldridge Foundation/	
			Space Technology Laboratories/ TRW Inc.	
			Space reclinology Laboratories/ Tixty Inc,	
			Redondo Beach CA. later Cleveland OH	28.6.57/74
			reduited beach on, later dieveland on	20.0.31/14

# N37TC Harry H. Delno/ Mission Airlines, Mojave CA 2.3.73/75

Burke Matthews, Austin TX: sale documentation not completed 30.1.75

N37T noted LAX 2.11.69, 19.5.70;

-				
BA-291	E18S	N2100	Butler Airplane Sales	3.7.57
	-9700		Danly Machine Specialties Inc	3.7.57/58
		N210Q	Sollitt Construction Co, South Bend IN	11.4.58/70
			Skystream Inc, Plymouth IN	20.1.70/71
			Coachmen Industries Inc, Middlebury IN	27.7.71/72
			John Crawford/ Airline Air Conditioning Co	2.11.72/73
			S. S. Airways Inc, Kansas City KS	8.2.74/82
			George D. Gandy, Lenaxa TX	4.5.82
			Verl Thompson, Springdale AR	11.82
			Verl Thompson, Springdale AR: restored to USCR	3.93
			Springdale Air Service, Springdale AR	15.6.95
			SCS Group Ltd, Springdale AR	13.9.95
			op: Springdale Air Service, Springdale AR	97
			Springdale Air Service, Springdale AR	13.7.98/99
			crashed Fort Smith AR	6.8.99
			Mosquito Bel Air, Greenville MS	9.11.00/01
			(conv. for spraying 10.00 by Crowley's Ridge Aviation,	
			Helena AR)	
			Vector Disease Control Inc, Waltham MA	5.3.02/06
			(mosquito spraying: subsidiary of Mosquito Bel Air)	
			Paul H. Bartlett, Marion NC	17.9.08/13
			Byron Rovey, La Grande OR	20.8.13/16
			Cascade Airways, Corvallis OR	23.8.17/20
			ouooudo / iii wayo, ooi vaiiio ort	20.0.17720

N210Q noted Kansas City-Fairfax 3.6.76; N210Q noted Memphis TN 8.97 Springdale Air Service; N210Q noted at Rockford IL 24.7.08, for sale at Courtesy Aircraft hangar; further details spraying: see Beech 18 by Robert Parmerter p.292;

BA-292	E18S	N2101	Butler Airplane Sales: CofA issued	11.7.57
			Danly Machine Specialties Inc	16.7.57/58
		N21011	Missouri State Highway Dept., Jefferson City MO	12.6.58/78
	-9700		(mods to E18S-9700 installed 6.61,	
			G18S type cockpit cab installed 10.61)	
			Welco Leasing Co	10.78/80
			(cabin cargo floor installed 11.78)	
			Louis W. Stallings	11.80/83
			op: Southwest Air Transport	83
			Delco Delp Corp	2.11.83
			Bahamas Customs Department: seized	26.4.84
			(found at Cistern Bay with a cocaine cargo 23.4.84)	
			Aviation One Inc, Cincinatti OH	20.8.64/65
			Nihon Kaisha Design Group	12.6.85
			J. M. DuFriend/ D & D Airepair, Perris CA	10.85/86
			Paralift Inc, Pasadena CA	8.6.86/88
			Auburn Flying Service, Auburn CA	1.88/93
			Native Village of Mekoryuk/	
			Bering Sea Reindeer Products, Mekoryuk AK	10.2.93/95
			Charles C. Bramel, Xenia OH	4.11.97/99
			op: Carolina Skysports, Louisburg NC	99
			Vee Jay Enterprises, Eaton OH	15.6.00/02
			Airplane Services Inc, Jay FL	4.2.03
			Frances T. Hess, Fayetteville GA	19.3.04/11
			K.R.Oddy Associates Inc, Orange Park FL	13/20

N21011 noted Green County OH 6.8.99 plate BA-292 built 7.57, another plate: converted to E18S-9700 6.61, owned Carolina Skysports, Louisburg NC, good condition; N21011 noted Middletown OH 20.7.02 plate BA-292: stored, all metallic: For Sale sign, Perris Valley Skydive & Skydive Indiana stickers inside cabin; N21011at Beech flyin Tullahoma TN 16.10.03;

N21011 at fly-in Lakeland FL 15.4.05 tailwheel; N21011 at fly-in Oshkosh 7.05 plate BA-292; N21011 at airshow Atlanta-Peachtree GA 10.05, allover metallic, flying; N21011 at fly-in Oshkosh 7.06, N21011 at fly-in Lakeland FL 21.4.07;

BA-293	E18S	N53S	Combs Aircraft Inc: CofA issued	12.7.57
271200	-9700		Mid-Continent Leasing Co	6.12.57/59
			Rockford Newspapers Inc, Rockford IL	4.12.59/70
			Frontier Ford Inc	31.7.70/72
			Viking International Airlines, Minneapolis MN	21.6.72/76
			(cargo door installed 12.72)	
			Eugene Pikovsky & William H. Ramsey, Minneapolis MN	29.9.76/81
			lsd: Viking International Airfreight, Minneapolis MN	5.10.76/79
			(cockpit door installed 2.77)	
			Robert J. Belmar/ Blue Star Aviation, Brownsville TX	31.8.81/84
			Pan American Specialty Equipment Corp, McAllen TX	29.6.84/88
			sold to Mexico	20.5.88

N53S noted Denver CO 12.60;

N53S noted Indianapolis IN 5.68 "Remarkable Rockford Illinois" titles, tailwheel, curtains in windows; USCR72: not listed;

N53S noted Brownsville TX 10.87 tailwheel;

BA-294	E18S	N54S	Beechcraft Aircraft Corp, Wichita KS: CofA issued	15.7.57
			Currey Sanders Aircraft Co, Shreveport LA	19.7.57
			Wheless Drilling Co, Shreveport LA	6.11.57/77
		(N24S)	ntu: Wheless Drilling Co, Shreveport LA	2.5.77
		N54S	John R. Webster, Shreveport LA	6.7.77/78
			Richard L. Burger	20.9.78/81
			found abandoned damaged in a ditch, Cox's Air Strip SC	
			loaded with 1,840lb marijuana. painted as "N70B"	8.3.81
			South Carolina Aeronautics Commission, Columbia SC North American Aviation Institute, Conway SC: donated (inst airframe, painted as "N5606NA" with "392" on tail)	4.81
			purchased by restorer, moved to Lake City SC, by	13
			in use by fire service near Florence SC by	16

"N5606NA" noted Marion County Airport, Lake City SC 9.10.95 complete, looks good condition, red & white; same location 6.13 with outer wings removed, fabric tattered, red and white; noted near Mytle Beach FL 2.16

-				
BA-295	E18S	N26Y	Tulsair Distributors Inc	22.7.57/58
			Pan American Petroleum Corp, Tulsa OK	21.8.58/65
			Standard Oil Co/ 910 Michigan Ave, Chicago IL	
		N910U	Nine-Ten Corp, Chicago IL	1.6.65
		N910R	Jack Adams Aircraft Sales, Walls MS	11.65/68
		N152JB	Jamison Bedding Inc, Nashville TN	12.65/68
			S. W. Sisk/ Orion Airways, St. Louis MO	7.68/69
			nosed over landing, Fayetteville AR	23.10.68
			George Sisk/ Orion Airways, St. Louis MO	68/69
			Maplewood Bank & Trust Co: repossessed	3.11.69/70
			Robert E. Staples, St Louis MO	12.69/71
			lsd: Sisk Aviation Activities, St Louis MO	70
			Apollo Airways, Kansas City MO	4.71/77
			(cargo floor & door installed prior to 73)	
			gear collapsed landing, Detroit-City MI	25.3.77
			Royal Air Freight/ Great Lakes Air Freight, Pontiac MI	14.6.77/91
			Jeffrey K. Gutow, San Carlos CA	3.12.91/94
			sold to Belize, struck-off USCR	30.3.94
			•	

N152JB accident report 23.10.68: Orion Airways, right gear was cocked outwards due mechanical failure on previous takeoff, 2 unhurt, 2.30am;

N152JB accident report 25.3.77: Apollo Airways, cargo flight Ft Wayne IN to Detroit, gear retracted due mechanical failure, pilot unhurt, 12.45am;

N152JB noted Detroit City MI 26.5.77, "Apollo Airways" titiles, minor damage, no props or tailwheel;

N152JB noted Youngstown OH 16.9.82 Royal Air Freight, Pontiac MI; N152JB noted Pontiac MI 7.91 Royal Air; N152JB noted Youngstown OH 16.9.82 Royal Air Freight;

BA-296	E18S	N5600D	Butler Airplane Sales: CofA issued	18.7.57
			Walker Manufacturing Co of Wisconsin	18.7.57/68
			Lexington Air Taxi/ Lexington Airways	6.68/70
			Mar Dora Inc, West Palm Beach FL: USCR	69
			Aviation Sales Inc	8.7.70/72
			Jim Hankins Air Service, Jackson MS	24.3.72/74
			(cargo floor installed 4.72)	
			Morey L. Wyman/ Wyman Pilot Service, Pontiac MI	30.3.74/83
			Hubert J. Dwyer/ Dwyer Air Cargo, Mason City IA	5.5.83/15
			tailwheel collapsed on landing, Cedar Rapids IA	11.7.83
			(retired Mason City IA, for ssle by auction 6.17)	
			struck-off USCR	30.4.15
		N5600D	PCA Leasing LLC, Park City UT: rest. to USCR	17.6.19

### USCR70 & 72: reg. pending;

N5600D accident report 11.7.83: Dwyer Aircraft Service, pilot unhurt;

N5600D noted Dayton OH 26.1.84 Dwyer Air Cargo;

N5600D noted Pontiac MI 17.9.78;

N5600D noted Mason City IA 8.97 "Dwyair Air Cargo";

N5600D noted Mason City IA 25.7.98 "Dwyair Air Cargo" plate BA-296 built 7.57;

N5600D noted Mason City IA 23.7.06 Dwyer Air Cargo, appears parked here some time;

N5600D & N20GL auction at Mason City IA 6.17: N5600D complete, metallic, parked in high grass;

BA-297	E18S	N5601D	built	7.57
D/( 201	L100		Coastal Rental Corp, Monroe LA	63/70
			Lyle Adams, Rayvville LA	72
			SMB Stage Line Inc, Des Moines IA	76/77
			Blackhawk Airways, Janesville WI prop blade failed, engine torn away,	12.1.77/84
			crashed destroyed in forced landing near Plymouth IN (wreck stored Janesville WI 82)	1.10.77
			struck-off USCR	12.7.84

accident report 1.10.77: Blackhawk Airways, cargo flight Dayton OH to Chicago, right propeller failed, right engine torn away, forced landing 4.56am, destroyed, pilot hurt; N5601D noted Janesville WI 10.5.82, derelict, "Blackhawk" titles;

DA 000	E400	NIOONI	Danala Airenatt Oama	0.57/50
BA-298	E18S	N36N	Beech Aircraft Corp	8.57/58
			Alamo Aviation, San Antonio TX	22.5.58
			Rodney DeLange	20.6.58/60
			SC State Development Board, Columbia SC	22.8.60/67
			SC Aeronautics Commission, Columbia SC	1.11.67/71
			(picture windows, 2 piece windshield installed	
	-9700		and mods to E18S-9700 completed 8.68)	
			Midlands Aviation Corp	1.7.71
			Rod M. Love, Columbia SC	11.9.71/81
			Barron Thomas Aviation, Dallas TX	16.4.81/82
			sold to Canada: struck-off USCR	6.82
		C-GPAV	Keewatin Air Ltd, Winnipeg MAN	7.82/83
			op: Icarus Flying Service	85
			National Business Funding Inc	29.3.85
			David Quinn, Entry Island, Magdalen Islands QUE	85
			sold to USA: struck-off Canadian Register	4.85
		N900WP	National Business Funding Inc: reg candidate	3.85
			Lafayette Aviation	25.3.85/88
			(cabin cargo floor fitted 2.87)	
			crashed into houses on takeoff, destroyed, Detroit MI	10.3.88

accident report 10.3.88: Warren MI, Lafayette Aviation: crashed into houses after takeoff Detroit, cargo misloaded, shifted on takeoff;

BA-299	E18S	N5603D N61A N613A N387W	Parker Pen Co, Janesville WI Parker Pen Co, Janesville WI Wyandotte Chemicals Corp, Wyandotte MI Wyandotte Chemicals Corp, Wyandotte MI Unitec Corp, Timonium MO Metro Air Service Co, Detroit-Metropolitan Airport MI wrecked in forced landing gear-up due engine failure, Lyndon Station WI struck-off USCR	6.57 57/61 16.2.61 62/64 66 5.6.70/71 15.9.70 25.2.71
			N387W: Metro Air Service, intentional wheels-up forced lar ble to maintain altitude, 1 unhurt;	nding due
BA-300	E18S -9700	N49R	Krispy Kreme Doughnut Co, Winston Salem NC (mods to E18S-9700 by Piedmont Aviation, Winston-Salem NC .57)	.57/64
		N911H N12TF	Piedmont Aviation, Winston Salem NC American Lease Plans Inc, Anderson SC	66/72 27.3.72/91
BA-301	E18S -9700	N24Y	Atlantic Aviation Corp: CofA issued Correale Construction Co, Hazleton PA Muratone Co, Philadelphia PA Semo Aviation, Malden MO Baron Aviation Services, Vichy MO sale reported, Weiner AR Henry B. Ponder, Heber Springs AR Russ Amos, Batesville AR Hoge Aviation, Pipersville PA	7.8.57 27.9.57/68 12.9.68/72 14.4.72/80 9.5.80/99 01/02 21.10.04/13 13.8.13/20 10.11.20/21
	N24Y not	ed St Louis M	O 3.76 "Semo Airways: tailwheel; St Louis MO 2.6.76 retire	d;
BA-302	E18S	N5604D	Alamo Aviation, San Antonio TX: CofA issued Centex-Zachary/Centex Construction Co, Dallas TX Corporate Air Industries Inc, Anaheim CA Murietta Farms Co, Madera CA	12.8.57 24.9.57/63 7.11.63/64 12.64/68
	trigear	N979ST	(Volpar Mk.IV trigear installed 1.65) Murietta Farms Co, Madera CA (G18S type two-piece windshield, and picture windows kit installed 7.68)	15.7.68/75
			William H. MillerSilver State Airlines (high-density pax seating installed 7.75) Aviation Parts Inc, Las Vegas NV	3.4.75/76 15.3.76
		N979SB	Aviation Parts Inc, Las Vegas NV Aviation Parts Inc, Las Vegas NV Land-Air Sales & Leasing Inc Aviation Parts Inc, Las Vegas NV op: Air Fast Freight crashed destroyed on takeoff, Catalina Island CA	11.76/77 1.6.77 15.8.77 77 22.8.77
			: Air Fast Freight, flight to Long Beach, 2 crew affected by ning from exhaust, both killed - photo shows brown & white	scheme;
BA-303	E18S	N54N	built Farm & Home Savings Association, Nevada MO MFA Security Service, Columbia MO reg. pending, Harrisonville MO William S. Schwab, Joplin MO Bob Kilpatrick Aircraft Inc, West Memphis AR crashed destroyed on takeoff in snow & fog, struck building, Wheeling-Pal Waukee IL	,57 63/64 66/69 70 72 9.11.73/75
			.3/75: Bob Kilpatrick Aircraft, aborted takeoff in snow & fog, struck greenhouse, 1 k, 1 hurt;	pilot & copilot
BA-304	E18S	N29N	built Digiorgio Fruit Corp, San Francisco CA Eureka Aero Industries, Eureka CA	,57 63/70 74/75

USCR72: not listed

N29N photo 8.74, tailwheel, "Eureka Aero" titles;

N29N accident report 28.5.75: Eureka Aero Industries, mail flight Amarillo TX to Ft Worth TX, descended into ground in extreme thunderstorms & hail, 10.22pm, pilot k;

BA-305	E18S	N27R N59U	Piedmont Aviation, Winston Salem NC: CofA issued R. J. Reynolds Tobacco Co R. J. Reynolds Tobacco Co DeVlieg Machine Co, Royal Oak MI Semo Aviation/ Semo Airways, Malden MO H. B. Lewis Dewie J. Sandlin, Harlingen TX struck-off USCR by FAA	29.8.57 30.8.57/59 11.5.59/60 20.5.60/72 22.4.72/81 24.1.81 19.3.81/13 24.4.13
	N59U no	ted St Louis M	O 29.9.72 Semo Airways;	
BA-306	E18S	N75Z	built	.57
		N829K	Hughes Supply Inc, Orlando FL Executive Air Leasing Inc, Orlando FL South Florida Aircraft Sales & Leasing Inc, Miami FL	63/70 71/74 13.3.74
		CC-CAK	sold to Chile, struck-off USCR reg. Transporte Aereo de Magallanes Ltda - TAMA,	23.7.74 .74
			Punta Arenas	80
			accident at Punta Arenas Aerodromo Luis Fuentes Martinez, Porvenir, Chile:	2.8.80
			/ Crodronio Edio i denico Martinez, i divenii, Oniie.	
			gate guard on plinth, painted as "CCHV"	07/20
	N829K no	oted Miami FL		07/20
BA-307	E18S	oted Miami FL N100W (2	gate guard on plinth, painted as "CCHV"  7.74 Executive Alr Leasing;  built	.57
BA-307			gate guard on plinth, painted as "CCHV"  7.74 Executive Alr Leasing;  built Landis Carr Aviation, Los Angeles Airport CA	.57 3.6.63
BA-307	E18S	N100W (2	gate guard on plinth, painted as "CCHV"  7.74 Executive Alr Leasing;  built  Landis Carr Aviation, Los Angeles Airport CA sold to Mexico, struck-off USCR (same day)	.57 3.6.63 3.6.63
BA-307	E18S		gate guard on plinth, painted as "CCHV"  7.74 Executive Alr Leasing;  built Landis Carr Aviation, Los Angeles Airport CA sold to Mexico, struck-off USCR (same day) reg.	.57 3.6.63 3.6.63 .63
BA-307	E18S	N100W (2	gate guard on plinth, painted as "CCHV"  7.74 Executive Alr Leasing;  built Landis Carr Aviation, Los Angeles Airport CA sold to Mexico, struck-off USCR (same day) reg. Banco Regional Del Norte S.A.	.57 3.6.63 3.6.63 .63 68
BA-307	E18S	N100W (2	gate guard on plinth, painted as "CCHV"  7.74 Executive Alr Leasing;  built Landis Carr Aviation, Los Angeles Airport CA sold to Mexico, struck-off USCR (same day) reg. Banco Regional Del Norte S.A. sold to US, struck-off Mexican Register	.57 3.6.63 3.6.63 .63
BA-307	E18S	N100W (2 XB-YOO	gate guard on plinth, painted as "CCHV"  7.74 Executive AIr Leasing;  built Landis Carr Aviation, Los Angeles Airport CA sold to Mexico, struck-off USCR (same day) reg. Banco Regional Del Norte S.A. sold to US, struck-off Mexican Register Industrial Nucleonics Corp Ross Aviation, Tulsa-Riverside OK	.57 3.6.63 3.6.63 .63 68 19.11.68
BA-307	E18S	N100W (2 XB-YOO	gate guard on plinth, painted as "CCHV"  7.74 Executive AIr Leasing;  built Landis Carr Aviation, Los Angeles Airport CA sold to Mexico, struck-off USCR (same day) reg. Banco Regional Del Norte S.A. sold to US, struck-off Mexican Register Industrial Nucleonics Corp Ross Aviation, Tulsa-Riverside OK (US CofA renewed 15.1.69) Great Western Airlines, Tulsa-Riverside OK (cargo floor installed 4.72)	.57 3.6.63 3.6.63 .63 68 19.11.68 11.68/69
BA-307	E18S	N100W (2 XB-YOO	gate guard on plinth, painted as "CCHV"  7.74 Executive AIr Leasing;  built Landis Carr Aviation, Los Angeles Airport CA sold to Mexico, struck-off USCR (same day) reg. Banco Regional Del Norte S.A. sold to US, struck-off Mexican Register Industrial Nucleonics Corp Ross Aviation, Tulsa-Riverside OK (US CofA renewed 15.1.69) Great Western Airlines, Tulsa-Riverside OK (cargo floor installed 4.72) forced landing at night in crop field, hit fence,	.57 3.6.63 3.6.63 .63 68 19.11.68 11.68/69 18.1.69
BA-307	E18S	N100W (2 XB-YOO	gate guard on plinth, painted as "CCHV"  7.74 Executive AIr Leasing;  built Landis Carr Aviation, Los Angeles Airport CA sold to Mexico, struck-off USCR (same day) reg. Banco Regional Del Norte S.A. sold to US, struck-off Mexican Register Industrial Nucleonics Corp Ross Aviation, Tulsa-Riverside OK (US CofA renewed 15.1.69) Great Western Airlines, Tulsa-Riverside OK (cargo floor installed 4.72) forced landing at night in crop field, hit fence, near Kalamazoo MI	.57 3.6.63 3.6.63 .63 68 19.11.68 11.68/69 18.1.69 2.6.69/76
BA-307	E18S	N100W (2 XB-YOO	gate guard on plinth, painted as "CCHV"  7.74 Executive AIr Leasing;  built Landis Carr Aviation, Los Angeles Airport CA sold to Mexico, struck-off USCR (same day) reg. Banco Regional Del Norte S.A. sold to US, struck-off Mexican Register Industrial Nucleonics Corp Ross Aviation, Tulsa-Riverside OK (US CofA renewed 15.1.69) Great Western Airlines, Tulsa-Riverside OK (cargo floor installed 4.72) forced landing at night in crop field, hit fence,	.57 3.6.63 3.6.63 .63 68 19.11.68 11.68/69 18.1.69

N2510C accident report 30.4.76: en route Kalamazoo-Detroit, fuel starvation due mechanical fault

with fuel pumps, hit crops, fence and a hog, 2.13am, pilot unhurt;

N2510C noted Kalamazoo MI 10.76 "Great Western Airlines", tailwheel, tatty;

N2510C noted Mojave CA 10.10.78;

N2510C noted Van Nuys CA 29.11.79 derelict, ex Great Western;

Changes of ownership after 30.4.76 accident probably for parts only;

BA-308	E18S	(N5602D)	ntu: Beech Aircraft Corp, Wichita KS	21.8.57
		N200HR	J. D. Reed Co, Houston TX: CofA issued	21.8.57
			Hampton C. Robinson, Houston TX	23.8.57/65
			American Aero Leasing Corp	19.3.65
			Gilley Airways Corp, Myrtle Beach SC	9.12.65/66
		N342E	Gilley Airways Corp, Myrtle Beach SC	18.2.66/68
	trigear		(Volpar trigear, G18S type windshield, picture windows kit installed 2.66)	

Hamilton Little Liner	Fiber Controls Corp, Gastonia NC Vercoa Air Service, Danville IL Royale Airlines Tul-Aero Inc Joseph T. Mackey op: Baja Airlines gear collapsed landing, Bahia de Los Angeles, Mexico landed gear-up on foamed runway, San Diego CA Aero Wasp, Redondo Beach CA Aircraft Associates Aerospace Products Inc, North Hollywood CA op: Silver State Airlines, Las Vegas NV (mods for Hamilton Little Liner by Hamilton Aviation, Tucson AZ 6.81)	12.68/70 22.9.70/74 28.1.74/75 14.2.75 25.9.75/77 76 20.2.76 26.5.76 14.6.77 12.77/79 22.1.79/81 81
	Lani Bird Inc/ Scenic Air Tour, Honolulu HI (fleet #24)	10.81/92
	Tomy International Inc dba Scenic Air Tours, Honolulu HI crashed into Mount Kaleakala, Kahului, Maui HI (9 k)	1.3.91/92 22.4.92

N342E noted Chicago-O'Hare 14.7.71 Vercoa AS;

N342E accident report 20.2.76: Baja Airlines: flight Mexicali-Bahia LA, 9 unhurt;

N342E accident report 26.5.76: Baja Airlines: mechanical failure in gear, 8 unhurt;

N342E noted Burbank CA 12.7.81 "for Silver State Airlines";

N342E noted Honolulu 9.83 "Lani Bird/Scenic Air Tour" Fleet #24, plate BA-308;

N342E noted Kahului HI 2.88 allover green "Scenic Air Tours" trigear; N342E noted Honolulu 7.89 "Scenic Air Tour" fleet #24, trigear;

crash report 22.4.92: struck Mount Kaleakala, operated by Tomy International dba Scenic Air Tours;

BA-309	E18S	N5606D	built	.57
		N301LA	Lakala Aviation, Kalamazoo MI	63/66
		N477GM	Commercial Credit Equipment Co, Lansing MI	69/72
			Bernard Florcke, Anchorage AK	16.5.78/79
			op: Gifford Aviation, Anchorage AK	79
			op: Aurora Air Service, Fairbanks AK	79
			gear-up forced landing on frozen lake,	
			after takeoff Kotzebue AK	25.10.79

N477GM reported as turbine when crashed 10.79: but see report below re engine warmup; Steve Darke quotes this is an unknown turbine conversion;

N477GM accident report 25.10.79: Aurora Air Service, cargo flight Kotzebue AK to Selawik AK, engine failed after takeoff, pilot landed gear-up on frozen lake to prevent gear breaking through ice, frost on wings, insufficient engine warm up, pilot unhurt;

BA-310	E18S	CN-TTC	Omnium Nord Africain, Casablanca & Rabat	12.57/73
		TR-LQG	(CN-TTC delivered via Prestwick 27.9.57) Ste Nideco SA/Air Inter Gabon, Port Gentil	3.73/78
		TN-LQG	CofA expired, struck-off Register	5.75
	CN-TTC	delivered via F	Prestwick 27.9.57 Omnium Nord Africain;	
	CNITTO	visited Delien	Compared O.4.7.60 Audio	
			Senegal 24.7.62 Ardic; ier Neu Chatel, Switzerland 31.5.67 at ski resort airfield	·,
BA-311			· ·	63/64
BA-311	CN-TTC	noted Columb	ier Neu Chatel, Switzerland 31.5.67 at ski resort airfield	,
BA-311	CN-TTC	noted Columb	ier Neu Chatel, Switzerland 31.5.67 at ski resort airfield Journal Publishing Co, Albuquerque NM	63/64

takeoff, stalled, crashed and burned, 2k;

BA-312	E18S	N18R (2	J. D. Reed Co, Houston TX: CofA issued	28.8.57
	-9700		Rowan Oil Co	4.9.57/61
			Champlin Oil & Refining Co	12.61/62
			L. F. Peterson, Fort Worth TX	10.62/70
			Texas A & M Research Foundation	1.12.70/71
			Trans-World Geophysical Consultants, Houston TX	7.7.71/72

Baldwin Contracting Co	11.72/75
Tampa Air Centre, Tampa FL	10.6.75/78
Aerospace Products Inc, North Hollywood CA	11.78/79
Thomas Bussard	8.2.79/84
Lee H. Cameron/ Aerospace Products Inc,	
North Hollywood CA	21.9.84/85
Aviation & Transportation Properties Inc, Auburn CA	6.85/86
Sylvia M. Denham, Auburn CA	12.6.86/89
Aeronautical Services Inc, Friday Harbour WA	17.4.89/99
(converted to all-cargo configuration 2.90)	
op: Catalina Flying Boats, Long Beach CA	90/99
Catalina Flying Boats, Long Beach CA	28.6.99/06
op: Phoenix Airtransport, Phoenix AZ	02/03
Harry Traufer/ Aircap Management Co, Opa Locka FL damaged in collision on taxiway with Cessna 208,	12.4.06/11
Opa Locka FL (repaired) crashed into house after takeoff, destroyed by fire.	6.11.07
Opa Locka FL (Traufer k)	2.5.11

N18R noted Chino CA 5.11.79;

N18R noted Long Beach CA 10.99, all metallic, tailwheel, at Catalina Flying Boats ramp;

N18R noted Chino 8.4.83 all metallic;

N18R noted Chino CA 13.11.83, right rudder damaged;

Note: In 1989 the owners of Aeronautical Services Inc, Friday Harbour WA purchased Long Beach based Catalina Flying Boats Inc and used this company to service Catalina Island: sold two Geese and used Beech 18s N18R, N911E, N9375Y;

N18R noted Long Beach CA 9.9.90;

N18R noted Long Beach CA 7.91 at Catalina Flying Boats ramp, plate BA-312;

N18R noted Long Beach CA 4.92, 2.4.93 in service, 4.95;

N18R noted Long Beach CA 5.10.98 no windows, no titles, op Catalina Flying Boats, tailwheel;

N18R noted Long Beach CA 17.8.99 no titles, op Catalina Flying Boats;

N18R noted Long Beach CA 18.9.01 op Catalina Flying Boats, i/s;

N18R noted Phoenix AZ 22.12.02 "Phoenix Airtransport" titles;

N18R noted Phoenix AZ 6.03 op by Phoenix Air Transport, all metallic, tailwheel;

N18R noted Opa Locka FL 4.06 "Phoenix Air Transport", all metallic, windows faired over;

BA-313	E18S	CN-TTD 6V-AAB	Omnium Nord Africain, Rabat Air Senegal crashed	12.57/63 5.63 .63
			n-Gatwick 26.9.60; Senegal 24.7.62 Ardic;	
BA-314	E18S	N5608D	Butler Airplane Sales: CofA issued	9.9.57
	-9700		Allegheny Ludlum Steel Corp, Pittsburgh PA	11.9.57/67
			Elmira Aeronautical Corp, Horseheads NY	16.3.67/70
			Bobbie J. Johnson/ Paris Airways, Paris TN	12.70/73
			International Sales & Leasing Inc	23.8.73/76
			(cargo door installed 9.75)	
			James Spector/ Great Western Associates	2.9.76/78
			John W. Albert/ Almore Aircraft, Miami FL	31.1.78/79
			William Blake: documentation not completed	16.1.79
BA-315	E18S	N5609D	Southern Airways Co: CofA issued	5.9.57/58
			Albany Air Service, Albany GA	9.8.58
			A. C. Samford Inc	9.8.58/62
	-9700		(mods to E18S-9700 installed 4.59)	
			Albany Air Service, Albany GA	9.10.62/65
	Trigear		(Volpar trigear, picture windows, G18S type windscreen	
	J		installed 3.65 by Capitol Aviation, Springfield IL)	
			Carenco Inc, Albany GA	12.65/80
			Calton Co	20.2.80/89
			University of the South, Sewanee TN	8.6.89/91
			lsd: Centre Airlines, Reedsville PA	1.9.90/91
			Centre Airlines, Reedsville PA	1.8.91
			David Nutt & Associates, Jackson MS	12.93/95

Burt Faibisoff, Lake Havasu City AZ	16.5.95/96
Hugh M. Eaton, Dublin NH	2.96/06
Input/Output Technology Inc, Valencia CA	8.1.08/20

#### N5609D at Oshkosh 31.7.04;

BA-316	E18S	N5611D	built 8.57, CofA issued	24.9.57
			Flightcraft Inc	25.9.57
			Weyerhaeuser Timber Co, Tacoma WA	25.9.57/67
	Junior		(test aircraft fitted Aerojet-General Junior JATO in rear	
	JATO		of engine nacelles 19.1.58, testflown with JATO at	
			Beech plant, Wichitra KS 58)	
			Atlantic Aviation Service	18.12.67/68
			Vercoa Air Service, Danville IL	29.2.68
			Sam Vires/ Mid South Aircraft Sales, Memphis TN (mods for MAUW 9800lb installed 13.10.68)	12.10.68
			S. W. Sisk/ Orion Airways, St. Louis MO	16.10.68/69
			struck trees, landed safely Iron Mountain MI	6.2.69
			Maplewood Bank & Trust Co MO: repossessed	3.11.69/70
			Sisk Aviation Activities, St Louis MO	14.1.70
			Skyway Aviation/ Skyway Airlines, Ft Leonardwood MO	12.2.70/78
			(mods. for MAUW 10,100lb installed 19.2.74)	
			taxied over steep embankment, Lexington KY	17.11.75
	Hamilton Extended	Nose	(Hamilton extended nose installed 1.7.76 by Houston Aviation)	
			Pacific Missionary Aviation, Agana, Guam	24.7.78/03
			(cargo airstair door & cockpit entry door installed 5.10.78	)
			Jonathon Rosenberg & Russell D. Large,	
			Fort Lee NJ & Philippines	18.12.03/07
			Russell D. Large, Angeles City, Philippines	17.9.07/17
			Michael M.Large, Angeles City, Philippines	3.8.17/20
			reg expired 31.8.20, struck-off USCR	8.12.20

accident report 6.2.69: Orion Airways, 7.20am, night mail flight, pilots drowsy due inadequate rest, allowed aircraft to descend, continued on to airfield;

N5611D noted St Louis MO 29.9.72 "Skyway Airlines";

N5611D accident report 17.11.75: taxy for takeoff for flight to Jefferson City MO, pilot misjudged speed while taxying 1.17pm, 11 minor injuries;

N5611D noted Tucson AZ 15.10.78;

N5611D long nose flew San Francisco-Honolulu-Majuro-Yap .79, based Yap;

Photo 89: bare metal with sharks mouth on extended nose;

N5611D noted Yap 23.3.95 all silver, red & white band, spread wings logo & cross;

N5611D photo at Clark, Philippines 2004;

N5611D noted Clark, Philippines 6.05 on rebuild, owned by Jonathon Rosenberg & Russel Large;

N5611D noted Clark 11.1.07 complete, tailwheel, extended nose, departed several days later;

N5611D noted Clark Field 7.07 no props, otherwise complete;

N5611D noted Clark Field 29.12.16;

BA-317	E18S	N29X (1	built	9.57
		N711L (2	rereg	24.1.58
			landing gear retracted on landing, Rochester NY	10.7.59
		N7117	Maine & New Hampshire Granite Corp, Manchester NH	63/70
		N711TL Gilley Airways, Hartsfield SC	71/73	
			landed gear locked-up, Watertown NY	30.5.73
			Burlington Airways/ Burl Air Freight, Burlington WI crashed destroyed on takeoff, due wake turbulence	77/79
			from preceeding Boeing 727, Indianapolis IN	27.2.79
			Charles E. Bush/ Bush Aviation, Fort Lauderdale FL	79
			Bush Aviation, Dania FL: restored to USCR	31.1.85
			struck-off USCR	13.11.85

N711L BA-317 photo 1.59 by Larry Smiley;

N7117 noted Washington-DCA 6.4.66;

N711TL accident report 30.5.73: Gilley Airways, gear mechanical failure, 2.19am;

BA-318	E18S	N76S	Anderson Air Activities: CofA issued	17.9.57
			Air-Craft Leasing Corp	19.9.57/60
	-9700		(mods to E18S-9700 installed 4.59)	
			Sundstrand Corp, Rockford IL	10.60/65
			Hartzog-Schneck Aviation, Rockford IL	24.9.65/66
			DC Aircraft Inc, Detroit-City Airport MI	1.4.66/68
			(cargo door installed 11.66)	
			Hartzog Aviation, Rockford IL	1.3.68/72
			Air Central Airlines	11.72/73
			Lima Aviation Corp	12.73/76
			(cargo floor, cockpit door installed 8.75)	
			Kenneth D. Burden & Gerald Grismore	16.8.76/77
			Allen County Air Services, Pandora OH	13.5.77/80
		N136JR	Jack L. Rhoades/ Rhoades International, Seymour IN	3.80/87
			Rhoades Aviation Inc, Columbus IN	9.87/89
			ran into ditch on takeoff, Elyria OH	19.7.88
		N136JJ	Centre Airlines, Centre Hill PA	15.3.89/93
			(wrap-around windshield installed 9.89)	
			Southern Air Freight, St Joseph LA	11.93/95
			SCS Group Ltd, Springdale AR	12.95
			Springdale Air Service, Springdale AR	13.7.98/99
			Kestrel Inc, Waukee IA	13.3.01/02
			Dash Flying Service, Chilton WI	19.11.04/06
			Mark M. Neal, Kensington MD	27.12.07/18
			Jonathon A. Myers, Fithian IL	23.8.18/20
			-	

N76S noted Chicago-O'Hare 30.9.71;

N76S noted Columbus IN 29.9.79 Rhoades International;

N76S noted Columbus IN 26.8.80 Rhoades International;

N136JJ noted Springdale AR 8.97 in service, Springdale Air Service: plate BA-318 built 9.57, another plate: converted to E18S-9700 4.59;

N136JJ noted Springdale 13.10.97 "Springdale Air Services"; N136JJ at fly-in Oshkosh 26.7.06 plate E18S-9700 BA-318 built 9.57;

N136JJ noted at Janesville WI 25.7.08, still has Springdale Air Services titles;

N136JJ visited Oshkosh flyin 7.16, 7.17;

BA-319	E18S	N5612D	Pacific Aircraft Sales Co: CofA issued	26.9.57/58
-9700	-9700		Frederickson Equipment Co, Truckee CA	11.2.58/67
			Qualitron Aero Inc	6.10.67/68
			Ross Aviation, Tulsa-Riverside OK	3.7.68/69
			(cargo floor installed 11.69)	
			Great Western Airlines, Tulsa-Riverside OK	70/76
			damaged when struck snowbank landing, Chicago IL	27.12.73
			Sam Vires/ Mid-South Aircraft Sales, Memphis TN	10.76/77
			Semo Aviation Inc, Malden MO	7.2.77/80
			(cockpit emergency hatch installed 5.77)	
			Coker Airfreight Inc, Dallas TX	11.80/81
			damaged in ground-loop landing, Lubbock TX	18.2.81
		N90CA	Coker Airfreight Inc, Dallas TX	5.9.81/83
			Mountain Air Cargo, Denver NC	13.9.83/87
			Reggie S. Hopwood/ Cape Central Airways, Malden MO	2.87/92
			Cape Central Airways, Cape Girardeau MO	6.92/94
			damaged, struck by vehicle, Kansas City MO	14.3.94
		N582MS	Cape Central Airways, Cape Girardeau MO	30.6.94/95
			Earl V. Long, Wichita KS	14.7.95
			Professional Aviation, Alcoa TN	12.95
			Kestrel Inc, Waukee IA	7.97
			Comanche Air, Winthrop WA	18.7.98/99
		N33HH	Comanche Air, Winthrop WA	6.1.99/15
			op: Cascade Air, Ephrata WA	00
			Brian D. Fleming, Longview WA	27.8.15/20

N5612D accident report 27.12.73: Great Western Airlines, swerved on landing into snowbank, pilot unhurt, 6.08am;

N5612D accident report 18.2.81: Coker Airfreight: cargo flight from Grand Prairie TX; N90CA noted Cincinatti-Lunken OH 9.11.93 metallic "Cape Central Airways" titles; N90CA 14.3.94: struck by airport police car on ramp while taxying Kansas City, on

#### freight flight for Cape Central AW; N582MS noted Wichita-Westport Airport KS 6.8.95 "Cape Central Airways"; N33HH noted Ephrata WA 15.10.14 polished metal, in service, no titles;

BA-320	E18S	N86D	Youngstown Airways/ Lease Air, Youngstown OH: CofA	26.9.57/63
		N8611	Air Orlando Inc, Orlando FL	2.5.63
			Richard R. Freeman, Orlando FL	2.12.63/64
			Robert Wray	10.64/65
		N1431T	Charles M. Stephenson	14.5.65
			landed gear-up, Opa Locka FL	22.5.65
			J. S. Showalter/ Showalter Co, Orlando FL	12.65/68
			S. W. Sisk/ Orion Airways, St. Louis MO	23.9.68/70
			Maplewood Bank & Trust Co: repossessed	3.11.69
			Sisk Aviation Activities, St. Louis MO	14.1.70
			Golden Eagle Aviation	9.70
			Skyway Aviation/ Skyway Airlines, Ft Leonardwood MO	26.3.71/80
	Hamilton		(Hamilton extended nose installed 4.75)	
	long nose		struck tug while taxying, St. Louis MO	8.3.79
			Nevada Aircraft Leasing Corp, Carson City NV	4.4.80/12
			struck-off USCR	6.7.12

N1431T noted St Louis MO 29.9.72 "Skyway AL"; N1431T accident report 8.3.79: Skyways Aviation, flight Ft Leonardwood to St Louis;

BA-321	E18S	N63E	Francis Aviation, Lansing MI	8.10.57
			Miller Industries Inc, Reed City MI	8.10.57/67
	-9700		(mods to E18S-9700 installed 8.59)	
			Miller Airmotive Inc/ Miller Airlines, Osceola MI	19.5.67/69
			McCollum Aviation, Danville IL	4.4.69/70
			Runway 5 Aviation Inc, West Mifflin PA	7.70/74
			Nanuet National Bank, Nanuet NY: repossessed	7.74
	Hamilton		(rebuilt as Hamilton Westwind III with PT6A-20 turbines	
	Westwind	d III b	by Hamilton Aircraft Co at Tucson AZ 12.74)	
			Great Western Airlines, Tulsa-Riverside OK	28.5.75
		N202GW	Great Western Airlines, Tulsa-Riverside OK	2.76/81
			ground collision with tug, Chicago-O'Hare IL	22.12.77
			minor structural damage in flight, Tulsa OK	26.11.80
			Viking International Airlines, Minneapolis MN	4.3.81
			Ajax Aircraft Leasing Inc, Dover DE	5.11.85
			Active Aero Charter, Willow Run MI: leased	8.88/89
			Ken & Karl Stoltzfus/K & K Aircraft Inc, Bridgewater VA	3.91/07
			(agricultural mods CofA 19.4.91,	
			rebuilt by K&K 12.95 with G18S cockpit, fitted for	
			agricultural & pest control spraying operations)	
			Brazoria County Mosquito Control, Angleton TX	18.12.08/16
			struck-off USCR	18.10.16

#### N202GW photo 4.77 as Westwind III;

N202GW accident report 22.12.77: Great Western, taxying after landing from Kansas City, 12.51am, 2 crew unhurt, ground tug did not give way;

N202GW noted Willow Run MI 3.8.89 "Active Aero Charter, Willow Run MI", Westwind;

N202GW visited Waynesboro VA 19.7.98 K&K Aircraft, turbine tailwheel, refuelled;

N202GW noted Bridgewater Air Park VA 30.7.98, tailwheel turbines, in service;

N202GW noted Los Alamitos CA 17.8.99 Westwind III K&K Aircraft, sprayer, "K&K Aircraft" titles,

plate BA-321 built 10.57, another plate: converted to E18S-9700 8.59;

N202GW noted Los Alamitos CA 13.8.02 with other K&K sprayers;

BA-322	E18S	N617M	McLean Trucking Co, Winston Salem NC	63/66
			Prompt Air Delivery Inc, Vero Beach FL, later	
			Washington-National DC	69/72
			Robert L. Green/ Green Aero, Clarkston MI	21.10.74/79
			crashed destroyed landing, Youngstown-Execuive OH	10.4.79

N617M noted Washington-DCA 2.10.68, plate BA-322;

N617M accident report 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jackson-Youngstown Exec OH, hard landing, attempted go-around, crashed, 2.42pm, pilot unhurt;

BA-323				
	E18S	N5615D	Atlantic Aviation Corp: CofA issued	10.10.57/58
	0700	N75200 (2	Atlantic Aviation Corp	1.58/59
	-9700		(mos to E18S-9700 installed 1.60)	6 6 60/61
			Miniature Precision Bearing Inc	6.6.60/61
			Treesdale Laboratories Inc Zinke-Smith Inc, Pompano Beach FL	15.9.61/63 9.1.63
		N216ZS	Zinke-Smith Inc, Pompano Beach FL	10.63/67
		112 1023	engine torn out on takeoff due prop failure, landed	10.03/07
			safely Ft Lauderdale FL: still painted as N75200	16.9.64
			Sunny South Aircraft Service	23.3.67
			K. C. Benbow Co	2.8.67/69
			Piedmont Aviation, Winston Salem NC	13.1.69
			Chattahoochee Air Service	14.8.69
			Richard J. Kavanaugh, Tifton GA	1.12.69/73
			Semo Aviation, Malden MO	30.1.73/79
			(pilot cockpit emegency hatch fitted 6.77)	
			H & R Leasing Co/ Hunt Pan Am Distributors	31.5.79
			Aircraft Leasing & Pilot Services Inc, Brownsville TX	11.79/91
			(last FAA communication from owner in 1983)	
	E400	NEOLID	D '(' A' ('O   O	10.57
BA-324	E18S	N5614D	Pacific Aircraft Sales Co State of California Department of Fish & Game,	10.57
			Sacramento CA	11.57/72
			(fish dropping hopper installed in belly 4.58,	
			extensive dropping of fingerlings in lakes)	
		N10FG	California Department of Fish & Game, Sacramento CA	19.5.72/74
	Hamilton		(rebuilt Tucson AZ 5.72 by Hamilton Aircraft Co as	
	Westwind I		Hamilton Westwind I: PT6A-27 turbines, Hamilton cargo	door,
	trigear		picture windows, Volpar Mk.IV trigear, G18S type windsh	
		N21FG	California Department of Fish & Game, Sacramento CA	6.3.74/84
		N51FG	California Department of Fish & Game, Sacramento CA	7.3.84
			Smithair Inc, Sharpsburg GA	8.8.84/90
			Smithair Inc, Sharpsburg GA Ajax Aircraft Leasing Inc, Dover DE	8.8.84/90 4.1.90/91
		(N983AA)	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI	4.1.90/91
		(N983AA) N51FG	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI	4.1.90/91 23.5.90/93
	N5614D no	N51FG	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI	4.1.90/91 23.5.90/93 3.3.93
		N51FG ted Tucson A	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear;	4.1.90/91 23.5.90/93 3.3.93
	N21FG note	N51FG ted Tucson A ed Arcata CA	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines;	4.1.90/91 23.5.90/93 3.3.93
	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ills on fish dro	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; opping: see Beech 18 by Robert Parmerter p.291;	4.1.90/91 23.5.90/93 3.3.93 8.6.93
BA-325	N21FG note	N51FG ted Tucson A ed Arcata CA	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; opping: see Beech 18 by Robert Parmerter p.291; Roscoe Turner Aeronautical Corp: CofA issued	4.1.90/91 23.5.90/93 3.3.93 8.6.93
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ills on fish dro	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; opping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball	4.1.90/91 23.5.90/93 3.3.93 8.6.93 21.10.57/58 27.1.58/60
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ills on fish dro	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; opping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball Bell Intercontinental Corp, Mishawaka IN	4.1.90/91 23.5.90/93 3.3.93 8.6.93
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ills on fish dro	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; opping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball Bell Intercontinental Corp, Mishawaka IN Howard Aero Service/ Alamo Aviation/	4.1.90/91 23.5.90/93 3.3.93 8.6.93 21.10.57/58 27.1.58/60 29.7.60/63
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ills on fish dro  N5617D	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; opping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball Bell Intercontinental Corp, Mishawaka IN Howard Aero Service/ Alamo Aviation/ Business Aircraft Corp, San Antonio TX	4.1.90/91 23.5.90/93 3.3.93 8.6.93 21.10.57/58 27.1.58/60 29.7.60/63 31.7.63
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ills on fish dro  N5617D	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; opping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball Bell Intercontinental Corp, Mishawaka IN Howard Aero Service/ Alamo Aviation/ Business Aircraft Corp, San Antonio TX Professional Pilot Service Inc	4.1.90/91 23.5.90/93 3.3.93 8.6.93 21.10.57/58 27.1.58/60 29.7.60/63 31.7.63 7.9.63/64
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ills on fish dro  N5617D	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; opping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball Bell Intercontinental Corp, Mishawaka IN Howard Aero Service/ Alamo Aviation/ Business Aircraft Corp, San Antonio TX Professional Pilot Service Inc Professional Pilot Service Inc	4.1.90/91 23.5.90/93 3.3.93 8.6.93 21.10.57/58 27.1.58/60 29.7.60/63 31.7.63 7.9.63/64 24.4.64
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ills on fish dro  N5617D	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; opping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball Bell Intercontinental Corp, Mishawaka IN Howard Aero Service/ Alamo Aviation/ Business Aircraft Corp, San Antonio TX Professional Pilot Service Inc Professional Pilot Service Inc Florida Tile Industries Inc	4.1.90/91 23.5.90/93 3.3.93 8.6.93 21.10.57/58 27.1.58/60 29.7.60/63 31.7.63 7.9.63/64 24.4.64 20.7.64/65
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ills on fish dro  N5617D	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; opping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball Bell Intercontinental Corp, Mishawaka IN Howard Aero Service/ Alamo Aviation/ Business Aircraft Corp, San Antonio TX Professional Pilot Service Inc Professional Pilot Service Inc Florida Tile Industries Inc Conequip Corp, Evansville IN	4.1.90/91 23.5.90/93 3.3.93 8.6.93 21.10.57/58 27.1.58/60 29.7.60/63 31.7.63 7.9.63/64 24.4.64
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ills on fish dro  N5617D	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; A 8.81 trigear turbines; A 8.82 trigear turbines A 8.82 trigear	4.1.90/91 23.5.90/93 3.3.93 8.6.93 21.10.57/58 27.1.58/60 29.7.60/63 31.7.63 7.9.63/64 24.4.64 20.7.64/65 29.6.65/71
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ills on fish dro  N5617D  N765FT N965FT	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; opping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball Bell Intercontinental Corp, Mishawaka IN Howard Aero Service/ Alamo Aviation/ Business Aircraft Corp, San Antonio TX Professional Pilot Service Inc Professional Pilot Service Inc Florida Tile Industries Inc Conequip Corp, Evansville IN (mods for E18S-9900 installed 12.66) damaged landing with gear locked-up, Evansville IN	4.1.90/91 23.5.90/93 3.3.93 8.6.93 21.10.57/58 27.1.58/60 29.7.60/63 31.7.63 7.9.63/64 24.4.64 20.7.64/65 29.6.65/71 28.5.67
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ills on fish dro  N5617D  N765FT N965FT N965FT	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; Apping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball Bell Intercontinental Corp, Mishawaka IN Howard Aero Service/ Alamo Aviation/ Business Aircraft Corp, San Antonio TX Professional Pilot Service Inc Professional Pilot Service Inc Florida Tile Industries Inc Conequip Corp, Evansville IN (mods for E18S-9900 installed 12.66) damaged landing with gear locked-up, Evansville IN Leon F. Roberts	4.1.90/91 23.5.90/93 3.3.93 8.6.93 21.10.57/58 27.1.58/60 29.7.60/63 31.7.63 7.9.63/64 24.4.64 20.7.64/65 29.6.65/71 28.5.67 2.2.71/72
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ills on fish dro  N5617D  N765FT N965FT	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; opping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball Bell Intercontinental Corp, Mishawaka IN Howard Aero Service/ Alamo Aviation/ Business Aircraft Corp, San Antonio TX Professional Pilot Service Inc Professional Pilot Service Inc Florida Tile Industries Inc Conequip Corp, Evansville IN (mods for E18S-9900 installed 12.66) damaged landing with gear locked-up, Evansville IN Leon F. Roberts Catlin Aviation Co	4.1.90/91 23.5.90/93 3.3.93 8.6.93 21.10.57/58 27.1.58/60 29.7.60/63 31.7.63 7.9.63/64 24.4.64 20.7.64/65 29.6.65/71 28.5.67 2.2.71/72 10.8.72/73
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ills on fish dro  N5617D  N765FT N965FT  N677RR N962H	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; Apping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball Bell Intercontinental Corp, Mishawaka IN Howard Aero Service/ Alamo Aviation/ Business Aircraft Corp, San Antonio TX Professional Pilot Service Inc Professional Pilot Service Inc Florida Tile Industries Inc Conequip Corp, Evansville IN (mods for E18S-9900 installed 12.66) damaged landing with gear locked-up, Evansville IN Leon F. Roberts Catlin Aviation Co Gary R. Levitz/ Western Aircraft Leasing Co	4.1.90/91 23.5.90/93 3.3.93 8.6.93 21.10.57/58 27.1.58/60 29.7.60/63 31.7.63 7.9.63/64 24.4.64 20.7.64/65 29.6.65/71 28.5.67 2.2.71/72 10.8.72/73 20.4.73/74
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ills on fish dro  N5617D  N765FT N965FT N965FT	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; Apping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball Bell Intercontinental Corp, Mishawaka IN Howard Aero Service/ Alamo Aviation/ Business Aircraft Corp, San Antonio TX Professional Pilot Service Inc Professional Pilot Service Inc Florida Tile Industries Inc Conequip Corp, Evansville IN (mods for E18S-9900 installed 12.66) damaged landing with gear locked-up, Evansville IN Leon F. Roberts Catlin Aviation Co Gary R. Levitz/ Western Aircraft Leasing Co Robert J. Binkley, Shawnee OK	4.1.90/91 23.5.90/93 3.3.93 8.6.93 21.10.57/58 27.1.58/60 29.7.60/63 31.7.63 7.9.63/64 24.4.64 20.7.64/65 29.6.65/71 28.5.67 2.2.71/72 10.8.72/73 20.4.73/74 18.4.74/79
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ills on fish dro  N5617D  N765FT N965FT  N677RR N962H	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; Apping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball Bell Intercontinental Corp, Mishawaka IN Howard Aero Service/ Alamo Aviation/ Business Aircraft Corp, San Antonio TX Professional Pilot Service Inc Professional Pilot Service Inc Florida Tile Industries Inc Conequip Corp, Evansville IN (mods for E18S-9900 installed 12.66) damaged landing with gear locked-up, Evansville IN Leon F. Roberts Catlin Aviation Co Gary R. Levitz/ Western Aircraft Leasing Co Robert J. Binkley, Shawnee OK Southland Flyers Inc	4.1.90/91 23.5.90/93 3.3.93 8.6.93 21.10.57/58 27.1.58/60 29.7.60/63 31.7.63 7.9.63/64 24.4.64 20.7.64/65 29.6.65/71 28.5.67 2.2.71/72 10.8.72/73 20.4.73/74
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ills on fish dro  N5617D  N765FT N965FT  N677RR N962H	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; Apping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball Bell Intercontinental Corp, Mishawaka IN Howard Aero Service/ Alamo Aviation/ Business Aircraft Corp, San Antonio TX Professional Pilot Service Inc Professional Pilot Service Inc Florida Tile Industries Inc Conequip Corp, Evansville IN (mods for E18S-9900 installed 12.66) damaged landing with gear locked-up, Evansville IN Leon F. Roberts Catlin Aviation Co Gary R. Levitz/ Western Aircraft Leasing Co Robert J. Binkley, Shawnee OK Southland Flyers Inc (cargo door & floor, cockpit hatch installed 7.79)	4.1.90/91 23.5.90/93 3.3.93 8.6.93 21.10.57/58 27.1.58/60 29.7.60/63 31.7.63 7.9.63/64 24.4.64 20.7.64/65 29.6.65/71 28.5.67 2.2.71/72 10.8.72/73 20.4.73/74 18.4.74/79 15.5.79/82
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ils on fish dro  N5617D  N765FT N965FT N965FT  N677RR N962H N26BB	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; Opping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball Bell Intercontinental Corp, Mishawaka IN Howard Aero Service/ Alamo Aviation/ Business Aircraft Corp, San Antonio TX Professional Pilot Service Inc Professional Pilot Service Inc Florida Tile Industries Inc Conequip Corp, Evansville IN (mods for E18S-9900 installed 12.66) damaged landing with gear locked-up, Evansville IN Leon F. Roberts Catlin Aviation Co Gary R. Levitz/ Western Aircraft Leasing Co Robert J. Binkley, Shawnee OK Southland Flyers Inc (cargo door & floor, cockpit hatch installed 7.79) Robert A. Younkin, Springdale AR	4.1.90/91 23.5.90/93 3.3.93 8.6.93 21.10.57/58 27.1.58/60 29.7.60/63 31.7.63 7.9.63/64 24.4.64 20.7.64/65 29.6.65/71 28.5.67 2.2.71/72 10.8.72/73 20.4.73/74 18.4.74/79 15.5.79/82 29.1.82/85
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ills on fish dro  N5617D  N765FT N965FT  N677RR N962H	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; Opping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball Bell Intercontinental Corp, Mishawaka IN Howard Aero Service/ Alamo Aviation/ Business Aircraft Corp, San Antonio TX Professional Pilot Service Inc Professional Pilot Service Inc Florida Tile Industries Inc Conequip Corp, Evansville IN (mods for E18S-9900 installed 12.66) damaged landing with gear locked-up, Evansville IN Leon F. Roberts Catlin Aviation Co Gary R. Levitz/ Western Aircraft Leasing Co Robert J. Binkley, Shawnee OK Southland Flyers Inc (cargo door & floor, cockpit hatch installed 7.79) Robert A. Younkin, Springdale AR Robert A. Younkin, Lowell AR	4.1.90/91 23.5.90/93 3.3.93 8.6.93 21.10.57/58 27.1.58/60 29.7.60/63 31.7.63 7.9.63/64 24.4.64 20.7.64/65 29.6.65/71 28.5.67 2.2.71/72 10.8.72/73 20.4.73/74 18.4.74/79 15.5.79/82
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ils on fish dro  N5617D  N765FT N965FT N965FT  N677RR N962H N26BB	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; Opping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball Bell Intercontinental Corp, Mishawaka IN Howard Aero Service/ Alamo Aviation/ Business Aircraft Corp, San Antonio TX Professional Pilot Service Inc Professional Pilot Service Inc Florida Tile Industries Inc Conequip Corp, Evansville IN (mods for E18S-9900 installed 12.66) damaged landing with gear locked-up, Evansville IN Leon F. Roberts Catlin Aviation Co Gary R. Levitz/ Western Aircraft Leasing Co Robert J. Binkley, Shawnee OK Southland Flyers Inc (cargo door & floor, cockpit hatch installed 7.79) Robert A. Younkin, Springdale AR Robert A. Younkin, Lowell AR (fitted c90 with nose-cockpit section from G18S)	4.1.90/91 23.5.90/93 3.3.93 8.6.93 21.10.57/58 27.1.58/60 29.7.60/63 31.7.63 7.9.63/64 24.4.64 20.7.64/65 29.6.65/71 28.5.67 2.2.71/72 10.8.72/73 20.4.73/74 18.4.74/79 15.5.79/82 29.1.82/85
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ils on fish dro  N5617D  N765FT N965FT N965FT  N677RR N962H N26BB	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; Opping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball Bell Intercontinental Corp, Mishawaka IN Howard Aero Service/ Alamo Aviation/ Business Aircraft Corp, San Antonio TX Professional Pilot Service Inc Professional Pilot Service Inc Florida Tile Industries Inc Conequip Corp, Evansville IN (mods for E18S-9900 installed 12.66) damaged landing with gear locked-up, Evansville IN Leon F. Roberts Catlin Aviation Co Gary R. Levitz/ Western Aircraft Leasing Co Robert J. Binkley, Shawnee OK Southland Flyers Inc (cargo door & floor, cockpit hatch installed 7.79) Robert A. Younkin, Springdale AR Robert A. Younkin, Lowell AR (fitted c90 with nose-cockpit section from G18S N5724M/BA-593)	4.1.90/91 23.5.90/93 3.3.93 8.6.93 8.6.93 21.10.57/58 27.1.58/60 29.7.60/63 31.7.63 7.9.63/64 24.4.64 20.7.64/65 29.6.65/71 28.5.67 2.2.71/72 10.8.72/73 20.4.73/74 18.4.74/79 15.5.79/82 29.1.82/85 12.85/91
BA-325	N21FG note further deta	N51FG  ted Tucson A ed Arcata CA ils on fish dro  N5617D  N765FT N965FT N965FT  N677RR N962H N26BB	Ajax Aircraft Leasing Inc, Dover DE op: Active Aero Charter, Willow Run MI ntu: Ajax Aircraft Leasing Inc, Belleville MI crashed dest. on takeoff, Detroit-Willow Run MI AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; A 7.81 trigear turbines; Opping: see Beech 18 by Robert Parmerter p.291;  Roscoe Turner Aeronautical Corp: CofA issued William H. Ball Bell Intercontinental Corp, Mishawaka IN Howard Aero Service/ Alamo Aviation/ Business Aircraft Corp, San Antonio TX Professional Pilot Service Inc Professional Pilot Service Inc Florida Tile Industries Inc Conequip Corp, Evansville IN (mods for E18S-9900 installed 12.66) damaged landing with gear locked-up, Evansville IN Leon F. Roberts Catlin Aviation Co Gary R. Levitz/ Western Aircraft Leasing Co Robert J. Binkley, Shawnee OK Southland Flyers Inc (cargo door & floor, cockpit hatch installed 7.79) Robert A. Younkin, Springdale AR Robert A. Younkin, Lowell AR (fitted c90 with nose-cockpit section from G18S)	4.1.90/91 23.5.90/93 3.3.93 8.6.93 21.10.57/58 27.1.58/60 29.7.60/63 31.7.63 7.9.63/64 24.4.64 20.7.64/65 29.6.65/71 28.5.67 2.2.71/72 10.8.72/73 20.4.73/74 18.4.74/79 15.5.79/82 29.1.82/85

N962H noted Addison TX 29.4.73;

N18RY at Oshkosh 8.99, "Beach House" & "Younkin Air Services, Springdale AR" titles, plate BA-325 built 10.57, another plate: conv. to E18S-9900 12.66; N18RY at Oshkosh 23.7.02 "Beech House"; N18RY visited Beech fly-in, Tullahoma TN 16.10.21;

Parmerter says USCR 7.71 & 1.73 list BA-325 as N977R but the FAA Index Card quotes only N677R as do most other sources. In his Index corrections list (AB-IX 25/6/06) he corrects BA-325 N977RA to N977RR;

BA-326	E18S	N33JD (3 XB-DAC	J. D. Reed Co, Houston TX reg	.57
	Volpar	N88002	reg	
	Centennial	N76MC	Volpar Inc, Van Nuys CA: USCR (prototype <i>Volpar Centennial</i> , conversion begun 8.75, longer fuselage than Turboliner & PT6A turboprops: project sold by Volpar 5.76 to Aerocom Inc)	7.75/76
	Aerocom Skyliner		Aerocom Inc, Reno-Stead NV (conversion continued at Reno .76/77 as prototype <i>Aerocom Skyliner</i> , extra fuselage stretch for 19 pax, single fin, new wing & undercarriage: construction not completed)	5.76/77
			Volpar Inc, Van Nuys CA: USCR stripped fuselage dumped at Volpar, Van Nuys CA, by	79/82 1.79

Aerocom, Reno NV was formed 5.76 as subsidiary of S&G Construction/ Northslope Enterprises, Anchorage AK to acquire design and production rights to the proposed Volpar Centennial development of the Turboliner. Took over Lear Avia plant at Reno-Stead to commence production. Included in the purchase was the uncompleted "Centennial" prototype, which was trucked to Reno to be used as the "Skyliner" prototype: stretched fuselage, all metallic outside a hangar near Volpar's at Van Nuys 1.79; see Beech 18 by Robert Parmerter pp.319, 393;

BA-327 E18S	N5618D (1	reg	.57	
	Coleman Co. Wichita KS	Coleman Co, Wichita KS	63/64	
		N334V	Mississippi Federal Cooperative, Jackson MS	66
			Orion Airways, St Louis MO	69/70
			Sisk Aviation Activities, St Louis MO	70/72
			Northwood Institute, Midland MI	79
			Combs Airways: USCR	91
			J. W. Duff/ Duffy's Aircraft Parts, Denver CO (stored in Duff's salvage yard, Denver 00)	00/15
			Reg expired 31.10.15, struck-off USCR	13.2.18

N334V noted Duffy's yard, Denver CO 7.8.00 standing on wheels, wings removed;

BA-328	E18S	N5619D	Atlantic Aviation Corp	11.57/58
DA-320		113019D	Doubleday & Co. Garden City NY	2.2.58/72
	trigear	NECAOD (O	, , , , , , , , , , , , , , , , , , ,	
		N5618D (2	William F. Burke	27.6.72/73
			Flite Time Inc	10.72/73
			Norwood Institute Corp, Midland MI	4.8.73/81
			John A. Daniels	26.1.81/82
			K & B Aircraft Broker Corp, Miami FL	16.3.82/83
		N729KB	Robert Bennett/ K & B Aircraft Broker Corp, Miami FL	18.9.83/86
			Arrowhead Airways, Blaine MN	12.7.86
		N621AA	Ernie Joyner/ Arrowhead Airways, Blaine MN	10.86/91
			Milton E. Glass, Anoka MN	17.5.91
			Farm Air Flying Service, Sacramento CA	7.12.91/93
		N328N	Wilbert R. Porter, Sacramento CA	20.1.93
			Norman E. Hibbard, Carson City NV	21.4.95/97
			sold to Switzerland: struck-off USCR	12.97
	tailwheel	HB-GJG	Adventure Flight AG, Zurich	22.12.97/01
			(based Buochs, Switzerland 01/03, flying in	
			US Navy red/white scheme "328", name Rosmarie)	

N5619D noted La Guardia NY 31.3.72 trigear;

HB-GJG trigear noted Stans-Buochs 25.4.01 & 2.7.01 red nose;

HB-GJG listed with aircraft of members of Antique Airplane Association of Switzerland 01;

HB-GJG noted Buochs, Switzerland 26.10.01, 1.7.02: both USN scheme, tailwheel, i/s;

HB-GJG noted Buochs 20.12.01 US Navy red & white scheme, tailwheel;

D-IROM noted Buochs 22.3.03 US Navy red/white scheme, no titles;

D-IROM noted Oberschleissheim, Germany 9.7.05 flying, tailwheel, USN red/white;

D-IROM noted Oberschleissheim 22.7.06, tailwheel, USN red/white scheme;

BA-329	E18S	N398B	Lang Aircraft: CofA issued	7.11.57/58
	-9700		Robert L. Graf	26.2.58/59
			Bankers Life Insurance of Nebraska	16.2.59/60
			Delhi-Taylor Oil Corp	7.6.60/63
			Florida Gas Transmission Co, Miami FL	19.4.63/68
			collided with automobile while taxying for departure,	
			Fort Lauderdale FL	27.1.65
			Ross Aviation, Tulsa-Riverside OK	12.68/69
			Great Western Airlines, Tulsa-Riverside OK	70/76
			Sam Vires/ Mid-South Aircraft Sales, Memphis TN	10.76/77
			American Lease Plan Inc, Charlotte NC	15.3.77/81
			Ralph Quinlan/ Mountain Air Cargo, Denver NC: Isd	16.3.77/86
			(Aerospace Products cargo door & cockpit door installed 5.77)	
			op: General Aviation Inc, Greenville TN	80
			Equipment Leasing Corp, Greenville SC	11.2.81/84
			Coastal States Aviation, Denver NC	1.2.85/86
			Union Flights, Sacramento CA	9.6.86/92
			Del Caribbean Corp, San Juan, Puerto Rico	21.7.92/97
			Tol Air Services, San Juan, Puerto Rico	27.6.97/99
			MBD Corp, San Juan, Puerto Rico	8.2.99/00
		N748T	MBD Corp, San Juan, Puerto Rico	14.3.01/13
			op: Tol Air Services, San Juan, Puerto Rico	99/10
			reg expired 30.9.13, struck-off USCR	26.1.18

N398B noted SFO 6.59 "Bankers Life Insurance of Nebraska" titles;

N398B noted LAX 6.11.87;

N398B noted St Croix USVI 1.98 "Tolair";

N748T noted San Juan PR 27.3.05 all metallic, windows faired over, no titles, tailwheel, in service; N748T photo in service Tol Air at Puerto Rico 5.10, all metallic, windows faired over;

E18S	N78A	Beech Aircraft Corp, Wichita KS: CofA issued	18.11.57/58
		Flightcraft Inc	7.8.58
	N2424 (2	Cheney Forest Products, Central Point OR	10.58/74
trigear		(Volpar Mk.IV trigear installed 3.64)	
		Frederick W. & Mary Jo Lawless	25.4.74
		Hollywood Flying Service	15.8.74/77
		Smithville Flying Service	17.1.77
		Sam Vires/ Mid-South Aircraft Sales, Memphis TN	22.8.77/78
		International Transfer Corp	22.9.78/80
		op: Pro Air Services, Opa Locka FL	79
		Harold E.Valley, Glenwood Springs CO: USCR	79
		Billy W. Mahaffey	1.8.80
		seized at Belize Airport with 1500lb marijuana:	
		Mahaffey & J. R. Sirmons arrested	30.8.80
		Government of Belize: impounded	1.9.80/81
		Raymond Weir, Belize	19.1.81
	N24JE	James Eakes & Robert L. Ross	22.1.81/83
		T. E. De Mint/ Astro Airways Corp, Pine Bluff AR	18.3.83/89
		(cabin cargo floor installed 1.86)	
			,
		both landed safely, Natchez MS	9.12.87
	N446DM	T. E. De Mint/ Astro Airways Corp, Pine Bluff AR	28.4.89/91
		Thomas M. Rawlins, Newcastle CA	11.1.91/95
		Alma D. Mallard, Idaho Falls ID	17.8.98/13
		N2424 (2 trigear	Flightcraft Inc  N2424 (2 Cheney Forest Products, Central Point OR  (Volpar Mk.IV trigear installed 3.64) Frederick W. & Mary Jo Lawless Hollywood Flying Service Smithville Flying Service Sam Vires/ Mid-South Aircraft Sales, Memphis TN International Transfer Corp op: Pro Air Services, Opa Locka FL Harold E.Valley, Glenwood Springs CO: USCR Billy W. Mahaffey seized at Belize Airport with 1500lb marijuana: Mahaffey & J. R. Sirmons arrested Government of Belize: impounded Raymond Weir, Belize  N24JE  N24JE  N24JE  James Eakes & Robert L. Ross T. E. De Mint/ Astro Airways Corp, Pine Bluff AR (cabin cargo floor installed 1.86) minor damage in midair collision with Beech 18 N492DM both landed safely, Natchez MS  N446DM  T. E. De Mint/ Astro Airways Corp, Pine Bluff AR Thomas M. Rawlins, Newcastle CA

struck-off USCR 7.6.13

N2424 noted Miami FL 3.10.78 trigear;

accident report 9.12.87: midair collision while cruising on positioning flight, both aircraft had same owner Aerovation Inc;

N446DM noted Flores, Guatemala 11.11.94 at airfield near Tikal Ate ruins;

Stripped E18S trigear hulk derelict at Flores, Guatemala 1.18, assumed this aircraft;

BA-331	E18S	N200UP	Upjohn Co	.58/61
		N208UP	Upjohn Co	22.5.61
		N208UB	Upjohn Co	16.6.61
			Francis Aviation, Lansing MI	63
			Louis F. Dow Co, St Paul MN	64/65
			prop failed, left engine separated from airframe,	
			crashed into water, destroyed by fire, Henderson KY	3.1.65

N208UB crash report: left propeller blade failure in flight over Henderson KY and left engine separated from airframe, came to rest in water, post-impact fire, 4k;

BA-332	E18S	N5621D	built	.58
		N724A	Anaconda Aluminum Co, Louisville KY	63/64
		N724AA	Poulan Beaird Inc, Shreveport LA	66/72
			Emerson Electric, Shreveport LA	78
			John R. Webster, Shreveport LA	12.1.79/82
			sold to Cayman Islands, struck-off USCR	23.7.82
BA-333	E18S	N19M	built	.58
	-9700		(mods to E18S-9700 completed 14.5.59)	
			Mellon National Bank, Pittsburgh PA	63/64
		N190X	Mellon National Bank, Pittsburgh PA	66
			Equitable Leasing Corp, Rochester NY	69/70
			op: Del Airways	70
		CF-ANA	Port Colburne Flying Service t/a Air Niagara,	
			St Catharines ONT	2.70/73
			tail blown into fence by windstorm while parked,	
			St Catharines ONT	14.8.72
			Collingwood Air Services	.73
			Laurentian Air Services Ltd, Ottawa ONT	76/78
			Skycraft Air Transport, Oshawa ONT	78/83
		C-FANA	Skycraft Air Transport, Oshawa ONT	84/93
			sold to USA, struck-off Canadian Register	9.93
		N5847	One Way Ride Inc, Portersville PA	9.93
		N5867	One Way Ride Inc, Portersville PA	16.9.93/99
			Jay D. Swarthout, Windsor CA (flew as "USAF WZ-333 <i>Tuff</i> " & "US Marines WZ333 Air FMF PAC")	24.4.00/02
			Jimmy Rollison, Nut Tree Airport, Vacaville CA	03/05
			Michele E. Yarbrough, Vacaville CA	17.8.05/20

CF-ANA noted Montreal-Dorval 27.2.71 Air Niagara;

CF-ANA noted Toronto-Malton ONT 26.3.71 Air Niagara title, tailwheel;

CF-ANA noted Youngstown OH 17.6.81 Skycraft;

C-FANA noted Oshawa ONT 8.84 "Skycraft" titles, tailwheel;

N5867 noted Vacaville-Nut Tree CA 7.6.02 "WZ-333" plate BA-333;

N5867 at fly-in Oshkosh 30.7.03 owned Jim Rollison, Vacaville CA, "US Marines WZ333 Air FMF PAC", plate BA-333 built 12.57, another plate -9700 conversion 14.5.59,;

N5867 at fly-in Merced CA 4.6.04 "333";

N5867 at Oshkosh WI fly-in 7.15;

BA-334	E18S	N5622D	built	.58
		N140J	Continental Oil Co, Houston TX	63/66
			Hankins Airways, Jackson MS	69/72
			PBF Enterprises Inc, North Canton OH	75
			op: Burlington Airways, Burlington WI	75
			crashed destroyed, Argos IN, forced landing in woods	

N140J accident report 1.4.75: Burlington Airways, flight Indianapolis IN to South Bend IN, fire in cabin & cockpit, struck trees, destroyed by fire 1.30am, pilot k;

BA-335	E18S	N5624D	Anderson Air Activities: CofA issued	13.12.57/58
-9	-9700		Twin Disc Clutch Co, Racine WI	25.8.58/64
			Marshall & Isley Bank, Milwaukee WI	10.64/68
	trigear		(Volpar Mk.IV trigear & Beech kit for Skywide G18S	
			panoramic window replacing two middle cabin windows	
			on both sides installed 10.64)	
			Air Journeys Inc, Little Rock AR	10.68/69
		N111EH	Air Journeys Inc, Little Rock AR	3.10.69/71
			James R. Laird & Associates Inc, Appleton WI	15.3.71/72
			Corporate Air Inc	29.6.72/74
			minor damage landed with nose gear down,	
			main gear locked-up, Windsor Locks-Bradley CT	19.12.73
			Frederick W. & Mary Jo Lawless	1.8.74/75
			Sam Vires/ Mid-South Aircraft Sales, Memphis TN	7.3.75
			Colonial Airlines	29.7.75/76
			Troy J. Sandifer	10.76/77
			North American Publishing Co, Houston TX	1.2.77/87
			Diamond Bar C	11.87/90
			Tom Neal, Pasadena CA	23.1.90/91
		N111TN	Tom Neal, Long Beach CA	8.8.91/93
			Patrick J. Foley, Middletown DE	22.5.93/94
		N57PF	Patrick J. Foley, Middletown DE Class of '57	2.94/02
			Charles W. Schooley, West Palm Beach FL	23.1.04/06
			H. Anthony Miller Jnr LLC, Warsaw IN	30.10.07
		N90TT	H. Anthony Miller Jnr LLC, Warsaw IN	8.1.08
			Monroe Motors Inc, Colorado Springs CO	11.12.09/12
			Beech Eighteen Aviation, Birmingham AL	25.4.12/14
			Michael Blackstone/ Skythrills LLC, Fullerton CA	10.9.14/20
			(flew as "Blackstone Airlines", executive cabin)	

accident report 19.12.73: Corporate Air, flight Windsor Locks to New York, returned to Bradley due gear problem, minor dam., 6 unhurt;

N111TN noted Chino CA 7.91 trigear;

N57PF at Oshkosh WI 7.97 trigear, allover red scheme, plate BA-335 built 12.57; N57PF owned Pat Foley up for sale 1.00 at Dutchess County Airport NY; N57PF noted Danbury CT 2.9.00 allover red scheme, retired but looks flyable; N90TT at Oshkosh 7.08, Tony Miller, Warsaw IN, plate BA-335 built 12.57;

BA-336	E18S	N5625D	built	.58
			left gear collapsed landing, Sandston VA	4.62
			(repaired at Sandston-Byrd Field VA)	
			Silas King, Portland OR	63/64
			Nevadair Co, Boulder City NV	66
			Lease Air Inc, San Diego-Montomery Field CA	69/72
			Virginia Financial Corp, Lathrp Wells NV	6.7.76/77
			struck-off USCR	8.7.77
	N5625D	noted Oakland	d CA 11.9.71;	
BA-337	E18S	N5626D	Alamo Aviation, San Antonio TX	16.1.58
BA-337	E18S -9700	N5626D	Alamo Aviation, San Antonio TX H. E. Butt Grocery Co, Corpus Christi TX	16.1.58 5.5.58/71
BA-337		N5626D	•	
3A-337		N5626D	H. E. Butt Grocery Co, Corpus Christi TX	5.5.58/71
BA-337		N5626D	H. E. Butt Grocery Co, Corpus Christi TX (two piece G18S type windshield fitted 6.67)	5.5.58/71
BA-337		N5626D	H. E. Butt Grocery Co, Corpus Christi TX (two piece G18S type windshield fitted 6.67) A. G. Wise Trucking, Grapevine TX	5.5.58/71 13.2.71/72
BA-337		N5626D	H. E. Butt Grocery Co, Corpus Christi TX (two piece G18S type windshield fitted 6.67) A. G. Wise Trucking, Grapevine TX Precision Flight Navigation Co Adcock Farms, Mer Rouge LA James R. Latta/ Latco Inc	5.5.58/71 13.2.71/72 7.2.72/76 11.76/78
BA-337		N5626D	H. E. Butt Grocery Co, Corpus Christi TX (two piece G18S type windshield fitted 6.67) A. G. Wise Trucking, Grapevine TX Precision Flight Navigation Co Adcock Farms, Mer Rouge LA James R. Latta/ Latco Inc Robert A. Younkin, Springdale AR	5.5.58/71 13.2.71/72 7.2.72/76
BA-337		N5626D	H. E. Butt Grocery Co, Corpus Christi TX (two piece G18S type windshield fitted 6.67) A. G. Wise Trucking, Grapevine TX Precision Flight Navigation Co Adcock Farms, Mer Rouge LA James R. Latta/ Latco Inc	5.5.58/71 13.2.71/72 7.2.72/76 11.76/78 28.8.78/82
BA-337		N5626D	H. E. Butt Grocery Co, Corpus Christi TX (two piece G18S type windshield fitted 6.67) A. G. Wise Trucking, Grapevine TX Precision Flight Navigation Co Adcock Farms, Mer Rouge LA James R. Latta/ Latco Inc Robert A. Younkin, Springdale AR	5.5.58/71 13.2.71/72 7.2.72/76 11.76/78 28.8.78/82 10.82/83
BA-337		N5626D	H. E. Butt Grocery Co, Corpus Christi TX (two piece G18S type windshield fitted 6.67) A. G. Wise Trucking, Grapevine TX Precision Flight Navigation Co Adcock Farms, Mer Rouge LA James R. Latta/ Latco Inc Robert A. Younkin, Springdale AR Todd Orlando Ham, Opdyke IL	5.5.58/71 13.2.71/72 7.2.72/76 11.76/78 28.8.78/82 10.82/83 25.2.83/86

		N916TM	sold to USA: struck-off Canadian Register May Air Xpress Inc, New Boston TX (US CofA issued 2.2.93: fitted with cargo door) Scott R. Michels, New Boston TX op: May Air Xpress, New Boston TX struck ground during aborted takeoff, Lake Elmo MN John W. Westling, Princeton MN struck-off USCR	11.92 11.92/95 5.12.95/01 95/97 2.10.97 11.7.02/05 6.10.05
	C-GEVR no	ted Toronto	ONT 4.8.89 "Air 500" tailwheel;	
BA-338	E18S -9700	N5627D	Currey Sanders Aircraft Co Canam Co	16.1.58 4.2.58/61
	trigear	N503N (2	Northern Natural Gas Co, Omaha NE Northern Natural Gas Co, Omaha NE (Volpar trigear installed 8.62)	11.1.61 27.2.61/64
			Aeronaut Air Service, Birmingham AL David A. McCoy/ Aircraft Leasing Co John R. Tarry & Theodore C. Walker/ T-W Enterprises,	4.4.64/67 25.5.67/68
			Elyria OH Sundorph Aeronautical Corp, Cleveland OH (Beech cargo door installed 4.70)	2.3.68/69 10.1.69/70
			Fred W. Johnson Funeral Home, St Paul MN Midwest Air Service, Fenton MO (copilot exit door installed 1.78)	12.70/73 2.7.73/92
			George R. Kabeller, Zephyrhills FL	26.7.92/94
			Hanair International Inc, Miami FL	31.3.94/95
			Carib Air Cargo, Lantana FL overturned by windstorm, Miami FL	26.5.95 2.2.98
			Hartford Holding Corp, Wilmington DE	10.2.98
			struck-off USCR: scrapped	14.4.98
			t'l TX 21.3.63, trigear; a 95: trigear, all metallic "Hanair" titles;	
BA-339	E18S	N5628D	Lopez-Grace Aviation: CofA issued R. D. Keene, Winter Garden FL Wesley Y. Bragg & Kenneth W. Andrews, Edgewater NJ Sam Vires/ Mid-South Aircraft Sales, Memphis TN	8.1.58 9.1.58/68 24.4.68/77 28.1.77
		N71SV	Sam Vires/ Mid-South Aircraft Sales, Memphis TN Sting Stables, Santa Rosa CA Fred Ayres: sale documentation not completed sale reported, Oakland CA: USCR	1.9.77 8.10.77/83 21.11.83 20.5.85/91
	N5628D no	ted Sky King	IN 30.5.76;	
BA-340	E18S	N72V	built	.58
			Tulsair Distributors Inc, Tulsa OK	63/64
			Executive Air Transport, Muskegon MI Aero American Aviation, Chicago-Du Page IL	66/72 22.2.77
			groundlooped landing, struck ditches, Atlanta GA (stolen aircraft, 2000lb over gross weight)	23.9.77
	N72V noted	l Chicago-Me	eigs Field 23.9.70;	
BA-341	E18S	YV-O-IVP-2		3.58
		YV-O-MMH	-2 Min. de Hacienda de Venezuala	9.66
		YV-T-ETB YV-C-FLB	rereg Aeractividades Venezolanas SA - AVSA	12.67 .72
BA-342	E18S	N5633D	Ohio Aviation Co, Dayton OH: dealer sold to West Germany, struck-off USCR	.58 13.8.58
		D-IEHL	Diehl Metalwerke, Nurnberg	.58/60
		D-IEHU	Travelair GmbH & Co, Bremen	4.61
		E DUO.	sold to France	7.62
		F-BHOG	Ste France Entretien et Reparation Materiel Aeronautique	<del>;</del> -

			S.F.E.R.M.A., Bordeaux Ste de'Achats Reparations et Ventes Automoibiles Aerospatiale Societe Nationale Indiustrielle, Paris op: Sud Aviation, Toulouse Air Continent, Cannes Aviasud, Nice Nantes Aviation, Chateau-Bougon accident	8.4.63 8.4.63/65 16.4.65/71 67/71 17.9.71/74 12.5.74/77 25.1.77/80 4.80
	D-IEHU a D-IEHU vi F-BHOG i	isited Gatwick noted Le Bournoted Dublin in noted Hurn 4. noted Gatwick noted Elton 3. noted Le Bournoted Elton 3. noted Gatwick noted Birming noted Paris-Lenoted Toussu.	ol 16.12.61 from Birmingham, Travelair GmbH; 1.2.62; 1.8.63 from/to Le Bourget SFERMA; 5.66 from Filton to Le Bourget; 20.8.66, 28.8.66; 6.8.66; 5.9.66; 1.9.67; 1.6.67 Sud Avtn; 1.7.67; 1.68 Sud Avtn; 1.68 Sud Avtn; 1.69 Sud Avtn; 1.60 Sud Avtn;	;
BA-343	E18S	4R-AAR	Ceylon Department of Survey, Colombo (donated as aid by US Government, fitted for photographic survey prior to delivery, delivered ex Wichita KS by Flightways Inc) crashed on delivery flight, landing Naples, Italy	1.58
	further de crashed 3	tails see Beed miles west of	ch 18 by Robert Parmerter p.281; f Naples, on delivery flight: see BA-376, BA-433;	
BA-344			Page Airways Inc, Rochester NY Timmins Aviation Ltd, Montreal QUE Department of Colonizatrion, Quebec City QUE Department of Transport & Communications, Quebec City QUE dam. ran off runway on takeoff Quebec Airport QUE Helisolair Ltd, Montreal QUE Aviation Sales International, Montreal QUE Desjardins Sauriol & Associates, Laval QUE Eli Graubart/ Air Exchange Inc, Wheeling IL (ferry permit 10.73 Montreal to Chicago) Floyd Carson, Burlingon ONT (Canadian recertification 11.73 at Brantford ONT) J. C. Turcan, Calgary ALTA Eli Graubart/ Air Exchange Inc, Wheeling IL Dixie Flight Centre Inc, Memphis TN Thomas L. Stinson, Lake City FL crashed near Cartagena, Colombia (crew injured but not found)	.58 25.4.58 24.2.60/70 22.3.60 16.12.70 25.3.71 5.4.72 1.10.73 16.11.73 6.12.73 12.11.74 22.11.74 3.75 31.3.75
BA-345	E18S trigear	N5637D	built Wyatt C. Hedrick, Fort Worth TX Wallace-Tiernan Inc, Bellevue NJ Volpar trigear collapsed while taxying after landing,	.58 63/64 66

Hatteras-Mitchell NC Television Communications Corp, New York NY N610TV Television Communications Corp, New York NY N76AL Television Communications Corp, New York NY 70/7	
N76LA Colorado Seafood Supply, Denver CO 78	
Cargo Air Inc, Houston TX 79	
midair collision with Baron N12WF near	
Fort Lauderdale FL: both landed safely 3.1.	79
crashed landing near Homestead FL, marijuana on board,	
struck earthbank and parked Cessna 182 N7187E 23.6	3.79
(aircraft reported stolen, 2 arrested)	
Hanger Two Inc, Miami FL 7.5.	81/84
struck-off USCR 29.1	10.84
(wreck stored at fire service, Texarkana TX 03)	

N610TV noted Teterboro NJ 20.7.71;

N76LA noted Greater Wilmington DE 2.9.74 trigear;

N76LA noted Miami FL 28.10.78 no titles; N76LA noted Miami FL 12.78 Cargo Air; N76LA accident report 23.6.79: stolen aircraft crashed on landing Goldstein strip near

Homestead FL, pilot & 1 pax unhurt, arrested for possession of marijuana; N76LA noted Opa Locka FL 18.7.81;

N76LA reported to be at airport fire station, Texarkana TX 6.8.03 - not sighted;

BA-346	E18S	N5632D	Atlantic Aviation Corp: CofA issued	10.2.58
_,	-9700		Carpenter Paper Co, Omaha NE	11.58/63
	0.00		Lamar T. Zimmerman, Pottstown PA	11.63/65
			landed gear-up, Reading PA	29.8.64
			Corporate Air Transport, Chicago IL	23.6.65/70
			accident, Negaune MI	6.2.66
			Northern Iowa Express, Des Moines IA	19.5.70
			SMB Stage Line, Des Moines IA	10.70/71
			Thomas Brickley, Festus MO	8.4.71/72
			Festus Flying Service, Festus MO	12.72/75
			(Aerospace Products cargo door installed 1.73)	12.72/10
			damaged struck poles landing, Urbana-Mad River OH	30.8.73
			Charles E. Bush/ Bush Aviation, Ft Lauderdale FL	2.2.75/76
			Avair Inc, Orlando FL	24.9.76/78
			Thomas W. May, New Boston TX	12.78/80
			(cargo floor & crew door installed 1.79)	12.70/00
			Cathryn E. Tedder/ CMT Leasing, Texarkana TX	15.5.80
			op: ABC Airlines Inc, Dallas-DFW TX	81
			James L. Hudson, Mesquite TX	24.4.81/91
			ARC Airlings Inc. Dallas DEW TY: leased	12 21/26
	N5632D	noted Et I aud	ABC Airlines Inc, Dallas-DFW TX: leased Texas State Technology Institute: inst. airframe	12.81/86 -
BA-347	E18S	noted Ft Laud	Texas State Technology Institute: inst. airframe  erdale FL 15.9.76;  ferry reg	.58
BA-347			Texas State Technology Institute: inst. airframe erdale FL 15.9.76;	-
	E18S		Texas State Technology Institute: inst. airframe  erdale FL 15.9.76;  ferry reg	-
	E18S U45	PP-FMN	Texas State Technology Institute: inst. airframe  ferdale FL 15.9.76;  ferry reg FA Brasileira as U45 FAB 2883  built	.58
	E18S U45	PP-FMN N5634D	Texas State Technology Institute: inst. airframe  Serdale FL 15.9.76;  ferry reg FA Brasileira as U45 FAB 2883  built Chotin Transportation Inc, New Orleans LA	.58
BA-347 BA-348	E18S U45	PP-FMN	Texas State Technology Institute: inst. airframe  Serdale FL 15.9.76;  ferry reg FA Brasileira as U45 FAB 2883  built Chotin Transportation Inc, New Orleans LA Permian Mud Service Inc, Odessa TX	.58 .58 63
	E18S U45	PP-FMN N5634D N14V (2	Texas State Technology Institute: inst. airframe  Serdale FL 15.9.76;  ferry reg FA Brasileira as U45 FAB 2883  built Chotin Transportation Inc, New Orleans LA	.58 .58 63 64/72
	E18S U45 E18S	PP-FMN  N5634D  N14V (2  N14VH	Texas State Technology Institute: inst. airframe  Serdale FL 15.9.76;  ferry reg FA Brasileira as U45 FAB 2883  built Chotin Transportation Inc, New Orleans LA Permian Mud Service Inc, Odessa TX Hamilton Aviation, Hamilton OH	.58 .58 63 64/72 73/75 24.11.75
	E18S U45 E18S	PP-FMN  N5634D  N14V (2  N14VH	Texas State Technology Institute: inst. airframe  Serdale FL 15.9.76;  ferry reg FA Brasileira as U45 FAB 2883  built Chotin Transportation Inc, New Orleans LA Permian Mud Service Inc, Odessa TX Hamilton Aviation, Hamilton OH crashed after takeoff, Fort Wayne IN	.58 .58 63 64/72 73/75 24.11.75
BA-348	E18S U45 E18S N14VH a mushed i	PP-FMN  N5634D  N14V (2  N14VH  accident report	Texas State Technology Institute: inst. airframe  Serdale FL 15.9.76;  ferry reg FA Brasileira as U45 FAB 2883  built Chotin Transportation Inc, New Orleans LA Permian Mud Service Inc, Odessa TX Hamilton Aviation, Hamilton OH crashed after takeoff, Fort Wayne IN  24.11.75: Hamilton Aviation, takeoff for mail flight to India ce on airframe, 9.53pm, pilot unhurt;	.58 .58 63 64/72 73/75 24.11.75
BA-348	E18S U45 E18S N14VH a mushed i	PP-FMN  N5634D  N14V (2  N14VH  accident report in on takeoff, i	Texas State Technology Institute: inst. airframe  Serdale FL 15.9.76;  ferry reg FA Brasileira as U45 FAB 2883  built Chotin Transportation Inc, New Orleans LA Permian Mud Service Inc, Odessa TX Hamilton Aviation, Hamilton OH crashed after takeoff, Fort Wayne IN  24.11.75: Hamilton Aviation, takeoff for mail flight to India ce on airframe, 9.53pm, pilot unhurt;  Currey Sanders Aircraft Co: CofA issued	.58 .58 63 64/72 73/75 24.11.75 anapolis IN,
BA-348	E18S U45 E18S N14VH a mushed i	PP-FMN  N5634D  N14V (2  N14VH  accident report in on takeoff, i  N5635D  (D-IDIM)	Texas State Technology Institute: inst. airframe  Perdale FL 15.9.76;  ferry reg FA Brasileira as U45 FAB 2883  built Chotin Transportation Inc, New Orleans LA Permian Mud Service Inc, Odessa TX Hamilton Aviation, Hamilton OH crashed after takeoff, Fort Wayne IN  24.11.75: Hamilton Aviation, takeoff for mail flight to India ce on airframe, 9.53pm, pilot unhurt;  Currey Sanders Aircraft Co: CofA issued ntu	.58 .58 63 64/72 73/75 24.11.75 anapolis IN,
BA-348	E18S U45 E18S N14VH a mushed i	PP-FMN  N5634D  N14V (2  N14VH  accident report in on takeoff, i  N5635D  (D-IDIM)	Texas State Technology Institute: inst. airframe  Perdale FL 15.9.76;  ferry reg FA Brasileira as U45 FAB 2883  built Chotin Transportation Inc, New Orleans LA Permian Mud Service Inc, Odessa TX Hamilton Aviation, Hamilton OH crashed after takeoff, Fort Wayne IN  24.11.75: Hamilton Aviation, takeoff for mail flight to India ce on airframe, 9.53pm, pilot unhurt;  Currey Sanders Aircraft Co: CofA issued ntu Dayton Steel Foundry Co	.58 .58 63 64/72 73/75 24.11.75 anapolis IN,  26.2.58/59 .59 19.1.59/62

		N872L	gear collapsed during landing, Columbus OH Jasper Aviation Southeastern Beechcraft Inc, Knoxville TN UC Leasing Inc, Memphis TN UC Leasing Inc, Memphis TN Regalair Inc Safe Wings Inc/ Lake Norman Aviation AM Air Corp, Southern Pines NC sale rep., Huntington NY destroyed in accident in Mexico	26.4.67 21.3.70 30.7.70 11.70/72 12.72/74 4.3.74/75 25.2.75/76 23.2.76/77 77 6.77
BA-350	E18S	N21Z	built Lockport Felt Company, Newfane NY	.58 63
		N711L (3 N177X (1 N1770 N877GP	rereg Harper Sibley, Rochester NY rereg Georgia Pacific Corp, Portland OR struck-off USCR	63/64 65/66 67/68 2.7.68/71 23.2.71
	N877GP no	oted Portland		23.2.71
BA-351	E18S	N5638D	built	.58
		N330D N330DW	Precision Scientific Co, Chicago IL Executive Airlines, Chicago IL Horizons Aviation Enterprises, Chicago IL Galt Flying Service, Ringwood IL crashed destroyed in forced landing, Lansing IL	63/64 66 69/70 25.5.71/74 13.7.74
	N330DW n	oted Chicago	o-O'Hare 23.9.70;	
BA-352	E18S	N87D (1 N4F (3 N4845	Youngstown Airways/ Lease Air, Youngstown OH: CofA Latrobe Construction Co, Latrobe PA Montgomery Aviation Corp, Montgomery AL Semo Aviation Inc, Malden MO Trans Air Cargo Inc, Ottumwa IA derelict hulk at Monterrey, Mexico	12.3.58 63/69 70/72 78/81 10.3.81/91 01
	photo: all n	netallic strippe	A 19.8.81 tailwheel, all metallic; ed hulk, large freight doors, no engines, tailwheel, al Airport, Mexico c01, photo of plate shows E18S BA-352	;
BA-353	E18S	N5639D	Beech Aircraft Corp, Wichita KS: CofA issued Flight Service Inc, Syracuse-Hancock Field NY Niagara Mohawk Power Corp, Syracuse NJ minor damage, struck taxiway sign, Newark NJ	17.3.58 63/64 66/72 20.6.75
		N705M	American Lease Plans, Charlotte NC op: Mountain Air Cargo, Denver NC op: General Aviation Inc, Greenville TN crashed destroyed on takeoff, Bradley CT	6.78/79 79 79 19.9.79
	N5639D no	oted Syracuse	e NY 27.8.74;	
BA-354	E18S	N5648D N212LM	built L. M. Berry & Co, Dayton OH Capitol City Underwriters, Indianapolis IN Granville Leasing Co, Chicago IL	.58 63/64 66 69/70
		CF-STJ	Norman Aircraft Ron Michaluk/St. Andrews Airways, Winnipeg MAN dam. gear-up landing St Teresa Point MAN struck cargo on ramp taxying Island Point MAN main gear collapaed landing Island Lake MAN	71 10.71/77 5.1.74 25.8.75 25.5.76
		N46952	(ferry permit Winnipeg to USA 4.77) Burlington Airways, Burlington WI (US CofA issued 4.8.77) struck fence in forced landing off-airport in fog,	23.4.77/80

## N46952 noted Opa Locka FL 13.10.79;

N46952 accident report 7.12.78: Burlington Airways, cargo flight Chicago to Indianapolis, fuel exhaustion, 7.47am, pilot unhurt;

BA-355	E18S -9700	N5640D	Beech Aircraft Corp, Wichita KS: CofA issued Californian Oil Co, Denver CO Chevron Oil Co, Denver CO Allegheny Leasing Corp, Baltimore MD Saint Aircraft Inc, St Petersburg FL	24.3.58 63/64 66 69 70
			Herbert E. Guynn, St Petersburg FL	71/72
			op: Sun Airline Inc	72
			swung landing, gear collapsed, Tallahassee FL	27.4.72
			Leo Overturf, Mena AR sale reported, American Fork UT: USCR	79 27.12.80/91
			J. W. Duff/ Duffy's Aircraft Parts, Denver CO	00
			(stored in Duff's salvage yard, Denver 00)	
	N5640D		FL 25.9.70; t 27.4.72: Sun Airline Inc, swerved landing, 6 unhurt; Denver CO 7.8.00 fuse only seen;	
BA-356	E18S U45	PP-FMO	ferry reg FA Brasileira as U45 FAB 2882	.58
	045	PT-KUU	Rico Taxi Aereo Ltda, Manaus	11.76/83
		11100	Taxi Aereo Rondonia Ltda, Santarem	6.77/79
BA-357	E18S	N5643D	built	.58
			Harcon Aircraft Inc, Miami FL	63/64
			South State Service Co, Tallahassie FL ANS Corp, Milburn NJ	66/72 79
			Gilley Airways Corp, Fulton-Oswego County NY	29.1.79/91
	N5643D	noted Schene	ctady NY 12.8.74;	
3A-358	E18S	N5645D	built	.58
			damaged, struck eagle at 8500 feet, Lamont WY	16.3.60
			Corporate Air Industries Inc, Long Beach CA Indianapolis Morris Plan Corp, Indianapolis IN	63
			crashed destroyed in forced landing, near Delta UT	1.7.63/64 5.3.64
3A-359	E18S	N23J	built	.58
			Kentucky Dept. of Aeronautics, Frankfort KY	63/69
			reg. pending	70
			Turb Air Inc, Miami FL (based in France 71/73 as N23J)	71/72
		F-BTCS	Fernand Gaspe/ Pyrenair Gaspe, Pau-Idron	22.11.73/83
		F-AZEJ	Amicale Jean-Baptiste Salis, La Ferte-Alais (flew as Luftwaffe "BT+CS", later RAF "436904", later USAAC "22425/V")	26.8.83/21
			badly dam. ran off runway on takeoff, La Ferte-Alais	12.9.21
			badiy daiii. faii on faiiway on takoon, Ea f ofto Aldio	.2.0.21

F-BTCS resident Montpellier 72-74 owned F. Gaspe;

F-BTCS noted La Ferte Alais 5.6.83;

F-AZEJ noted La Ferte Alais 18.6.91 "436904";

F-AZEJ flying at airshow La Ferte-Alais 6.95, barrel rolls;

F-AZEJ noted La Ferte Alais 6.7.96;

F-AZEJ at fly-in Le Tourquet 21.9.02 allover dark colour USAAC "22425";

F-AZEJ noted La Ferte Aais 18.11.03 "22425";

F-AZEJ noted La Ferte Alais 15.5.05, flying USAAC "22429/V";

F-AZEJ noted La Ferte Alais 4.6.06 flying "22425/V";

F-AZEJ noted Orleans-Bricy 10.6.06,

F-AZEJ noted Lyons-Bron 17.6.06 USAAC "V", tailwheel;

BA-360	E18S	N5644D	Raytheon Manufacturing, Bedford MA	.58		
271 000	-9700		North American Aviation Inc, Columbus OH	63/66		
			North American Rockwell Corp, El Segundo CA	69/70		
			G. J. Douglas, Azle TX	71/72		
			Semo Aviation Inc/Semo Airways, Malden MO	78/84		
			damaged ran off taxiway, Birmingham AL	26.6.78		
			Air Machines & Services Inc, St James MO	5.84		
			Coast Air Freight Inc, Long Beach CA	6.85/86		
			Gold Coast Air Inc, Hawthorne CA	1.87		
			sale reported, Salt Lake City UT	91/99		
			David C. Smith, Brewster WA	18.5.00/06		
			Clifton A. Parkhill, Oxnard CA	14.10.09/20		
	N5644D noted LAX 25.6.85 Coast Air Freight, no titles; N5644D noted Van Nuys CA 7.4.87, 10.87;					
			ys 9.11.87 "Coast Air Freight, Long Beach CA";			
BA-361	E18S	N4369D	built	.58		
		N458X	Jervis B. Webb Co, Detroit MI	63/64		
		N48X	Jervis B. Webb Co, Detroit MI			
		N458X	Jervis B. Webb Co, Detroit MI	66		
			Northern Airlines, St Marys OH	69/70		
			Great Western Airlines, Tulsa-Riverside OK	74/77		
			struck-off USCR	8.7.77		
BA-362	E18S	N24J	built	.58		
			Packaging Corp of America, Grand Rapids MI	63/66		
			J. W. Woodward, Little Rock AR	69/70		
			George Summers, Parowan UT	18.6.73/91		
BA-363	E18S	N4331D	Beech Aircraft Corp, Wichita KS: CofA issued	10.6.58		
			Fred G. Reed, Chicago IL	63		
			Addison Products Co, Addison MI	64		
		N18T (2		11.64/66		
		N18T (2 N1890	Addison Products Co, Addison MI			
			Addison Products Co, Addison MI Department of Defense, Atlanta GA	11.64/66		
			Addison Products Co, Addison MI	11.64/66 69		
		N1890 oted Atlanta G	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68;	11.64/66 69 70/72 82/91		
	"N189" n	N1890 oted Atlanta G oted at Mesa	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68; AZ 1.4.72 rep. as US Dept of Interior – probably this airc	11.64/66 69 70/72 82/91		
BA-364		N1890 oted Atlanta G	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68; AZ 1.4.72 rep. as US Dept of Interior – probably this airc  Beech Aircraft Corp, Wichita KS: CofA issued	11.64/66 69 70/72 82/91 craft;		
BA-364	"N189" n	N1890 oted Atlanta G oted at Mesa	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68; AZ 1.4.72 rep. as US Dept of Interior – probably this airc  Beech Aircraft Corp, Wichita KS: CofA issued Leonard Refineries Inc, Alma MI	11.64/66 69 70/72 82/91 craft; 26.6.58 63/64		
BA-364	"N189" n	N1890 oted Atlanta G oted at Mesa	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68; AZ 1.4.72 rep. as US Dept of Interior – probably this airc  Beech Aircraft Corp, Wichita KS: CofA issued Leonard Refineries Inc, Alma MI Aircraft Owners Inc, Miami FL	11.64/66 69 70/72 82/91 craft;		
BA-364	"N189" n	N1890 oted Atlanta G oted at Mesa	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68; AZ 1.4.72 rep. as US Dept of Interior – probably this airc  Beech Aircraft Corp, Wichita KS: CofA issued Leonard Refineries Inc, Alma MI Aircraft Owners Inc, Miami FL Gee & Jensen Consulting Engineers,	11.64/66 69 70/72 82/91 craft; 26.6.58 63/64 66		
BA-364	"N189" n	N1890 oted Atlanta G oted at Mesa	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68; AZ 1.4.72 rep. as US Dept of Interior – probably this airc  Beech Aircraft Corp, Wichita KS: CofA issued Leonard Refineries Inc, Alma MI Aircraft Owners Inc, Miami FL Gee & Jensen Consulting Engineers, West Palm Beach FL	11.64/66 69 70/72 82/91 craft; 26.6.58 63/64 66 69/72		
BA-364	"N189" n	N1890 oted Atlanta G oted at Mesa	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68; AZ 1.4.72 rep. as US Dept of Interior – probably this airce  Beech Aircraft Corp, Wichita KS: CofA issued Leonard Refineries Inc, Alma MI Aircraft Owners Inc, Miami FL Gee & Jensen Consulting Engineers, West Palm Beach FL Tampa Air Center, Tampa FL	11.64/66 69 70/72 82/91 craft; 26.6.58 63/64 66 69/72 79/84		
BA-364	"N189" n	N1890 oted Atlanta G oted at Mesa	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68; AZ 1.4.72 rep. as US Dept of Interior – probably this airce  Beech Aircraft Corp, Wichita KS: CofA issued Leonard Refineries Inc, Alma MI Aircraft Owners Inc, Miami FL Gee & Jensen Consulting Engineers, West Palm Beach FL Tampa Air Center, Tampa FL Leon B. Canady, Starke FL	11.64/66 69 70/72 82/91 craft; 26.6.58 63/64 66 69/72 79/84 6.85		
BA-364	"N189" n	N1890 oted Atlanta G oted at Mesa	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68; AZ 1.4.72 rep. as US Dept of Interior – probably this airce Beech Aircraft Corp, Wichita KS: CofA issued Leonard Refineries Inc, Alma MI Aircraft Owners Inc, Miami FL Gee & Jensen Consulting Engineers, West Palm Beach FL Tampa Air Center, Tampa FL Leon B. Canady, Starke FL Span Tech Inc, Glasgow KY	11.64/66 69 70/72 82/91 craft; 26.6.58 63/64 66 69/72 79/84 6.85 3.88/91		
3A-364	"N189" n	N1890 oted Atlanta G oted at Mesa	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68; AZ 1.4.72 rep. as US Dept of Interior – probably this airce  Beech Aircraft Corp, Wichita KS: CofA issued Leonard Refineries Inc, Alma MI Aircraft Owners Inc, Miami FL Gee & Jensen Consulting Engineers, West Palm Beach FL Tampa Air Center, Tampa FL Leon B. Canady, Starke FL Span Tech Inc, Glasgow KY James L. Nolton, Marco Island FL	11.64/66 69 70/72 82/91 craft; 26.6.58 63/64 66 69/72 79/84 6.85 3.88/91 2.92		
BA-364	"N189" n	N1890 oted Atlanta G oted at Mesa	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68; AZ 1.4.72 rep. as US Dept of Interior – probably this airce Beech Aircraft Corp, Wichita KS: CofA issued Leonard Refineries Inc, Alma MI Aircraft Owners Inc, Miami FL Gee & Jensen Consulting Engineers, West Palm Beach FL Tampa Air Center, Tampa FL Leon B. Canady, Starke FL Span Tech Inc, Glasgow KY James L. Nolton, Marco Island FL op: Marco Aviation, Marco Island FL	11.64/66 69 70/72 82/91 craft; 26.6.58 63/64 66 69/72 79/84 6.85 3.88/91 2.92 94		
3A-364	"N189" n	N1890 oted Atlanta G oted at Mesa	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68; AZ 1.4.72 rep. as US Dept of Interior – probably this aird  Beech Aircraft Corp, Wichita KS: CofA issued Leonard Refineries Inc, Alma MI Aircraft Owners Inc, Miami FL Gee & Jensen Consulting Engineers, West Palm Beach FL Tampa Air Center, Tampa FL Leon B. Canady, Starke FL Span Tech Inc, Glasgow KY James L. Nolton, Marco Island FL op: Marco Aviation, Marco Island FL Cape Central Airways, Cape Girardeau MO	11.64/66 69 70/72 82/91 craft; 26.6.58 63/64 66 69/72 79/84 6.85 3.88/91 2.92 94 10.94		
BA-364	"N189" n	N1890 oted Atlanta G oted at Mesa	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68; AZ 1.4.72 rep. as US Dept of Interior – probably this aird  Beech Aircraft Corp, Wichita KS: CofA issued Leonard Refineries Inc, Alma MI Aircraft Owners Inc, Miami FL Gee & Jensen Consulting Engineers, West Palm Beach FL Tampa Air Center, Tampa FL Leon B. Canady, Starke FL Span Tech Inc, Glasgow KY James L. Nolton, Marco Island FL op: Marco Aviation, Marco Island FL Cape Central Airways, Cape Girardeau MO crashed landing, Kansas City MO	11.64/66 69 70/72 82/91 craft; 26.6.58 63/64 66 69/72 79/84 6.85 3.88/91 2.92 94 10.94 8.12.94		
BA-364	"N189" n	N1890 oted Atlanta G oted at Mesa	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68; AZ 1.4.72 rep. as US Dept of Interior – probably this aird  Beech Aircraft Corp, Wichita KS: CofA issued Leonard Refineries Inc, Alma MI Aircraft Owners Inc, Miami FL Gee & Jensen Consulting Engineers, West Palm Beach FL Tampa Air Center, Tampa FL Leon B. Canady, Starke FL Span Tech Inc, Glasgow KY James L. Nolton, Marco Island FL op: Marco Aviation, Marco Island FL Cape Central Airways, Cape Girardeau MO	11.64/66 69 70/72 82/91 craft; 26.6.58 63/64 66 69/72 79/84 6.85 3.88/91 2.92 94 10.94		
BA-364	"N189" no E18S N5647D	N1890 oted Atlanta G oted at Mesa / N5647D	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68; AZ 1.4.72 rep. as US Dept of Interior – probably this airce Beech Aircraft Corp, Wichita KS: CofA issued Leonard Refineries Inc, Alma MI Aircraft Owners Inc, Miami FL Gee & Jensen Consulting Engineers, West Palm Beach FL Tampa Air Center, Tampa FL Leon B. Canady, Starke FL Span Tech Inc, Glasgow KY James L. Nolton, Marco Island FL op: Marco Aviation, Marco Island FL Cape Central Airways, Cape Girardeau MO crashed landing, Kansas City MO Dodson Aviation, Rantoul KS: wreck for parts  Aviation parts yard, Rantoul KS 7.97, crashed condition	11.64/66 69 70/72 82/91 craft; 26.6.58 63/64 66 69/72 79/84 6.85 3.88/91 2.92 94 10.94 8.12.94 98/02		
BA-364	"N189" no E18S N5647D plate BA- N5647D plate BA-	N1890 oted Atlanta G oted at Mesa A N5647D noted Dodson 364 built 6.58 noted Dodson	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68; AZ 1.4.72 rep. as US Dept of Interior – probably this airce Beech Aircraft Corp, Wichita KS: CofA issued Leonard Refineries Inc, Alma MI Aircraft Owners Inc, Miami FL Gee & Jensen Consulting Engineers, West Palm Beach FL Tampa Air Center, Tampa FL Leon B. Canady, Starke FL Span Tech Inc, Glasgow KY James L. Nolton, Marco Island FL op: Marco Aviation, Marco Island FL Cape Central Airways, Cape Girardeau MO crashed landing, Kansas City MO Dodson Aviation, Rantoul KS: wreck for parts  Aviation parts yard, Rantoul KS 7.97, crashed condition	11.64/66 69 70/72 82/91 craft; 26.6.58 63/64 66 69/72 79/84 6.85 3.88/91 2.92 94 10.94 8.12.94 98/02		
	"N189" no E18S N5647D plate BA- N5647D plate BA-	N1890 oted Atlanta G oted at Mesa A N5647D noted Dodson 364 built 6.58 noted Dodson	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68; AZ 1.4.72 rep. as US Dept of Interior – probably this aird  Beech Aircraft Corp, Wichita KS: CofA issued Leonard Refineries Inc, Alma MI Aircraft Owners Inc, Miami FL Gee & Jensen Consulting Engineers, West Palm Beach FL Tampa Air Center, Tampa FL Leon B. Canady, Starke FL Span Tech Inc, Glasgow KY James L. Nolton, Marco Island FL op: Marco Aviation, Marco Island FL Cape Central Airways, Cape Girardeau MO crashed landing, Kansas City MO Dodson Aviation, Rantoul KS: wreck for parts  Aviation parts yard, Rantoul KS 7.97, crashed condition; Aviation parts yard, Rantoul KS 23.7.98 faded titles "M	11.64/66 69 70/72 82/91 craft; 26.6.58 63/64 66 69/72 79/84 6.85 3.88/91 2.92 94 10.94 8.12.94 98/02		
	N5647D plate BA- N5647D noted uni	N1890  oted Atlanta G oted at Mesa A  N5647D  noted Dodson 364 built 6.58 noted Dodson moved in yard	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68; AZ 1.4.72 rep. as US Dept of Interior – probably this airce Beech Aircraft Corp, Wichita KS: CofA issued Leonard Refineries Inc, Alma MI Aircraft Owners Inc, Miami FL Gee & Jensen Consulting Engineers, West Palm Beach FL Tampa Air Center, Tampa FL Leon B. Canady, Starke FL Span Tech Inc, Glasgow KY James L. Nolton, Marco Island FL op: Marco Aviation, Marco Island FL Cape Central Airways, Cape Girardeau MO crashed landing, Kansas City MO Dodson Aviation, Rantoul KS: wreck for parts  Aviation parts yard, Rantoul KS 7.97, crashed condition Aviation parts yard, Rantoul KS 23.7.98 faded titles "M 24.7.99 & 11.8.00 & 6.8.02;	11.64/66 69 70/72 82/91 craft; 26.6.58 63/64 66 69/72 79/84 6.85 3.88/91 2.92 94 10.94 8.12.94 98/02 n,		
BA-364 BA-365	N5647D plate BA- N5647D noted uni	N1890  oted Atlanta G oted at Mesa A  N5647D  noted Dodson 364 built 6.58 noted Dodson moved in yard	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC  A 3.10.68; AZ 1.4.72 rep. as US Dept of Interior – probably this airce Beech Aircraft Corp, Wichita KS: CofA issued Leonard Refineries Inc, Alma MI Aircraft Owners Inc, Miami FL Gee & Jensen Consulting Engineers, West Palm Beach FL Tampa Air Center, Tampa FL Leon B. Canady, Starke FL Span Tech Inc, Glasgow KY James L. Nolton, Marco Island FL op: Marco Aviation, Marco Island FL Cape Central Airways, Cape Girardeau MO crashed landing, Kansas City MO Dodson Aviation, Rantoul KS: wreck for parts  Aviation parts yard, Rantoul KS 7.97, crashed condition Aviation parts yard, Rantoul KS 23.7.98 faded titles "M 24.7.99 & 11.8.00 & 6.8.02; built	11.64/66 69 70/72 82/91 craft; 26.6.58 63/64 66 69/72 79/84 6.85 3.88/91 2.92 94 10.94 8.12.94 98/02 n,		

Hudson Bay (fitted with survey noise coil, tail mounted movable boom Ore Hunter & trailing magnetometer bomb by Field Aviation, Toronto:

referred to as Hudson Bay Ore Hunter 67/76)

C-FFLC Skycraft Air Transport, Oshawa ONT .82/85

lsd: Soundair 82 crashed into Lake Erie, near Cleveland OH 5.6.85

CF-FLC noted Toronto 7.67 with magentometer survey gear;

CF-FLC noted Toronto 3.76 with magentometer survey gear: gear removed by 78;

CF-FLC noted Oshawa ONT 26.8.80 Hudson Bay Air Transport;

CF-FLC noted Toronto ONT 25.8.81 Hudson Bay Air Transport;

C-FFLC noted Youngstown OH 8.6.82 Soundair Isd ex Skycraft;

BA-366	E18S	N28J	Beech Aircraft Corp, Wichita KS: CofA issued	4.8.58
			A F L C Inc, Birmingham AL	63/64
	ATE N271VM Westwind I trigear		A F L C Inc/ Vulcan Materials Co, Birmingham AL (converted .66 to trigear <i>Westwind I</i> by ATE at Long Beach CA)	66/71
	Hamilton Westwind II	N49AB II	A F L C Inc, Alton IL (rebuilt as <i>Hamilton Westwind III</i> with tail gear by Hamilton Aircraft, at Tucson AZ)	72
	tailgear	N342T	rereg	2.74
			Great Western Airlines, Tulsa-Riverside OK	77/82
			gear collapsed landing, Covington KY	20.12.77
			struck snowbank landing, Latrobe PA	23.2.79
			ran off runway, right gear torn off, Naples FL	21.1.83
			James M. Van Hise, Little Rock AR	7.83
			Aero Systems Inc. Erie CO	11.84
			Connie Kalitta Services Inc, Willow Run MI	5.87
			op: Active Aero Charter, Willow Run MI	89
			Ajax Aircraft Leasing Inc, Dover DE	2.90/91
			K & K Aircraft Inc, Bridgewater VA (broken-up for parts, Bridgewater VA)	24.3.92/04
			South West Aero Exchange, Owasso OK	03
			scrapped, struck-off USCR	27.9.04

N342T accident report 20.12.77: Great Western, cargo flight from Dayton OH, heavy landing, 10.30pm, 2 crew unhurt;

N342T noted Willow Run MI 3.8.89 "Active Aero Charter, Willow Run MI", rep. as Turboliner; N342T noted Willow Run MI 7.91, stored minus engines & tail;

N342T fuselage noted Bridgewater VA 11.8.99 in K&K storage shed on far side of airfield;

BA-367	E18S	N19J	Ohio Aviation Co, Dayton OH: dealer	.58	
			M & R Dietetic Laboratories Inc, Columbus OH	.58/64	
			tfd: Ross Laboratories, Columbus OH	.64/66	
		N1809	Skyways Inc, Dayton Municiple OH	69/73	
			Hamilton Aviation, Hamilton OH	5.6.73	
			gear collapsed during forced landing due to engine f	ailure	
			on takeoff, Dayton-Municiple OH	20.7.73	

N1809 accident report: Vandalia-Dayton Municiple: ferry permit with gear down and no starter, lost engine after takeoff due water in fuel, pilot unhurt;

BA-368	E18S	N5641D	built	.58
		N153T	Texas Eastern Transmission Corp, Shreveport LA	62/63
		N153J	Texas Eastern Transmission Corp, Shreveport LA	8.63
			gear collapsed landing Columbia MS	8.4.64
		N515J	Georgia Pacific Corp, Crossett AR	66
		N415GP	Georgia Pacific Corp, Crossett AR	67/72
	ATE		(rebuilt as American Turbine Engine Co ATE Westwind I:	
	Westwind I		PT6A-27 turbines, trigear, completed .67)	
	trigear		North Eastern Airlines	73
			Hamilton Aircraft Co, Tucson AZ	11.4.73
			sold to Kenya, struck-off USCR	6.9.73
		5Y-ASF	Caspair Ltd, Nairobi-Wilson	11.73/78

Hamilton (rebuilt as *Hamilton Westwind III* with tail gear) Westwind III crashed 400 miles west of Khartoum, Sudan

tailgear

N415GP noted Tucson AZ 24.5.73 at Hamilton Aircraft ramp, Westwind trigear; N415GP noted Nairobi-Wilson 5.9.73 Westwind III "North Eastern AL"; 5Y-ASF noted Nairobi-Wilson 12.76 owned Caspair, in Caspair hangar on maintenance;

BA-369	E18S	N21J	built	.58
			Roger W. Stribling, Jackson MS	63
			Alamo Aircraft Inc, Evansville IN	64
			B & P Motor Express Inc, Pittsburgh PA	66/69
			Jack D. Wall, Memphis TN	70
		N21DD	Robert H. Ford, Muscle Shoals AL	.72
			crashed destroyed on takeoff, Sumter SC	17.9.72

N21DD accident report 17.9.72: flight Sumter to Muscle Shoals AL, 300lb above gross weight, engine failed on takeoff, 4 k;

BA-370	E18S	N5646D	built	.58	
		N262AA	Moore Brush Newspaper Inc, Canton OH	63/66	
			WHBC Inc, Canton OH	69/70	
			SMB Stage Line, Des Moines IA	71/73	
			crashed destroyed by fire, landing Muscatine IA	27.11.73	

N262AA crash report 27.11.73: SMB Stage Line, flight Des Moines IA to Chicago, 3 attempts to land in freezing rain, flew into ground 10pm,

BA-371	E18S	N753C	built	4.58
	-9700		Polaris Corp, Milkwaukee WI	63/64
			Fred J. Banducci, Bakersfield CA	66/70
		N753CW Leo Pike, Bakersfield CA	.70/72	
			Bakersfield Aviation Services/ Air Rovers Inc,	
			Bakersfield CA	79
			minor damage, midair collision Santa Ynez CA with	
			Beech E18S N8711 during ferry flight	7.4.84
			Gold Coast Air Inc, Hawthorne CA	4.85/86
			James B. Wilkins, Downey CA	9.87
			Aerospace Products Inc, North Hollywood CA	7.91
			Glenn A. Bagley, Honolulu HI	24.10.91/92
			sold to Micronesia, struck-off USCR	24.7.92
		V6-CAA	Caroline Pacific Air, Pohnei	.96
		N753CW	Bob Keys, Palau, Micronesia & Noosa QLD	97/00
			(delivered Palau to Caboolture QLD via Cairns 26.10.97,	
			Edtended overhaul at Bundaberg QLD .98/00)	
		,	Robert H. Keys, Noosa Qld	16.6.00/15
			(ferried via Cairns to Honiara 4.09, based Honiara)	
			Solomon Islands Seaplanes. Honiara: leased	7.09/10
			(commenced tourist ops. Honiara 5.7.09,	
			back at Caboolture QLD 2015)	
			Brenton Hurt/ Territory Air Hire Pty Ltd, Darwin NT	17.11.15/22
			undercarriage retracted early on takeoff, aircraft settled	
			on to ground on belly during test flight Caboolture QLD	18.3.16
			(repaired at Caboolture, ff 28.8.19, del. to Darwin)	

N753CW noted Bakersfield CA 4.11.79;

midair collision 7.4.84: both being ferried from Santa Maria to Hawthorne CA & Long Beach CA respectively: N753CW minor damage, N8711 badly damaged, both diverted to Santa Ynez, N8711 ran off runway on landing;

N753CW noted Oceanside CA 27.11.87 retired, no titles;

N753CW noted Cairns 26.10.97 "C Pacific AIr" titles, V6-CAA painted over, N753CW hand-painted on tail, departed for Caboolture Qld.;

N753CW noted Caboolture Qld 11.97 in hangar;

N753CW noted Caboolture 4.1.98 outside;

BA-371 noted Bundaberg Qld 20.9.98 in hangar on overhaul no reg;

3.5.78

BA-371 noted Bundaberg 15.10.98 no reg: plate BA-371 built 4.58 conv to 9700lbs 30.1.64; BA-371 noted Bundaberg 30.1.99 new blue/white colour scheme, no reg, under overhaul;

BA-371 noted Bundaberg 11.2.99

N753CW not on USCR 98/00;

VH-CII noted Archerfield 10.00 new blue white paint scheme;

VH-CII noted Caloundra QLD 10.8.01, 29.8.01 blue & white good condition;

VH-CII noted Bundaberg 9.02 blue & white, outside, no props;

VH-CII noted Bundaberg 7.03 blue & white, outside;

VH-CII noted Bundaberg 28.1.04 blue & white, outside, plate BA-371;

VH-CII noted Bundaberg 16.7.05 blue & white;

VH-CII based Caboolture 06/07, lived in hangar but hangar cleared out c7.07 and then parked on grass, blue & white;

VH-CII flew into Bundaberg airshow 3.8.07;

Solomon Islands Seaplanes commenced 5.7.09. Founded by Captain Bob Keys, a veteran of 45 years in the aviation industry. Operators Certificate granted 11.08 and have an office at the international terminal at Henderson, 9 pax E18S is in service with Goose due approx 9.09, Chief Engineer Bob Jamieson and Chief Pilot Andy Wade;

Damaged during test flight Caboolture Qld 17.3.16 in preparation for delivery to Darwin. Pilot attempted to avoid kangaroos on the grass strip, became airborne, retracted gear but aircraft settled back on to the ground. Returned to hangar the same day for repair.

VH-CII under repair and major rebuild at Caboolture 6.17;

VH-CII visited Scone NSW 17.6.22 from Maitland NSW flown by Paul Bennett to collect a P-40 to fly to an airshow, CII has been maintained by Paul Bennett Airshows at their Maitland hangar for the past 2 years for the NT owner;

	E18S	N142LM	Beech Aircraft Corp, Wichita KS: CofA issued	6.5.58
		N301V	Money Investment Co, Phoenix AZ	63/66
			ground collision on taxiway with light aircraft N8316J,	
			Phoenix-Sky Harbour AZ	1.8.67
			Upper Valley Aviation, McAllen TX	69/70
			G. G. Snediker/ Snedigar Flying Service/ Pro Air Lines,	
			Rapid City SD	72/77
			Bard Air Freight Inc, Detroit MI	78
		N70CB	Bard Air Freight Inc, Detroit MI	20.5.78/84
			Bard Air Corp, Detroit MI	86/91
			Viking Group Inc, Detroit MI	6.92
			Skydive Greene County, Xenia OH	1.93
			Sky Charter Inc, Miami FL	22.11.93/13
			struck-off USCR	16.9.13

N70CB noted Detroit-Downtown MI 9.80 "Bard Air"; N70CB noted Toronto ONT 8.10.85 Bard Air, on a car parts charter;

BA-373	E18S	PP-FCN	built	.58
BA-374	E18S	N3030C	Beech Aircraft Corp, Wichita KS: CofA issued	7.7.58
			Charles P. McGaha, Wichita Falls TX	63/64
		N3038C	Austin White Lime Co, Austin TX	66/72
			Air Express Inc, Greensborough NC	79
			Southland Flyers, Memphis TN	79
			op: Air Cargo America Inc, Miami FL	83/86
	Hamilton		Sarah E. Orme, Homestead FL	9.83
	extended nose		Southern Aircraft Inc, Lantana FL	7.89/91
			Air Cargo Inc, Fort Lauderdale FL	1.94
			May Air Xpress, New Boston TX	4.5.94/95
			Scott R. Michels, Stillwater MN	29.1.98/99
			Beech Transportation Inc, Eden Prairie MN	23.6.99/00
			Navair Inc, Eden Prairie MN	2.2.00/06
			Ram Control, Osceola WI	8.09
			crashed, destroyed Flying Cloud Airport MN	12.8.09

N3030C noted Houston Int'l TX 10.9.62, tailwheel, "M" on engine cowls;

N3038C noted Miami FL 3.83 landed, tailwheel," Air Cargo America" titles;

N3038C noted Miami FL 3.11.87:

N3038C noted Ft Lauderdale Executive FL 10.11.91 Hamilton extended nose;

N3038C noted Ft Lauderdale Executive FL 12.91 all metallic, Hamilton extended nose;

N3038C noted Flying Cloud MN 7.02, Hamilton long nose, excellent condition;

N3038C noted Flying Cloud MN 8.04 long nose, freighter;

N3038C noted Eden Prairie-Flying Cloud MN 30.7.05 polished metal, long nose, tailwheel; N3038C noted Flying Cloud MN 29.7.06 long nose, stored outside left engine removed;

3A-375	E18S	N266AA	Beech Aircraft Corp, Wichita KS: CofA issued	24.7.58
			Buckeye Pipeline Co, New York NY	63/64
		N995BP	Buckeye Pipeline Co, New York NY	66
		N995H	American Aero Leasing Corp, Elizabeth NJ	69/72
			Davis & Horne Flying Service	73/74
			damaged right tyre blew out, landing El Paso TX	27.10.73
			engine torn away due propeller blade failure on takeoff,	
			Topeka KS	7.10.74
			W. W. Dailey, Coolidge AZ	79
			Morey Wyman/ Wyman Pilot Service, Pontiac MI	83/84
			struck trees on landing, skidded on belly across field,	
			Youngstown OH	19.6.83
			Gary F. Annas, Brighton MI, later Minden NV	31.12.90/06
			retired, stripped hulk, Pontiac MI	97

N995H noted Pontiac MI 17.9.78;

N995H noted Pontiac MI 9.80 plate BA-375; N995H accident report 19.6.83 Wyman Pilot Service: crashed during go-around in fog, 2 crew unhurt;

N995H noted Pontiac MI 2.97 stripped hulk;

BA-376	E18S	4R-AAS	Ceylon Dept. of Survey, Colombo-Ratmalana (donated as aid by US Government, fitted for photographic survey prior to delivery)	20.8.58
			arrived Colombo on delivery flight ex Beech	20.8.58
			crashed during training flight, Lunawa, Ceylon	25.8.58
			(wreck stored in hangar Ratmalana 58/59)	23.0.30
BA-377	E18S	N5652D	Beech Aircraft Corp, Wichita KS: CofA issued	13.8.58
			Murphy Oil Corp, El Dorado AR	61
		N360M	Murphy Oil Corp, El Dorado AR	27.4.61/66
		N860M	Ross Aviation, Tulsa-Riverside OK	69
			Great Western Airlines, Tulsa-Riverside OK	70/77
			Bobbie J. Johnson, Camden TN	29.11.77/91
	N860M p	photo c71 "Gre	eat Western Airlines" titles, passenger cabin, tailwheel;	
BA-378	E18S	N17Z	built	.58
		N415A	Aluminum Company of America, Dravosburg PA	63/66
			Geo Update Inc, Salt Lake City UT	69/70
			Palm Beach Air Traders, Lantana FL	15.4.74/75
			struck-off USCR	9.5.75
BA-379	E18S	N46L (2	Beech Aircraft Corp, Wichita KS: CofA issued	26.8.58
_,,,,,,			Lincoln National Life Insurance, Fort Wayne IN	63/64
			Excel Corp, Elkhart IN	66
			Continental Bus Interiors Inc. Elkhart IN	69/70
			Phillips Realty Co, Greensboro NC	71/72
			Eagle Aviation, Flint MI	79/82
			Robert L. Green, Clarkston MI	8.83
			Mark H. Thompson, Marietta GA	11.83
			Daniel J. Wetli, Antwerp OH	4.85
			damaged engine fire on start-up, Fort Wayne IN	24.11.85
			retired derelict, Pontiac MI	89
			Wyman Pilot Service, Pontiac MI	91
			David L. Schulze, Flint MI	3.12.93/05

Donald R. Adamson, Lonoke AR

4.4.05

63 64

N46L noted Youngstown OH 12.3.82 Eagle Aviation; N46L noted Pontiac MI 4.8.89 retired, derelict;

N8711

	N46L not	ted Pontiac Mi	I 4.8.89 retired, derelict;	
BA-380	E18S	N19U	built	.58
	50	55	Cochran Aviation Inc, Oakland Airport CA	59
			crashed	.59
			(nose, cowlings, gear doors, extended tailwheel,	
			cabin windows and other components fitted to C-45G	
			N234JC/AF-317 of Golden Gate Aviation, Oakland .59)	
BA-381	E18S	N5649D	built	.58
D/ ( 00 )	2.00	N516T	Tennessee Gas & Transmission Co, Houston TX	62
		N516J	J. S. Abercrombie	11.62
		N516K	Kilroy Co of Texas Inc, Houston TX	63
			Pan Air Corp, New Orleans LA	66/72
			struck post taxying, New Orleans-Lake Front LA	19.5.69
			Cathryn E. Tedder, Texarkana TX	1.82
			James Price, Freeport, Bahamas	79
			sale reported, McAllen TX: USCR	91
			19.5.69: Pan Air Corp, struck fire plug taxying at night; ka FL 3.10.78;	
BA-382	E18S	N5651D	Beech Aircraft Corp, Wichita KS: CofA issued	15.9.58
	-9700		Batesville Casket Co, Batesville IN	63/64
		N534H	Hillenbrand Industries, Batesville IN	66
		N538H	Ohio Aviation Corp, Dayton OH	69
			Belmont Charter Service, Detroit MI	70
			Combs Airways Inc, Billings-Logan MT	71/72
			Festus Flying Service, Festus MO	79
			HoganAir Inc, Hamilton OH	2.84
		N96HA	HoganAir Inc, Hamilton OH	5.84/86
		N9669N	HoganAir Inc, Hamilton OH	10.86
			The Eagle and the Hawks Inc, Middletown OH	91/94
			Miami Valley Aviation, Middletown OH	18.3.94/98
			The Eagle and the Hawks Inc, Middletown OH	29.5.98/14
			op: Miami Valley Aviation, Middletown OH	98/05
			George Loudakis, Stuart FL	1.12.15/20
	N96HA n N9669N N9669N Miami Va	oted Hamilton noted Middlet noted Middlet alley Aviation,	ansas-Mustang TX 8.6.76 bare metal; n OH 13.8.85 all metallic no titles; own OH 6.94 no titles, reported HoganAir, tailwheel, freight own OH 5.97, 22.7.98 & 9.98, 7.8.99, 22.7.00, 20.7.02: all no titles, plate E18S-9700 BA-382 built 9.58;	er;
,			own OH 12.10.02 no titles; own OH 1.8.05, offered for sale with N8711H, Miami Valley	Aviation has
	ceased o		own on 1.0.00, onered for sale with No71117, Mianii Valley	AviauUii Ilas
			own 17.6.06 retired;	
			on OH 6.11.10 complete;	
D 4 000	E460	N1467	1. 30	<b>50</b>
BA-383	E18S	N18Z	built	.58
	-9700	NIZZOD	Collins Radio Co, Cedar Rapids IA	63/72
		N77CR	Collins Radio Co, Cedar Rapids IA	70
		N18E	Rockwell International, Cedar Rapids IA Philip W. Schultz, Lancaster CA	79 1.11.84/22
	N/10F	tad Lanasster	·	
			-Fox Field CA 27.3.93;	
			g, plates BA-383 built 9.59, -9700 mod 16.9.60; -in, Tullahoma TN 16.10.21;	
BA-384	E18S -9700	N87D (2	Youngstown Airways/ Lease Air, Youngstown OH: CofA (mods. For E18S-9700 installed 4.59)	26.9.58
	0.00	N8711	Jack Adams Aircraft Sales Inc. Walls MS	63

Jack Adams Aircraft Sales Inc, Walls MS Beach Air Service, Fort Lauderdale FL

		Bear Manufacturing Corp, Rock Island IL	66/72
trigear		C & L Inc, Homer AK	79
		Aurora Air Service, Fairbanks AK	80/81
		Coast Air Freight, Long Beach CA	11.81/85
		ran off runway landing Santa Ynez CA, landing after	
		midair collision with Beech E18S N753CW	7.4.84
		TELCO, Naperville IL	1.85
		Englund Aviation, Mobile AL	11.87
		Robert B. Burwell, West Chicago IL	3.12.90/14
	(N890P)	ntu: Robert B. Burwell, West Chicago IL	4.91
	N8711	(N8711 retired engineless, nose damaged, Aurora IL 99	/02)
		struck-off USCR by FAA	4.5.15

N8711 noted Indianapolis IN 29.5.76 trigear "Bear Manufacturing Co" titles;
N8711 noted LAX 19.7.83 Airborne Express scheme leased from Coastal AW LGB;
N8711 noted LAX 1.9.83 Airborne Express scheme & titles, op. by Coast Air Freight, trigear;
midair collision 7.4.84: both being ferried from Santa Maria to Long Beach CA & Hawthorne
respectively: N753CW minor damage N8711 badly damagd both diverted to Santa Ynez, N8711 ran
off runway on landing;

N8711 noted Aurora IL 2.8.99 trigear, props removed and nose damaged, plate BA-384 built 9.58, another plate: converted to E18S-9700 4.59; N8711 noted Aurora IL 30.12.01 engineless;

BA-385	E18S	N5653D	Atlantic Aviation Corp, Hackensack NJ	11.58
			Dorado Beach Hotel & Golf Club, New York NY	11.58/61
			Dorado Beach Hotel Corp, Dorado, Puerto Rico	11.61/64
			Penn Aire Aviation, Franklin PA	5.64
			Continental Aircraft Sales, Medford NJ	12.65
			Thunderbird Airways Inc, Medford NJ	12.65/66
			(modified 2.66 to operate without door, approved by	
			FAA for "emergency delivery of food after blizzard")	
			Longhorn Airways, Medford NJ	4.66
			American Turbine Sales Corp/	
			American Turbine Engine Co, Long Beach CA	9.66
	ATE		(rebuild as prototype ATE Westwind I completed 9.66:	
	Westwind I		Volpar trigear, PT6A-20 turbines, picture windows,	
	trigear		airconditioning etc, retained twin tailplanes)	
			Jack Adams Aircraft Sales, Walls MS	3.67
			American Turbine Sales Corp, Long Beach CA	4.67
			Ambassador Airlines, Las Vegas-McCarran NV	8.67/68
			Carco Air Service of Nevada Inc, Las Vegas NV	7.68
			(Beech cargo door installed 3.69)	0= 0 00
			hard landing, gear collapsed, Bettles AK	25.8.69
			(turbine props reversed prematurely during short field	
			landing demonstration: repaired by Field Aviation Co,	
			Calgary ALTA)	10.00/70
			Nevada National Bank, Las Vegas NV	12.69/72
			(Beech cargo door removed 2.72)	0.70
	1.1		Hamilton Aircraft Co, Tucson AZ	3.72
	Hamilton		(rebuilt as Hamilton Westwind III: Volpar trigear replaced	_
	Westwind I	11	by tailwheel landing gear, crew door & Hamilton long nos	e,
	tailgear		max AUW 11230 lb kit, completed by Hamilton 3.72)	00 0 70/05
			SMB Stage Line Inc, Des Moines IA	23.3.72/85
			Jarex Corp, Columbus IN	9.85
			Jet Way Enterprises Inc, Willow Run MI Ajax Aircraft Leasing Inc, Dover DE	11.85 6.87/89
			Active Aero Charter, Willow Run MI: Isd	6.87/89
			Ken & Karl Stoltzfus/K & K Aircraft Inc, Bridgewater VA	3.91/04
				3.91/04
			(CofA renewed 19.4.91 after fitted for agricultural & pest control sprayer operations)	
			Brazoria County Mosquito Control, Angleton TX	17.6.04/05
		N897SB	Brazoria County Mosquito Control, Angleton TX  Brazoria County Mosquito Control, Angleton TX	3.05/16
		1109130	Victoria Jet Aviation, Victoria TX	14.10.16/17
			Elliot Weiss, Fresno TX	121.7.17/20
			LINOT VVOIGG, I TOGITO TA	121.1.11/20

Bill of Sale to Dorado Beach Hotel 11.58 signed by Lawrence S. Rockefeller, owner; Further info: see Beech 18 by Robert Parmerter p.332;

N5653D noted LAX 18.3.67 Ambassador Airlines, Turbo Volpar

N5653D accident report 25.8.69: demo flight of Westwind Mk.1, soft surface;

N5653D noted Tucson AZ 11.8.71 at Hamilton Aircraft ramp, Westwind turbine conversion;

N5653D noted Tucson AZ 3.4.72 at Hamilton ramp, Westwind turbine;

N5653D noted Columbus OH 5.72 "SMB" titles, PT6As, tailwheel, extended nose;

N5653D noted St Louis MO 29.9.72 turbine tailwheel "SMB Stage Line",

N5653D noted St Louis MO 3.76 "SMB Stage Line", tailwheel turbine;

N5653D noted Port Columbus OH 26.5.76 Westwind III "SMB Stage Line" titles;

N5653D noted Des Moines IA 21.12.78:

N5653D noted Dallas-FTW 7.11.81 "SMB" insignia, Hamilton Westind turbines, tailwheel;

N5653D noted Willow Run MI 3.8.89 "Active Aero Charter, Willow Run", Westwind III;

N5653D noted Los Alamitos CA 17.8.99 K&K Aircraft, sprayer, plate BA-385 built 10.58;

N5653D noted Los Alamitos CA 13.8.02 with other K&K sprayers;

E18S	N5654D	Beech Aircraft Corp, Wichita KS	8.12.58
-9700		sold to Canada, struck-off USCR	19.5.59
	CF-ANT (2	Anthes-Imperial Co Ltd, St Catherines ONT	23.4.59/67
		(replaced D18S CF-ANT A-352 rereg CF-LLF 4.59)	
		Perimeter Flying Associates Ltd, Winnipeg MAN	6.6.67
		Perimeter Aviation Ltd, Winnipeg MAN	28.2.69/72
		op: Air Niagara, St Catharines ONT	3.69/71
		gear collapsed landing St Therese Point MAN	24.6.70
		B. F. Klassen Construction Ltd, Winnioeg MAN	12.8.71/74
		left gear collapsed landing on snow, Gods Narrows MAN	13.12.71
		landed gear-up Thompson MAN	22.8.72
		Lac du Bonnet Air Park, Lac Bonnet MAN	24.4.74
		Slate Falls Airways Ltd, Sioux Lookout ONT	26.7.76
		wrecked, ran off runway on takeoff Round Lake ONT (wreck buried at Round Lake Airport)	25.11.76
		-9700	-9700 sold to Canada, struck-off USCR CF-ANT (2 Anthes-Imperial Co Ltd, St Catherines ONT (replaced D18S CF-ANT A-352 rereg CF-LLF 4.59) Perimeter Flying Associates Ltd, Winnipeg MAN Perimeter Aviation Ltd, Winnipeg MAN op: Air Niagara, St Catharines ONT gear collapsed landing St Therese Point MAN B. F. Klassen Construction Ltd, Winnipeg MAN left gear collapsed landing on snow, Gods Narrows MAN landed gear-up Thompson MAN Lac du Bonnet Air Park, Lac Bonnet MAN Slate Falls Airways Ltd, Sioux Lookout ONT wrecked, ran off runway on takeoff Round Lake ONT

#### CF-ANT noted Toronto-Malton ONT 1.1.71, tailwheel;

BA-387	E18S	N5655D N500W	Beech Aircraft Corp, Wichita KS: CofA issued S. J. Groves & Sons Co, Ann Arbor MI	21.10.58 63/66
		N762SP	John C. Mosby, Ladue MO	69
		147 0201	Highland Management Co, St Louis MO	70/72
			gear collapsed landing, Festus MO	3.11.74
			sale reported: USCR	74/91
			date reported. Goot	7 170 1
BA-388	E18S	N27Y	Beech Aircraft Corp, Wichita KS: CofA issued	21.11.58
	-9700		Basic Products Corp, Milwaukee WI	63
			Gopher Aviation, Rochester Airport MN	64
			Eclipse Fuel Engineering Co, Rockford IL	66/72
			Bakersfield Aviation Services/ Air Rovers Inc,	
			Bakersfield CA	79
			A. A. Portanova & Sons, Agoura CA	8.81
		Robert A. Youkin, Springdale AR	4.84	
			Wal-Mart Stores Inc., Bentonville AR	2.85
			crashed forced landing in field after takeoff, Terrell TX	2.1.86
			(carrying photographs developed for Wal-Mart stores)	
			sale reported, Springdale AR: USCR	91/06
			South West Aero Exchange, Owasso OK (dismantled in salvage yard, Owasso OK 97/00)	97/00

N27Y noted Oakland CA 1.59, tailwheel, no titles;

N27Y noted Bakersfield CA 20.9.77 tailwheel,

N27Y noted Bakersfield CA 4.11.79;

N27Y noted Owasso OK 13.10.97 stripped hulk;

N27Y fuselage noted SW Aero Exchange Owasso OK 10.8.00;

BA-389	E18S	N691T	built	.58	
	trigear		Crose-Perrault Equipment Corp, Houston TX	63/64	
			Walker Developments Inc, Columbia SC	66	
			op: Gold Coast Airways, Palm Beach FL	68	
			Hill Aircraft & Leasing Corp, Atlanta GA	69/70	
			Southeast Commuter Airlines, Mobile AL	71/72	

			op: Island Air Tours, Honolulu HI Robert A. Justman/ Justman Enterprises Inc/ Hawaiian Sky Tour, Honolulu HI op: Circle Rainbow Air, Honolulu HI <i>Lara</i>	76 79 79
		RP-C690	op: Hawaiian Sky Tour, Honolulu HI <i>Lara</i> sold to Philippines: struck-off USCR Charles R. Miller/ Commuter Air Philippines, Manila CofA expired 1.3.04, struck-off Register	.80/84 2.7.87 87/03 .08
	N691T no N691T no N691T no N691T no N691T no N691T no RP-C690 RP-C690	oted Kahului Hi oted Honolulu S oted Honolulu S oted Honolulu S oted Honolulu S o noted Manila S o noted Manila S		
BA-390	E18S	XB-DAX	built	.58
		XB-TUN XA-SIN	rereg rereg	.67/72
	XB-DAX	noted Mexico (	·	=
BA-391	E18S	N185AA	built	.58
		NIAGNAT	Vinnell Corp, Alhambra CA	63/70
		N45WT N45TB	rereg Bartlite Inc, San Antonio TX	71/73
		111012	Holborn Investments Inc, Woodbury NJ	26.11.73/74
			gear collapsed landing, Williston FL	9.1.74
	NASTD n			
	11431611	oted San Antor	nio TX 16.5.73	
BA-392	E18S	oted San Antor N5659D	nio TX 16.5.73  built	.58
BA-392			built Winthrop Rockefeller, Little Rock AR	63/64
BA-392			built Winthrop Rockefeller, Little Rock AR Central Flying Service, Little Rock AR	63/64 16.4.66/70
BA-392	E18S	N5659D	built Winthrop Rockefeller, Little Rock AR Central Flying Service, Little Rock AR crashed destroyed landing, Kansas City MO Central Flying Service, mail flight, time 0108 Local, flew	63/64 16.4.66/70 14.2.70
	E18S	N5659D  report 14.2.70: in snow & free  N5657D (1	built Winthrop Rockefeller, Little Rock AR Central Flying Service, Little Rock AR crashed destroyed landing, Kansas City MO  Central Flying Service, mail flight, time 0108 Local, flew ezing drizzle;  built	63/64 16.4.66/70 14.2.70 into ground during
	E18S accident approach	N5659D report 14.2.70: in snow & free	built Winthrop Rockefeller, Little Rock AR Central Flying Service, Little Rock AR crashed destroyed landing, Kansas City MO  Central Flying Service, mail flight, time 0108 Local, flewering drizzle;  built Concord Mobile Homes Inc, Elkhart IN	63/64 16.4.66/70 14.2.70 into ground during .58 63/64
	E18S accident approach	N5659D  report 14.2.70: in snow & free  N5657D (1	built Winthrop Rockefeller, Little Rock AR Central Flying Service, Little Rock AR crashed destroyed landing, Kansas City MO  Central Flying Service, mail flight, time 0108 Local, flew exing drizzle;  built Concord Mobile Homes Inc, Elkhart IN Lasalle & Deitch Inc, Elkhart IN	63/64 16.4.66/70 14.2.70 into ground during
	E18S accident approach	N5659D  report 14.2.70: in snow & free  N5657D (1	built Winthrop Rockefeller, Little Rock AR Central Flying Service, Little Rock AR crashed destroyed landing, Kansas City MO  Central Flying Service, mail flight, time 0108 Local, flew exing drizzle;  built Concord Mobile Homes Inc, Elkhart IN Lasalle & Deitch Inc, Elkhart IN Montgomery Aviation Corp/ Huntsville Aviation,	63/64 16.4.66/70 14.2.70 into ground during .58 63/64
	E18S accident approach	N5659D  report 14.2.70: in snow & free  N5657D (1	built Winthrop Rockefeller, Little Rock AR Central Flying Service, Little Rock AR crashed destroyed landing, Kansas City MO  Central Flying Service, mail flight, time 0108 Local, flew exing drizzle;  built Concord Mobile Homes Inc, Elkhart IN Lasalle & Deitch Inc, Elkhart IN	63/64 16.4.66/70 14.2.70 into ground during .58 63/64 66
	E18S accident approach	N5659D  report 14.2.70: n in snow & free  N5657D (1	built Winthrop Rockefeller, Little Rock AR Central Flying Service, Little Rock AR crashed destroyed landing, Kansas City MO  Central Flying Service, mail flight, time 0108 Local, flew exing drizzle;  built Concord Mobile Homes Inc, Elkhart IN Lasalle & Deitch Inc, Elkhart IN Montgomery Aviation Corp/ Huntsville Aviation, Montgomery AL hit trees during night landing, Montgomery AL Norman C. Mayes, Powell TN	63/64 16.4.66/70 14.2.70 into ground during .58 63/64 66 69/72 10.12.69 79
	E18S accident approach	N5659D  report 14.2.70: n in snow & free  N5657D (1	built Winthrop Rockefeller, Little Rock AR Central Flying Service, Little Rock AR crashed destroyed landing, Kansas City MO  Central Flying Service, mail flight, time 0108 Local, flew exing drizzle;  built Concord Mobile Homes Inc, Elkhart IN Lasalle & Deitch Inc, Elkhart IN Montgomery Aviation Corp/ Huntsville Aviation, Montgomery AL hit trees during night landing, Montgomery AL Norman C. Mayes, Powell TN Semo Aviation, Malden MO	63/64 16.4.66/70 14.2.70 Finto ground during .58 63/64 66 69/72 10.12.69 79 80
	E18S accident approach	N5659D  report 14.2.70: n in snow & free  N5657D (1	built Winthrop Rockefeller, Little Rock AR Central Flying Service, Little Rock AR crashed destroyed landing, Kansas City MO  Central Flying Service, mail flight, time 0108 Local, flew exing drizzle;  built Concord Mobile Homes Inc, Elkhart IN Lasalle & Deitch Inc, Elkhart IN Montgomery Aviation Corp/ Huntsville Aviation, Montgomery AL hit trees during night landing, Montgomery AL Norman C. Mayes, Powell TN Semo Aviation, Malden MO op: General Aviation Inc, Greenville TN	63/64 16.4.66/70 14.2.70 Finto ground during .58 63/64 66 69/72 10.12.69 79 80 80
	E18S accident approach	N5659D  report 14.2.70: n in snow & free  N5657D (1 N679T	built Winthrop Rockefeller, Little Rock AR Central Flying Service, Little Rock AR crashed destroyed landing, Kansas City MO  Central Flying Service, mail flight, time 0108 Local, flew exing drizzle;  built Concord Mobile Homes Inc, Elkhart IN Lasalle & Deitch Inc, Elkhart IN Montgomery Aviation Corp/ Huntsville Aviation, Montgomery AL hit trees during night landing, Montgomery AL Norman C. Mayes, Powell TN Semo Aviation, Malden MO op: General Aviation Inc, Greenville TN Coker Airfreight Inc, Dallas TX	63/64 16.4.66/70 14.2.70 into ground during .58 63/64 66 69/72 10.12.69 79 80 80 .80/81
	E18S accident approach	N5659D  report 14.2.70: n in snow & free  N5657D (1	built Winthrop Rockefeller, Little Rock AR Central Flying Service, Little Rock AR crashed destroyed landing, Kansas City MO  Central Flying Service, mail flight, time 0108 Local, flew exing drizzle;  built Concord Mobile Homes Inc, Elkhart IN Lasalle & Deitch Inc, Elkhart IN Montgomery Aviation Corp/ Huntsville Aviation, Montgomery AL hit trees during night landing, Montgomery AL Norman C. Mayes, Powell TN Semo Aviation, Malden MO op: General Aviation Inc, Greenville TN Coker Airfreight Inc, Dallas TX Coker Airfreight Inc, Dallas TX	63/64 16.4.66/70 14.2.70 Finto ground during .58 63/64 66 69/72 10.12.69 79 80 80
	E18S accident approach	N5659D  report 14.2.70: n in snow & free  N5657D (1 N679T	built Winthrop Rockefeller, Little Rock AR Central Flying Service, Little Rock AR crashed destroyed landing, Kansas City MO  Central Flying Service, mail flight, time 0108 Local, flew ezing drizzle;  built Concord Mobile Homes Inc, Elkhart IN Lasalle & Deitch Inc, Elkhart IN Montgomery Aviation Corp/ Huntsville Aviation, Montgomery AL hit trees during night landing, Montgomery AL Norman C. Mayes, Powell TN Semo Aviation, Malden MO op: General Aviation Inc, Greenville TN Coker Airfreight Inc, Dallas TX coker Airfreight Inc, Dallas TX ran off runway landing, struck drainage channel, nosed over, Lubbock TX	63/64 16.4.66/70 14.2.70 into ground during .58 63/64 66 69/72 10.12.69 79 80 80 .80/81 9.81/84 30.6.82
	E18S accident approach	N5659D  report 14.2.70: n in snow & free  N5657D (1 N679T	built Winthrop Rockefeller, Little Rock AR Central Flying Service, Little Rock AR crashed destroyed landing, Kansas City MO  Central Flying Service, mail flight, time 0108 Local, flew ezing drizzle;  built Concord Mobile Homes Inc, Elkhart IN Lasalle & Deitch Inc, Elkhart IN Montgomery Aviation Corp/ Huntsville Aviation, Montgomery AL hit trees during night landing, Montgomery AL Norman C. Mayes, Powell TN Semo Aviation, Malden MO op: General Aviation Inc, Greenville TN Coker Airfreight Inc, Dallas TX coker Airfreight Inc, Dallas TX ran off runway landing, struck drainage channel, nosed over, Lubbock TX nn: Skyfreighters Corp, Dallas TX	63/64 16.4.66/70 14.2.70 into ground during .58 63/64 66 69/72 10.12.69 79 80 80 .80/81 9.81/84 30.6.82 84/85
BA-392 BA-393	E18S  accident approach E18S  N679T acduring lai	N5659D  report 14.2.70: n in snow & free  N5657D (1 N679T  N91CA	built Winthrop Rockefeller, Little Rock AR Central Flying Service, Little Rock AR crashed destroyed landing, Kansas City MO  Central Flying Service, mail flight, time 0108 Local, flew ezing drizzle;  built Concord Mobile Homes Inc, Elkhart IN Lasalle & Deitch Inc, Elkhart IN Montgomery Aviation Corp/ Huntsville Aviation, Montgomery AL hit trees during night landing, Montgomery AL Norman C. Mayes, Powell TN Semo Aviation, Malden MO op: General Aviation Inc, Greenville TN Coker Airfreight Inc, Dallas TX Coker Airfreight Inc, Dallas TX ran off runway landing, struck drainage channel, nosed over, Lubbock TX nn: Skyfreighters Corp, Dallas TX struck-off USCR	63/64 16.4.66/70 14.2.70 into ground during .58 63/64 66 69/72 10.12.69 79 80 80 .80/81 9.81/84 30.6.82 84/85 4.85
	E18S  accident approach E18S  N679T acduring lai	N5659D  report 14.2.70: n in snow & free  N5657D (1 N679T  N91CA	built Winthrop Rockefeller, Little Rock AR Central Flying Service, Little Rock AR crashed destroyed landing, Kansas City MO  Central Flying Service, mail flight, time 0108 Local, flew ezing drizzle;  built Concord Mobile Homes Inc, Elkhart IN Lasalle & Deitch Inc, Elkhart IN Montgomery Aviation Corp/ Huntsville Aviation, Montgomery AL hit trees during night landing, Montgomery AL Norman C. Mayes, Powell TN Semo Aviation, Malden MO op: General Aviation Inc, Greenville TN Coker Airfreight Inc, Dallas TX coker Airfreight Inc, Dallas TX ran off runway landing, struck drainage channel, nosed over, Lubbock TX nn: Skyfreighters Corp, Dallas TX struck-off USCR	63/64 16.4.66/70 14.2.70 into ground during .58 63/64 66 69/72 10.12.69 79 80 80 .80/81 9.81/84 30.6.82 84/85 4.85
	E18S  accident approach E18S  N679T acduring lai	N5659D  report 14.2.70: n in snow & free  N5657D (1 N679T  N91CA	built Winthrop Rockefeller, Little Rock AR Central Flying Service, Little Rock AR crashed destroyed landing, Kansas City MO  Central Flying Service, mail flight, time 0108 Local, flew ezing drizzle;  built Concord Mobile Homes Inc, Elkhart IN Lasalle & Deitch Inc, Elkhart IN Montgomery Aviation Corp/ Huntsville Aviation, Montgomery AL hit trees during night landing, Montgomery AL Norman C. Mayes, Powell TN Semo Aviation, Malden MO op: General Aviation Inc, Greenville TN Coker Airfreight Inc, Dallas TX Coker Airfreight Inc, Dallas TX ran off runway landing, struck drainage channel, nosed over, Lubbock TX nn: Skyfreighters Corp, Dallas TX struck-off USCR	63/64 16.4.66/70 14.2.70 into ground during .58 63/64 66 69/72 10.12.69 79 80 80 .80/81 9.81/84 30.6.82 84/85 4.85

Union Oil Co of California, Palatine IL	66/70
Don J. Wangalin, Palatine IL	71/72
SMB Stage Line Inc, Des Moines IA	74/81
Universal Aircraft Sales & Leasing Inc, Detroit MI	.81
Gussic Ventures Inc, Unalakleet AK	7.89/94
Hageland Aviation Services, Anchorage AK	12.7.94/99
Beech Transportation, Eden Prairie MN	11.10.99/00
Navair Inc, Eden Prairie MN	7.2.00/06
Chart Air Inc, Fort Lauderdale FL	7.6.10/16
Southern Cross Aviation, Wilmington DE	20.3.17
Seven Stars Air Cargo Group, Carolina, Puerto Rico	7.6.17/20

N16U noted Flying Cloud MN 7.02, excellent condition, tailwheel;

N16U noted Flying Cloud 25.7.04 tailwheel, owned Navair, extended nose (not Hamilton long nose);

N16U noted Flying Cloud 8.04; Flying Cloud 30.7.05 tailwheel;

N16U noted Flying Cloud 29.7.06 under maintenance: plate BA-394 built 12.58,

another plate: converted to 9799AUW 26.3.59;

BA-395	E18S	N97N	Beech Aircraft Corp, Wichita KS: CofA issued	7.1.59
	trigear		Martin Marietta Corp, Baltimore MD	63
	_	N94P	Perry Enterprises Inc, Frenso CA	66/70
		N94PB	Perry Enterprises Inc, Fresno CA	71
		N967	Federated Leasing Associates, Miami FL	79
			George K. Armagost/ Pro Air Services, Opa Locka FL	82/84
			damaged wheels-up landing, Opa Locka FL	22.9.83
			Julac Export Corp, Boynton Beach FL	4.84
			Union Flights, Sacramento CA	2.85/95
			Jim Hankins Air Service, Jackson MS	12.5.95/96
			Sky Charter Inc, Opa Locka FL	11.96/99
			South Florida Aircraft Leasing, Opa Locka FL	22.4.99/00
			op: Florida Air Cargo, Opa Locka FL	00
			TMF Aircraft Inc, Miami FL	19.10.01/13
			struck-off USCR by FAA	23.5.13

N967 noted Tallahassie Municiple FL 28.10.77, trigear;

N967 noted Sacramento-Executive CA 4.82 trigear, no titles;

accident report 22.9.83: landed wheels-up, Pro Air Services;

N967 noted Sacramento-Executive CA 17.8.87 trigear "Union Flights";

N967 noted Bakersfield CA 7.91 trigear "Union Flights"; N967 noted Santa Barabara CA 10.93 "Union Flights" titles, trigear; N967 noted Opa Locka FL 1.96, 21.1.97 trigear, Union Flights scheme, rep op Florida Air Cargo;

N967 noted Opa Locka FL11.4.97 trigear, 9.97 trigear;

N967 noted Opa Locka FL 2.4.00 "Florida Air Cargo" titles, blue & metallic;

N967 noted Opa Locka FL 27.11.00, 4.4.01 plate BA-395;

N967 noted Opa Locka FL 5.01 trigear;

BA-396	E18S	N100NH	National Homes Corp, Lafayette IN crashed	27.3.59/62 4.11.62
BA-397	E18S	N383B	built	.58
	-9700		(mods to E18S-9700 installed 24.7.59)	
			Carpenter Paper Co, Omaha NE	63
			Ohio Aviation Co, Vandalia-Dayton Municiple OH	64
			McDonough Co, Parkersburg WV	66
			Rambar Aviation, Parkersburg WV	69/72
			op: Little Mountain Air Cargo, Denver NC	78
			damaged on takeoff, Columbia SC	14.3.78
			Southern National Leasing Corp, Charlotte NC	79
			Equipment Leasing Corp, Greenville SC	81/84
			Mountain Air Cargo, Denver NC: Isd	81/84
			ran off runway landing, down embankment,	
			Franklin-Chess Lambertson PA	8.11.83
			Coastal States Aviation, Denver NC	3.85
			Springdale Air Service, Springdale AR	24.3.86/95
			struck-off USCR	30.3.95
			(retired dismantled Springdale AR: parts source 97)	

00

N383B accident report 14.3.78: Little Mountain Air Cargo, cargo flight Charlotte NC to Columbia SC, struck raised runway lights landing 12.22pm, pilot unhurt;

N383B noted Miami 10.8.81 arrived, Mountain Air Cargo;

N383B accident report 8.11.83: Mountain Air Cargo;

N383B noted Columbus OH 2.4.84;

N383B noted Shreveport LA 10.87:

N383B noted Springdale AR 8.97 & 10.97 fuselage stacked against Springdale AS hangar wall: plate BA-397 built 12.58;

N383B noted SW Aero Exchange Owasso OK 10.8.00 plate BA-397, built 12.58, another plate: conv to -9700 24.7.59, standing on wheels wings removed;

BA-398	E18S	N510E N80D (2 N510E N513E	Beech Aircraft Corp, Wichita KS: CofA issued Youngstown Airways/ Lease Air, Youngstown OH G. C. Murphy Co, McKeesport PA G. C. Murphy Co, McKeesport PA Western Suburban Airways, Chicago IL Caribbean Aviation Services, Miami FL sale reported, Miami FL: USCR	23.1.59 63/69 70 71/72 4.76/79 80/91
			rdale FL 1.10.72; . 14.8.77 Caribbean Avtn;	00/01
BA-399	E18S	N300G	built Goad Motor Co, San Antonio TX Blankenship Developments Inc, Lubbock TX Land Marketing Inc, Lubbock TX Dorlaine A. Romain, Big Fork MT crashed destroyed on takeoff, Laredo TX	.58 63/64 66/70 71/72 8.5.78 11.10.78
	N300G no	oted Addison	TX 29.4.73;	
BA-400	E18S	N686Q	H. L. Coble Construction Co, Greensboro NC Two 8 Co, Corpus Christi TX Johnson Flying Service, Missoula MT Blackhawk Airways, Janesville WI Charles T. Madsen, Dutch Harbour AK Aleutian Air Ltd, Dutch Harbor AK & Juneau AK crashed destroyed after takeoff, Juneau AK	.58/64 66/70 72/73 79 7.82 13.6.83/02 10.4.02

"Flying" 5.59 report: 400th Super 18 purchased by H.L.Coble Construction Co of Greensborough NC who already operated a Twin Bonanza. Delivery ex Beech factory by H.L.Coble, president of the industrial building company, also K.V.Brough Vice President of Greensboro-High Point Air Service (Beech dealers), Coble's chief pilot Roscoe E. Harris & company pilot James C. Lawson;

### N686Q noted Missoula MT 21.7.73 JFS, red scheme;

crash report 10.4.02: struck shallow water on tidal mud flats a half mile from Juneau Airport, sole occupant pilot killed: he was on a second trip carrying a full load of wooden roofing for a friend's remote lodge, aircraft was described by loaders as "completely full". Nose pitched up when airborne RWY 08 at about 200 ft and fell into mud flats:

BA-401	E18S	N5661D	built	.58
		N151G	Georgia Pacific Corp, Portland OR	63/70
			sold to Brazil	.68
		PT-DHI	CIA Amazonas Madeiras & Laminados	8.68
			Taxi Aereo Rondonia Ltda, Santarem	79
			Rico Taxi Aereo Ltda, Manaus	83
			Carlos Edo/ Extreme Demonstracoes Aereas Ltda,	
			Campinas-Amarais	99/16
			op: Esquadrilha Oi: formation team #4	02/16

PT-DHI noted Campinas-Amarais, Brazil 15.7.99 all red, in service with other aircraft of Extreme Demonstracoes Aereas, all in same red scheme;

PT-DHI at airshow Itirapina Brazil 22.5.05 pseudo military scheme #4;

# PT-DHI at airshow Araras, Brazil 7.10.06 display scheme #4, flying, tailwheel; PT-DHI noted Amarais, Brazil .16 in hangar with display team T-6s;

BA-402	E18S	N888X	Beech Aircraft Corp, Wichita KS: CofA issued	11.2.59
	-9700		(mods to E18S-9700 installed 1.5.59)	
		N388W	Wyandotte Chemicals Corp, Wyandotte MI	63/64
		N737SW	Joseph E. Seagram & Sons Distillery Inc, New York NY	66/70
			James Barbitta & Associates, Akron OH	71/72
			Southernair Inc, Chattanooga TN	79
			Karl J. Wagner, Wichita KS	4.84
			Springdale Air Service, Springdale AR	10.85/86
			Robert A. Younkin, Lowell AR	5.91
			William P. Eckles, Oklahoma City OK	27.7.93/06
			(flew 02 in USAF markings)	
			TDP Inc, Wilmington DE	19.6.09/16
			forced landing on highway FL, no dam., flown out	2.4.13
			Aztec Worldwide Airlines Inc, Fort Lauderdale FL	18.7.16/19

N737SW noted Westchester County NY 6.70, tailwheel, no titles, owned Seagrams Whiskey; N737SW noted McAlester OK 5.8.02 plate BA-402 built 2.59, plate -9700 mods 1.5.59, painted in USAF scheme;

BA-403	E18S	N569BV	built	.59
	-9700		Besser Co, Alpena MI	63/66
			Buffalo Aeronautical Corp, Buffalo NY	69/83
			Crown Star Inc, Los Angeles CA	12.83
			Estel M. Blevins, Palm Harbour FL	10.85
			DCI Inc, Lutz FL	7.86
			sold to Canada: struck-off USCR	17.10.86
		C-GDRJ	Dean River Air Services Ltd, Nimpo Lake BC	17.11.89/91
			White Bark Enterprises Ltd, Williams Lake BC	27.2.91
			Carson Air Ltd, Williams Lake BC	12.91/93
			Summit Air Charters Ltd, Atlin BC	3.93/95
			Enterprise Air Inc, Oshawa ONT	13.2.95/98
			sold to USA, struck-off Canadian Register	20.11.98
		N1939K	Gus McLeod/ McLeod Kendall Inc, Dagsboro NE	11.98/03
			(US CofA renewed 26.11.98)	
			James E. Slocum, Moscow TN	21.8.04/11
			Crazy Woiman LLC, Tupelo MS	26.9.11/20

N569BV noted Buffalo NY 27.8.74 bare metal;

N569BV noted Muskoka ONT 1.11.86;

C-GDRJ noted Oshawa ONT 9.96 Enterprise Air;

C-GDRJ noted Oshawa ONT 6.98 Enterprise Air;

NC1939K at fly-in Oshkosh 8.99 titles "McLeod-Kendall Polar Expedition" & "Gus McLeod, Gaithersburg MD", "C-GDRJ" readable on port fin, "C-FDRJ" readable on starboard fin, plate E18S-9700 BA-403 built 2.59;

NC1939K at fly-in Oshkosh 30.7.03;

NC1030K at fly-in Oshkosh 24.7.06 Jim & Val Slocum, up for sale;

N1939K at fly-in Lakeland FL 21.4.07;

N1939K at Beech fly-in Tullahoma TN 14.10.07;

N1939K visited Oshkosh WI fly-in 28.7.14; 7.15, 7.16;

BA-404	E18S	N187AA	built	.59
		N157SC	Carmen Diorio, Philadelphia PA crashed destroyed during landing, Millville NJ	63/67 7.6.67
BA-405	E18S	N651Q	built	2.59
DA-400 L100	L100	LIOO NOOTQ	E. & J. Gallo Winery, Modesto CA	63/72
			sale reported: USCR	79
			Mountain Skyways Inc, Kalispell MT	2.84
			Southwest Airlift Inc, El Paso TX	4.85
			Robert A. Younkin, Lowell AR	10.86
			sold to Canada: struck-off USCR	1.10.86
		C-GJEO	Leuenberger Air Services Ltd, Nakina ONT Air 500 Ltd, Toronto ONT	5.11.86/88 8.88/92

	sold to USA: struck-off Canadian Register	25.8.92
N651Q	Express Air Inc, Greenville SC	14.9.92/94
	Earl V. Long, Wichita KS	.94/95
	Blue Ridge Aviation	3.1.95
	sold to Canada, struck-off USCR	17.4.95
C-GJEO	936430 Ontario Ltd, Woodstock ONT	3.5.95/96
	Samaritan Air Service Ltd, Toronto ONT	6.3.96/01
	struck-off Register	3.6.01
	Stevenson Aviation, Portage MAN	18
	(outer wings removed, instructional airframe, titles	
	"Stevenson Aviation & Aerospace Training Centre")	

C-GJEO noted Toronto 20.11.91 "Air 500" titles, tailwheel;

C-GJEO noted Toronto 6.98;

Reg cancelled by DoT 3.6.01 due mail returned as undeliverable address; noted Southport Airport, Portage MAN 8.18: C-GJEO inst airframe, outer wings removed; plate BA405 built 2.59;

BA-406	E18S	N188AA	built	.59
		N2700S (1	rereg	
		N149AA (2	Wisconsin Electric Cooperative, Madison WI	63/70
		•	Joseph Fontana, Kingsford MI	71/72
			Astro Airways, Pine Bluff AR	74
			damaged when landed gear-up, Laredo TX	30.4.74
			Semo Aviation/ Semo Airways, Malden MO	79/85
			Springdale Air Service, Springdale AR	10.85/86
			crashed Texarkana AR	7.11.86/89
			struck-off USCR	21.3.89

N149AA accident report 30.4.74: Astro Airways, pilot failed to extend gear, flight to Laredo from Torreon, Mexico, 2 crew unhurt, 3pm;

BA-407	E18S	N5657D (2	built	.59
<i>D</i> , (10)		,	Airlease Corp, San Francisco CA	63/70
			Cooper Tire & Rubber Co, Findlay OH	71/72
			Lee R. Griffith, Lake Dallas TX	15.10.75
			missing after departure Dallas TX: not found	28.10.75
BA-408	E18S	N5663D(1	built	.59
	-9700	N952 (1	Colorado Interstate Gas Co, Colorado Springs CO	63/64
		N952F	damaged landing, San Lucas-Hotel Carbo, Mexico	24.2.65
			S. F. Bracamonte, San Diego CA	66
		N405JB	S. F. Bracamonte, San Diego CA	69/72
		N405JR	National Air Freight	75
			Herbert A. Garms, Smith NV	78
			Bob Andrews, Fort Lauderdale FL	24.1.79/91

N405JB noted San Diego CA 9.4.72, no titles N405JR noted Hayward CA 19.9.75 "National Air Freight" titles, tailwheel;

BA-409	E18S	CF-LFT	built	.59
		CF-PER	Majestic Contractors Ltd, Toronto ONT	63
			Northern Telephone Ltd, New Liskeard ONT	65/70
			Air Niagara Ltd, St Catharines ONT	72/74
			White River Air Services	.74
		C-FPER	Air Niagara Ltd, Toronto-Malton ONT	79/83
			damaged accident, Ottawa ONT (repaired)	13.2.79
			struck-off Register	8.83
			Centennial College, Scarborough ONT: inst. airframe	02
			National Air Force Museum of Canada, Trenton AB ONT	18/19

CF-PER photo 10.63, tailwheel;

CF-PER noted Montreal-Droval 10.67 visitor, private;

CF-PER noted Toronto-Malton 8.10.81 in service, no titles, tailwheel;

CF-PER noted 3.02 inside Centennial College hangar at Scarborough ONT, cockpit

BA-410	E18S	N387B	built	.59
			Waukesha Motor Co, Waukesha WI	63/66
			Hartzog-Schneck Aviation, Rockford IL	69
			Batvin Aviation Corp, Genoa City WI	70
			Air Charter Inc, Janesville WI	71/72
			Morey Wyman/ Wyman Pilot Service, Pontiac MI	8.3.73
			crashed destroyed on takeoff, Corapolis PA	7.12.73

N387B accident report 7.12.73: Morey L. Wyman, flight Corapolis-Pontiac MI, pilot took intersection departure, stalled after takeoff 3.33am, fire after impact, 2 k;

BA-411	E18S	N197A N197AA	Beech Aircraft Corp, Wichita KS: CofA issued rereg	26.3.59
		N197G	Automatic Air Service, Camden NJ COAD Inc, Woodcrest NJ	63/64 66
			Delta Casualty Co, Chicago IL	69/72
			P. Brooks Construction Co, Ruskin FL (noted Barranquilla Colombia 4.82 in compound of impounded drug running aircraft) (to FA Colombiana as FAC 564)	20.4.78

### N197G noted Chicago-O'Hare 30.9.71;

noted Barranquilla Colombia 4.82 in compound of impounded drug running aircraft: registration obscured, "N1.7G" readable": almost certainly this aircraft;

BA-412	E18S	N5000T (1	reg	.59
		N5000U	Kinzua Corp, Kinzua OR	63/66
			Flightcraft Inc, Portland OR	69/70
			Lewis Enterprises Inc, Portland OR	71/72
			State Forestry Department, Salem OR	78
		N149PA	Providence Air Charter, Providence RI	10.78/79
			James A. Dole, Coventry RI	21.8.78/79
			op: Providence Air Charter, Providence RI	79
			crashed destroyed landing, Stewart AFB NY	4.4.79
			-	

### N5000U noted Portland OR 27.4.72;

N149PA accident report 4.4.79: Providence Air Charter, cargo flight Boston to Stewart AFB, Newburg NY, stalled in go-around, ice on airframe, 11.15pm, pilot serious injuries;

BA-413	E18S	N5001T (2	Beech Aircraft Corp, Wichita KS: CofA issued	9.4.59
	-9700		Thiokol Chemical Corp, Brigham City UT	31.8.61
			Compax Corp, San Antonio TX	66/79
			Larry Johnson	80
			William R. Sandlin/ Sandlin Flying Service, Harlingen TX	28.3.80
		XB-CFQ	Allen J. K. Devine, Tijuana	-
		N5001T	William R. Sandlin/ Sandlin Flying Service, Harlingen TX	88
		(N616T)	ntu: William R. Sandlin, Harlingen TX	10.88
		N5001T	William R. Sandlin, Harlingen TX	10.88
		N7765N	William R.Sandlin, Evant TX	12.88/95
			May Air Xpress, New Boston TX	31.3.95/02
			Scott Glover, Mt Pleasant TX	.02/03
			Thro Aviation, Bohemia NY	7.03
			(departed Mt Pleasant TX on delivery to NY 31.7.03)	
			North American Leasing LLC, Fort Myers FL	12.7.04/19
			reg expired, struck-off USCR	9.1.19

## XB-CFQ photo at Houston TX 12.83;

Parmerter states: aircraft logbook makes no mention of XB-CFQ but there is a gap in the records

from sale to Sandlin 28.3.80 until 10.84 when a number of STCs were carried out on the aircraft: he assumes that was the period reregistered in Mexico;

Mexican register 93 quotes XB-CFQ Allen Devine, Tijuana - presumed not yet deleted;

N7765N noted New Boston TX 8.97 engineless in barn near grass airstrip: plate BA-413 built 3.59; N7765N noted Texarkana AR 16.8.99 parked outside May Air Xpress hangar engineless; N7765N noted Texarkana AR 2.8.02 plate BA-413 3.59, May Air Express, now all silver and restored to passenger interior;

N7765N at fly-in Oshkosh 7.05, plate BA-413 built 3.59;

N7765N noted Naples FL 17.9.06 civil scheme, tailwheel in service;

BA-414	E18S	N149S	built	.59
		N149R	Northwestern Refining Co, St Paul MN	63/64
			Admiral Merchants Motor Freight Inc, St Paul MN	66
			Gopher Aviation, Flying Cloud Airport MN	69/72
			SMB Stage Line Inc, Des Moines IA	72/85
	Hamilton		(rebuilt as Hamilton Westwind III tailgear 10.72)	
	Westwind III	l	North Continent Airlines, Long Beach CA: Isd.	85/86
			Ajax Aircraft Leasing Inc, Dover DE	8.86
			Active Aero Charter: Isd	87
			crashed destroyed after takeoff, Quincy IL	18.2.87

USCR quotes N149R as first reg; FAA file confirms mod to Westwind III;

N149R noted Burbank CA 2.11.72 Westwind;

N149R noted Tucson AZ 3.4.72 at Hamilton Aircdraft ramp, Westwind III turbines;

"N148R" noted Muskogee OK 2.3.73 at SMB maintenance base, turbines: must be N149R;

N149R noted Columbus OH 10.8.74 PT6As tailwheel, "SMB Stage Lines";

N149R noted Phoenix AZ 23.8.85 turbines, radio callsign "North Continent 500";

accident report 18.2.87: Active Aero Charter;

BA-415	E18S	N1700	Beech Aircraft Corp, Wichita KS: CofA issued	9.4.59
	trigear		Kerr McGee Oil Industries, Oklahoma City OK	63/64
	· ·		Equitable Leasing Corp, Ashville NC	66
		N1707H	Equitable Leasing Corp, Ashville NC	68/70
			op: Gold Coast Airlines, Miami FL	68/69
		N30TD	Aire International Inc, Louisville-Bowman Field KY	71/72
			Tampa Air Centre, Tampa FL	79/84
			lsd: Dolphin Airways	82
			Leon B. Canady, Starke FL	6.85
			R. D. McSwiggan, Griffin GA	17.7.86/99
			Tol Air Inc, San Juan, Puerto Rico	00
			sale reported, San Juan, Puerto Rico: USCR	01/12
			(noted retired at Tolair ramp, San Juan PR 6.00)	
			struck-off USCR	19.7.12

N1707H noted Miami FL 8.10.68 trigear "Gold Coast Airlines",

N1707H noted Opa Locka FL 28.9.70 trigear;

N30TD noted Griffin GA 26.6.96 trigear freighter;

N30TD noted Griffin GA 12.96 op Academy Airlines;

N30TD noted San Juan PR 16.6.00 at Tolair ramp, not operational;

BA-416	E18S	N5668D	Beech Aircraft Corp, Wichita KS: CofA issued	16.4.59
	-9700		Owensboro Aviation, Owensboro KY	63
			George H. Bailey Leasing Corp, Fort Wayne IN	64/69
			Finn Industries Division, Chicago IL	70/72
			ran off runway landing, hit two parked aircraft,	
			Anchorage-Merrill Field AK	14.6.77
			Dale Jackson, Anchorage AK	79
			Gordon Aviation/ Gordon Air Express, Anchorage AK	12.81/84
			Billy A. Robbins, Calabasas CA	7.86/99
			op: Jordan Air Express	93
			California Associates Ltd, Oakdale CA	7.5.99
			Tom Neal, Rancho Mirage CA	28.2.00/02
			Fred J. Willert, Chula Vista CA	23.12.03/20

N5668D noted Chicago-Meigs Field OH 23.7.71;

N5668D noted Anchorage-Merrill Field 15.9.79 windowless freighter, in service;

N5668D noted Lancaster-Fox CA 22.9.85;

N5668D noted San Diego-Montgomery Field CA 3.93, tailwheel, "Gordon Air Express" titles painted over, operates night freight flights;

N5668D noted San Diego-Montgomery Field CA 12.93, retired outside, Jordan Air Express, plate BA-416;

N5668D noted Chino CA 16.8.00 under maintenance, cargo door being removed;

BA-417	E18S	N5675D	built	.59
⊃A-4 I I	E103	עכ זסטוו	Anderson Bros Manufacturing Co, Rockford IL	63/64
		N675D	Anderson Bros Manufacturing Co, Rockford IL	66/70
			Brennan Cattle Co, Kirkland IL	71/72
			Hamilton Aviation, Hamilton OH	73
			Bentley Flight Service, Detroit MI	79
			John J. Murphy, Pontiac-Oakland MI	17.7.79/87
			struck-off USCR	1.87
	N675D not	ed Rockford II	_ 23.7.71;	
3A-418	E18S	N666X	built	19.2.59
	-9700		Braymont Inc, Syracuse NY	63/69
			S & B Flite Inc, Baldwinsville NY	70/72
			Merrimack Airlines Corp, Bedford MA	78
			D&C Leasing Corp, Lawrence MA	79
			Providence Air Charter, Providence RI	80
			damaged ground-loop taxying for takeoff, Columbus IN	30.8.80
			Rhoades International, Seymour IN	80
			Roy D. Hartley, Parma Heights OH	21.10.81/95
			struck-off USCR	17.4.95
	N666X not	ed Syracuse N	NY 27.8.74;	
3A-419	E18S	N5663D (2	Beech Aircraft Corp, Wichita KS: CofA issued	29.4.59
J/\- <del>-</del> 13	-9700	N390V	Victor Adding Machine Co, Chicago IL	64
	-9700	143904		
			Cherokee Village Development Co, Cherokee Village AR	
			SMB Stage Line Inc, Des Moines IA	69/77
			Precision Valley Aviation, Springfield VT	78/84
			Rockingham Aviation Corp/ K&K Aircraft, Bridgewater VA	8.84
			(converted for aerial application, 350 gallon cabin	
			chemical tank installed for gipsy moth and mosquito	
			spraying contracts)	
			Darlene Gilding, Memphis TN	24.1.86/05
			Beech of Dreams Inc, Wilmington DE	16.11.05/07
			Skyranch Aviation, Alma AR	13.11.08/17
			Gryder Netyworks LLC, Griffin GA	9.5.17/18
			Pinion Air Service, Great Falls MT	7.10.19/20
	N390V not	ed Chicago-O	'Hare 24.2.69 SMB Stage Lines;	
	N390V not	ed Dallas-Love	e TX 10.4.73 SMB Stage Lines;	
			VT 7.10.80, tailwheel, in service;	
			TN 2.95, no titles, tailwheel;	
			TN 8.98 as locally based freighter;	
			ch MS 31.7.02 plate BA-419 built 4.59, plate -9600 mods;	
	N/39/1// not			
	N390V note	ed Olive Brand	ch MS 5.8.03, freighter, for sale;	
	N390V note (not sighted	ed Olive Brand d at Olive Bran	nch MS 8.05 by GR but told it was still on the field)	
	N390V note (not sighted N390V note	ed Olive Brand d at Olive Brand ed Eloy AZ 11	nch MS 8.05 by GR but told it was still on the field) .8.08;	
3A-420	N390V note (not sighted N390V note	ed Olive Brand d at Olive Bran	nch MS 8.05 by GR but told it was still on the field) .8.08; built	.59
3A-420	N390V note (not sighted N390V note	ed Olive Brand d at Olive Brand ed Eloy AZ 11	built Southland Paper Mills Inc, Lufkin TX	63/69
3A-420	N390V note (not sighted N390V note	ed Olive Brand d at Olive Brand ed Eloy AZ 11	nch MS 8.05 by GR but told it was still on the field) .8.08; built	
3A-420	N390V note (not sighted N390V note	ed Olive Brand d at Olive Brand ed Eloy AZ 11	built Southland Paper Mills Inc, Lufkin TX	63/69
3A-420	N390V note (not sighted N390V note	ed Olive Brand d at Olive Brand ed Eloy AZ 11 N112L	built Southland Paper Mills Inc, Lufkin TX registration pending: USCR	63/69
3A-420	N390V note (not sighted N390V note	ed Olive Brand d at Olive Brand ed Eloy AZ 11 N112L HH-PRO	built Southland Paper Mills Inc, Lufkin TX registration pending: USCR reg reg	63/69 70/72
3A-420	N390V note (not sighted N390V note	ed Olive Brand d at Olive Brand ed Eloy AZ 11 N112L HH-PRO	built Southland Paper Mills Inc, Lufkin TX registration pending: USCR reg Roy E. Amos, Fort Myers Beach FL	63/69 70/72 7.82
3A-420	N390V note (not sighted N390V note	ed Olive Brand d at Olive Brand ed Eloy AZ 11 N112L HH-PRO	built Southland Paper Mills Inc, Lufkin TX registration pending: USCR reg Roy E. Amos, Fort Myers Beach FL David Fernandez Alvarado, St Croix USVI	63/69 70/72 7.82 9.83
3A-420	N390V note (not sighted N390V note	ed Olive Brand d at Olive Brand ed Eloy AZ 11 N112L HH-PRO	built Southland Paper Mills Inc, Lufkin TX registration pending: USCR reg Roy E. Amos, Fort Myers Beach FL David Fernandez Alvarado, St Croix USVI Luis E. Hernandez, Rio Piedras, Puerto Rico	63/69 70/72 7.82 9.83 2.85
3A-420	N390V note (not sighted N390V note	ed Olive Brand d at Olive Brand ed Eloy AZ 11 N112L HH-PRO	built Southland Paper Mills Inc, Lufkin TX registration pending: USCR reg Roy E. Amos, Fort Myers Beach FL David Fernandez Alvarado, St Croix USVI Luis E. Hernandez, Rio Piedras, Puerto Rico Abigail F. Lopez, Rio Pedras, Puerto Rico	63/69 70/72 7.82 9.83 2.85 3.88/92
3A-420	N390V note (not sighted N390V note	ed Olive Brand d at Olive Brand ed Eloy AZ 11 N112L HH-PRO	built Southland Paper Mills Inc, Lufkin TX registration pending: USCR reg Roy E. Amos, Fort Myers Beach FL David Fernandez Alvarado, St Croix USVI Luis E. Hernandez, Rio Piedras, Puerto Rico	63/69 70/72 7.82 9.83 2.85

DA 101	E400	NIOCEO	1. 20	
BA-421	E18S	N665Q	built Alama Aviation, San Antonia TV	.59
	-9700	N665M	Alamo Aviation, San Antonio TX	63/64
			H. B. Zachry Corp, San Antonio TX	66/69
			Midwest Airways, Milwaukee WI	70/72
			Semo Aviation, Malden MO	79
			Marian E. Riner, Mullsboro DE	8.83/91
			Jim West/ Skydive Greene County Inc, Xenia OH	27.1.92/13
			crashed after takeoff Xenia OH	1.5.93
			(stored at owner's farm, Xenia OH 05)	0 = 40
			struck-off USCR	6.5.13
	N665M no N665M no N665M no	ted Green Co ted Xenia OH	MO 2.6.75; een County OH 3.92, Skydive Greene County, no titles, tailv ounty OH 6.8.99 Skydive, engines removed, plate: BA-421 E I 1.8.05 stored outside at Jim West's farm near airfield, wing County", being used for spares, plate E18S-9700;	E18S-9700;
BA-422	E18S	N5696D	built	5.59
5, 122	2.00	1100002	North American Van Lines Inc, Fort Wayne IN	63/68
	G18S cab		Mid Continent Airlines, Morris IL	69/70
			Blackhawk Airways, Janesville WI	26.9.77/79
			(purchased in damaged condition, G18S cab removed	
			and installed in Blackhawk's N166H)	
			struck-off USCR	4.12.79
			(stripped and derelict, Janesville WI 82)	
			-O'Hare 31.10.68 NA Van Lines; le WI 10.5.82, retired derelict;	
BA-423	E18S	N954 (1	Colorado Interstate Gas Co, Colorado Springs CO	.59/64
		N954F	rereg	00
		N1814	National Finance Inc, Wilmington DE	66
			Rambar Aviation, Parkersburg WV struck ILS antennae landing, Detroit-City MI	69/70 17.6.70
			Dobbelaere Aviation, Oakwood OH	4.1.71/74
			struck-off USCR	25.7.74
			7.6.70: Rambar Aviation, windshift during landing in	
	thundersto	rm on wet rui	nway, ran off runway, 5 unhurt;	
BA-424	E18S	N2067C	Beech Aircraft Corp, Wichita KS: CofA issued	13.5.59
	-		nacelle fire after JATO firing, landed safely, St Paul MN	5.12.60
			Waldorf Paper Products Co, St Paul MN	63/64
			Lease Air Inc, San Diego-Montgomery Field CA	69/72
			located damaged abandoned, stolen, California	4.4.78
			Aerospace Products Inc, North Hollywood CA	79
			Wyman Pilot Service, Pontiac MI	82/84
			Northern Airmotive Corp, Kenosha WI, later Hillsboro OH	15.6.89/00
			crashed destroyed on takeoff, Fayette County OH	10.10.00
	N2067C ni	oted Oakland	CA 17.9.68:	
		oted Oakland		
			MI 9.80, plate BA-424;	
			own OH 16.6.82 Wyman Pilot Service;	
			gton Court House-Fayette County OH 8.99 with Northern Ai	rmotive;
			p Northern Airmotive Corp, crashed immediately after taked	
			e-Fayette County OH on positioning flight to Airborne Airpa	
ОН,	struck grou		off and exploded, P&W R985s pilot was owner of company	-
DA 425	E100	NZECE	I D Stovens & Co New York NY	50/64
BA-425	E18S	N75SF N75S	J. P. Stevens & Co, New York NY rereg	.59/64
		117.00	10109	

rereg N1157S

N7581 First Federal Savings & Loan, Raleigh NC

69/70 B J Aero Freight Inc, Oskaloosa IA 7.1.74/75 crashed destroyed landing, Rockford IL 2.1.75

photo shows N72SF, N73SF, N74SF, N75SF & N176SF in row at Wallace NC 4.61, all tailwheel, all owned J.P.Stevens & Co;

Published USCR66: not listed under any of the regs;

N7581 noted Houston-Hobby TX 6.5.73;

accident report 2.1.75: BJ Aero Freight, mail flight Ottumwa IA to Rockford, airframe ice, stalled in the circuit;

BA-426	E18S	N1905L	built	.59
	-9700		Special Services Corp. Greenville SC	63/64
		N1905K	rereg	
		N932R	Rust Engineering Corp, Birmingham AL	66/72
			Compass Aviation Ltd, Farmingdale NY	28.2.75
			sold to Bolivia, struck-off USCR	28.3.75
		CP-1197	Aero Sur Ltda, Cochabamba	.75/78
			op: Taxi Aerosur, Cochabamba	76/78
			Aerovias Balcazar - AEROBAL, Cochabamba	85/86
			Aerobal Machanics School, Cochabamba:	
			ground instructional airframe	85

N932R noted San Antonio TX 16.5.73;

CP-1197 noted Cochabamba 26.9.78 "Taxi Aerosur" titles;

CP-1197 noted Cochabamba 1.5.85 in use as instructional airframe at Aerobal mechanics school;

BA-427	E18S	N2071C	built	.59
	-9700		Anchor Hocking Glass Corp, Lancaster PA	61/66
		CF-HBE	reg	
		N9000M	Skagit Corp, Sedro Woolley WA	68/70
			(US CofA renewed 13.6.68)	
			CSC Leasing Co, Seattle WA	71/72
			Stockert Flying Service, South Bend IN	79/81
			(operated as STS Freightliner 79)	
	Hamilton		Florida Airmotive Inc, Lantana-Palm Beach FL	4.81/84
	Extended	N171LG (2	Florida Airmotive Inc, Lantana-Palm Beach FL	2.84/86
	Nose	•	Florida Caribair Inc, Boynton Beach FL	91
			US Dept of Justice, Arlington VA	5.93
			Caribbean Leasing Corp. Orlando FL	14.9.93/95
			op: Avmac Air	95
			ditched in sea due in-flight fire, en route Orlando FL to	
			Freeport, Bahamas	28.8.95

N9000M noted Seattle-Boeing Field WA 29.4.72 "Pacific Land Associates" titles; N9000M noted Oshawa ONT 20.4.79 "Stockert FS Freightliner"; N9000M noted Detroit Metropolitan-Wayne County 4.79 tailwheel "STS Freightliner"; N9000M noted Lantana FL 16.3.81 "SFS Freightliner";

BA-428	E18S	N379B	built	.59
	-9700		Kawneer Co, Niles MI	63
			American Metal Climax Inc, Niles MI	64/66
			Patrick Plywood Enterprises Inc, Elkhart IN	69
			Patrick Industries Inc, Elkhart IN	72
		CF-WDV	Millardair Ltd, Toronto-Malton ONT	7.73/78
		C-FWDV	Millardair Ltd, Toronto-Malton ONT	78/93
			sold to USA: struck-off Canadian Register	5.93
Hamilton extended nose	N7058U	Casablanca Air Transport, New York NY	20.5.93	
		Classic Air Transport Inc, Ridgewood NJ	1.94	
			Ronald P. Wayner, White River, South Africa	2.3.94/95
	Hamilton		(dep. Lanseria for relief work in Rwanda 6.94)	
	extended		op: Mercy Air South Africa	94/10
	nose		exported to South Africa, struck-off USCR	17.4.95
		ZS-OIJ	Nelair Pty Ltd, White River	10.98
			Bateleur Air, Namibia	.10

15/18

N379B visited Toronto ONT 15.4.64;

CF-WDV noted Toronto ONT 25.8.74 "Millardair":

C-FWDV noted Toronto ONT 15.9.79 "Millardair" titles, tailwheel;

C-FWDV noted Toronto ONT 5.8.89 "Millardair" titles, tailwheel;

N7058U flew Quelimane-Nelspruit, South Africa 9.4.95;

N7058U noted Witrivier, South Africa 29.1.96, resident, plate BA-428;

N7058U noted airshow Margate, Natal 1.5.96;

ZS-OIJ noted Johannesburg-Rand 17.8.14 flying; also 21.4.16 all metallic extended nose;

ZS-OIJ landed at Mongena Game Lodge, near Pretoria 11.10.15;

E18S BA-429 Turkish Air Force as 6938 .59

photo: E18S Turkish AF 6938 at Prestwick on delivery (no date), military scheme;

BA-430	E18S -9700 Junior JATC	N2069C	Arkansas Power & Light Co, Little Rock AR: CofA issued (Aerojet-General Junior JATO kit installed in rear of nacelles 59)	10.6.59/64
			Central Flying Service, Little Rock AR	69/79
			Paul W. Milam, Fayetteville AR	1.82
			Mid South Operations Inc, Fayetteville AR	7.83
			Richards Aviation, Memphis TN	84
			Springdale Air Service, Springdale AR	20.3.87/99
			ground collision with Cessna 310 on UPS ramp,	
			Memphis TN	27.1.94
			ground collision with Springdale E18S N4980V	
			on taxiway at UPS ramp Dallas-Ft Worth TX	29.12.97
			Air West Inc, Mesa AZ	26.2.01/03
			Mark Todd LLC, Mesa AZ	15.5.03/11
			Aztec Worldwide Airlines Inc, Wilmington DE	14.12.11/20

N2069C noted Memphis TN 9.85 in service, no windows, tailwheel, no titles;

N2069C noted Texarkana AR 8.97 Springdale Air Service: in service, plate BA-430, built 6.59;

N2069C noted Mesa AZ 6.01, tailwheel; Mesa 1.8.02, 28.6.03 tailwheel;

N2069C noted Mesa AZ 10.10.04 tailwheel in service, rough paintwork, reportedly op Air West;

N2069C noted Mesa AZ 3.06 "Harley Davidson" nose art; N2069C noted Mesa AZ 18.7.08 freighter, "Air West";

BA-431	E18S	N452C	built	.59
-9700		Peter Kiewit & Sons Inc, Omaha NE	63/64	
			Ruby Co, Boise ID	66/69
		N452CC	Johnson Flying Service, Missoula MT	70/72
			Dickinson Air Service, Dickinson ND	79
			Frank E. Fairchild	81
		confiscated at West Palm Beach FL: due use in illega	al	
		drug smuggling operations	2.81	
		Crown Air Services, Fort Lauderdale FL	6.81	
		Smithair Inc, Sharpsburg GA	9.82/85	
		ran off runway, nosed over, Jonesboro GA	20.9.83	
		Robert G. Stanford, Kodiak AK	12.3.90/93	
			struck-off USCR	30.4.93

N452CC noted Toronto ONT 4.11.85 "Summit" logo on tail;

BA-432	E18S	N670Q	Beech Aircraft Corp, Wichita KS	6.59
	-9700		Beech demonstrator, Aerojet-General Junior JATO	
			installed in rear of engine nacelles)	
		N404T	Trostel Aviation Co, Milwaukee WI	63/69
			Par Aviation, Hales Corners WI	70/79
			Richard W. Hansen, Batavia IL	2.12.83/06
			(departed Chicago 19.6.97 to Europe for tour,	
			returned to Chicago 11.7.97)	

G18S cab (fitted c86 with Beech G18S cockpit cab mod. removed

from N68V BA-282)

Pissed Away N404T LLC, Bellevue WA 25.8.10/12

Greatest Generation Naval Museum, San Diego CA, later

Colorado Sporings CO 11.1.13/20

N404T noted Reno NV 12.9.75;

N404T at fly-in Oshkosh WI 1.8.91;

N404T at Beech flv-in Tullahoma TN 10.93 & 16.10.94:

N404T at Beech fly-in Wichita KS 9.10.97, plate BA-432;

N404T noted Janesville WI 26.7.99 visiting for maintenance, owned Richard Hansen IL,

plate BA-432 E18S-9700 built 6.59, still carried markings for Chicago-Europe flight 19.6.97 to 1.7.97; N404T at fly-in Lakeland FL 10.4.01;

N404T at Beech fly-in Tullahoma TN 16.10.02, by now fitted G18S cab;

N404T at fly-in Oshkosh 7.03 Richard Hansen, won award;

N404T at Beech fly-in Tullahoma TN 16.10.03;

N404T at fly-in Oshkosh 30.7.10;

BA-433	E18S	4R-AAU	Ceylon Survey Department, Colombo	28.7.59/82
			(fitted for photographic survey prior to delivery) arr. Colombo on delivery flight ex Beech	7.59
			(retired Colombo-Ratmalana 80/81) to Sri Lanka AF as CS450	.82
		op: Sri Lanka Government Survey Department	82/89	
			op: No.2 Training Wing, Ratmalana AB Sri Lanka Air Force Museum, Ratmalana AB	94/21

4R-AAU noted Ratmalana 13.4.63 "Ceylon Survey Dept" titles, tailwheel;

4R-AAU noted dismantled, Colombo-Ratmalana 3.80;

4R-AAU reported derelict at Ratmalana 81;

CS450 still in service 89;

CS450 noted in SLAFM Ratmalana 3.97, 2.11; 2.16;

Sri Lanka AF report 88: H18 delivered in 1982 and op for Govt Survey Dept 82/83;

BA-434	(E18S)		E18S-9700 BA-444 modified at Beech factory to	
	Ġ18S <sup>′</sup>		become prototype for the Super G18S model,	
			FAA type certification 8.10.59)	
		N2072C	Beech Aircraft Corp, Wichita KS	.60
		N866A	Tidewater Construction Corp, Norfolk VA	63/64
		N8668	Piedmont Aviation, Winston Salem NC	66
		N8668V	Business Aircraft Leasing, Gainesville FL	69
			Virginia Equipment Corp, Suffolk VA	70/72
			Heilig Meyers Co, Suffolk VA	79
		(N106TD)	ntu: Fayette Aviation NC	2.80
	N8668V	rereg	80	
		N101RG	GALCO Leasing Co, Houston TX	11.80
			Bentley International Trading, Santa Monica CA	6.82
			struck-off USCR	7.82

Certification of G18S: see Beech 18 by Robert Parmerter p.294;

N101RG noted Oklahoma City OK 16.6.81 "Annie" under cockpit, tailwheel, excellent condition;

E18S	N1250 (2	Iowa Engineering Co, Cedar Rapids IA	4.59/66
-9700	N1258	Altorfer Machinery Corp, Cedar Rapids IA	69/70
		ran off runway into snow and mud,	
		gear collapsed, landing Kansas City MO	16.12.70
		S. W. Sisk, St Louis MO	71/72
	Madison National Airways Inc., Madison IN	29.5.73/74	
		crashed destroyed by fire on takeoff, Madison IN	11.9.74
			-9700 N1258 Altorfer Machinery Corp, Cedar Rapids IA ran off runway into snow and mud, gear collapsed, landing Kansas City MO S. W. Sisk, St Louis MO Madison National Airways Inc, Madison IN

N1258 accident report: operator Madison Nation- (full name obscured), hit trees after airborne 12.10am, flight to Lexington KY, 2 crew k;

_				
BA-436	E18S	N10J	Beech Aircraft Corp, Wichita KS: CofA issued	6.7.59
	-9700	N540MC (2	Interstate Life Insurance Co, Chattanooga TN	63/67
		N549MC	Interstate Life Insurance Co. Chattanooga TN	11.67

	Seymour Rose, Glencoe IL Impex Corp, Camp Hill PA	30.1.68/70 70
N3131W	Southland Oil Co, Yazoo City MS	71/72
	S. S. Airways Inc, Kansas City KS	74/81
	ground collision with van, Chicago-O'Hare IL	17.12.77
	Frank Taylor, Drexell Hill PA	7.81
	US Customs Service, Washington DC	4.84
	Lansing Community College, Lansing MI	5.1.90/14
	(instructional airframe at College 99)	
	struck-off USCR	17.2.14

N549MC noted La Guardia NY 3.6.70 Implex Corp; N3131W noted Kansas City-Fairfax MO 3.6.76;

N3131W accident report 17.12.77: SS Airways, taxying for departure to Kansas City at 4.05am, 2 crew unhurt;

BA-437	E18S	N156H	Beech Aircraft Corp, Wichita KS: CofA issued	9.7.59
	-9700		Flint Steel Corp, Tulsa OK	63
			Cherokee Village Development Corp,	
			Cherokee Village AR	64
			Greensboro High Point Air Service, Greensboro NC	66/72
			Professional Air Charter, San Francisco CA	.80
		Cocker Air Freight, Dallas TX	1.83/84	
			renamed: Skyfreighters Corp, Dallas TX	7.84
		Onyx Aviation, Oklahoma City OK	9.84	
		Telford Aviation, Waterville ME	8.85	
	Barron Thomas Aviation, Dallas TX	12.87		
		Royal Air Freight, Pontiac MI	27.1.88/08	
			(retired derelict, Pontiac MI 91/00)	
			struck-off USCR	1.12.08

N156H noted Detroit-City MI 24.5.76;

N156H noted Pontiac MI 7.91 poor condition, plate E18S-9700 BA-437;

N156H noted Pontiac MI 2.97 Royal, retired stored;

N156H noted Pontiac 3.3.97;

N156H noted Pontiac 7.98 stored;

N156H noted Pontiac MI 23.7.00 derelict, plate BA-437 built 7.59;

BA-438	E18S	N930R	Beech Aircraft Corp, Wichita KS: CofA issued	17.7.59	
	-9700		Rust Engineering Co, Pittsburgh PA	63/66	
			Saunders Leasing System, Birmingham AL	69/70	
			Osborne & Co, Birmingham AL	71/79	
			James J. Thompson, Birmingham AL	7.82	
			Twin Beech Aviation, Birmingham AL	1.84/95	
			Doug Armstrong/ A & M Aviation Inc, Matthews NC	1.10.97/14	
			David B. Garrett, Polson MT	27.8.14/20	

N930R noted Birmingham AL 5.93, tailwheel, just completed interior refurbishment,

no titles, always had been an executive aircraft never a freighter;

N930R noted Pell City AL 5.93, tailwheel, in service;

N930R visited Beech fly-in Tullahoma TN 16.10.94

N930R visited Beech fly-in 13.10.95 plate BA-438;

N930R at fly-in Oshkosh WI 8.97 plate BA-438 E18S-9700 built 7.59;

N930R at Oshkosh 8.98 civil scheme, award winner: owner Doug Armstrong NC;

N930R at Beech fly-in Tullahoma TN 16.10.98 flown Doug Armstrong;

N930R at airshow Lakeland FL 4.99;

N930R at fly-in Oshkosh 8.99 Doug Armstrong;

N930R at Beech fly-in Tullahoma TN 16.10.02 Doug Armstrong;

N930R at Beech fly-in Tullahoma TN 18.10.14; Oshkosh 7.15, 7.16;

BA-439	E18S	N2094C	Skyways Aircraft Ferry Service Inc, Van Nuys CA	.59	
			exploded mid-air near Wake Island, Pacific on		
			delivery flight to Japan	1.9.59	

further details, see Beech 18 by Parmerter p.289;

BA-440 E18S N324B Beech Aircraft Corp, Wichita KS: CofA issued 24.7.59 G18S Cab N317MH A. C. Houston Lumber Co, Boise ID 63/64 Medusa Equipment Co, Oildale/Bakersfield CA 66/72 Tye Sales Co, Lockney TX 79 Lawrence T. Biedenharn, San Antonio TX 5.91 Ronald R. Hyde, Kenedy TX 22.12.93/06

Cheryl H. Walton, Indianapolis IN

9.4.07/20

N317MH noted San Francisco CA 4.8.66:

N317MH at Beech fly-in Tullahoma TN Beech fly-in 10.94, plate BA-440;

N317MH at Beech fly-in Tullahoma TN Beech fly-in 13.10.95;

N317MH at fly-in Oshkosh WI 1.8.96;

N317MH at fly-in Oshkosh 8.97 plate BA-440;

N317MH at Beech fly-in Wichita KS 11.10.97, plate BA-440;

N317MH at Oshkosh 8.98 plate: BA-440 built 7.59, owner Ron Hyde, Kenedy TX;

N317MH at Beech flyin Tullahoma TN 16.10.98 tailwheel, Ron Hyde, Kenedy TX;

N317MH at fly-in Oshkosh 8.99 Ron & Pat Hyde, Kenedy TX;

N317MH at Beech fly-in Tullahoma TN 10.10.99 Ron Hyde TX;

N317MH at fly-in Oshkosh 30.7.00 owned Ron Hyde, Kenedy TX, plate BA-440 built 7.59;

N317MH at Beech fly-in, Tullahoma TN 18.10.00;

N317MH at fy-in Oshkosh 3.7.02;

N317MH at Beech fly-in Tullahoma TN 16.10.02 Ron Hyde;

N317MH at fly-in Oshkosh 30.7.03 Ron Hyde;

N317MH at Beech fly-in Tullahoma TN 16.10.03;

N317MH at fly-in Oshkosh 31.7.04;

N317MH at fly-in Oshkosh 7.06 Ron Hyde; noted at Janesville WI 25.7.08;

BA-441	E18S	N246AA	Beech Aircraft Corp, Wichita KS: CofA issued	6.8.59
2,	-9700	N1230S	United States Rubber Co, New York NY	63
			Bowes Seal Fast Corp, Indianapolis IN	64
			Marion Brick Corp, Marion OH	66/69
			William L. Hart, Arlington VA	70
			Air Chicago Freight Airlines, Chicago IL	71/72
	Hamilton	N102SA	Shorter Airlines, Miami FL	.72/73
	extended		Ridder Air Enterprises, Whiteman MA	79
	nose		Universal Action Corp, Middleburg Heights OH	4.84
			Robert B. Burwell, West Chicago IL	11.90/98
			op: Viking Express, Chicago-Midway IL	97
			Kestrel Inc, Waukee IA	30.4.98/20
			op: Turks Air Cargo, Opa Locka FL	13

N1230S noted Washington-DCA 30.9.70,

N1230S Chicago-O'Hare 28.8.71 Air Chicago;

N102SA noted Detroit-City Airport MI 5.72 "Shorter Airlines" titles, standard nose, tailwheel, polished metal scheme;

N102SA noted San Antonio TX 1.9.73 & 28.9.73, Hamilton conversion, Shorter AL;

N102SA photo 8.78 with Hamilton long nose;

N102SA noted Aurora IL 8.97 Viking;

N102SA noted Oskaloosa IA 24.7.98 in service, freighter, Kestrel Inc, lengthened nose, plate: BA-441 built 7.59 as E18S-9700, AUW increased to 10,100 lb by Hamilton Aircraft; N102SA retired Opa Locka FL late 2013, ferried to FLL Executive .15 parked 15-16;

BA-442	E18S	N137X	Beech Aircraft Corp, Wichita KS: CofA issued	31.7.59	
			Collins Radio Co, Richardson TX	63/66	
			(Collins flying avionics showcase)		
	-9700		(mods to E18S-9700 installed 4.67)		
		N901NC	Belton Bagging Co, Belton SC	69/72	
			United Leasing Corp, Richmond VA	79	
			Equipment Leasing Corp, Greenville SC	7.81/84	
			op: General Aviation Inc, Greenville TN	80	
			lsd: Mountain Air Cargo, Denver NC	.80/84	
			Coastal States Aviation, Denver NC	3.85	
			Mountain Air Cargo, Denver NC	86	
			P B Leasing Company, Naperville IL	5.87	
			Milton Glass, Anoka MN	2.88	
		N962AA	Milton Glass/ Arrowhead Airways Anoka MN	3.88	

N992PT	S D Air Express, Jackson WI op: Ernie Joyner/ Arrowhead Airways, Blaine MN Trans Gulf Airways, Slidell LA Taylor Energy Co, New Orleans LA Taylor Energy Co, New Orleans LA insurance write-off New Orleans, probably due Hurricane Katrina 10.05)	2.89 90 31.8.92/99 8.6.99 14.7.99/06
	struck-off USCR	9.8.06

N962AA noted Slidell LA 9.8.98, plate: BA-442 built 7.59; plate -9700 conv. 4.67; N962AA at airshow Lakeland FL 4.99 Trans Gulf AW, Slidell LA, no titles;

BA-443	E18S	N326W	Beech Aircraft Corp, Wichita KS: CofA issued	28.7.59
			White Motor Co, Lansing MI	63/66
			SMB Stage Line Inc, Des Moines IA	69/80
			Crawford Aviation	.80
			Aurora Air Service, Fairbanks AK	81/91
			ran into ditch landing, Tobin Creek AK	30.7.81
			Roger W. Brooks/ Brooks Fuel Inc, Fairbanks AK (stored stripped, derelict, Fairbanks AK 96/11)	28.10.92/13
			reg expired, struck-off USCR	30.7.13

N326BW noted Fairbanks AK 26.5.90;

N326W noted Fairbanks 4.96, derelict with N114V: both stored by Brooks for future use;

N326W noted Fairbanks AK 15.8.00, wreck used for spares only;

N326W noted Fairbanks AK 18.4.04 at Brooks fuel junk area, N326W noted Fairbanks AK 8.9.04 at Brooks fuel junk area, engineless;

N326W noted Fairbanks 26.9.05 at Brooks fuel, parts & engines removed, same 6.08;

N326W noted Fairbanks 8.7.11 stored;

BA-444	E18S	N352B	Beech Aircraft Corp, Wichita KS: CofA issued	18.8.59		
			Electric Autolite Co, Toledo OH	63		
			Eltra Corp, Toledo OH	64		
			National Flight Service, Toledo OH	66		
			Ross Aviation, Tulsa-Riverside OK	69		
			Great Western Airlines, Tulsa-Riverside OK	70/80		
			lsd: International Aviation Corp, Minneapolis-Crystal MN	80		
			Crawford Aviation	.80		
			Midwest Aviation Corp, Davenport IA	20.7.81/85		
			forced landing in ploughed field, Pharr TX	10.3.85		
BA-445	E18S	N89D	Youngstown Airways/ Lease Air, Youngstown OH	.59/64		
	-9700	N6911	Lease Air Inc, Youngstown OH	66		
			SMB Stage Line Inc, Des Moines IA	69/79		
			op; Island Airlines Hawaii, Honolulu HI	.79/80		
			First Venture Corp, Bartlesville OK	5.12.79/82		
			crashed, destroyed by fire, Hakalau HI	28.4.82		
	N6911 noted Chicago-O'Hare 8.9.71 SMB Stage Lines;					
	N6911 noted Chicago-O'Hare 30.9.71 SMB Stage Lines;					
	N6911 noted Muskogee OK 2.3.73 at SMB Stage Line maintenance base;					
	N6911 nc	N6911 noted Dallas-Love TX 12.7.73;				
	N6911 nc	oted noted Hor	nolulu 9.10.80 Island Airlines Hawaii, no titles;			
BA-446	E18S	N2083C	built	8.59		
	0700		11 ( 11 1 ( ) 1 B: OH	00/70		

BA-440	E185	N2083C	Duit	8.59	
	-9700		Hartzell Industries Inc, Piqua OH	63/72	
			Orville E. Horten, Indianapolis IN	79	
			Indianapolis Air Charter Services, Indianapolis IN	3.83/86	
			Indianaero Inc, Bloomington IN	4.89/91	
			David B. Norcutt, Mount Airy MD	8.93	
			Aero Express Inc, Dearborn Heights MI	8.9.94/95	
			op: Blackhawk Airways, Rock County WI	97	
			Kenneth R. Phillips/ Phillips Air Service,		
			Del Rio TX	22.1.98	
			crashed on takeoff, Del Rio TX	8.4.98	
			struck-off USCR	5.11.98	

N2083C noted Fort Wayne IN 28.5.76;

N2083C noted Bloomington IN 10.91, tailwheel, no titles;

N2083C noted Grosse Isle MI 2.97 "Aero Express" titles;

N2083C noted Rock County WI 7.97 "Aero Express" titles painted over, rep. op. Blackhawk Airways, plate BA-446 built 8.59;

N2083C was stripped for parts 5.10 by Bill Signs to restore his E18S N666AK;

BA-447	E18S -9700	N2079C	Beech Aircraft Corp, Wichita KS: CofA issued Southern Alrways Co, Altlanta Airport GA Dickerson Inc, Monroe NC sale reported, Elberton GA struck-off USCR	19.8.59 63/64 69/72 77 18.10.77
		XB-ADS	Rogelio R. Perez, Mexicali	93
BA-448	E18S	N680Q	Beech Aircraft Corp, Wichita KS: CofA issued	4.8.60
	trigear		Sewart Seacraft Inc, Berwick LA	63/64
			Crosby Forest Products Co, Picayune MS	66/70
			Delmar L. Phillips, Converse TX	71/72
			Stillwater Publishing Co, Stillwater OK	79/91
			PWA Aircraft Inc, Ponca City OK	11.93/96
			La Tour Air, New Baltimore MI	14.5.96
		N190CM	La Tour Air, New Baltimore M	10.96
			Mike Strong Resources Inc, Birmingham AL	10.8.98/01
			Barrels of Fun Inc, Lebanon MO	25.5.01
			B & B Leasing Co, Lebanon MO	19.7.02
			Markley C. Brown, Santa Ynez CA	29.7.03
		N7MB	Markley C. Brown, Santa Ynez CA	6.10.03/05
			TDH Investments LLC, Dewey AZ	8.3.06
			Beechit LLC, Precott AZ	11.8.09/12
			Michael H. Glenn, Midland TX	3.1.13/20

N680Q noted Oklahoma City OK 25.6.81 trigear, no titles;

N190CM noted Pontiac MI 12.96;

N190CM noted Pontiac 7.97 trigear;

N190CM visited Beech fly-in Tullahoma TN 16.10.98 trigear owned Michael &

Catherine Strong, Birmingham AL;

N190CM at Beech fly-In Tullahoma TN 10.10.99 Michael Strong, Alabama;

N190CM at Beech flyIn, Tullahoma TN 18.10.00;

N190CM BA-448 advertised for sale T-A-P 5.01: trigear TT5650hrs: always corporate executive airplane, Dee Howard spar strap, meticulously maintained, \$225K: Strong Resources;

BA-449	E18S	N161DP	Beech Aircraft Corp, Wichita KS: CofA issued Detroiter Mobile Homes Inc, St Louis MI	.59 63/64
		N5000M	Continental Independent Telephone, St Louis MO Continental Telephone Service Corp, Wentzville MO	66 69/72
		NSOUCIVI	sale reported, Azusa CA	6.76/91
		noted Topeka noted Bakersfi	KS 24.8.70; eld-Meadows Field CA 20.4.72;	
BA-450	E18S	N509B	built	.59
			Conley Lott Nichols Machinery Co, Dallas TX	63/72
			Modern Aero Inc, Dallas-Redbird TX struck-off USCR	19.12.73/77 22.8.77
BA-451	E18S	N2095C	built	.59
			Lodi Drilling & Service Co, Longview TX	63/72
			Robert L. Burns, Shawnee Mission KS	17.3.77/91
BA-452	E18S	N438A	Armco Steel Corp, Topeka KS	.59
			Shakespeare Co, Kalamazoo MI	63/66
			Jack Adams Aircraft Sales, Walls MS	69 70/74
			Jim Hankins Air Service/ Hankins Airways, Jackson MS	70/74

landed gear locked-up, Albany NY	18.1.74
Wyman Pilot Service, Pontiac MI	16.3.78/79
crashed destroyed during a 3 aircraft formation flypast	
at night over a relative's house. Burton OH	9.5.79

N438A noted Nashville TN 17.10.73 Hankins Airways;

N438A accident report 18.1.74: Hankins Airways, flight from Lebanon NH, temperature 12 degrees below zero, mechanical fault in gear extention, 1am, 2 unhurt;

N438A accident report 9.5.79: Wyman Pilot Service: flight Youngstown OH to Pontiac MI, 3 aircraft formation low flypast over leader's mother's house, 12.05am, N438A struck trees & burned, pilot k;

BA-453	E18S	N435A	Armco Steel Corp, Topeka KS: CofA issued	18.9.59/66
	-9700	N4351	Wedekind Aircraft Inc, Middletown OH	69/70
			Crosco Inc, Canton OH	71/79
			John Schweller, Wilmington DE	3.86
		N712JS	John Schweller, Wilmington DE	4.86
	G18S Cab		Classic Aircraft Inc, St Louis MO	7.89/91
			Alton E. "Chuck" Cianchette, Palmyra ME	8.12.91/02
			Chuck's Classic Aircraft LLC, Palmyra MF	6.3.02/20

N4351 noted Chicago-O'Hare IL 23.7.71;

N712JS at Oshkosh WI 1.8.89, plate BA-453;

N712JS at Beech flv-in Wichita KS 10.92:

N712JS at Beech flyins Tullahoma TN 10.93,16.10.94 & 13.10.95, plate BA-453;

N712JS at Oshkosh WI 8.97 "Miss Maine" plate BA-453 E18S-9700 built 9.59;

N712JS at Beech FlyIn Wichita KS 11.10.97 plate BA-453 "Miss Maine";

N712JS at Beech fly-in Tullahoma TN 4.98 "Miss Maine", owned Chuck Cianchette, Newport ME;

N712JS at Beech flyin Tullahoma TN 16.10.98 tailwheel, Chuck Cianchette, Palmyra ME;

N712JS at Oshkosh 8.99 Chuck Cianchette "Miss Maine";

N712JS at Beech Flv-In Tullahoma TN 10.10.99 Chuck Cianchette ME:

(Chuck Cianchette killed 15.1.00 in crash of his Cessna 190 195 in KY)

N712JS at Beech flyin Tullahoma TN 16.10.02 owned Chuck Cianchette, Newport ME, name "Miss Maine" on nose;

N712JS noted Tullahoma TN 1.3.03 exec scheme, parked outside Staggerwing museum;

N712JS noted Tullahoma TN 16.10.03 at Staggerwing museum;

N712JS noted Tullahoma TN 14.10.07 at Beech fly-in, civil scheme "Miss Maine"; same 18.10.14;

BA-454	E18S	N436A	Armco Steel Corp, Topeka KS	.59/64
			Millie Carlisle, Jackson WY	66
			Gopher Aviation, Rochester Airport MN	69/70
	Hamilton		SMB Stage Line Inc, Des Moines IA	76/85
	Westwind III		(rebuilt .72 as Hamilton Westwind III)	
			op: North Continent Airlines, Long Beach CA	85/86
			SMB Stage Line, Dallas-Ft Worth TX	10.86
			sold to Philippines: struck-off USCR	18.9.89
		RP-C1126	Metro Manila Airways International, Manila	.89/92
			Territory Airlines, Goroka PNG t/a Metroair	.91/92
			retired Manila, stripped airframe sold	.92
			Charles R. Miller/ CM Air, Manila: parts use (rep. re-engined with P&W R-985s)	94/97
			(16p. 16-611gilled with 1 dw K-3005)	

N436A noted Tucson AZ 3.4.72 at Hamilton Aiervcraft ramp, Westwind III turbines;

N436A photo 12.75 as Westwind III;

N436A noted St Louis MO 2.6.76, Westwind III, "SMB Stage Line" titles;

N436A noted Pittsburg PA 18.3.78 Westwind III tailwheel, "SMB Stage Line" titles;

N436A noted Des Moines IA 26.8.80 Westwind III "SMB Stage Lines" titles;

N436A noted Tucson AZ 16.3.84, Hamilton Westwind, no engines;

N436A noted Phoenix AZ 7.2.85 North Continent (no titles);

N436A noted LAX 6.8.85 in freight service, turbines, North Continent (no titles);

N436A noted Dallas-Ft Worth TX 10.87, tailwheel Tradewind, "SMB Stage Lines",

RP-C1126 noted Manila 1.91 Westwind III tailwheel, long nose, "Metro Manila Airways International" titles;

Metro Manila Airways purchased by Territory Airlines PNG c91 to acquire charter licence and hangar facilities at Manila Domestic Airport, renamed Metroair: Talair Twin Otters replaced the 2 Westwinds; the 2 Hamilton Westwinds wewre included in purchase but not required. Paul Howard recalls closing down Metroair 2.92, the PT-6A-20 turbines & props from Westwinds were removed and sent to

Goroka PNG for resale and Beech 18 airframes offered for sale without turbines; sold in Manila presumeably for parts;

RP-C1126 noted Manila 2.1.94;

BA-455	E18S	N439A	Armco Steel Corp, Topeka KS & Houston TX: CofA	15.10.59/66
	-9700		SMB Stage Line Inc, Des Moines IA	69/81
			B & B Aircraft Service, Fort Lauderdale FL	9.81
		N50BP	B & B Aircraft Service, Fort Lauderdale FL	11.81/82
			D & D Airfreight Service, Fort Myers FL	11.86
			Wauchula Flying Service, Wauchula FL	8.88/91
			damaged when nosed over on landing, Wauchula FL	12.1.90
			exported, struck-off USCR	11.2.92
			Lee Cameron & Larry Stahl/ C & S Inc,	
			North Hollywood CA	96
		N95AP	C & S Inc, North Hollywood CA	5.97/98
	AT-11		(composite rebuild using fuselage & perspex nose of	
	nose		AT-11 N241X, ferried to Whiteman Air Park CA 3.6.97)	
	H18	-	C & S Inc, North Hollywood CA	5.98/04
	mods		(rebuild continued at Whiteman Air Park CA 98,	
			H18 raised cabin roof, windows & windshield,	
			mods to MAUW 10,100 lb, CofA 12.11.98)	
			Bogie Bros LLC, Oklahoma City OK	6.6.06/18
			ran off runway landing, struck fence, Guyon KS	1.6.08
			reg expired 30.4.18, struck-off USCR	13.9.18
			•	

further details on composite rebuild see Beech 18 by Robert Parmerter p.381;

N439A noted Topeka KS 4.6.76 "SMB Stage Line" titles;

N439A noted Toronto ONT 13.5.79 SMB Stage Line;

N241X noted Whiteman Air Park CA 15.8.00, rebuild by Lee Cameron of Aerospace Products almost complete, using nose section ex AT-11 N241X from Clearwater FL, and H18 forward fuselage from a H18 involved in a midair collision, E18S tail, rear fuse and wings, planned to fly 10.00, plate BA-455 built 6.5.56;

USCR00: quotes id. BA-455;

Advertised for sale in T-A-P 5.01: "Beech AT-11/E18/H18" only one in the world,10,100 gross, 318 gallons fuel, HS props, metal controls, relicensed, Hamilton strap, cabin configured baggage door LH, photo door inward opening R-side, new H18 windshield, magnetometer possibilities, \$660K: apply Aerospace Products;

N241X noted in hangar Whiteman Airpark 6.9.01 & 13.8.02;

Still being advertised in T-A-P regularly til 5.04: Aerospace Products;

	Sun benig	auveriiseu iii	1-A-P regularly til 5.04. Aerospace Products,	
BA-456	E18S	N311D	built Dow Chemical Co, Tulsa OK Miller Container Corp, Milan IL SMB Stage Line, Des Moines IA crashed destroyed after takeoff in fog, Dodge City KS	.59 63/64 66 69/75 3.3.75
			3.3.75: SMB Stage Line, mail flight Dodge City to Hays KS, 9.47pm, destroyed, pilot k;	
BA-457	E18S	N307B	Beech Aircraft Corp, Wichita KS: CofA issued Corey Custom Airtravel Inc, Detroit MI Midwestern Airlines, Detroit MI Southeastern Airways Corp, Double Springs AL Mohican Air Service Inc, Cleveland OH Northern Airmotive Corp, Kenosha WI, later Hillsboro OH KJL Aviation, Wilmington DE	14.1.59 63/66 67/70 71/72 79/91 26.5.93/00 29.11.00/20
		-	n Court House OH 6.8.99 op Northern Airmotive; shed metallic, tailwheel, in service;	
BA-458	E18S -9700	N40DC (2 N240DC N2405C	Daniel Construction Co, Greenville SC Daniel Construction Co, Greenville SC Belmont Charter Service, Detoit MI	.59/63 64/66 69/72

Van Dusen Acceptance Corp, Minneapolis MN

Frank C. Bonansinga, Ilopango, San Salvador

6.73

Hamilton		(Hamilton long cargo nose installed at Tucson AZ	
long nose		by Hamilton Aircraft 73)	
	YS-133P	Frank C. Bonansinga, Ilopango, San Salvador	.73/76
		(based Ilopango, San Salvador 72/76)	6.73/76
	N133PA	Frank C. Bonansinga, Desert Hot Springs CA	12.76
		Lee Morris, Galveston TX	77
		Skytram Aviation, Laredo TX	9.2.79/82
		struck-off USCR	18.9.82

N2405C noted Tucson AZ 24.5.73 at Hamilton Aircraft ramp;

Frank Bonansinga (ex Air America pilot), purchased E18S in 6.73, had Hamilton mods installed by Hamilton Aircraft in Tucson. Hamilton long cargo nose, spar strap, metal cabin liner, pilot hatch and cargo door: he says the long nose added 10 knots and made it more stable and easier to land with more aft CofG. Based it at ilopango, San Salvador on cargo & pax work.

Flew several medivacs non-stop to New Orleans & Miami, and one to Tampa then Boston with sick US Embassy person. Brought back full loads of used clothing from New Orleans and Brownsville TX which was sold in op stores in San Salvador. "I was a poor businessman but I loved flying it for the few years I was in Central America." Aircraft was painted pale green. He repainted it white when he brought it back to USA and sold it in 1977. He believes subsequently sold to Mexico;

BA-459	E18S	N440DC	Daniel Construction Co, Greenville SC	.59/66
	-9700	N449DC	Daniel Construction Co, Greenville SC	3.66
		N4490C	Belmont Air Charter Service, Detroit MI	15.11.68/72
			sold to Canada, struck-off USCR	1.2.72
		CF-QCG	Bale Comeau Air Service, Hauterive QUE	2.72
			Golfe Air Quebec Ltee, Hauterive QUE	74
			Air Caravane, Montreal-Dorval QUE	76/78
			Robert W. McCreadie, Winnipeg MAN	9.4.79/01
			(stored at CFB Trenton with unid. Beech 18 airframe 96)	
			struck-off Register	12.6.01
			(complete airframe offered for sale 2017)	

CF-QCG noted Montreal 21.10.73 reported as Golfair; CF-QCG noted CFB Trenton 6.96 with an unid Beech 18 hulk;

BA-460	E18S	N90D	Youngstown Airways/ Lease Air, Youngstown OH	.59/64
	-9700		Beckett Aviation Corp, Youngstown OH	66
		N9001	SMB Stage Line, Des Moines IA	69/78
			Southern National Leasing Corp, Charlotte NC	79
			op: General Aviation Inc, Greenville TN	80
			Equipment Leasing Corp, Greenville SC	7.81/84
			lsd: Mountain Air Cargo, Denver NC	81/84
			Coastal States Aviation, Denver NC	3.85
			Pelican transport Inc, Lake Worth FL	4.86
			Aubrey Aviation, Ocala FL	6.87
			Guy Pere, Fairbanks AK	5.90/91
			Methow Aviation, Everett WA	19.2.92/98
			Comanche Air, Winthrop WA	28.9.98/06
			op: Methow Aviation, Everett-Paine Field WA	00/05
			Aero Equipment LLC, Kenai AK	14.7.07/11
			op: Air Supply Alaska, Kenai AK	09/11
			crashed destroyed, New Stuyahok AK	3.1.11

N9001 noted Miami FL 22.3.87 op by Air Cargo America;

N9001 noted Miami FL 3.11.87;

N9001 noted West Palm Beach Executive FL 2.90, exec scheme, extended nose;

N9001 noted Seattle-Boeing Field 6.6.01;

N9001 noted Ephrata WA 4.8.02 "Methow" titles, tailwheel, in service;

N9001 noted Moses Lake WA 18.10.02 "Methow";

N9001 noted Ephrata WA 11.02 yellow & black;

N9001 noted Ephrata WA 5.4.03 "Methow" yellow scheme, tailwheel in service; N9001 noted Ephrata WA 8.5.05 "Methow" titles, "Bumble Beech" name, tailwheel, in service;

N9001 noted Kenai AK 6.08, 8.09 "Air Supply Alaska" titles, yellow & black, in service;

BA-461	G18S	N766A	built	.59
			National Financing Inc. Wilmington DF	63/64

# N511W (1 rereg

BA-462				
BA-462	G18S	N9590R	built	.59
			C & C Contractors Inc, Albuquerque NM	63
			Huston Peanut Co, Columbus GA	64
			Jack Adams Aircraft Sales, Walls MS	66
			SMB Stage Line Inc, Des Moines IA	69/72
			Perkiomen Airways Ltd, Reading PA trading as	
			Sun International Airways, San Juan, Puerto Rico	9.76/97
			op: Air Pensylvania	80
			op: Sun International Airways, San Juan, Puerto Rico	80
			Christopher E. Poindexter, Lone Wolf OK	6.97/11
			struck-off USCR	4.1.11
	N9590R not	ted Topeka I	KS 2.10.71;	
	N9590R rep	o. retired der	elict, San Juan PR 78;	
D.A. 400	0.100	110.400	1. 10	
BA-463	G18S	N243B	built	.59
			Graubart Aviation, Valparaiso IN	63
			Executive Flight Services Inc, Portland OR	64/69
			Bullhead Air Transport Corp, Bullhead City AZ	70/72
	Volpar		(rebuilt by Volpar .73 as <i>Turboliner II</i> for Winship)	
	Turboliner II	I N600WA	Winship Air Service, Anchorage AK	2.11.73/76
			crashed dest. landing, Dutch Harbour AK	22.7.76
BA-464	G18S	N9604R	Beech Aircraft Corp, Wichita KS: CofA issued	21.10.59
			Buckeye Union Casualty Co, Columbus OH	63/72
			Hill Brothers Aviation, Pekin IL	79
			McNeely Air Charter Service, Earle AR	4.85/86
			Jim Ratiff Air Service, Columbus MS	9.89
				12.9.89
			gear collapsed landing, Jackson MS	
			Doak Boreing, Magnolia AR	11.90/91
			Robert A. Youkin, Springdale AR	1.93
			Robert W. Sagers, Fallbrook CA, later Toledo WA,	
			later Kearneysville WV	23.2.93/06
			Howard M. Bohl, Temecula CA	21.12.10/20
	N9604R note N960R note N9604R at I N9604R at I	ted Chino CA ed Madera C Beech fly-In fly-in Lakelai Beech fly-in	Jim Ratiff Air Service, gear collapsed on landing; A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; nd FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;	0.59;
	N9604R note N960R note N9604R at 1 N9604R at 1 N9604R at 1	ted Chino Ca ed Madera C Beech fly-In fly-in Lakelar Beech fly-in Beech fly-in	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; nd FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;	
BA-465	N9604R note N960R note N9604R at I N9604R at I	ted Chino CA ed Madera C Beech fly-In fly-in Lakelai Beech fly-in	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; nd FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03; built	.59
BA-465	N9604R note N960R note N9604R at 1 N9604R at 1 N9604R at 1	ted Chino Ca ed Madera C Beech fly-In fly-in Lakelai Beech fly-in Beech fly-in N123L	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; and FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;  built Holley Carburettor Co, Warren MI	.59 63/64
BA-465	N9604R note N960R note N9604R at 1 N9604R at 1 N9604R at 1	ted Chino Ca ed Madera C Beech fly-In fly-in Lakelar Beech fly-in Beech fly-in	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; and FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;  built Holley Carburettor Co, Warren MI W. R. Boles, Monroe LA	.59 63/64 66
BA-465	N9604R note N960R note N9604R at 1 N9604R at 1 N9604R at 1	ted Chino Ca ed Madera C Beech fly-In fly-in Lakelai Beech fly-in Beech fly-in N123L	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; and FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;  built Holley Carburettor Co, Warren MI W. R. Boles, Monroe LA Herlin Inc, Shreveport LA	.59 63/64 66 69/70
BA-465	N9604R note N960R note N9604R at 1 N9604R at 1 N9604R at 1	ted Chino Ca ed Madera C Beech fly-In fly-in Lakelai Beech fly-in Beech fly-in N123L	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; and FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;  built Holley Carburettor Co, Warren MI W. R. Boles, Monroe LA	.59 63/64 66
BA-465	N9604R note N960R note N9604R at 1 N9604R at 1 N9604R at 1	ted Chino Ca ed Madera C Beech fly-In fly-in Lakelai Beech fly-in Beech fly-in N123L	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; and FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;  built Holley Carburettor Co, Warren MI W. R. Boles, Monroe LA Herlin Inc, Shreveport LA Ross Aviation, Tulsa-Riverside OK	.59 63/64 66 69/70
BA-465	N9604R note N960R note N9604R at 1 N9604R at 1 N9604R at 1	ted Chino Ca ed Madera C Beech fly-In fly-in Lakelai Beech fly-in Beech fly-in N123L	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; and FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;  built Holley Carburettor Co, Warren MI W. R. Boles, Monroe LA Herlin Inc, Shreveport LA Ross Aviation, Tulsa-Riverside OK op: Great Western Airlines, Tulsa OK	.59 63/64 66 69/70 16.11.70/74
BA-465	N9604R note N960R note N9604R at 1 N9604R at 1 N9604R at 1	ted Chino Ca ed Madera C Beech fly-In fly-in Lakelai Beech fly-in Beech fly-in N123L	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; and FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;  built Holley Carburettor Co, Warren MI W. R. Boles, Monroe LA Herlin Inc, Shreveport LA Ross Aviation, Tulsa-Riverside OK op: Great Western Airlines, Tulsa OK crashed destroyed by fire, forced landing off airport	.59 63/64 66 69/70 16.11.70/74 70/74
BA-465	N9604R note N960R note N9604R at 1 N9604R at 1 N9604R at 1	ted Chino Ca ed Madera C Beech fly-In fly-in Lakelai Beech fly-in Beech fly-in N123L	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; and FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;  built Holley Carburettor Co, Warren MI W. R. Boles, Monroe LA Herlin Inc, Shreveport LA Ross Aviation, Tulsa-Riverside OK op: Great Western Airlines, Tulsa OK	.59 63/64 66 69/70 16.11.70/74
BA-465	N9604R note N960R note N9604R at I N9604R at I N9604R at I	ted Chino Ca ed Madera C Beech fly-In fly-in Lakelai Beech fly-in N123L N123A	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; and FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;  built Holley Carburettor Co, Warren MI W. R. Boles, Monroe LA Herlin Inc, Shreveport LA Ross Aviation, Tulsa-Riverside OK op: Great Western Airlines, Tulsa OK crashed destroyed by fire, forced landing off airport	.59 63/64 66 69/70 16.11.70/74 70/74
	N9604R note N960R note N9604R at I N9604R at I N9604R at I	ted Chino Ca ed Madera C Beech fly-In fly-in Lakelai Beech fly-in N123L N123A	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; and FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;  built Holley Carburettor Co, Warren MI W. R. Boles, Monroe LA Herlin Inc, Shreveport LA Ross Aviation, Tulsa-Riverside OK op: Great Western Airlines, Tulsa OK crashed destroyed by fire, forced landing off airport at night, Fort Scott KS  Great Western: flight Tulsa to Kansas City MO, engine sho	.59 63/64 66 69/70 16.11.70/74 70/74
	N9604R note N960R note N9604R at I N9604R at I N9604R at I N9604R at I	ted Chino Ca ed Madera C Beech fly-In fly-in Lakelai Beech fly-in N123L N123A dent report:	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; and FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;  built Holley Carburettor Co, Warren MI W. R. Boles, Monroe LA Herlin Inc, Shreveport LA Ross Aviation, Tulsa-Riverside OK op: Great Western Airlines, Tulsa OK crashed destroyed by fire, forced landing off airport at night, Fort Scott KS  Great Western: flight Tulsa to Kansas City MO, engine shiss, struck trees, 2.20am, pilot serious injuries; built	.59 63/64 66 69/70 16.11.70/74 70/74 1.3.74
	N9604R note N960R note N9604R at I N9604R at I N9604R at I N9604R at I	ted Chino Ca ed Madera C Beech fly-In fly-in Lakelai Beech fly-in N123L N123A dent report:	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; and FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;  built Holley Carburettor Co, Warren MI W. R. Boles, Monroe LA Herlin Inc, Shreveport LA Ross Aviation, Tulsa-Riverside OK op: Great Western Airlines, Tulsa OK crashed destroyed by fire, forced landing off airport at night, Fort Scott KS  Great Western: flight Tulsa to Kansas City MO, engine shiss, struck trees, 2.20am, pilot serious injuries;  built Southern Airways of Florida Inc, Orlando FL	.59 63/64 66 69/70 16.11.70/74 70/74 1.3.74 ut
	N9604R note N960R note N9604R at I N9604R at I N9604R at I N9604R at I	ted Chino Carlo Madera C Beech fly-In fly-in Lakelai Beech fly-in N123L N123A dent report: uel, power lo	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; and FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;  built Holley Carburettor Co, Warren MI W. R. Boles, Monroe LA Herlin Inc, Shreveport LA Ross Aviation, Tulsa-Riverside OK op: Great Western Airlines, Tulsa OK crashed destroyed by fire, forced landing off airport at night, Fort Scott KS  Great Western: flight Tulsa to Kansas City MO, engine shiss, struck trees, 2.20am, pilot serious injuries;  built Southern Airways of Florida Inc, Orlando FL Business Mens Assurance Co, Kansas City MO	.59 63/64 66 69/70 16.11.70/74 70/74 1.3.74 ut
	N9604R note N960R note N9604R at I N9604R at I N9604R at I N9604R at I	ted Chino Ca ed Madera C Beech fly-In fly-in Lakelai Beech fly-in N123L N123A dent report:	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; and FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;  built Holley Carburettor Co, Warren MI W. R. Boles, Monroe LA Herlin Inc, Shreveport LA Ross Aviation, Tulsa-Riverside OK op: Great Western Airlines, Tulsa OK crashed destroyed by fire, forced landing off airport at night, Fort Scott KS  Great Western: flight Tulsa to Kansas City MO, engine shiss, struck trees, 2.20am, pilot serious injuries;  built Southern Airways of Florida Inc, Orlando FL Business Mens Assurance Co, Kansas City MO Pegasus Transport Inc, Cincinatti OH	.59 63/64 66 69/70 16.11.70/74 70/74 1.3.74 ut
	N9604R note N960R note N9604R at I N9604R at I N9604R at I N9604R at I	ted Chino Carlo Madera C Beech fly-In fly-in Lakelai Beech fly-in N123L N123A dent report: uel, power lo	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; and FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;  built Holley Carburettor Co, Warren MI W. R. Boles, Monroe LA Herlin Inc, Shreveport LA Ross Aviation, Tulsa-Riverside OK op: Great Western Airlines, Tulsa OK crashed destroyed by fire, forced landing off airport at night, Fort Scott KS  Great Western: flight Tulsa to Kansas City MO, engine shiss, struck trees, 2.20am, pilot serious injuries;  built Southern Airways of Florida Inc, Orlando FL Business Mens Assurance Co, Kansas City MO Pegasus Transport Inc, Cincinatti OH Thomas E. Nentwick, Leetonia OH	.59 63/64 66 69/70 16.11.70/74 70/74 1.3.74 ut
	N9604R note N960R note N9604R at I N9604R at I N9604R at I N9604R at I	ted Chino Carlo Madera C Beech fly-In fly-in Lakelai Beech fly-in N123L N123A dent report: uel, power lo	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; and FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;  built Holley Carburettor Co, Warren MI W. R. Boles, Monroe LA Herlin Inc, Shreveport LA Ross Aviation, Tulsa-Riverside OK op: Great Western Airlines, Tulsa OK crashed destroyed by fire, forced landing off airport at night, Fort Scott KS  Great Western: flight Tulsa to Kansas City MO, engine shiss, struck trees, 2.20am, pilot serious injuries;  built Southern Airways of Florida Inc, Orlando FL Business Mens Assurance Co, Kansas City MO Pegasus Transport Inc, Cincinatti OH Thomas E. Nentwick, Leetonia OH Semo Aviation/ Semo Airways, Malden MO	.59 63/64 66 69/70 16.11.70/74 70/74 1.3.74 ut 11.59 63/64 66 69/70 71/72 76/84
	N9604R note N960R note N9604R at I N9604R at I N9604R at I N9604R at I	ted Chino Carlo Madera C Beech fly-In fly-in Lakelai Beech fly-in N123L N123A dent report: uel, power lo	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; and FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;  built Holley Carburettor Co, Warren MI W. R. Boles, Monroe LA Herlin Inc, Shreveport LA Ross Aviation, Tulsa-Riverside OK op: Great Western Airlines, Tulsa OK crashed destroyed by fire, forced landing off airport at night, Fort Scott KS  Great Western: flight Tulsa to Kansas City MO, engine shiss, struck trees, 2.20am, pilot serious injuries;  built Southern Airways of Florida Inc, Orlando FL Business Mens Assurance Co, Kansas City MO Pegasus Transport Inc, Cincinatti OH Thomas E. Nentwick, Leetonia OH Semo Aviation/ Semo Airways, Malden MO Northwest Air Cargo Inc, Springdale AR	.59 63/64 66 69/70 16.11.70/74 70/74 1.3.74 ut 11.59 63/64 66 69/70 71/72 76/84 4.84
BA-465	N9604R note N960R note N9604R at I N9604R at I N9604R at I N9604R at I	ted Chino Carlo Madera C Beech fly-In fly-in Lakelai Beech fly-in N123L N123A dent report: uel, power lo	A 12.93, hangared good condition; A 10.96 "Wayward Wind" in service: plate BA-464 built 10 Tullahoma TN 10.10.99 Bob Sager; and FL 10.4.01; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03;  built Holley Carburettor Co, Warren MI W. R. Boles, Monroe LA Herlin Inc, Shreveport LA Ross Aviation, Tulsa-Riverside OK op: Great Western Airlines, Tulsa OK crashed destroyed by fire, forced landing off airport at night, Fort Scott KS  Great Western: flight Tulsa to Kansas City MO, engine shiss, struck trees, 2.20am, pilot serious injuries;  built Southern Airways of Florida Inc, Orlando FL Business Mens Assurance Co, Kansas City MO Pegasus Transport Inc, Cincinatti OH Thomas E. Nentwick, Leetonia OH Semo Aviation/ Semo Airways, Malden MO	.59 63/64 66 69/70 16.11.70/74 70/74 1.3.74 ut 11.59 63/64 66 69/70 71/72 76/84

	Jim Hankins Air Service, Jackson MS	3.93
	sold to Canada: struck-off USCR	7.93
C-GJKA	Central Pacific Outfitters Ltd/ Bottenfields Winisk Air,	
	Pickle Lake ONT	10.1.94/96
	Land-Sea-Air Transport Ltd, Cochenour ONT	29.1.96/97
	Gold Belt Air Transport, Pickle Lake ONT	5.6.97/99
	Parachtisme Nouvel Air, Farnham QUE	16.5.00/06
N45CF	Aircraft Guaranty Corp, Houston TX: trustee: USCR	27.5.08/20
	Carlo Ferrari, Grenchen, Switzerland	.08/20
	(flew 19 as olive drab USAAF "436784")	

N788MW noted St Louis MO 15.9.76 Semo AW;

C-GJKA noted St Mathias QUE 10.8.00 op Parachutisme Nouvel Air, tailwheel;

C-GJKA noted St Mathias QUE 20.3.05, Parachutisme Nouvel Air, parachute ops;

C-GJKA noted Farnham QUE 11.9.05, tailwheel in service;

C-GJKA noted Rockcliffe ONT 26.8.06 for Classic Air Rallye, tailwheel in service;

N45CF at fly-in Tannheim, Gernany 28.8.10 all metallic, owned Carlo Ferrari;

N45CF noted Hahnweide, Germany 3.9.11 bare metal;

N45CF visited Fairford UK 14.7.14, Mulhouse-Habsheim 27.6.15 polished metal;

N45CF visited Fairford UK 17.7.17 polished metal;

BA-467	G18S	N5555X	Beech Aircraft Corp, Wichita KS: CofA issued	5.11.59
			Clifford M. Farmer, Atherton CA	63/64
			T. R. Carpenter/ / Empire State Airlines/ Flight Service Inc,	
			Syracuse-Hancock Field NY	66/73
			Joseph S. Sneden/ Pro-Pilots Inc, Syracuse NY	.73/79
			Stockert Flying Service, South Bend IN	79/81
			P B Leasing Co, West Chicago IL	2.3.81
		N100VE	P B Leasing Co, West Chicago IL	7.81/86
			lsd: Viking Express, Chicago-Midway IL	.81/86
			damaged ran off runway landing, struck snow bank,	
			Minneapolis MN	28.12.85
			crashed into houses, destroyed Chicago IL	28.9.86
			(stored dismantled, fire damaged, in salvage yard, Owasso OK 00)	

Joseph S. Sneden Jr was Chief Pilot for Empire State Airlines, and after scheduled Services were discontinued, continued with associate company Flight Service Inc. He purchased N5555X in 1973 when Flight Service's owner moved to Florida. Sneden's own company Pro-Pilots Inc flew it on charter and night freight; for passenger charters the dark brown all-leather interior was re-installed;

During 1973-78 Snedden/Pro-Pilots Inc provided pilots and maintenance for BA-141 for Utica Mutual Insurance Co;

N5555X noted Syracuse NY 27.8.74;

accident reports 28.12.85 & 28.9.86: both op. Viking Express;

N100VE fuselage noted in SW Aero Exchange yard, Owasso OK 10.8.00, plate BA-467;

BA-468	G18S	N697Q	Beech Aircraft Corp, Wichita KS: CofA issued	6.11.59
			Ruan Inc, Des Moines IA	63/66
			SMB Stage Line Inc, Des Moines IA Betty IV	69/79
			gear collapsed during landing, Tulsa OK	5.5.69
			Ajax Aircraft Leasing, Dover DE	1.83
			ACE Air Cargo Express Inc, Cleveland OH	8.84/86
			Robert A. Younkin, Lowell AR	6.87
			Younkin Air Service, Springdale AR	6.88
			Tamboo Trading Co, Palm Beach FL	7.88/97
			Missionary Flights & Services Inc, West Palm Beach FL	2.97
			Hartford Holing Corp, Wilmington DE	21.8.97/99
			Carib-Air Cargo Inc, Lantana FL	7.12.99/01
			struck while parked at Key West FL by DC-3 N79MA	
			which suffered brake failure while taxying after landing	21.8.00
			Randell Stevenson, Wildwood MO	02/06
			Barron Aviation, Perry MO	26.8.10/12
			rolled inverted at 11,000 feet, crashed in residential stree	et,
			dest., Taylorville IL (12 parachutists jumped, pilot k)	11.8.12

N697Q noted Chicago-O'Hare 16.4.69 "SMB Stage Lines";

N697Q accident report 5.5.69: SMB Stage Line, gear collapsed due mechanical failure;

N697Q noted Chicago-O'Hare 23.9.70 "SMB Stage Lines";

N697Q noted Pontiac MI 9.80 plate BA-468;

N697Q noted West Palm Beach FL 10.5.92;

N697Q photo Ft Lauderdale FL early 00: tailwheel, "Carib Air Cargo" titles;

N697Q noted Lantana-West Palm Beach County FL 5.4.01;
N697Q noted St Louis MO 18 8 03 all metaalic freighter, plate R4-468 built 11 50

	N697Q no	oted St Louis I	MO 18.8.03 all metaalic freighter, plate BA-468 built 11.59;	
BA-469	G18S	N9615R N565BA	Beech Aircraft Corp, Wichita KS: CofA issued Hawthorne Metal Products Co, Royal Oak MI	6.11.59 63/64
		NEGELIO	William F. Lomasney, Harper Woods AL	66
		N565US	US Equipment Corp, Detroit MI	69/79
			Juan Rodriguez, Clinton MO	9.84
			Five of Us Inc, Clinton MD	7.89/91
			Robert E. Haydon, Hartwood VA	8.92
			Gerald A. Stevens, Boca Raton FL	12.94/96
			Avlite Aviation, Paso Robles CA	9.96
			Thomas Leatherwood, Paso Robles CA	.96
			John G. Wood, Winter Haven FL	9.7.98/99
			Rasmus Nielson, Des Moines WA, later Seattle WA (departed Tacoma WA 27.5.07 on flight to Denmark by Ras Nielson, via Reykjavík 6.6.07,	14.4.00/14
			arrived back at Tacoma-Narrows WA 23.6.07)	27 6 14/10
			William R. Nolte, Murray NE	27.6.14/18
		N10C	Dynamic Avlease Inc, Bridgewater VA	20.8.19
		N18G	Dynamic Avlease Inc, Bridgewater VA	16.3.20
	N565US a N565US a N565US a departed planned to N565US a	at Beech fly-in at Beech fly-in at fly-in Arlingt Tacoma-Narro o attend airsho at Beech fly-in	on WA 13.7.02, tailwheel, excellent condition; Tullahoma TN 16.10.02; Tullahoma TN 16.10.03; Ion WA 7.02, 7.7.05 & 7.7.06 civil scheme, tailwheel; Iows Airport 27.5.07 on flight to Denmark, pilot Ras Nielson, Iows in Denmark; Tullahoma TN 14.10.07; Oshkosh 7.08; Ish 7.17 brown & white;	,
BA-470	G18S	N118W	built	.59
			Midwest Oil Co, Fort Worth TX	63/64
			Bryant Chucking Grinder Co, Springfield VT	66/70
			Carson Helicopters Inc, Perkasie PA	25.2.72/73
			crashed destroyed by fire after takeoff in snow,	
			Ann Arbor MI	29.12.73
			flight Ann Arbor to Allentown PA return, encrusted snow of 5 minor injuries;	on
BA-471	G18S	N9621R	Ohio Aviation Co, Dayton OH: dealer	.59
_,, ,, ,	0.00	11002111	M & R Dietetic Laboratories Inc, Columbus OH	.59/64
			tfd: Ross Laboratories, Columbus OH	.64/66
	trigear		(modified to Volpar trigear)	.0 1/00
	ingeai		Jack Adams Aircraft Sales, Walls MS	69
			D-W Corp, Des Moines IA	70/79
			D-W Corp, Des Montes IA	10/19

Frank Cannavo, Lester PA

Aero Taxi Inc, New Castle DE

Cannavo Inc, New Castle DE

Aero Taxi Inc, New Castle DE

Randys Olde Towne Service Inc, Traverse City MI

4.84

3.2.95

12.88/99

3.2.95/99

4.10.00/22

BA-472	G18S	N92D	Lease Air Inc, Youngstown OH: CofA issued Harbison Walker Refractories Co, Pittsburgh PA	14.11.59 63
			Beckett Aviation, Youngstown OH	63
			Lease Air Inc, Youngstown OH	64/66
		N9210	SMB Stage Line Inc, Des Moines IA	69/72
			Blackhawk Airways, Janesville WI	79
			Methow Aviation Inc, Wenatchee WA	7.2.83/95
			lsd: Airpac Airlines, Seattle WA	84
			Comanche Air, Winthrop WA	28.9.98/06
			op: Methow Aviation, Everett-Paine Field WA	00/04
			Aero Equipment LLC, Kenai AK	3.9.08/13
			Michael W. Renfro, Bethel AK reg expired 30.9.19, struck-off USCR	30.9.13/19 6.1.20
			OH 63 op Beckett Aviation, tailwheel; 24.5.90 "Methow" titles;	
			ene ID 17.10.91 "Methow" in service;	
			e WA 8.95 "Methow";	
	N9210 note	d Ephrata WA	A 16.9.04 "Methow", tailwheel, in service;	
BA-473	G18S	N561B	built	.59
			Rex Rutter Manufacturing Co, New Orleans LA	63/72
		(0.00)400	Richard Theriault, Rumford ME	78
		(C-GQWX)	ntu: Toronto Piper Sales & Service, Toronto Airport ONT (inspection at Toronto-Malton 1.79)	6.11.78
		C-GOPI	Robert M. West, Grand Bend ONT: reg. and CofA	12.3.79/81
			Burke Lighting (Western) Ltd, Winnipeg MAN	8.81
			The Air Ranger Ltd, Winnipeg Airport MAN	25.8.81
			North Cariboo Flying Service, Fort St John BC	8.9.81/82
		N32809	Rick Lytjes/ Air America Inc, Avoca PA	25.8.82
			Michael Malone, Fort Pierce FL	9.83
			Indian River Helicopter Service, Fort Pierce FL	3.84
			Florida Airmotive Inc, Lantana-Palm Beach FL	9.84
			Piper East Inc, Concord NH	10.84
			op: Wiggins Airways, Manchester NH	84
			crashed dest. after takeoff, Laconia NH	1.11.84
		-1-14 4	1.11.84: Wiggins Airways;	
	N32809 acc	ciaent report 1	1.11.04. Wiggins Allways,	
BA-474	N32809 acc	N377H	International Telephone & Telegraph Corp (IT&T),	50/00
BA-474			International Telephone & Telegraph Corp (IT&T), New York NY	.59/60
BA-474			International Telephone & Telegraph Corp (IT&T), New York NY Hamilton Management Corp, Denver CO	.59/60 63/66
BA-474			International Telephone & Telegraph Corp (IT&T), New York NY Hamilton Management Corp, Denver CO International Telephone & Telegraph Corp (IT&T),	63/66
BA-474	G18S		International Telephone & Telegraph Corp (IT&T), New York NY Hamilton Management Corp, Denver CO International Telephone & Telegraph Corp (IT&T), New York NY	63/66 69/79
BA-474	G18S Hamilton		International Telephone & Telegraph Corp (IT&T), New York NY Hamilton Management Corp, Denver CO International Telephone & Telegraph Corp (IT&T), New York NY Africa Inland Mission International, Pearl River NY	63/66
BA-474	G18S  Hamilton Extended	N377H	International Telephone & Telegraph Corp (IT&T), New York NY Hamilton Management Corp, Denver CO International Telephone & Telegraph Corp (IT&T), New York NY Africa Inland Mission International, Pearl River NY (delivered from US to Africa via Azors 5.88)	63/66 69/79
BA-474	G18S Hamilton		International Telephone & Telegraph Corp (IT&T), New York NY Hamilton Management Corp, Denver CO International Telephone & Telegraph Corp (IT&T), New York NY Africa Inland Mission International, Pearl River NY (delivered from US to Africa via Azors 5.88) Africa Inland Mission International/ AIM Air,	63/66 69/79 .88
BA-474	G18S  Hamilton Extended	N377H	International Telephone & Telegraph Corp (IT&T), New York NY Hamilton Management Corp, Denver CO International Telephone & Telegraph Corp (IT&T), New York NY Africa Inland Mission International, Pearl River NY (delivered from US to Africa via Azors 5.88) Africa Inland Mission International/ AIM Air, Pearl River NY & Nairobi, Kenya	63/66 69/79
BA-474	G18S  Hamilton Extended	N377H N344EA	International Telephone & Telegraph Corp (IT&T), New York NY Hamilton Management Corp, Denver CO International Telephone & Telegraph Corp (IT&T), New York NY Africa Inland Mission International, Pearl River NY (delivered from US to Africa via Azors 5.88) Africa Inland Mission International/ AIM Air, Pearl River NY & Nairobi, Kenya (delivered from Nairobi-Wilson to Lanseria 12.97)	63/66 69/79 .88 18.7.88/97
BA-474	G18S  Hamilton Extended	N377H	International Telephone & Telegraph Corp (IT&T), New York NY Hamilton Management Corp, Denver CO International Telephone & Telegraph Corp (IT&T), New York NY Africa Inland Mission International, Pearl River NY (delivered from US to Africa via Azors 5.88) Africa Inland Mission International/ AIM Air, Pearl River NY & Nairobi, Kenya (delivered from Nairobi-Wilson to Lanseria 12.97) Luis Rebelo/ Mid-Dav Pty Ltd, Lanseria	63/66 69/79 .88
BA-474	G18S  Hamilton Extended	N377H N344EA	International Telephone & Telegraph Corp (IT&T), New York NY Hamilton Management Corp, Denver CO International Telephone & Telegraph Corp (IT&T), New York NY Africa Inland Mission International, Pearl River NY (delivered from US to Africa via Azors 5.88) Africa Inland Mission International/ AIM Air, Pearl River NY & Nairobi, Kenya (delivered from Nairobi-Wilson to Lanseria 12.97) Luis Rebelo/ Mid-Dav Pty Ltd, Lanseria Saxon Wings	63/66 69/79 .88 18.7.88/97 19.12.97
BA-474	G18S  Hamilton Extended	N377H N344EA	International Telephone & Telegraph Corp (IT&T), New York NY Hamilton Management Corp, Denver CO International Telephone & Telegraph Corp (IT&T), New York NY Africa Inland Mission International, Pearl River NY (delivered from US to Africa via Azors 5.88) Africa Inland Mission International/ AIM Air, Pearl River NY & Nairobi, Kenya (delivered from Nairobi-Wilson to Lanseria 12.97) Luis Rebelo/ Mid-Dav Pty Ltd, Lanseria	63/66 69/79 .88 18.7.88/97

N344EA noted Nairobi-Wilson 23.1.91AIM-Air;

N344EA del. Wilson-Lanseria 12.97 Hamilton long nose;

ZS-OEP noted Lanseria 10.2.98, 12.4.99;

ZS-OEP noted Lanseria 9.5.03 stored without engines, damage to belly; ZS-OEP noted Lanseria 5.10.03 stored engineless, Hamilton long nose, tailwheel;

ZS-OEP noted Lanseria 18.4.04 stored in Foster Aero hangar;

Further details African ops: see Beech 18 by Robert Parmerter p.299;

ZS-OEP noted Johannesburg-Rand 21.11.05;

ZS-OEP noted Rand 9.5.06 damaged dismantled in SFS hangar, was previously stored Lanseria; ZS-OEP noted Rand 10.06;

	G18S	N316MU	Mutual Benefit Health & Accident, Omaha NE	.59/64
BA-475	0100	N316Q	rereg	.59/04
		N319A	Duncan Corp, Tarkio MO	66
			SMB Stage Line Inc, Des Moines IA	69/79
			Castle Air, Los Angeles CA	11.81/82
			sale reported, Los Angeles CA	29.7.83/91
BA-476	G18S	N648B	Beech Aircraft Corp, Wichita KS: CofA issued	24.11.59
			Chicago Steel Service Co, Chicago IL	63/64
		N151E	Peter Eckrich & Sons Inc, Fort Wayne IN	66
		N15111	Executive Aircraft Corp, Indianapolis IN	69
			Johnson Flying Service, Indianapolis IN	70/72
		N151H	rereg	12.77
			D. Graves, Brownsburg IN	79
			Indianapolis Air Charter Services, Indianapolis IN	82/86
			Indianaero Inc, Bloomington IN	4.89/91
			Crouch Ag Aviation, Cameron MO	12.94/95
			Ryan Air Service, Anchorage AK	6.4.95
			Arctic Transportation Service, Anchorage AK	9.5.95/99
			damaged in accident, Kotzebue AK	12.9.96
			James M. Johnston, Nome AK	29.11.99/06
		N985S	Thomas Johnston, Wasilla AK	21.10.09/20
			urg IN 29.5.76 enlarged windows; wn OH 17.6.82 Indianapolis Air Charter Services;	
BA-477	G18S	YV-P-EPK	(2 built	2.60
		YV-T-WTV	V	
		YV-717P		78
		YV-316C		
		YV-668P		83
		1 4-0001		00
		YV-122CP	Aeroejecutivos C.A., Miranda	.83
	YV-717P	YV-122CP	Aeroejecutivos C.A., Miranda cka FL 3.10.78, tailwheel;	
BA-478	YV-717P	YV-122CP		
BA-478		YV-122CP noted Opa Lo	cka FL 3.10.78, tailwheel;	.83
BA-478		YV-122CP noted Opa Lo	cka FL 3.10.78, tailwheel;	.59
BA-478		YV-122CP noted Opa Lo	built Pilot Freight Carriers Inc, Winston Salem NC	.83 .59 63/72
BA-478	G18S	YV-122CP noted Opa Loc N180P	built Pilot Freight Carriers Inc, Winston Salem NC Wyman Pilot Service, Pontiac MI crashed destroyed on takeoff, Rockingham NC	.59 63/72 2.78
BA-478	G18S N180P no N180P ac	YV-122CP noted Opa Loc N180P  sted San Francicident report 2	built Pilot Freight Carriers Inc, Winston Salem NC Wyman Pilot Service, Pontiac MI crashed destroyed on takeoff, Rockingham NC  bisco CA 10.69, tailwheel, "Pilot Freight Carriers" titles; 2.3.78: Wyman Pilot Service, cargo flight Rockingham to F	.59 63/72 2.78 2.3.78
	G18S N180P no N180P ac airframe,	YV-122CP noted Opa Loc N180P sted San Franc cident report 2 snow on runw	built Pilot Freight Carriers Inc, Winston Salem NC Wyman Pilot Service, Pontiac MI crashed destroyed on takeoff, Rockingham NC cisco CA 10.69, tailwheel, "Pilot Freight Carriers" titles; 2.3.78: Wyman Pilot Service, cargo flight Rockingham to Fay, hit wires after takeoff 8.20pm, pilot hurt;	.59 63/72 2.78 2.3.78 Pontiac MI, snow on
	G18S N180P no N180P ac	YV-122CP noted Opa Loc N180P  sted San Francicident report 2	built Pilot Freight Carriers Inc, Winston Salem NC Wyman Pilot Service, Pontiac MI crashed destroyed on takeoff, Rockingham NC cisco CA 10.69, tailwheel, "Pilot Freight Carriers" titles; 2.3.78: Wyman Pilot Service, cargo flight Rockingham to Fay, hit wires after takeoff 8.20pm, pilot hurt; built	.59 63/72 2.78 2.3.78 Pontiac MI, snow or
	G18S N180P no N180P ac airframe,	YV-122CP noted Opa Loc N180P sted San Franc cident report 2 snow on runw	built Pilot Freight Carriers Inc, Winston Salem NC Wyman Pilot Service, Pontiac MI crashed destroyed on takeoff, Rockingham NC  cisco CA 10.69, tailwheel, "Pilot Freight Carriers" titles; 2.3.78: Wyman Pilot Service, cargo flight Rockingham to Fay, hit wires after takeoff 8.20pm, pilot hurt;  built Rent Car Inc, Boise ID	.59 63/72 2.78 2.3.78 Pontiac MI, snow or .59 63/64
	G18S N180P no N180P ac airframe,	YV-122CP noted Opa Loc N180P sted San Franc cident report 2 snow on runw	built Pilot Freight Carriers Inc, Winston Salem NC Wyman Pilot Service, Pontiac MI crashed destroyed on takeoff, Rockingham NC  cisco CA 10.69, tailwheel, "Pilot Freight Carriers" titles; 2.3.78: Wyman Pilot Service, cargo flight Rockingham to Fay, hit wires after takeoff 8.20pm, pilot hurt;  built Rent Car Inc, Boise ID Southeastern Beechcraft Inc, Knoxville TN	.59 63/72 2.78 2.3.78 Pontiac MI, snow or .59 63/64 66/69
	G18S N180P no N180P ac airframe,	YV-122CP noted Opa Loc N180P sted San Franc cident report 2 snow on runw	built Pilot Freight Carriers Inc, Winston Salem NC Wyman Pilot Service, Pontiac MI crashed destroyed on takeoff, Rockingham NC  cisco CA 10.69, tailwheel, "Pilot Freight Carriers" titles; 2.3.78: Wyman Pilot Service, cargo flight Rockingham to Fay, hit wires after takeoff 8.20pm, pilot hurt;  built Rent Car Inc, Boise ID Southeastern Beechcraft Inc, Knoxville TN Jim Hankins Air Service, Jackson MS	.83 .59 63/72 2.78 2.3.78  Pontiac MI, snow or .59 63/64 66/69 70/72
	G18S N180P no N180P ac airframe,	YV-122CP noted Opa Loc N180P sted San Franc cident report 2 snow on runw	built Pilot Freight Carriers Inc, Winston Salem NC Wyman Pilot Service, Pontiac MI crashed destroyed on takeoff, Rockingham NC  bisco CA 10.69, tailwheel, "Pilot Freight Carriers" titles; 2.3.78: Wyman Pilot Service, cargo flight Rockingham to Fay, hit wires after takeoff 8.20pm, pilot hurt;  built Rent Car Inc, Boise ID Southeastern Beechcraft Inc, Knoxville TN Jim Hankins Air Service, Jackson MS Morey L. Wyman/ Wyman Pilot Service, Pontiac MI	.59 63/72 2.78 2.3.78 Pontiac MI, snow or .59 63/64 66/69 70/72 76/81
	G18S N180P no N180P ac airframe,	YV-122CP noted Opa Loc N180P sted San Franc cident report 2 snow on runw	built Pilot Freight Carriers Inc, Winston Salem NC Wyman Pilot Service, Pontiac MI crashed destroyed on takeoff, Rockingham NC  bisco CA 10.69, tailwheel, "Pilot Freight Carriers" titles; 2.3.78: Wyman Pilot Service, cargo flight Rockingham to Fay, hit wires after takeoff 8.20pm, pilot hurt;  built Rent Car Inc, Boise ID Southeastern Beechcraft Inc, Knoxville TN Jim Hankins Air Service, Jackson MS Morey L. Wyman/ Wyman Pilot Service, Pontiac MI damaged, groundlooped on takeoff, Youngstown OH	.83 .59 63/72 2.78 2.3.78  Pontiac MI, snow or .59 63/64 66/69 70/72 76/81 20.1.77
	G18S N180P no N180P ac airframe,	YV-122CP noted Opa Loc N180P sted San Franc cident report 2 snow on runw	built Pilot Freight Carriers Inc, Winston Salem NC Wyman Pilot Service, Pontiac MI crashed destroyed on takeoff, Rockingham NC  bisco CA 10.69, tailwheel, "Pilot Freight Carriers" titles; 2.3.78: Wyman Pilot Service, cargo flight Rockingham to Fay, hit wires after takeoff 8.20pm, pilot hurt;  built Rent Car Inc, Boise ID Southeastern Beechcraft Inc, Knoxville TN Jim Hankins Air Service, Jackson MS Morey L. Wyman/ Wyman Pilot Service, Pontiac MI	.59 63/72 2.78 2.3.78 Pontiac MI, snow on .59 63/64 66/69 70/72 76/81
	G18S  N180P no N180P ac airframe, S	YV-122CP noted Opa Loc N180P  sted San France cident report 2 snow on runw. N9633R	built Pilot Freight Carriers Inc, Winston Salem NC Wyman Pilot Service, Pontiac MI crashed destroyed on takeoff, Rockingham NC  bisco CA 10.69, tailwheel, "Pilot Freight Carriers" titles; 2.3.78: Wyman Pilot Service, cargo flight Rockingham to Fay, hit wires after takeoff 8.20pm, pilot hurt;  built Rent Car Inc, Boise ID Southeastern Beechcraft Inc, Knoxville TN Jim Hankins Air Service, Jackson MS Morey L. Wyman/ Wyman Pilot Service, Pontiac MI damaged, groundlooped on takeoff, Youngstown OH	.83 .59 63/72 2.78 2.3.78  Pontiac MI, snow or .59 63/64 66/69 70/72 76/81 20.1.77 5.1.81
BA-479	G18S  N180P no N180P ac airframe, S	YV-122CP noted Opa Loc N180P  sted San France cident report 2 snow on runw. N9633R	built Pilot Freight Carriers Inc, Winston Salem NC Wyman Pilot Service, Pontiac MI crashed destroyed on takeoff, Rockingham NC  bisco CA 10.69, tailwheel, "Pilot Freight Carriers" titles; 2.3.78: Wyman Pilot Service, cargo flight Rockingham to Fay, hit wires after takeoff 8.20pm, pilot hurt;  built Rent Car Inc, Boise ID Southeastern Beechcraft Inc, Knoxville TN Jim Hankins Air Service, Jackson MS Morey L. Wyman/ Wyman Pilot Service, Pontiac MI damaged, groundlooped on takeoff, Youngstown OH struck-off USCR	.83 .59 63/72 2.78 2.3.78  Pontiac MI, snow or .59 63/64 66/69 70/72 76/81 20.1.77 5.1.81
BA-479	N180P no N180P ac airframe, s G18S	YV-122CP noted Opa Loc N180P  sted San France cident report 2 snow on runw.  N9633R  accident report limited use of	built Pilot Freight Carriers Inc, Winston Salem NC Wyman Pilot Service, Pontiac MI crashed destroyed on takeoff, Rockingham NC  bisco CA 10.69, tailwheel, "Pilot Freight Carriers" titles; 2.3.78: Wyman Pilot Service, cargo flight Rockingham to Fay, hit wires after takeoff 8.20pm, pilot hurt;  built Rent Car Inc, Boise ID Southeastern Beechcraft Inc, Knoxville TN Jim Hankins Air Service, Jackson MS Morey L. Wyman/ Wyman Pilot Service, Pontiac MI damaged, groundlooped on takeoff, Youngstown OH struck-off USCR	.59 63/72 2.78 2.3.78 Pontiac MI, snow or .59 63/64 66/69 70/72 76/81 20.1.77 5.1.81 m, 2 crew unhurt:
BA-479	N180P no N180P ac airframe, s G18S	YV-122CP noted Opa Loc N180P  sted San France cident report 2 snow on runw.  N9633R  accident report limited use of	built Pilot Freight Carriers Inc, Winston Salem NC Wyman Pilot Service, Pontiac MI crashed destroyed on takeoff, Rockingham NC  bisco CA 10.69, tailwheel, "Pilot Freight Carriers" titles; 2.3.78: Wyman Pilot Service, cargo flight Rockingham to Fay, hit wires after takeoff 8.20pm, pilot hurt;  built Rent Car Inc, Boise ID Southeastern Beechcraft Inc, Knoxville TN Jim Hankins Air Service, Jackson MS Morey L. Wyman/ Wyman Pilot Service, Pontiac MI damaged, groundlooped on takeoff, Youngstown OH struck-off USCR  2.20.1.77: Wyman, flight Youngstown to Pontiac MI, 2.47allegs due a prior loss of control in same type of aircraft"; built	.59 63/72 2.78 2.3.78 Pontiac MI, snow of .59 63/64 66/69 70/72 76/81 20.1.77 5.1.81 m, 2 crew unhurt:
BA-479	N180P no N180P ac airframe, s G18S	N180P  Sted San France Scident report 2 Snow on runw.  N9633R  Accident report limited use of  N1127M	built Pilot Freight Carriers Inc, Winston Salem NC Wyman Pilot Service, Pontiac MI crashed destroyed on takeoff, Rockingham NC  bisco CA 10.69, tailwheel, "Pilot Freight Carriers" titles; 2.3.78: Wyman Pilot Service, cargo flight Rockingham to Fay, hit wires after takeoff 8.20pm, pilot hurt;  built Rent Car Inc, Boise ID Southeastern Beechcraft Inc, Knoxville TN Jim Hankins Air Service, Jackson MS Morey L. Wyman/ Wyman Pilot Service, Pontiac MI damaged, groundlooped on takeoff, Youngstown OH struck-off USCR  2.20.1.77: Wyman, flight Youngstown to Pontiac MI, 2.47allegs due a prior loss of control in same type of aircraft";  built Miles Laboratories Inc, Elkhart IN	.59 63/72 2.78 2.3.78 Pontiac MI, snow or .59 63/64 66/69 70/72 76/81 20.1.77 5.1.81 m, 2 crew unhurt:
BA-479	N180P no N180P ac airframe, s G18S	N180P  Sted San France Scident report 2 Snow on runw.  N9633R  Accident report limited use of  N1127M	built Pilot Freight Carriers Inc, Winston Salem NC Wyman Pilot Service, Pontiac MI crashed destroyed on takeoff, Rockingham NC  bisco CA 10.69, tailwheel, "Pilot Freight Carriers" titles; 2.3.78: Wyman Pilot Service, cargo flight Rockingham to Fay, hit wires after takeoff 8.20pm, pilot hurt;  built Rent Car Inc, Boise ID Southeastern Beechcraft Inc, Knoxville TN Jim Hankins Air Service, Jackson MS Morey L. Wyman/ Wyman Pilot Service, Pontiac MI damaged, groundlooped on takeoff, Youngstown OH struck-off USCR  2.20.1.77: Wyman, flight Youngstown to Pontiac MI, 2.47allegs due a prior loss of control in same type of aircraft";  built Miles Laboratories Inc, Elkhart IN Miles Laboratories Inc, Elkhart IN	.59 63/72 2.78 2.3.78 2.3.78 Pontiac MI, snow or .59 63/64 66/69 70/72 76/81 20.1.77 5.1.81 m, 2 crew unhurt:
BA-479 BA-480	N180P no N180P ac airframe, s G18S	N180P  Sted San France Scident report 2 Snow on runw.  N9633R  Accident report limited use of  N1127M	built Pilot Freight Carriers Inc, Winston Salem NC Wyman Pilot Service, Pontiac MI crashed destroyed on takeoff, Rockingham NC  bisco CA 10.69, tailwheel, "Pilot Freight Carriers" titles; 2.3.78: Wyman Pilot Service, cargo flight Rockingham to Fay, hit wires after takeoff 8.20pm, pilot hurt;  built Rent Car Inc, Boise ID Southeastern Beechcraft Inc, Knoxville TN Jim Hankins Air Service, Jackson MS Morey L. Wyman/ Wyman Pilot Service, Pontiac MI damaged, groundlooped on takeoff, Youngstown OH struck-off USCR  2.20.1.77: Wyman, flight Youngstown to Pontiac MI, 2.47allegs due a prior loss of control in same type of aircraft";  built Miles Laboratories Inc, Elkhart IN Miles Laboratories Inc, Elkhart IN Ross Aviation, Tulsa-Riverside OK	.83 .59 63/72 2.78 2.3.78  Pontiac MI, snow or .59 63/64 66/69 70/72 76/81 20.1.77 5.1.81  m, 2 crew unhurt: .59 63/64 66 69

Kurt Fleter	.80
Roy Musgrove/ Alaska Express, Anchorage AK	5.81
crashed destroyed after takeoff, Anvik AK	4.6.81
struck-off USCR	10.87

Has been quoted as a turbine conversion but crash photographs show radial engines; N146PA accident report 4.6.81: Alaska Express, stalled on initial climb, cargo flight to Anchorage AK, 188 lbs over max gross weight, destroyed by fire after impact, pilot k.

BA-481	G18S	N233HC	Hooker Chemical Corp, Niagara Falls NY: CofA	16.12.59/64
			Malcolm Jacobs Co, St Louis MO	66
			Frederick H. Beach, Wilmington DE	69/72
			Yankee Aviation, Beloit WI	76/79
			Indianapolis Air Charter Services, Indianapolis IN	12.82/86
			Indianaero Inc, Bloomington IN	6.89/91
			Chris Spatz, Conway AR	2.94
		N584MS	Chris Spatz, Conway AR	7.94/95
		N233H	rereg	
			Bill Ingram/ Quick Air Freight Inc, Danville IL	8.9.97/06
			Michael W. Renfro, Bethel AK	12.2.10/19
			reg expired, struck-off USCR	1.11.19

N233HC noted New York-La Guardia NY 2.61, tailwheel;

N233H noted Danville IL 7.10.97 "Quick Air";

N233H at fly-in Oshkosh 1.8.98 polished metallic "Quick Air" titles, owned Bill Ingram, Danville IL and flown by Robert Auman, plate: BA-481 built 12.59;

N233H at fly-in Oshkosh 8.99 metallic "Quick Air" titles, Bill Ingram/Quick Air Freight Inc, Danville IL;

N233H at fly-in Oshkosh 26.7.01 "Quick Air Freight", tailwheel;

N233H noted Springdale AR 12.01 all metallic, tailwheel, op by Quick Air Freight;

N233H at fly-in Oshkosh 26.7.02 Quick Air;

N233H noted St Louis MO 25.1.03, tailwheel, cargo run;

N233H at fly-in Oshkosh WI 30.7.03 Quick Air;

N233H at fly-in Oshkosh 7.05 "Quick Alr"; N233H at fly-in Oshkosh 7.06 "Quick Air"; Oshkosh 7.08 "Quick Air"

further details: see Beech 18 by Robert Parmerter p. 301-302;

BA-482	G18S	N9696R	Beech Aircraft Corp, Wichita KS: CofA issued	22.12.59	
			Duncan Corp, Tarkio MO	63/64	
		N138Z	Intermountain Aviation, Marana AZ	66/69	
			USDA Forest Service, Albuquerque NM	69/70	
		N138ZL	USDA Forest Service, Atlanta GA	71/72	
			Federal Extension Service, Stillwater OK	79	
			Triangle Aircraft Air Charter, Baldwin KS	3.86/91	
			Southwest Assets Inc	94	
			Aerospace Products Inc, North Hollywood CA	12.4.94/95	
			Mid America Transport International Inc, Gibraltar MI	29.6.95/99	
			Tellico Air Services, Madisonville TN	22.3.99	
		N450TA	Tellico Air Services, Madisonville TN	12.8.99/00	
			Professional Air Charter Inc, Nashville TN	16.11.00/02	
			Kenneth R. Phillips, Brackettville TX	17.3.04/07	
			Kestrel Inc, Waukee IA	30.1.09/20	

N138ZL noted Grosse Isle MI 1.98; N450TA at Beech flyin Tullahoma TN 16.10.02;

BA-483	G18S	N9644R	built	.60
			Texas Power & Light Co, Dallas TX	63/66
			Richard P. Scaling, Stamford TX	69/79
			Hammonds Commuter Air Service, Houma LA	81
			Crow Inc, Millbury OH	9.83/85
			Olson Air Service, Nome AK	7.91/95
			John A. Marden, Concord MA	11.95/96
		AW-01	Tonga Defence Services Air Wing as AW-01	.96/06
			(fitted maritime surveillance gear Seattle WA,	
			delivered Honolulu-Christmas Island-Pago Pago 2.5.96,	
			Pago Pago-Tonga 4.5.96: for maritime patrols)	

19.11.96

94/06

N9644R noted Cincinatti OH 17.5.85 Crow Air Freight; N9644R noted Ottawa ONT 28.7.85 "Crow Air Freight" titles;

further details Tonga use: See Beech 18 by Robert Parmerter p.195, 302-303 report 6.96: purchased by Tonga Defence Force from a freight company in Alaska, refitted in Seattle with \$250,000 surveillance and communications equipment; arrived Tonga on delivery flight 4.5.96:

photo AW-01"Tonga Defence Services" flying Tonga 96;

AW-01 noted Tonga-Fua'amotu 2.97;

AW-01 noted Auckland-Ardmore NZ 8.97 completed after repairs to hurricane damage;

AW-01 noted Tongatapu, Tonga 16.2.00;

AW-01 noted Nuku'Alofa-Tongatapu 26.7.06 (AW-02 Bellanca 7GCBC also there)

BA-484	G18S	N228AA	Beech Aircraft Corp, Wichita KS: CofA issued	17.3.60
		N308C	Container Corp of America, Chicago IL	63/66
			Howard A. Weiss, Chicago IL	69
			SMB Stage Line Inc, Des Moines IA	.69/81
			Universal Aircraft Sales & Leasing Inc, Detroit MI: USCR	17.6.81/12
			dismantled in tech school, Pontiac MI by	7.91
			struck-off USCR	25.9.12

N308C noted Chicago-O'Hare IL 12.1.70 SMB Stage Line;

N308C noted Kansas City MO 13.12.70;

N308C noted Ottumwa IA 29.8.79 tailwheel "SMB Stage Line" titles;

N308C noted Oklahoma City OK 8.9.80 "SMB Stage Line" titles, tailwheel;

N308C noted Oklahoma City OK 15.12.80 "SMB Stage Line" titles, tailwheel;

N308C noted Pontiac MI 7.91: fuselage in tech. school, plate BA-484;

BA-485	G18S	N9660R	built	.60
		N517T	Tennessee Gas Transmission Co, Houston TX	63/64
			Tenneco Inc, Houston TX	66
		N517E	rereg	10.67
			Jess Hall, Houston TX, later Weatherford TX	69/79
			Bohlke International Airways, St Croix, US Virgin Islands	12.84/86
			Tol Air Services, San Juan, Puerto Rico	19.4.91
		N353T	Tol Air Inc, San Juan, Puerto Rico	8.91/96
			ditched in sea off NAS Roosevelt Roads, Puerto Rico	11.12.96

#### N353T based Antigua 94;

accident report 11.12.96: ditched en route San Juan-St Vincent, diverted due engine problems, aircraft located but pilot not found, accident report quotes owner as MBD Corp;

BA-486	G18S	N542B	Beech Aircraft Corp, Wichita KS: CofA issued	7.1.60
			Welbilt Vulcan Co, Memphis TN	63/64
			National Bank of Commerce, Memphis TN	66
			Ralph A. Miller, Norfolk VA	69/72
			Dole Aviation	74
			wing struck truck, taxying Boston-Logan MA	6.6.74
		N145PA	Providence Air Charter, Providence RI	1.4.78/79
			damaged on takeoff, Newburgh NY	5.4.79
			Don Kipp, Palm Beach FL: rest. to USCR	7.81
			Robin Tjader Lechnir, Boston MA	3.82
			Charles Green, Miami FL	28.12.83/14
			last FAA contact with owner 1989: struck-off USCR	5.9.14

Steve Darke quotes this is an unknown turbine conversion;

N542B noted Providence RI 14.8.74;

N542B accident report 6.6.74: Dole Aviation, left wing struck truck crossing taxiway while taxying for takeoff 11.03pm, flight to New York;

BA-487	G18S	N9658R	built	.60
		N965DC	rereg	

N686E	H. L. Coble Construction Co, Greensboro NC	63/64
N661JB	CC Leasing Corp, Baltimore MD	66
N6614B	Priority Air Despatch Inc, Washington-National DC	69/72
	right gear collapsed landing, Griffiss AFB NY	2.12.69
	Semo Aviation, Malden MO	8.6.73/75
	crashed destroyed near Troy AL	6.3.75

accident report 2.12.69: quotes "N4416B": Priority Air Despatch: right gear fatigue failure; N6614B accident report 6.3.75: Semo Aviation, mail flight Montgomery Al to Troy, struck trees on approach in fog, destroyed, pilot k, 3.50am;

	арргоаоп	m rog, acomo	σα, ριοι κ, σ.σσαιτι,	
BA-488	G18S	N9659R N119T	Beech Aircraft Corp, Wichita KS: CofA issued Texas Eastern Transmission Corp, Shreveport LA Johnson Flying Service, Missoula MT Evergreen Air of Montana, Missoula MT Clyde Frederickson, Polson MT sale reported, Jonesboro GA: USCR	14.1.60 63/66 69/73 10.75/77 79 91
	N119T nc	oted Missoula I	MT 21.7.73 JFS, red scheme;	
BA-489	G18S	N274AA N573D N5730U	E. I. duPont de Nemours Co Inc, Wilmington DE E. I. duPont de Nemours Co Inc, Wilmington DE Jack R. Peck/ Alaska Aeronautical Industries, Anchorage AK crashed destroyed landing, Sanak Island, Kenai AK	.60/64 66 12.1.68 18.12.68
BA-490	G18S	N900X XB-DHM Oscar K. B	Beech Aircraft Corp, Wichita KS: CofA issued Jones & Loughlin Steel Corp, Pittsburgh PA Priority Air Dispatch Inc, Washington-National DC Great Western Airlines, Tulsa-Riverside OK sale rep., Harlingen TX: USCR reg salderrama, Hermosillo	19.1.60 63/66 69/72 75/79 16.1.82/91 c91 93
BA-491	G18S	N9681R XB-MAH	Alamo Aviation Inc, San Antonio TX sold to Mexico, struck-off USCR reg. R. F. Corona, Guadalajara	12.2.60/62 9.3.62 .62 77
BA-492		N9662R N104KC noted San Fran	built Pioneer Aircraft Leasing Corp, Burbank CA Kern County Land Co, San Francisco CA M. R. Clarke Co, San Leandro CA Union Flights, Sacramento CA crashed destroyed on takeoff, Sacramento-Executive Cancisco CA 4.8.66 (rep as "N9626R" assumed this acft)	.60 63/64 66 69/79 29.6.78/79 A 4.1.79
			t 4.1.79: Union Flights: stalled after takeoff, 5.38pm, 2 crev	v k;
BA-493	G18S	HZ-IBN	Mohammed bin Ladin/ Bin Ladin Corp crashed near Abha, Saudi Arabia	4.60/67 3.9.67
	HZ-IBN fu	ırther details: s	see Beech 18 by Robert Parmerter p.300;	
BA-494	G18S	N9690R	Beech Aircraft Corp, Wichita KS: CofA issued Poole Motors Inc, Raleigh NC Federal Resources Corp, Salt Lake City UT Cape Air Leasing, Hyannis MA Gull Air, Hyannis MA & West Palm Beach FL Aviation One Inc Lake Clark Air Inc, Port Alsworth AK Jet Air Express Inc, Wilmington DE Aerolease of America Inc, Carson City NV Tropic Air Cargo, Sebastian FL Dove Enterprises LLC, Wilmington DE	27.1.60 63/64 66/72 79 77/86 7.87 7.88/96 6.2.96/99 13.10.99/02 20.3.03/05 27.12.05/19

06/19

N9690R noted Hyannis MA 3.4.78 "Gull Air" titles, tailwheel in service;

N9690R noted Hyannis MA 27.9.80 "Gull Air", tailwheel, plate BA-494;

N9690R photo 4.85 "Gull Air" tailwheel;

N9690R noted Anchiorage-Merrill Field 27.5.90;

N9690R noted Houston-Hobby TX 19.11.98, op Jet Air Express Inc (no titles), tailwheel;

N9690R noted Fort Laudwerdale Executive FL 2.11.04;

N9690R noted North Perry FL 3.4.06 "Aztec Airways" titles, freighter no windows, tailwheel:

N9690R noted Nassau, Bahamas 22.11.06 "Aztec Airways" titles, tailwheel, in service;

BA-495	G18S	N9669R	Beech Aircraft Corp, Wichita KS: CofA issued	4.2.60
			Custom Finance Co, Vicksburg MS	63/64
			Clark Equipment Co, Buchanan MI	66/69
			Niles Airways, Niles MI	70/72
		CF-IGD	Koenena Air Service Ltd, Yellowknife NWT	11.73/76
			Aviair Aviation Ltd, Kamloops BC	.82/87
			sold to USA: struck off Canadian Register	4.87
		N9669R	Richard Wixom/ Blackhawk Airways, Janesville WI	8.4.87/91
			Blackhawk Airways, Janesville WI	1.94/96
			Flight Training Centre, Janesville WI	11.96
			Gail Force Corp, Janesville WI	18.9.98/99
			William B. Baum, Seattle WA	14.5.01/11
			Rogers Racing & Restorations Inc, Mukilteo WA	8.12.11/16
			Matt Engram, Branson MO	20.4.16/20

N9669R noted Janesville-Rock County WI 7.91 "Blackhawk AW", plate BA-495;

N9669R noted Willow Run MI 11.11.97 Blackhawk;

N9669R noted Janesville-Rock County WI 2.8.98 Gail Force Express,

N9669R noted Janesville WI 26.7.99 Gail Force, plate: BA-495 built 1.60;

N9669R noted Rockford IL 31.7.00 at Courtesy Aircraft for resale;

N9669R noted Bellingham WA 6.03 "Aire Marjorie" titles, civil scheme, tailwheel, i/s; N9669R noted Arlington WA flyin 12.7.03, tailwheel, "US Army 04771 82<sup>ND</sup> AIRBORNE DIVISION"; N969R at flyin Arlington WA 7.7.05;

Adv for sale 11.15 Courtesy Aircraft: TT 13,454 hrs, same Army paint scheme

G18S	N9675R	built	.60
		Sunnyland Packing Co, Thomasville GA	63/64
	N675SP	Sunnyland Packing Co, Thomasville GA	66
	N6750P	Domestic Aviation, Millersburg OH	69/70
		Ross Aviation, Tulsa-Riverside OK	71/72
		Great Western Airlines, Tulsa-Riverside OK	77/79
		Aero Transit Inc, Danvers MA	.80
		ACE Air Cargo Express Inc, Cleveland OH	1.83/86
		Royal Air Freight, Pontiac MI	20.1.89/91
		sold to Venezuala, struck-off USCR	4.2.91
	YV-757C	Aviogenex Cargo	95
		retired on airport dump, Caracas	99
	G18S	N675SP N6750P	Sunnyland Packing Co, Thomasville GA N675SP Sunnyland Packing Co, Thomasville GA N6750P Domestic Aviation, Millersburg OH Ross Aviation, Tulsa-Riverside OK Great Western Airlines, Tulsa-Riverside OK Aero Transit Inc, Danvers MA ACE Air Cargo Express Inc, Cleveland OH Royal Air Freight, Pontiac MI sold to Venezuala, struck-off USCR YV-757C Aviogenex Cargo

N6750P noted Terre Haute IN 14.12.85 Ace Air Cargo: YV-757C noted Caracas 24.9.99 on dump;

BA-497	E18S		(E18S model from G18S production line)	3.60
		N901T (1	Skyways Aircraft Ferrying Service Inc, Los Angeles CA	31.3.60
		•	sold to Japan, struck-off USCR	26.5.60
		JA5060	Japan Civil Aviation Bureau, Civil Aviation College	4.60
			Ministry of Transportation, Miyazaki	65
			Civil Aviation College, Sendai	70
			retired, broken-up: struck-off Register	18.6.74

Produced by Beech with E18S style cockpit windows, 5 cabin seats plus jumpseat: see Beech 18 by Robert Parmerter p.286;

BA-498	G18S	N161M	built	.60	
			General Development Air Service, Miami FL	63	
			Beach Air Service, Fort Lauderdale FL	64	

	Big Dutchman Inc, Zeeland MI	66
	US Industries Inc, Zeeland MI	69/70
	Joseph Fontana, Kingsford MI	71/72
N75FA	Flight Express Cargo, Essington PA	24.2.77
	crashed after takeoff, Pittsburgh PA	17.8.77

N75FA accident report: flight Pittsburgh to Cleveland OH, engine failed after takeoff, crashed during forced landing back on airport, stalled in, 5.41am, 2 hurt;

			nding back on airport, stalled in, 5.41am, 2 hurt;	<del>,</del>
BA-499	G18S	PT-BFX	built Central Electrica de Furnas SA, Rio de Janeiro Taxi Aereo Rio Ltda, Rio de Janeiro	.60 65 83
			os Dumont 8.1.68; os Dumont 10.3.72 Taxi Aereo Rio;	
BA-500	G18S	N9684R	built Koss Construction Co, Des Moines IA Streamline Pastics Inc, Knoxville TN Great Western Airlines, Tulsa-Riverside OK Deral D. Browning, Roanoke AL crashed on takeoff, Atlanta-Charlie Brown GA	.60 63/69 70/72 74/80 28.4.80 13.12.80
	N9684R n N9684R a trees, fire	oted Dayton C accident report after impact, 6	O'Hare 18.5.74 Great Western Airlines; OH 27.5.76 Great Western Airlines; 13.12.80: operator not quoted, aborted takeoff, ran off ru 5.01am; 1700 lbs over gross weight, CofG 7.6 inches bey he since last layoff, frost on airframe;	
BA-501	G18S	N704B N704GP CF-BUS	built C. H. Dexter & Sons Inc, Windsor Locks CT Georgia Pacific Corp, Portland OR Pacific Coastal Airlines Northern Thunderbird Air, Prince George BC Central BC Air Services, Kamloops BC North Cariboo Flying Service, Fort Saint John BC named White Tornado crashed into mountain slope, 80M north of Saint John struck-off Register (wreck in situ at 3,000 feet elevation, seen 8.16)	.60 63/66 69/72 11.72 74 76/77 80 BC .80 4.81
			s BC 27.9.77, in service, blue & white, no titles; n mountain slope at 3,000 ft AMSL, fuselage intact;	
BA-502	G18S	N9683R N100X (2 N189X N188X	Beech Aircraft Corp, Wichita KS: CofA issued American Snuff Co, Memphis TN rereg Rowan Drilling Co, Fort Worth TX M. L. Mulcher Co, Virden IL struck truck taxying after landing, Springfield IL St Germaine Aviation, Hinsdale IL damaged when hit snowbank landing, Oshkosh WI Eugene Pikowsky, Minneapolis MN op: Viking International Air Freight, Minneapolis MN Dave Davis, League City TX struck-off Register	15.2.60 63/64 66 69/70 29.8.0 71/72 4.3.75 76/79 76/79 3.3.82/12 14.8.12
BA-503	G18S	N269A N375S	built John T. Dorrance, Gladwyne PA International Salt Co, Flemington NJ Elk Mountain Flying Service, Kinston NC Jack Hudson, Gallup NM Ronald W. Smith/ Smithair, Atlanta GA badly damaged by windstorm, Atlanta GA struck-off USCR	.60 63/64 66/70 71/72 79 15.9.78/91 19.11.81 21.6.91

BA-504	G18S	N1847R	built	.60
			Rahr Malting Co, Manitowoc WI	63/70
		N74FA	Fontana Aviation, Iron Mountain MI	71/72
			K-Airways Inc, Kenosha WI	79/86
			crashed on mountain, destroyed, Copperhill TN	22.2.86

accident report 22.2.86: night freight flight Kenosha WI to Milwaukee then Atlanta, Pilot calls to ATC non-standard then no replies, acft cruising 11,000 feet until descended without clearance, struck trees on a moiuntain, crashed and burned, operator K-Airways Inc;

BA-505	G18S	N9682R	Beech Aircraft Corp, Wichita KS: CofA issued	18.2.60
			Bailey Leasing Corp, Fort Wayne IN	63/66
			Howard A. Weiss, Washington DC	69
			Jim Hankins Air Service, Jackson MS	70/72
			Morey Wyman/ Wyman Pilot Service, Pontiac MI	79/84
			Aaron T. Hale, Cleveland OH	7.88
			Hale Aviation, Romulus MI: USCR	16.6.89/97
			M. Corley Tedder, Texarkana TX: for parts	97/03
			(stripped hulk in compound Texarkana TX 97/08)	
			Tom May/ May Air Xpress, New Boston TX: for parts	03
			struck-off USCR	1.7.13
			Steve Dean/ Flight of the Phoenix Aviation Museum,	
			Gilmer TX	.03
			(awaiting collection from Texarkana 03/08, planned to	
			be restored for static display)	

N9682R noted Dallas-FTW TX 12.93, all metallic, in service; N9682R noted Texarkana AR 8.97 & 6.8.98 & 16.8.99: all metallic, dismantled in compound; N9682R noted Texarkana AR 2.8.02 & 6.8.03 both still in compound off airport; Tommy May donated his 2 E18S hulks at Texarkana to Steve Dean's museum .03, had not beenbcollected by 8.03, unmovedTexarkana 22.7.08 dismantled;

BA-506	G18S	N9649R	Beech Aircraft Corp, Wichita KS: CofA issued	23.2.60
			International Milling Co, Minneapolis MN	63/64
			Titus Manufacturing Co, Waterloo IA	66
		N735EB	E. T. Barwick Industries, Chamblee GA	69
		N732EB	E. T. Barwick Industries, Chamblee GA	70/72
			Southland Flyers Inc, Memphis TN	29.12.77/14
			last owner contact with FAA 1984, struck-off USCR	17.11.14
		N732EB	Kris A. Nace, Glendale OR: rest. to USCR	22.9.17/19
			sale rep., c/o Taigh Ramey, Stockton CA	10.19
			struck-off USCR	29.5.21

N9649R noted Atlanta GA 3.10.68;

N732EB noted Oklahoma City OK 6.9.79 no titles, tailwheel;

N732EB noted Memphis TN 5.80;

N732EB noted Stockton CA 10.19 at Taigh Ramey's Vintage Aircraft hangar. stripped;

BA-507	G18S	N941S	built	.60
			Stokely Van Camp Inc, Indianapolis IN	63/66
		N9415	Diehl Machines Inc, Wabash IN	69
			Champion Pneumatic Machinery Co, Princeton IL	70/72
			Gilley Airways Corp, Hartsville SC	30.3.76/77
			struck-off USCR	11.11.77
BA-508	G18S	N9689R	built	.60
			Dorsey Trailers, Elba AL	63/69
		N844C	PA Glass Sand Co, Wilmington DE	70/79
		N843C	Pennsylvania Glass Sand Corp, Wilmington DE	5.80
			struck-off USCR	8.12.86
BA-509	G18S	XC-CEO	Mexican Government	.60
		XC-CNI	Mexican Government	
		N36F	Johnson Flying Service, Missoula MT	69/75
			Evergreen Air of Montana, Missoula MT	10.75/77

Volpar Turboliner II		(converted to <i>Volpar Turboliner II</i> 16.8.77, conv. No.21: special long range version <i>Asterix VLR</i> )	
Asterix VLR		sold to France, struck-off USCR	30.9.77
	F-ODHJ	SA Interthon, Abidjan, Ivory Coast	13.6.78/91
		op: Ste Interthon, Mahe	90
		op: Saipex Aero	91
		sold to USA, struck-off French Register	22.4.91
	N81CK	American International Airways, Detroit MI	17.4.91
		Kalitta Flying Service, Detroit-Willow Run MI	11.92/99
		Kitty Hawk Charters Inc, Morristown TN	6.5.99/02
		Jim Hankins Air Service, Jackson MS	7.1.02/14
		(purchased 10.01 at Kitty Hawk auction \$78.5K,	
		TT 20.9076 hrs)	
	N320GB	GB Airlink Inc, Fort Lauderdale FL	18.9.14/19
		Airsquid Aviation, Las Vegas NV	3.1.20

Asterix VLR was a special long range reconnaissance model for Interthon at Abidjan: standard additional 757 litres in 2 cabin tanks extending range to 2200NM: used for fish spotting: see Beech 18 by Robert Parmerter p.392;

N36F noted Missoula MT 21.7.73 JFS, blue scheme;

N81CK noted Willow Run 7.91 at Kalitta ramp, Turboliner, retired stored, F-ODHJ visible;

N81CK noted Willow Run 8.96 Kalitta, as Turboliner;

N81CK noted Willow Run MI 2.3.97, 5.97;

N81CK noted Willow Run 23.7.00, Kitty Hawk Charters, Volpar Turboliner, plate BA-509 built 3.60;

N81CK noted Jackson MS 1.8.02 plate G18S BA-509 built 3.60, Turboliner serial 021 date 8.77;

N81CK noted Jackson-Hawkins Field MS 5.8.03 Volpar, "JHAS" titles;

N81CK noted Panama City FL 13.8.05 turbine Trigear Hankins Air Service;

N81CK noted Jackson-Hawkins Field MS 5.8.08 Turboliner;

Connie Kalitta had an auction of retired turbine Beech 18s at Willow Run 7.02:

- N231LJ (Bu23835) sold to Nick Quint/Blackhawk Airways for \$2500, towed by road to Janesvill 7.02;
- Jim Hankins purchased N231SK, N4209V, N81CK, N404CK
- 10 others broken up for scrap 5 cockpit & nose sections purchased by Dave Warren, Tulsa OK;

BA-510	G18S	N9916R	built	.60
		R. H. Fulton, Lubbock TX	R. H. Fulton, Lubbock TX	63/66
			C. W. Zumbiel Corp, Cincinatti OH	69/70
		N11BZ	C. W. Zumbiel Corp, Cincinatti OH	
		N11ZB C. W. Zumbiel Corp, Cincinatti OH	C. W. Zumbiel Corp, Cincinatti OH	71/72
			Wyman Pilot Service, Pontiac MI	10.78
			crashed destroyed landing, Cleveland-Hopkins OH	11.10.78

accident report: N11Z G18S: Wyman Pilot Service, cargo flight Bowling Green KY to Cleveland, heavy landing, go around, crashed wheels-up, cargo shifted, dest: pilot hurt, first flight in this model;

BA-511	G18S	N605V	Beech Aircraft Corp, Wichita KS: CofA issued	11.3.60
			Kirsch Company, Sturgus MI	63/64
		N605L	rereg	
		N7711S (2	gear retracted on takeoff, Austin TX	7.8.65
			Travco Inc, Wilmington DE	66/70
			Aircraft Finance Co, Memphis TN	71/72
			op: Great Western Airlines, Tulsa OK	77
			Seymour Canter, Murrieta CA	79
			sale reported	8.81/91
BA-512	G18S	N9680R	built	.60
			Louisiana State Police, Baton Rouge LA	63
			State of Louisiana Public Safety, Baton Rouge LA	64/66
			J. B. McDuff, Burnet TX	69/70
			Tidwell Industries, Haleyville TN	71/72
			Howard G. Schlick, Central Point OR	79
			Air Cortez, Ontario CA	79
			Lucky Seven Airways	80
			(departed Chino CA 9.8.80 on deivery to new owner FL)	
			Wayne Sturtman Aircraft Sales, Merritt Island FL	91/98

N9680R noted Comotara KS 5.6.76; N9680R noted Chino CA 5.4.80 "Lucky Seven Airways" titles; N9680R noted Chino CA 7.80 "Lucky Seven Airways" titles, tailwheel; noted Chino CA 9.8.80, departed on delivery to new owner Orlando FL;

BA-513	G18S	N9900R	built	.60
			Howard Sober Inc, Lansing MI	63/70
			Jerry Moore Inc, Canton OH	71/72
			Frank J. Cannavo/ Aero Taxi, Lester PA	15.4.77/85
			ran off runway on takeoff, struck ditch, gear collapsed,	
			Allentown-Wilkes Barre PA	2.2.83
			struck-off USCR	20.2.85
	N9900R a	accident report :	2.2.83: Air Taxi Inc, main gear collapsed;	
BA-514	G18S	N772AA	Atlantic Aviation: CofA issued	19.3.60
			National Financing Inc, Wilmington DE	63/64
			IT&T Corp, New York NY	64
		N610G	IT&T Corp, New York NY	
		N710G	IT&T Corp, New York NY	66/76
			Ford & Ivester Associates, Waltham MA	79
			GM Airlines, Opa Locka FL	6.82
			Anton J. Koprivnik, Miami FL	3.87/89
		N610RB	Reynaldo A. Blanco, Miami FL	4.89/91
			dam. accident San Andros, Bahamas	20.10.89
			Manuel Alen, Miami FL	18.1.92/14
			struck-off USCR	13.11.14
RA-515	N710G no N610RB i	oted Opa Locka noted Tamiami	ia 64 "IT&T" emblem; FL 22.3.87, 9.10.87; FL 18.9.90, 5.92;	60
BA-515	N710G no	oted Opa Locka	FL 22.3.87, 9.10.87;	.60 63/66 20.11.68/91
BA-516	N710G no N610RB i	oted Opa Locka noted Tamiami N333X N334X	FL 22.3.87, 9.10.87; FL 18.9.90, 5.92;  built George Hall Corp, Ogdensburg NY Millers Aviation, Mooresville NC	63/66
BA-515 BA-516	N710G no N610RB i	oted Opa Locka noted Tamiami N333X	FL 22.3.87, 9.10.87; FL 18.9.90, 5.92; built George Hall Corp, Ogdensburg NY	63/66
	G18S G18S trigear	N333X N334X N9907R N5000T (3	FL 22.3.87, 9.10.87; FL 18.9.90, 5.92;  built George Hall Corp, Ogdensburg NY Millers Aviation, Mooresville NC  built .60 Thiokol Chemical Corp, Brigham City UT	63/66 20.11.68/91 31.8.61/72
BA-516	G18S G18S trigear	N333X N334X N9907R N5000T (3	FL 22.3.87, 9.10.87; FL 18.9.90, 5.92;  built George Hall Corp, Ogdensburg NY Millers Aviation, Mooresville NC  built .60 Thiokol Chemical Corp, Brigham City UT struck-off USCR	63/66 20.11.68/91 31.8.61/72
BA-516	G18S G18S trigear	N333X N333X N334X N9907R N5000T (3	FL 22.3.87, 9.10.87; FL 18.9.90, 5.92;  built George Hall Corp, Ogdensburg NY Millers Aviation, Mooresville NC  built .60 Thiokol Chemical Corp, Brigham City UT struck-off USCR  ey AZ 7.11.69 trigear;  Ohio Oil Co/ Marathon Oil Co, Findlay OH: CofA issued	63/66 20.11.68/91 31.8.61/72 16.11.72
BA-516	G18S G18S trigear	N333X N333X N334X N9907R N5000T (3	FL 22.3.87, 9.10.87; FL 18.9.90, 5.92;  built George Hall Corp, Ogdensburg NY Millers Aviation, Mooresville NC  built .60 Thiokol Chemical Corp, Brigham City UT struck-off USCR	63/66 20.11.68/91 31.8.61/72 16.11.72
BA-516	G18S G18S trigear	N333X N333X N334X N9907R N5000T (3	FL 22.3.87, 9.10.87; FL 18.9.90, 5.92;  built George Hall Corp, Ogdensburg NY Millers Aviation, Mooresville NC  built .60 Thiokol Chemical Corp, Brigham City UT struck-off USCR  ey AZ 7.11.69 trigear;  Ohio Oil Co/ Marathon Oil Co, Findlay OH: CofA issued Ohio Aviation Co, Dayton OH Knight Aircraft Corp, Miami FL	63/66 20.11.68/91 31.8.61/72 16.11.72 26.3.60/64 70/72
BA-516	G18S G18S trigear	N529M N729M N729M	FL 22.3.87, 9.10.87; FL 18.9.90, 5.92;  built George Hall Corp, Ogdensburg NY Millers Aviation, Mooresville NC  built .60 Thiokol Chemical Corp, Brigham City UT struck-off USCR  ey AZ 7.11.69 trigear;  Ohio Oil Co/ Marathon Oil Co, Findlay OH: CofA issued Ohio Aviation Co, Dayton OH Knight Aircraft Corp, Miami FL	63/66 20.11.68/91 31.8.61/72 16.11.72 26.3.60/64 70/72 79
BA-516	G18S G18S trigear	N333X N333X N334X N9907R N5000T (3 N529M N729M N300MF (2	FL 22.3.87, 9.10.87; FL 18.9.90, 5.92;  built George Hall Corp, Ogdensburg NY Millers Aviation, Mooresville NC  built .60 Thiokol Chemical Corp, Brigham City UT struck-off USCR  ey AZ 7.11.69 trigear;  Ohio Oil Co/ Marathon Oil Co, Findlay OH: CofA issued Ohio Aviation Co, Dayton OH Knight Aircraft Corp, Miami FL Missionary Flights International, West Palm Beach FL Missionary Flights International, West Palm Beach FL	63/66 20.11.68/91 31.8.61/72 16.11.72 26.3.60/64 70/72 79 5.80/82 4.82
BA-516	G18S G18S trigear	N333X N333X N334X N9907R N5000T (3 N529M N729M N300MF (2	FL 22.3.87, 9.10.87; FL 18.9.90, 5.92;  built George Hall Corp, Ogdensburg NY Millers Aviation, Mooresville NC  built .60 Thiokol Chemical Corp, Brigham City UT struck-off USCR  ey AZ 7.11.69 trigear;  Ohio Oil Co/ Marathon Oil Co, Findlay OH: CofA issued Ohio Aviation Co, Dayton OH Knight Aircraft Corp, Miami FL Missionary Flights International, West Palm Beach FL Coast Air Freight Inc, Long Beach CA	63/66 20.11.68/91 31.8.61/72 16.11.72 26.3.60/64 70/72 79 5.80/82
BA-516	G18S G18S trigear	N333X N333X N334X N9907R N5000T (3 N529M N729M N300MF (2	FL 22.3.87, 9.10.87; FL 18.9.90, 5.92;  built George Hall Corp, Ogdensburg NY Millers Aviation, Mooresville NC  built .60 Thiokol Chemical Corp, Brigham City UT struck-off USCR  ey AZ 7.11.69 trigear;  Ohio Oil Co/ Marathon Oil Co, Findlay OH: CofA issued Ohio Aviation Co, Dayton OH Knight Aircraft Corp, Miami FL Missionary Flights International, West Palm Beach FL Missionary Flights International, West Palm Beach FL	63/66 20.11.68/91 31.8.61/72 16.11.72 26.3.60/64 70/72 79 5.80/82 4.82 6.85
BA-516	G18S G18S trigear	N333X N333X N334X N9907R N5000T (3 N529M N729M N300MF (2	built George Hall Corp, Ogdensburg NY Millers Aviation, Mooresville NC  built  60 Thiokol Chemical Corp, Brigham City UT struck-off USCR  by AZ 7.11.69 trigear;  Ohio Oil Co/ Marathon Oil Co, Findlay OH: CofA issued Ohio Aviation Co, Dayton OH Knight Aircraft Corp, Miami FL Missionary Flights International, West Palm Beach FL Coast Air Freight Inc, Long Beach CA Union Flights, Sacramento CA Jim Jankins Air Service, Jackson MS	63/66 20.11.68/91 31.8.61/72 16.11.72 26.3.60/64 70/72 79 5.80/82 4.82 6.85 1.86/95 27.7.95/97
BA-516	G18S G18S trigear	N333X N333X N334X N9907R N5000T (3 N529M N729M N300MF (2	built George Hall Corp, Ogdensburg NY Millers Aviation, Mooresville NC  built  .60 Thiokol Chemical Corp, Brigham City UT struck-off USCR  ey AZ 7.11.69 trigear;  Ohio Oil Co/ Marathon Oil Co, Findlay OH: CofA issued Ohio Aviation Co, Dayton OH Knight Aircraft Corp, Miami FL Missionary Flights International, West Palm Beach FL Missionary Flights International, West Palm Beach FL Coast Air Freight Inc, Long Beach CA Union Flights, Sacramento CA Jim Jankins Air Service, Jackson MS John C. Hooper, Carriere MS	63/66 20.11.68/91 31.8.61/72 16.11.72 26.3.60/64 70/72 79 5.80/82 4.82 6.85 1.86/95 27.7.95/97 15.5.97/01
	G18S G18S trigear	N333X N333X N334X N9907R N5000T (3 N529M N729M N300MF (2 N729M	built George Hall Corp, Ogdensburg NY Millers Aviation, Mooresville NC  built George Hall Corp, Ogdensburg NY Millers Aviation, Mooresville NC  built .60 Thiokol Chemical Corp, Brigham City UT struck-off USCR  by AZ 7.11.69 trigear;  Ohio Oil Co/ Marathon Oil Co, Findlay OH: CofA issued Ohio Aviation Co, Dayton OH Knight Aircraft Corp, Miami FL Missionary Flights International, West Palm Beach FL Missionary Flights International, West Palm Beach FL Coast Air Freight Inc, Long Beach CA Union Flights, Sacramento CA Jim Jankins Air Service, Jackson MS John C. Hooper, Carriere MS Frank U. Cain, Katy-Sugerland TX	63/66 20.11.68/91 31.8.61/72 16.11.72 26.3.60/64 70/72 79 5.80/82 4.82 6.85 1.86/95 27.7.95/97 15.5.97/01 8.7.02/05
BA-516	G18S G18S trigear	N333X N333X N334X N9907R N5000T (3 N529M N729M N300MF (2 N729M	built George Hall Corp, Ogdensburg NY Millers Aviation, Mooresville NC  built George Hall Corp, Ogdensburg NY Millers Aviation, Mooresville NC  built .60 Thiokol Chemical Corp, Brigham City UT struck-off USCR  by AZ 7.11.69 trigear;  Ohio Oil Co/ Marathon Oil Co, Findlay OH: CofA issued Ohio Aviation Co, Dayton OH Knight Aircraft Corp, Miami FL Missionary Flights International, West Palm Beach FL Missionary Flights International, West Palm Beach FL Coast Air Freight Inc, Long Beach CA Union Flights, Sacramento CA Jim Jankins Air Service, Jackson MS John C. Hooper, Carriere MS Frank U. Cain, Katy-Sugerland TX Frank U. Cain, Katy TX: ntu	63/66 20.11.68/91 31.8.61/72 16.11.72 26.3.60/64 70/72 79 5.80/82 4.82 6.85 1.86/95 27.7.95/97 15.5.97/01 8.7.02/05 7.02
BA-516	G18S G18S trigear	N333X N333X N334X N9907R N5000T (3 N529M N729M N300MF (2 N729M	built George Hall Corp, Ogdensburg NY Millers Aviation, Mooresville NC  built George Hall Corp, Ogdensburg NY Millers Aviation, Mooresville NC  built .60 Thiokol Chemical Corp, Brigham City UT struck-off USCR  by AZ 7.11.69 trigear;  Ohio Oil Co/ Marathon Oil Co, Findlay OH: CofA issued Ohio Aviation Co, Dayton OH Knight Aircraft Corp, Miami FL Missionary Flights International, West Palm Beach FL Missionary Flights International, West Palm Beach FL Coast Air Freight Inc, Long Beach CA Union Flights, Sacramento CA Jim Jankins Air Service, Jackson MS John C. Hooper, Carriere MS Frank U. Cain, Katy-Sugerland TX	63/66 20.11.68/91 31.8.61/72 16.11.72 26.3.60/64 70/72 79 5.80/82 4.82 6.85 1.86/95 27.7.95/97 15.5.97/01 8.7.02/05

USCR1966 & 69: N529M & N729M not listed;

N729M noted Toledo-Express OH 25.5.76;

N729M noted LAX 24.7.85 Coast Air Freight (no titles);

N729M noted Ontario CA 25.1.87;

N729M noted Santa Maria CA 11.6.90 Union Flights;

N729M noted Sugarland TX 8.5.03;

N729M noted West Houston TX 9.8.03 flown by owner Frank Cain, titles "Trans Pearl River Airline" & "Window Screen Company", plate BA-517 built 3.60;

BA-518	G18S	N93D	built	.60
BA-519	G18S	N9912R	built	.60
		N49K (2	rereg	6.6.61
		,	Walston Aircraft Sales & Service, Alton IL	63/64
			Alton Box Board Co, Alton IL	66/70
			Midwest Piper Sales Inc, Wichita KS	71/72
			Semo Aviation Inc, Malden MO	76/79
			Levitz Aviation Service, Fort Lauderdale FL	12.83
			Aviation One Inc, Cincinatti OH	12.85
			Florida Fresh Seafood, Miami FL	10.88/91
			H & G Import & Export Corp, Fort Lauderdale FL	94/95
			crashed destroyed by fire, Fort Lauderdale FL	16.2.94
			K & K Aircraft Inc, Bridgewater VA (for parts)	23.2.95
			struck-off USCR	5.6.95

N49K noted Ft Lauderdale FL 24.8.71;

N49K noted Tulsa OK 30.9.71;

N49K noted Ft Lauderdale-Exec FL 21.11.83 tailwheel, Levitz Aviation Service, no titles, in service; N49K noted Ft Lauderdale FL 4.11.87;

BA-520	G18S	N9913R	Beech Aircraft Corp, Wichita KS: CofA issued	11.4.60
		N512T	Tennessee Gas Transmission Co, Houston TX	63/64
			Tenneco Inc, Houston TX	66
		N512E	Hickory Springs Manufacturing Co, Hickory NC	69/70
			Tailwinds Inc, Old Brookville NY	79
			Springdale Air Service, Springdale AR	16.6.86/00
			damaged by fire during landing, Springdale AR	2.4.95
			South West Aero Exchange, Owasso OK	00
			(stored dism. fire damaged in salvage yard,	
			Owasso OK 00)	

N512E noted MacArthur NY 8.8.74 Tailwinds Inc;

N512E noted Springdale AR 8.97, spares source, fuselage stacked against Springdale Air Service hangar, badly burnt cockpit area on starboard side: plate BA-520 built 3.60;

N512E noted Springdale AR 13.10.97 fire damaged;

N512E fuselage noted in SW Aero Exchange yard, Owasso OK 10.8.00, plate BA-520 built 3.60, spar kit #178 22.4.75;

BA-521	G18S	N9918R	Beech Aircraft Corp, Wichita KS: CofA issued	12.4.60
			Airfleet Leasing Corp, Gainsville FL	63/64
		George H. Bailey Co, Fort Wayne IN	66	
			Cleveland Aero Inc, Cleveland OH	69
			Henry O. Moffett, Centreport NY	70
			op: Eastern Caribbean Airlines	70
			Miami Aviation Corp, Opa Locka FL	71/72
			Lee Maples/ Maples Aviation Co Inc, Rolla MO	11.72/02
			op: Baron Air Services, Rolla MO	98
			John G. Wood, Winter Haven FL	4.2.03/15
			Andrew Hochhaus, Norfolk VA	31.12.15/20

N9918R noted Bridgetown, Barbados 31.5.70 Eastern Caribbean Airlines;

N9918R noted Opa Locka FL 23.8.71;

N9918R at fly-in Oshkosh WI 30.7.94 owner Lee Maples, won Classic Grand Champion;

N9918R noted Rolla National MO 26.8.98 owned Baron AS, plate: BA-521 built 4.60;

N9918R at fly-in Oshkosh 23.7.02;

N9918R noted Rolla-Vichy MO 7.8.02, plate BA-521;

N9918R at Beech fly-in Tullahoma TN 16.10.03;

N9918R at fly-in Oshkosh 31.7.04;

N9918R at fly-in Oshkosh 7.06;

N9918R at Beech flyin Tullahoma TN 14.10.07; same 18.10.14;

BA-522	G18S	N9920R	built	.60
		N2634 (2	Socony Mobil Oil Co, New York NY	63/64

		N2634E	Mobile Oil Corp, New York NY Irving Industries Inc, Lexington KY	66 69/70
BA-523	G18S	N572B	built	.60
			Burford Toothaker Tractor Co, Montgomery AL	63
			Burford Equipment Co, Montgomery AL	64/72
		N1WF	Signal Airmotive Corp, Chatanooga TN	79
		N400R	rereg	1.79
			Sky Train Inc, McAllen TX	4.82
			sale reported	14.10.82/91
BA-524	G18S	N9699R	Beech Aircraft Corp, Wichita KS: CofA issued	27.4.60
			Winn Dixie Inc, Greenville SC	63/64
		N219W	Winn Dixie Inc, Greenville SC	66/72
			sale reported: USCR	79
			M. Corley Tedder, Texarkana TX	10.82/87
			Jan E. Goodson, Texarkana TX	7.87
			M. Corley Tedder, Texarkana TX	91
			May Air Xpress, New Boston TX	12.92/97
			M. Corley Tedder, Texarkana TX	17.3.97/13
			struck-off USCR	12.11.13

N219W noted Atlanta TX 8.97, plate BA-524;

N219W noted Atlanta TX 6.8.98 & 16.8.99: both owned Corley M. Tedder, plate: BA-524 built 4.60; N219W noted Atlanta TX 2.8.02 & 6.8.03 both stored inside Corley Tedder hangar;

BA-525	G18S	N9941R	built	.60
		Wiles Holloway Inc, Baton Rouge LA	Wiles Holloway Inc, Baton Rouge LA	63
			Goldrus Drilling Co, Houston TX	64
		N941R	Goldrus Drilling Co, Houston TX	66/70
		CF-ZYT	D. C. Plaunt, Sudbury ONT	3.71/72
		N741GB	A. Newton Ball, Anchorage AK	8.77
			forced landing after takeoff, Anchorage AK	17.8.77
			Air Parts Inc, Anchorage AK	78/79
			(stored in Air Parts Inc yard, Anchorage 78/79)	
			struck-off USCR	10.3.81
		_		
BA-526	G18S	N277S	Beech Aircraft Corp, Wichita KS: CofA issued	6.6.60
			Hardware Mutual Casualty, Stevens Point WI	63/66
			Airlie Foundation, Warrenton VA	69/72
		N103AF	Wilmington Flying Service, Troy MI	79
		Earth Resourced Conservation Society, Atlanta GA	Earth Resourced Conservation Society, Atlanta GA	5.82
			Richard J. Wixom/ Blackhawk Airways, Janesville WI	7.86/91
			(fitted with wings removed from N68V BA-282 c86)	
			Blackhawk Airways, Janesville WI	1.94/95
			Gail Force Corp/ Gail Force Express, Beloit WI	10.1.97/00
			Catalina Flying Boats Inc, Long Beach CA	24.11.00/11
			op: Phoenix Airtransport, Phoenix AZ	01/02
			N103AF LLC, Englewood CO	21.1.12/14
			Point to Point LLC, Arlington WA	26.6.14/17
			emergency landing Ketchikan AK due power loss,	
			ditched in sea, sank near Ketchikan AK	3.3.17

N103AF noted Janesville-Rock County WI 7.91 "Blackhawk Airways", plate BA-526, built 5.60; N103AF noted Janesville-Rock County WI 7.97 op. Gail Force Express, no titles;

N103AF noted Janesville WI 26.7.99, landed, Gail Force;

Report 1.00: Gail Force Express operating Beech 18s on US Mail run Albany NY to Williamsport PA including N103AF rotating between maintenance at Blackhawk Airways, Janesville WI;

Report 6.00: Gail Force have ceased operations, all their Beech 18s have been flown to Rockford IL for resale;

N103AF noted Phoenix AZ 3.3.01 no titles;

N103AF noted Long Beach CA 29.4.01,

N103AF noted Long Beach CA 13.5.01 operated by Catalina Flying Boats;

N103AF noted Phoenix AZ 22.12.02 "Phoenix Airtransport" titles; N103AF noted Deer Valley AZ 4.03 "Phoenix Airtransport" titles; Deer Valley 22.5.08 no titles; N103AF noted Arlington WA 20.9.15, blue & white, tailwheel, in service with Point to Point on

N933GM	Grimes Manufacturing Co, Urbana OH	-
	Ladd Christiansen, Salt Lake City UT	79
	Madison Aviation Centre, London OH	79
	op: General Aviation Inc, Greenville TN	80
(N933GW)	ntu	
N933GM	Cape Air Leasing, Hyannis MA	12.81
	Gull Air, Hyannis MA & West Palm Beach FL	9.83/86
	Aviation One Inc	7.87
	GC & C Inc, Tampa FL	1.88
	Mark Thiem Enterprises Inc, Tampa FL	7.88
	Jim Hankins Air Service, Jackson MS	2.89
	Premium Allied Tool Inc, Owensboro KY	7.89/91
	Jim Hankins Air Service, Jackson MS	11.93
	Air Plans Inc, Dover DE	30.3.94/99
	Clyde Peters, Crete NE	98
	Carla J. Payne, Fort Worth TX	24.4.01/06
	Glen W. Ernst, Bend OR	31.1.07/15
	struck-off USCR	30.4.15
N933GM	Glen W.Ernst Estate, Bend OR: rest. to USCR	1.8.17/18
	Mid-Atlantic Aviation, New Castle DE	12.6.18/20

N933GM noted Montreal-Dorval QUE 23.8.74;

N933GM noted Palmer AK 8.94;

N933GM at fly-in Oshkosh 8.98 owned Clyde Peters, Lincoln NE, plate: BA-533 built 5.60;

N933GM at fly-in Oshkosh 26.7.01 tailwheel;

N933GM noted at ranch Slidell TX 9.5.03;

BA-534	G18S	N9990R	Beech Aircraft Corp, Wichita KS: CofA issued	9.6.60
			El Paso National Bank, El Paso TX	63/66
			Edward P. Mayer, Frontenac MO	69
			Malcolm Jacobs Aviation, Chesterfield MO	70
			Ross Aviation, Tulsa-Riverside OK	71/77
			Great Western Airlines, Tulsa OK	77/79
			Executive Aviation	85
			damaged, ran off runway on takeoff, Newark NJ	28.8.85
			K & K Aircraft Inc, Bridgewater VA	7.86
			KDW Schools Inc, Arlington TX	7.90/94
			L. H. Underwood & Son Aerial Patrol Inc, Guthrie OK	6.12.94
			sale rep.	98
			Douglas Durning, Oklahoma City OK	99
			Michael B. Ohlinger/ Sterling Air Service,	
			Weslaco-Mid Valley TX, later Mission TX	22.6.01/05
		N33KM	Michael B. Ohlinger, Mission TX	5.4.05/15
			Eckles Aircraft LLC, Weslaco TX	4.10.17/20

N9990R noted Chicago O'Hare IL 15.9.79 Great Western, retired stored;

N9990R accident report 28.8.85: owned Executive Aviation, freight flight;

N9990R at airshow Oklahoma City OK 20.6.98;

N9990R noted Weslaco TX 5.5.03;

N9990R noted Weslaco-Mid Valley Airport (near McAllen) 10.8.03 owned Michael Ohlinger of Sterling Air Service (also 3 freighter Queenairs): plate BA-534 built 6.60;

N33KM noted Weslaco TX 7.8.08;

BA-535	G18S	N530M	Marathon Oil Co, Findlay OH	.60/64
D/ ( 000	0100	N730M	Broughton Plant & Equipment Co, Parkersburg WV	66/72
			Midwest Air Charter, Elyria OH	74/79
			minor damage, landed gear-up, Philadelphia PA	10.12.74
			op: Airborne Express	79
			David K. Dill, Indianapolis IN	79
			Indianapolis Air Charter Services, Indianapolis IN crashed during takeoff, Indianapolis IN	17.9.82 17.9.82

N730M accident report 10.12.74: Midwest Air Charter, failed to extend gear, 12.10pm; N730M accident report 17.9.82: Indianapolis Air Charter, swerved on takeoff, left wing dug in, aircraft spun around, pilot unhurt;

BA-536	G18S	N674Q XB-JEM N67VQ N268AA	built Jack Adams Aircraft Sales, Walls MS reg reg Atlantic Aviation Corp, Wilmington DE N268AA Inc, Fort Lauderdale FL American Flag Airlines Inc, Fort Lauderdale FL Exuma Express sale reported: USCR Hill Air Co, Fort Lauderdale FL James E. Sheehan, Pompano Beach FL scrapped, struck-off USCR	.60 63 66/70 79 84/86 91 9.92 8.1.93/05 22.9.05
	N268AA not N268AA not N268AA not	ted Ft Lauder ted Ft Lauder	on-DCA 30.9.70; rdale FL 25.10.84; 23.8.87; rdale FL 5.92; rdale FL 21.1.98 retired, stored; rdale 4.4.01;	
BA-537			Transair Ltd, St James MAN Empire Leasing Corp, Montreal QUE Bradley Air Services Ltd, Carp ONT Bradley Air Services Ltd, Carp ONT Air 500, Toronto ONT struck-off Register  LTA 12.9.71 Bradley Air Service; MAN 17.4.79 visitor Bradley AS;	.60 65/66 70/76 76/85 87 3.89
	C-FTAE not C-FTAE not	ed Carp ONT ed Carp ONT	「8.80 "Bradley Air Services" titles, tailwheel; 「2.10.85 retired, Bradley AS; ∥O 3.4.87 Air 500;	
BA-538	G18S	N319Z N351WB N351WP	Beech Aircraft Corp, Wichita KS: CofA issued Great Lakes Pipe Line Co, Kansas City MO rereg Williams Bros Pipe Line Co, Tulsa OK landed gear-up, Okmulgee OK Kern Pump Co, Bakersfield CA Old River Crop Dusting Inc, Bakersfield CA Robert A. Younkin, Lowell AR John Dowd/ Syracuse Flying Service, Syracuse KS James Warren, Castle Rock CO, later Coeur d'Alene ID Big Sky EDM Inc, Hayden ID Gary B. Peters, Clarkston WA Forte Aviation Parts Inc, Fort Lauderdale FL sold to Brazil, struck-off USCR	7.7.60 63/64 66/69 2.6.69 70/79 3.82 2.86 1.90/92 13.7.93/14 22.10.14/17 27.4.17/18 5.12.19 12.2.20
	N351WP no Beech flyin N351WP at N351WP no N351WP at Castle Rock N351WP at N351WP at N351WP at N351WP at	nted Shafter-N Tullahoma TI Beech fly-in Beech fly-in Ited Janesvilli fly-in Oshkos CO, tailwhee fly-in Lakelar fly-in Arlingto Beech fly-in fly-in Arlingto	Aero Store Aviation Ltda eld-Meadows Field CA 20.4.72; Miner Field CA 28.4.84; N 16.10.94, tailwheel, Jim Warren, Castle Rock CO; Wichita KS 10.92 John & Sue Ann Dowd; Wichita KS 11.10.97 John & Sue Ann Dowd; e WI 26.7.99 en route Oshkosh, owned Jim Warren, Denvelsh 8.99, plate BA-538 built 6.60, Jim & Georgia Warren of	2.20
BA-539	G18S	N162DP N321	Beech Aircraft Corp, Wichita KS: CofA issued Federal Mogul Bower Bearings Inc, Detroit MI Semo Aviation Inc/ Semo Airways, Malden MO Farmington Airmotive Inc, Farmington MO	15.7.60 63/72 79/84 10.84

			Interstate Aviation, Farmington MO	7.88
			Bowman Aviation, Fort Wayne IN	2.91 10.90
			Ralph E. Pingel, Farmington MO Graves Aircraft Inc, El Reno OK	5.91
		N555CG	Graves Aircraft Inc, El Reno OK	6.91
			Grant Aviation, Emmonak AK	16.9.94/99
			damaged at Nome AK	21.3.97
			(fire under cockpit, extinguished with corrosive material	
			which caused severe corrosion)	00
			Bob Heckman, Anchorage AK (ferried to Anchorage for restoration by 00)	00
			Turbo North Aviation, Anchorage AK	00
			Angels of Mercy Ministries, Xenia OH	01/03
			Airplane Services Inc, Jay FL	27.2.03
			Lewis Flying & Maintenance Service, Morse LA	18.8.03
			James C. Bramel, Washington Court OH	27.8.04/05
			Lewis Flying & Maintenance Service, Morse LA reg expired 31.12.19, struck-off USCR	24.3.05/20 3.4.20
			ge-Merrill Field AK 8.94; Tullahoma TN 14.10.07;	
BA-540	G18S	N94D	Youngstown Airways/ Lease Air, Youngstown OH: CofA	18.7.60/66
		NO440	Beckett Aviation Corp, Youngstown OH	66
		N9412	rereg SMB Stage Line Inc, Des Moines IA	69/72
			Perkiomen Airways, Reading PA	9.76/97
			Christopher E. Poindexter, Lone Wolf OK	6.97/11
			struck-off USCR	4.1.11
	N9412 not	ted Chicago-O	'Hare 2.4.69 SMB Stage Lines;	
BA-541	G18S	N127BD	built	.60
		N172SG	Mayco Investments Inc, Wichita KS	63
			George H. Bailey Co, Fort Wayne IN	64
			D. L. Peterson Trust, Baltimore MD	66
			crashed into mountain, destroyed, Weston VT	19.3.68
BA-542	G18S	N5002T	Beech Aircraft Corp, Wichita KS: CofA issued	1.8.60
		N534D	Thiokol Chemical Corp, Bristol PA	63/64 66
		N334D	Wiles Holloway Inc, Baton Rouge LA Currey Sanders Aircraft Co, Shreveport LA	69/72
			Dale Jackson, Anchorage AK	79
			Harold W. Tobey, Anchorage AK	6.81
			Gordon Aviation, Anchorage AK	12.81/85
			Douglas R. Moran, Santa Ana CA	8.88/91
		N18DM	Douglas R. Moran, Santa Ana CA	5.91
			Theodore W. Hunt, Waldport OR D & D Air Transport, Houston TX	12.92 24.8.94
		N502DD	D & D Air Transport, Houston TX D & D Air Transport, Houston TX	24.8.94 12.94/95
		1100200	Christopher C. Cecil, Almont MI	20.8.97/06
			(flew in USAAC blue & red scheme)	<del>-</del>
			Florida Bahama Trading Co, Palm Beach FL	19.12.08/12
			Chart Air Inc, Fort Lauderdale FL	3.4.12/17
			Southern Cross Aviation, Wilmington DE	15.3.17
			Seven Stars Air Cargo Corp, Carolina, Puerto Rico	25.10.18/20
	N534D no		e-Merrill Field AK 9.79 windowless freighter, no titles; e-Merrill Field AK 10.7.85 Gordon Air Express; лі 7.97	
	N502DD r	noted Pontiac-	Oakland MI 25.8.02 in blue & red USAAC scheme; Fara Field GA 20.9.17, landed, blue & white, tailswheel;	
BA-543	G18S	N331Z	Beech Aircraft Corp, Wichita KS: CofA issued	15.8.60
			Bovaird Supply Co, Tulksa OK	63/64
			George H. Bailey Co, Fort Wayne IN	66
			•	

	Kinder Transportation Corp, Elkhart IN	69
	Kinder Manufacturing Co, Elkhart IN	70
	Donohoh & Sons Inc, Fort Smith AR	71/72
N79LA	Brennan & Hargreaves Inc, Bradley CT	76/79
	gear collapsed landing, Burlington VT	12.6.77
	Air Cape, Hyannis MA	80/81
	damaed in accident	23.5.81
	Ridder Air Enterprises, Whitman MA	6.81/83
	Blackhawk Airways, Janesville WI	1.84/85
	TELCO, Naperville IL	1.85
	M. Corley Tedder, Texarkana TX	10.87
	Thomas W. May, New Boston TX	8.88/91
	May Air Xpress, New Boston TX	30.7.91/03
	(retired, hulk stored Texarkana AR 98/03)	
	Steve Dean/ Flight of the Phoenix Aviation Museum,	
	Gilmer TX: hulk donated	.03
	(awaiting collection from Texarkana 8.03)	
	struck-off USCR	9.5.13

N79LA noted Dayton OH 27.5.76 "BH" titles;

N79LA accident report 12.6.77: Brennan & Hargreaves, flight from Hartford CT, intentional groundloop at end of runway, main left gear failed, pilot unhurt, 11.49am;

N79LA noted Hyannis MA 9.80 "Air Cape" in service, plate BA-543;

N79LA noted Texarkana AR 6.8.98 & 16.8.99: stripped hulk in compound with 2 other Beech 18s; N79LA noted Texarkana AR 2.8.02 still in compound off airport;

Tommy May donated his 2 E18S hulks at Texarkana to Steve Dean's museum .03, had not been collected by 8.03;

BA-544	G18S	N95D	Youngstown Airways/ Lease Air, Youngstown OH: CofA	15.8.60/66
		N9511	LOM Inc, Youngstown OH	69/72
		N999WG	Apollo Airways, Detroit MI	76/79
			renamed: Gelco Courier Services, Chicago IL	79
			Bryan P. Shaw, Signal Mountain TN	10.8.79
			(noted Barranquilla, Colombia 4.82 stored in	
			compound of impounded drug running aircaft)	
			struck-off USCR	1.7.13

N999WG noted Detroit-City MI 24.5.76;

N999WG noted Barranquilla Colombia 4.82 in impounded drug runners compound, derelict condition, yellow paint scheme, less engines and parts;

BA-545	G18S	N318M	built	.60
			R. L. Manning Co, Denver CO	63/66
			Alexander H. Smith, Baltimore MD	69
			Beeline Aviation, Colorado Springs CO	70
			Scientific Communications Inc, Chicago IL	12.8.70/71
			crashed destroyed after takeoff, Grand Canyon AZ	16.4.71

N318M accident report 16.4.71: flight Grand Canyon to Los Angeles, pilot turned into rising terrain, 257lb over gross weight, high density altitude, 5k;

BA-546	G18S	N9993R	built	.60
			Bendix Corp, South Bend IN	63/64
			Your Host Inc, Columbus OH	66
		N966YH	SMB Stage Line Inc, Des Moines IA	69/72
			Perkiomen Airways Ltd, Reading PA	9.76/97
			op: Sun International Airways, San Juan, Puerto Rico	.76/81
			struck by vehicle on ground, San Juan, puerto Rico	11.5.79
			damaged in ground-loop on landing, San Juan	28.1.81
			Christopher E. Poindexter, Lone Wolf OK	6.97/11
			struck-off USCR	4.1.11

N966YH accident report 11.5.79: Perkiomen Airways: flight Aguadilla PR to San Juan, taxying after landing 6.11am, pilot & 10 pax unhurt;

N966YH accident report 28.1.81: Sun International, flight St Thomas USVI-San Juan PR, pilot and 9 pax unhurt;

Russell Stover Candies Inc, Kansas City MO Grimes Manufacturing Co, Urbana OH N932GM Grimes Manufacturing Co, Urbana OH Johnson Welded Products, Urbana OH op: General Aviation Inc, Greenville TN Madison Aviation Centre, London OH WCW Corp, Midland TX Wood Flying Service, Laredo TX Isd: Viking Express, Chicago-Midway IL struck-off USCR  A-548 G18S N9991R Beech Aircraft Corp, Wichita KS: CofA issued Southern Ohio Aviation Sales, West Carrollton OH 69 70/72 79 79 80 80 80 81.82 81.82 89 11.9.13	2/13
N932GM Grimes Manufacturing Co, Urbana OH 70/72 Johnson Welded Products, Urbana OH 79 op: General Aviation Inc, Greenville TN 80 Madison Aviation Centre, London OH 80 WCW Corp, Midland TX 5.82 Wood Flying Service, Laredo TX 9.11.82 Isd: Viking Express, Chicago-Midway IL 89 struck-off USCR 11.9.13	2/13
Johnson Welded Products, Urbana OH op: General Aviation Inc, Greenville TN 80 Madison Aviation Centre, London OH WCW Corp, Midland TX 5.82 Wood Flying Service, Laredo TX 9.11.82 Isd: Viking Express, Chicago-Midway IL 89 struck-off USCR 11.9.13  A-548 G18S N9991R Beech Aircraft Corp, Wichita KS: CofA issued 2.9.60	2/13
op: General Aviation Inc, Greenville TN  Madison Aviation Centre, London OH  WCW Corp, Midland TX  Wood Flying Service, Laredo TX  Isd: Viking Express, Chicago-Midway IL  struck-off USCR  11.9.13  A-548 G18S N9991R Beech Aircraft Corp, Wichita KS: CofA issued  2.9.60	2/13
Madison Aviation Centre, London OH  WCW Corp, Midland TX  Wood Flying Service, Laredo TX  Isd: Viking Express, Chicago-Midway IL  struck-off USCR  M-548 G18S  N9991R  Beech Aircraft Corp, Wichita KS: CofA issued  2.9.60	2/13
WCW Corp, Midland TX  Wood Flying Service, Laredo TX  Isd: Viking Express, Chicago-Midway IL  Struck-off USCR  A-548 G18S  N9991R  Beech Aircraft Corp, Wichita KS: CofA issued  2.9.60	2/13
Wood Flying Service, Laredo TX Isd: Viking Express, Chicago-Midway IL 89 89 811.9.13  A-548 G18S N9991R Beech Aircraft Corp, Wichita KS: CofA issued 2.9.60	2/13
Isd: Viking Express, Chicago-Midway IL 89 struck-off USCR 11.9.13  A-548 G18S N9991R Beech Aircraft Corp, Wichita KS: CofA issued 2.9.60	2/13
A-548 G18S N9991R Beech Aircraft Corp, Wichita KS: CofA issued 2.9.60	
A-548 G18S N9991R Beech Aircraft Corp, Wichita KS: CofA issued 2.9.60	
• • • • • • • • • • • • • • • • • • •	3
Southern Ohio Aviation Sales, West Carrollton OH 63/64	
N711Y (3 Terminal Transport Co, Indianapolis IN 66	
N9991R rereg .66	
N18C Commercial Motor Freight, Indianapolis IN 69/72	
N18CK rereg	
N1800L rereg 5.77	
Cannavo Aviation, Philadelphia PA 79	
op: General Aviation, Greenville TN 81	
NMC Associates, Arden NC 12.81	
American Jet Leasing, Chicago IL 8.84	
James Carner, Fairbanks AK 5.89	
Auburn Flying Service, Auburn CA 1.90/9 <sup>-1</sup>	1
Simpsons Alaska Flocations Inc, Dover DE 4.93/99	5
Arizona Beech Boys Corp, Scottsdale AZ 27.2.9	5/96
reg. pending, Norman OK 98	
Wild Blue Yonder Inc, Goldsby OK 18.3.99	9/01
ran off runway on takeoff, Taos NM 6.7.00	
N181WB Wild Blue Yonder Inc, Goldsby OK 4.4.01/	/11
sold to Australian syndicate 7.11	
VH-NWB Neville Pringle, Sydney NSW 22.11.	11/12
(due to depart CA on ferry to Australia 15.2.12)	
dam. when ran off runway on takeoff for testflight,	
Hollister CA 14.2.12	
(VH-NWB noted dism. in parts yard, Hollister CA 8.14)	2

N18C noted San Antonio TX 16.5.73;

N1800L noted William AZ airshow 10.96: plate BA-548 built 8.60;

N1800L advertised for sale 4.97 hangared Scottsdale AZ, excellent condition, contact Curtis Clark; 6.7.00 accident report: owned Wild Blue Yonder Inc, Goldsby OK: FAA inspector giving PPL instruction, ran off runway on takeoff Taos NM: lower right tailplane and rudder damaged, wing skin wrinkled and right main tyre blew out;

N181WB noted Chickasha OK 6.10.02 tailwheel, in service;

N181WB noted Taos NM 7.10.03 in service, tailwheel, brown & white;

Windward Aviation list Be18 VH-NWB as a pending ferry to Australia December 2011, planned to be based at Wedderburn airfield near Sydney;

VH-NWB noted Hollister CA dism. damaged aircraft compound 17.8.14, brown & cream paint

scheme;

BA-549	G18S	N299AA	reg	.60
	trigear	N37P N376U	Pure Oil Co, Palatine IL rereg	63/64
		N876U	Jim Hankin Air Service, Jackson MS	69/72
			Brennan Air Freight Inc, Clintonville WI City of Wasau minor structural damage, cargo door opened on	79
			approach, Clintonville WI	9.3.79
			Sair Aviation/ Sair Air Freight, Syracuse NY crashed destroyed on takeoff, Syracuse NY	.80/83 24.10.83

N876U noted Milwaukee WI 3.7.79 Brennan Air Freight; accident report 9.3.79: quoted as "N847U": Brennan Air Freight, flight Milwaukee WI to Clintonville WI, aft cargo door opened, 11pm, pilot unhurt: assumed this acft; N876U noted Syracuse NY 9.8.80 "Sair Air Freight" titles;

DA 550	C198	N0212V	Pageh Aircraft Corn, Wighita KS: CofA issued	15.0.60
BA-550	G18S	N9312Y	Beech Aircraft Corp, Wichita KS: CofA issued White Motor Co, Cleveland OH	15.9.60 63/66
			SMB Stage Line Inc, Des Moines IA	69/72
			Perkiomen Airways, Reading PA	79
			Sun International, San Juan, Puerto Rico	80
			Air Pennsylvania	80
			Aurora Air Service, Fairbanks AK	9.83/85
			Ed Begley, Glasgow KY	10.85
			McNeely Charter Service, Earle AR	12.87
			Nighthawk Express, Mankato KS	2.89/91
			May Air Xpress, New Boston TX	5.5.94/97
			crashed destroyed, Crosbytown TX	6.10.97
			ed San Juan PR on pax services; a, Puierto Rico 8.80, tailwheel in service, op by Sun Inter	national;
BA-551	G18S	N4353Z	built	.60
D/ ( 00 1	0100	N353Z	Air Ferry International, Pacific Palisades CA	28.10.60
		140002	sold to Japan, struck-off USCR	22.11.60
		JA5503	reg	11.60
		0/1000	Maritime Safety Board, Kagoshima	65
			Maritime Safety Agency, Kagoshima  Maritime Safety Agency, Kagoshima	70/80
			Ken-Ichi Azuma	81
			retired, struck-off Register	11.4.81
	JA5503 n	oted Chofu 13 oted Kagoshir oted Kagoshir		
BA-552	JA5503 n	oted Kagoshir	ma 30.10.72,	3.10.60
BA-552	JA5503 n JA5503 n G18S	oted Kagoshir oted Kagoshir	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window,	3.10.60
BA-552	JA5503 n JA5503 n G18S Junior	oted Kagoshir oted Kagoshir N9300Y	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles)	
BA-552	JA5503 n JA5503 n G18S	oted Kagoshir oted Kagoshir	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX	63/69
BA-552	JA5503 n JA5503 n G18S Junior	oted Kagoshir oted Kagoshir N9300Y	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX	63/69 1.5.68
BA-552	JA5503 n JA5503 n G18S Junior	oted Kagoshir oted Kagoshir N9300Y	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA	63/69 1.5.68 70/72
BA-552	JA5503 n JA5503 n G18S Junior	oted Kagoshir oted Kagoshir N9300Y	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA National Equipment Rental Ltd, Hyde Park NY	63/69 1.5.68 70/72 79
BA-552	JA5503 n JA5503 n G18S Junior	oted Kagoshir oted Kagoshir N9300Y	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA National Equipment Rental Ltd, Hyde Park NY Air Best de Puerto Rico, San Juan, Puerto Rico	63/69 1.5.68 70/72 79 79
BA-552	JA5503 n JA5503 n G18S Junior	oted Kagoshir oted Kagoshir N9300Y N9967L	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA National Equipment Rental Ltd, Hyde Park NY Air Best de Puerto Rico, San Juan, Puerto Rico Air Limo of Florida Inc, Miami FL	63/69 1.5.68 70/72 79 79 1.10.80/86
BA-552	JA5503 n JA5503 n G18S Junior	oted Kagoshir oted Kagoshir N9300Y	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA National Equipment Rental Ltd, Hyde Park NY Air Best de Puerto Rico, San Juan, Puerto Rico Air Limo of Florida Inc, Miami FL Air Limo of Florida Inc, Miami FL	63/69 1.5.68 70/72 79 79 1.10.80/86 18.4.86/04
BA-552	JA5503 n JA5503 n G18S Junior	oted Kagoshir oted Kagoshir N9300Y N9967L	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA National Equipment Rental Ltd, Hyde Park NY Air Best de Puerto Rico, San Juan, Puerto Rico Air Limo of Florida Inc, Miami FL Air Limo of Florida Inc, Miami FL Paradise Aircraft Sales, Murrieta CA	63/69 1.5.68 70/72 79 79 1.10.80/86 18.4.86/04 29.11.04/05
BA-552	JA5503 n JA5503 n G18S Junior	oted Kagoshir oted Kagoshir N9300Y N9967L	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA National Equipment Rental Ltd, Hyde Park NY Air Best de Puerto Rico, San Juan, Puerto Rico Air Limo of Florida Inc, Miami FL Air Limo of Florida Inc, Miami FL Paradise Aircraft Sales, Murrieta CA Larry G. Bentley, Corona CA	63/69 1.5.68 70/72 79 79 1.10.80/86 18.4.86/04 29.11.04/05 15.4.05/06
3A-552	JA5503 n JA5503 n G18S Junior	oted Kagoshir oted Kagoshir N9300Y N9967L	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA National Equipment Rental Ltd, Hyde Park NY Air Best de Puerto Rico, San Juan, Puerto Rico Air Limo of Florida Inc, Miami FL Air Limo of Florida Inc, Miami FL Paradise Aircraft Sales, Murrieta CA Larry G. Bentley, Corona CA Chino Aircraft Sales Inc, Chino CA	63/69 1.5.68 70/72 79 79 1.10.80/86 18.4.86/04 29.11.04/05 15.4.05/06 10/18
BA-552	JA5503 no JA5503 no G18S Junior JATO	oted Kagoshir oted Kagoshir N9300Y N9967L N5722T	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA National Equipment Rental Ltd, Hyde Park NY Air Best de Puerto Rico, San Juan, Puerto Rico Air Limo of Florida Inc, Miami FL Air Limo of Florida Inc, Miami FL Paradise Aircraft Sales, Murrieta CA Larry G. Bentley, Corona CA Chino Aircraft Sales Inc, Chino CA reg expired, struck-off USCR	63/69 1.5.68 70/72 79 79 1.10.80/86 18.4.86/04 29.11.04/05 15.4.05/06
BA-552	JA5503 no JA5503 no G18S Junior JATO	oted Kagoshir oted Kagoshir N9300Y N9967L N5722T	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA National Equipment Rental Ltd, Hyde Park NY Air Best de Puerto Rico, San Juan, Puerto Rico Air Limo of Florida Inc, Miami FL Air Limo of Florida Inc, Miami FL Paradise Aircraft Sales, Murrieta CA Larry G. Bentley, Corona CA Chino Aircraft Sales Inc, Chino CA reg expired, struck-off USCR	63/69 1.5.68 70/72 79 79 1.10.80/86 18.4.86/04 29.11.04/05 15.4.05/06 10/18
BA-552	JA5503 no JA5503 no G18S Junior JATO N9967L no N9967L no	oted Kagoshir oted Kagoshir N9300Y N9967L N5722T oted St Thomoted Opa Loc	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA National Equipment Rental Ltd, Hyde Park NY Air Best de Puerto Rico, San Juan, Puerto Rico Air Limo of Florida Inc, Miami FL Air Limo of Florida Inc, Miami FL Paradise Aircraft Sales, Murrieta CA Larry G. Bentley, Corona CA Chino Aircraft Sales Inc, Chino CA reg expired, struck-off USCR  as USVI 13.5.78; ka FL 10.84;	63/69 1.5.68 70/72 79 79 1.10.80/86 18.4.86/04 29.11.04/05 15.4.05/06 10/18
BA-552	JA5503 no JA5503 no G18S Junior JATO N9967L no N9967L no N5722T no	oted Kagoshir oted Kagoshir N9300Y N9967L N5722T Toted St Thomoted Opa Located	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA National Equipment Rental Ltd, Hyde Park NY Air Best de Puerto Rico, San Juan, Puerto Rico Air Limo of Florida Inc, Miami FL Air Limo of Florida Inc, Miami FL Paradise Aircraft Sales, Murrieta CA Larry G. Bentley, Corona CA Chino Aircraft Sales Inc, Chino CA reg expired, struck-off USCR  as USVI 13.5.78; ka FL 10.84; ka FL 22.3.87;	63/69 1.5.68 70/72 79 79 1.10.80/86 18.4.86/04 29.11.04/05 15.4.05/06 10/18 8.6.18
BA-552	JA5503 nr. JA5503 nr. G18S Junior JATO  N9967L nr. N9967L nr. N5722T nr. N5722T nr.	N9300Y N9967L N5722T Noted St Thompoted Opa Located Opa Located Corona (a) of the colored Corona (b) of the colored Corona (c) of the colored Corona	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA National Equipment Rental Ltd, Hyde Park NY Air Best de Puerto Rico, San Juan, Puerto Rico Air Limo of Florida Inc, Miami FL Air Limo of Florida Inc, Miami FL Paradise Aircraft Sales, Murrieta CA Larry G. Bentley, Corona CA Chino Aircraft Sales Inc, Chino CA reg expired, struck-off USCR  as USVI 13.5.78; ka FL 10.84; ka FL 22.3.87; CA 19.8.05 plate BA-522 built 9.60 "Trans Islands" for sa	63/69 1.5.68 70/72 79 79 1.10.80/86 18.4.86/04 29.11.04/05 15.4.05/06 10/18 8.6.18
BA-552	JA5503 nr. JA5503 nr. JA5503 nr. G18S  Junior JATO  N9967L nr. N9967L nr. N5722T nr. N5722T nr. N5722T nr.	N9300Y  N9300Y  N9967L  N5722T  Noted St Thomoted Opa Located Opa Located Corona (acted Corona (acte	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA National Equipment Rental Ltd, Hyde Park NY Air Best de Puerto Rico, San Juan, Puerto Rico Air Limo of Florida Inc, Miami FL Air Limo of Florida Inc, Miami FL Paradise Aircraft Sales, Murrieta CA Larry G. Bentley, Corona CA Chino Aircraft Sales Inc, Chino CA reg expired, struck-off USCR  as USVI 13.5.78; ka FL 10.84; ka FL 22.3.87; CA 19.8.05 plate BA-522 built 9.60 "Trans Islands" for sa CA 2.2.06;	63/69 1.5.68 70/72 79 79 1.10.80/86 18.4.86/04 29.11.04/05 15.4.05/06 10/18 8.6.18
BA-552	JA5503 nr. JA5503 nr. JA5503 nr. G18S  Junior JATO  N9967L nr. N9967L nr. N5722T nr. N5722T nr. N5722T nr. N5722T nr.	N9300Y  N9300Y  N9967L  N5722T  N5722T  Noted St Thom oted Opa Located Corona (acted Corona coted Corona (acted Corona coted Corona (acted Corona coted Corona (acted Coro	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA National Equipment Rental Ltd, Hyde Park NY Air Best de Puerto Rico, San Juan, Puerto Rico Air Limo of Florida Inc, Miami FL Air Limo of Florida Inc, Miami FL Paradise Aircraft Sales, Murrieta CA Larry G. Bentley, Corona CA Chino Aircraft Sales Inc, Chino CA reg expired, struck-off USCR  as USVI 13.5.78; ka FL 10.84; ka FL 22.3.87; CA 19.8.05 plate BA-522 built 9.60 "Trans Islands" for sa CA 2.2.06; 11.06 small "Trans Islands" titles;	63/69 1.5.68 70/72 79 79 1.10.80/86 18.4.86/04 29.11.04/05 15.4.05/06 10/18 8.6.18
BA-552	JA5503 nr. JA5503 nr. JA5503 nr. G18S  Junior JATO  N9967L nr. N9967L nr. N5722T nr. N5722T nr. N5722T nr. N5722T nr. N5722T nr. N5722T nr.	N9300Y  N9300Y  N9967L  N5722T  N5722T  Noted St Thomoted Opa Located Corona (acted Corona cotted Corona (acted Corona cotted Corona (acted Corona cotted Corona (acted Co	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA National Equipment Rental Ltd, Hyde Park NY Air Best de Puerto Rico, San Juan, Puerto Rico Air Limo of Florida Inc, Miami FL Air Limo of Florida Inc, Miami FL Paradise Aircraft Sales, Murrieta CA Larry G. Bentley, Corona CA Chino Aircraft Sales Inc, Chino CA reg expired, struck-off USCR  as USVI 13.5.78; ka FL 10.84; ka FL 22.3.87; CA 19.8.05 plate BA-522 built 9.60 "Trans Islands" for sa CA 2.2.06;	63/69 1.5.68 70/72 79 79 1.10.80/86 18.4.86/04 29.11.04/05 15.4.05/06 10/18 8.6.18
BA-552	JA5503 nr. JA5503 nr. JA5503 nr. G18S  Junior JATO  N9967L nr. N9967L nr. N5722T nr. N5722T nr. N5722T nr. N5722T nr. N5722T nr. N5722T nr.	N9300Y  N9300Y  N9967L  N5722T  N5722T  Noted St Thomoted Opa Located Corona (acted Corona cotted Corona (acted Corona cotted Corona (acted Corona cotted Corona (acted Co	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA National Equipment Rental Ltd, Hyde Park NY Air Best de Puerto Rico, San Juan, Puerto Rico Air Limo of Florida Inc, Miami FL Air Limo of Florida Inc, Miami FL Paradise Aircraft Sales, Murrieta CA Larry G. Bentley, Corona CA Chino Aircraft Sales Inc, Chino CA reg expired, struck-off USCR  as USVI 13.5.78; ka FL 10.84; ka FL 22.3.87; CA 19.8.05 plate BA-522 built 9.60 "Trans Islands" for sa CA 2.2.06; 11.06 small "Trans Islands" titles; A 17.7.08, 3.11 blue & white, no titles, in service; A 18.7.16, faded paint blue & white, no titles; Chino 17.7.	63/69 1.5.68 70/72 79 79 1.10.80/86 18.4.86/04 29.11.04/05 15.4.05/06 10/18 8.6.18
	JA5503 nr. JA5503 nr. JA5503 nr. G18S  Junior JATO  N9967L nr. N9967L nr. N5722T nr. N5722T nr. N5722T nr. N5722T nr. N5722T nr.	N9300Y  N9300Y  N9967L  N5722T  N5722T  Noted St Thomeoted Opa Located Opa Located Corona (noted Corona (noted Chino Coroted Chino Chi	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA National Equipment Rental Ltd, Hyde Park NY Air Best de Puerto Rico, San Juan, Puerto Rico Air Limo of Florida Inc, Miami FL Air Limo of Florida Inc, Miami FL Paradise Aircraft Sales, Murrieta CA Larry G. Bentley, Corona CA Chino Aircraft Sales Inc, Chino CA reg expired, struck-off USCR  as USVI 13.5.78; ka FL 10.84; ka FL 22.3.87; CA 19.8.05 plate BA-522 built 9.60 "Trans Islands" for sa CA 2.2.06; 11.06 small "Trans Islands" titles; A 17.7.08, 3.11 blue & white, no titles, in service;	63/69 1.5.68 70/72 79 79 1.10.80/86 18.4.86/04 29.11.04/05 15.4.05/06 10/18 8.6.18
	JA5503 nr. JA5503 nr. JA5503 nr. G18S  Junior JATO  N9967L nr. N9967L nr. N5722T nr. N5722T nr. N5722T nr. N5722T nr. N5722T nr.	N9300Y  N9300Y  N9967L  N5722T  N5722T  Noted St Thomeoted Opa Located Opa Located Corona (noted Corona (noted Chino Coroted Chino Chi	ma 30.10.72, ma 28.3.80;  Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window, also Junior JATO units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA National Equipment Rental Ltd, Hyde Park NY Air Best de Puerto Rico, San Juan, Puerto Rico Air Limo of Florida Inc, Miami FL Air Limo of Florida Inc, Miami FL Paradise Aircraft Sales, Murrieta CA Larry G. Bentley, Corona CA Chino Aircraft Sales Inc, Chino CA reg expired, struck-off USCR  as USVI 13.5.78; ka FL 10.84; ka FL 22.3.87; CA 19.8.05 plate BA-522 built 9.60 "Trans Islands" for sa CA 2.2.06; 11.06 small "Trans Islands" titles; A 17.7.08, 3.11 blue & white, no titles, in service; A 18.7.16, faded paint blue & white, no titles; Chino 17.7.  Societe Schneider et Compagnie., Paris-Le Bourget	63/69 1.5.68 70/72 79 79 1.10.80/86 18.4.86/04 29.11.04/05 15.4.05/06 10/18 8.6.18

F-BJLC visited Gatwick 8.1.61, 6.7.61;

F-BJLC visited Gatwick 8.1.61, 6.7.61;
F-BJLC visited Le Bourget 6.63;
F-BJLC visited London-Heathrow 30.10.63 & 14.11.63 both op Taxis Aeriens Mercure;
F-BJLC visited Dublin 23.1.65, Escadrille Mercure, charter from Paris for football match;
F-BJLC visited Gatwick 16.11.65 to Castle Donnington;
F-BJLC noted Paris 6.67;

BA-554	G18S	N411UM	built	.60
		N56K (2	Weyerhaeuser Co, Tacoma WA	9.2.62/66
			landed gear-up, Chicago-O'Hare IL	17.3.66
		N753K	Weyerhaeuser Co, Gig Harbour WA	69/70
			exported to Philippines, struck-off USCR	22.5.70
		PI-C1975	reg	.70
		RP-C1975	Philippine Flour Mills, Manila	78
			Greenbelt Products Inc, Manila	80/81
			Central Bank of Philippines, Manila	90
BA-555	G18S	N901TC	built	.60
		N901T (2	rereg	
			Investment Securities Co, Wilmington DE	63/64
		N901PC	Preston Ester, St Louis MO	66/70
			Bank of St Louis, St Louis MO	71/72
			Festus Flying Service, Festus MO	23.2.77/78

N901PC accident report 16.11.78: Festus Flying Service, cargo flight Wichita KS to Hays KS, spun in on approach, freezing drizzle, 3am: pilot & 1 pax k;

BA-556	G18S	N153X	built	10.60
		N625W	Stuart Investment Co, Lincoln NE	63/66
		N625G	rereg	
		N621NU	University of Nebraska, Lincoln NE	69/70
		N621KE	N. E. Isaacson & Associates, Reedsburg WI	71/72
			Viking International Airlines, Minneapolis MN	79
			Burl-Air Freight Inc, Burlington WI	79/82
			James R. Beardsley/ Crystal Lake School of Aviation,	
			Crystal Lake IL	11.82/83
			K & K Aviation, Bridgewater VA	.83
			rep. op by Alliance Airlines, Kenosha WI	84
			TELCO, Naperville IL	1.85
			op: Viking Express, Chicago-Midway IL	87
			Thomas W. May, New Boston TX	10.87/94
			May Air Xpress, New Boston TX	21.3.94/99
			Beech Transportation, Eden Prairie MN	27.4.99
			crashed on takeoff, Minneapolis-St Paul MN	23.7.99
			(wreck stored St Paul-Flying Cloud MN 00)	

N621KE noted Lexington KY 9.79 no titles, tailwheel;

N621KE noted DuPage IL 8.87 Viking Express;

N621KE noted Atlanta TX 10.87 plate BA-556;

N621KE noted Texarkana AR 8.97 in service May Air Xpress: plate BA-556 built 10.60; accident report 23.7.99: May Air Xpress, tailwheel undercarriage, pilot positioned from Flying Cloud to Minneapolis 5.15am for flight to Duluth MN, right engine lost power airborne at MSP at 7.20AM, attempted to return, heavy landing, ran off runway, gear collapsed, skidded to side of runway;

BA-557	G18S	N9308Y	built	.60
		N607RP	Ralston Purina Co, Chesterfield MO	63/69
		N807P	P. R. Insulation Ltd, Houston TX	70/72
	Hamilton		PCD Corp, McAllen TX	24.3.78/89
	extended		struck drainage ditch on takeoff, McAllen TX	5.7.78
	nose	RP-C986	Metro Manila Airways, Manila	.89/91
			Charles R. Miller/ CM Aero, Manila	93/98
			J. G. Gomez, Clark Field	.00
			(in service 03, with Hamilton long-nose mod)	

N807P accident report 5.7.78: flight McAllen to Tampico, Mexico, aborted takeoff due power loss, 5am, "destroyed", 2 unhurt;

RP-C986 noted Manila 2.1.94 tailwheel, standard nose, white with red trim;

RP-C986 noted Manila 4.2.98 tailwheel, Hamilton long cargo nose, at CM Aero ramp;

RP-C986 noted Manila 5.03 tailwheel, Hamilton long cargo nose, at CM Aero ramp,

doors open operational, white with red trim;

G18S	N2222X	Beech Aircraft Corp, Wichita KS: CofA issued	2.11.60
trigear		Robert Graf Inc, Tarkio MO	63
		Thompson Tractor Co, Birmingham AL	64
	N2222K	rereg	
	N1031B (1	Mack Trucks Inc, Somerville NJ	66
	N10313	Jim Hankins Air Service, Jackson MS	69/72
		nose gear collapsed landing, Boulder City NV	25.2.74
		Stephen Wilmans, Las Vegas NV	79
		Aristera Co, Lubbock TX	8.9.78
		sale rep.	91
		trigear N2222K N1031B (1	trigear  Robert Graf Inc, Tarkio MO Thompson Tractor Co, Birmingham AL rereg N1031B (1 Mack Trucks Inc, Somerville NJ N10313 Jim Hankins Air Service, Jackson MS nose gear collapsed landing, Boulder City NV Stephen Wilmans, Las Vegas NV Aristera Co, Lubbock TX

N10313 accident report 25.2.74: nose gear did not fully extend due mechanical fault;

BA-559	G18S	N96D	Youngstown Airways/ Lease Air Inc, Youngstown OH	10.60
			Wean Engineering Co, Warren OH	1.61/64
		N9611	Youngstown Airways/ Lease Air Inc, Youngstown OH	4.65/66
			Bailey Leasing Corp, Fort Wayne IN	3.67
	ATE	N961GP	Georgia Pacific Corp, Augusta GA & Portland OR	6.67/71
	Westwind III		(converted by American Turbine Engine Co,	
			Long Beach CA 9.68 as the sole ATE Westwind III,	
			PT-6A-20s with conventional tailwheel, TT 4782 hrs)	
			Hamilton Aircraft Co, Tucson AZ	7.71
			SMB Stage Line Inc. Des Moines IA	21.7.71/85
	Hamilton		(rebuilt as <i>Hamilton Westwind III</i> 9.74 with tailwheel,	
	Westwind III	1	Hamilton Extended Nose, 11230 lb AUW kit,	
		•	and Hamilton cargo door)	
			Jarex Corp, Columbus IN	9.85
			Jet Way Enterprises Inc, Willow Run MI	11.85
			Ajax Aircraft Leasing Inc, Dover DE	6.87
			Isd: Active Aero Charter, Willow Run MI	.87/89
			Ken & Karl Stoltzfus/K & K Aircraft Inc, Bridgewater VA	3.91/08
			(agricultural & pest sprayer)	0.01/00
			Suncoast Air Cargo LLC, Palm City FL	29.4.08/12
			Skydive Greene County, Xenia OH	6.3.13
		N74C I		19.6.13/20
		N74GJ	Skydive Greene County, Xenia OH	19.0.13/20

further details see Beech 18 by Robert Parmerter p.335;

N96D visited Toronto ONT 23.4.64;

N961GP notyed Port Columbus IN 26.5.76, Westwind III, "SMB Stage Line";

N961GP noted Des Moines IA 26.8.80 Westwind III tailwheel, "SMB Stage Line" titles;

N961GP noted Willow Run MI 3.8.89, Active Aero Charter;

N961GP advertised for sale 11.90: Westwind III tailwheel;

N961GP noted Los Alamitos CA 17.8.99 Westwind III, plate BA-559 built 10.60,

"K & K Aircraft" titles, sprayer;

N961GP noted Los Alamitos CA 13.8.02 with other K&K sprayers;

BA-560	G18S	N847B	Beech Aircraft Corp, Wichita KS: CofA issued	22.11.60
			American Republic Insurance Co, Des Moines IA	63/66
			SMB Stage Line Inc, Des Moines IA	69/78
			Blackhawk Airways, Janesville WI	80/84
			J. Richard Wixom/ Blackhawk Airways, Janesville WI	10.84/86
			General Air Service, Valley City MD	6.89/91
			North Atlantic Seafood, New Middletown OH	2.92
			Alvin H. Dill, New Middletown OH	7.93/97
			Charles H. Hainline, Albany OR	6.97/02
			Anthony R. L. Quadrani, Sagola MI	31.3.03/04
		N727AV (2	Anthony R. L. Quadrani, Sagola MI	8.12.04/06
		`	Sport Truck LLC, Coldwater MI	4.1.10/11
			Aircraft & Aviation Professionals LLC, Coldwater MI	31.1.12/16
			Zulu Forty One Inc, Anchorage AK	17.1.17/20

N847B noted Jacksonville-Herlong FL 19.8.98, "Hail Lines - Slow but Costly" titles, plate: BA-560 built 11.60; Charles Hainline was setting up P-2 tanker business; N847B noted Alamogordo NM 28.2.05 "Hain Lines" titles, in service;

BA-561	G18S	N9321Y	Beech Aircraft Corp, Wichita KS: CofA issued	15.11.60
		N511WP (2	West Point Manufacturing Co, La Grange GA	63
		N511W (2	West Point Manufacturing Co, La Grange GA	64/69
			Abrams Aerial Surveys, Lansing MI	70/79
			Wayne Sturman Aircraft Sales, Merritt Island FL	10.81/06
			struck-off USCR	17.8.06

N511W noted Albany NY 17.11.75 tailwheel;

BA-562	G18S	N273V	built	.60
			Wilcox Electric Co, Kansas City MO	63
			Cabot Corp, Pampa TX	64/66
			Henry O. Moffett Co, Centreport NY	69/70
		8P-ECA	Eastern Caribbean Airlines, Seawell	6.71/74
		N273V	reg	.74
			William Mitchell	77/77
			crashed destroyed near Aero Oasis Airport FL	20.8.77

N273V noted Bridgetown, Barbados 8.12.68;

N273V noted Opa Locka FL 27.5.70 panoramic windows;

8P-ECA noted Opa Locka FL 18.6.73,

8P-ECA noted Opa Locka FL 7.10.73;

N273V accident report 20.8.77: stalled on climb for parachuting from Aero Oasis, planned flight to Immokalee FL, 953lb over MAUW, CofG beyond after limit, auto gasoline being used, sod strip, 1 k, 1 serious, 9 minor injuries;

BA-563	G18S	N470T	Beech Aircraft Corp, Wichita KS	2.12.60
			sold to Switzerland, struck-off USCR	27.12.60
		F-BERT	Ste Automobiles M.Berliet, Lyon-Bron	26.1.61/68
			Ste des Entereprises H. Courbot, Montrouge	26.3.68
			Ste Avia Taxi, Paris	19.12.68/78
			Struck-off Register	19.10.78
			(stored dism. at La Ferte-Alais 00/11)	

F-BERT arrived Birmingham 9.1.61 ex Prestwick, to Gatwick next day,

F-BERT displayed at Paris Air Show, Le Bourget 3.6.61 with E18S N34L;

F-BERT visited Gatwick 14.4.61;

F-BERT arrived Perpignan ex Lyon 13.12.61 Automobile Berliet;

F-BERT visited Gatwick 24.9.62, Manchester 24-26.9.62; Cambridge 24.10.62 Automobile Berliet;

F-BERT visited Edinburgh-Turnhouse 8.7.63 Automobile Berliet;

F-BERT noted London-Gatwick 17.2.64, 9.9.64, 30.9.64;

F-BERT noted Glasgow 10.9.64 Automobiles Berliet, to Woolsington, plate BA-563;

F-BERT arrived Elmdon 28.4.65 ex Paris

F-BERT visited Southend 1.6.65 Berliet, from Lyons to Barkstone Heath;

F-BERT arrived Southend 30.6.65 Berliet, from Lyons to Cambridge;

F-BERT noted Palma Majorca 25.8.66;

F-BERT noted Gatwick 9.12.66;

F-BERT visited Amsterdam 10.1.68;

F-BERT visited London-Heathrow 22.2.68; Amsterdam-Schiphol 28.6.68;

Reportedly retired 10.2.69;

F-BERT major components noted at La Ferte-Alais 3.9.00;

BA-564	G18S	N9375Y	Beech Aircraft Corp, Wichita KS: CofA issued	7.12.60
			J. R. Gray Co, Dallas TX	63
			William H. Ball, Indianapolis IN	64
			Bailey Leasing Corp, Fort Wayne IN	66
			Ohio Valley Riggers & Erectors Inc, Dayton OH	69/72
			Aero Services Inc	76
			HNT Corp, Sherman Oaks CA	79
			Air Cortez International, Ontario CA	.79/84
			Able Computer, Irvine CA	4.84
			Union Flights, Sacramento CA	11.86
			Aeronautical Services Inc, Friday Harbour WA	20.4.89/99
			op: Catalina Flying Boats, Long Beach CA	89/99

minor damage on takeoff, Long Beach CA	23.11.98
Catalina Flying Boats Inc, Long Beach CA	28.6.99/06
op: Phoenix Airtransport, Phoenix AZ	.02
Nord Aviation, Santa Teresa NM	18.9.07/20

N9375Y noted Washington-DCA 30.9.70;

N9375Y noted Kansas City-Fairfax MO 3.6.76 "Aero Services Inc" titles;

N9375Y noted Ontario CA 6.1.83 "Air Cortez International" titles;

N9375Y noted San Diego CA 4.83 "Air Cortez" titles, tailwheel, in service;

83 report: N9275Y with Air Cortez International, based Las Vegas NV 10 pax config;

N9375Y noted Las Vegas NV 10.83 "Air Cortez" titles, tailwheel;

N9375Y noted Orange County CA 5.84 "Able Computer", tailwheel;

N9375Y noted LAX 31.10.87;

(See note at BA-312 re Catalina Flying Boats);

N9375Y noted Long Beach CA 8.89 at Catalina Flying Boats ramp, plate BA-564;

N9375Y noted Long Beach CA 9.90,

N9375Y noted Long Beach CA 7.91 at Catalina Flying Boats ramp, also 4.92, 4.95;

N9375Y noted Long Beach 9.11.97 "Catalina Flying Boats" small titles, tailwheel;

23.11.98 accident report: ran off runway on takeof LGB, came to rest on dirt off runway facing opposite direction: minor damage to right outer wing, right gear and tailwheel, operator Catalina Flying Boats, on cargo flight, pilot Thomas W. Glasgow;

N9375Y noted Long Beach CA 17.8.99 op Catalina Flying Boats:

N9375Y noted Phoenix-Sky Harbour AZ 4.01 "Catalina Flying Boats Inc" windowless;

N9375Y noted Phoenix AZ 22.12.02 "Phoenix Airtransport" titles;

N9375Y noted Long Beach CA 18.8.05 at Catalina Flying Boats;

BA-565	G18S	N9374Y	built	.60
			Bailey Leasing Corp, Fort Wayne IN	63/66
			Central Soya Co, Chicago IL	69
			Duncan Aviation, Omaha NE	70/72
			Hamilton Aviation, Hamilton OH	73
			Jimmy F. Godwin, Eustis FL	79
			Hoffman Flying Service, Saginaw MI	26.11.84/91
			sold to Canada: struck-off USCR	10.5.91
		C-FKEL	V. Kelner Airways Ltd, Pickle Lake ONT	31.5.91/93
			846090 Ontario Ltd, Thunder Bay ONT	1.93/96
			Wildcountry Airways, Red Lake ONT	21.4.93/05
			struck-off register	20.1.05
BA-566	G18S	N9400Y	built	.60
			Security Insurance Co, New Haven CT	63/64
			Sklar Producing Co, Shreveport LA	66/70
			Sklar & Philips Oil Co, Shreveport LA	71/72
			SS Airways, Kansas City KS	79
			ground-loop, struck ditches on takeoff, Lansing IL	17.9.80
			struck-off USCR	3.87
BA-567	G18S	N149A	built	00
	0100	IN I + 3/A	Duit	.60
	0100	N2700S (2		.60 63/64
	0100		Stewart Equipment Co, Philadelphia PA DBS Transit Co, Harrisburg PA	
	0.100		Stewart Equipment Co, Philadelphia PA	63/64
	0100		Stewart Equipment Co, Philadelphia PA DBS Transit Co, Harrisburg PA	63/64
	0100		Stewart Equipment Co, Philadelphia PA DBS Transit Co, Harrisburg PA Fischer Bros Aviation/ Fischer Bros Flight Training/	63/64 66

N2700S photo 5.70 "GCS Airlines - Fischer Bros Aviation" titles, tailwheel;

N2700S noted Manassas OH 7.71 "GCS Airlines" titles, tailwheel;

N2700S noted Mansfield OH 7.71 "GCS Airlines" titles, op Fischer Bros Aviation, tailwheel, extended nose (not Hamilton long nose);

N2700S accident report 17.11.72: G18S Metro Air System, flight Hopkinsville KY to Lexington KY, crashed en route in icing conditions, 798 lb over gross weight, CofG 2.72 inches rear of aft limit, pilot & 10 pax killed;

BA-568	G18S	N579B (2	Beech Aircraft Corp, Wichita KS: CofA issued	5.1.61
			E. W. Bliss Co, Canton OH	63/64
		N5798	Grimes Manufacturing Co, Urbana OH	66/69

N931GM	Grimes Manufacturing Co, Urbana OH Projects Unlimited, Dayton OH	70/72 79
	op: General Aviation, Greenville TN	80
	Madison Aviation Centre, London OH	80
	Cape Air Leasing, Hyannis MA	7.81
	op: Gull Air, Hyannis MA	82
	Gull Air, Hyannis MA & West Palm Beach FL	9.83/86
	Aviation One Inc	7.87
	Terrell Leasing Co, Terrell TX	9.88
	Thomas W. May, New Boston TX	3.89/91
	May Air Xpress, New Boston TX	9.3.94/13
	(stripped hulk in compound Texarkana AR 97/08)	
	struck-off USCR	22.5.13

N931GM noted Texarkana AR 8.97 stored in compound near airport with two other Beech 18s; N931GM noted Texarkana 6.8.98 & 16.8.99 unchanged;

N931GM noted Texarkana AR 2.8.02, 6.8.03 still in compound off airport;

N931GM noted Texarkana AR 22.7.08 dismantled in compound with N9682R;

N931GM still at Texarkana AR 9.17 stripped hulk standing on its wheels;

BA-569	G18S	N9423Y	built Bankers Leasing Corp, Boston MA	.61 63/64
			crashed destroyed by fire, wing structural failure in flight, near Toadlena NM	16.7.64
BA-570	G18S	N766X (1	built	.61
		N652TM	Volpar Inc, Van Nuys CA	14.11.68/69
		XC-CIU	Mexican Government	-
BA-571	G18S	N9449Y	Beech Aircraft Corp, Wichita KS: CofA issued	16.1.61
			McLaughlin Inc, Great Falls MT	63/64
			Kiekhaefer Corp, Fond du Lac WI	66/69
			Brunswick Corp, Fond du Lac WI (merger)	22.4.69/71
		N36BC	Brunswick Corp, Fond du Lac WI	28.6.71
			David B. Fields, Midland TX	10.87
			Glen E. Johnson, Fort Worth TX	8.89/94
			RZM Corp, Evansville IN	5.4.94/95
			Scott White/ Scotts Flying Service,	
			Hockessin DE & Castlewood VA	26.7.95/11
			Bancroft Contracting Corp, South Paris ME	13.6.11/20

N9449Y noted Chicago-Meigs Field 23.9.70;

N36BC noted Midland TX 10.87 plate BA-571;

N36BC visited Beech fly-in Tullahoma TN 13.10.95, plate BA-571;

N36BC at fly-in Oshkosh WI 1.8.96;

N36BC at fly-in Oshkosh 1.8.98, Scott White, Castlewood VA, plate: BA-571 built 1.61;

N36BC noted Tullahoma TN 4.98;

N36BC at Beech flyin Tullahoma TN 16.10.98 tailwheel, Scott & Brenda White, Castlewood VA;

N36BC at airshow Lakeland FL 4.99 tailwheel, Scott White, Castlewood VA;

N36BC at Beech fly-in Tullahoma TN 10.10.99 Scott White VA;

N36BC at Beech fly-in, Tullahoma TN 18.10.00;

N36BC at Waco fly-in, Waco TX 25.8.01 plate BA-571;

N36BC at Beech fly-in Tullahoma TN 16.10.02;

BA-572	G18S	N9448Y (1	Beech Aircraft Corp, Wichita KS: CofA issued	24.1.61
			Atlantic Aviation Corp, Teterboro NJ	63
		N2427	Owens Corning Fibreglass Corp, Toledo OH	64
			Kiekitaefer Corp, Fond du Lac WI	66/69
			escape hatch released in flight, struck tailplane,	
			landed safely Quincy IL	25.3.66
			Brunswick Corp, Fond du Lac WI (merger)	22.4.69/71
		N34BC	Brunswick Corp, Fond du Lac WI	28.6.71
		N100KU (2	University of Kansas, Lawrence KS	76/79
		N400KU `	rereg	1.80
			Ronald W. Smith/ Smithair Inc, Atlanta GA	81/95
			badly damaged by windstorm, Atlanta GA	19.11.81

Ronald W. Smith, Fort Myers Beach FL	19.1.95
RBS Aviation Group Inc, Dover DE	25.7.95/05
Brenda Smith, Jonesboro GA	16.11.05/11
Daniel R. Gudgel, Hillsboro ND, later Lemoore CA	.13/20

N100KU noted Lawrence KS 3.6.76; N400KU reported in service with Smithair 85; N400KU noted Tara Field GA 5.8.05 plate BA-572 built 1.61, op by Smith Air;

BA-573	G18S	N2019C	Beech Aircraft Corp, Wichita KS: CofA issued	2.2.61
			Smiths Transfer Corp, Staunton VA	63/70
			Goldston Transfer Inc, Eden NC	71/72
			Anderson Aviation, Anderson IN	76/86
			Dragon Air Inc, Tonawanda NY	8.90/97
			Air Cargo Express Inc, Amherst NY	19.2.97/99
			Pro-Freight Cargo Services Inc, Opa Locka FL	29.2.00
			Great American Transportation Co, Nashville TN	24.10.01/05
		N6B	Great American Transportation Co, Nashville TN	.04/12
			Russell W. Berithgeers, Burns TN	5.9.13/15
			dam, gear-up landing at closed airfield, Nashville TN	22.4.12
			struck-off USCR	3.2.15

N2019C noted Andewrson IN 28.5.76;

N2019C noted Youngstown OH 4.2.83 Anderson Aviation;

N2019C noted Palm Beach FL 28.6.02 "Pro Freight Cargo Service" titles, in service;

N2019C at Beech fly-in Tullahoma TN 16.10.03;

N2019C noted Nashville-Cornelia Fort Airpark TN 8.4.04 all metallic, tailwheel, in service;

BA-574	G18S	N9461Y	built	.61
			Tecumseh Products Co, Tecumseh MI	63/64
			Kiekhaefer Corp, Fond du Lac WI	66/69
			Brunswick Corp, Fond du Lac WI (merger)	22.4.69/71
		N33BC	Brunswick Corp, Fond du Lac WI	28.6.71/72
		N38BC	rereg	
		N38RM	Robert Z. Blue, Mount Prospect IL	77/79
			op: Georgia Air Freight	78
			gear collapsed landing, West Chicago-Dupage IL	11.1.78
			P B Leasing Co, Naperville IL	81/82
			lsd: Viking Express Inc, Chicago-Midway IL	81/82
			Miami Valley Bank, Quincey OH	2.82
			struck dirt bank on takeoff, Chicago IL	30.8.82
		N103VE	P B Leasing Co, Naperville IL	12.82
			Isd: Viking Express Inc, Chicago-Midway IL	82
		N38RM	P B Leasing Co, Naperville IL	17.3.82/91
			op: Viking Express Inc, Chicago-Midway IL	82/91
			crashed on takeoff, West Chicago IL	4.12.91

N38RM accident report 11.1.78: Georgia Air Freight, flight Grand Rapids MI to West Chicago, mechanical gear failure, 9.45pm, 2 crew unhurt;

BA-575	G18S	N1171	built	.61
			Borg Warner Gear Division, Muncie IN	63/69
			Borg Warner Corp, Birmingham MI	70/72
			Millwood Aviation, New York NY	27.1.76/80
			struck-off USCR	9.5.80
BA-576	G18S	N576M	Beech Aircraft Corp, Wichita KS: CofA issued	14.2.61
			T. J. O'Connor Cattle Co, Victoria TX	63
			Aggregate Plant Product Co, San Antonio TX	66/72
			Larry Johnson, McAllen TX	79
			Raul A. Lopez, McAllen TX	25.5.83/13
			damaged in accident	21.6.83
			last FAA contact with owner 1989, struck-off USCR	23.4.13
BA-577	G18S	N9490Y	Beech Aircraft Corp, Wichita KS: CofA issued	17.5.61
			Sanders Currey Aircraft Co, Shreveport LA	63

Ohio Aviation Co, Dayton OH	64
Sohio Petro Co, Oklahoma City OK	66
SMB Stage Line Inc, Des Moines IA	69/81
William R. Sandlin, Harlingen TX	.81
Castle Air, Los Angeles CA	2.82
Rainbow Islands Cargo Inc, Honolulu HI	6.83/85
Sun Pacific Airlines, Honolulu HI	4.85/86
Western Venture Capital Corp, Tulsa OK	11.86/13
struck-off USCR	23.5.13

N9490Y noted Honolulu 9.83 "Rainbow Islands Cargo", plate BA-577; N9490Y noted Honolulu 12.10.83 Rainbow Islands Cargo tailwheel; N9490Y noted Honolulu 6.84 "Rainbow Islands Cargo";

BA-578	G18S Junior JATO	PZ-TAQ	Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin & additional baggage capacity, delivered with Junior Jato units in engine nacelles)	2.61
	JATO	N50CN	reg	
		N100SS	Fred N. Stalder, Harrisonville MO	79
			struck-off USCR	4.82
			Fred N. Stalder, Harrisonville MO: restored to USCR	3.86
			struck-off USCR	4.86
BA-579	G18S	N9499Y	built	.61
			Aetna Life Insurance Co, Hartford CT	63/64
		N16A	United Properties Inc, Warwick RI	66/70
		N723T	Tobey Inc, Wethersfield CT	71/72
			Great Western Airlines, Tulsa-Riverside OK	77
			Blackhawk Airways, Janesville WI	79/84
			Richard J. Wixom/ Blackhawk Airways, Janesville WI	11.10.84/86
			crashed landing, Janesville WI	26.2.86

N723T noted Chicago-O'Hare IL 23.10.78; accident report 26.2.86: crashed off runway during landing, owned Richard J. Wixom;

BA-580	G18S	N9966R	Beechcraft Aircraft Corp, Wichita KS	.60/63
	H18		(CofA as G18S 6.7.60, modified as prototype H18,	
			ff as H18 29.8.60: used for test flying 60/63,	
			H18 FAA type certificate issued 11.7.62,	
			N9966R CofA as H18 issued 5.7.63)	
		N616T (1	Duncan Beechcraft Inc, Tarkio MO	64/66
		N38W (2	Duncan Beechcraft Inc, Tarkio MO	7.66/70
		•	Josam Manufacturing Co, Michigan City IN	71/72
			Caribe Air, Birmingham AL	79
			Clifford A. Marlatt/ Sky Castle Aviation, New Castle IN	7.5.79/11
			Bank of Utah, Salt Lake City UT: trustee	19.10.11/20

## N38W noted New York-JFK 21.7.71;

BA-581	G18S	N9933R	Beech Aircraft Corp, Wichita KS	.61
			(Beech demonstrator 61)	
			Associates Investment Co, South Bend IN	63/64
	Hamilton	N215W	Burton Supply Co, Youngstown OH	66
	Westwind		SMB Stage Line Inc, Des Moines IA	69/79
	III		struck snowbank landing, turned over on to back,	
			Chicago-O'Hare IL	24.1.79
			Blackhawk Airways, Janesville WI	.79/83
			(wreck purchased, temporary repairs to ferry O'Hare to	
			Janesville WI .79 with nose from another aircraft &	
			aluminium windshield with small pilot vision holes;	
			rebuilt using C-45H cabin roof from N35136/AF-629,	
			G18S cab, used nose, returned to service 79)	
			struck hill destroyed, while low flying under cloud near	
			Keyser WV	30.6.83
			-	

N9933R featured in Beech publicity photos of G18S: central elongated panoramic cabin window; N215W noted Muskogee OK 2.3.73 SMB Stage Line maintenance base; N215W noted Ft Worth-Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; N215W accident report 30.6.83: Blackhawk Airways: freight flight, struck hill in low cloud, pilot k; Further details on the composite 1979 rebuild: aee Beech 18 by Parmerter p.302;

BA-582	G18S	N234W (1	Western Gas Service Co, El Paso TX struck-off USCR	12.6.61/63 11.2.63
BA-583	G18S	N4S N192K	Rock Island Lumber Co, St Paul MN Weyerhaeuser Co, Tacoma WA Weyerhaeuser Co, Tacoma WA Master Jobbers Inc, La Crosse IN Ross Aviation, Tulsa-Riverside OK Great Western Airlines, Tulsa-Riverside OK Herbert A. Hartley, Brownsville TX struck-off USCR	.61/63 64/66 69 70 71/72 77/80 9.5.80/83 8.6.83
	N192K not	ed San Antoni	o-Stinson TX 17.5.73;	
BA-584	G18S Junior JATO	PZ-TAR	Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin & additional baggage capacity, del. with Junior Jato units in engine nacelles)	3.61/65
			crashed Kabelebo	23.6.65
BA-585	G18S	N97D	Youngstown Airways/ Lease Air, Youngstown OH Wheeling Steel Corp, Wheeling WV	.61 63/64
		N9711	Wheeling Steel Corp, Wheeling WV struck snowbank landing, Wheeling WV Alpat Aviation, Bowmansville NY David Warren & Son, Orlando FL Barrow Aircraft Brokerage Ltd, New York NY	66 2.12.66 69/70 79 11.9.79/91
BA-586	G18S	N1290Z N129GP (1 N1291N	built General Precision Inc, Tarrytown NY General Precision Inc, Tarrytown NY Allied Aviation, Columbia SC Sierra West Airlines, Oxnard CA damaged landing gear locked-up, Nashville TN Frank A. Neuhausen, Santee CA Morey Wyman/ Wyman Pilot Service, Pontiac MI McNeely Charter Service, Earle AR Thomas W. May, New Boston TX May Air Xpress, New Boston TX Robert L. Brown, Springdale AR Springdale Air Service, Springdale AR N1291N Inc, Pembroke Pines FL Bush Air Inc, Wilmington DE wrecked at North Perry FL by Hurricane Wilma struck-off USCR as "destroyed" reg. candidate struck-off USCR	4.61 63/64 66/69 71/72 74 8.4.74 79 84 3.88 8.89/91 9.3.94/97 4.98 13.7.98/99 20.8.01 22.4.02/05 8.05 14.12.05 30.9.08/11 27.6.11

N1291N accident report 8.4.74: Sierra West Airlines, mail flight, flight Nashville to Louisville KY, gear mechanical fault airborne, returned for landing 9.15pm, 2 crew unhurt;

N1291N noted Bakersfield-Meadows Field CA 12.74, tailwheel, "Sierra West Airlines" titles,

N1291N noted Van Nuys CA 1.76;

N1291N noted Pontiac MI 9.80;

N1291N noted Dallas-FTW TX 12.93 all metallic, took off;

N1291N noted Texarkana AR 7.97 May Air Xpress;

N1291N noted Springdale AR 16.8.99 all metallic no reg, plate BA-586 built 4.61;

N1291N noted Opa Locka FL 4.4.01;

N1291N noted North Perry FL 10.8.05 freighter, being worked on;

BA-587 (	G18S	N1200Z	Beech Aircraft Corp, Wichita KS: CofA issued	27.7.61
			State of North Carolina, Raleigh NC	63/64
			Commercial Credit Equipment, Rockford IL	66/72
		N120ZZ	op: Flight Express Cargo, Philadelphia PA	77/79
			crashed on takeoff, Cleveland-Hopkins OH	1.11.77
			SSM Inc, Newark DE	78
			Swift Air Charter, Cleveland-Hopkins OH	2.10.78/13
			struck-off USCR	19 4 13

N120ZZ accident report 1.11.77: Flight Express, cargo flight to Detroit, tailwheel failed, groundlooped, gusty winds, 4.50am, pilots seat slid back on takeoff, 2 crew unhurt;

BA-588	G18S	N98D	Youngstown Airways/ Lease Air, Youngstown OH: CofA	4.8.61
			Crucible Steel Co of America, Pittsburgh PA	63/64
			Beckett Aviation Corp, West Mifflin PA	66
		N9800 (2	Bailey Leasing Corp, Fort Wayne IN	66
		•	Time Airlines, Benton Harbour MI	69/71
			Midwest Commuter Airlines Corp, Indianapolis IN	71/72
			Flight Express Cargo, Philadelphia PA	79
			sale reported, Houston TX	91
			·	

N9800 noted Chicago-O'Hare 18.5.70 Time Airlines; N9800 noted Cleveland-Hopkins IL 4.71 "Time Air Lines" titles, tailwheel, in service;

BA-589	G18S	N1384Z	Beech Aircraft Corp, Wichita KS	.61
			sold to Argentina, struck-oiff USCR	19.10.61
		LV-PJB	delivery reg.	8.61
		LV-HNH	Ministry Economy Secr Energy & Gas	4.9.62
		LQ-HNH	Argentine Government	64
		LV-HNH	rereg	
			Juan Carlos Rodriguez Louro, Buenos Aires	21.11.79
			retired, stored Buenos Aires-Don Torcuato	91/95
			under restoration, all metallic, Don Torcuarto	97/01

LQ-HNH noted Buenos Aires-Ezeiza 22.7.64;

LV-HNH noted Buenos Aires-Ezeiza 8.76;

LV-HNH noted Don Torcuato, Argentina 7.86;

LV-HNH noted Don Torcuato 28.5.91 stored;

LV-HNH noted Don Torcuato 8.95, derelict in open;

LV-HNH noted Don Torcuato 6.12.97 under rebuild in hangar, previously outside semi-derelict; BA-589 noted at Don Torcuato 2.11.01 all metallic, overhaul partially completed, no engines;

BA-590	G18S	N404G	built	.61
			P. H. Glatfelter Co, Spring Grove PA	63/64
		N404H	P. H. Glatfelter Co, Spring Grove PA	66
			Burgess Aviation, Holland MI	69
			Paul J. Chauvin, Detroit MI	71/72
			Abrams Aerial Survey, Lansing MI	72/82
			PDL Associates Inc, Northridge CA	9.82/91
			Mid Atlantic Air Museum, Reading PA	8.1.92/20

N404G photo Reading PA 6.64 owned P.H. Gladfelter Paper Corp, tailwheel; N404H noted Tampa FL 9.81, tailwheel, not titles, no external survey gear;

N404H noted Fulton NY 7.93;

N404H noted at MAAM Reading PA 16.5.01;

N404H noted Reading PA 5.02 civil scheme outside MAAM hangar;

BA-591	G18S	N1125M	built	.61
			Schwitzer Corp, Indianapolis IN	63/66
			Wallace Murray Corp, Indianapolis IN	69/70
			Apollo Airways, Chicago IL	71/77
			struck snowbank on takeoff, Boston-Logan MA	20.2.72
			Northern Air Service, Grand Rapids MI	21.4.78/79
		N400NA	Northern Air Service, Grand Rapids MI	2.79/85
			damaged in forced landing after takeoff, Evart MI	11.8.83

struck-off USCR 25.7.85

N1125M noted Boston MA 13.6.73 Apollo Airways;

N1125M noted Detroiut-City MI 24.5.76, 26.5.77 "Apollo Airways", tailwheel;

"N402NA" noted Indianapolis IN 6.6.80 Northern Air Freight – probaby a missighting of N400NA;

N400NA noted London ONT 3.12.80 Northern Air Freight;

N400NA noted Youngstown OH 16.9.82 Northern Air Service;

N400NA noted Toronto ONT 5.8.83 Northern Air Service;

accident report 11.8.83: Northern Air Service, freight flight, engine failure on takeoff Evart MI, forced landing near a street near airport;

	forced lan	nding near a st	reet near airport;	
BA-592	G18S	N505X	built	.61
			Page Airways, Rochester NY	62
			midair collision with US Navy F3H Demon Bu145299,	
			N505X crashed into ocean	2.10.62
BA-593	G18S	N414GN	Gust Newberg Construction Co, Chicago IL	.61/66
		N5724M	Gust K. Newburg, Chicago IL	71/79
			left gear collapsed taxying, Pal-Waukee IL	7.3.71
			Hartzog Aviation, Rockford IL	3.82
			Squadron of the Quad City, Moline IL	5.82
			Jim Hankins Air Service Inc, Jackson MS	9.85/86
			Jim Ratliff Air Service, Columbus MS	12.87/89
	turbine		crashed, gear-up landing, Greenwood MS	15.8.89
	trigear		(PT6A-20 turbines, trigear by 89)	
			struck-off USCR	31.8.89
			wreck sold for parts: nose-cockpit section fitted	
			to N18RY/BA-325)	
	accident :	15.8.89: lande	eft gear broke through ice covering soft ground taxying afted gear up Greenwood MS, pilot attempted go around but hit cargo ops, Jim Ratliff Flying Service;	er landing, t runway,
BA-594	G18S	N1394Z	Beech Aircraft Corp, Wichita KS: CofA issued	5.9.61
			Chicago & Northwest Railway Co, Chicago IL	63/64
			Hartzog Schneck Aviation, Rockford IL	66/70
			reg. pending: USCR	71
			Thomas Russell, Knoxville TN	22.9.82/13
			last FAA contact with owner 85: struck-off USCR	31.1.13
BA-595	G18S	N1500Z	built	.61
			Kansas Nebraska Natural Gas Co, Hastings NE	63/69
			Airkaman of Omaha Inc, Omaha NE	70
			prop blade detached on takeoff, Laramie WY	24.10.69
			Summit Aero Leasing, Akron OH	13.7.70/91
			gear collapsed on takeoff, Augusta GA	21.7.73
	accident i	report 24.10.69	propeller blade failed on takeoff Laramie WY;	
BA-596	G18S	N163DP	built	.61
			Francis Aviation, Lansing MI	63
			Borg Warner Corp, Chicago IL	64/66
		N174YC	York Corp, York PA	69
			Central Tool & Die Inc, Hopkinsonville KY	70
			Michael D. McGee: USCR	76
			crashed destroyed landing, Chicago-DuPage County IL	31.5.76
			t 31.5.76: flight International Falls MN to West Chicago-Dul nt in weather below minimums, stalled, dest: 7k;	Page,
BA-597	G18S	N948Q	Beech Aircraft Corp, Wichita KS: CofA issued	9.10.61
D. ( 007	3100	110-00	Ohio Aviotion Co. Claveland O.I.	0.10.01

Ohio Aviation Co, Cleveland OH

Dana Corp, Toledo OH

Perfect Circle Corp, Hagerstown IN

Harrison Security Services, Jackson MS

Jim Hankins Air Service, Jackson MS

63

64

66

69/70

71/72

William Catalina, Greenwell LA	78
ditched in sea at night near Nassau, Bahamas	12.9.78
John S. Smith, Montgomery AL: USCR	18.12.78/91

N948Q accident report 12.9.78: flight Barangia, Colombia to Great Inagua Bahamas, destination Fort Lauderdale FL, power failure, ditched 10.30pm, 2 on board unhurt;

BA-598	G18S	N1557Z	built	.61
			Montana Power Co, Butte MT	63/64
			Tradewind Airport Corp, Amarillo CA	66
			Dan Futrell, Nashville AR	69/70
		N331E	Ag Air Inc, Belle Glade FL	
		N331SE	Barnett Serio Oil Co, Natchez MS	71/72
			Joseph J. Tucker, Hattiesburg MS	79
			Walkers Cay Air Terminal, Fort Lauderdale FL	2.82
		N444PV	Walkers Cay Air Terminal, Fort Lauderdale FL	3.82/83
			crashed destroyed after takeoff, Fort Lauderdale FL	14.4.83
	pilot was	able to avoid b	4.4.83: Walkers International Inc: engine failure on takeoff ouildings near airport boundary, struck trees and crashed in impact fire, pilot minor injuries;	
BA-599	G18S	N9334Y	built	.61
27.1000	0.00		E. I. duPont de Nemours & Co, Wilmington DE	63/66
		N577DU	E. I. duPont de Nemours & Co, Wilmington DE	
		N547DA	Deleware Air Freight Co, Wilmington DE	69/70
			Sebastiano Cannavo, Lester PA	71/79
			Cannavo Aviation/ Aero Taxi Inc, Claymont DE	16.10.80/81
			crashed on takeoff, New Cumberland PA	12.6.81
BA-600	G18S	N959T	E. I. duPont de Nemours & Co, Wilmington DE: CofA Spencer Chemical Co, Kansas City KS Gulf Oil Corp, Kansas City MO	21.11.61 63/64 66
			Priority Air Transport System, Redwood City CA	69
			struck vehicle taxying, San Francisco CA	30.1.69
			Eureka Aero Industries, Eureka CA	70/72
			Great Western Airlines, Tulsa OK	77/81
			William R. Sandlin, Harlingen TX	24.2.81/91
	accident i	report 30.1.69:	Priority Air Transport, night mail flight, 12.30am;	
	N959T nc	ited San Franc	csico CA 2.71 "Eureka Aero Industries", tailwheel;	
	N959T no	oted Victoria T.	X 9.5.73 "Eureka Aero Industries" titles;	
BA-601	G18S	N1480W	E. I. duPont de Nemours & Co, Wilmington DE: CofA	11.12.61
			Midcontinent Leasing Co, Amarillo TX	63/66
			Public Service Co, Junction City KS	69
			Gates Aviation Corp, Denver CO	70
		N1480K	Ross Aviation, Tulsa-Riverside OK	71/80
			op: Great Western Airlines, Tulsa OK	75/80
			groundloop landing, rolled tail-first into ditch,	
			Dallas-Fort Worth Regional TX	15.7.75
			Saber Aviation/ Sabre Cargo Airlines, Charlotte NC	87/88
			crashed on takeoff, Morganton NC	24.2.88
			Piedmont Air Cargo, Gastonia NC	12.90/95
			Midline Air Freight, Cecilia KY	
			<u> </u>	24.8.95/04
			William B. Chase, Des Moines IA	3.1.05/17
			gear collapsed landing, Ft Lauderdale-Executive FL	19.10.16
			Jane A. Theberge, Oakland Park FL	17.10.17/19
			op: Maurice Roundy, Fort Lauderdale FL	17/19

N1480K noted South Weymouth MA 16.8.74; 15.7.75 accident report: Great Western: 3.02am, flight Tulsa OK to Dallas;

(based Ft Lauderdale-Executive, freight ops to Bahamas)

## 24.2.88 accident: Sabre Aviation, ran off runway on takeoff Morganton NC, cargo ops; N1480K noted Ankeny IA 22.7.06 freighter conversion, "Miss Magoo";

BA-602	G18S	CC-PRC CC-CEM	built rereg	1.62
		OO-OLIVI	rereg	
BA-603	G18S	N925G	Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator January-August 1962)	2.2.62
			Pennsalt Chemicals Corp, Philadelphia PA	63/64
		N985G	O'Sullivan Rubber Corp, Winchester VA	66
			Atlantic Aviation Service, Philadelphia PA	69
			Robert E. Moore, Wilmington DE	70
		N74LA	Eugene Pikowsky, Minneapolis MN	76/79
			op: Viking Int'l Air Freight, Minneapolis MN	10.76/82
			Sam Medley, Dallas TX	1.83
			ACE Air Cargo Express Inc, Cleveland OH	10.83/86
			Royal Air Freight, Pontiac MI (retired, poor condition, Pontiac MI 00)	20.1.89/14
			struck-off USCR	18.11.14

N74LA noted McAllen TX 7.10.82 "VIA" titles;

N74LA noted Pontiac MI 2.97 Royal;

N74LA noted Pontiac MI 3.3.97,

N74LA noted Pontiac MI 7.98;

N74LA noted Pontiac MI 23.7.00 parked in long grass, poor condition;

BA-604	G18S	N80D (3	Youngstown Airways/ Lease Air, Youngstown OH: CofA	6.2.62/66
		N8087	SMB Stage Line, Des Moines IA	68/81
			struck parked aircraft, taxying Columbia MO	16.5.74
			struck fence on takeoff, DeKalb IL	23.5.78
			Edward B. Harp	.81
			Cocker Aviation, Dallas TX	11.81
		N93CA	Cocker Air Freight, Dallas TX	2.82/84
			renamed: Skyfreighters Corp, Dallas TX	11.84/85
			ACE Air Cargo Express Inc, Cleveland OH	11.85/86
			North Coast Aviation, Cleveland OH	4.88
			Bering Air Inc, Nome AK	16.2.90/99
			Hartford Holding Corp, Wilmington DE	7.4.00
			Trans North Aviation, Anchorage AK	.00
			Bellair Inc, Fairbanks AK	31.7.00/01
			Aerolease of America Inc, Carson City NV	9.10.01
			Methow Aviation, Everett WA	7.12.01/05
			Kestrel Inc, Waukee IA	25.5.05/06
			Hans W. Munich, Yakutat AK	30.1.09/13
			ran off runway landing, starboard gear collapsed,	
			Yakutat AK	13.7.09
			Reg expired 30.9.13, struck-off USCR	24.1.18
			•	

N8087 noted Chicago-O'Hare 27.1.69 SMB Stage Line;

N8087 noted Muskogee OK 2.3.73 SMB Stage Line maintenance base;

N8087 accident report 16.5.74: SMB Stage Line: mail flight Kansas City MO to Columbia MO, taxying after landing struck Piper N3977W, 2.26am;

N8087 accident report 23.5.78: SMB Stage Line: flight DeKalb to Rockford IL 6pm, forced landing on airport after takeoff, pilot unhurt;

N93CA noted Fairbanks AK 8.01 good condition, long centre window, brown & white;

N93CA noted Ephrata WA 18.10.02 "Methow" titles, tailwheel;

N93CA noted Ephrata WA 12.8.03 on Methow freight run to Moses Lake then Seattle;

N93CA noted Seattle-Boeing field 27.4.04 Methow in service;

accident report 13.7.09: Yakutatat AK, cargo flight, tail wheel;

BA-605	G18S	N340K	built	.62
			Panhandle Eastern Pipe Line Co, Kansas City MO	63/69
			reg. pending	70
			Industrial Bearing & Transmission Co, Kansas City MO	71/72
			ran off runway, struck ditches, Beaver Falls PA	16.9.76
			Grace A. Hambel, Lisle IL	79

Lester H. Hambel, Clarendon Hills CA	10.81
D & H Flying Service, Kenosha WI	12.82/92
Bering Air Inc, Nome AK	4.3.92/95
crashed on takeoff, Nome AK	18.12.95
(wreckage was buried)	

N340K noted Fort Worth-Oak Grove TX 3.5.73;

	N34UK NC	ntea Fort vvortn	-Oak Grove TX 3.5.73;			
BA-606	G18S	N523 N569AG	Ohio Oil Co/ Marathon Oil Co, Findlay OH: CofA issued Stan Socia Corp, Tyler TX First National Bank, Carthage TX	14.2.62/66 69 70		
		N569QA	First National Bank, Carthage TX J & J Aircraft Leasing, Fort Lauderdale FL	71/72 79		
			Kenneth D. Munn, Hayward CA	11.82		
			Julie A. Schwerzmann, Watertown NY	6.83		
			Evelio Hernandez, Miami FL	4.84		
			op: Air Cargo America, Miami FL	85		
			Mark J. Von Mandel, Miami FL	6.9.85/13		
			op: Air Cargo America Inc, Miami FL	.85/87		
			last FAA contact with owner 1991, struck-off USCR	23.4.13		
	N569QA I	noted Hayward noted Miami FL noted Opa Loc	. 29.7.85 Air Cargo America;			
BA-607	G18S	N19Y (2	built Wayerhaayaar Ca. Dhymayth NC	3.62		
	trigear	N192Y	Weyerhaeuser Co, Plymouth NC	16.4.62/68 29.3.68		
		PI-C1932	exported to Philippines, struck-off USCR Weyerhauser Philippines Inc, Manila	.68		
			Balesin Corp, Manila	78/80		
		IXI -0 1932	Pacific Airways Corp, Manila	87/90		
			7.5.86 trigear, yellow & white, no titles; 8.10.87 Pacific Airways;			
BA-608	G18S	N172M	built	.62		
			E. K. Jenkins Inc, Great Falls MT	63/66		
			Falcon Airlines	68		
			Alvin O. West, Washington DC	69		
			Hill Aircraft & Leasing Corp, Atlanta GA	70/72		
			Great Western Airlines, Tulsa-Riverside OK	74/77		
			damaged on takeoff, Denver-Stapleton CO Providence Air Charter, Providence RI	12.12.74 78		
		(N147PA)	ntu: Providence Air Charter, Providence RI	4.78		
		N172M	Providence Air Charter, Providence RI	8.78/80		
		141721	Aero Marine Surveys Inc, Groton CT	12.6.80/83		
			(retired, parts stripped, Groton CT by 11.80)	80		
			struck-off USCR	20.7.83		
	N172M no	N172M noted Washington-DCA 2.10.68 Falcon Airlines; N172M noted Miami FL 22.8.71;				
			2.12.74: Great Western, mail flight, groundlooped on take	off in gusty winds		
		oilot unhurt; oted Groton C1	28.11.80 wfu derelict, no titles;			
BA-609	G18S	N220H	Halliburton Co, Duncan OK	2.62/72		
	<b></b>		SMB Stage Line Inc, Des Moines IA	76/77		

BA-609	G18S	N220H	Halliburton Co, Duncan OK	2.62/72
			SMB Stage Line Inc, Des Moines IA	76/77
			Blackhawk Airways, Janesville WI	78/79
			Buck Maxon, Kotzebue AK	11.82
			James Rood, Kotzebue AK	8.83
			Northwestern Aviation, Kotzebue AK	84
			ACE Air Cargo Express Inc. Cleveland OH	5.85/86
			Bering Air Inc, Nome AK	6.2.89/95
			forced landing on tundra, Brevig Mission AK (wreck abandoned, reportedly buried;	23.12.89

6.4.95

accident report 23.12.89: Bering Air, forced landing due engine failure, airframe & engines not

	recovered by	operator;		
BA-610	G18S	N959B	Beech Aircraft Corp, Wichita KS	3.62/64
		N871MP	Mead Corp, Atlanta GA	66
			Ohio University, Athens OH	69
			Rambar Aviation, Parkersburg WV	70
			crashed destroyed landing, Greater Pittsburg PA	12.11.70
			PRambar Aviation, crashed Clinton PA, flew below Glideslo port of runway, 2 hurt;	pe,
3A-611	G18S	N1709G	built	1.62
			Carey Baxter & Kennedy Inc, New York NY	63/64
		N788G	Cars Unlimited Corp, Allentown PA	66
			First Union National Bank, Charlotte NC	69/72
			hit dirt bank on takeoff, Willmar MN	11.3.73
			Hamilton Aircraft Inc, Tucson AZ	74/79
			(open storage stripped Tucson 74/78 in Hamilton	0
			storage compound)	
	Hamilton		(rebuilt as <i>Hamilton Westwind III</i> : PT-6A-20s, tailwheel,	
	Westwind III		completed by Hamilton Aviation 1.80)	
	westwind iii			40.0.00/00
		C-GBST	Condor Aviation Services, Hamilton ONT	19.2.80/82
			(ferry permit 2.80 Tucson AZ to Hamilton ONT)	
			ground collision with Cessna 310 CF-ZKK, Toronto ONT	23.4.80
			(repaired Toronto, test flown 6.80)	
			undercarriage collapsed landing Toronto ONT	12.2.81
			Commerce Leasing Ltd, Toronto ONT	15.9.82
			struck-off Canadian Register	21,12.82
		N3281T	Ajax Aircraft Leasing Inc, Dover DE	3.1.83/89
			gear collapsed on takeoff, Belleville MI	24.10.84
			op: Action Aero Charter	89
			crashed destroyed landing, Covington KY	9.3.89
	BA-611 note		Z 7.9.79 "derelict";	
	reported not accident rep N3281T note	ort 24.10.84 ed Toronto (	vestwind in, I: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; DNT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;	
<u></u>	reported not accident rep N3281T note crash report	ort 24.10.84 ed Toronto ( 9.3.89: des	e: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; ONT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;	62/63
3A-612	reported not accident rep N3281T note	ort 24.10.84 ed Toronto (	e: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; DNT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;  Youngstown Airways/ Lease Air, Youngstown OH	.62/63 13 6 66/71
3A-612	reported not accident rep N3281T note crash report	ort 24.10.84 ed Toronto ( 9.3.89: des N81D (2	e: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; ONT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;  Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH	13.6.66/71
3A-612	reported not accident rep N3281T note crash report	ort 24.10.84 ed Toronto ( 9.3.89: des N81D (2 (N8101)	E: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; ONT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;  Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH ntu	13.6.66/71 70
BA-612	reported note accident rep N3281T note crash report	ort 24.10.84 ed Toronto ( 9.3.89: des N81D (2 (N8101) N81D	e: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; ONT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;  Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH ntu struck-off USCR	13.6.66/71
3A-612	reported note accident rep N3281T note crash report	ort 24.10.84 ed Toronto ( 9.3.89: des N81D (2 (N8101) N81D	E: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; ONT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;  Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH ntu	13.6.66/71 70
	reported note accident rep N3281T note crash report G18S  N81D noted	ort 24.10.84 ed Toronto ( 9.3.89: des N81D (2 (N8101) N81D Toronto-Ma	E: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; DNT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;  Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH ntu struck-off USCR	13.6.66/71 70 12.2.71
	reported note accident rep N3281T note crash report	ort 24.10.84 ed Toronto ( 9.3.89: des N81D (2 (N8101) N81D	E: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; DNT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;  Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH ntu struck-off USCR  Alton ONT 3.63 no titles, tailwheel;  Beech Aircraft Corp, Wichita KS: CofA issued	13.6.66/71 70 12.2.71 14.6.62
	reported note accident rep N3281T note crash report G18S  N81D noted	ort 24.10.84 ed Toronto ( 9.3.89: des N81D (2 (N8101) N81D Toronto-Ma	E: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; DNT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;  Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH ntu struck-off USCR  Alton ONT 3.63 no titles, tailwheel;  Beech Aircraft Corp, Wichita KS: CofA issued Travelers Insurance Co, Hartford CT	13.6.66/71 70 12.2.71 14.6.62 63/64
	reported note accident rep N3281T note crash report G18S  N81D noted	ort 24.10.84 ed Toronto ( 9.3.89: des N81D (2 (N8101) N81D Toronto-Ma	E: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; DNT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;  Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH ntu struck-off USCR  Alton ONT 3.63 no titles, tailwheel;  Beech Aircraft Corp, Wichita KS: CofA issued Travelers Insurance Co, Hartford CT Beck Welding & Manufacturing Inc, Elkhart IN	13.6.66/71 70 12.2.71 14.6.62 63/64 69/70
	reported note accident rep N3281T note crash report G18S  N81D noted	ort 24.10.84 ed Toronto ( 9.3.89: des N81D (2 (N8101) N81D Toronto-Ma	E: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; DNT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;  Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH ntu struck-off USCR  Alton ONT 3.63 no titles, tailwheel;  Beech Aircraft Corp, Wichita KS: CofA issued Travelers Insurance Co, Hartford CT Beck Welding & Manufacturing Inc, Elkhart IN Thunander Flying Service, Elkhart IN	13.6.66/71 70 12.2.71 14.6.62 63/64 69/70 71/79
	reported note accident rep N3281T note crash report G18S  N81D noted	ort 24.10.84 ed Toronto ( 9.3.89: des N81D (2 (N8101) N81D Toronto-Ma	E: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; DNT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;  Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH ntu struck-off USCR  Alton ONT 3.63 no titles, tailwheel;  Beech Aircraft Corp, Wichita KS: CofA issued Travelers Insurance Co, Hartford CT Beck Welding & Manufacturing Inc, Elkhart IN	13.6.66/71 70 12.2.71 14.6.62 63/64 69/70
3A-613	reported note accident rep N3281T note crash report G18S  N81D noted	ort 24.10.84 ed Toronto ( 9.3.89: des N81D (2 (N8101) N81D Toronto-Ma	E: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; DNT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;  Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH ntu struck-off USCR  Alton ONT 3.63 no titles, tailwheel;  Beech Aircraft Corp, Wichita KS: CofA issued Travelers Insurance Co, Hartford CT Beck Welding & Manufacturing Inc, Elkhart IN Thunander Flying Service, Elkhart IN Scarborough Aviation, Pontiac MI	13.6.66/71 70 12.2.71 14.6.62 63/64 69/70 71/79
3A-613	reported note accident rep N3281T note crash report G18S  N81D noted G18S	ort 24.10.84 ed Toronto ( 9.3.89: des  N81D (2  (N8101)  N81D  Toronto-Ma	E: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; DNT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;  Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH ntu struck-off USCR  Alton ONT 3.63 no titles, tailwheel;  Beech Aircraft Corp, Wichita KS: CofA issued Travelers Insurance Co, Hartford CT Beck Welding & Manufacturing Inc, Elkhart IN Thunander Flying Service, Elkhart IN Scarborough Aviation, Pontiac MI  Beech Aircraft Corp, Wichita KS: CofA issued	13.6.66/71 70 12.2.71 14.6.62 63/64 69/70 71/79 23.6.80/91 5.7.62
3A-613	reported note accident rep N3281T note crash report G18S  N81D noted G18S	ort 24.10.84 ed Toronto ( 9.3.89: des  N81D (2  (N8101)  N81D  Toronto-Ma	E: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; DNT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;  Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH ntu struck-off USCR  Alton ONT 3.63 no titles, tailwheel;  Beech Aircraft Corp, Wichita KS: CofA issued Travelers Insurance Co, Hartford CT Beck Welding & Manufacturing Inc, Elkhart IN Thunander Flying Service, Elkhart IN Scarborough Aviation, Pontiac MI  Beech Aircraft Corp, Wichita KS: CofA issued Houston Beechcraft Inc, Houston TX	13.6.66/71 70 12.2.71 14.6.62 63/64 69/70 71/79 23.6.80/91 5.7.62 63
3A-613	reported note accident rep N3281T note crash report G18S  N81D noted G18S	ort 24.10.84 ed Toronto ( 9.3.89: des  N81D (2  (N8101)  N81D  Toronto-Ma  N1864T  N1780G	E: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; DNT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;  Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH ntu struck-off USCR  Alton ONT 3.63 no titles, tailwheel;  Beech Aircraft Corp, Wichita KS: CofA issued Travelers Insurance Co, Hartford CT Beck Welding & Manufacturing Inc, Elkhart IN Thunander Flying Service, Elkhart IN Scarborough Aviation, Pontiac MI  Beech Aircraft Corp, Wichita KS: CofA issued Houston Beechcraft Inc, Houston TX Royal Crown Cola Co, Columbus GA	13.6.66/71 70 12.2.71 14.6.62 63/64 69/70 71/79 23.6.80/91 5.7.62
3A-613	reported note accident rep N3281T note crash report G18S  N81D noted G18S	ort 24.10.84 ed Toronto ( 9.3.89: des  N81D (2  (N8101)  N81D  Toronto-Ma  N1864T  N1780G  N356SW	E: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; DNT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;  Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH ntu struck-off USCR  Alton ONT 3.63 no titles, tailwheel;  Beech Aircraft Corp, Wichita KS: CofA issued Travelers Insurance Co, Hartford CT Beck Welding & Manufacturing Inc, Elkhart IN Thunander Flying Service, Elkhart IN Scarborough Aviation, Pontiac MI  Beech Aircraft Corp, Wichita KS: CofA issued Houston Beechcraft Inc, Houston TX Royal Crown Cola Co, Columbus GA Royal Crown Cola Co, Columbus GA	13.6.66/71 70 12.2.71 14.6.62 63/64 69/70 71/79 23.6.80/91 5.7.62 63 64
3A-613	reported note accident rep N3281T note crash report G18S  N81D noted G18S	ort 24.10.84 ed Toronto ( 9.3.89: des  N81D (2  (N8101)  N81D  Toronto-Ma  N1864T  N1780G	E: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; DNT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;  Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH ntu struck-off USCR  Alton ONT 3.63 no titles, tailwheel;  Beech Aircraft Corp, Wichita KS: CofA issued Travelers Insurance Co, Hartford CT Beck Welding & Manufacturing Inc, Elkhart IN Thunander Flying Service, Elkhart IN Scarborough Aviation, Pontiac MI  Beech Aircraft Corp, Wichita KS: CofA issued Houston Beechcraft Inc, Houston TX Royal Crown Cola Co, Columbus GA Royal Crown Cola Co, Columbus GA Royal Crown Cola Co, Columbus GA	13.6.66/71 70 12.2.71 14.6.62 63/64 69/70 71/79 23.6.80/91 5.7.62 63 64
BA-613	reported note accident rep N3281T note crash report G18S  N81D noted G18S	ort 24.10.84 ed Toronto ( 9.3.89: des  N81D (2  (N8101)  N81D  Toronto-Ma  N1864T  N1780G  N356SW	E: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; DNT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;  Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH ntu struck-off USCR  Alton ONT 3.63 no titles, tailwheel;  Beech Aircraft Corp, Wichita KS: CofA issued Travelers Insurance Co, Hartford CT Beck Welding & Manufacturing Inc, Elkhart IN Thunander Flying Service, Elkhart IN Scarborough Aviation, Pontiac MI  Beech Aircraft Corp, Wichita KS: CofA issued Houston Beechcraft Inc, Houston TX Royal Crown Cola Co, Columbus GA Royal Crown Cola Co, Columbus GA Construction Equipment Co, Greenville SC	13.6.66/71 70 12.2.71 14.6.62 63/64 69/70 71/79 23.6.80/91 5.7.62 63 64 66 69
BA-612 BA-613	reported note accident rep N3281T note crash report G18S  N81D noted G18S	ort 24.10.84 ed Toronto ( 9.3.89: des  N81D (2  (N8101)  N81D  Toronto-Ma  N1864T  N1780G  N356SW	E: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; DNT 24.9.85 turbine; t., Action Aero Charter: took off with frost on airframe;  Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH ntu struck-off USCR  Alton ONT 3.63 no titles, tailwheel;  Beech Aircraft Corp, Wichita KS: CofA issued Travelers Insurance Co, Hartford CT Beck Welding & Manufacturing Inc, Elkhart IN Thunander Flying Service, Elkhart IN Scarborough Aviation, Pontiac MI  Beech Aircraft Corp, Wichita KS: CofA issued Houston Beechcraft Inc, Houston TX Royal Crown Cola Co, Columbus GA Royal Crown Cola Co, Columbus GA Royal Crown Cola Co, Columbus GA	13.6.66/71 70 12.2.71 14.6.62 63/64 69/70 71/79 23.6.80/91 5.7.62 63 64

	Bo-S-Aire Airlines, Greenville SC	77
N5BA	Shirley J. Bowman/ Bo-S-Aire Airlines, Anderson SC	9.77/89
	landed gear locked up, Jacksonville FL	12.10.81
	cargo door separated in flight, Huntsville AL	16.11.82
	tailwheel collapsed landing, ran off runway,	
	Jacksonville FL	6.6.83
	Don Haynes Aviation, Anderson SC	8.88
	Jacob C. Bowman, Anderson SC	1.91
	Robert D. McSwiggan, Fayetteville GA	3.92
	Piedmont Air Cargo, Gastonia NC	5.92/95
	Springdale Air Service, Springdale AR	10.95/96
	SCS Group Inc, Springdale AR	7.3.96/98
	op: Springdale Air Service, Springdale AR	97/98
	Springdale Air Service, Springdale AR	13.7.98/99
	Kestrel Inc, Waukee IA	13.3.01
	Gulf Air Taxi, Yakutat AK	7.6.02
	George E. Thomas, Yakutat AK	24.6.03/06
	Oleetho-3 Inc, Hemet CA	14.9.06/12
	Carlsbad Raceway Corp, Hemet CA	6.6.12/20

N158YC noted Miami FL 10.8.77 Bo-S-Alre;

N5BA accident report 12.10.81: Bo-S-Aire: cargo flight Atlanta GA to Jacksonville, gear would not extend due mechanical failure 11.15pm, pilot unhurt;

N5BA accident report 16.11.82: Bo-S-Aire: left cargo door installed under Hamilton STC, incorrectly installed. 2 crew uninjured:

N5BA accident report 6.6.83: Bo-S-Aire Airlines Inc, tailwheel collapsed on landing, pilot lost control, ran off runway, pilot unhurt;

N5BA noted Toronto ONT 25.10.85 "Bo-S-Aire" titles;

N5BA noted Springdale AR 8.97 freighter no windows, Springdale Air Service, in service: plate BA-614 built 6.62;

N5BA noted Texarkana AR 5.8.98, windowless freighter, landed on freight run from Springdale AR owned Springdale Air Service, plate: BA-614 built 6.62;

N5BA noted Springdale AR 26.8.99 Springdale Air Service;

N5BA noted Hemet CA 14.5.08 blue & white windowlesss freighter, tailwheel 10.8.15, 14.11.15;

BA-615	G18S	N1557S	Beech Aircraft Corp, Wichita KS: CofA issued	8.62
	trigear		National Financing Inc, Wilmington DE	63
			Herb Singer Inc, State College PA	64/72
			Harold E. Bahlow, Canton MI	79
			Ajax Aircraft Leasing Inc, Dover DE	1.83
			Kokomo Aviation, Kokomo IN	11.84/91
			Piedmont Air Cargo, Gastonia NC	1.92/97
			US Motorsports Inc, Stateville NC	29.7.97
		N604DK	US Motorsports Inc, Stateville NC	10.97/99
			Air 4CE 1, Chicago IL	26.4.99
		N770DA	Air 4CE 1, Chicago IL	25.8.99/17
			(retired, parked Janesville WI as N604DK .99/16)	
			struck-off USCR	10.3.17

N1557S noted Washington-DCA 30.9.70 trigear;

N1557S noted Statesville NC 1.97 trigear "Piedmont Air Cargo" titles;

N604DK noted Janesville WI 26.7.99 trigear

N604DK noted Janesville WI 30.7.00, 28.7.02 & 23.7.03 trigear, plate BA-615, had arrived early 99 from Florida and being prepared for new owner at Du Page IL, ex freighter no windows "USAV" titles, previous titles "Piedmont Air Cargo" discernable;

noted at Janesville WI 25.7.08 parked outside, not operational, still N604DK;

noted at Janesville 26.7.15 parked outside, trigear, tailplane removed;

N604DK noted Janesville 30.7.16 outside, outer wings and tailplane removed, no windows;

		=		
BA-616	G18S	XC-BUX	Mexican Government	.62
		XC-CUW	Sria. Rec. Hidraulicos, Mexico City	3.63/77
			Transporte Aereo Federal	86
		N50WA	Westernair Inc, Albuquerque NM	15.9.86
			Robert L. Wills, Twin Falls ID	2.87
			Kurt A. Tedhams, Phoenix AZ	19.5.89/14
			Worldwide Warbirds Inc, Heber City UT	29.10.14/20

BA-617	G18S	JA5505	Maritime Safety Board, Kagoshima Maritime Safety Agency, Kagoshima Ken-Ichi Azuma retired 11.4.81: struck-off Register	9.62/65 70/78 81 18.4.81
		oted at Wichita oted Kagoshin	a KS 3.9.62 awaiting delivery;	10.4.01
BA-618	H18	N925K	Beech Aircraft Corp, Wichita KS: CofA issued (first production H18, company demonstrator from 8.62)	6.9.62
			Louisiana State Rice Milling Co, Abbeville LA	63/64
		N220T	Trunkline Gas Co, Houston TX	66
			damaged in gear-up landing, Houston-Hobby TX	20.4.67
		N2209	Trunkline Gas Co, Houston TX	69
		N220WH	Wiles-Holloway Inc, Baton Rouge LA	69 70
			Morris Trading Corp, Sarasota FL	70 78/80
		(N12208C)	Clifford A. Marlatt/ Sky Castle Aviation, New Castle IN	6.1.79
		(N220SC) N220WH	ntu: Sky Castle Aviation Aero Services Inc, Union City TN	3.84
		INZZUVVII	Air Machines & Services Inc, St James MO	3.86
			Hogan Air Inc, Hamilton OH	5.86
		(N74HA)	ntu: Hogan Air Inc, Hamilton OH	7.86
		N220WH	James G. Branam, Gatlinburg TN	6.87
			Tol Air Services, San Juan, Puerto Rico	4.90
		N779T	Tol Air Inc, San Juan Puerto Rico	23.5.90/99
			MBD Corp, San Juan Puerto Rico	8.2.99/13
			op: Tol Air Inc, San Juan, Puerto RIco	99/10
			(retired, stripped, San Juan, Puerto Rico 12/13)	
			reg expired 31.12.13, struck-off USCR	24.1.18
	N779T no N779T no N779T ph	oted St Croix U oted San Juan noto in service	d separately both as BA-618 in USCR 69 & 70; SVI 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired ove merter also quotes N2290 for BA-618: RP confirms is misp	
BA-619	N779T no N779T no N779T ph Beech 18	oted St Croix U oted San Juan noto in service	SVI 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired over merter also quotes N2290 for BA-618: RP confirms is misp Roscoe Turner Aeronautical Corp: CofA issued	29.10.62
BA-619	N779T no N779T no N779T ph Beech 18	oted St Croix United San Juan Inted San Juan Inted in service by Robert Par  N700M (2  N708M	SVI 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmerter also quotes N2290 for BA-618: RP confirms is misp  Roscoe Turner Aeronautical Corp: CofA issued Inland Container Corp, Indianapolis IN rereg	29.10.62 12.62/66
BA-619	N779T no N779T no N779T ph Beech 18	oted St Croix United San Juan Intel San Juan Intel Int	SVI 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmenter also quotes N2290 for BA-618: RP confirms is mispersonal container Aeronautical Corp: CofA issued Inland Container Corp, Indianapolis IN rereg S. J. Groves & Sons, Liverpool NY	29.10.62 12.62/66 69/72
BA-619	N779T no N779T no N779T ph Beech 18	oted St Croix United San Juan Inted San Juan Inted in service by Robert Par  N700M (2  N708M	SVI 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmenter also quotes N2290 for BA-618: RP confirms is mispersonal container Aeronautical Corp: CofA issued Inland Container Corp, Indianapolis IN rereg S. J. Groves & Sons, Liverpool NY Banlee Travel, Rehoboth DE	29.10.62 12.62/66 69/72 79
BA-619	N779T no N779T no N779T ph Beech 18	oted St Croix United San Juan Intel San Juan Intel Int	SVI 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmenter also quotes N2290 for BA-618: RP confirms is misperson and container Aeronautical Corp: CofA issued Inland Container Corp, Indianapolis IN rereg S. J. Groves & Sons, Liverpool NY Banlee Travel, Rehoboth DE Jerry L. Englund/ Englund Aviation, Mobile AL	29.10.62 12.62/66 69/72 79 2.88/91
BA-619	N779T no N779T no N779T ph Beech 18	oted St Croix United San Juan Intel San Juan Intel Int	SVI 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmerter also quotes N2290 for BA-618: RP confirms is misperson and container Corp, Indianapolis IN rereg S. J. Groves & Sons, Liverpool NY Banlee Travel, Rehoboth DE Jerry L. Englund/ Englund Aviation, Mobile AL Richard L. Jack, Mount Pleasant MI	29.10.62 12.62/66 69/72 79 2.88/91 3.92/96
BA-619	N779T no N779T no N779T ph Beech 18	oted St Croix United San Juan Intel San Juan Intel Int	SVI 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmerter also quotes N2290 for BA-618: RP confirms is misperson and container Corp, Indianapolis IN rereg S. J. Groves & Sons, Liverpool NY Banlee Travel, Rehoboth DE Jerry L. Englund/ Englund Aviation, Mobile AL Richard L. Jack, Mount Pleasant MI James W. Boyd, Sioux City IA	29.10.62 12.62/66 69/72 79 2.88/91 3.92/96 12.96/99
BA-619	N779T no N779T no N779T ph Beech 18	oted St Croix United San Juan Intel San Juan Intel Int	SVI 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmerter also quotes N2290 for BA-618: RP confirms is mispered in the second state of the s	29.10.62 12.62/66 69/72 79 2.88/91 3.92/96 12.96/99 17.7.00/21
BA-619	N779T no N779T no N779T ph Beech 18 H18 trigear	nted St Croix United San Juan Indto in service by Robert Par  N700M (2  N708M  N502W  N50225	SVI 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmerter also quotes N2290 for BA-618: RP confirms is mispermerter also quotes N2290 for BA-618: RP confirms is mispermerter also quotes N2290 for BA-618: RP confirms is mispermerter also quotes N2290 for BA-618: RP confirms is mispermerter also quotes N2290 for BA-618: RP confirms is mispermerter also quotes N290 for BA-618: RP conf	29.10.62 12.62/66 69/72 79 2.88/91 3.92/96 12.96/99
BA-619	N779T no N779T no N779T ph Beech 18 H18 trigear	oted St Croix United San Juan Intel San Juan Intel Int	SVI 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmerter also quotes N2290 for BA-618: RP confirms is mispermerter also quotes N2290 for BA-618: RP confirms is mispermerter also quotes N2290 for BA-618: RP confirms is mispermerter also quotes N2290 for BA-618: RP confirms is mispermerter also quotes N2290 for BA-618: RP confirms is mispermerter also quotes N290 for BA-618: RP conf	29.10.62 12.62/66 69/72 79 2.88/91 3.92/96 12.96/99 17.7.00/21
	N779T no N779T no N779T ph Beech 18 H18 trigear	nted St Croix United San Juan Indto in service by Robert Par  N700M (2  N708M  N502W  N50225	SVI 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmerter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N290 for BA-618: RP confi	29.10.62 12.62/66 69/72 79 2.88/91 3.92/96 12.96/99 17.7.00/21 3.1.22
	N779T no N779T no N779T ph Beech 18 H18 trigear	oted St Croix United San Juan Indto in service by Robert Par N700M (2 N708M N502W N50225	SVI 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmerter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N290 for BA-618: RP confirms is mispermenter also quotes N290 for BA-618: RP confirms is mispermenter also quotes IN rereg S. J. Groves & Sons, Liverpool NY Banlee Travel, Rehoboth DE Jerry L. Englund/ Englund Aviation, Mobile AL Richard L. Jack, Mount Pleasant MI James W. Boyd, Sioux City IA FI Systems Inc, Bandon OR reg expired 19.2.21, struck-off USCR ant MI 10.96;  built Tecumseh Products Co, Tecumseh MI	29.10.62 12.62/66 69/72 79 2.88/91 3.92/96 12.96/99 17.7.00/21 3.1.22
	N779T no N779T no N779T ph Beech 18 H18 trigear	oted St Croix United San Juan Index San Juan Index San Juan Index San Juan Index San I	SVI 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmerter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N290 for BA-618: RP confirms is mispermenter also quotes N290 for BA-618: RP confirms is mispermenter also quotes IN rereg S. J. Groves & Sons, Liverpool NY Banlee Travel, Rehoboth DE Jerry L. Englund/ Englund Aviation, Mobile AL Richard L. Jack, Mount Pleasant MI James W. Boyd, Sioux City IA FI Systems Inc, Bandon OR reg expired 19.2.21, struck-off USCR ant MI 10.96;  built Tecumseh Products Co, Tecumseh MI Georgia Pacific Corp, Portland OR	29.10.62 12.62/66 69/72 79 2.88/91 3.92/96 12.96/99 17.7.00/21 3.1.22
	N779T no N779T no N779T ph Beech 18 H18 trigear	oted St Croix United San Juan Indto in service by Robert Par N700M (2 N708M N502W N50225	SVI 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmerter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N290 for BA-618: RP confirms is mispermenter also quotes N290 for BA-618: RP confirms is mispermenter also quotes IN rereg S. J. Groves & Sons, Liverpool NY Banlee Travel, Rehoboth DE Jerry L. Englund/ Englund Aviation, Mobile AL Richard L. Jack, Mount Pleasant MI James W. Boyd, Sioux City IA FI Systems Inc, Bandon OR reg expired 19.2.21, struck-off USCR ant MI 10.96;  built Tecumseh Products Co, Tecumseh MI	29.10.62 12.62/66 69/72 79 2.88/91 3.92/96 12.96/99 17.7.00/21 3.1.22
	N779T no N779T no N779T ph Beech 18  H18 trigear  N50225 n	oted St Croix United San Juan India in service by Robert Par N700M (2 N708M N502W N50225 N50225 N9539Y N955GP	SVI 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmerter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N2290 for BA-618: RP confirms is mispermenter also quotes N290 for BA-618: RP conf	29.10.62 12.62/66 69/72 79 2.88/91 3.92/96 12.96/99 17.7.00/21 3.1.22 11.62 63/66 69/72 75/78
BA-620	N779T no N779T no N779T ph Beech 18  H18 trigear  N50225 n  H18	nted St Croix United San Juan Index In Service by Robert Par N700M (2 N708M N502W N50225 N50225 N9539Y N955GP	SVÍ 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmerter also quotes N2290 for BA-618: RP confirms is misperated and container Corp, Indianapolis IN rereg S. J. Groves & Sons, Liverpool NY Banlee Travel, Rehoboth DE Jerry L. Englund/ Englund Aviation, Mobile AL Richard L. Jack, Mount Pleasant MI James W. Boyd, Sioux City IA FI Systems Inc, Bandon OR reg expired 19.2.21, struck-off USCR ant MI 10.96;  built Tecumseh Products Co, Tecumseh MI Georgia Pacific Corp, Portland OR Northern Flying Service, Pontiac MI struck-off USCR	29.10.62 12.62/66 69/72 79 2.88/91 3.92/96 12.96/99 17.7.00/21 3.1.22 11.62 63/66 69/72 75/78 10.3.78
BA-620	N779T no N779T no N779T ph Beech 18  H18 trigear  N50225 n	oted St Croix United San Juan Index	SVÍ 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmerter also quotes N2290 for BA-618: RP confirms is misperated and container Corp, Indianapolis IN rereg S. J. Groves & Sons, Liverpool NY Banlee Travel, Rehoboth DE Jerry L. Englund/ Englund Aviation, Mobile AL Richard L. Jack, Mount Pleasant MI James W. Boyd, Sioux City IA FI Systems Inc, Bandon OR reg expired 19.2.21, struck-off USCR ant MI 10.96;  built Tecumseh Products Co, Tecumseh MI Georgia Pacific Corp, Portland OR Northern Flying Service, Pontiac MI struck-off USCR  bolis IN 30.5.76;  Beech Aircraft Corp, Wichita KS: CofA issued	29.10.62 12.62/66 69/72 79 2.88/91 3.92/96 12.96/99 17.7.00/21 3.1.22 11.62 63/66 69/72 75/78 10.3.78
BA-620 BA-621	N779T no N779T no N779T ph Beech 18  H18 trigear  N50225 n  H18	nted St Croix United San Juan Inted San Juan Inted San Juan Inted Intervice by Robert Par N700M (2 N708M N502W N50225 N50225 N5056P	SVÍ 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmerter also quotes N2290 for BA-618: RP confirms is misperated and container Corp, Indianapolis IN rereg S. J. Groves & Sons, Liverpool NY Banlee Travel, Rehoboth DE Jerry L. Englund/ Englund Aviation, Mobile AL Richard L. Jack, Mount Pleasant MI James W. Boyd, Sioux City IA FI Systems Inc, Bandon OR reg expired 19.2.21, struck-off USCR  ant MI 10.96;  built Tecumseh Products Co, Tecumseh MI Georgia Pacific Corp, Portland OR Northern Flying Service, Pontiac MI struck-off USCR  bolis IN 30.5.76;  Beech Aircraft Corp, Wichita KS: CofA issued E. I. duPont de Nemours & Co, Wilmington DE	29.10.62 12.62/66 69/72 79 2.88/91 3.92/96 12.96/99 17.7.00/21 3.1.22 11.62 63/66 69/72 75/78 10.3.78
BA-620	N779T no N779T no N779T ph Beech 18  H18 trigear  N50225 n  H18	nted St Croix United San Juan Inted San Juan Inted San Juan Inted Interest	SVÍ 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmerter also quotes N2290 for BA-618: RP confirms is misperater also quotes N2290 for BA-618: RP confirms is misperater also quotes N2290 for BA-618: RP confirms is misperater also quotes N2290 for BA-618: RP confirms is misperater also quotes N2290 for BA-618: RP confirms is misperater also quotes N2290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes IN received N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP co	29.10.62 12.62/66 69/72 79 2.88/91 3.92/96 12.96/99 17.7.00/21 3.1.22 11.62 63/66 69/72 75/78 10.3.78
BA-620	N779T no N779T no N779T ph Beech 18  H18 trigear  N50225 n  H18	nted St Croix United San Juan Inted San Juan Inted San Juan Inted Intervice by Robert Par N700M (2 N708M N502W N50225 N50225 N5056P	SVÍ 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmerter also quotes N2290 for BA-618: RP confirms is misperater also quotes N2290 for BA-618: RP confirms is misperater also quotes N2290 for BA-618: RP confirms is misperater also quotes N2290 for BA-618: RP confirms is misperater also quotes N2290 for BA-618: RP confirms is misperater also quotes N2290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes IN received N290 for BA-618: RP confirms is misperater also quotes IN received N290 for BA-618: RP confirms is misperater also quotes IN received N290 for BA-618: RP confirms is misperater also quotes IN received N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes IN received N290 for BA-618: RP confirms is misperater also quotes IN received N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes R	29.10.62 12.62/66 69/72 79 2.88/91 3.92/96 12.96/99 17.7.00/21 3.1.22 11.62 63/66 69/72 75/78 10.3.78
BA-620	N779T no N779T no N779T ph Beech 18  H18 trigear  N50225 n  H18	nted St Croix United San Juan Inted San Juan Inted San Juan Inted Interest	SVÍ 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmerter also quotes N2290 for BA-618: RP confirms is misp.  Roscoe Turner Aeronautical Corp: CofA issued Inland Container Corp, Indianapolis IN rereg S. J. Groves & Sons, Liverpool NY Banlee Travel, Rehoboth DE Jerry L. Englund/ Englund Aviation, Mobile AL Richard L. Jack, Mount Pleasant MI James W. Boyd, Sioux City IA FI Systems Inc, Bandon OR reg expired 19.2.21, struck-off USCR  ant MI 10.96;  built Tecumseh Products Co, Tecumseh MI Georgia Pacific Corp, Portland OR Northern Flying Service, Pontiac MI struck-off USCR  bolis IN 30.5.76;  Beech Aircraft Corp, Wichita KS: CofA issued E. I. duPont de Nemours & Co, Wilmington DE State of Ohio Highways Dept., Columbus OH State of Ohio, Columbus OH Air Service Centre Inc, Hamilton OH	29.10.62 12.62/66 69/72 79 2.88/91 3.92/96 12.96/99 17.7.00/21 3.1.22 11.62 63/66 69/72 75/78 10.3.78
BA-620	N779T no N779T no N779T ph Beech 18  H18 trigear  N50225 n  H18	nted St Croix United San Juan Inted San Juan Inted San Juan Inted Interest	SVÍ 1.98 "Tolair"; PR 16.6.00 all metal, op by Tolair; Tol Air at Puerto Rico 5.10, all metallic, windows faired overmerter also quotes N2290 for BA-618: RP confirms is misperater also quotes N2290 for BA-618: RP confirms is misperater also quotes N2290 for BA-618: RP confirms is misperater also quotes N2290 for BA-618: RP confirms is misperater also quotes N2290 for BA-618: RP confirms is misperater also quotes N2290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes IN received N290 for BA-618: RP confirms is misperater also quotes IN received N290 for BA-618: RP confirms is misperater also quotes IN received N290 for BA-618: RP confirms is misperater also quotes IN received N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes IN received N290 for BA-618: RP confirms is misperater also quotes IN received N290 for BA-618: RP confirms is misperater also quotes N290 for BA-618: RP confirms is misperater also quotes R	29.10.62 12.62/66 69/72 79 2.88/91 3.92/96 12.96/99 17.7.00/21 3.1.22 11.62 63/66 69/72 75/78 10.3.78

River City Aviation, Cape Girardeau MO	7.92
Jim Hankins Air Service, Jackson MS	1.93
Jack C. Fisher, Mayfield KY	10.93/95
Susan Dacy/ S. Dacy Enterprises Inc. Harvard IL	3.8.98/20

N360H at fly-in Oshkosh WI 1.8.91;

N360H noted Janesville-Rock County WI 2.8.98;

N360H at Beech fly-in Tullahoma TN 10.93;

N360H at Beech fly-in Tullahoma TN 16.10.98 tailwheel, owned Susan Dacy;

N360H noted Janesville WI 26.7.99,

N360H noted Janesville WI 10.8.02 plate BA-621;

N360H noted Janesville WI 23.7.03

N360H at Beech fly-in Tullahoma TN 16.10.03;

BA-622	H18	N51K (2	built	10.62
J <b></b>			Rockford Screw Products Co. Rockford IL	63/64
		N518K	Greenlee Bros & Co. Rockford IL	66/72
			Joseph P. Navik, Rochester NY	2.12.77/81
			crashed destroyed by fire landing, Fort Lauderdale FL	13.8.81
BA-623	H18	N555CB (2 N5559B	Cleveland Brothers Equipment Co, Harrisbburg PA rereg	9.62/64
		N390R	Otis Redding Enterprises Inc, Macon GA	31.10.67
			crashed into Lake Monoma, near Madison WI (7 killed, including singer Otis Redding)	10.12.67

N555CB noted at Wichita KS 3.9.62 just rolled off production line;

Published 1966 USCR: not listed any reg;

10.12.67 accident report: entered spin in fog and crashed into water of Lake Monoma during landing approach to Madison WI; Otis Redding and 4 members of his Bar-Keys band were killed;

BA-624	H18	SU-ANH	Eastern Petroleum	2.63/66
			crashed near Cairo	20.3.66
BA-625	H18	N9614Y	built	11.62
			Atlantic Aviation Corp, Teterboro NJ	63
			National Financing Inc, Wilmington DE	64/66
		N18T (3	Addison Products Co, Addison TX	69/72
		N18TK	Smith Aero Service, Montgomery AL	79
			Springfield Air Service, Springfield MA	79/83
			Bowman Aviation, Anderson SC	8.83
		N29BA	Bo-S-Aire Airlines Inc, Anderson SC	11.83/89
			Don Haynes Aviation, Anderson SC	8.88/89
			struck-off USCR	2.89
			Jacob C. Bowman, Anderson SC: rest. to USCR	1.91
			Hinchinbrook Equipment Co, Palmer AK	4.10.91/99
			Nevada Direct Leasing Corp, Carson City NV	15.9.99/02
			op: New Horizons Telecom Inc, Palmer AK	00
			Matthew J. Ziomek, Kingman AZ	19.5.04/06
			Aero Flite Inc, Kingman AZ	6.6.06/12
			ATC Aero LLC, Kingman AZ	25.7.12/20

N18TK noted Fort Wayne IN 28.5.76;

N18TK noted Cleveland OH 16.9.82 Springfield Air Service;

N29BA noted Palmer AK 8.94, tailwheel, no windows, in service;

BA-626	H18	N2345Z	built	11.62	_
			Furrs Realty Co, Lubbock TX	63/64	
			Cecil Ruby Co, Austin TX	66	
			Executive Air Service, Alexandria VA	69	
			Joseph Fontana/ Fontana Aviation, Iron Mountain MI	3.11.69/70	
			crashed destroyed landing. Lansing MI	23.12.70	

accident report 23.12.70: Fontana Aviation, flight Iron Mountain to Lansing MI, stalled on approach due airframe icing, 1am in fog & freezing rain;

BA-627	H18	N166A	built	9.62
		N517DC	L. C. Cassidy & Son Inc, Clearwater FL	63/64
	trigear		(Volpar Trigear installed early .63 by Volitan Aviation,	
			Pacoima CA: first H18 to have trigear, prior to	
			factory installation which commenced late 63)	
			crashed during forced landing off-airport due	
			engine failure on takeoff, Cincinatti-Lunken OH	9.8.64
		N4746G	James J. Coulas, Chicago IL	66/69
			(flew Keflavik-Prestwick 10.6.67 then Dublin, Gatwick)	
			Weldbend Corp, Chicago IL	70/79
			Oklahoma Aircraft Sales, Yukon OK	9.81
			James E. Dodd, Miami FL	4.82
			Daniel G. Doumis, Fort Myers FL	6.84
			Morgan T. James, Coral Gables FL	4.86
			Daniel G. Doumis, Fort Myers FL	91
			Valerie Balubar, Hayward CA	14.11.91/92
			sold to Philippines, struck-off USCR	14.2.92
		RP-C3737	reg	.92
			CofA expired 22.2.93, struck-off Register	11.11.98

N517DC was first H18 converted to Volpar trigear at Volpar .63, then delivered to pilot Col Rosco Turner of the L.C.Cassidy & Sons Flight Dept, Indianapois IN;

N4746G flew Keflavik-Prestwick 11.6.67, to Glasgow 11.6.67;

N4746G noted Dublin, Ireland 12.6.67 trigear, from Glasgow, to Liverpool; at Elmdon 14.6.67;

N4746G noted Gatwick 15.6.67, 17.6.67 trigear;

N4746G noted Opa Locka FL 6.10.68 trigear;

N4746G noted Indianapolis IN 30.5.76;

BA-628	H18	N1481G	Beech Aircraft Corp, Wichita KS: CofA issued	31.10.62
			Schneck Engine Service & Supply, Rockford IL	63
			Sealed Power Corp, Muskegon MI	66
			General Aviation Inc, Lansing MI	69/78
			Aero Taxi-Rockford Inc, Rockford IL	14.4.84/00
			Blackstone Rotorcraft Inc, Hartselle AL	12.3.01/06
			David Robertson, Cullman AL	26.2.08/15
			struck-off USCR	14.5.15

N1481G noted Deer Valley AZ 7.11.68;

N1481G noted Rockford IL 8.00, tailwheel;

N1481G noted Rockford IL 7.91 at Aero Taxi ramp;

N1481G noted Tucson AZ 9.95;

N1481G noted Huntsville AL 10.98 Aero Taxi Rockford;

N1481G noted Rockford IL 26.7.99 Aero Taxi, usually based Huntsville AL:

BA-629	H18	N228A	Beech Aircraft Corp, Wichita KS: CofA issued	12.11.62
			United Airmotive Distributors, Wichita KS	63/64
			Coca Cola Bottling Co, Fort Worth TX	66
			Ryan Mortgage Corp, Fort Worth TX	69
			Dan Futrell, Nashville AR	70
			W. F. Larson Inc, Plainview TX	71/72
			Meridan Aviation, Salt Lake City UT	79
			ACE Air Cargo Express Inc, Cleveland OH	11.85/86
			Johnson Aviation Co, Elyria OH	5.88
			James D. Rowe/ Bering Air, Nome AK	1.11.88/99
			crashed, nosed over on to back during landing,	
			White Mountain AK	24.8.91
			Turbo North Aviation, Anchorage AK	.00
			Bellair Inc, Fairbanks AK	31.7.00
			Aerolease of America Inc, Carson City NV	9.10.01
			Methow Aviation, Burlington WA	20.3.02/05
			Engen Farms LLC, Mount Vernon WA	10.5.06/07
			James M. Walker, Henderson NV	23.6.09/18

struck-off USCR 25.8.18

N228A noted Dallas-Love TX 2.10.71; N228A noted Ephrata WA 12.8.03 "Methow" titles, tailwheel, in service; N228A noted Chino CA 8.11 with engines and nose removed, "Methow" titles part removed;

D.A. 000	1140	NOOD (O		40.44.00
BA-630	H18	N82D (2	Youngstown Airways/ Lease Air, Youngstown OH: CofA Wean Engineering Co, Warren OH	16.11.62 63/64
			Lease Air Inc, Youngstown OH	66
		N8217	SMB Stage Line Inc, Des Moines IA	69/80
		110217	Universal Aircraft Sales, Detroit MI	.80
			Charles J. Toman, Painesville OH	6.89
		N368HC	Charles J. Toman, Painesville OH	6.90/91
		11000110	Jim Hankins Air Service, Jackson MS	2.5.95/19
			(rest. project at Jackson MS 97/05, painted N8217)	2.0.00, 10
			struck-off USCR	17.1.19
	N8217 no N8217 no N8217 no N8217 no	oted Jackson Noted Jackson Noted Jackson Noted Jackson Noted Jackson-	e OK 2.3.73 SMB Stage Line maintenance base; MS 18.7.97 stripped hulk; MS 11.8.98, fuselage on undercarriage, Hankins AS; MS 1.8.02 restoration project; Hawkins Field MS 5.8.03 JHAS, just fuselage on gear, park	
			Hawkins Field MS 16.8.05 engine tail & outer wings remove Hawkins Field MS 5.8.08, fuselage in storage;	ed;
	710277 770	21.00 000NOO11 1	Tamane From Me 6.6.60, raddage m dierage,	
BA-631	H18	N50L (2	built	10.62
			Transcontinental Gas Pipe Line Corp, Houston TX	63/66
		N5012	Transcontinental Gas Pipe Line Corp, Houston TX	69
			Joseph Fontana/ Fontana Aviation, Iron Mountain MI	70/74
		N72FA	crashed dest. landing, Iron Mountain MI	17.10.74
			17.10.74: Fontana Aviation: mail flight from Lansing MI, str	uck terrain on
DA 622	approach	1.51am for la	nding, pilot k;	
BA-632			built, CofA issued	25.7.62
BA-632	approach	1.51am for la	built, CofA issued South Lake Farms, Fresno CA	25.7.62 63/66
BA-632	approach	1.51am for la	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA	25.7.62 63/66 69/72
BA-632	approach	1.51am for la	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA	25.7.62 63/66 69/72 78
BA-632	approach	1.51am for la	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA ACE Air Cargo Express Inc, Cleveland OH	25.7.62 63/66 69/72
BA-632	approach	1.51am for la	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA	25.7.62 63/66 69/72 78
BA-632	approach H18  confirmed	N989B N989B	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA ACE Air Cargo Express Inc, Cleveland OH crashed on landing, destroyed by fire, Kansas City-Downtown MO	25.7.62 63/66 69/72 78 21.11.78/88
BA-632 BA-633	approach H18  confirmed	N989B N989B	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA ACE Air Cargo Express Inc, Cleveland OH crashed on landing, destroyed by fire, Kansas City-Downtown MO	25.7.62 63/66 69/72 78 21.11.78/88
	H18  confirmed N989B no	n 1.51am for la N989B d as always tal oted San Anto.	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA ACE Air Cargo Express Inc, Cleveland OH crashed on landing, destroyed by fire, Kansas City-Downtown MO  ilgear; nio TX 16.5.73;  Atlantic Aviation Corp, Wilmington DE Dentists Supply Co of New York, York PA	25.7.62 63/66 69/72 78 21.11.78/88 1.4.88
	H18  confirmed N989B no	n 1.51am for la N989B d as always tai oted San Anto. N1551S	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA ACE Air Cargo Express Inc, Cleveland OH crashed on landing, destroyed by fire, Kansas City-Downtown MO  ilgear; nio TX 16.5.73;  Atlantic Aviation Corp, Wilmington DE Dentists Supply Co of New York, York PA Dentsply International Inc, York PA	25.7.62 63/66 69/72 78 21.11.78/88 1.4.88
	H18  confirmed N989B no	n 1.51am for la N989B d as always tal oted San Anto.	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA ACE Air Cargo Express Inc, Cleveland OH crashed on landing, destroyed by fire, Kansas City-Downtown MO  ilgear; nio TX 16.5.73;  Atlantic Aviation Corp, Wilmington DE Dentists Supply Co of New York, York PA Dentsply International Inc, York PA Canadian Auto Market, Montreal QUE	25.7.62 63/66 69/72 78 21.11.78/88 1.4.88 8.63 64/70 71/72 12.72
	H18  confirmed N989B no	n 1.51am for la N989B d as always tai oted San Anto. N1551S	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA ACE Air Cargo Express Inc, Cleveland OH crashed on landing, destroyed by fire, Kansas City-Downtown MO  ilgear; nio TX 16.5.73;  Atlantic Aviation Corp, Wilmington DE Dentists Supply Co of New York, York PA Dentsply International Inc, York PA Canadian Auto Market, Montreal QUE Provincial Aviation Inc, Montreal-Dorval QUE	25.7.62 63/66 69/72 78 21.11.78/88 1.4.88 8.63 64/70 71/72 12.72 74
	H18  confirmed N989B no	n 1.51am for la N989B d as always tai oted San Anto. N1551S	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA ACE Air Cargo Express Inc, Cleveland OH crashed on landing, destroyed by fire, Kansas City-Downtown MO  ilgear; nio TX 16.5.73;  Atlantic Aviation Corp, Wilmington DE Dentists Supply Co of New York, York PA Dentsply International Inc, York PA Canadian Auto Market, Montreal QUE Provincial Aviation Inc, Montreal-Dorval QUE op: Air Amos	25.7.62 63/66 69/72 78 21.11.78/88 1.4.88 8.63 64/70 71/72 12.72 74 81
	H18  confirmed N989B no	n 1.51am for la N989B d as always tar oted San Anto N1551S CF-FTB	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA ACE Air Cargo Express Inc, Cleveland OH crashed on landing, destroyed by fire, Kansas City-Downtown MO  ilgear; nio TX 16.5.73;  Atlantic Aviation Corp, Wilmington DE Dentists Supply Co of New York, York PA Dentsply International Inc, York PA Canadian Auto Market, Montreal QUE Provincial Aviation Inc, Montreal-Dorval QUE op: Air Amos Air Saguenay, Lake Sebastian QUE	25.7.62 63/66 69/72 78 21.11.78/88 1.4.88 8.63 64/70 71/72 12.72 74 81 81/82
	H18  confirmed N989B no	n 1.51am for la N989B d as always tai oted San Anto. N1551S	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA ACE Air Cargo Express Inc, Cleveland OH crashed on landing, destroyed by fire, Kansas City-Downtown MO  ilgear; nio TX 16.5.73;  Atlantic Aviation Corp, Wilmington DE Dentists Supply Co of New York, York PA Dentsply International Inc, York PA Canadian Auto Market, Montreal QUE Provincial Aviation Inc, Montreal-Dorval QUE op: Air Amos Air Saguenay, Lake Sebastian QUE Sept-Iles Aero Club, Sept-Iles QUE	25.7.62 63/66 69/72 78 21.11.78/88 1.4.88 8.63 64/70 71/72 12.72 74 81 81/82 83
	H18  confirmed N989B no	n 1.51am for la N989B d as always tar oted San Anto N1551S CF-FTB	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA ACE Air Cargo Express Inc, Cleveland OH crashed on landing, destroyed by fire, Kansas City-Downtown MO  ilgear; nio TX 16.5.73;  Atlantic Aviation Corp, Wilmington DE Dentists Supply Co of New York, York PA Dentsply International Inc, York PA Canadian Auto Market, Montreal QUE Provincial Aviation Inc, Montreal-Dorval QUE op: Air Amos Air Saguenay, Lake Sebastian QUE Sept-Iles Aero Club, Sept-Iles QUE Aviation Quebec Labrador Ltee, Sept-Iles QUE	25.7.62 63/66 69/72 78 21.11.78/88 1.4.88 8.63 64/70 71/72 12.72 74 81 81/82 83 12.83/87
	H18  confirmed N989B no	n 1.51am for la N989B d as always tar oted San Anto N1551S CF-FTB	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA ACE Air Cargo Express Inc, Cleveland OH crashed on landing, destroyed by fire, Kansas City-Downtown MO  ilgear; nio TX 16.5.73;  Atlantic Aviation Corp, Wilmington DE Dentists Supply Co of New York, York PA Dentsply International Inc, York PA Canadian Auto Market, Montreal QUE Provincial Aviation Inc, Montreal-Dorval QUE op: Air Amos Air Saguenay, Lake Sebastian QUE Sept-Iles Aero Club, Sept-Iles QUE Aviation Quebec Labrador Ltee, Sept-Iles QUE Aviation Maintenance Ltd, Sault Ste Marie ONT	25.7.62 63/66 69/72 78 21.11.78/88 1.4.88 1.4.88 8.63 64/70 71/72 12.72 74 81 81/82 83 12.83/87 88/93
	H18  confirmed N989B no	n 1.51am for la  N989B  d as always tar oted San Anto  N1551S  CF-FTB  C-FFTB	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA ACE Air Cargo Express Inc, Cleveland OH crashed on landing, destroyed by fire, Kansas City-Downtown MO  ilgear; nio TX 16.5.73;  Atlantic Aviation Corp, Wilmington DE Dentists Supply Co of New York, York PA Dentsply International Inc, York PA Canadian Auto Market, Montreal QUE Provincial Aviation Inc, Montreal-Dorval QUE op: Air Amos Air Saguenay, Lake Sebastian QUE Sept-Iles Aero Club, Sept-Iles QUE Aviation Quebec Labrador Ltee, Sept-Iles QUE Aviation Maintenance Ltd, Sault Ste Marie ONT sold to USA, struck-off Canadian Register	25.7.62 63/66 69/72 78 21.11.78/88 1.4.88 1.4.88 8.63 64/70 71/72 12.72 74 81 81/82 83 12.83/87 88/93 5.93
	H18  confirmed N989B no	n 1.51am for la N989B d as always tar oted San Anto N1551S CF-FTB	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA ACE Air Cargo Express Inc, Cleveland OH crashed on landing, destroyed by fire, Kansas City-Downtown MO  ilgear; nio TX 16.5.73;  Atlantic Aviation Corp, Wilmington DE Dentists Supply Co of New York, York PA Dentsply International Inc, York PA Canadian Auto Market, Montreal QUE Provincial Aviation Inc, Montreal-Dorval QUE op: Air Amos Air Saguenay, Lake Sebastian QUE Sept-Iles Aero Club, Sept-Iles QUE Aviation Quebec Labrador Ltee, Sept-Iles QUE Aviation Maintenance Ltd, Sault Ste Marie ONT sold to USA, struck-off Canadian Register Glen Johnson, Fort Worth TX	25.7.62 63/66 69/72 78 21.11.78/88 1.4.88 1.4.88 8.63 64/70 71/72 12.72 74 81 81/82 83 12.83/87 88/93
	H18  confirmed N989B no	n 1.51am for la  N989B  d as always tar oted San Anto  N1551S  CF-FTB  C-FFTB	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA ACE Air Cargo Express Inc, Cleveland OH crashed on landing, destroyed by fire, Kansas City-Downtown MO  ilgear; nio TX 16.5.73;  Atlantic Aviation Corp, Wilmington DE Dentists Supply Co of New York, York PA Dentsply International Inc, York PA Canadian Auto Market, Montreal QUE Provincial Aviation Inc, Montreal-Dorval QUE op: Air Amos Air Saguenay, Lake Sebastian QUE Sept-Iles Aero Club, Sept-Iles QUE Aviation Quebec Labrador Ltee, Sept-Iles QUE Aviation Maintenance Ltd, Sault Ste Marie ONT sold to USA, struck-off Canadian Register Glen Johnson, Fort Worth TX (US CofA renewed 12.5.93)	25.7.62 63/66 69/72 78 21.11.78/88 1.4.88 1.4.88 8.63 64/70 71/72 12.72 74 81 81/82 83 12.83/87 88/93 5.93 4.5.93/06
	H18  confirmed N989B no	N989B  d as always tai oted San Anto  N1551S  CF-FTB  C-FFTB  N6GJ	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA ACE Air Cargo Express Inc, Cleveland OH crashed on landing, destroyed by fire, Kansas City-Downtown MO  ilgear; nio TX 16.5.73;  Atlantic Aviation Corp, Wilmington DE Dentists Supply Co of New York, York PA Dentsply International Inc, York PA Canadian Auto Market, Montreal QUE Provincial Aviation Inc, Montreal-Dorval QUE op: Air Amos Air Saguenay, Lake Sebastian QUE Sept-Iles Aero Club, Sept-Iles QUE Aviation Quebec Labrador Ltee, Sept-Iles QUE Aviation Maintenance Ltd, Sault Ste Marie ONT sold to USA, struck-off Canadian Register Glen Johnson, Fort Worth TX (US CofA renewed 12.5.93) CJ Aviation Services, Wilmington DE	25.7.62 63/66 69/72 78 21.11.78/88 1.4.88 1.4.88 8.63 64/70 71/72 12.72 74 81 81/82 83 12.83/87 88/93 5.93 4.5.93/06 5.10.10/12
	H18  confirmed N989B no	n 1.51am for la  N989B  d as always tar oted San Anto  N1551S  CF-FTB  C-FFTB	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA ACE Air Cargo Express Inc, Cleveland OH crashed on landing, destroyed by fire, Kansas City-Downtown MO  ilgear; nio TX 16.5.73;  Atlantic Aviation Corp, Wilmington DE Dentists Supply Co of New York, York PA Dentsply International Inc, York PA Canadian Auto Market, Montreal QUE Provincial Aviation Inc, Montreal-Dorval QUE op: Air Amos Air Saguenay, Lake Sebastian QUE Sept-lles Aero Club, Sept-lles QUE Aviation Quebec Labrador Ltee, Sept-lles QUE Aviation Maintenance Ltd, Sault Ste Marie ONT sold to USA, struck-off Canadian Register Glen Johnson, Fort Worth TX (US CofA renewed 12.5.93) CJ Aviation Services, Wilmington DE CJ Aviation Services, Wilmington DE	25.7.62 63/66 69/72 78 21.11.78/88 1.4.88 1.4.88 8.63 64/70 71/72 12.72 74 81 81/82 83 12.83/87 88/93 5.93 4.5.93/06 5.10.10/12 12/17
	H18  confirmed N989B no	N989B  d as always tai oted San Anto  N1551S  CF-FTB  C-FFTB  N6GJ	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA ACE Air Cargo Express Inc, Cleveland OH crashed on landing, destroyed by fire, Kansas City-Downtown MO  ilgear; nio TX 16.5.73;  Atlantic Aviation Corp, Wilmington DE Dentists Supply Co of New York, York PA Dentsply International Inc, York PA Canadian Auto Market, Montreal QUE Provincial Aviation Inc, Montreal-Dorval QUE op: Air Amos Air Saguenay, Lake Sebastian QUE Sept-Iles Aero Club, Sept-Iles QUE Aviation Quebec Labrador Ltee, Sept-Iles QUE Aviation Maintenance Ltd, Sault Ste Marie ONT sold to USA, struck-off Canadian Register Glen Johnson, Fort Worth TX (US CofA renewed 12.5.93) CJ Aviation Services, Wilmington DE	25.7.62 63/66 69/72 78 21.11.78/88 1.4.88 1.4.88 8.63 64/70 71/72 12.72 74 81 81/82 83 12.83/87 88/93 5.93 4.5.93/06 5.10.10/12

CF-FTB noted Montreal-Dorval QUE 23.8.74; N6GJ noted Bangor ME 7.02 visitor from Texas; N6GJ noted Greenville ME 7.9.02; N62CJ visited Oshkosh WI fly-in 28.7.14; N62CJ at Beech fly-in Tullahoma TN 18.10.14; N62CJ visited Oshkosh 7.17 blue & white, tailwheel; N62CJ visited Beech fly-in, Tullahoma TN 16.10.21, tailwheel;

BA-634	H18	N789LN N744G	Liberty National Life Insurance, Birmingham AL Highway Trailer Industries. Edgerton WI groundlooped on takeoff, gear collapsed,	10.62/66 20.3.67/69
			Chicago-O'Hare IL struck-off USCR	27.10.68 11.2.69
BA-635	H18	N1775G	built Chotin Transportation Inc, New Orleans LA Bodcaw Co, Dallas TX Fontana Aviation, Iron Mountain MI struck-off USCR	4.63 63/64 66/72 11.12.74/77 20.12.77
	N1775G	noted Dallas-L	ove TX 2.10.71;	
BA-636	H18	N1511S	built Galles Motor Co, Albuquerque NM Flexsteel Industries Inc, Dubuque IA Aerospace Products Inc, North Hollywood CA	12.62 63/64 66/72 91
BA-637	H18	N1461G	Southern Airways Co, Atlanta GA Georgia Civil Defense Dept, Atlanta GA Georgia Dept. of Air Transportation, Atlanta GA Starflight Inc, Memphis TN damaged ran off runway on takeoff, Talladega AL crashed destroyed by fire after takeoff, Oklahoma City-Expressway Air Park OK	12.62/63 64/69 70/79 17.7.79/85 11.2.83 5.11.85

N1461G noted Atlanta GA 3.10.68 Pickrick Co;

N1461G accident report 11.2.83: Starlight Inc, ran off runway on takeoff, struck a ditch and undercarriage collapsed: confirms tailwheel, 3 unhurt, explosives in cargo continued to explode for more than an hour after the crash;

N1461G accident report 5.11.85: right engine lost power soon after airborne, aircraft rolled right and struck power lines before impacting ground, destroyed by post-crash fire, 2k;

BA-638	H18	N39V	Beech Aircraft Corp, Wichita KS: CofA issued	4.1.63
			Piedmont Aviation, Winston Salem NC:	9.63/64
	trigear	N200DH	Dobbs Houses Inc, Memphis TN	66
	•	N2009H	Public Leasing Corp, Oklahoma City OK	69/72
			Mercy Flights Inc, Medford OR	78
		N117MF	Mercy Flights Inc, Medford OR	10.78/89
		N117ME	Mercy Flights Inc. Medford OR	3.89
			Doak V. Boreing, Magnolia AR, later Hot Springs AR	8.89/91
			Tom E. Demint/ Astro Airways, Pine Bluff AR	12.93/97
			River City Aviation Inc, Wilmington DE	29.5.97/99
			op: McNeely Charter Service, West Memphis AR	98
			Air Classic Cargo Inc, Spring Hill FL	18.6.99/02
			L J Aviation, Wilmington DE	5.10.04/05
			Monarch Air Group, Palm City FL	9.6.05/12
			nose gear collapsed on landing, Fort Lauderdale FL	4.9.07
			struck-off USCR	7.6.12

N117MF noted Oakland CA 11.11.85 "Mercy Flights Inc" titles, trigear;

N117ME noted Pine Bluff AR 4.96 Astro Airways;

N117ME noted West Memphis AR 4.8.98 McNeely Charter Service, plate: BA-638;

N117ME noted Tallahassie FL 24.5.04;

N117ME noted Kissimmee FL 12.4.05 & 25.4.05: trigear, in service;

BA-639	H18	N9689Y	Beech Aircraft Corp, Wichita KS: CofA issued	10.1.63
			Topeka Aircraft Sales & Service, Topeka KS	9.63/64
			Southern Airways Beechcraft Inc, Atlanta GA	66
			Chiminage Corp. Winter Park FL	69/72

N74JT	White Spot Equipment Co, Huntington Beach CA	79
	op: Code Three Air Cargo	79
	Starr Enterprises Inc, Van Nuys CA	10.9.80/82
	op: Western States Express	81
	crashed on takeoff, Fresno CA	18.6.82

N74JT noted Van Nuys CA 28.8.79 Code Three Air Cargo; N74JT noted Van Nuys 26.7.81; N74JT noted LAX 10.81 large "WSE" logo, windowless freighter, tailwheel; crash 18.6.82: over gross weight, aft CofG;

BA-640	H18	N936S	Sundstrand Corp, Rockford IL	12.63/64
			Crown Steel Products Co, Orrville OH	66
			Kenneth A. Little, Canton OH	69/72
			William D. Burrow, Canton OH	79
			op: B.A.S. Airlines	c81
			Superior Contractors & Assoc., Acworth GA	10.82
			Lanier & Lanier Inc, Acworth GA	19.9.83/91
			struck-off USCR	27.3.91
			Hankins Air Service, Jackson MS: hulk	.98
			(fuselage stored Jackson-Higgins Field MS 98,	
			to be stripped for interior fittings)	

N936S noted Albany County NY 8.71, no titles, tailwheel; N936S noted Jackson-Higgins Field MS 11.8.98, fuselage only, recently purchased by Hankins Air Service from owner in Atlanta area, to strip interior fittings;

BA-641	H18	N269VW	AFLC Inc, Birmingham AL	2.63/66
			Savannah Terminal Inc, Savannah GA	69/70
		CF-RQD	Aviation Sales International Ltd, Montreal QUE	11.72
			Edward R. Hill, Frobisher Bay, Yukon Territory	74
		C-FRQD	Air-Dale Ltd, Sault Ste Marie ONT	78/88
			Great Northern Freight Forwarding Ltd,	
			Sault Ste Marie ONT	12.88/17
			Aviation Maintenance Ltd, Echo Bay ONT	1.3.17/21
		N98JD	Springer Aerospace Ltd, Wilmington DE	17.2.22
			sold back to Canada, struck-off USCR	8.4.22
		C-FRQD	Frank Kelner, Fowler ONT	9.6.22

CF-RQD noted Montreal-Dorval QUE 23.8.74; C-FRQD at fly-in Oshkosh WI 1.8.89, tailwheel, plate BA-641; C-FRQD at fly-in Oshkosh WI 1.8.91;

BA-642	H18	N925J	Beech Aircraft Corp, Wichita KS: CofA issued	25.2.63
			(company demonstrator 63)	
			Amerock Corp, Rockford IL	64/70
			Film Corp of America, Jenkintown PA	71/72
			Thomas E. Christ, Racine WI	79
			op: Check-Air Inc. Milwaukee WI	79
			Indianapolis Air Charter Services, Indianapolis IN	11.83/86
			ACE Air Cargo Express, Cleveland OH	8.8.86/90
			right gear collapsed landing, Philadelphia PA	12.11.86
			Mohican Air Services, Cleveland OH: for spares	97/07
			(dismantled, fuselage dumped Wakeman OH 97/07)	
			struck-off USCR	22.5.13

accident report 12.11.86: owned ACE Air Cargo Express;

fuselage noted Wakeman OH 7.97;

fuselage dumped in bushes Wakeman OH 9.8.99 plate BA-642;

Don Paolucci of Mohican Air Services purchased N8962A, N925J + another from a company at Cleveland-Hopkins as spares only. He has owned Wakeman OH airfield since 1981, still does 2007;

BA-643	H18	N739E	Beech Aircraft Corp, Wichita KS: CofA issued	4.3.63	
			Eaton Manufacturing Co, Cleveland OH	63/64	
		N739F (1	George H. Bailey Co, Fort Wayne IN	66	
		•	Winn Dixie Inc, Charlotte NC	1.66	

N135W (2	Winn Dixie Stores Inc, Jacksonville FL groundloop landing, gear collapsed, Jacksonville FL Winn Dixie Inc, Charlotte NC	2.66/72 3.12.67 78
	gear collapsed landing, Pittsburgh PA	25.1.79
	International Aviation Corp, Minneapolis MN	79
	ACE Air Cargo Express, Cleveland OH	80/86
	struck snowbank taxying, Chicago-O'Hare IL	9.1.81
	minor damage on takeoff, Dayton OH	14.1.85
	Johnson Aviation Co, Elyria OH	5.88
	James D. Rowe/ Bearing Air, Nome AK	1.11.88/99
	damaged ran off runway landing, Deering AK	7.9.90
	Turbo North Aviation, Anchorage AK	22.6.00/05
	Mark W. Bills, Wasilla AK	11.7.05/06
	crashed on landing, Kotzebue AK	27.4.06
	reg pending, Osceola WI: USCR	10/12
	struck-off USCR	30.8.12

N135W noted Tampa FL 25.9.70;

accident report 19.1.81: H18S N134W (assumed this acft) Ace Air Cargo, struck by jetblast behind B747, rolled into snowbank, 7.03am, flight from Detroit;

N135W accident report 14.1.85: Ace Air Cargo Express;

N135W noted Anchorage AK 12.8.00 retired stored, for sale, rep as Bering Air;

N135W noted Anchorage AK 17.4.04, in service;

BA-644	H18	N522	Marathon Oil Co, Findlay OH	9.63/66	
		N2130S	Florida Development Commission, Tallahassie FL	69	
			State of Florida, Tallahassie FL	70/72	
		N18AW	Bailey Leasing Corp, Fort Wayne IN	79	
			Mark H. Thompson, Marietta GA	6.82/83	
			gear collapsed landing, Elgin AFB FL	5.8.83	
			T. Sawyer	85	
			crashed dest. after takeoff, Cartersville GA	12.2.85	

accident report 5.8.83: gear collapsed landing Elgin AFB, owner Mark H.Thompson; accident report 12.2.85: crashed immediately after takeoff Cartersville GA snowing and low cloud, cargo flight, pilot inexperience listed as a cause, aircraft's owner prepared the flight for departure;

BA-645	H18	N345NF	built	3.63
			Mid Continent Leasing Co, Amarillo TX	63
			Mohio Leasing Corp, Chicago IL	66
	Dumod mods		op: Commuter Airlines	67/68
			Speedbird Aircraft Corp, Fort Wayne IN	69/70
			Frederick J. Strauss, Fort Wayne IN	71/72
		N148PA	Providence Air Charter, Providence RI	6.77/79
			James A. Dole, Coventry RI	79
			Newair Flight Inc, New Haven CT	3.85
			Wilford Blease, Greenville NH	6.85
			ACE Air Cargo Express, Cleveland OH	10.9.85/86
			crashed destroyed on takeoff, Louisville KY	11.2.86
			(dismantled, fuselage dumped Wakeman OH 99)	

N345NF noted Fort Wayne IN 28.5.76;

N148PA noted Toronto ONT 11.9.79 Providence Air Charter;

accident report 11.2.86 op ACE Air Cargo Express; USCR99: ACE Air Cargo Express;

N148PA fuselage cut in two dumped in bushes Wakeman OH 9.8.99;

BA-646	H18	N245M	Tulsair Distributors Inc, Tulsa OK	4.63
			Dealers Transport Co, Memphis TN	64/70
			First National Bank of Memphis, Memphis TN	71/72
			Edwards Petroleum, Big Spring TX	79
			Wilson C. Edwards, Big Spring TX	18.8.83/18
			Jamie Stewart Dawson, Celina TX	18.10.19/20

N245M noted Big Spring TX 22.10.15 in Connie Edwards' hangar, good condition;

BA-647	H18	N83D (2	Youngstown Airways/ Lease Air, Youngstown OH	4.63/66
		N81DA	SMB Stage Line Inc, Des Moines IA	69/72
			Kenneth Stoeckmann, Livermore CA	79
			Jeff S. Sanders, Portland OR	6.12.79/91
			op: Air Fast Freight, Long Beach CA	83
			op: North Continent Airlines, Long Beach CA	.83/85
			op: Coast Air Freight Inc, Long Beach CA	85
			damaged ran off runway landing. Santa Maria CA	13.2.85

N81DA noted Long Beach CA 7.9.83 North Continent Airlines; N81DA accident report 13.2.85: op Coast Air Freight, no indication extent of damage;

BA-648	H18	N24K (2	built	.63
		•	Mahlon C. Kline, Philadelphia PA	64/66
			Niles Machine & Welding Co, Niles OH	69/72
			ran off runway on takeoff, ran into canal,	
			submerged in water, Marco Island FL	25.3.72
			Aero Craft Leasing, Plymouth MI	79
			Burl-Air Freight Inc, Burlington WI	23.3.79/80
			crashed, forced landing on road, Covington KY	19.10.79
			struck-off USCR	30.10.80
BA-649	H18	N52L (2	Transcontinental Gas Pipe Line Corp, Houston TX	6.63/66
		N5214	Transcontinental Gas Pipe Line Corp, Houston TX	69
		N73FA	Fontana Aviation, Iron Mountain MI	24.11.69/74
			crashed destroyed landing Iron Mountain MI	3.7.74
				64/72
BA-650	H18	N8612M	Beech Aircraft Corp, Wichita KS: CofA issued	19.8.63
			Owensboro Aviation, Owensboro KY	
			Lyman S. Cox, Owensboro KY	79
			Air Kentucky Airlines, Owensboro KY	79
			John M. Walker, Kansas City MO	8.81
			Mid South Aircraft Sales, Memphis TN	9.81
			Oklahoma Aircraft Corp, Yukon OK	2.82
			Classic Air Inc, Norman OK	4.82
			Bullfrog Inc, Owensboro KY	3.83/94 23.3.94/96
			Jim Hankins Air Service, Jackson MS Green & Green Construction Co, Grenada MS	26.2.96/99
			Seahorse Aviation, Rye NH	13.9.00
			W. J. Burdis, Coraopolis PA	7.1.02/05
			Steven Oxman, Riva MD	22.3.05/06
		N87711	Steven Oxman, Riva MD	11.4.06/15
		110//11	ran off runway landing, stbd gear collapsed, Dayton OH	24.7.09
			Planeview Aviation Services, Ahoskie NC	23.6.15/22
		(N8612M)	rereg res.	1.21
		(140012141)	10109 100.	1.41

N8612M at fly-in Oshkosh WI 8.97 plate BA-650; N8612M noted Beaver County PA 1.10.04, tailwheel, in service;

N8612M noted Lakeland FL 14.5.05 tailwheel;

N87711 at fly-in Lakeland FL 8.4.06, tailwheel; N87711 at fly-in Oshkosh 24.7.06 Steve Oxman;

N87711 at Beech fly-in Tullahoma TN 14.10.07; Oshkosh 7.08; Oshkosh 28.7.14; N87711 at Beech fly-in Tullahoma TN 18.10.14; Oshkosh 7.16, 7.17 brown & white;

BA-651	H18	N958B	Beech Aircraft Corp, Wichita KS: CofA issued	16.9.63/64
	trigear		(second H18 factory-fitted with Volpar trigear)	
	_		Missouri Portland Cement Co, St Louis MO	66/70
			Grede Foundries Inc, Milwaukee WI	71/72
			landed with gear locked-up, Saginaw MI	31.1.75
			Strout Aviation, Gahanna OH	79
			op: Air Bama, Muscle Shoals AL	83
			Volpar International Corp, Van Nuys CA	6.83
			Air Siesta Inc, McAllen TX	12.84

William R. Sandlin, Harlingen TX	4.85/91
Jim Hankins Air Service, Jackson MS	18.3.92/02
Mike Hatfield/ Command International Airways/	
Comat International Airways, Orlando FL	21.8.02/05
blown on to back by Hurricane Frances, Orlando FL	5.9.04
struck-off USCR as destroyed	23.9.05

N958B accident report 31.1.75: type Volpar H18, Hamilton spar mod. gear locked up;

N958B noted Indianapolis IN 30.5.76 trigear;

N958B noted Tucson AZ 11.1.83 "Air Bama" titles;

N958B noted Carlsbad CA 13.6.83, 9.83, 2.84 all "Air Bama", trigear, plate BA-651;

N958B noted McAllen TX 10.87 trigear;

N958B noted Jackson-Higgins Field MS 11.8.98, trigear freighter, Hankins Air Service;

N958B noted Panama City FL 13.8.98 trigear freighter Hankins AS;

N958B: Jim Hankins Air Service fleet Status Report 10.8.98: TT 9465 hrs;

Report 11.9.04: blown on back by hurricane recently, wreck trucked out: had been active flying at Orlando prior to this;

BA-652	H18	N422X (1	Beech Aircraft Corp, Wichita KS	.63
	trigear		(first H18 factory-fitted with Volpar trigear)	
		N22X (2	New York Conservation Dept., Albany NY: delivered	11.63/66
			(flown for New York Mayor, Nelson Rockefeller)	
		N722X	State Dept. of Education, Tallahassie FL	69/72
		N22XL	sale rep.	79
			Condor Aviation, Tonawanda NY	12.83
			Sair Aviation, Syracuse NY	9.84/91
			Jim Hankins Air Service, Jackson MS	2.93/95
			El Jeffe Aviation Services, Monroe LA	12.95/99
			Beltway Motel, Baltimore MD	16.9.00/03
			crashed into ravine on takeoff, Westminster MD	23.11.03

N422X photo as trigear;

N722X noted Gainesville FL 3.10.68 trigear, plate BA-652;

N22XL noted Frederick MD 7.97 Jim Hankins, trigear;

N22XL noted Reno-Stead NV 10.98 trigear, displayed at Air Races with For Sale signs;

N22XL noted Camarillo CA 5.99 "For Sale" signs;

N22XI accident report 23.11.03: trigear, no injuries, wrecked;

	N22XI a	ccident report	23.11.03: trigear, no injuries, wrecked;	
BA-653	H18	N84D (3	Youngstown Airways/ Lease Air, Youngstown OH	9.63/66
		N8451	SMB Stage Line Inc, Des Moines IA	69/81
			Royal Airways, Burleson TX	10.81/84
			Patricia C. Johnson, Edgewater FL	11.90
			Howard Harding, Roosevelt UT	9.91
			William McGrath/ Island Airlines, Nantucket MA	7.4.93/95
		N408BK	William F. McGrath, Nantucket MA	1.95/06
			op: Island Airlines, Nantucket MA	
			Woodstone Corp, Stockdale TX	16.7.09/17
			Richard L.Ward, Griffin GA	9.4.18/19
		N18RW	Richard L.Ward, Griffin GA.	10.19
	N8451 r N408BK	noted Oklahom (photo: tailwhe	ove TX 2.5.73 SMB Stage Line; a City OK 23.12.80 tailwheel, "SMB Stage Line" titles; rel, "Island Airlines" titles, in service; nee FL 4.99 flying "Island Airlines" titles, tailwheel;	
DA CEA	1140	N2470	b ila	0.02
BA-654	H18	N347G	built	9.63
			Combs Aircraft, Denver-Stapleton CO	64/66
			SMB Stage Line Inc, Des Moines IA	69/81
			Universal Aircraft Sales, Detroit MI	6.81
			Jet Services Inc	87
			Blue Ridge Aviation, Morganton NC	5.89/91
			Piedmont Air Cargo, Gastonia NC	8.1.92/95
			crashed during landing, Morganton NC	25.2.92

10.4.95

struck-off USCR

BA-655	H18	N1731G N273MB C-GWUY	Southern Airways Co, Atlanta GA Murray Biscuit Co, Augusta GA Galaxy Aviation, Drayton Valley ALTA destroyed, hit mountain at 3000 ft, Wrangell AK	10.63/64 66/72 8.75 11.8.77			
	C-GWUY a weather, 6		rt 11.8.77: flight Ketchikan to Wrangell, VFR flight into poor	-			
BA-656	H18	N9724Y	Atlantic Aviation Corp, Wilmington DE: CofA issued Maguire Leasing Corp, New York NY Palm Air Aviation, West Palm Beach FL Henry A. Keller, Miami FL FIT Aviation Inc, Melbourne FL National Bumper Exchange, West Memphis AR crashed Maico, Colombia (during illegal drug run)	20.11.63/64 66 69/70 71/72 79 19.8.80 26.9.80			
	N9724Y no	ted Opa Loci	ka FL 23.8.71;				
BA-657	H18 trigear	N919X	Page Airways, Rochester NY: CofA issued damaged ran off icy runway, landing Worcester MA Simmons Machine Tool Corp, Albany NY Malcolm Jacobs Aviation, Chesterfield MO Topeka Inn Management Inc, Topeka KS Golden Isles Aviation, St Simons Island GA Lease Merchant Inc, Boyd TX crashed forced landing off-airport, Gillette WY	3.12.63/64 11.12.64 66/69 70 71/72 79 22.4.81 27.9.81			
	N919X noted Schenectady NY 8.69 "Simmons" titles, trigear;						
BA-658	H18	N925N	Beech Aircraft Corp, Wichita KS (company demonstrator 64) Mechling Barge Lines Inc, Wilmington DE	12.63/64			
		N33JC	Penn Dixie Leasing Corp, New York NY struck-off USCR: "exported"	70			
		N925N	Boca Raton Flying Service, Boca Raton FL crashed in forced landing off-airport due dual engine failure on approach to land Fort Lauderdale FL	4.1.73 14.10.73			
	Not on US0 N33JC was BA-658 ad	CR under eith s a KingAir by vertised for sa	s N925N to N33JC, N925N, no details on export; ner reg 7.65, 7.66, 1.67; and again 1.72; v 1.73 USCR; ale in 7.73 Trade-A-Plane 0.73: H18 N925N flight Miami-FLL, hit trees, 5 hurt;				
BA-659	H18	N350T	Tex Sun Beechcraft Inc, San Antonio TX	12.63/64			
	trigear -9700	N879T	R & B Inc, Beverly Hills CA South Plains Contracting Co, Lubbock TX Newscame & Work Metalizing Co, Algren CH	66 69 70/73			
		N13AW	Newsome & Work Metalizing Co, Akron OH Newsome & Work Metalizing Co, Akron OH	70/72 79			
		N811BF	Basler Flight Service Inc, Oshkosh WI Basler Flight Service Inc, Oshkosh WI Basler Turbo Conversions Inc, Oshkosh WI Welch Aviation, Alpena MI River City Aviation, West Memphis AR op: McNeely Charter Service, West Memphis AR Jim Hankins Air Service, Jackson MS Air Cargo Inc, Sebastian FL reg expired 31.12.13, struck-off USCR	6.82/89 2.89/91 15.3.94/96 22.1.96 1.10.96/99 98/99 17.3.00/03 25.2.04/13 29.1.18			

N811BF noted Oshkosh WI 27.7.89 Basler ramp, "Basler" titles, trigear, plate BA-659;

N811BF noted Oshkosh 1.8.90 "Basler Airlines" titles, trigear;

N811BF noted Oshkosh WI 1.8.91 "Basler" titles;

N811BF noted Dexter MO 14.10.97;

N811BF noted West Memphis AR 4.8.98 trigear, McNeely Charter Service, plate: H18-9700 mods; N811BF noted West Memphis AR 15.8.99 trigear McNeely Charter Service;

8.02 report: N811BF still in service with Hankins;

N811BF noted Jackson-Hawkins Field MS 5.8.03 trigear, Jim Hankins AS; N811BF noted St John's, Antigua 22.12.04 trigear, no titles;

BA-660	H18	N330KL	built	.64
	trigear		nosed over landing, Broomfield-Jefferson CO	6.11.64
	· ·		Eagle Food Centre, Rock Island IL	66
		N336GU	General United Leasing Corp, Des Moines IA	69
	Volpar		Princeton Mining Co, Terre Haute IN	70/72
	Turboliner	N638CZ	Tombigbee Aviation, Savannah TN	79
			op: Circle Rainbow Air Inc, Honolulu HI: delivered	10.80/84
			Circle Rainbow Air Inc, Honolulu HI	12.86
			struck-off USCR	9.3.90
		RP-C1103	Pacific Airways, Manila	-
			open storage, engines removed, Manila	07
		RP-C2984	C. M. Aero Services, Manila	3.12

N638CZ noted Honolulu 9.83 "Circle Rainbow Air"titles, trigear, plate BA-660; RP-C1103 noted Manila Domestic 16.4.07 stored engineless;

BA-661	H18	N800G	built	.64
			Reeves Brothers Inc, Spartanburg SC	66/69
			damaged struck snowbank landing Newport News VA	30.1.66
			Presidential Flight Service Corp, St Louis MO	70
			Williams Patent Crusher, St Louis MO	71/72
			gear collapsed landing, Bonne Terre MO	8.11.71
			crashed destroyed landing, Bloomington IL	21.12.72
BA-662	H18	N558B	Beech Aircraft Corp, Wichita KS: CofA issued	13.2.64
	trigear		Cleveland Pneumatic Industries, Cleveland OH	66
	_	N5580	rereg	
		N787Q	John Figi, Marshfield WI	71/72
			nose gear collapsed landing, Birmingham AL	29.3.78
			Nathaniel I. Gunn, Nixa MO	79
			General Electric Credit Corp, Sunnyvale CA	15.7.80/81
			op: Western States Express	81
			crashed destroyed during forced landing Newhall CA,	
			off-airport after takeoff from Van Nuys CA	28.1.81
			· · · · · · · · · · · · · · · · · · ·	

N787Q accident report 28.1.81: Western States Express, cargo flight Van Nuys to Las Vegas NV to Salt Lake City UT, power loss both engines probably due carburetter icing, 12.42am, pilot high alcohol level, pilot & 1 pax k;

BA-663	H18	G-ASNX	Short Brothers & Harland Ltd, Gatwick	1.64
	trigear		Cameron Iron Works Ltd, Leeds	2.64/69
	J		(British CofA issued 6.2.64, del. via Prestwick 31.3.64	·)
		9Q-CSP	reg	12.69
		F-BVEB	Midi Aviation/ Air Midi, Nice	13.6.74/92
			Association pour la Sauvegarde des Avions Anciens -	_
			ASPAA, Marmande	21.9.92/94
			(flew 93 as "US Navy BA663/EB")	
			sold to USA: struck-off Register	3.5.94
		N18ET	Gary E. Tillman, Rome GA	4.5.94
			Rivair Flying Service, Tulsa OK	20.12.94/06
			(US CofA 12.5.94, del. Toussus-Glasgow-Reykjavik 1	7.5.94)
			Peter H. McMillan, San Francisco CA	5.2.07/08
		N663TB	Peter H. McMillan, San Francisco CA	22.2.08
			Beech H-18 Inc, Wilmington DE	20.4.09/12
			(based North Weald, England 10/11)	
			Peter H. McMillan, San Francisco CA	28.9.12/20

G-ASNX del via Prestwick 31.3.64 fitted Volpar trigear, for American owned Cameron Iron Works; G-ASNX first noted Gatwick 31.3.64, reported as delivery;

G-ASNX noted Leeds-Bradford 13.4.64 Cameron Iron Works trigear;

G-ASNX noted Bournemouth 5.4.64;

G-ASNX at Biggin Hill airshow 7.5.64 displayed by UK Beech agents Short Bros, trigear;

G-ASNX noted Heathrow 26.5.64 Cameron Iron Works;

G-ASNX noted Gatwick 2.8.64;

G-ASNX noted Staverton 11.8.64;

G-ASNX noted Dublin 5.9.64 Cameron Iron Works, trigear;

G-ASNX noted Northolt 9.10.64 Cameron Iron Works;

G-ASNX noted Goodwood 19.4.65 Cameron Iron Works;

G-ASNX noted Heathrow 6.11.64 Cameron Iron Works;

G-ASNX noted Weathersfield 4.6.65 Cameron Iron Works;

G-ASNX noted Gatwick 19.6.65;

G-ASNX noted London-Heathrow 13.7.65 & 5.8.65 Cameron Iron Works;

G-ASNX visited Yeadon 2.9.65 Cameron Iron Works;

G-ASNX noted Yeadon 20.12.65;

G-ASNX at Biggin Hill Air Fair 3.66;

G-ASNX noted Amsterdam-Schiphol 6.3.66 trigear, "Cameron Iron Works";

G-ASNX noted Biggin Hill 14.5.66 "Cameron Iron Works";

G-ASNX arrived Cambridge 26.7.66 for repsray, departed 1.8.66, Cameron Iron Works;

G-ASNX noted Dusseldorf, West Germany 27.1.67;

G-ASNX noted Yeadon 21.11.68;

9Q-CSP noted Fairoaks UK 2.11.69;

9Q-CSP noted Gatwick 1.1.70 ex G-ASNX;

9Q-CSP noted Geneva Switzerland 19.12.70;

9Q-CSP noted London-Gatwick 20.3.71;

9Q-CSP noted London-Redhill 12.4.73 trigear;

F-BVEB noted Paris-Le Bourget 11.4.74 trigear;

F-BVEB visited Stansted 22.4.84, trigear no titles; Brussels 18.12.84 Midi Aviation;

F-BVEB arrived Newcastle UK 31.10.85 ex Nice, trigear, no titles, rep owned by Air Midi;

F-BVEB noted Toussus le Noble 28.7.91 for sale, no titles;

F-BVEB noted Bergerac 6.93 "USN BA-663/EB";

N18ET delivered to USA via Glasgow 5.94 as "USN BA-663/EB";

N18ET noted Tulsa-Jones Field OK 27.8.98 "USN BA-663/EB", freight door being installed at Rivair;

N18ET noted Tulsa-Jones Field 7.11.99 on overhaul "USN EB" trigear;

N18ET noted Tulsa-Jones OK 11.8.00 "USN BA663 EB VC-10", trigear;

N18ET noted Tulsa-Jones OK 3.02 "USN BA663 EB VC-10";

N663TB at airshow Little Gransden, England 29.8.10, trigear, grey white & blue, flying

N663TB noted North Weald 8.10, trigear;

H18	N8934M	built, CofA issued	31.1.64
trigear		E. L. Bruce Co, Memphs TN	66
· ·		Auchter Company, Jacksonville FL	69/72
		Rourke Aircraft Sales, Bartlesville OK	79
		Oklahoma Aircraft Corp, Yukon OK	8.82
		Jimmy L. Fun, Rock Springs WY	5.88
		Mike Vermeulen & Norman A. Knapp/ M & N Aviation,	
		Rock Springs WY	6.90/98
		David Oreck/ Park 7 Aviation, New Orleans LA	.98/06
		Hat Aviation of Statesboro, Statesboro GA	3.10.07/11
		Biff Thompson, Statesboro GA	27.5.11/17
		Sale rep., Macon GA	18
			trigear  E. L. Bruce Co, Memphs TN Auchter Company, Jacksonville FL Rourke Aircraft Sales, Bartlesville OK Oklahoma Aircraft Corp, Yukon OK Jimmy L. Fun, Rock Springs WY Mike Vermeulen & Norman A. Knapp/ M & N Aviation, Rock Springs WY David Oreck/ Park 7 Aviation, New Orleans LA Hat Aviation of Statesboro, Statesboro GA Biff Thompson, Statesboro GA

N8934M noted Reno NV 13.9.75 trigear;

N8934M noted Van Nuys CA 8.11.79;

N8934M at fly-in Oshkosh 1.8.98 trigear owned by Norm Knapp & Mike Vermeulen of M & N Aviation, Rock Springs WY, plate: BA-664;

N8934M at Beech fly-in Tullahoma TN 16.10.98 David Oreck, New Orleans LA;

N8934M at Beech fly-in Tullahoma TN 10.10.99 David Oreck LA;

N8934M at Beech fly-in Tullahoma TN 18.10.00;

N8934M at Beech fly-in Tullahoma TN 16.10.03;

BA-665	H18	N933T	built	.64	
	trigear		Textron Inc, Providence RI	66/69	
			Boca Raton Flying Service, Boca Raton FL	70/72	
			James A. Tripp, Punta Gorda FL	79	
			Waring Aviation, Charlottesville VA	9.82/83	
			Regency Enterprises, Rayville LA	7.83	

Sair Aviation, Syracuse NY	2.84/91
Jim Hankins Air Service, Jackson MS	11.91/99
Freight Runners Express Inc, Milwaukee WI	4.2.00/05
Kamaka Air, Honolulu HI	12.8.05/17
(del. to Honolulu ex Oakland CA 17.10.05)	
University of Hawaii, Honolulu	17.1.18
struck-off USCR	17.12.18

N933T noted Oklahoma City OK 30.10.80 trigear, no titles;

N933T noted Jackson MS 18.7.97 trigear;

N933T noted Jackson-Higgins Field MS 11.8.98, trigear freighter, Hankins Air Service;

N933T: Jim Hankins Air Service fleet Status Report 10.8.98: TT 11,770 hrs;

N933T noted Milwaukee WI 3.5.01 op Freight Runners Express since 2000;

N933T noted Milwaukee WI 8.01,

N933T noted Milwaukee 22.7.02 trigear;

N933Tflew Junta Muni CA to North Las Vegas 8.9.05;

N933T noted Honolulu 26.10.05 just arrived ex Wisconsin on delivery to Kamaka Air, trigear;

BA-666	H18	N8984M	built	.64				
	trigear		(delivered to London-Gatwick 12.12.64,					
		01 1 411	repainted 9L-LAH at Gatwick 12.64)	40.04/74				
		9L-LAH	Diamond Corp of Sierra Leone, Freetown	12.64/71				
		N470LC	(9L-LAH del. to USA via Prestwick-Reykjavik 26.11.71)	70/00				
		N170LG	Florida Airmotive Inc, Lantana-Palm Beach FL	72/86				
			(US CofA renewed 10.2.72)	10.00/01				
			Aero Sun Inc, Lake Worth FL	10.90/91				
			Westwind Trading Inc, Lake Worth FL Michael P. Bainton, Deerfield Beach FL	8.93 28.3.94/95				
			Hopetown Investments Inc, Miami FL	5.7.95/96				
			Tom E. Demint, Pine Bluff AR	9.5.96/02				
			Excaliber 800 Inc, Wilmington DE	29.10.04/12				
			Hentry E. Midura, Winder GA, later Athens GA	24.1.13/20				
	N8984M	del Gatwick 1	2.12.64, trigear, panoramic windows, plate BA-666;					
			vick as 9L-LAH 26.12.64 owner DTWA;					
		9L-LAH noted Biggin Hill 28.12.64, 6.1.65 trigear, reportedly ex N8984M;						
		9L-LAH noted Biggin Hill 20.12.04, ७.1.03 trigear, reportedly ex । १०७४मण, 9L-LAH noted Gatwick 20.8.66 Diamond Corp of SL;						
			, ,					
		9L-LAH noted Colombier Switzerland 29.7.68; 9L-LAH noted Berne, Switzerland 8.11.68, to Gatwick same day; Turnhouse Scotland 10.11.68;						
	Geneva 11.11.68;							
	9L-LAH noted Southampton UK 24.7.70;							
	9L-LAH noted Abidjan 9.1.71 trigear DCWA;							
		9L-LAH noted Fairoaks UK 2.5.71						
	9L-LAH displayed by Dismore Aviation at Cranfield Business and Light Aircraft Show 5.9.71							
		N170LG noted Palm Beach FL 8.10.73;						
		N170LG noted Lantana FL 16.3.81 trigear;						
		N170LG noted Lantana FL 16.5.51 trigear, N170LG noted Miami FL 14.9.83 Florida Airmotive, (with N169LG A-592, both being op for Air						
	Florida);							
	N170LG noted Palm Beach FL 31.8.93 trigear;							
	N170LG noted Pine Bluff AR 5.8.98 trigear, owned Ted Demint;							
	N170LG noted time Blain AlX 5.5.35 trigear, owned red Berlink,  N170LG at Beech fly-in Tullahoma TN 16.10.98 trigear, Tom & Linda Demint, Pine Bluff AR;							
	N170LG at Beech hy-in Tulianoma TN 70.10.90 trigear, form & Linda Berlint, Time Blun AIX,  N170LG noted Cincinatti-Lunken OH 5.8.99 trigear, good condition;							
	N170LG noted Cincinati-Lunken Of 15.5.99 tilgear, good contaiton, N170LG at Beech fly-in Tullahoma TN 10.10.99 Tom Demint AR;							
	N170LG at Beech fly-in, Tullahoma TN 18.10.00;							
		N170LG at Beech hy-lif, Tulianoma TN 18.10.00, N170LG noted Fond Du Lac WI 24.7.02. parking for Oshkosh, plate BA-666 trigear;						
	N170LG noted Fond Du Lac Wi 24.7.02. parking for Oshkosh, plate BA-000 trigear, N170LG at Beech fly-in Tullahoma TN 16.10.03;							
		=						
BA-667	H18	N906T	Beech Aircraft Corp: demonstrator	.64				
	Trigear		(demo tour of Latin & South America 3.64-4.64,					
	<b>3</b> ·		tour of SE Asia 10.64)					

Continental Air Services Inc, Reno NV & Laos

(purchased N18843 & N906T at Bangkok

sold locally .77, not delivered to Sweden)

(evacuated to Bangkok-Don Muang .75, stored) Bo Larsson, Vasteras, Sweden, later Reno NV .65/77

23.3.77

.77

	sold to Thailand, struck-off USCR	24.3.77
HS-CHP	Sununt & Co, Bangkok	3.6.77
	op: Sky of Siam Ltd, Bangkok "Sununt 9"	3.6.77/84
	damaged, props struck ground on takeoff,	
	Phetchabun Province, Thailand	5.11.77
	(wfu open storage Bangkok-Don Muang 84)	
	Boonyong Thiraworawong: purchased at auction	3.86
	Thai Yon Tractor Ltd: displayed at a yard near	
	Don Muang, in Sky of Siam paint scheme	86/88

N906T noted Don Muang Bangkok 9.75 in storage on a taxiway in centre of field with other Beech 18s and Porters evacuated from Vietnam;

BA-667 & advertised for sale 76 by Continental Air Services Pte Ltd, Singapore, both located at Don Muang Airport, Bangkok: also advertised were 7 Porters, 2 DC3s, 2 CV440s; N906T noted Don Muang 10.3.76 trigear, parked with 3 CASI Turbo Porters;

N906T & N18843 purchased at Bangkok .77 by Bo Larsson from Aros Parachutingclub, Vasteras, Sweden: N18843 delivered to Sweden .77 but he sold N906T locally prior to leaving Bangkok; HS-CHP noted Bangkok 2.5.84, stored, "Sky of Siam" titles, "Sununt 9" on nose;

HS-CHP noted Don Muang 21.8.86 trigear;

HS-CHP displayed at garage near Don Muang 86, trigear;

BA-667 noted gate guard few miles north Bangkok Airport 10.87, no reg.; noted 87/88 on Highway 31 near Don Muang stored in yard at garage, blue/white; noted 9.8.88 Thai Yon Tractor Ltd yard, north of Don Muang "Thai Yon Tractor Ltd" titles: further details South American tour 64: see Beech 18 by Robert Parmerter p.307;

BA-668	H18	N952 (2	Colorado Interstate Gas Co, Colorado Springs CO: Cof/ damaged engine fire while taxying after landing,	A 20.2.64/67
			Colorado Springs CO	29.3.67
			International Air Service Co, Burlingame CA	69/70
			Malcolm Jacobs Aviation, Chesterfield MO	71/72
			sold to Canada, struck-off USCR	7.10.74
	trigear	C-GPCD	Pacific Coastal Airlines Ltd, Nanaimo BC	11.74/79
	trigear	0-01 OD	Airwest Airlines, Vancouver BC	80
		N8495A	Ridder Air Enterprises Inc, Whitman MA	26.9.80/82
		NOTSOA	Plymouth Air Services Ltd, Plymouth MA	4.82
			Ridder Air Enterprises Inc, Whitman MA	2.83
			Coopair Ltd, Weston MA	6.83/96
			Jim Hankins Air Service, Jackson MS	30.1.96
			Alexander Aircraft Inc, Zellwood FL	4.98
			•	19.5.98/99
			John E. Schnepf, Roche Harbour WA	3.3.00/07
			Blue Yonder Inc, Sand Springs OK	28.4.07
			DIVI Co, Wilmington DE	20.4.07
			(departed Tulsa OK 21.7.07 on ferry to Europe,	
			via Reykjavik 27.7.07, Wick-Rotterdam 28.7,	
			arrived Basle-Mulhouse 29.7.07, still based there 15)	00 7 07/47
			Aircraft Guarantee Corp, Onalaska TX: trustee	23.7.07/17
			sale rep., Liestal, Switzerland	3.7.17
		NIO 405 A	struck-off USCR	6.2.18
		N8495A	E3932 Inc trustee, Gloucestershire Airport, England (based Germany 21)	4.12.19/21
		D-INEO	reg. res.	7.21

C-GPCD noted Vancouver 9.76, "Pacific Coastal Airlines Ltd, Nanaimo BC" titles, trigear; C-GPCD noted Vancouver BC 9.8.79; Nanaimo BC 19.9.79;

C-GPCD noted Cassidy, Vancouver Island BC 26.6.80 "Pacific Coastal Airline", trigear, large cabin windows;

N8495A noted Tulsa-Jones OK 11.8.00, plate BA-668;

N8495A noted Rotterdam 29.7.07 on ferry, trigear, factory H18 type scheme;

BA-669	H18	N1964A	Beech Aircraft Corp, Wichita KS: CofA issued	24.2.64
	trigear		Albamarle Paper Manufacturing, Richmond VA	69
			Leggetts Inc, Danville VA	70/72
			Warrender Flying Service	74
			landed right gear locked-up, Omaha NE	22.1.74
		N333DM	rereg	11.76
			Airbama Inc, Muscle Shoals AL	79

	Coastal Construction Co, San Louis Obispo CA	79
	op: Circle Rainbow Air Inc, Honolulu HI	.80/84
	Circle Rainbow Air Inc, Honolulu HI	12.86/90
	sold to Philippines: struck-off USCR	9.3.90
RP-C984	Charles R. Miller/ CM Aero Services, Manila	.89/98

N1964A accident report 22.1.74: Volpar H18, Warrender Flying -, 7 unhurt; N333DM noted Van Nuys CA 28.8.79 at Volpar hangar, ex Airbamba, trigear; N333DM noted Van Nuys CA 29.11.79 at Volpar hangar, ex Airbamba, trigear; N333DM finally SOR 3.02 as "destroyed or scrapped"; RP-C984 noted Manila 1.94 trigear, white & red, no titles; RP-C984 noted Manila 4.2.98 trigear red/white in service, on CM Air ramp;

BA-670	H18	N954 (2	Colorado Interstate Gas Co, Colorado Springs CO: CofA	10.3.64/66
	trigear		International Air Service Co, Burlingame CA	69/70
			Malcolm Jacobs Aviation, Chesterfield MO	71/72
			Shenandoah Oil	
			Four Sons Flying Service, Wichita KS	78
			Mid-America Sprayers Inc, Johnson KS	79
			Pundzak Advertising, Des Moines IA	6.86
			Air SRV Inc/ Lone Star Flight Museum, Galveston TX	16.8.89/22
			reg expired, struck-off USCR	10.12.21

N954 noted Oakland CA 7.11.69 trigear;

N954 noted Houston-Hobby TX 7.5.73 trigear;

Four Sons Flying Service commenced scheduled service 78 with N954 between Garden City-Dodge City-Wichita-Topeka;

N954 noted Lone Star Flight Museum, Galverton TX 26.4.92;

N954 advertised for sale 96 by Courtesy Aircraft, Rockford IL: H18 factory fitted trigear, executive paint scheme:

N954 at airshow Oklahoma City OK 20.6.98, exec scheme, trigear;

N954 at airshow Offutt AFB NE 29.8.98 exec scheme, LSFM support aircraft for their warbirds which attended the airshow;

N954 noted Galveston TX 29.9.98 trigear;

N954 noted LSFM Galveston TX 9.8.03 trigear, plate BA-670;

N954 noted Galveston TX 8.10.05;

BA-671	H18	N1050U	built	.64
	trigear	N711D	National Financing Inc, Wilmington DE	66
	_		Sperry Rand Corp, White Plains NY & Phoenix AZ	69/72
			Associated Products of America, New York NY	79
			Floair Inc, Wichita KS	17.9.80
			sold to Indonesia, struck-off USCR	24.11.80
			(del. to Indonesia as N711D, via Singapore 11.80)	
		PK-BIH	Indonesian Aviation Corp/ Indoavia, Jakarta	82/90
			struck-off Register	20.7.18
BA 672			e-Seletar 11.80;	64
BA-672	H18	N8825M	built	.64
		N105PE	Wolman Construction Co, Silver Spring MD	66
			IDA Leasing Corp, New York NY	69
			Loving Insurance Agency, Silver Spring MD	70
			Royal Brand Inc, Massillon OH	71/79
			Cannavo Aviation/ Aero Taxi, Claymont DE	19.3.81/83
			crashed destroyed landing, Allentown PA	25.11.83
	N105PE i	noted Ft Laud	erdale FL 13.6.71;	
BA-673	H18		FA Brasileira as TC-45T FAB 2885	.64/78
	trigear		(FAB designation changed .70 from TC-45T to U-45T)	
		PT-KXH	Jose A. Simioni	1.78
			Atlanta Taxi Aereo Ltda, Salvador	2.78/84

FAB type designations: see Beech 18 by Robert Parmerter p 310,311

BA-674	H18		FA Brasileira as TC-45T FAB 2886	.64/77	
_,, 0, ,	trigear		(FAB designation changed .70 from TC-45T to U-45T)		
		PT-KVY	Jose A. Simioni	.77	
			Paulista, Brazil 12.80 reported as derelict; ka FL 18.7.81;		
BA-675	H18		FA Brasileira as TC-45T FAB 2887	.64/77	
	trigear	PT-KXQ	(FAB designation changed .70 from TC-45T to U-45T) reg	.78	
	PT-KXQ r	noted Lencois	Paulista, Brazil 26.12.80		
3A-676	H18		FA Brasileira as TC-45T FAB 2889	.64/77	
	trigear	PT-KXG	(FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver	10.3.78	
			Transportes Aereos Regionais da Bacia Amazonica SA - TABA, Culaba/Belem		
	PT-KXG r	noted Belem 7	.81 trigear, in service, TABA;		
3A-677	H18		FA Brasileira as TC-45T FAB 2890	.64/77	
	trigear		(delivered to Brazil via Miami FL 21.5.64) (FAB designation changed .70 from TC-45T to U-45T)		
		PT-KXK	Rolim A. Amaro	4.78	
			Transportes Aereos Regionais SA - TAM, Sao Paulo-Congonhas	79/80	
			Jose A. Simioni	19/00	
		N2656X	J & M Aircraft Inc, Opa Locka FL (US CofA issued 18.3.82)	25.2.82	
			American Professional Air Service, Miami FL	11.9.82/91	
			ami FL 21.5.64 trigear, on delivery; ska FL 4.82 trigear;		
BA-678	H18		FA Brasileira as TC-45T FAB 2891	.64/74	
	trigear		(FAB designation changed .70 from TC-45T to U-45T) crashed destroyed Salvador, Bahia, Brazil	20.8.74	
	photo Mia	ami FL on deli	ivery to FAB "TC-45T 2891", trigear;		
3A-679	H18		FA Brasileira as TC-45T FAB 2892: delivered	6.64/77	
	trigear		(FAB designation changed .70 from TC-45T to U-45T) retired by FAB: offered for disposal	10.5.77	
		PT-KVZ	Jose A. Simioni	.78	
			Rio Taxi Aereo Ltda, Manaus (PT-KVZ wfu Opa Locka FL 83/93, for sale)	1.7.82/93	
		N679ZH	Zack B. Hinton, Locust Grove GA	4.8.93	
			Perrone Leather Apparel Inc, Gloversville NY	8.94/95	
		N26PL	(restored 94/96 for US CofA, ff 7.3.96) Bill Perrone/ Perrone Leather Apparel Inc/		
		INZUI L	Townsend Leather, Gloversville NY	4.95/17	
			Michael Landa, Fayetteville AR, Grove OK Twin Beech LLC, Kalispell MT	7.12.17/21 11.12.21/22	
	PT-KVZ noted Opa Locka FL 20.6.78 trigear, ex FAB scheme;				
			Paulista, Brazil 26.12.80, ka FL 9.83 attractive civil scheme,		
			ka FL 8.84 "For Sale"signs,		
	PT-KVZ n	oted Opa Loc	ka FL 27.11.84, 2.8.86, 22.3.87 trigear;		
		oted Opa Loc oted Opa Loc	ka FL 8.8.89 parked on road side of hangar; ka FL 10.89		
			ka FL 10.09, ka FL 10.11.91 road side of hangar: plate H18 BA679;		
	PT-KVZ n	oted Opa Loc	ka FL 6.12.91 trigear, on grass in front of hangar;		
	ri-KVZ n	otea Opa Loc	ka FL 16.4.92, 8.5.92;		

PT-KVZ long-term storage Opa Locka 86/93 trigear;

N26PL visited fly-in Lakeland FL 3.96 Bill Perrone;

N26PL flying 97 US Army style scheme, no titles, fitted Perrone custom leather interior; N26PL at Beech fly-in Wichita KS 11.10.97 "Townsend Leather" & "Perone Leather Aviation Apparel" titles, USAF scheme;

N26PL at fly-in Oshosh 1.8.98 Townsend Leather, Johnstown NY, plate: BA-679 TC-45T 2892; N26PL at fly-in Oshkosh 30.7.03;

Twin Beech Bulletin #9 has rep on Bill Perrone's restoration of this aircraft: complicated due original delivery to FAB was as non-certificated type TC-45T without US CofA: details Parmerter p.310; N26PL advertised for sale by Courtesy Aircraft 2.16: "Perrone" titles, TT 3,896 hrs, trigear, Green and white with USAF insignia. 4 leather club chairs:

			ale by Couriesy Aircian 2.16. Ferrone lines, 11 3,696 hrs, ISAF insignia, 4 leather club chairs;	ingear,			
BA-680	H18 trigear		FA Brasileira as TC-45T FAB 2893 (FAB designation changed .70 from TC-45T to U-45T)	.64/77			
	angean	PT-KXA	Jose A. Simioni	1.78			
		1 1 1001	Nilton Pinto Duarte, Americana	83			
	FAB U45	T 2893 noted	Rio-Santos Dumont 20.10.72 ex TC-45T;				
BA-681	H18		FA Brasileira as TC-45T FAB 2894	.64/77			
	trigear		(FAB designation changed .70 from TC-45T to U-45T)				
	Ū	PT-KXB	Jose A. Simioni	27.10.77			
			Transportes Aereos Regionais da Bacia Amazonica SA -	-			
			TABA, Culaba/Belem	7.79			
			Alfredo Sabatini Judnior, Sao Paulo	83			
			struck-off Register	.92			
3A-682	H18		FA Brasileira as TC-45T FAB 2895	.64/77			
571 002	trigear		(FAB designation changed .70 from TC-45T to U-45T)	.0 1777			
	uigeai	PT-KXC	Jose A. Simioni	19.10.77			
		1 1 1000	Joaquim Olavio de Costa, Sao Paulo	83			
		N4296E	Cornish Corp, Miami FL	11.7.83			
		N4290E					
			Steven Ferraro, Miami FL	9.84			
			Frank Diblase, Lauderdale FL	9.86			
			Manuel A. Farinas, Miami FL	6.88/91			
			Alligator Air Transport Co, Ft Lauderdale FL	10.3.92/13			
			struck-off USCR by FAA	11.6.13			
	FAB 2895	5 noted Rio-Sa	Rio-Santos Dumont 20.10.72 ex TC45T; antos Dumont 5.7.73;				
	PT-KXC noted Opa Locka FL 24.11.79;						
	N4296E noted Ft Lauderdale FL 20.9.90 trigear;						
	N4296E noted Ft Lauderdale FL 5.5.92 trigear;						
	N4296E r	N4296E noted Ft Lauderdale FL 4.95;					
	N4296E noted Ft Lauderdale FL10.4.97, 9.97;						
	N4296E noted Ft Lauderdale FL 12.1.98 trigear, retired stored;						
	N4296E noted Ft Lauderdale FL 11.8.05 in service;						
			erdale-Executive FL 5.2.09;				
BA-683	H18		FA Brasileira as TC-45T FAB 2896	.64/77			
	trigear		(FAB designation changed .70 from TC-45T to U-45T)	÷*			
		PT-KXL	Jose A. Simioni	26.1.78			
		I I IVVL	Alberto Ris, Vitorio	83			
3A-684	H18		FA Brasileira as TC-45T FAB 2897	64/77			
JA-004				.64/77			
	trigear	DT IOM	(FAB designation changed .70 from TC-45T to U-45T)	44.0.70/00			
		PT-KXM	Moacyr Bueno de Moraes, Sao Paulo	11.8.78/83			
			Museu Aeroespaciale, Campos dos Afonsos AB	98/05			
			dos Afonsos AB Rio 11.4.98 in Museu Aerospaciale restora n at Campo dos Afonsos 1.00; not seen at museum by 201				
BA-685	H18	PP-FMR	Ministerio de Fazenda, Rio de Janeiro	.64/65			
_, . 555	trigear		to FA Brasileira as TC-45T FAB 2909	78			
	uigeai		(EAR designation changed 70 from TC 45T to LL 45T)	, 0			

(FAB designation changed .70 from TC-45T to U-45T)

5.78/83

Jose Gilberto de Farias, Vera Cruz

PT-KXJ

## (note: PP-FMR still registered 83 Min. Fazenda: struck-off egister 28.3.91)

PT-KXJ noted Opa Locka FL 20.6.78, trigear, not titles;

	PI-KXJ NO	otea Opa Loc	ka FL 20.6.78, trigear, not titles;			
BA-686	H18 trigear		FA Brasileira as TC-45T FAB 2899 (FAB designation changed .70 from TC-45T to U-45T)	.64/77		
		PT-KXD	Jose A. Simioni Armando Viana Egresa	3.1.78 79		
			Transportes Aereos Regionais SA - TAM,			
			Sao Paulo-Congonhas	12.79		
		N4498M ETL1319	K & B Enterprises Inc: US reg candidate (to FA Mexicana as H18-2899)	26.10.83 -		
			Santa Lucia AB museum, Mexico City (displ. as "FAM ETL1319")	18/20		
	PT-KXD n	oted Opa Loc	ska FL 4.10.77, civil reg taped on over FAB basic scheme,	;		
BA-687	H18 trigear		FA Brasileira as TC-45T FAB 2898 (FAB designation changed .70 from TC-45T to U-45T)	.64/77		
	uigeai	PT-KXE	Jose A. Simioni	27.10.77		
			Atlanta Taxi Aereo Ltda, Salvador	79/83		
			retired Salvador	03/11		
			Dumont 7.1.68; Rio-Santos Dumont 20.10.72;			
	PT-KXE p	hoto (no date	) Salvador: civil scheme very weathered, flat tyres, trigear r retired 10.03, unmoved 12.08;	<del></del> ,		
BA-688	H18	N5638K	built Midwestern Corn. Dec Meines IA	.64		
			Midwestern Corp, Des Moines IA	66		
			Magna Charta Consultants, Denver CO	69 70/73		
		N800WA	Air Travel Service Co, Lincoln NE Winship Air Service/ Troy Air, Anchorage AK	70/72 74/79		
	Valor-	NOUUVVA	Winship Air Service/ Troy Air, Anchorage AK (named <i>Alaskan Trader</i> )	74/79 74/79		
	Volpar Turboliner	. 11	(conversion to Turboliner II trigear completed 1.75)	20.7.77		
	(conv. #01		gear collapsed landing, damaged by fire, Galena AK gear collapsed on takeoff run, Kenai AK	20.7.77 23.1.81		
	(COIIV. #0 I	0)	Troy Air, Anchorage AK	1.84		
		N800TH	Troy Air, Anchorage AK	3.84/90		
			Connie Kalitta Services, Willow Run MI	6.90/91		
			Kalitta Flying Service, Detroit-Willow Run MI	11.92/93		
		N508FS	FS Air Service, Anchorage AK	5.93		
			Kalitta Flying Service, Detroit-Willow Run MI	6.93/99		
			Kitty Hawk Charters Inc, Morristown TN	16.6.99/00		
			Dixie Aviation Enterprises, Hendersonville TN	7.2.02/06		
		N30GB	GB Airlink inc, Fort Launderdale FL	9.6.10/18		
			Airsquid Aviation, Las Vegas NV	3.1.20		
	N800WA accident report 20.7.77: Troy Air Service, heavy landing due propeller going into reverse thrust, fire after impact, 8 unhurt; N800WA noted Van Nuys 12.11.77 Troy Air					
	N800WA accident report 23.1.81: Troy Air, minor damage, gear mechanical failure; N800TH noted Anchorage AK 27.5.90 Turboliner, no titles; N508FS noted Anchorage AK 8.94 op FS Air Services;					
	N508FS noted Anchorage 10.94 "FS Air" titles, Turboliner, blue/white; N508FS noted Willow Run MI 23.7.00 "FS Air" titles, overhaul in Kitty Hawk hangar;					
		oted Willow F oted Willow F	Run 1.03; Run 11.6.03 "FS Air" titles, no props;			
BA-689	H18	N404X (1	built	.64		
		N18X (2	Ontario Airways, Auburn NY	66		
		N218X	Ontario Airways, Auburn NY	.66		
			heavy landing, gear collapsed, Dayton OH	21.7.67		
			Automatic Sprinkler Corp, Cleveland OH	69		
			rea, pendina	70		

reg. pending

70

			Carolina Leasing Inc, Anderson SC	79
			James H. Bailey, Laurinburg NC	8.81
			Waring Aviation, Charlottesville VA	11.81/83
			Sair Aviation, Syracuse NY	84
			crashed destroyed after takeoff, Plattsburgh NY	19.3.84
BA-690	H18	N1151S	built	.64
	trigear	N1161S	J. P. Stevens & Co, New York NY	66
	_	N561DL	Southern Airways Beechcraft Inc, Atlanta GA	.66
			Douglas & Lomaston Co, Columbus NE	.66/72
		N21S	Gifford Aviation, Anchorage AK	79
			Panorama Air Tour, Honolulu HI (fleet #65)	.79/84
			AirTour Acquisition Corp, Honolulu HI	82
			Pacific Air Express Inc, Honolulu HI	3.84
			ditched in sea after takeoff Honolulu HI	17.7.84
	N21S not colour scl N21S Hot N21S not N21S not Panorama accident i	ed Honolulu 5 heme, brown o nolulu 23.8.81 ed Hilo 26.8.8 ed Honolulu F a Air fleet list o report 17.7.84	GA 3.10.68 trigear, plate BA-690; 5.9.79 "Panorama Air Tour" titles, fleet #65 ,trigear: new & white ; "Panorama AT #65; It in Beech 18 tourist formation; If 9.83 "Panorama Air" titles, trigear, plate BA-690; as at 15.11.83: BA-690 tt 10,102 hrs, fleet #65; : Pacific Air Express, engine failure on takeoff Honolulu trately ditched into sea next to airport;	·

BA-691	H-18	N1152S	J. P. Stevens & Co, New York NY: CofA issued	20.6.64	
	trigear	N1162S	Southern Airways Beechcraft, Atlanta GA	66	
			Dixie Yarns Inc, Chattanooga TN	69	
			Executive Flight Service, Portland OR	70/72	
			Claude Ross, Rhine GA	78/79	
			sale reported, Miami FL: USCR	91	

N1162S noted Indianapolis IN 30.5.76 trigear; N1162S noted Atlanta-Fulton County GA 6.78, no titles, trigear;

BA-692	H18	N958T	built	.64
			Central Oil Co, Laurel MS	66
BA-693	H18	N372PW	Beech Aircraft Corp, Wichita KS: CofA issued	18.6.64
	trigear		Shop Rite Food Stores, Albuquerque NM	66
	· ·		Phillips Supply Co, Cincinatti OH	69
		N372PS	Phillips Supply Co, Cincinatti OH	70
			Allegheny Aviation, Pittsburgh PA	71/72
			Superior Electrical Contractors, Acworth GA	79
			Gene F. Fisher, Bolling Springs PA	3.84/91
			Carl W. Scholl, Borrego Springs CA & Chino CA	19.9.94/97
			DB Aero Inc, Wilmington DE	20.5.97/20

N372PS noted Chino CA 3.93,12.93, 2.95, 24.4.95, 20.9.95 all trigear, good condition, green/white; Believed DB Aero is Darryl Bond/Aero Classics, Chino (warbird & racing pilot); N372PS visited Oshkosh WI fly-in 7.15. 7.16;

BA-694	H18	N8804M (1	Beech Aircraft Corp, Wichita KS	.64
	trigear	N20PA (2	Pennsylvania Aeronautics Commission, Cumberland PA	.64/70
	_		State of Pennsylvania, Cumberland PA	71/83
			Sair Aviation, Syracuse NY	18.10.84/91
			damaged forced landing in field, Utica NY	1.6.88
			struck-off USCR	28.1.91

N20PA noted Reading PA 20.7.68 yellow, "The Keystone State" titles, trigear; N20PA noted Youngstown OH 25.2.83 State of PA, trigear; accident report 1.6.88: Sair Aviation, forced landing in field, undercarriage collapsed;

BA-695	H18	N925H	Beech Aircraft Corp, Wichita KS	.64/65
	trigear		(company demonstrator 64/65)	

	Calaveras Cement Co, San Andreas CA	66
	Bush Hog Division, Selma AL	69/72
N55JM	rereg	
N58JM	rereg	.75
	Astro Airways, Pine Bluff AR	20.7.77/78
	crashed destroyed landing. Centreville IL	25.3.78

N925H noted Concord CA 11.65, trigear, Beech demonstrator and Mrs Olive Beech's personal aircraft;

N58JM accident report 25.3.78: flight Pine Bluff AR to East St Louis IL, struck wires on ILS approach in freezing drizzle 11am, 3k, 3 serious injuries;

	approach in	n freezing di	rizzle 11am, 3k, 3 serious injuries;		
BA-696	H18 trigear	N7952K	Beech Aircraft Corp, Wichita KS: CofA issued Twin Disc Clutch Co, Racine WI James R. Bussard, Pontiac MI Provo Flying Service Renge Inc, Boynton Beach FL op: Charles Air Service accident Nassau, Bahamas	9.7.64 66/70 79 83/85 27.5.86/90 90 25.3.90	
	N7952K no	ted Ft Laud	ale FL 20.11.83 trigear "Provo Flying Service" small titles; erdale-Executive FL 20.3.85 Provo Flying Service; In no details, owner Charles Air Service;		
BA-697	H18	N177G	built	.64	
		N1772	landed wheels-up, Knoxville-Island TN Southeastern Beechcraft Inc, Knoxville TN Barnett First National Bank, Jacksonville FL Aamtax Corp, St Petersburg FL	21.11.64 66/70 70/72 5.6.73/91	
	N1772 note	ed West Pali	m Beach FL 19.7.81;		
BA-698	H18 trigear	N7962K	Beech Aircraft Corp, Wichita KS: CofA issued Tecumseh Products Inc, Tecumseh MI R & K Construction Inc, Orlando FL	9.7.64 66/70 71/72	
		N88DB N161SP	rereg AP St Philip Inc, Tampa FL Providence Air Charter, Providence RI op: Air Pensylvania Perkiomen Airways Ltd, Reading PA aborted takeoff, rolled into 14 feet gully, Hazelton PA	1.77/79 80 80/81 31.3.81 11.3.81	
	N161SP noted Miami FL 3.10.77, trigear, no titles, took off; N161SP accident report 11.3.81: Air Pensylvania: pax flight, took off with snow on wings, ran off runway into gully, 2 crew & pax unhurt;				
BA-699	H18 trigear	N7998K	Beech Aircraft Corp, Wichita KS: CofA issued General Oilfield Supply Co, Evansville IN nose gear collapsed landing, Atlanta-Fulton GA Julac Export Corp, Boynton Beach FL Renge Inc, Boynton Beach FL Justin K. Houghton, Shelbourne VT	29.1.65 66/79 17.4.81 10.81 5.86/91 7.7.92/20	
	N7998K no	ted Fort Laเ	uderdale FL 20.11.83 no titles, trigear; uderdale-Executive FL 25.10.84, 5.92; on VT 2.1.08 trigear, vista windows, exec paint scheme, in	n service;	
BA-700	H18	N828LS	Beech Aircraft Corp, Wichita KS: CofA issued	24.7.64	
	ATE		struck post taxying after landing, Houston TX Riviana Foods Inc, Abbeville LA	19.4.65 66	
	Westwind I		(rebuilt as <i>ATE Westwind I</i> trigear .67)	00	
	trigear	N995RF	Riviana Foods Inc, Abbeville LA	69/70	
	J	N355C	C. M. Waters, Alexandria LA	71/72	
			Metro Air Taxi, College Park MD	79	
			on: Active Aero Charter, Willow Pun MI	01	

op: Active Aero Charter, Willow Run MI

gear retracted on landing roll, Detroit-Metro MI

81

11.7.81

	Smithair Inc, Sharpsburg GA	85
	Ajax Aircraft Leasing Inc, Dover DE	5.85/93
N982AA	Ajax Aircraft Leasing Inc, Belleville MI	3.3.93
N355C	Ajax Aircraft Leasing Inc, Belleville MI	.93/94
	Yip Group, Belleville MI	11.94/95
	Rousch Air Inc, Livonia MI	16.2.95/11
	(support aircraft for Jack Rousch Ford Race Team,	
	retired Atlanta-Tara Field GA by 2009)	
	struck-off USCR	18.7.11
	(noted open storage stripped Tara Field GA 8.17,	
	reported fuselage to become a childrens playhouse)	

accident report 19.4.65: reg quoted as "N828LS": minor damage, no injuries;

N355C noted Washington-National 9.73, trigear PT-6 turbines;

N355C photo 3.81, no titles: trigear, turbines;

N355C accident report 11.7.81: no operator quoted, minor damage, cargo flight Ashville GA to

Detroit MI, pilot inadvertantly retracted gear 12.15am;

N355C noted Willow Run MI 14.7.81 Westwind I,

N335C noted Willow Run MI 3.8.89 trigear turbines,

N335C noted Willow Run MI 7.91 trigear turbine;

N355C noted Toronto ONT 16.2.85 Smithair, Sharpsburg GA;

N355C noted Willow Run MI 2.97 as Westwind I:

N355C noted Willow Run MI 2.3.97 trigear;

N335C noted Willow Run MI 8.97 Westwind I;

N355C noted Willow Run MI 3.8.99 freighter, stored with props removed, trigear, plate BA-700;

N355C noted Willow Run MI 23.7.00 freighter, stored with props removed, trigear;

N355C noted Willow Run MI 1.03 trigear;

N355C noted Willow Run 11.6.03 intact;

N355C noted Tara Field GA 20.8.17 standing outside on trigear, turbine nacelles, parts missing

BA-701	H18	N5733K	Beech Aircraft Corp, Wichita KS: CofA issued	31.7.64	
	trigear	N251R	Riegel Paper Corp, New York NY	66	
	· ·		International Air Service Co, Burlingame CA	69/70	
			Midvale Dynamics Corp, Clayton MO	71/72	
		N123MD	On Mark Aviation, Knoxville TN	79	
			Sair Aviation, Syracuse NY	7.84	
			Jim Hankins Air Service, Jackson MS	25.7.90/05	
			Monarch Air Group, Palm City FL	14.6.05/07	
			crashed destroyed after takeoff, Fort Lauderdale FL	21.9.07	

N123MD noted St Louis MO 2.6.76 trigear;

N123MD noted Panama City FL 13.8.98 trigear freighter, Jim Hankins AS;

N123MD: Jim Hankins Air Service fleet Status Report 10.8.98: TT 10,752 hrs;

8.02 report: N123MD still in service with Hankins;

crash 21.9.07 cargo flight to Bahamas, operated by Monarch Air Group, pilot badly hurt, struck building and crashed on highway, aircraft destroyed;

BA-702	H18	N7969K	Beech Aircraft Corp, Wichita KS: CofA issued	19.8.64
	trigear		Lehigh Portland Cement Co, Allentown PA	66
	J		Reading Aviation Service/ Suburban Airlines,	
			Reading PA	69/72
			Midstate Airlines, Marshfield WI	77/79
			Union Flights, Sacramento CA	.79/94
			Polynesian Airways, Honolulu HI	18.5.94/97
			crashed on takeoff, destroyed by fire Honolulu HI	22.2.97

BA-703	H18	PT-CEZ	Central Electrica de Furnas SA, Rio	.64/65	
	trigear		FA Brasileira as FAB TC-45T 2908		
	Ü	PT-KXI	reg.	.78	
			Jose R. D. Fortunato	9.6.80	
			Carlos Alberto Edo Palma, Sao Paulo	83	

BA-704	H18	N5645K	built	.64
D/1-1 U <del>1</del>	trigear	NOTOR	Iowa Beef Packers, Denison IA	66/69
	trigcar		Nickerson & Nickerson Service Co, Eldon MO	70
			Tidwell Industries Inc, Haleyville LA	71/73
			Volpar Inc, Van Nuys CA	75
			Bailey Leasing Corp, Fort Wayne IN	20.2.75
			Helitrans Australia, Cairns QLD	20.5.75/76
			(N5645K departed Oakland CA 7.6.75 on del. to	20.5.75/70
			Australia, arrived Cairns 14.6.75)	
		VH-PDI	Helitrans Australia Pty Ltd, Cairns QLD: reg	11.2.76/78
		VIII DI	Sunbird Airlines, Gladstone QLD	1.9.78
			Sunbird Airlines Pty Ltd, Gladstone QLD	19.12.78/80
			Helimuster Pty Ltd, Sydney-Bankstown NSW	14.1.80
			Eagle Airways, Sydney-Bankstown NSW	7.3.80/80
			nose gear collapsed landing Bankstown NSW	23.8.84
			Noel R. Vinson Trading Pty Ltd, Sydney NSW	5.9.84
			A. S. Collins, Sydney NSW	2.10.84
			Airtransit, Adelaide SA	88/89
		VH-ATX	Airtransit, Adelaide SA	6.12.89/94
			renamed: Air Kangaroo Island, Adelaide SA	90/94
			Russell Mann/ Sunland Aviation,	
			Brisbane-Archerfield QLD: delivered to Archerfield	17.6.94/04
			(restored at Archerfield 94/99, ff 27.4.99)	
			Russell Mann/ Antique Airways, Redcliffe QLD	.99/11
			Anthony Mitchell, Perth WA	15.7.11/14
			Lena Votrubec, Sydney NSW	27.1.15/20
			• •	

N5645K purchased by Helitrans from Volpar in deal through Bailey Leasing Co, TT 4683 hrs; ferry pilot was Peter Jensen of Helitrans who arrived Van Nuys 4.75 while aircraft being prepared by Volpar;

N5645K noted Long Beach CA 20.5.75 for installation of ferry kit;

Jensen was endorsed on type then departed Van Nuys 6.6.75 for Oakland, departed Oakland on evening of 7.6.75 for Hawaii; routed Honolulu, Pago Pago, Port Vila, Cairns: 52 hrs 15min flying time ex Van Nuys;

Operated with N number for first 6 months based Cairns, with VH-PDI on wings, flew to Sydney 7.75 to collect a Turbomeca turbine for a chopper; last flight as N5645K was Moresby-Cairns 14.12.75 for inspection for Australian CofA CAA gave type certification 1.76, ff after maintenance Cairns 14.2.76 as VH-PDI; Used for regular flight Cairns to PNG & West Irian; after 1977 Helitrans began withdrawing from rotary sphere (from a total of 26 helicopters), and established Bankair with a weeknight courier by VH-PDI to Brisbane, then founded Sunbird Airlines 9.10.78 on the Helitrans licence with PDI as its first aircraft on inaugural scheduled pax service Rockhampton-Gladstone QLD;

## Australian Register:

11.2.76 VH-PDI:

owner George H.Bailey Co Inc, Ft Wayne IN. CofR Holder: Helitrans Australia Pty Ltd, Cairns Qld 21.6.78 VH-PDI: owner Helitrans PNG Pty Ltd, Lae PNG CofR Holder: Helitrans Australia Pty Ltd, Cairns Qld

N5645K arrived Mascot 12.7.75 Helitrans;

N5645K noted Mascot NSW 17.7.75, 19.7.75;

N5645K still on USCR91: Bailey Leasing Corp;

VH-PDI arrived Moorabbin 3.9.76 to collect parts from Jayrow Helicopters, based at Cairns with Helitrans Pty Ltd;

VH-PDI noted Bankstown 12.9.76 white & red;

VH-PDI noted Cairns 12.11.79 red/white scheme"Sunbird Airlines" titles; report:

Sunbird Airlines used VH-PDI on passenger scheduled service Rockhampton-Gladstone;

VH-PDI noted Bankstown 28.4.80 operator Eagle AW new blue/white scheme "HM" on tail no titles; VH-PDI visited Perth WA 4.5.80:

VH-PDI noted Bankstown 26.5.80 Eagle Airways;

VH-PDI visited Essendon 6.80 "Eagle Airways" titles with Big Bird cartoon on nose;

VH-PDI noted Bankstown 20.4.81 "Eagle Airways" titles, blue & white;

(VH-ATX listed as DoT Reserved Regs list 7.88 as H18 forAir-Transit)

VH-ATX noted Adelaide 30.12.89 trigear;

VH-ATX noted Adelaide SA 8.11.90 Airtransit;

VH-ATX noted Archerfield 12.95 stripped:

VH-ATX delivered to Redcliffe QLD 4.5.99 to be based here with Antique Airways who also have Beech 17 Staggerwing VH-UXP & Tiger Moth VH-BJE;

VH-ATX at airshow Scone NSW 29.9.01;

VH-ATX at airshow Port Macquarie NSW 2.11.02 trigear, flying;

VH-ATX at airshow RAAF Amberley QLD 2.10.04 "Antique Airways" titles;

VH-ATX at airshow Bundaberg QLD 15.7.05 "Antique Airways" trigear, flying;

VH-ATX noted Coolangatta 31.7.08, crew training prior to being based for a year at Derby WA;

VH-ATX noted Derby WA 12.8.08; reportedly auctioned at Derby in 2010;

VH-ATX noted Wollongong-Albion Park NSW 14.7.16, 14.2.20;

		_		
BA-705	H18	N5738K	built	.64
			Arkansas Best Freight System, Fort Smith AR	69/70
		N500JH	Vero Aero Inc, Vero Beach FL	71/76
			Bob Bixler, San Jose CA	1.3.76
			sold to Tahiti, struck-off USCR	1.6.76
		F-ODCT	Jacques Brun, Papeete, Tahiti	27.8.76/80
			CofA expired 31.7.78, retired at Papeete, Tahiti	
			Michael Mousseigne, Villepreux, France: reg	25,8,80
			burnt for fire practice Tahiti: struck-off Register	5.10.89
BA-706	H18	N303X	built	.64
	trigear		Brockway Glass Co, Brockway PA	66
		N3033	Lester Welch, Tampa FL	69/70
			Jack Adams Aircraft Sales, Walls MS	71/72
		N729F	L. L. Hyde, Comstock NE	25.1.78/80
			op: Allen County Air	80
			crashed destroyed landing in snowstorm, Olathe KS	15.2.80
	N729F ad	ccident report 1	e AZ 26.5.73 trigear; 5.2.80: Allen County Air, cargo flight Olathe to Iola KS, i	
			Executive, due NDB & ILS u/s at destination, ice on airfifailed, 3.28pm, pilot k;	rame,
BA-707	H18	N611Y	built	.64
			W. H. Gonyea, Springfield OR	66/70
			Woodmont Stables, Upper Montclair NY	71/72
			3D Enterprises, Shreveport LA	78
			Ben G. O. Neal Inc, Grand Cane LA	27.12.78/82
			struck-off USCR	6.12.82
			Strack on Cook	0.12.02
	N611Y no	oted New York-	La Guardia NY 8.9.71, 31.3.72;	
BA-708	H18	N5765K (2	Beech Aircraft Corp, Wichita KS: CofA issued	23.9.64
	trigear	N22T (2	Fort Worth National Bank, Fort Worth TX	66/70
	<b>3</b>	`	Fort Worth National Co of Texas, Fort Worth TX	71/72
		N22TL	rereg	<del>-</del>
		N22TB	rereg	
			John B. McDuff, Houston TX	79
			G. D. Ward, Stephenville TX	4.83
			sale reported: USCR	91
			saic reported. Ooon	3 I
	N22TL no	oted San Anton	io TX 16.5.73 trigear;	
BA-709	H18	N888Q	Beech Aircraft Corp, Wichita KS: CofA issued	2.10.64
	trigear		BLC Corp, Boston MA	66/70
	. 3		Linden Flight Service, Linden NJ	71/72
		N21U (2	Louisiana Executive Air, Morgan City LA	79
		14210 (2	(noted impounded, Grand Turk 4.81)	, 0
			Lawrence D. Morris, Manchester KY	4.82
			Lawrence D. Worlds, Manchester KT	40.02

Haiti Water Supply Inc, Miami FL

sale reported, Miami FL: USCR

12.82

91

BA-710	H18	N5658K N717Z	Beech Aircraft Corp, Wichita KS: CofA issed Lockheed Aircraft Corp, Marietta GA	18.9.64 66/69
		INT ITZ	Pine Branch Coal Sales, Lexington KY	70
				70 71/72
			Mercury Aircraft Inc, Lexington KY	
			crashed destroyed landing in fog, Charlottsville VA	29.11.71
			Sunstream Aircraft Inc, Chicago IL	30.5.74/94
			struck-off USCR	4.94
BA-711	H18	N926T	built	.64
			Leon Fill, Huntington Woods MI	66/69
	ATE		Normich Laboratories, Detroit MI	70/72
	Westwind I		(rebuilt as ATE Westwind I trigear with PT-6A-60As,	
	trigear		completed 7.70, CofA issued 13.7.70;	
	J		ATE kit 600, serial #39: mod. plate states Westwind I-60	00)
	Hamilton		(later converted to Hamilton Westwind III with conventio	•
	Westwind II	I	tailwheel and PT6A-27s by Hamilton)	
	tailgear		Lawrence C. Maxson/ Maxson Aviation, Kotzebue AK	78/79
	J		gear collapsed landing on short strip, Omilik AK	10.7.79
			Blackhawk Airways, Janesville WI	80
			op: Pronto Aviation Services, El Paso TX	c81
		Buck Maxs	on, Kotzebue AK	3.83
			Methow Aviation, Wenatchee WA & Everett WA	26.2.86/01
			Cascade Air, Ephrata WA	00
			(retired stored Ephrata WA 00, Methow titles)	
			damaged in groundloop on takeoff, Seattle WA	10.3.86
			Jim West/ Skydive Greene County Inc, Xenia OH	10.12.02/13
		N75GJ	Skydive Greene County Inc, Xenia OH	.13/20

FAA File: By 78 BA-711 had PT6A-27 turbines, owned Maxson Aviation;

(USCR 91 quotes type H18/T, PT-6A-60As)

10.3.86 accident: Methow Aviation: groundloop on takeoff Seattle-Tacoma Airport, PT6A-27s; N926T noted Everett WA 24.5.90 Westwind III "Merthow" titles;

N926T noted Ephrata WA 22.3.00 dumped, "Methow" titles, no engines; reported as Hamilton Westwind I-600, c/n 39;

N926T noted Ephrata WA 22.5.01 ex longtime resident of Paine Field;

N926T noted Xenia OH 1.8.05 in hangar at Jim West's farm near airfield, under rebuild to fly, plate: Westwind I-600, c/n 39 date 20.7.70 Hamilton Aircraft, Tucson AZ;

BA-712	H18	JA5506	built	23.10.64
			Maritime Safety Board, Sendai	65
			Maritime Safety Agency, Hiroshima	70/80
			Nihon Technology Corp	80
		N8475E	Eugene C. Eversole, Honolulu HI	22.7.80
			(US CofA issued 19.5.81)	
			Àdrian I. Dalsey, Honolulu HI	23.7.81/86
			op: DHL Cargo, Honolulu HI	81/83
		RP-C709	Commuter Air Philippines, Manila	86/91
			Air Charter Philippines, Manila crashed	90
			wreck stored Bacolod, Philippines	90/94
			struck-off Register	20.9.06

JA5506 noted Osaka 27.4.73 & 24.5.73 both MSA (plate BA-712);

JA5506 noted Hiroshima 12.2.74;

JA5506 noted Hiroshima 25.7.77;

JA5506 noted Hiroshima 30.6.80 retired;

N8475E noted Honolulu 23.8.81 in service with DHL in DHL orange & white scheme no titles; RP-C709 noted Manila 10.9.86 tailwheel, "Commuter Air Philippines" titles, ex DHL orange And white paint scheme;

RP-C709 wrecked fuselage noted Bacolod 1.91 & 1.94;

BA-713	H18	N8631Q	built	.64
		N153GP	Georgia Pacific Corp, Portland OR	66/72

ATE	(rebuilt as American Turbine Engine Co ATE Westwind I:	
Westwind I	PT6A turbines, trigear completed 68)	
trigear	FFC Inc	74
	Isd: Mountain Air Cargo, Denver NC	74
Hamilton	(rebuilt as Hamilton Westwind III with tail gear,	
Westwind III	by Hamilton Aviation at Tucson AZ)	
tailgear	Tobey Inc, Simsbury CT	78
	Check-Air, Milwaukee WI	.77/79
	op: Mountain Air Cargo, Denver NC	80/84
	Coastal States Aviation, Denver NC	10.86
	struck-off USCR	14.9.88
RP-C934	Metro Manila Airways International, Manila	.88/90
	(delivered via Keflavik-Glasgow 25.7.88)	
	Territory Airlines, Goroka PNG/ Metroair	.90
	retired Manila .90, stripped airframe sold	.92
	struck-off Register	.92
	Charles R. Miller/ CM Aero, Manila: for parts	93/97

N153GP photo in "Janes" as type Westwind III;

N153GP noted Milwaukee WI 11.3.77 Westwind III tailwheel, "Check Air" titles;

N153GP noted Indianapolis IN 7.9.84 freighter, callsign "Mountain Air 14";

N153GP noted Milwaukee WI 1.9.78 Check Air;

N153GP del. Keflavik-Aberdeen-Glasgow 25.7.8 Manila Airways titles;

RP-C934 photo Manila 88: Westwind III "Manila Airways" titles, long nose, tailwheel;

Note: Metro Manila Airways International purchased by TAL, PNG .90 to acquire charter licence and hangar facilities at Manila and renamed Metroair, Westwinds replaced by TAL Twin Otters;

Metroair closed down 2.92 by TAL: turbines and propellers of the 2 Westwinds removed and sent to PNG for resale, airframes offered for sale: appears both went to Chuck Miller for parts; RP-C934 noted Manila 2.1.94;

Parmerter quotes Georgia Pacific Chief Pilot Bob Carter as stating that N153GP was rereg N153LP for a period in 1973 with the affiliated company Louisiana Pacific.

BA-714	H18	N7996K	built	.64
	trigear	N571DU	rereg	
		N571DD	Atlantic Aviation Corp, Wilmington DE	66
			E. I. DuPont de Nemours & Co, Wilmington DE	69/70
			Uni-Lease Inc, Allenhurst NJ	71/72
			R. D. Goodner, Duncan OK	75/79
			Cannavo Aviation, Claymont DE	11.83
			Mid-South Aircraft Sales, Memphis TN	7.87
			Cape Central Airways, Cape Girardeau MO	8.3.88/94
			struck-off USCR	17.3.94

N571DC noted Long Beach CA 6.8.71: reg not listed by Parmerter; N571DD noted Harlingen TX 11.75, trigear;

BA-715	H18	N5758K	built	.64
		N572D	Atlantic Aviation Corp, Wilmington DE	66
			E. I. DuPont de Nemours & Co, Wilmington DE	69
			National Financing Inc, Wilmington DE	70/72
		N500MM	Misener Marine Construction Inc, St Petersburg FL	24.6.74
			crashed destroyed by fire, St Augustine FL	31.12.74
BA-716	H18	N140Q	built	.64
	trigear		Thomas J. Watson, Stowe VT	66
			Exel Corp, Elkhart IN	69/72
		N140QC	rereg	
		N23LT	Niles Machine & Welding Co, Niles OH	79
			Eighty Five Delta Inc, Nennah WI	4.83
			Basler Flight Service, Oshkosh WI	1.85/89
		N911BF	Basler Flight Service, Oshkosh WI	1.89/94
			Basler Turbo Conversions Inc, Oshkosh WI	15.3.94/96
			Welch Aviation, Alpena MI	22.1.96
			DJW Inc. Wooster OH	7.96/97

N223JW	DJW Inc, Wooster OH	4.97/99
	Jerome Airport, Pittsburgh-Allegheny County PA	15.9.99/05
	Michael E. Rindler, Southwest Harbour ME	26.6.06/08
	Richard L. Standage, Moorpark CA	12.5.10/11
	Sold to new owner, Trier, Germany	11/15
	Aircraft Guaranty Corp Trustee: USCR: based Germany	4.6.11/13
	stbd main gear retracted landing, ran off runway,	
	Trier-Fohren, Germany	21.10.12
	exported to Germany, struck-off USCR	15.5.13

N911BF at fly-in Oshkosh WI 27.7.89 "Basler" trigear, plate BA-716; N223JW at fly-in Oshkosh 30.7.00 trigear owned Jay Airport, Allegheny County Airport, N223JW noted Pittsburgh, large nose art "Latitude Adjustment" plate BA-716; N223JW at fly-in Oshkosh 27.7.03 "Latitude Adjustment", trigear; N223JW at Beech fly-in Tullahoma TN 14.10.07 blue & white, trigear;

66/69
70
.70
72/85
1.5.85
4.90/96
3.4.96/02
8.10.03/07
06/07
9.2.07

N45GM noted Gillette WY 3.8.00 trigear, plate BA-717 built 11.67; N45GM noted Ankeky IA 9.5.03 trigear no titles; accident report 9.2.07: op Bygone Aviation LLC, freight flight from Wichita to Great Bend, crashed during ILS in poor weather;

BA-718 •	H18	N8668Q	Beech Aircraft Corp, Wichita KS: CofA issued	9.11.64
	trigear		Noble Drilling Corp, Tulsa OK	66/72
	J		Oklahoma State University, Stillwater OK	79/82
		N430SU	Oklahoma State University, Stillwater OK	11.82/91
			Ted Neal/ California Coast University, Prescott AZ	21.7.94/94
		N700TN	California Coast University, Prescott AZ	18.8.94/99
			Lace Air Inc, Dover DE	22.12.99/01
			California Coast University, Santa Ana CA	20.2.01/07
			Mercy Airlift Inc, Palm Springs CA	16.7.08/12
			B-25 Mitchell Inc, Tulsa OK	7.6.12/18
			Real Aeroplane Club, Breighton, England	.18/20
			Real Aero Inc, Wilmington DE: USCR	27.8.18/20
			(del to England via Goose Bay-Narsarsuaq 17-18.6.19)	

N8668Q noted Tulsa OK 30.9.71 trigear; N700TN nored Breighton, Yorkshire 29.6.19, orange & white, trigear;

BA-719	H18	N5666K	Beech Aircraft Corp, Wichita KS: CofA issued	12.11.64
	trigear		66	
	3 - 1			70/72
		N7377M	rereg	
		N105AF	Airlie Foundation, Warrenton VA	79
			Doak V. Boreing, Hot Springs AR	10.87/95
		Pro Turbine Inc, Hot Springs AR	Pro Turbine Inc, Hot Springs AR	8.97
	C-Tiger Enterprises Ltd, Wilmington DE op: GB Airlink, Fort Lauderdale FL	C-Tiger Enterprises Ltd, Wilmington DE	18.11.97/07	
		op: GB Airlink, Fort Lauderdale FL	02/05	
			struck-off USCR as scrapped	23.1.07

N105AF noted Atlanta TX 10.87 trigear;

N105AF noted Ft Lauderdale FL 12.1.98, 9.12.98 trigear;

N105AF noted Ft Lauderdale-Executive FL 28.6.02 "GB Airlink" titles, trigear, in service;

N105AF noted Ft Lauderdale FL 4.4.01;

N105AF noted Ft Lauderdale FL 5.03 "GB AirLink" titles, trigear in service;

N105AF noted Ft Lauderdale FL 12.1.05 "GB Air Link" titles, trigear

BA-720	H18	N5850S	Beech Aircraft Corp, Wichita KS: CofA issued	7.1.65
			Krause Milling Co, Millwaukee WI	66/78
			Clifford A. Marlatt/ Sky Castle Aviation, New Castle IN	78/80
		(N585SC)	ntu: Sky Castle Aviation	3.79
		N5850S	David Kent Dill, Indianapolis IN	4.82
			Kelley Cars Inc, Fort Wayne IN	10.83
			Ronald W. Smith, Fort Lauderdale FL	12.12.85/87
			crashed destroyed, Rockford IL	22.9.87
BA-721	H-18	N404X (2	Beech Aircraft Corp, Wichita KS: CofA issued	17.2.65
	trigear	•	Brockway Glass Co, Brockway PA	11.65/66
	_	N4043	rereg	
		N595AF	Albany Felt Company	
			dam. landing Bromont QUE Canada, slid off snow cover	ed
			runway into snow drift, nose gear torn off	17.12.68
			Page Airways, Rochester NY	69
		N5959F	Page Airways, Rochester NY	70
			Graham Manufacturing Co, Batavia NY	71/99
			(business flights to UK & Europe 6.75 & 6.77)	
			Sterling A. May, Dallas TX	24.5.99/02
			C. & L. Kelley Inc, Fort Myers FL	29.5.03/16
			Mid Atlantic Air Museum, Reading PA	16.3.16/20

further detail European visits: Parmerter p.310;

N5959F noted Staverton UK 19.6.77,

N5959F noted Manchester 23.6.77 "Volpar";

N5959F departed Hurn for Faroe Isles 14.6.75;

N5959F noted Prestwick 24.6.77 Graham Manufacturing Co;

N5959F won award at Reading PA airshow 78: Graham Manufacturing Co;

N5959F noted Toronto ONT 3.4.82 Graham Manufacturing Co NY (no titles);

N5959F at Tullahoma TN Beech fly-in 10.10.90;

N5959F at Tullahoma TN Beech fly-in 16.10.94;

N5959F at Tullahoma TN Beech fly-in 13.10.95;

N5959F at Wichita KS Beech fly-in 11.10.97;

N5959F at Beech fly-in Tullahoma TN 14.10.07;

Adv for sale 11.15: based Ft Myers FL, TT 9630 hrs;

BA-722	H18	N909T	built	.65
			Texize Chemical Inc, Greenville SC	66
			crashed destroyed by fire, landing Norwich NY	12.1.68
BA-723	H18	N5860S	built	.65
		N46A (2	rereg	.65
		N711 (4	Margaretta Carpenter, Wilmington DE	66/72
		N711LC	rereg	9.4.73
			W. F. Larson Inc, Plainview TX	79
			Flite Service Inc, Pine Mountain GA	18.5.85/94
			emergency landing due right engine fire,	
			wing extensive fire damage, Sandersville GA	8.10.87
			struck-off USCR	19.7.94
BA-724	H18	N835K	Kellogg Co, Battle Creek MI: CofA issued	19.4.65/66
	trigear		Georgia Iron Works, Grovetown GA	69/79
	· ·		Mid South Aircraft Sales, Memphis TN	7.81
			Thomas G. Todd, Tavernia FL	8.81/95
			Steve Hopkins	97
			Golf Capital Corp, Miami FL	27.5.98/99
			Eureka Operating Company, Odessa TX	6.3.99/02

N835K noted Hilton Head Island SC 3.9.77;

N835K noted Tamiami FL 1.5.95 trigear;

Advertised for sale 4.97 Steve Hopkins: factory trigear, only 3 owners since new;

crash report 1.7.02: owned by private individual, commercial pilot only occupant, departed Taos NM and struck the ground 2 hours later near a farm at Tatum NM, destroyed;

BA-725	H18	N398T	Diesel Engine Sales Inc, St. Augustine FL: CofA issued	19.4.65/66
271120	trigear	N3987	Ring Power Corp, Jacksonville FL	69
	3 - 1		Cone Bros Contracting Co, Tampa FL	70
		N51AN (2	Air North, Burlington VT	71/72
		•	Chicago & Southern Airlines, Chicago IL	71
		N38BW	Sam Vires/ Mid-South Aircraft Sales, Memphis TN	79
			Panorama Air Tour, Honolulu HI (fleet #66)	79/85
			Airtour Acquisition Corp, Honolulu HI	82
			Lani Bird Inc, Honolulu HI	6.85
			Waikiki Circle Tour & Travel, Honolulu HI	7.85
			Tomy International Inc, Honolulu HI	3.91/95
			Matthew R. Barnett, Honolulu HI	31.8.95/96
			Raymond Hinely, Greensboro GA	24.4.96/06
			Larry Joe Pruden, Louise MS	18.5.09/20

N38BW noted Kona HI 5.10.80 Panorama AT #66;

N38BW noted Kauai HI 27.8.81 "Panorama Air Tour" #66 brown scheme, trigear;

N38BW noted Honolulu 9.83 "Panorama Air" fleet #66, trigear;

Panorama Air fleet list as at 15.11.83: BA-725 tt 11,798 hrs, fleet #66;

N38BW noted Honolulu 29.10.85 Lani Bird;

N38BW noted Kahului HI 2.88 "Scenic Air Tours" titles, allover yellow;

N38BW noted Honolulu 7.89 "Scenic Air Tours", fleet #28; trigear, flying;

N38BW noted Honolulu 12.93, 23.11.94: "Scenic Air Tours": fleet #28, green, trigear;

N38BW noted Ft Lauderdale FL 9.12.98, trigear, op Carib Air Cargo;

N38BW noted Ft Lauderdale FL 4.4.01 trigear;

BA-726	H18	N727X	Beech Aircraft Corp, Wichita KS: CofA issued	14.6.65
	trigear	N129GP (2	Ontario Airways, Auburn NY	66/67
		N1299P	rereg	
		N177X (2	Henson Aviation, Hagerstown MD	71/72
			DelMar Mullens, Hayward CA	79
			Complete Equity Markets Inc, Wheeling IL	6.84
		N516CE	Complete Equity Markets Inc, Wheeling IL	11.84
			Carrier Executive Motors Inc, Wheeling IL	21.5.86/06
		N777XJ	Great Planes Inc, Lawrence KS	24.11.09/13
			David B. Fields, Midland TX	2.8.13/20

N177X noted Hayward CA 25.7.81, N177X noted Hayward CA 4.84;

N516CE noted Janesville-Rock County WI 7.91 Blackhawk Airways ramp, plate BA-726;

N516CE noted Rock County WI 7.97 trigear, plate BA-726;

N516CE noted Janesville-Rock County WI 7.8.97, 2.8.98, 26.7.99, based here, trigear;

N516CE noted Janesville-Rock County WI 10.9.02 hangared here, departed for Atlanta;

N516CE noted Janesville WI 23.7.03 trigear;

N777XJ at Beech fly-in Tullahoma TN 18.10.14;

BA-727 •	H18	N7927K	built	.65
	trigear	trigear Michigan Aeronautics Commission, Lansir	Michigan Aeronautics Commission, Lansing MI	66
	-	N6000M (2	Michigan Aeronautics Commission, Lansing MI	69/99
		(flew Michigan Governor, George Romney)	(flew Michigan Governor, George Romney)	
			minor damage hit snowbank landing, Grayling MI	12.3.75
		N6000M	Cody Welch/ CF & S Company Inc, Linden MI:	
			restored to USCR	4.8.99/01
			KEL LLC, Ogallala NE	17.1.02/05
			Time Bandits LLC, Henderson NV	18.4.06/13
			Aircraft Guaranty Corp, TX: trustee: USCR	29.3.13/20
			(N6000M del via Goose Bay LAB to Narsaruaq 11.5.13, via Reykjavik, Iceland 13.5.13)	
			, ,,	

N6000M accident report 12.3.75: flight Marquette Mi to Grayling, 3.15pm, 6 unhurt; N6000M at fly-in Oshkosh 30.7.00 trigear, plate BA-727, owned Cody Welch/CF&S Co; N6000M at fly-in Oshkosh 26.6.01 trigear;

N6000M at fly-in Oshkosh 23.7.02 trigear, plate BA-727 PSI Digital NE;

BA-728	H18	JA5133	built	4.65
			sold to USA, struck-off Register	27.9.76
		N92756	reg	9.76
			(US CofA issued 11.5.77)	70/04
			M & M Air Service, Huntsville AL	79/94 13.9.94/17
			Jim Hankins Air Service, Jackson MS	13.9.9 <del>4</del> /17 c01
			damaged on ground by windstorm, Columbus GA (under rebuild by Hankins at Jackson MS 8.02)	CUT
			Dakota Express LLC, Wilmington DE	14.11.17/20
	.IΔ5133 n	oted Chiyoufu	•	14.11.17720
		oted Chofu 13.		
		oted Tokyo-Ha		
	JA5133 n	oted Chofu 18.	.12.75;	
		oted Jackson i		
			MS 11.8.98, Hankins Air Service;	
			r Service fleet Status Report 10.8.98: TT 8823 hrs;	
			MS 1.8.02 under rebuild for Hankins A/S after windstorm of	lamage at
			-728 spar kit 1509 s/n 195 22.4.75;	
	N92756 n	oted Jackson i	MS 5.8.08 Jim Hankins AS;	
BA-729	H18	N402A	Beech Aircraft Corp, Wichita KS: CofA issued	14.7.65
J. 1 L J	trigear	N402A N402AP	Atlas Plastics Corp, Cape Girardeau MI	.65/69
	9001		Computer & Business Management, Cleveland OH	71/72
		N22BR	Two Bar Ranch, Wheatland WY	79
		· · · · · · · · · · · · · · · · · · ·	James E. Swann, Greenwood MO	9.82
			Jerry L. Englund/ Englund Air Inc, Mobile AL	2.88
			James E. Swann, Independence MO	1.89
			Englund Air Inc, St Elmo AL	1.90
			Jim Hankins Air Service, Jackson MS	15.11.90/17
	N22BD:	lim Hankins Air	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE	
	8.02 repo N22BR no	rt: N22BR still . oted Jackson-F	Jim Hankins Air Service, Jackson MS	15.11.90/17
BA-730	8.02 repo N22BR no N22BR no	rt: N22BR still option of the still option option of the still option option of the still option optio	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;	15.11.90/17 14.11.17/20
BA-730	8.02 repo N22BR no N22BR no H18	rt: N22BR still . oted Jackson-F	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS;	15.11.90/17
BA-730	8.02 repo N22BR no N22BR no	rt: N22BR still oted Jackson-F oted Jackson-F N630TL	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;  Time Life Inc, New York NY: CofA issued	15.11.90/17 14.11.17/20 2.8.65/70
BA-730	8.02 repo N22BR no N22BR no H18	rt: N22BR still oted Jackson-F oted Jackson-F N630TL N684HA	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;  Time Life Inc, New York NY: CofA issued Tecumseh Aircraft Leasing, Dover DE	15.11.90/17 14.11.17/20 2.8.65/70 71/72
BA-730	8.02 repo N22BR no N22BR no H18 trigear	rt: N22BR still oted Jackson-h oted Jackson-h N630TL N684HA N97BC	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;  Time Life Inc, New York NY: CofA issued Tecumseh Aircraft Leasing, Dover DE McBride & Shoff, Metamora IL	15.11.90/17 14.11.17/20 2.8.65/70 71/72 79
	8.02 repo N22BR no N22BR no H18 trigear	rt: N22BR still oted Jackson-h oted Jackson-h N630TL N684HA N97BC oted Detroit-Do	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;  Time Life Inc, New York NY: CofA issued Tecumseh Aircraft Leasing, Dover DE McBride & Shoff, Metamora IL Richard J. Jones, Detroit MI	15.11.90/17 14.11.17/20 2.8.65/70 71/72 79 2.8.79/91
	8.02 repo N22BR no N22BR no H18 trigear	rt: N22BR still oted Jackson-h oted Jackson-h N630TL N684HA N97BC	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;  Time Life Inc, New York NY: CofA issued Tecumseh Aircraft Leasing, Dover DE McBride & Shoff, Metamora IL Richard J. Jones, Detroit MI  Dewntown MI 9.80 trigear;	15.11.90/17 14.11.17/20 2.8.65/70 71/72 79 2.8.79/91
	8.02 repo N22BR no N22BR no H18 trigear	rt: N22BR still oted Jackson-h oted Jackson-h N630TL N684HA N97BC oted Detroit-Do	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;  Time Life Inc, New York NY: CofA issued Tecumseh Aircraft Leasing, Dover DE McBride & Shoff, Metamora IL Richard J. Jones, Detroit MI  Dewntown MI 9.80 trigear;  reg Maritime Safety Agency, Sendai	15.11.90/17 14.11.17/20 2.8.65/70 71/72 79 2.8.79/91 1.9.65 70/81
	8.02 repo N22BR no N22BR no H18 trigear	rt: N22BR still oted Jackson-h oted Jackson-h N630TL N684HA N97BC oted Detroit-Do	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;  Time Life Inc, New York NY: CofA issued Tecumseh Aircraft Leasing, Dover DE McBride & Shoff, Metamora IL Richard J. Jones, Detroit MI  Dewntown MI 9.80 trigear;  reg Maritime Safety Agency, Sendai retired	15.11.90/17 14.11.17/20 2.8.65/70 71/72 79 2.8.79/91 1.9.65 70/81 30.6.81
	8.02 repo N22BR no N22BR no H18 trigear	rt: N22BR still oted Jackson-h oted Jackson-h N630TL N684HA N97BC oted Detroit-Do	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;  Time Life Inc, New York NY: CofA issued Tecumseh Aircraft Leasing, Dover DE McBride & Shoff, Metamora IL Richard J. Jones, Detroit MI  Dewntown MI 9.80 trigear;  reg Maritime Safety Agency, Sendai retired Fora Sorenson, Pensacola FL	15.11.90/17 14.11.17/20 2.8.65/70 71/72 79 2.8.79/91 1.9.65 70/81 30.6.81 11.8.81
	8.02 repo N22BR no N22BR no H18 trigear	rt: N22BR still oted Jackson-h oted Jackson-h N630TL N684HA N97BC oted Detroit-Do	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;  Time Life Inc, New York NY: CofA issued Tecumseh Aircraft Leasing, Dover DE McBride & Shoff, Metamora IL Richard J. Jones, Detroit MI  Dewntown MI 9.80 trigear;  reg Maritime Safety Agency, Sendai retired Fora Sorenson, Pensacola FL op: Circle Rainbow Air Inc, Honolulu HI	15.11.90/17 14.11.17/20 2.8.65/70 71/72 79 2.8.79/91 1.9.65 70/81 30.6.81 11.8.81 83
	8.02 repo N22BR no N22BR no H18 trigear	rt: N22BR still oted Jackson-h oted Jackson-h N630TL N684HA N97BC oted Detroit-Do	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;  Time Life Inc, New York NY: CofA issued Tecumseh Aircraft Leasing, Dover DE McBride & Shoff, Metamora IL Richard J. Jones, Detroit MI  Dewntown MI 9.80 trigear;  reg Maritime Safety Agency, Sendai retired Fora Sorenson, Pensacola FL op: Circle Rainbow Air Inc, Honolulu HI Hutchinson Auto & Air Transport, Honolulu HI	15.11.90/17 14.11.17/20 2.8.65/70 71/72 79 2.8.79/91 1.9.65 70/81 30.6.81 11.8.81
	8.02 repo N22BR no N22BR no H18 trigear	rt: N22BR still oted Jackson-h oted Jackson-h N630TL N684HA N97BC oted Detroit-Do	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;  Time Life Inc, New York NY: CofA issued Tecumseh Aircraft Leasing, Dover DE McBride & Shoff, Metamora IL Richard J. Jones, Detroit MI  Dewntown MI 9.80 trigear;  reg Maritime Safety Agency, Sendai retired Fora Sorenson, Pensacola FL op: Circle Rainbow Air Inc, Honolulu HI Hutchinson Auto & Air Transport, Honolulu HI Circle Rainbow Air Inc, Honolulu HI	15.11.90/17 14.11.17/20 2.8.65/70 71/72 79 2.8.79/91 1.9.65 70/81 30.6.81 11.8.81 83 1.84 12.86
	8.02 repo N22BR no N22BR no H18 trigear	rt: N22BR still oted Jackson-h oted Jackson-h N630TL N684HA N97BC oted Detroit-Do JA5507 N69094	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;  Time Life Inc, New York NY: CofA issued Tecumseh Aircraft Leasing, Dover DE McBride & Shoff, Metamora IL Richard J. Jones, Detroit MI  Dewntown MI 9.80 trigear;  reg Maritime Safety Agency, Sendai retired Fora Sorenson, Pensacola FL op: Circle Rainbow Air Inc, Honolulu HI Hutchinson Auto & Air Transport, Honolulu HI Circle Rainbow Air Inc, Honolulu HI struck-off USCR	15.11.90/17 14.11.17/20 2.8.65/70 71/72 79 2.8.79/91 1.9.65 70/81 30.6.81 11.8.81 83 1.84 12.86 21.10.88
	8.02 repo N22BR no N22BR no H18 trigear	rt: N22BR still oted Jackson-h oted Jackson-h N630TL N684HA N97BC oted Detroit-Do	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;  Time Life Inc, New York NY: CofA issued Tecumseh Aircraft Leasing, Dover DE McBride & Shoff, Metamora IL Richard J. Jones, Detroit MI  Dewntown MI 9.80 trigear;  reg Maritime Safety Agency, Sendai retired Fora Sorenson, Pensacola FL op: Circle Rainbow Air Inc, Honolulu HI Hutchinson Auto & Air Transport, Honolulu HI Circle Rainbow Air Inc, Honolulu HI struck-off USCR Pacific Airways Corp, Manila	15.11.90/17 14.11.17/20 2.8.65/70 71/72 79 2.8.79/91 1.9.65 70/81 30.6.81 11.8.81 83 1.84 12.86 21.10.88 .89/91
	8.02 repo N22BR no N22BR no H18 trigear	rt: N22BR still oted Jackson-h oted Jackson-h N630TL N684HA N97BC oted Detroit-Do JA5507 N69094	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  The Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;  Time Life Inc, New York NY: CofA issued Tecumseh Aircraft Leasing, Dover DE McBride & Shoff, Metamora IL Richard J. Jones, Detroit MI  Dewntown MI 9.80 trigear;  reg Maritime Safety Agency, Sendai retired Fora Sorenson, Pensacola FL op: Circle Rainbow Air Inc, Honolulu HI Hutchinson Auto & Air Transport, Honolulu HI Circle Rainbow Air Inc, Honolulu HI struck-off USCR Pacific Airways Corp, Manila ditched in river Cagayan de Oro	15.11.90/17 14.11.17/20 2.8.65/70 71/72 79 2.8.79/91 1.9.65 70/81 30.6.81 11.8.81 83 1.84 12.86 21.10.88
	8.02 repo N22BR no N22BR no H18 trigear N97BC no	rt: N22BR still oted Jackson-h oted Jackson-h N630TL N684HA N97BC oted Detroit-Do JA5507 N69094  RP-C1104	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;  Time Life Inc, New York NY: CofA issued Tecumseh Aircraft Leasing, Dover DE McBride & Shoff, Metamora IL Richard J. Jones, Detroit MI  wintown MI 9.80 trigear;  reg Maritime Safety Agency, Sendai retired Fora Sorenson, Pensacola FL op: Circle Rainbow Air Inc, Honolulu HI Hutchinson Auto & Air Transport, Honolulu HI Circle Rainbow Air Inc, Honolulu HI struck-off USCR Pacific Airways Corp, Manila ditched in river Cagayan de Oro badly damaged during salvage, wreck dumped Cebu by	15.11.90/17 14.11.17/20 2.8.65/70 71/72 79 2.8.79/91 1.9.65 70/81 30.6.81 11.8.81 83 1.84 12.86 21.10.88 .89/91 11.7.92
	8.02 repo N22BR no N22BR no H18 trigear N97BC no H18	rt: N22BR still oted Jackson-F oted Jackson-F N630TL N684HA N97BC oted Detroit-Do JA5507 N69094  RP-C1104	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  The Service Fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;  Time Life Inc, New York NY: CofA issued Tecumseh Aircraft Leasing, Dover DE McBride & Shoff, Metamora IL Richard J. Jones, Detroit MI  Sewntown MI 9.80 trigear;  reg Maritime Safety Agency, Sendai retired Fora Sorenson, Pensacola FL op: Circle Rainbow Air Inc, Honolulu HI Hutchinson Auto & Air Transport, Honolulu HI Circle Rainbow Air Inc, Honolulu HI struck-off USCR Pacific Airways Corp, Manila ditched in river Cagayan de Oro badly damaged during salvage, wreck dumped Cebu by span 13.8.72;	15.11.90/17 14.11.17/20 2.8.65/70 71/72 79 2.8.79/91 1.9.65 70/81 30.6.81 11.8.81 83 1.84 12.86 21.10.88 .89/91 11.7.92
BA-730	H18 trigear  N97BC no.  H18  H18	rt: N22BR still oted Jackson-h oted Jackson-h N630TL N684HA N97BC oted Detroit-Do JA5507  N69094  RP-C1104  oted Chofu, Jacted Sendai 26	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  **Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;  Time Life Inc, New York NY: CofA issued Tecumseh Aircraft Leasing, Dover DE McBride & Shoff, Metamora IL Richard J. Jones, Detroit MI  **Dewntown MI 9.80 trigear;**  reg Maritime Safety Agency, Sendai retired Fora Sorenson, Pensacola FL op: Circle Rainbow Air Inc, Honolulu HI Hutchinson Auto & Air Transport, Honolulu HI Circle Rainbow Air Inc, Honolulu HI struck-off USCR Pacific Airways Corp, Manila ditched in river Cagayan de Oro badly damaged during salvage, wreck dumped Cebu by  **Span 13.8.72; 5.12.73 MSA;**	15.11.90/17 14.11.17/20 2.8.65/70 71/72 79 2.8.79/91 1.9.65 70/81 30.6.81 11.8.81 83 1.84 12.86 21.10.88 .89/91 11.7.92
	8.02 repo N22BR no N22BR no H18 trigear N97BC no H18 JA5507 no JA5507 no N69094 no	rt: N22BR still oted Jackson-F oted Jackson-F N630TL N684HA N97BC oted Detroit-Do JA5507  N69094  RP-C1104  oted Chofu, Jacoted Sendai 26 eported in Japa	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  The Service Fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;  Time Life Inc, New York NY: CofA issued Tecumseh Aircraft Leasing, Dover DE McBride & Shoff, Metamora IL Richard J. Jones, Detroit MI  Swintown MI 9.80 trigear;  reg Maritime Safety Agency, Sendai retired Fora Sorenson, Pensacola FL op: Circle Rainbow Air Inc, Honolulu HI Hutchinson Auto & Air Transport, Honolulu HI Circle Rainbow Air Inc, Honolulu HI struck-off USCR Pacific Airways Corp, Manila ditched in river Cagayan de Oro badly damaged during salvage, wreck dumped Cebu by Inpan 13.8.72; 5.12.73 MSA; Interview Inc. 10.8.98: TT 9262 hrs; Interview Int	15.11.90/17 14.11.17/20 2.8.65/70 71/72 79 2.8.79/91 1.9.65 70/81 30.6.81 11.8.81 83 1.84 12.86 21.10.88 .89/91 11.7.92
	8.02 repo N22BR no N22BR no H18 trigear N97BC no H18 JA5507 no JA5507 no JA5507 no N69094 no N69094 no	rt: N22BR still oted Jackson-Foted Jackson-Foted Jackson-Foted Jackson-Foted Jackson-Foted Detroit-Double JA5507  N69094  RP-C1104  oted Chofu, Jackson-Foted Sendai 20 deported in Japan poted Honolulu	Jim Hankins Air Service, Jackson MS Dakota Express LLC, Wilmington DE  **Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;  Time Life Inc, New York NY: CofA issued Tecumseh Aircraft Leasing, Dover DE McBride & Shoff, Metamora IL Richard J. Jones, Detroit MI  **Dewntown MI 9.80 trigear;**  reg Maritime Safety Agency, Sendai retired Fora Sorenson, Pensacola FL op: Circle Rainbow Air Inc, Honolulu HI Hutchinson Auto & Air Transport, Honolulu HI Circle Rainbow Air Inc, Honolulu HI struck-off USCR Pacific Airways Corp, Manila ditched in river Cagayan de Oro badly damaged during salvage, wreck dumped Cebu by  **Span 13.8.72; 5.12.73 MSA;**	15.11.90/17 14.11.17/20 2.8.65/70 71/72 79 2.8.79/91 1.9.65 70/81 30.6.81 11.8.81 83 1.84 12.86 21.10.88 .89/91 11.7.92

BA-732	H18	JA5150	Maritime Safety Agency, Niigata	10.65/82
		oted Chofu 5. oted Yao Japa	5.81 no titles; an 25.4.82 Kyoritsu Koku;	
BA-733	H18	N204CS N204CC	built Southern Airways, Atlanta GA Colonial Stores Inc, Jacksonville FL Central Trust Leasing Corp, Cleveland OH Larry Johnson, McAllen TX crashed destroyed after takeoff, Brownsville TX	.65 66 69 70 16.2.78 20.11.78
			t 20.11.78: Larry Johnson, cargo flight Brownsville to Spr wreck 3 miles from airport, pilot k;	ingfield MO, took off
BA-734	P.2022 no P.2022 no	oted Hong Kor	Indonesian Aviation Corp/Indoavia, Jakarta sold to Indonesian Police Indonesian Air & Water Police/ Angk.Kepolisian seither BA-734 or BA-737, definitely not BA-743; ang 31.3.69 "Polisi"; ang 2.70 "Polisi"; ang 2.70 "Polisi";	2.11.65/66 21.11.66 11.66/92
	P.2022 no	oted Jakarta-K	Cemajoran 13.10.73; Cabe, Indonesia (based there) 92 in service "Polisi Udara"	" titles;
BA-735	H18 trigear	PK-BIB	Indonesian Aviation Corp/ Indoavia, Jakarta damaged in accident Kaimana (repaired) derelict in hangar with PK-BIE, scrapped struck-off Register	1.11.65/00 7.5.75 c07 20.7.18
	PK-BIB no PK-BIB no	oted Singapor oted Jakarta-H	e-Seletar 13.3.72, e-Seletar 3.5.72 trigear no titles; łalim 11.95, in service "Indoavia" titles ,"Bomberai" on no th Indoavia paint scheme, derelict in hangar c2005, parts	
BA-736	H18 trigear	PK-BIC	Indonesian Aviation Corp/ Indoavia, Jakarta crashed Sintang	11.65/82 11.11.79
	PK-BIC n	oted Singapor	e-Seletar 8.5.72 trigear, no titles;	
BA-737	H18 trigear	PK-BID	Indonesian Aviation Corp/ Indoavia, Jakarta (to Indonesian Police as)	2.12.65 21.11.66
	Could be	Polisi P.2022:	see BA-734	
BA-738	H18 trigear	PK-BIE	Indonesian Aviation Corp/ Indoavia, Jakarta "Bayu" derelict in hangar with PK-BIE, scrapped struck-off Register	12.65/00 c07 20.7.18
	PK-BIE no	oted Jakarta-k	e-Seletar 9.5.72; Kemajoran 6.74; th Indoavia paint scheme, derelict in hangar c2005, parts	cut off;
BA-739	H18 trigear	PP-FMV PT-FMV PT-LPO	built Sudene-Superit do des do Nordeste, Recife Base Aerofotogrametria SA	.66 83 14.7.88
	PT-FMV r	noted Recife-E	Encanta Moca 19.7.81 trigear, "Sudene" titles, named "As	a Branca 1";
BA-740	H18 trigear	N908T N700CC (2	Beech Aircraft Corp, Wichita KS: CofA issued W. C. Ruffin, Gainesville FL probably: Continental Air Services, Laos (open storage Bangkok-Don Muang 75 with Vietnam evacuee aircraft)	30.1.66 69/70 75

N701CC	rereg	5.78
	Nuggett Oil Inc, Crestview FL	79
	Moonlight Express Corp, Flushing NY	5.3.80
	crashed destroyed near Troxelville PA	18.11.80

N908T noted Bangkok-Don Muang 23.9.75, trigear, stored in centre of field with group of Vietnam evacuee aircraft: Beech 18s, Porters;

N701CC accident report 18.11.80: Moonlight Express, flight New York to Pittsburgh PA, uncontrolled descent, airframe ice, deicing equipment u/s, dest. 1.53am, pilot k;

BA-741	H18	N2095W	Beech Aircraft Corp, Wichita KS: CofA issued	14.2.66															
			Bowman Transport Inc, East Gadsden AL	69															
			Edward P. Mayer, St Louis MO	70															
		N1LH	Malcolm Jacobs Aviation, Chesterfield MO	71/72															
			Gifford Aviation, Anchorage AK	77/79															
																	hard landing, gear collapsed, Noatak AK	31.5.77	
			sale reported, Anchorage-Merrill Field AK	4.81/91															

N1LH accident report 31.5.77: Gifford Aviation Inc, cargo flight Anchorage to Noatak, runway slopes upward, 2 crew unhurt;

BA-742	H18	N5900S	built	.66
	trigear		Granite Construction Co, Watsonville CA	69/70
		N1900G	Granite Construction Co, Watsonville CA	71/72
			ditched into Pacific Ocean on delivery flight, Hilo HI to	
			Papeete, Tahiti	11.2.76
		(F-ODBV)	ntu: M. Brun, Papeete, Tahiti	2.76

N1900G noted Watsonville CA 23.4.72 trigear;

N1900G accident report 11.2.76: ferry flight, one engine feathered, unable to maintain altitude, not located, 1 crew missing;

BA-743	H18 trigear	N5436U	Floair Inc, Wichita Municiple Airport KS Indonesian Army/TNI-AD as A-8037 Indonesia Timur	4.67 5.67/82
			(del. to Indonesia via Oakland CA 14.5.67)	

A-8037 del. via Oakland CA 14.5.67 in full Angkatan Darat scheme & titles with N5436U on sticker on fuselagesides;

A-8037 noted Port Moresby PNG 9.11.68 "Angkatan Darat", named "Indonesia Timur 1", bringing Army military commander for West Irian;

A-8037 noted Hong Kong-Kai Tak 31.3.69 Angkatan Darat;

A-8037 noted Singapore-Seletar 22.9.72 "Angkatan Darat" under maintenance;

A-8037 noted Seletar 30.11.75 TNI-AD;

	H18	JA5136	Japan Airlines, Tokyo	4.5.67/74
	trigear		sold abroad, struck-off Japanese Register	17.4.74
		(VH-CKQ)	ntu: Trans West Air Charter, Perth WA	4.74
			(purchase cancelled due Australian certification problem	s)
		N35AP	Harmor Inc, Newport Beach CA	4.74/79
			(US CofA issued 24.10.74)	
			op: Brandt Air, Honolulu HI (fleet #7)	76/79
			op: Alii Hawaii Air, Honolulu HI	78
			groundloop landing, gear collapsed, Molokai HI	19.5.78
			retired Honolulu, open storage	79
			struck-off USCR	6.81
			Robert S. Whittinghill, Honolulu HI: restored to USCR	24.10.84/93
			op: Lani Bird, Honolulu HI	84
		RP-C1159	Pacific Airways Corp, Manila	5.93
			retired derelict Cebu-Mactan AB	06

JA5136 noted Tokyo-Chofu 20.5.74 JAL;

N35AP noted Kahului HI 4.12.76 trigear "Brandt" above windows, "B" on tail fins;

N35AP accident report 19.5.78: Alii Hawaii Air, flight from Honolulu 5pm, 10 unhurt;

N35AP noted Honolulu 4.9.79 derelict, trigear, Brandt Fleet #7, stored with other derelict Beech 18s and a Dove next to Brandt Air hangar;

N35AP noted Honolulu 7.89 poor condition, plate BA-744; RP-C1159 noted Cebu-Mactan AB 6.1.94 in green primer; RP-C1159 noted Cebu-Mactan AB early 06, trigear, derelict with RP-C1358;

BA-745	H18	JA5137	Japan Air Lines	5.5.67
	trigear		(delivered via Oakland CA 5.67. San Francisco 7.6.67) crashed Murayama C5ity, Yamagata	5.10.67
BA-746	H18	JA5138	Japan Air Lines	25.5.67
	trigear		(delivered via Oakland CA 31.5.67)	
			sold abroad, struck-off Japanese Register	9.4.74
		(VH-CKS)	ntu: Trans West Air Charter, Perth WA	4.74
		NOAAD	(purchase cancelled due Australian certification problem	
		N34AP	Harmor Inc, Newport Beach CA	4.74/79
			op: Alii Hawaii Air, Honolulu HI	79
			op: Brandt Air, Honolulu HI (fleet #9)	79
			Scenic Air Tour/ Lani Bird, Honolulu HI (#22)	.80/83
			op: Scenic Air Tours Hawaii, Honolulu HI	85/89
			crashed in canyon, dest. Waipio Valley HI (11k)	11.6.89
BA-747	JA5138 n N34AP no plate BA- N34AP no N34AP no N34AP no N34AP no N34AP no crash repo	oted Tokyo-Ha oted Honolulu : 746, manufacto oted Lenai HI 2 ow Honolulu-M oted Honolulu : oted Kauai HI oted Maui 9.85 ort 11.6.89: Sc	2.9.79 trigear "Ali Hawaii Air" titles, in service, op. by Brarured 5.67); 2.9.79; 3.9.79; 3.0lokai-Lanai-Honolulu 5.9.79 op Brandt Air, fresh baked b. 3.12.11.79; 3.7.8.81 trigear "Lani Bird", white with red trim; 3.7.8.81 engine fire taxying, no damage: "Lani Bird"; 3.83 "Scenic Air Tour/Lani Bird" fleet #22, trigear, plate Bird "Scenic Air Tours" titles (only), allover red, trigear #22; 3.2 tenic Air Tours Flt 21 was a sightseeing flight from Hilo to 1930 ft in a scenic area near a waterfall, 50 miles north of Firm Japan Air Lines 3.0 sold abroad, struck-off Japanese Register 3.1 ntu: Trans West Air Charter, Perth WA 3.2 ntu: Trans West Air Charter, Perth WA 4.3 (purchase cancelled due Australian certification problem Indonesian Aviation Corp/Indoavia, Jakarta Mega	9.6.67 8.8.74 4.74 9.8.74 4.74 9.8.74/90
	JA5139 n	oted Chiyoufu	struck-off Register eredvia Oakland CA .67 (no date), "JAL" emblem on fuse 7.5.72; e-Seletar 11.9.75;	20.7.18 , trigears;
BA-748	H18	JA5140	Japan Air Lines	7.67/74
	trigear		(delivered via San Francisco CA 14.7.67)	
			sold to USA, struck-off Japanese Register	18.2.74
		N33AP	Harmor Inc, Newport Beach CA (US CofA issued 14.3.74, N33AP dep. Sendai, Japan on 23.2.74 on del. to Honolulu via Midway island)	2.74/81
			struck-off USCR Robert S. Whittinghill, Honolulu HI: restored USCR op: Lani Bird, Honolulu HI op: Polynesian Air-Ways Inc, Honolulu HI dam. landing, Lanai HI struck-off USCR	6.81 24.10.84/13 84/85 .85/92 14.2.92 16.4.13
	"JA40" no N33AP no N33AP no	oted Tokyo-Har oted Honolulu oted Honolulu	CA .67 "JAL" emblem on fuse, trigear; neda 4.69 - probably this acft; 1.76 Island Air Tours, trigear; 2.89 & 7.89: both "Polynesian Airways" "Darryl O" trigear; 6.10.91 in service, metallic, Polynesian Airways titles	

BA-749	H18	JA5141	Japan Air Lines	.67/74
trigea	trigear		(delivered via San Francisco CA 14.7.67)	
			sold abroad, struck-off Japanese Register	5.2.74
			(F-OCUU departed Sendai, Japan 10.2.74 on del. to	
			Tahiti via Hachijo)	
		F-OCUU	Jacques Brunn, Papeete, Tahiti	2.12.74/76
			Rodolphe Klima, Papeete, Tahiti	15.6.76/77
			Air Tahiti, Papeete	2.2.77/80
			op: Tahiti Air Tours Service – TATS	-
			sold to USA, struck-off French Register	27.5.80
		N8476H	Clyde L. Neill, Indian Wells CA	28.7.80
			(US CofA issued 14.11.80)	
			Air Cortez International Inc, Ontario CA	81/86
			Jerry L. Englund/ Englund Air Inc, Mobile AL	9.86/91
			George A. Long, Baker LA	10.92/94
			Jim Hankins Air Service, Jackson MS	17.11.94/02
			Monarch Air Group LLC, Palm City FL	2.2.06/13
			Kevin McCole, Brookline NH	10.1.13/16
			Joanne McCole, Brookline NH	26.8.16/20

F-OCUU photo Tahiti 70s "TATS" titles above windows, trigear; F-OCUU noted Orange County CA 17.8.80; N8476H noted Yuma AZ 2.81 trigear "Air Cortez" titles;

N8476H noted Las Vegas NV 17.8.82 Air Cortez International (10 pax config.);

N8476H noted Ontario CA 14.2.83 trigear, "Air Cortez International" titles;

N8476H noted Las Vegas NV 4.2.84 "Air Cortez International" titles, trigear;

N8476H: Jim Hankins Air Service fleet Status Report 10.8.98: TT 13,900hrs;

8.02 report: N8476H still in service with Hankins;

BA-750	H18	JA5142	Japan Air Lines	25.7.67/74
	trigear		(delivered via San Francisco CA 30.7.67)	
	<b>3</b>		sold abroad, struck-off Japanese Register	12.6.74
		(VH-CKN)	ntu: Trans West Air Charter, Perth WA	1.74
		,	(purchase cancelled due Australian certification problems	s)
		N18843	Continental Air Services Inc, Los Angeles CA	<sup>^</sup> 5.74/79
			(US CofA issued 30.6.74, based Laos,	
			evacuated to Bangkok-Don Muang 4.75, open storage	
			with other Vietnam civil contractor aircraft)	
			Bo Larsson/ Parachutingclub Aros, Vasteras, Sweden:	
			who purchased N18843 & N906T at Bangkok	.77
			(delivered Bangkok to Sweden, via Antwerp 12.4.77)	
			op: Parachutingclub Aros, Vasteras-Johannisberg,	
			Sweden	77
			(parachuting ops. most of 1977, then	
			retired, stored Vasteras-Johannisberg for 2 years)	
			Volpar International Corp, Van Nuys CA	80/81
			op: Circle Rainbow Air, Honolulu HI "Mieko"	79/84
			Circle Rainbow Air Inc, Honolulu HI	12.86/91
			sold to Philippines: struck-off USCR	9.3.90
		RP-C1105	Pacific Airways Corp, Manila	.89/93
		RP-C1986	Pacific Airways Corp, Manila	.93/94
			crashed landing Manila (repaired)	4.94
		RP-C1358	Pacific Airways Corp, Manila	1.96/97
			Commuter Air, Manila	10
		RP-C9842	CM Aero Service, Manila	11/12

N18843 photo Vientiane, Laos 74 trigear;

N18843 photo Vientiane, Laos 5.75: trigear, parked with lineup Turbo Porters

N62161, N62156, N62148 plus two others & United States of America C-47 0-16364;

N18843 noted Bangkok-Don Muang 23.9.75, trigear, stored in centre of field with Vietnam evacuee Beech 18s and Porters;

BA-667 & -750 advertised for sale 76 by Continental Air Services Pte Ltd, Singapore, both located at Don Muang Airport, Bangkok: also advertise 7 Porters, 2 DC3s, 2 CV440s;

N18843 noted Honolulu 5.9.79 "Circle Rainbow Alr" titles, name "Mieko";

N18843 noted Kahului HI 8.82 "Circle Rainbow Air", trigear in service; N18843 noted Honolulu 9.83 "Circle Rainbow Air", trigear, plate BA-750;

RP-C1986 noted Manila 2.1.94 trigear, white with red trim, no titles;

RP-C1986 noted Cebu-Mactan AB early 06, trigear, derelict with RP-C1159; RP-C1358 noted Manila 3.3.10 Commuter Air, being changed to RP-C9842;

3A-751	H18 trigear	N7025N JA5508	Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR Maritime Safety Agency, Chitose	13.11.67 13.11.67 1.68/81
	JA5508 n	oted Chofu 1:	retired 3.8.72:	9.7.81
			11.9.78 MSA;	
BA-752	H18	LV-PIB	delivery reg.	11.67
	trigear	LV-JFH	Firma Arte Grafica Ed Argentina Juan Quevedo	29.12.67 4.8.75
			Morales Russo SA	31.3.76
			Jesus Ibarguren Echeverria, Necochea	9.8.85
			retired, open storage, San Fernando (flying, based Moron, Argentina 06/20)	96
	LV-JFH n	oted Torcuato	o-Halcon 7.3.86;	
			nando 19.10.96, open storage, plate BA-752;	
			w General-Rodriguez-Ildefonso Durana 9.3.13; w Alvear 18.9.19 polished metal, green trim, trigear;	
3A-753	H18	JA5143	Japan Air Lines, Tokyo	3.68/76
	trigear	- · ·	(delivered via San Francisco CA 25.3.68)	
			sold to USA, struck-off Japanese Register	14.4.76
		N2990F	B & B Enterprises, Honolulu HI	15.4.76/82 80/83
			op: Panorama Air Tour, Honolulu HI (fleet #60) Airtour Acquisition Corp, Honolulu HI	16.9.82/83
			ditched in sea after takeoff, Kailua-Kona HI	8.9.83
	JA5143 n	oted San Frai	ncisco CA 25.3.68 on delivery "JAL" insignia;	
	N2990F r N2990F r N2990F r	noted Kahului noted Hilo HI 2 noted Honoluli	HI 27.7.76 Panorama Air Tour; 26.8.81 "Panorama AT #60", in Beech 18 tourist formation u HI 1.83 "Panorama AT" trigear;	
3A-754	N2990F r N2990F r N2990F r	noted Kahului noted Hilo HI 2	HI 27.7.76 Panorama Air Tour; 26.8.81 "Panorama AT #60", in Beech 18 tourist formation u HI 1.83 "Panorama AT" trigear; Japan Air Lines, Tokyo	.68/76
3A-754	N2990F r N2990F r N2990F r	noted Kahului noted Hilo HI 2 noted Honoluli	HI 27.7.76 Panorama Air Tour; 26.8.81 "Panorama AT #60", in Beech 18 tourist formation u HI 1.83 "Panorama AT" trigear; Japan Air Lines, Tokyo (delivered via Oakland CA 4.68)	.68/76
3A-754	N2990F r N2990F r N2990F r	noted Kahului noted Hilo HI 2 noted Honoluli	HI 27.7.76 Panorama Air Tour; 26.8.81 "Panorama AT #60", in Beech 18 tourist formation u HI 1.83 "Panorama AT" trigear;  Japan Air Lines, Tokyo (delivered via Oakland CA 4.68) sold to USA, struck-off Japense Register	
3A-754	N2990F r N2990F r N2990F r	noted Kahului noted Hilo HI 2 noted Honoluli JA5144	HI 27.7.76 Panorama Air Tour; 26.8.81 "Panorama AT #60", in Beech 18 tourist formation u HI 1.83 "Panorama AT" trigear;  Japan Air Lines, Tokyo (delivered via Oakland CA 4.68) sold to USA, struck-off Japense Register reg (US CofA issued 11.11.76)	.68/76 23.8.76
3A-754	N2990F r N2990F r N2990F r	noted Kahului noted Hilo HI 2 noted Honoluli JA5144	HI 27.7.76 Panorama Air Tour; 26.8.81 "Panorama AT #60", in Beech 18 tourist formation u HI 1.83 "Panorama AT" trigear;  Japan Air Lines, Tokyo (delivered via Oakland CA 4.68) sold to USA, struck-off Japense Register reg (US CofA issued 11.11.76) B & B Enterprises, Honolulu HI	.68/76 23.8.76 22.8.76 79
3A-754	N2990F r N2990F r N2990F r	noted Kahului noted Hilo HI 2 noted Honoluli JA5144	HI 27.7.76 Panorama Air Tour; 26.8.81 "Panorama AT #60", in Beech 18 tourist formation u HI 1.83 "Panorama AT" trigear;  Japan Air Lines, Tokyo (delivered via Oakland CA 4.68) sold to USA, struck-off Japense Register reg (US CofA issued 11.11.76) B & B Enterprises, Honolulu HI Panorama Air Tour, Honolulu HI (fleet #61)	.68/76 23.8.76 22.8.76 79 80/85
3A-754	N2990F r N2990F r N2990F r	noted Kahului noted Hilo HI 2 noted Honoluli JA5144	HI 27.7.76 Panorama Air Tour; 26.8.81 "Panorama AT #60", in Beech 18 tourist formation a HI 1.83 "Panorama AT" trigear;  Japan Air Lines, Tokyo (delivered via Oakland CA 4.68) sold to USA, struck-off Japense Register reg (US CofA issued 11.11.76) B & B Enterprises, Honolulu HI Panorama Air Tour, Honolulu HI (fleet #61) Airtour Acquisition Corp, Honolulu HI	.68/76 23.8.76 22.8.76 79 80/85 82
3A-754	N2990F r N2990F r N2990F r	noted Kahului noted Hilo HI 2 noted Honoluli JA5144	HI 27.7.76 Panorama Air Tour; 26.8.81 "Panorama AT #60", in Beech 18 tourist formation u HI 1.83 "Panorama AT" trigear;  Japan Air Lines, Tokyo (delivered via Oakland CA 4.68) sold to USA, struck-off Japense Register reg (US CofA issued 11.11.76) B & B Enterprises, Honolulu HI Panorama Air Tour, Honolulu HI (fleet #61)	.68/76 23.8.76 22.8.76 79 80/85
3A-754	N2990F r N2990F r N2990F r	noted Kahului noted Hilo HI 2 noted Honolulu JA5144 N26035	HI 27.7.76 Panorama Air Tour; 26.8.81 "Panorama AT #60", in Beech 18 tourist formation a HI 1.83 "Panorama AT" trigear;  Japan Air Lines, Tokyo (delivered via Oakland CA 4.68) sold to USA, struck-off Japense Register reg (US CofA issued 11.11.76) B & B Enterprises, Honolulu HI Panorama Air Tour, Honolulu HI (fleet #61) Airtour Acquisition Corp, Honolulu HI John A. Bombaro, Newport News VA Atlantic Aero Inc, Greensboro NC Cape Central Airways, Cape Girardeau MO	.68/76 23.8.76 22.8.76 79 80/85 82 11.85 1.87 5.90/91
3A-754	N2990F r N2990F r N2990F r	noted Kahului noted Hilo HI 2 noted Honolulu JA5144 N26035	HI 27.7.76 Panorama Air Tour; 26.8.81 "Panorama AT #60", in Beech 18 tourist formation a HI 1.83 "Panorama AT" trigear;  Japan Air Lines, Tokyo (delivered via Oakland CA 4.68) sold to USA, struck-off Japense Register reg (US CofA issued 11.11.76) B & B Enterprises, Honolulu HI Panorama Air Tour, Honolulu HI (fleet #61) Airtour Acquisition Corp, Honolulu HI John A. Bombaro, Newport News VA Atlantic Aero Inc, Greensboro NC Cape Central Airways, Cape Girardeau MO Cape Central Airways, Cape Girardeau MO	.68/76 23.8.76 22.8.76 79 80/85 82 11.85 1.87 5.90/91 7.94/95
3A-754	N2990F r N2990F r N2990F r	noted Kahului noted Hilo HI 2 noted Honolulu JA5144 N26035	HI 27.7.76 Panorama Air Tour; 26.8.81 "Panorama AT #60", in Beech 18 tourist formation a HI 1.83 "Panorama AT" trigear;  Japan Air Lines, Tokyo (delivered via Oakland CA 4.68) sold to USA, struck-off Japense Register reg (US CofA issued 11.11.76) B & B Enterprises, Honolulu HI Panorama Air Tour, Honolulu HI (fleet #61) Airtour Acquisition Corp, Honolulu HI John A. Bombaro, Newport News VA Atlantic Aero Inc, Greensboro NC Cape Central Airways, Cape Girardeau MO Cape Central Airways, Cape Girardeau MO Air Cargo Express, Little Rock AR	.68/76 23.8.76 22.8.76 79 80/85 82 11.85 1.87 5.90/91 7.94/95 28.6.95/99
3A-754	N2990F r N2990F r N2990F r	noted Kahului noted Hilo HI 2 noted Honolulu JA5144 N26035	HI 27.7.76 Panorama Air Tour; 26.8.81 "Panorama AT #60", in Beech 18 tourist formation a HI 1.83 "Panorama AT" trigear;  Japan Air Lines, Tokyo (delivered via Oakland CA 4.68) sold to USA, struck-off Japense Register reg (US CofA issued 11.11.76) B & B Enterprises, Honolulu HI Panorama Air Tour, Honolulu HI (fleet #61) Airtour Acquisition Corp, Honolulu HI John A. Bombaro, Newport News VA Atlantic Aero Inc, Greensboro NC Cape Central Airways, Cape Girardeau MO Cape Central Airways, Cape Girardeau MO	.68/76 23.8.76 22.8.76 79 80/85 82 11.85 1.87 5.90/91 7.94/95
BA-754	N2990F r N2990F r N2990F r H18 trigear	noted Kahului noted Hilo HI 2 noted Honolulu JA5144 N26035 N583MS N26035	HI 27.7.76 Panorama Air Tour; 26.8.81 "Panorama AT #60", in Beech 18 tourist formation a HI 1.83 "Panorama AT" trigear;  Japan Air Lines, Tokyo (delivered via Oakland CA 4.68) sold to USA, struck-off Japense Register reg (US CofA issued 11.11.76) B & B Enterprises, Honolulu HI Panorama Air Tour, Honolulu HI (fleet #61) Airtour Acquisition Corp, Honolulu HI John A. Bombaro, Newport News VA Atlantic Aero Inc, Greensboro NC Cape Central Airways, Cape Girardeau MO Cape Central Airways, Cape Girardeau MO Air Cargo Express, Little Rock AR Air Classic Cargo Inc, Orlando FL AOM Aircraft LLC, Newark DE	.68/76 23.8.76 22.8.76 79 80/85 82 11.85 1.87 5.90/91 7.94/95 28.6.95/99 18.6.99/14
BA-754	N2990F r. N2990F r. N2990F r. H18 trigear  JA5144 n. JA5144 n. N26035 r. N26035 ii	noted Kahului noted Hilo HI 2 noted Honolulu JA5144 N26035 N583MS N26035 oted Oakland noted Nagoya noted Hilo HI 2 n Panorama fi	HI 27.7.76 Panorama Air Tour; 26.8.81 "Panorama AT #60", in Beech 18 tourist formation a HI 1.83 "Panorama AT" trigear;  Japan Air Lines, Tokyo (delivered via Oakland CA 4.68) sold to USA, struck-off Japense Register reg (US CofA issued 11.11.76) B & B Enterprises, Honolulu HI Panorama Air Tour, Honolulu HI (fleet #61) Airtour Acquisition Corp, Honolulu HI John A. Bombaro, Newport News VA Atlantic Aero Inc, Greensboro NC Cape Central Airways, Cape Girardeau MO Cape Central Airways, Cape Girardeau MO Air Cargo Express, Little Rock AR Air Classic Cargo Inc, Orlando FL AOM Aircraft LLC, Newark DE	.68/76 23.8.76 22.8.76 79 80/85 82 11.85 1.87 5.90/91 7.94/95 28.6.95/99 18.6.99/14 8.4.14/20
BA-754	N2990F r. N2990F r. N2990F r. H18 trigear JA5144 n. JA5144 n. N26035 r. N26035 r.	noted Kahului noted Hilo HI 2 noted Honolulu JA5144 N26035 N583MS N26035 oted Oakland noted Nagoya noted Hilo HI 2 n Panorama fi	HI 27.7.76 Panorama Air Tour; 26.8.81 "Panorama AT #60", in Beech 18 tourist formation a HI 1.83 "Panorama AT" trigear;  Japan Air Lines, Tokyo (delivered via Oakland CA 4.68) sold to USA, struck-off Japense Register reg (US CofA issued 11.11.76) B & B Enterprises, Honolulu HI Panorama Air Tour, Honolulu HI (fleet #61) Airtour Acquisition Corp, Honolulu HI John A. Bombaro, Newport News VA Atlantic Aero Inc, Greensboro NC Cape Central Airways, Cape Girardeau MO Cape Central Airways, Cape Girardeau MO Air Cargo Express, Little Rock AR Air Classic Cargo Inc, Orlando FL AOM Aircraft LLC, Newark DE  CA 4.68 full JAL scheme; 18.8.72; 26.8.81 trigear "Panorama AT #61" in Beech 18 tourist formiteet list as at 15.11.83: BA-754 tt 16,413hrs, fleet #61; vs CA 3.8.85 "Panorama Air" titles;  Japan Air Lines, Tokyo	.68/76 23.8.76 22.8.76 79 80/85 82 11.85 1.87 5.90/91 7.94/95 28.6.95/99 18.6.99/14 8.4.14/20
	N2990F r. N2990F r. N2990F r. H18 trigear  JA5144 r. JA5144 r. N26035 r. N26035 r.	N583MS N26035  N583MS N26035  Oted Oakland oted Nagoya oted Hilo HI 2 of Panorama flooted Van Nuy	HI 27.7.76 Panorama Air Tour; 26.8.81 "Panorama AT #60", in Beech 18 tourist formation at HI 1.83 "Panorama AT" trigear;  Japan Air Lines, Tokyo (delivered via Oakland CA 4.68) sold to USA, struck-off Japense Register reg (US CofA issued 11.11.76) B & B Enterprises, Honolulu HI (fleet #61) Airtour Acquisition Corp, Honolulu HI John A. Bombaro, Newport News VA Atlantic Aero Inc, Greensboro NC Cape Central Airways, Cape Girardeau MO Cape Central Airways, Cape Girardeau MO Air Cargo Express, Little Rock AR Air Classic Cargo Inc, Orlando FL AOM Aircraft LLC, Newark DE  CA 4.68 full JAL scheme; 18.8.72; 26.8.81 trigear "Panorama AT #61" in Beech 18 tourist formeet list as at 15.11.83: BA-754 tt 16,413hrs, fleet #61; vs CA 3.8.85 "Panorama Air" titles;  Japan Air Lines, Tokyo (delivered via San Francisco CA 27.5.68)	.68/76 23.8.76 22.8.76 79 80/85 82 11.85 1.87 5.90/91 7.94/95 28.6.95/99 18.6.99/14 8.4.14/20  mation;
	N2990F r. N2990F r. N2990F r. H18 trigear JA5144 n. JA5144 n. N26035 r. N26035 r.	N583MS N26035  N583MS N26035  Oted Oakland oted Nagoya oted Hilo HI 2 of Panorama flooted Van Nuy	HI 27.7.76 Panorama Air Tour; 26.8.81 "Panorama AT #60", in Beech 18 tourist formation a HI 1.83 "Panorama AT" trigear;  Japan Air Lines, Tokyo (delivered via Oakland CA 4.68) sold to USA, struck-off Japense Register reg (US CofA issued 11.11.76) B & B Enterprises, Honolulu HI Panorama Air Tour, Honolulu HI (fleet #61) Airtour Acquisition Corp, Honolulu HI John A. Bombaro, Newport News VA Atlantic Aero Inc, Greensboro NC Cape Central Airways, Cape Girardeau MO Cape Central Airways, Cape Girardeau MO Air Cargo Express, Little Rock AR Air Classic Cargo Inc, Orlando FL AOM Aircraft LLC, Newark DE  CA 4.68 full JAL scheme; 18.8.72; 16.8.81 trigear "Panorama AT #61" in Beech 18 tourist formation for the set list as at 15.11.83: BA-754 tt 16,413hrs, fleet #61; Is CA 3.8.85 "Panorama Air " titles;  Japan Air Lines, Tokyo (delivered via San Francisco CA 27.5.68) sold to USA, struck-off Japanese Register	.68/76 23.8.76 22.8.76 79 80/85 82 11.85 1.87 5.90/91 7.94/95 28.6.95/99 18.6.99/14 8.4.14/20  mation;
	N2990F r. N2990F r. N2990F r. H18 trigear JA5144 n. JA5144 n. N26035 r. N26035 r.	N583MS N26035  N583MS N26035  Oted Oakland oted Nagoya oted Hilo HI 2 oted Van Nuy JA5145	HI 27.7.76 Panorama Air Tour; 26.8.81 "Panorama AT #60", in Beech 18 tourist formation at HI 1.83 "Panorama AT" trigear;  Japan Air Lines, Tokyo (delivered via Oakland CA 4.68) sold to USA, struck-off Japense Register reg (US CofA issued 11.11.76) B & B Enterprises, Honolulu HI (fleet #61) Airtour Acquisition Corp, Honolulu HI John A. Bombaro, Newport News VA Atlantic Aero Inc, Greensboro NC Cape Central Airways, Cape Girardeau MO Cape Central Airways, Cape Girardeau MO Air Cargo Express, Little Rock AR Air Classic Cargo Inc, Orlando FL AOM Aircraft LLC, Newark DE  CA 4.68 full JAL scheme; 18.8.72; 26.8.81 trigear "Panorama AT #61" in Beech 18 tourist formeet list as at 15.11.83: BA-754 tt 16,413hrs, fleet #61; vs CA 3.8.85 "Panorama Air" titles;  Japan Air Lines, Tokyo (delivered via San Francisco CA 27.5.68)	.68/76 23.8.76 22.8.76 79 80/85 82 11.85 1.87 5.90/91 7.94/95 28.6.95/99 18.6.99/14 8.4.14/20  mation; .68/73 25.10.73

Harmor Inc, Newport Beach CA	20.4.74
op: Island Air	74
destroyed, struck mountain, Hilo HI (11 k)	11.4.74

JA5145 noted San Francisco CA 27.5.68 on delivery, "JAL" insignia; JA5145 photo 3.71 in Japan, "JAL" emblem, trigear;

JA5145 noted Chofu 26.11.72;

N28358 accident report 11.4.74: Island Air -, flew into mountain slope, dest. 9.41am;

BA-756	H18	N2052A	Sugihara Shigeyoshi, Scarsdale NY	4.6.69
			exported to Japan, struck-off USCR	6.6.69
		JA5164	All Nippon Airways, Tokyo	.69/71
			crashed Nagoya Airport	14.2.71
BA-757	H18	N2069A	Sugihara Shigeyoshi, Scarsdale NY	4.6.69
			exported to Japan, struck-off USCR	6.6.69
		JA5167	All Nippon Airways, Tokyo	6.69/71
			damaged Kochi (repaired)	10.9.69
			Sumikoh Consultant Co	20.10.71
			retired, struck-off Register as scrapped	10.7.78
BA-758	JA5167 r		a Japan 7.5.72 with JA5139; 3.8.72 with JA5507, JA5508, JA5133, JA5503; Japan Air Lines, Tokyo	.69/73
BA-758	JA5167 r	noted Chofu 13	Japan 7.5.72 with JA5139; 3.8.72 with JA5507, JA5508, JA5133, JA5503;  Japan Air Lines, Tokyo SNKS Co Toa Domestic Airlines, Tokyo	27.7.73 .73/74
BA-758	JA5167 r	JA5147	Japan 7.5.72 with JA5139; 3.8.72 with JA5507, JA5508, JA5133, JA5503;  Japan Air Lines, Tokyo SNKS Co Toa Domestic Airlines, Tokyo sold to USA, struck-off Japanese Register	27.7.73 .73/74 26.2.76
BA-758	JA5167 r	noted Chofu 13	Japan 7.5.72 with JA5139; 3.8.72 with JA5507, JA5508, JA5133, JA5503;  Japan Air Lines, Tokyo SNKS Co Toa Domestic Airlines, Tokyo	27.7.73 .73/74
BA-758	JA5167 r	JA5147	Japan 7.5.72 with JA5139; 3.8.72 with JA5507, JA5508, JA5133, JA5503;  Japan Air Lines, Tokyo SNKS Co Toa Domestic Airlines, Tokyo sold to USA, struck-off Japanese Register reg	27.7.73 .73/74 26.2.76
BA-758	JA5167 r	JA5147	Japan 7.5.72 with JA5139; 3.8.72 with JA5507, JA5508, JA5133, JA5503;  Japan Air Lines, Tokyo SNKS Co Toa Domestic Airlines, Tokyo sold to USA, struck-off Japanese Register reg (US CofA issued 23.7.76)	27.7.73 .73/74 26.2.76 2.76
BA-758	JA5167 r	JA5147	Japan 7.5.72 with JA5139; 3.8.72 with JA5507, JA5508, JA5133, JA5503;  Japan Air Lines, Tokyo SNKS Co Toa Domestic Airlines, Tokyo sold to USA, struck-off Japanese Register reg (US CofA issued 23.7.76) Morgan Air Transport, Pensacola FL Lani Bird Inc/ Scenic Air Tour, Honolulu HI Tomy International Inc, Honolulu HI	27.7.73 .73/74 26.2.76 2.76
BA-758	JA5167 r	JA5147	Japan 7.5.72 with JA5139; 3.8.72 with JA5507, JA5508, JA5133, JA5503;  Japan Air Lines, Tokyo SNKS Co Toa Domestic Airlines, Tokyo sold to USA, struck-off Japanese Register reg (US CofA issued 23.7.76) Morgan Air Transport, Pensacola FL Lani Bird Inc/ Scenic Air Tour, Honolulu HI Aloha	27.7.73 .73/74 26.2.76 2.76 79
BA-758	JA5167 r	JA5147	Japan 7.5.72 with JA5139; 3.8.72 with JA5507, JA5508, JA5133, JA5503;  Japan Air Lines, Tokyo SNKS Co Toa Domestic Airlines, Tokyo sold to USA, struck-off Japanese Register reg (US CofA issued 23.7.76) Morgan Air Transport, Pensacola FL Lani Bird Inc/ Scenic Air Tour, Honolulu HI Op: Scenic Air Tour, Honolulu HI op: Scenic Air Tour, Honolulu HI Matthew R. Barnett, Honolulu HI	27.7.73 .73/74 26.2.76 2.76 79 79/84 5.91/95 89 31.8.95
BA-758	JA5167 r	JA5147	Japan 7.5.72 with JA5139; 3.8.72 with JA5507, JA5508, JA5133, JA5503;  Japan Air Lines, Tokyo SNKS Co Toa Domestic Airlines, Tokyo sold to USA, struck-off Japanese Register reg (US CofA issued 23.7.76) Morgan Air Transport, Pensacola FL Lani Bird Inc/ Scenic Air Tour, Honolulu HI Op: Scenic Air Tour, Honolulu HI op: Scenic Air Tour, Honolulu HI Op: Scenic Air Tour, Honolulu HI Dove Development Corp, Greenville TX	27.7.73 .73/74 26.2.76 2.76 79 79/84 5.91/95 89 31.8.95 11.95
BA-758	JA5167 r	JA5147	Japan 7.5.72 with JA5139; 3.8.72 with JA5507, JA5508, JA5133, JA5503;  Japan Air Lines, Tokyo SNKS Co Toa Domestic Airlines, Tokyo sold to USA, struck-off Japanese Register reg (US CofA issued 23.7.76) Morgan Air Transport, Pensacola FL Lani Bird Inc/ Scenic Air Tour, Honolulu HI Op: Scenic Air Tour, Honolulu HI op: Scenic Air Tour, Honolulu HI Matthew R. Barnett, Honolulu HI	27.7.73 .73/74 26.2.76 2.76 79 79/84 5.91/95 89 31.8.95

JA5147 noted Sendai 26.12.73 Toa;

JA5147 noted Tokyo-Chofu 24.2.74 Toa;

N99799 noted Honolulu 7.89 fleet #20, trigear;

N99799 noted Honolulu 2.9.79 & 5.9.79 "Lani Bird" titles name "Aloha" trigear; N99799 noted Lihue HI 6.10.80 "Lani Bird" fleet #20;

N99799 noted Honolulu 9.83 "Scenic Air Tour/Lani Bird" Fleet #20, trigear, plate BA-758;

N99799 noted Honolulu 7.89 Scenic Air Tour Fleet #20, flying;

N99799 noted Jackson-Higgins Field MS 11.8.98, trigear pax seating, Hankins AS;

N99799: Jim Hankins Air Service fleet Status Report 10.8.98: TT 21,715 hrs;

N99799 noted Boston-Logan MA 7.02 trigear;

BA-759	H18	JA5148	Japan Air Lines, Tokyo	.69/73
	trigear		SNKS Co	18.5.73
	· ·		Toa Domestic Airlines, Tokyo	.73
			sold to USA, struck-off Japanese Register	26.2.76
		N99800	reg	2.76
			(US CofA issued 2.9.76)	
			International Racing Service, Huntington Harbor CA	79
			Flite Services Inc, Pine Mountain GA	1.84
			Jim Hankins Air Service, Jackson MS	2.90
			Big Red Inc, Jackson MS	3.5.90/06
			Rugged Investment One LLC, Miami FL	15.3.07/20

JA5148 noted Sendai 26.12.73 Toa;

JA5148 noted Tokyo-Chofu 24.3.74 JAL;

further details N99800: see Beech 18 by Robert Parmerter p.241;

N99800 noted Van Nuys CA 23.9.77 trigear, N99800 painted over previous reg; N99800 noted Oshkosh WI 27.7.89 trigear, plate BA-759;

	119900011	ioleu Ostikosi	TWI 27.7.09 trigear, plate BA-709,	
BA-760	H18	JA5149	Japan Air Lines, Tokyo	.69/73
	trigear		SNKS Co	21.9.73
	-		Toa Domestic Airlines, Tokyo	.73
			sold to USA, struck-off Japanese Register	26.2.76
		N99801	reg	2.76
			Gifford Aviation, Anchorage AK	79
			Panorama Air Tour, Honolulu HI (fleet #64)	.79/84
			AirTour Acquisition Corp, Honolulu HI	82
			Sunshine Aero Industries Inc, Crestview FL	2.11.84/20
	N99801nd Panorama N99801 n	oted Honolulu a Air fleet list a noted Crestvie	Japan 26.12.73, in service, Toa Domestic; HI 9.83 "Panorama Air", trigear, plate BA-760; as at 15.11.83: BA-760 tt 13,259 hrs, fleet #64; w FL 14.8.05 plate BA-760, Sunshine Aero Industries: ope th special radar in connection with Predator UAV project;	rated
BA-761	H18	N2072A	Sugihara Shigeyoshi, Scarsdale NY	3.9.69
			exported to Japan, struck-off USCR	8.9.69
		JA5169	All Nippon Airways	9.69/71
			crashed Omura, Nagasaki	14.2.71
BA-762	H18	N2079A	Shigyoshi Sugihara, Scarsdale NY	8.9.69
DA-102	1110	INZUI JA	exported to Japan, struck-off USCR	11.9.69
		JA5509	Maritime Safety Agency, Chitose	10.69/81
		070009	retired, struck-off Japanese Register	18.2.81
	JA5509 n	oted Tokyo-H	aneda 10.5.73 MSA;	
BA-763	H18	N2080A	built	.69
	trigear	JA5172	Japan Civil Aviation Bureau Aeronautical College	1.70/78
			(departed Beech factory on delivery to Japan 26.11.69,	
			ferried by Air Capital International)	
			op: Japan Civil Aviation Bureau Aeronautical College/	
			Koku Daigaku, Miyazuki	74
			op: Maritime Safety Agency, Naha	75
		N763C	Circle Rainbow Air Inc, Honolulu HI	4.6.85/92
		DD 2225	sold to Philippines, struck-off USCR	27.1.92
		RP-C692	Charles R. Miller/ CM Aero, Manila	90/98
			J. G. Gomez, Clark Field	.00/01
			crashed Manila, Philippines	21.11.01
	N2080A r JA5172 n JA5172 n RP-C692	noted Oakland oted Tokyo-C oted Naha 7.1 noted Manila		
BA-764	H18	N2088A	built	.69
	Trigear	JA5173	Japan Civil Aviation Bureau Aeronautical College (departed Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International) op: Japan Civil Aviation Bureau Aeronautical College/	1.70/80
			Koku Daigaku, Miyazuki	74
			op: Maritime Safety Agency, Hiroshima	80
		N26493	Pacific International Traders Inc. Palau	25.12.81
		ロメとしてひし	i aono memandiai maucio IIIV. I alau	CU. 1C.U.

Trigear	JA5173	Japan Civil Aviation Bureau Aeronautical College (departed Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International)	1.70/80
		op: Japan Civil Aviation Bureau Aeronautical College/	
		Koku Daigaku, Miyazuki	74
		op: Maritime Safety Agency, Hiroshima	80
	N26493	Pacific International Traders Inc, Palau	25.12.81
		Robert E. Etchell, Koror, Micronesia	1.82
		Hutchinson Auto & Air Transport, Honolulu HI	3.84
		Circle Rainbow Air, Honolulu HI	.86/92
		struck-off USCR	23.1.92
		Matthew R. Barnett, Honolulu HI: restored to USCR	22.6.94/95
		Charles B. Mobus. New York NY	18.7.95/11
		Beach Aero Partners Inc, Westhampton Beach NY	10.1.12/15

Dakota Express LLC, Lantana FL 27.9.17/18 Mike Spaulding, Cairns QLD Australia 8.18 (del. via Santa Monica CA-Hilo HI 13.5.19) 2.8.19/20

VH-MBU Mike Spaulding Pty Ltd, Cairns QLD

JA5173 noted Tokyo-Chofu 15.12.74 operator Koku Daigaku:

JA5173 noted Hiroshima 30.6.80 MSA:

(Pacific International Traders, Palau had two DC-8-50 freighters in 81)

N26493 noted Agana, Guam 18.10.82 trigear, faded blue & yellow scheme, previous insignia

N26493 was noted as delivered ex Chofu, Japan 16.4.82: possibly returned for maintenance? N26493 noted Honolulu 8.9.91, 6.10.91,

N26493 noted Honolulu 12.93: derelict, trigear ex JA5173 visible;

N26493 noted Teterboro NJ 16.7.98 trigear;

VH-MBU noted Mareeba Qld 20.8.19 in Mike Spaulding's North Queensland Warbirds hangar; VH-MBU noted Parafield SA 9.4.21;

BA-765	H18	N2091A	Shigeyoshi Sugihara, Scarsdale NY	11.69/70	
	trigear		(dep. Beech factory on delivery to Japan 26.11.69,		
	3 - 3		ferried by Air Capital International, dep. Oakland CA 1.70)		
			exported to Japan, struck-off USCR	<sup>27.1.70</sup>	
		JA5174	Japan Civil Aviation Bureau Aeronautical College/		
			Koku Daigaku, Miyazuki	2.70/78	
			Civil Aviation College Maintenance Division, Miyazaki	02	
			(static display in hangar, excellent condition)		

## last Beech 18 manufactured

Further details Japan sale and ferry: Parmerter p.312/313;

N2091A noted Agusta-Redwing GA 26.11.69, trigear, ferry markings;

JA5174 noted Kagoshima 6.5.76 trigear;

JA5174 noted Chofu 7.81 Civil Avtn bureau, trigear i/s;

JA5174 noted Miyazaki in CAC Maintenance Division hangar, immaculate

could be an instructional airframe;